Appendix E

Phase I Environmental Site Assessment and Closure Letter

PARTNER



PHASE I ENVIRONMENTAL SITE ASSESSMENT REPORT

790 Shiloh Road

Windsor, California 95492

Report Date: December 10, 2021
Partner Project No. 21-34725.1



Prepared for:

NYL Investors, LLC
MNCVAD II-BIG SHILOH JV LLC
MNCVAD II-IND SHILOH CA LLC
McMorgan Northern California Value Add/Development Fund II, LP
NYL Investors NCVAD II GP, LLC,
and the partners, members, managers, affiliates, successors and assigns of all the above named parties

PARTNER

December 10, 2021

Mr. Bruce Peterson
NYL Investors, LLC
51 Madison Avenue, 9th Floor
New York, New York 10010

MNCVAD II-BIG SHILOH JV LLC
MNCVAD II-IND SHILOH CA LLC
McMorgan Northern California Value
Add/Development Fund II, LP
NYL Investors NCVAD II GP, LLC

Subject: **Phase I Environmental Site Assessment**
790 Shiloh Road
Windsor, California 95492
Partner Project No. 21-347251.1

Dear Mr. Peterson:

Partner Assessment Corporation (Partner) is pleased to provide the results of the *Phase I Environmental Site Assessment* (Phase I ESA) report of the abovementioned address (the "subject property"). This assessment was performed in conformance with the scope and limitations as detailed in the ASTM Practice E1527-13 Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process.

This assessment included a site reconnaissance as well as research and interviews with representatives of the public, property ownership, site manager, and regulatory agencies. An assessment was made, conclusions stated, and recommendations outlined.

We appreciate the opportunity to provide environmental services to you. If you have any questions concerning this report, or if we can assist you in any other matter, please contact me at (561) 412-3776 or wmarcus@partneresi.com.

Sincerely,

William Marcus
Principal

EXECUTIVE SUMMARY

Partner Assessment Corporation (Partner) has performed a Phase I Environmental Site Assessment (ESA) in accordance with the scope of work and limitations of ASTM Standard Practice E1527-13, the Environmental Protection Agency Standards and Practices for All Appropriate Inquiries (AAI) (40 CFR Part 312) and set forth by NYL Investors, LLC for the property located at 790 Shiloh Road, Town of Windsor, Sonoma County, California (the "subject property"). The Phase I ESA is designed to provide NYL Investors, LLC with an assessment concerning environmental conditions (limited to those issues identified in the report) as they exist at the subject property.

Property Description

The subject property is located on the south side of Shiloh Road and the west side of Highway 101 within a mixed industrial, commercial, and agricultural area of Sonoma County. Please refer to the table below for further description of the subject property:

Subject Property Data	
Address:	790 Shiloh Road, Windsor, California
Additional Address:	5937 Pruitt Avenue
Property Use:	Industrial – mostly vacant land
Land Acreage (Ac):	45.1 Ac
Number of Buildings:	One
Number of Floors:	One with a mezzanine
Gross Building Area (SF):	45,200 SF
Date of Construction:	1978
Assessor's Parcel Number (APN):	059-271-095
Type of Construction:	Wood-Framed and poured concrete slab foundation
Current Tenants:	JL Modular Inc and Ahlborn Structural Steel Inc
Site Assessment Performed By:	Zachary Oretsky of Partner
Site Assessment Conducted On:	November 30, 2021

The subject property is predominantly vacant land. An industrial building currently occupied by JL Modular Inc and Ahlborn Structural Steel Inc is located on the western border. Onsite operations consist of sanding, painting, welding, and assembly of steel beams and modular portions of commercial structures, typical administrative office activities, and general equipment maintenance. Bridge cranes are located within the building and adjacent to the south of the building. A propane above ground storage tank (AST) is located adjacent to the west of the building. Access is provided via a gravel entrance road from Pruitt Avenue. A majority of the subject property consists of unimproved grassland and other native vegetation. Pruitt Creek traverses through the central and northern portions of the subject property and a small east-west oriented channel is located on the southern portion.

According to available historical sources, the subject property was undeveloped or in use agriculturally as early as 1933 and developed with the current structure in 1978. The subject property and adjacent parcels to the west were first developed in the late 1950's by Fluor Corporation as an engineered wood product manufacturing facility. Since 1972, the facility has been occupied by Standard Structures Inc. (SSI). SSI owned and operated a laminated wood beam manufacturing facility from 1972 to 2012. The subject

property is now considered a separate parcel and is currently used for assembly of steel beams and modular portions of commercial structures. Tenants on the subject property have included Standard Structures Inc (1978-2012); JL Modular Inc (2016-Present); and Ahlborn Structural Steel Inc (2016-Present).

The immediately surrounding properties consist of Windsor Valero gas station to the north across Shiloh Road; Sonoma County Day School and a vineyard to the south; FedEx Ground to the southwest; vineyards and agricultural grassland to the east across Highway 101; and a multi-tenant industrial complex, Northgate Ready Mix, Elite Concrete, and Storage Pro Self Storage of Windsor to the west.

According to the March 29, 2013 Phase II Environmental Site Assessment report prepared by Hurvitz Environmental Services for the western adjacent property at 5900 Pruitt Avenue, groundwater was encountered at a depth of approximately 16 feet below ground surface (bgs). Based on topographic map interpretation, the direction of groundwater flow is inferred to be toward the west-northwest.

Findings

A *recognized environmental condition (REC)* refers to the presence or likely presence of any hazardous substances or petroleum products in, on, or at a property: due to release to the environment; under conditions indicative of a release to the environment; or under conditions that pose a material threat of a future release to the environment. The following was identified during the course of this assessment:

- Partner did not identify recognized environmental conditions during the course of this assessment.

A *controlled recognized environmental condition (CREC)* refers to a REC resulting from a past release of hazardous substances or petroleum products that has been addressed to the satisfaction of the applicable regulatory authority, with hazardous substances or petroleum products allowed to remain in place subject to the implementation of required controls. The following was identified during the course of this assessment:

- Partner did not identify controlled recognized environmental conditions during the course of this assessment.

A *historical recognized environmental condition (HREC)* refers to a past release of any hazardous substances or petroleum products that has occurred in connection with the property and has been addressed to the satisfaction of the applicable regulatory authority or meeting unrestricted use criteria established by a regulatory authority, without subjecting the property to any required controls. The following was identified during the course of this assessment:

- Partner reviewed a previous Phase 1 ESA for the subject property by Hurvitz Environmental Services Inc (HES) dated March 29, 2013. The assessment was performed on a larger parcel of land that included the subject property. According to the 2013 HES report, the subject property was formerly occupied by Standard Structures Inc (SSI) from 1978 to 2012 for industrial use. The subject property building was historically used for the manufacture of glue laminated trusses. According to a Site Screening performed at the site in 1991 by Ecology and Environment Inc, two glue wastewater settling ponds previously existed at the northwest end of the site (at least one of the former ponds is located onsite east of the subject building). The North Coast Regional Water Quality Control Board

(NCRWQCB) issued the facility waste discharge requirements under order # 74-83 in 1974 which prohibited the drainage of glue waste to any holding or disposal pond. SSI eliminated the use of the ponds at that time and added a decorative pond adjacent to the State Highway 101. In 1980, the NCRWQCB observed glue wastes being dumped into the on-site decorative pond. The pond and adjacent Pruitt Creek were sampled by the NCRWQCB on October 27, 1980. Phenol was present in the pond water and phenolic compounds were present in the pond soil. As a result, the NCRWQCB issued a Cleanup and Abatement Order (CAO) No 80-190 to the facility on October 1, 1980 to abate waste discharge to the pond and to remove the pond waste and close the pond. On June 3, 1981, the NCRWQCB rescinded the CAO under Order No. 81-140 because all cleanup and abatement activities were completed and had been assessed.

In January 1990, under the authority of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 (CERCLA) and the Superfund Amendments and Reauthorization Act of 1986 (SARA) the US Environmental Protection Agency (EPA) tasked Ecology and Environment, Inc's Field Investigation Team (FIT) to conduct a Screening Site Inspection of the Standard Structures site. During the Site Screening soil and groundwater samples were collected. The sample results were found to be inconclusive, and the final assessment concluded that further assessment was unnecessary. However, in 1991, the EPA revised the Hazard Ranking System (HRS) and asked Ecology and Environment Inc., to reassess the Standard Structures Site. The site re-assessment concluded that no further remedial action was to be planned under CERCLA. The basis for the assessment stated that the predominant hazardous substances utilized at SSI were phenol, resorcinol, methylene chloride, and paraformaldehyde, which all have low toxicity values. In addition, an observed release to groundwater had not been documented at the site.

Partner opines that although the CAO was rescinded and the EPA concluded that further remedial action was not required, if development of the property is to occur, evaluation of the soil within the vicinity of the former pond should be considered for characterization.

An *environmental issue* refers to environmental concerns identified by Partner, which do not qualify as RECs; however, warrant further discussion. The following was identified during the course of this assessment:

- Due to the age of the subject property building, there is a potential that asbestos-containing materials (ACM) are present. Overall, all suspect ACMs were observed in good condition and do not pose a health and safety concern to the occupants of the subject property at this time. Should these materials be replaced, the identified suspect ACMs would need to be sampled to confirm the presence or absence of asbestos prior to any renovation or demolition activities to prevent potential exposure to workers and/or building occupants.

Conclusions and Opinions

Partner has performed a Phase I ESA in conformance with the scope and limitations of ASTM Practice E1527-13 of 790 Shiloh Road in the City of Windsor, Sonoma County, California (the "subject property"). Any exceptions to, or deletions from, this practice are described in **Section 1.5** of this report.

This assessment has revealed evidence of a historical recognized environmental condition and environmental issues in connection with the subject property. Based on the conclusions of this assessment, Partner makes the following conclusions:

- An Operations and Maintenance (O&M) Program should be implemented in order to safely manage the suspect ACMs located at the subject property.
- Evaluation of the soil conditions within the vicinity of the former glue evaporation pond should be considered if development of the property is to occur.

TABLE OF CONTENTS

1.0 INTRODUCTION 1

1.1 Purpose 1
1.2 Scope of Work 1
1.3 Limitations 2
1.4 User Reliance 2
1.5 Limiting Conditions 3

2.0 SITE DESCRIPTION 4

2.1 Site Location and Legal Description 4
2.2 Current Property Use 4
2.3 Current Use of Adjacent Properties 4
2.4 Physical Setting Sources 5
2.4.1 Topography 5
2.4.2 Hydrology 5
2.4.3 Geology/Soils 5
2.4.4 Flood Zone Information 6

3.0 HISTORICAL INFORMATION 7

3.1 Aerial Photograph Review 7
3.2 Fire Insurance Maps 9
3.3 City Directories 9
3.4 Historical Topographic Maps 11

4.0 REGULATORY RECORDS REVIEW 13

4.1 Regulatory Agencies 13
4.1.1 Health Department 13
4.1.2 Fire Department 13
4.1.3 Air Pollution Control Agency 13
4.1.4 Regional Water Quality Agency 14
4.1.5 Department of Toxic Substances Control 14
4.1.6 Building Department 14
4.1.7 Planning Department 15
4.1.8 Oil & Gas Exploration 15
4.1.9 Assessor's Office 15
4.2 Mapped Database Records Search 15
4.2.1 Regulatory Database Summary 16
4.2.2 Subject Property Listings 16
4.2.3 Adjacent Property Listings 17
4.2.4 Sites of Concern Listings 19
4.2.5 Unplottable Listings 20

5.0 USER PROVIDED INFORMATION AND INTERVIEWS 21

5.1 Interviews 21
5.1.1 Interview with Owner 21
5.1.2 Interview with Report User 22
5.1.3 Interview with Key Site Manager 22
5.1.4 Interviews with Past Owners, Operators and Occupants 22

5.1.5 Interview with Others 22
5.2 User Provided Information 22
5.2.1 Title Records, Environmental Liens, and AULs 22
5.2.2 Specialized Knowledge 22
5.2.3 Actual Knowledge of the User 22
5.2.4 Valuation Reduction for Environmental Issues 22
5.2.5 Commonly Known or Reasonably Ascertainable Information 23
5.2.6 Previous Reports and Other Provided Documentation 23
6.0 SITE RECONNAISSANCE 26
6.1 General Site Characteristics 26
6.2 Potential Environmental Hazards 27
6.3 Non-ASTM Services 28
6.3.1 Asbestos-Containing Materials (ACMs) 28
6.3.2 Lead-Based Paint (LBP) 29
6.3.3 Radon 30
6.3.4 Lead in Drinking Water 30
6.3.5 Mold 30
6.4 Adjacent Property Reconnaissance 31
7.0 FINDINGS AND CONCLUSIONS 32
8.0 SIGNATURES OF ENVIRONMENTAL PROFESSIONALS 34
9.0 REFERENCES 35

Figures

Figure 1 Site Location Map
Figure 2 Site Plan
Figure 3 Topographic Map

Appendices

Appendix A Site Photographs
Appendix B Historical/Regulatory Documentation
Appendix C Regulatory Database Report
Appendix D Qualifications

1.0 INTRODUCTION

Partner Assessment Corporation (Partner) has performed a Phase I Environmental Site Assessment (ESA) in conformance with the scope and limitations of ASTM Standard Practice E1527-13 and the Environmental Protection Agency Standards and Practices for All Appropriate Inquiries (AAI) (40 CFR Part 312) for the property located at 790 Shiloh Road in the City of Windsor, Sonoma County, California (the "subject property"). Any exceptions to, or deletions from, this scope of work are described in the report.

1.1 Purpose

The purpose of this ESA is to identify existing or potential Recognized Environmental Conditions (as defined by ASTM Standard E1527-13) affecting the subject property that: 1) constitute or result in a material violation or a potential material violation of any applicable environmental law; 2) impose any material constraints on the operation of the subject property or require a material change in the use thereof; 3) require clean-up, remedial action or other response with respect to Hazardous Substances or Petroleum Products on or affecting the subject property under any applicable environmental law; 4) may affect the value of the subject property; and 5) may require specific actions to be performed with regard to such conditions and circumstances.

This ESA was performed to permit the *User* to satisfy one of the requirements to qualify for the innocent landowner, contiguous property owner, or bona fide prospective purchaser limitations on scope of Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) (42 U.S.C. §9601) liability (hereinafter, the "*landowner liability protections*," or "*LLPs*"). ASTM Standard E1527-13 constitutes "*all appropriate inquiry* into the previous ownership and uses of the *property* consistent with good commercial or customary practice" as defined at 42 U.S.C. §9601(35)(B).

1.2 Scope of Work

The scope of work for this ESA is in accordance with the requirements of ASTM Standard E1527-13. This assessment included: 1) a property and adjacent site reconnaissance; 2) interviews with key personnel; 3) a review of historical sources; 4) a review of regulatory agency records; and 5) a review of a regulatory database report provided by a third-party vendor. Partner contacted local agencies, such as environmental health departments, fire departments and building departments in order to determine any current and/or former hazardous substances usage, storage and/or releases of hazardous substances on the subject property. Additionally, Partner researched information on the presence of activity and use limitations (AULs) at these agencies. As defined by ASTM E1527-13, AULs are the legal or physical restrictions or limitations on the use of, or access to, a site or facility: 1) to reduce or eliminate potential exposure to hazardous substances or petroleum products in the soil or groundwater on the subject property; or 2) to prevent activities that could interfere with the effectiveness of a response action, in order to ensure maintenance of a condition of no significant risk to public health or the environment. These legal or physical restrictions, which may include institutional and/or engineering controls (IC/ECs), are intended to prevent adverse impacts to individuals or populations that may be exposed to hazardous substances and petroleum products in the soil or groundwater on the property.

1.3 Limitations

Partner warrants that the findings and conclusions contained herein were accomplished in accordance with the methodologies set forth in the Scope of Work. These methodologies are described as representing good commercial and customary practice for conducting an ESA of a property for the purpose of identifying recognized environmental conditions. There is a possibility that even with the proper application of these methodologies there may exist on the subject property conditions that could not be identified within the scope of the assessment or which were not reasonably identifiable from the available information. Partner believes that the information obtained from the record review and the interviews concerning the subject property is reliable. However, Partner cannot and does not warrant or guarantee that the information provided by these other sources is accurate or complete. The conclusions and findings set forth in this report are strictly limited in time and scope to the date of the evaluations. The conclusions presented in the report are based solely on the services described therein, and not on scientific tasks or procedures beyond the scope of agreed-upon services or the time and budgeting restraints imposed by the Client. No other warranties are implied or expressed.

Some of the information provided in this report is based upon personal interviews, and research of available documents, records, and maps held by the appropriate government and private agencies. This report is subject to the limitations of historical documentation, availability, and accuracy of pertinent records, and the personal recollections of those persons contacted.

This practice does not address requirements of any state or local laws or of any federal laws other than the all appropriate inquiry provisions of the LLPs. Further, this report does not intend to address all of the safety concerns, if any, associated with the subject property.

1.4 User Reliance

NYL Investors, LLC engaged Partner to perform this assessment in accordance with an agreement governing the nature, scope and purpose of the work as well as other matters critical to the engagement. All reports, both verbal and written, are for the sole use and benefit of NYL Investors, LLC and MNCVAD II-BIG SHILOH JV LLC, MNCVAD II-IND SHILOH CA LLC, McMorgan Northern California Value Add/Development Fund II, LP, NYL Investors NCVAD II GP, LLC, and the partners, members, managers, affiliates, successors and assigns of all the above named parties. Either verbally or in writing, third parties may come into possession of this report or all or part of the information generated as a result of this work. In the absence of a written agreement with Partner granting such rights, no third parties shall have rights of recourse or recovery whatsoever under any course of action against Partner, its officers, employees, vendors, successors or assigns. Any such unauthorized user shall be responsible to protect, indemnify and hold Partner, Client and their respective officers, employees, vendors, successors and assigns harmless from any and all claims, damages, losses, liabilities, expenses (including reasonable attorneys' fees) and costs attributable to such Use. Unauthorized use of this report shall constitute acceptance of and commitment to these responsibilities, which shall be irrevocable and shall apply regardless of the cause of action or legal theory pled or asserted. Additional legal penalties may apply.

This report has been completed under specific Terms and Conditions relating to scope, relying parties, limitations of liability, indemnification, dispute resolution, and other factors relevant to any reliance on this report. Any parties relying on this report do so having accepted Partner's standard Terms and Conditions, a copy of which can be found at http: / www.partneresi.com/terms-and-conditions.php.

1.5 Limiting Conditions

The findings and conclusions contain all of the limitations inherent in these methodologies that are referred to in ASTM E1527-13.

Specific limitations and exceptions to this ESA are more specifically set forth below:

- Interviews with past owners, operators and occupants were not reasonably ascertainable and thus constitute a data gap. Based on information obtained from other historical sources (as discussed in **Section 3.0**), this data gap is not expected to alter the findings of this assessment.
- Partner's view of the ground in the vacant portions of the property during the site assessment was obstructed due to dense vegetation. Based on information obtained from other historical sources, this limitation is not expected to alter the overall findings of this assessment.

2.0 SITE DESCRIPTION

2.1 Site Location and Legal Description

The subject property at 790 Shiloh Road in Windsor, California is located on the south side of Shiloh Road and the west side of Highway 101. According to the Sonoma County Assessor, the subject property is identified as Assessor Parcel Number (APN) 059-271-095, and ownership has been vested in Standard Industrial East LLC since 2013.

Please refer to **Figure 1: Site Location Map, Figure 2: Site Plan, Figure 3: Topographic Map**, and **Appendix A: Site Photographs** for the location and site characteristics of the subject property.

2.2 Current Property Use

The subject property is predominantly vacant land. An industrial building currently occupied by JL Modular Inc and Ahlborn Structural Steel Inc is located on the western border. Onsite operations consist of sanding, painting, welding, and assembly of steel beams and modular portions of commercial structures, typical administrative office activities, and general equipment maintenance. Bridge cranes are located within the building and adjacent to the south of the building. A propane above ground storage tank (AST) is located adjacent to the west of the building. Access is provided via a gravel entrance road from Pruitt Avenue. A majority of the subject property consists of unimproved grassland and other native vegetation. Pruitt Creek traverses through the central and northern portions of the subject property and a small east-west oriented channel is located on the southern portion.

The subject property is designated for heavy industrial, light industrial, and gateway commercial development by the Town of Windsor.

The subject property was identified as a California Environmental Reporting System Hazardous Waste (CERS HAZ), Certified Unified Program Agency (CUPA) Sonoma, Toxic Pollutant Emissions Facilities (Emissions), and Resource Conservation and Recovery Act (RCRA) Non-Generator/No Longer Regulated (NON-GEN) site in the regulatory database report, as further discussed in **Section 4.2**.

2.3 Current Use of Adjacent Properties

The subject property is located within a mixed industrial, commercial, and agricultural area of Sonoma County. During the vicinity reconnaissance, Partner observed the following land use on properties in the immediate vicinity of the subject property:

Immediately Surrounding Properties	
North:	Shiloh Road beyond which is Windsor Valero gas station (705 Shiloh Road)
South:	Sonoma County Day School (4400 Day School Place) and a vineyard; FedEx Ground warehouse to the southwest (500 Caletti Avenue)
East:	Highway 101 beyond which are vineyards and agricultural grassland
West:	A multi-tenant industrial complex (5900 Pruitt Avenue); Northgate Ready Mix (5922 Pruitt Avenue); Elite Concrete (5885 Pruitt Avenue); and Storage Pro Self Storage of Windsor (200 Caletti Avenue)

The adjacent properties were identified as Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS), CERCLIS No Further Remedial Action Planned (NFRAP), Deed Restrictions and Land Use Restrictions (DEED), RCRA Small Quantity Generator (SQG), RCRA Large Quantity Generator (LQG), RCRA Non-Corrective Action (TSD), RCRA NON-GEN, Delisted Hazardous Waste Facility (HAZ), Emissions, Facility Index and Registry System (FINDS/FRS), Facility and Manifest Data (HAZNET), Hazardous Materials Information Reporting System (HMIRS), Solid Waste Information System (SWF/LF), CERS Tank (TANK), Leaking Underground Storage Tank (LUST), Underground Storage Tank (UST), Local Oversight Program (LOP) Sonoma, Delisted Tank (TNK), and Delisted County, sites in the regulatory database report of **Section 4.2**.

2.4 Physical Setting Sources

2.4.1 Topography

The United States Geological Survey (USGS) *Healdsburg, California* Quadrangle 7.5-minute series topographic map was reviewed for this ESA. According to the contour lines on the topographic map, the subject property is located at approximately 120 feet above mean sea level (MSL). The contour lines in the area of the subject property indicate the area is sloping toward the northwest.

A copy of the most recent topographic map is included as **Figure 3** of this report.

2.4.2 Hydrology

According to the March 29, 2013 Phase II Environmental Site Assessment report prepared by Hurvitz Environmental Services for the western adjacent property at 5900 Pruitt Avenue, groundwater was encountered at a depth of approximately 16 feet below ground surface (bgs). Based on topographic map interpretation, the direction of groundwater flow is inferred to be toward the west-northwest.

Pruitt Creek traverses through the central and northern portions of the subject property and a small east-west oriented channel is located on the southern portion.

No settling ponds, lagoons, surface impoundments, wetlands or natural catch basins were observed at the subject property during this assessment.

According to available information, a public water system operated by the Town of Windsor serves the subject property vicinity. According to a representative, shallow groundwater beneath the subject property is not utilized for domestic purposes. The sources of public water for Windsor are groundwater from wells near the Russian River and is purchased from the Sonoma County Water Agency.

2.4.3 Geology/Soils

The subject property is situated within the Coastal Ranges physiographic province of the State of California. The Coast Ranges are northwest-trending mountain ranges (2,000 to 4,000, occasionally 6,000 feet elevation above sea level), and valleys. The ranges and valleys trend northwest, subparallel to the San Andreas Fault. Strata dip beneath alluvium of the Great Valley. To the west is the Pacific Ocean. The coastline is uplifted, terraced and wave-cut. The Coast Ranges are composed of thick Mesozoic and Cenozoic sedimentary strata. The northern and southern ranges are separated by a depression containing the Mountain View Bay. The

northern Coast Ranges are dominated by irregular, knobby, landslide-topography of the Franciscan Complex. The eastern border is characterized by strike-ridges and valleys in Upper Mesozoic strata. In several areas, Franciscan rocks are overlain by volcanic cones and flows of the Quien Sabe, Sonoma and Clear Lake volcanic fields. The Coast Ranges are subparallel to the active San Andreas Fault. The San Andreas is more than 600 miles long, extending from Pt. Arena to the Gulf of California. West of the San Andreas is the Salinian Block, a granitic core extending from the southern extremity of the Coast Ranges to the north of the Farallon Islands.

Based on information obtained from the USDA Natural Resources Conservation Service Web Soil Survey online database, the subject property is mapped as Clear Lake Clay and Huichica loam. This profile consists of loam at shallow depths and clay at greater depths. The soils are moderately well drained, and the runoff class is listed as "very high". The soils formed on terraces from alluvium derived from igneous, metamorphic, and sedimentary rock. Slopes range from 0 to 5 percent.

2.4.4 Flood Zone Information

Partner performed a review of the Flood Insurance Rate Map, published by the Federal Emergency Management Agency. According to Community Panel Numbers 06097C0568E and 06097C0568E, dated December 2, 2008, the subject property appears to be located in Zones AE, Zone X, and a Regulatory Floodway.

A copy of the reviewed flood map is included in **Appendix B** of this report.

3.0 HISTORICAL INFORMATION

Partner obtained historical use information about the subject property from a variety of sources. A chronological listing of the historical data found is summarized in the table below:

Historical Use Information		
Period/Date	**Source**	**Description/Use**
1933-1976	Topographic Maps, Aerial Photographs	Undeveloped/Agricultural Land
1978-Present	Topographic Maps, Aerial Photographs, City Directories, Previous Report, Interviews, On-Site Observations	Industrial

Tenants on the subject property include Standard Structures Inc (1978-2012); JL Modular Inc (2016-Present); and Ahlborn Structural Steel Inc (2016-Present). Potential environmental concerns were identified in association with the former use of the subject property, as further discussed in **Section 5.2.6**.

3.1 Aerial Photograph Review

Partner obtained available aerial photographs of the subject property and surrounding area from Environmental Risk Information Services (ERIS) on November 17, 2021. The following observations were noted to be visible on the subject property and adjacent properties during the aerial photograph review:

Date: 1942	***Scale: 1"=500'***
Subject Property:	Appears to be undeveloped land with agricultural row crops developed in the southwestern portion of the subject property; there appears to be a creek running through the northern portion of the subject property and a channel running east-west through the southern portion of the subject property.
North:	Appears to be both undeveloped land and agricultural land across a road
South:	Appears to be developed with agricultural row crops
East:	Appears to be undeveloped land
West:	Appears to be undeveloped land

Date: 1952	***Scale: 1"=500'***
Subject Property:	Appears to be mostly undeveloped land with a creek running through the northern portion of the subject property; a small portion of the northern sliver of land appears to be agricultural grassland; the southern portion appears to be agricultural land across an east-west oriented channel
North:	No significant changes visible
South:	No significant changes visible
East:	No significant changes visible
West:	Appears to be undeveloped land with some agricultural grassland beyond which is developed with a large industrial yard with multiple industrial buildings and outdoor storage areas possibly used for lumber manufacturing

Date: 1956	***Scale: 1"=500'***
Subject Property:	No significant changes visible
North:	No significant changes visible
South:	No significant changes visible

Date: 1956	***Scale: 1"=500'***
East:	Appears to be mostly undeveloped land with some agricultural land to the southeast
West:	Appears to be cleared land beyond which is a large industrial complex with multiple industrial buildings, roadways, storage yards, etc.

Date: 1965	***Scale: 1"=500'***
Subject Property:	No significant changes visible
North:	Appears to be developed with multiple highway entrance and exit roadways along a road
South:	No significant changes visible
East:	Appears to be agricultural grassland across a major highway
West:	The industrial complex has expanded and now extends to the adjacent property to the west which appears to be developed with a large industrial building and associated storage yards

Date: 1968	***Scale: 1"=500'***
Subject Property:	No significant changes visible
North:	Appears to be developed with a commercial building across a road
South:	No significant changes visible
East:	No significant changes visible
West:	No significant changes visible

Date: 1973, 1976	***Scale: 1"=500'***
Subject Property:	No significant changes visible other than what appears to be a tower or cylindrical structure in the center of the property
North:	No significant changes visible
South:	No significant changes visible
East:	No significant changes visible
West:	The industrial property appears to be developed with additional storage yards abutting the subject property and artificial surface water ponds

Date: 1983, 1993	***Scale: 1"=500'***
Subject Property:	Appears to be mostly vacant/cleared land with an industrial building developed on the southwest portion of the property; there appears to be large pond located adjacent to the northeast of the building; the tower is no longer visible
North:	No significant changes visible
South:	No significant changes visible
East:	No significant changes visible
West:	No significant changes visible

Date: 1998	***Scale: 1"=500'***
Subject Property:	No significant changes visible; the pond is no longer visible
North:	No significant changes visible
South:	No significant changes visible

Date: 1998		*Scale: 1"=500'*
East:	No significant changes visible	
West:	No significant changes visible	

Date: 2004, 2005, 2006		*Scale: 1"=500'*
Subject Property:	No significant changes visible	
North:	No significant changes visible	
South:	Appears to be developed with a vineyard and recreational complex or school	
East:	No significant changes visible	
West:	No significant changes visible	

Date: 2009, 2010, 2012, 2014, 2016		*Scale: 1"=500'*
Subject Property:	No significant changes visible	
North:	No significant changes visible	
South:	No significant changes visible; a large commercial warehouse appears to be developed to the southwest	
East:	No significant changes visible	
West:	The artificial ponds in the southern portion of the property are no longer visible	

Date:		*Scale: 1"=500'*
Subject Property:	The northernmost portion of the property appears to be developed with a storage yard	
North:	No significant changes visible	
South:	No significant changes visible	
East:	No significant changes visible	
West:	No significant changes visible	

Date: 2018, 2020		*Scale: 1"=500'*
Subject Property:	No significant changes visible	
North:	No significant changes visible	
South:	No significant changes depicted	
East:	No significant changes visible	
West:	The artificial pond adjacent to the east of the large industrial building appears to be filled with dirt for alternative industrial use	

Copies of select aerial photographs are included in **Appendix B** of this report.

3.2 Fire Insurance Maps

Partner requested Fire Insurance Maps from ERIS on November 18, 2021. Fire Insurance Maps were not available for the subject property.

A copy of the ERIS Fire Insurance Map cover sheet is included in **Appendix B** of this report.

3.3 City Directories

Partner reviewed historical city directories obtained from ERIS on November 23, 2021 for past names and businesses that were listed for the subject property and adjacent properties. The findings are presented in the following table:

City Directory Search for 790 Shiloh Road and 5937 Pruitt Avenue (Subject Property)

Year(s)	Occupant Listed
1972	Subject property addresses not listed
1975	Subject property addresses not listed
1981	Subject property addresses not listed
1985	Subject property addresses not listed
1990	Subject property addresses not listed
1995	Subject property addresses not listed
2000	Subject property addresses not listed
2006	Subject property addresses not listed
2008	Subject property addresses not listed
2012	Subject property addresses not listed
2016	**JL Modular Inc** (5937 Pruitt Avenue)
2020	**JL Modular Inc** (5937 Pruitt Avenue)

According to the city directory review, the subject property has been occupied JL Modular Inc for industrial use since 2016.

City Directory Search for Adjacent Properties

Year(s)	Occupant Listed
1972	Vernon E Ford (705 Shiloh Road)
1975	**Sturgis & Sons MBL SV** (705 Shiloh Road)
1981	Patricia D Murphy (705 Shiloh Road)
1985	XXXX (705 Shiloh Road)
1990	**Vics Autowtv Rpr** (701 Shiloh Road); XXXX (705 Shiloh Road)
1995	XXXX (701 Shiloh Road)
2000	XXXX (701 Shiloh Road)
2006	Nitin Desai (705 Shiloh Road)
2008	**Standard Structures**, Windsor Presbyterian Church (5900 Pruitt Avenue)
2012	Windsor Presbyterian Church (5891 Pruitt Avenue); **Standard Structures**, Winewood Products (5900 Pruitt Avenue); Northgate Ready Mix (5922 Pruitt Avenue)
2016	SBKW Concrete Inc (5885 Pruitt Avenue); Pacific Crest Fence Co, **Standard Industrial East** (5897 Pruitt Avenue); Alpine Spring Distributing, Big Shots Screen Printing, Cali Kustomz, Dennis Grove Concrete Pumping, Olde World Workshops, Reynolds Packaging Kama, Sonoma Soil Builders, **Standard Structures**, True Liberty Bags, **Vintage Performance**, Western Tree (5900 Pruitt Avenue); Northgate Ready Mix (5922 Pruitt Avenue)
2020	Elite Concrete Construction Inc (5873 Pruitt Avenue); SBKW Concrete Inc (5885 Pruitt Avenue); Investments Soco (5892 Pruitt Avenue); Dennis Grove Concrete Pumping, Disel Performance Allied, **New Metal Coachworks LLC**, North Bay Bottling, Reynolds Packaging Kama, Sonoma Soil Builders, True Liberty Bags, **Vintage Performance**, Western Tree (5900 Pruitt Avenue); Standard Industrial East LLC, Northgate Ready Mix (5922 Pruitt Avenue)

* XXXX= A phone number is present but is not registered to a tenant or is disconnected.

According to the city directory review, the adjacent properties have been occupied by various industrial tenants since at least 2008 and auto service and repair facilities since 1975.

Copies of reviewed city directories are included in **Appendix B** of this report.

3.4 Historical Topographic Maps

Partner reviewed historical topographic maps obtained from ERIS on November 18, 2021. The following observations were noted to be depicted on the subject property and adjacent properties during the topographic map review:

Date: 1933, 1940	
Subject Property:	Depicted as undeveloped land
North:	Depicted as undeveloped land across a road
South:	Depicted as undeveloped land
East:	Depicted as undeveloped land
West:	Depicted as undeveloped land

Date: 1955	
Subject Property:	No significant changes depicted
North:	Depicted with three dwellings or agricultural buildings across Shiloh Road
South:	No significant changes depicted
East:	No significant changes depicted
West:	Depicted as mostly undeveloped land with seven structures adjacent to the west of the northern portion of the subject property beyond which is a larger industrial building

Date: 1980	
Subject Property:	No significant changes depicted
North:	Depicted as mostly undeveloped land with a highway on-ramp and exit road across Shiloh Road
South:	No significant changes depicted
East:	Depicted as undeveloped land across a major highway
West:	Depicted as developed with a large industrial building, two smaller industrial structures, and associated railroad inlet

Date: 1993	
Subject Property:	Depicted as developed with an industrial building and surface pond in the central region of property
North:	Depicted with a small building across Shiloh Road and depicted with a highway on-ramp and exit
South:	Partially as partial agricultural orchard
East:	Partially depicted as agricultural orchard across Highway 101
West:	Depicted as developed with additional industrial buildings and associated roads and surface ponds

Date: 2015	
Subject Property:	Site specific features are not depicted; existing roads and water features are depicted
North:	Site specific features are not depicted; existing roads are depicted
South:	Site specific features are not depicted except for the depiction of a school

Date:	***2015***
East:	Site specific features are not depicted; the existing Highway 101 is depicted
West:	Site specific features are not depicted; existing roads and water features are depicted

Copies of reviewed topographic maps are included in **Appendix B** of this report.

4.0 REGULATORY RECORDS REVIEW

4.1 Regulatory Agencies

4.1.1 Health Department

Regulatory Agency Data	
Name of Agency:	Sonoma County Environmental Health Services (SCEHS) Sonoma County Hazardous Materials (HAZMAT)
Point of Contact:	Administrative Personnel
Agency Address:	625 5th Street, Santa Rosa, California
Agency Phone Number:	(707) 565-6565
Date of Contact:	November 23, 2021
Method of Communication:	Email/Online
Summary of Communication:	No records regarding hazardous substance use, storage or releases, or the presence of USTs and AULs on the subject property were on file with the SCEHS of Sonoma County HAZMAT.

4.1.2 Fire Department

Regulatory Agency Data	
Name of Agency:	Sonoma Fire Prevention Division (SFPD)
Point of Contact:	Nicole Watson
Agency Address:	2300 County Center Drive #B220, Santa Rosa, California
Agency Phone Number:	(707) 565-3707
Date of Contact:	November 23, 2021
Method of Communication:	Email
Summary of Communication:	No records regarding hazardous substance use, storage or releases, or the presence of USTs and AULs on the subject property were on file with the SFPD.

4.1.3 Air Pollution Control Agency

Regulatory Agency Data	
Name of Agency:	Bay Area Air Quality Management Division (BAAQMD)
Point of Contact:	Rochele Henderson
Agency Address:	375 Beale Street, Suite 600, San Francisco, California
Agency Phone Number:	(415) 516-1916
Date of Contact:	November 17, 2021
Method of Communication:	Email
Summary of Communication:	No Permits to Operate (PTO), Notices of Violation (NOV), or Notices to Comply (NTC) or the presence of AULs, dry cleaning machines, or USTs were on file for the subject property with the BAAQMD.

4.1.4 Regional Water Quality Agency

Regulatory Agency Data	
Name of Agency:	Regional Water Quality Control Board (RWQCB)
Point of Contact:	https://geotracker.waterboards.ca.gov/
Agency Address:	1001 I Street, Sacramento, California
Agency Phone Number:	(916) 341-5263
Date of Contact:	November 17, 2021
Method of Communication:	Online
Summary of Communication:	No records regarding hazardous substance use, storage or releases, or the presence of USTs and AULs on the subject property were on file with the RWQCB.

4.1.5 Department of Toxic Substances Control

Regulatory Agency Data	
Name of Agency:	California Department of Toxic Substances Control (DTSC)
Point of Contact:	https://hwts.dtsc.ca.gov/ https://www.envirostor.dtsc.ca.gov/public/
Agency Address:	1001 I Street, Sacramento, California
Agency Phone Number:	(916) 324-1826
Date of Contact:	November 17, 2021
Method of Communication:	Online
Summary of Communication:	According to records reviewed, hazardous waste manifests are on file with the DTSC for Ahlborn Structural Steel and Standard Structures Inc in relation to industrial use on the subject property and adjacent property to the west as further discussed in Section 4.2.

4.1.6 Building Department

Regulatory Agency Data	
Name of Agency:	Windsor Building Department (WBD)
Point of Contact:	Courtney Rider
Agency Address:	9291 Old Redwood Highway Bldg. 400, Windsor, California
Agency Phone Number:	(707) 838-1105
Date of Contact:	November 18, 2021
Method of Communication:	Email
Summary of Communication:	Records were available for review, as further discussed in the following table.

Building Records Reviewed for 790 Shiloh Road and 5937 Pruitt Avenue (Subject Property)

Year(s)	Owner/Applicant	Description
2009	Caletti, Richard C & Floramay	Replace two existing T-Mobile antennas
2009	Caletti, Richard C & Floramay	Inspection report for antenna replacement
2010	Caletti, Richard C & Floramay	Install fiber box (E) cell facility
2010	Caletti, Richard C & Floramay	Inspection report for fiber box

4.1.7 Planning Department

Regulatory Agency Data	
Name of Agency:	Windsor Planning Division (WPD)
Point of Contact:	https://www.townofwindsor.com/173/Planning-Division
Agency Address:	9291 Old Redwood Highway, Windsor, California
Agency Phone Number:	(707) 838-1021
Date of Contact:	November 17, 2021
Method of Communication:	Online
Summary of Communication:	According to records reviewed, the subject property is zoned IH for heavy industrial, IL for light industrial, and CG for gateway commercial development by the Town of Windsor.

4.1.8 Oil & Gas Exploration

Regulatory Agency Data	
Name of Agency:	California Geologic and Energy Management Division (CalGEM)
Point of Contact:	https://maps.conservation.ca.gov/doggr/wellfinder/
Agency Address:	801 K Street, MS 18-05, Sacramento, California
Agency Phone Number:	(916) 445-9686
Date of Contact:	November 17, 2021
Method of Communication:	Online
Summary of Communication:	According to CalGEM, no oil or gas wells are located on or adjacent to the subject property.

4.1.9 Assessor's Office

Regulatory Agency Data	
Name of Agency:	Sonoma County Assessor
Point of Contact:	https://gis-sonomacounty.hub.arcgis.com/
Agency Address:	585 Fiscal Drive #104F, Santa Rosa, California
Agency Phone Number:	(707) 565-1888
Date of Contact:	November 17, 2021
Method of Communication:	Online
Summary of Communication:	According to records reviewed, the subject property is identified by Assessor Parcel Number (APN) 059-271-095 and is currently owned by Standard Industrial East LLC. The current building was constructed in 1978 and totals approximately 45,200 square feet on a 45.1-acre lot.

A copy of pertinent documents is included in **Appendix B** of this report.

4.2 Mapped Database Records Search

Information from standard federal, state, county, and city environmental record sources was provided by ERIS. Data from governmental agency lists are updated and integrated into one database, which is updated as these data are released. The information contained in this report was compiled from publicly available sources and the locations of the sites are plotted utilizing a geographic information system, which geocodes the site addresses. The accuracy of the geocoded locations is approximately +/-300 feet.

Using the ASTM definition of migration, Partner considers the migration of hazardous substances or petroleum products in any form onto the subject property during the evaluation of each site listed on the radius report, which includes solid, liquid, and vapor.

4.2.1 Regulatory Database Summary

Radius Report Data				
Database	**Search Radius (mile)**	**Subject Property**	**Adjacent Properties**	**Sites of Concern**
Federal NPL or Delisted NPL Site	1.00	N	N	N
Federal CERCLIS Site	0.50	N	**Y**	N
Federal CERCLIS-NFRAP Site	0.50	N	**Y**	N
Federal RCRA CORRACTS Facility	1.00	N	N	N
Federal RCRA TSDF Facility	0.50	N	N	N
Federal RCRA Generators Site (LQG, SQG, CESQG)	0.25	N	**Y**	N
Federal IC/EC Registries	0.50	N	N	N
Federal ERNS Site	Subject Property	N	N	N
State/Tribal Equivalent NPL	1.00	N	N	N
State/Tribal Equivalent CERCLIS	1.00	N	N	N
State/Tribal Landfill/Solid Waste Disposal Site	0.50	N	N	N
State/Tribal Leaking Storage Tank Site	0.50	N	**Y**	N
State/Tribal Registered Storage Tank Sites (UST/AST)	0.25	N	**Y**	N
State/Tribal Voluntary Cleanup Sites (VCP)	0.50	N	N	N
State/Tribal Spills	0.50	N	N	N
Federal Brownfield Sites	0.50	N	N	N
State Brownfield Sites	0.50	N	N	N
CERS HAZ	0.125	**Y**	**Y**	N
CUPA Sonoma, Emissions, RCRA NON-GEN	0.25	**Y**	**Y**	N
FINDS/FRS	Subject Property	N	**Y**	N
HMIRS	0.125	N	**Y**	N
RCRA-TSD, SWF/LF, DEED, LOP Sonoma	0.50	N	**Y**	N
CERS TANK, Delisted TNK	0.25	N	**Y**	N

4.2.2 Subject Property Listings

The subject property is identified as a CERS HAZ, CUPA Sonoma, Emissions, and RCRA NON-GEN site in the regulatory database report, as discussed below:

- **Ahlborn Structural Steel Inc** at 5937 Pruitt Avenue, is registered in the CERS HAZ database as a chemical storage facility. Four violations were issued in 2017 for failing to submit administrative documentation associated with the hazardous waste generated on the subject property. These violations were returned to compliance in 2018. A second inspection was conducted in May of 2021 with no violations reported. This facility is also listed in the Sonoma CUPA database for an active

stormwater permit. No further information is provided. Additionally, this facility was verified as a non-generator of hazardous waste in 2020 with an EPA identification number CAL000456688. According to information available in the California DTSC Hazardous Waste Tracking System (HWTS) online database, this facility is described with the NAICS code 332323 for "ornamental and architectural metal work manufacturing". In 2021, approximately one ton of hazardous waste with a waste code description "oxygenated solvent" was transferred offsite. Based on the regulatory oversite, the non-generator status, the absence of any outstanding violations or releases, this listing is not expected to represent an environmental concern.

4.2.3 Adjacent Property Listings

The adjacent property to the west is identified as a CERCLIS, CERCLIS-NFRAP, DEED, CUPA Sonoma, RCRA-SQG, RCRA-LQG, RCRA-TSD, RCRA NON-GEN, Delisted HAZ, Emissions, FINDS/FRS, HAZNET, HMIRS, SWF/LF, and CERS TANK site in the regulatory database report, as discussed below:

- The property, identified as **Standard Structures Inc/Carl's Ready Mix** at 920 Shiloh Road and 340 Standard Avenue, is located adjacent to the west of the subject property and situated hydrologically down-gradient. This site is listed in the HMIRS database for a leaking package that was unloaded from a FedEx truck at the property in 2002. The package was examined, and it was determined that a small leak of liquid containing nitric acid was contained within the package. The undamaged portion of the packaged was returned to the carrier and the contents of the package were safely secured with no contamination reported at the site. This facility was registered in the HAZNET database from 1996 to 2011 with the EPA identification number CAL00160715. During this time, this facility was listed as a hazardous waste generator with waste code descriptions including unspecified solvent mixture, asbestos containing waste, waste oil and mixed oil, oil/water separation sludge, unspecified oil-containing waste, polychlorinated biphenyls, polymeric resin waste, latex waste, unspecified organic liquid mixture, laboratory waste chemicals, liquids with halogenated organic compounds, and other organic waste. Additionally, this facility is listed as a small quantity generator of ignitable waste, benzene, trichloroethylene, and tetrachloroethylene in 2003. Since 2015, this facility has been delisted from as a generator of hazardous waste. Based on the absence of any violations or releases, the delisted status, and the down-gradient position relative to the subject property, this listing is not expected to represent an environmental concern.
- The property, identified as **Shiloh Oaks Company** at 5900 Pruitt Avenue, is located adjacent to the west of the subject property and situated hydrologically down-gradient. This listing includes the industrial and light industrial tenants that currently occupy and have historically occupied this facility. Multiple hazardous material incident reports were issued in 2007 to 2008 in which delivered packages were found to contain leaking containers of hazardous materials. None of these incidents reported in a release to the subsurface at the property. Packages were safely secured and returned to the carrier. In 2013, Hurvitz Environmental Services (HES) performed a Phase II Environmental Site Assessment in which the onsite irrigation well was sampled for total petroleum hydrocarbons as gasoline, diesel, motor oil, benzene, toluene, ethylbenzene, xylenes, methyl tert butyl ether,

formaldehyde, chromium VI, lead, phenols, and polynuclear aromatic hydrocarbons. Results were reported to be below detectable limits.

In 2016, Engineering Fire and Environmental Services (EFI Global) performed a Phase II subsurface investigation in which soil, soil vapor, and groundwater sampling was conducted to evaluate if the former presence of a sewage collection pond and fire pond, as well as the historical chlorinated solvent usage from the 1950s until 2012 resulted in a significant release of volatile organic compounds (VOCs), petroleum hydrocarbons, and toxic metals to the subsurface. EFI Global stated that the southwest portion of the site had been impacted by petroleum hydrocarbons. An additional subsurface investigation was performed by ERC in 2017. Further soil and groundwater samples in the southwest portion of the property were analyzed for petroleum hydrocarbons and VOCs. ERC stated that on-site contamination of petroleum hydrocarbons was localized in the southwest corner of the property. Groundwater in this localized area contained low residual concentrations of petroleum hydrocarbons and VOCs. The NCRWQCB issued a no further action in 2017 stating that an environmental covenant be issued restricting groundwater use in the limited area of impact. Based on the analytical results, regulatory oversight with no further action recommended, and down-gradient position relative to the subject property, this listing is not expected to represent an environmental concern.

- The property, identified as **Northgate Ready Mix** at 5922 Pruitt Avenue, is located adjacent to the west of the subject property and situated hydrologically down-gradient. This facility is registered as a hazardous waste generator and chemical storage facility equipped with a 3,000-gallon aboveground petroleum storage tank in the CERS database. Multiple violations were issued in 2013, 2016, and 2018 for failing to properly label hazardous waste containers and to properly submit proper documentation related to hazardous material generation and storage. Violations have since been returned to compliance and the most recent inspection, performed in 2018, reported no violations. This site was delisted from the California EPA database in 2018. Based on the absence of outstanding violations or releases, the delisted status, and the down-gradient position in relation to the subject property, this listing is not expected to represent an environmental concern.
- The property, identified as **SMCI Windsor Fire Remediation Processing/SMCI Windsor Receiving Yard** at 5885 Pruitt Avenue, is located adjacent to the west of the subject property and situated hydrologically down-gradient. This facility is registered as a solid waste composting facility in which on-site operations consist of chipping and grinding wood waste and green materials. There appears to be no violations or releases associated with this listing. Based on the nature of onsite operations, the absence of any violations or releases, and the down-gradient position in relation to the subject property, this listing is not expected to represent an environmental concern.

The adjacent property to the north is identified as a CERS TANK, Delisted TNK, CUPA Sonoma, Delisted County, Emissions, LOP Sonoma, LUST, UST, and RCRA NON-GEN site in the regulatory database report, as discussed below:

- The property, identified as **Exxon Mobil Oil Corporation/Salkhi Petroleum Inc/Windsor Valero/Shiloh Union 76 Gas Station/B & B Service Station/Mobil Station (Former)** at 705 Shiloh Road, is located adjacent to the north of the subject property, across Shiloh Road and is situated hydrologically cross-gradient. Since 1968, this location has been occupied by a variety of businesses including an auto repair facility, a towing company, and electrical contractor. The site is currently occupied by Windsor Valero gasoline service station. In 1987 a 350-gallon used-oil UST, a 10,000-gallon UST, and an 8,000-gallon UST were removed from the site. Approximately 100-cubic yards of soil were excavated from the UST pit and removed. In 2003, groundwater containing concentrations of total petroleum hydrocarbons as gas, methyl tert butyl ether, and benzene was removed. Groundwater and soil removal continued until 2010. In 2013, the Sonoma County Department of Health Services closed the case with no further action recommended. The location is currently occupied by Windsor Valero gasoline service station and is registered in the UST and CERS TANK databases. Information related to the number of USTs on-site, the tank construction, capacity, and date of installation are not provided. Multiple inspections were conducted from 2013 to 2021. Multiple violations were issued related to the administrative documentation and secondary containment equipment associated with the USTs on-site. No violations were issued during the most recent inspection conducted on February 23, 2021. Based on the absence of any outstanding violations or releases, the regulatory oversight and case closure with no further action recommended, and the cross-gradient position in relation to the subject property, this listing is not expected to represent an environmental concern.

The property to the southwest is identified as a CERS HAZ, CUPA Sonoma, HMIRS, and RCRA-SQG in the regulatory database report, as discussed below:

- The property, identified as **FedEX Ground Package System Inc** at 500 Caletti Avenue, is located adjacent to the southwest of the subject property and situated hydrologically down-gradient. This facility is registered as a small-quantity generator of hazardous waste including VOCs and petroleum hydrocarbons. Multiple violations were issued in 2013 and 2020 related to the administrative documentation of hazardous waste storage on the property. These violations have since been returned to compliance. Multiple hazardous material incidents occurred from 2008 to 2016 in which packages containing leaking containers were delivered or handled at the facility. Spills were either contained inside the packages or immediately contained and cleaned on-site with no releases to the subsurface at the property. Based on the small quantity of hazardous waste generated, the absence of outstanding violations or releases, the regulatory oversite, and the down-gradient position in relation to the subject property, this listing is not expected to represent an environmental concern.

Based on the findings, vapor migration is not expected to represent an environmental concern at this time.

4.2.4 Sites of Concern Listings

No sites of concern are identified in the regulatory database report.

Based on the findings, vapor migration not expected to represent an environmental concern at this time.

4.2.5 Unplottable Listings

The property to the west is identified as a CERCLIS site in the regulatory database report, as previously discussed in **Section 4.2.3**.

A copy of the regulatory database report is included in **Appendix C** of this report.

5.0 USER PROVIDED INFORMATION AND INTERVIEWS

In order to qualify for one of the *Landowner Liability Protections (LLPs)* offered by the Small Business Liability Relief and Brownfields Revitalization Act of 2001 (the *Brownfields Amendments*), the *User* must conduct the following inquiries required by 40 CFR 312.25, 312.28, 312.29, 312.30, and 312.31. The *User* should provide the following information to the *environmental professional*. Failure to provide this information could result in a determination that *all appropriate inquiries* is not complete. The *User* is asked to provide information or knowledge of the following:

- Review Title and Judicial Records for Environmental Liens and AULs
- Specialized Knowledge or Experience of the User
- Actual Knowledge of the User
- Reason for Significantly Lower Purchase Price
- Commonly Known or *Reasonably Ascertainable* information
- Degree of Obviousness
- Reason for Preparation of this Phase I ESA

Fulfillment of these user responsibilities is key to qualification for the identified defenses to CERCLA liability. Partner requested our Client to provide information to satisfy User Responsibilities as identified in Section 6 of the ASTM guidance.

Pursuant to ASTM E1527-13, Partner requested the following site information from NYL Investors, LLC (User of this report).

User Responsibilities				
Item	**Provided By User**	**Not Provided By User**	**Discussed Below**	**Does Not Apply**
Environmental Pre-Survey Questionnaire			**X**	
Title Records, Environmental Liens, and AULs			**X**	
Specialized Knowledge			**X**	
Actual Knowledge			**X**	
Valuation Reduction for Environmental Issues			**X**	
Identification of Key Site Manager	**Section 5.1.3**			
Reason for Performing Phase I ESA	**Section 1.1**			
Prior Environmental Reports			**X**	
Other				**X**

5.1 Interviews

5.1.1 Interview with Owner

Please see **Sections 5.1.3** and **5.1.5** for information provided by subject property personnel.

5.1.2 Interview with Report User

Please refer to **Section 5.2** below for information requested from the Report User. Because the Report User (Client) is a lender, it is understood that the Report User would not have knowledge of the property that would significantly impact our ability to satisfy the objectives of this assessment. The lack of this information is not considered to represent a significant data gap.

5.1.3 Interview with Key Site Manager

Mr. Ozzy Pulido, key site manager, indicated that he had no information pertaining to any pending, threatened, or past litigation relevant to hazardous substances or petroleum products in, on, or from the subject property; any pending, threatened, or past administrative proceedings relevant to hazardous substances or petroleum products in, on, or from the subject property; or any notices from a governmental entity regarding any possible violation of environmental laws or possible liability relating to hazardous substances or petroleum products.

5.1.4 Interviews with Past Owners, Operators and Occupants

with past owners, operators and occupants were not conducted since information regarding the potential for contamination at the subject property was obtained from other sources.

5.1.5 Interview with Others

According to Mr. Tim Gudim, the subject property was developed in 1978 for industrial use. Mr. Gudim further stated that there are no USTs, clarifiers, oil/water separators, groundwater monitoring wells, or hazardous substance use/storage/generation on the subject property to the best of his knowledge. According to Mr. Gudim, the subject property was formerly occupied by a Standard Strictures Inc from 1978 to 2012. A previous Phase I ESA and subsurface investigation was conducted, as further discussed in **Section 5.2.6.**

5.2 User Provided Information

5.2.1 Title Records, Environmental Liens, and AULs

At the request of the User, Partner contracted ERIS to perform a limited chain of title and/or environmental lien search for the subject property. No environmental liens or AULs were identified for the subject property.

5.2.2 Specialized Knowledge

No specialized knowledge of environmental conditions associated with the subject property was provided by the User at the time of the assessment.

5.2.3 Actual Knowledge of the User

No actual knowledge of any environmental lien or AULs encumbering the subject property or in connection with the subject property was provided by the User at the time of the assessment.

5.2.4 Valuation Reduction for Environmental Issues

No knowledge of valuation reductions associated with the subject property was provided by the User at the time of the assessment.

5.2.5 Commonly Known or Reasonably Ascertainable Information

The User did not provide information that is commonly known or *reasonably ascertainable* within the local community about the subject property at the time of the assessment.

5.2.6 Previous Reports and Other Provided Documentation

The following information was provided to Partner for review during the course of this assessment:

Phase 1 Environmental Site Assessment, Standard Industrial – 5900 Pruitt Avenue Windsor, California Hurvitz Environmental Services Inc (March 29, 2013)

Hurvitz Environmental Services Inc (HES) prepared this report on behalf of Currie Properties. The assessment was performed in accordance with ASTM Standard E1527-05. The assessment consisted of a site reconnaissance, interviews with knowledgeable personnel, review of historical information, a review of federal, state and local regulatory databases and included a limited asbestos survey. The assessment was performed on a larger parcel of land that included the subject property. Pertinent information contained in this report is summarized below:

- At the time of the 2013 assessment, the subject property building was unoccupied.
- According to the HES report, the subject property was formerly occupied by Standard Structures Inc from 1978 to 2012 for industrial use. The subject property building was historically used for the manufacture of glue laminated trusses.
- According to a Site Screening performed at the site in 1991 by Ecology and Environment Inc, two glue wastewater settling ponds previously existed at the northwest end of the site (at least one of the former ponds is located onsite east of the subject building). The North Coast Regional Water Quality Control Board (NCRWQCB) issued the facility waste discharge requirements under order # 74-83 in 1974 which prohibited the drainage of glue waste to any holding or disposal pond. SSI eliminated the use of the ponds at that time and added a decorative pond adjacent to the State Highway 101. In 1980, the NCRWQCB observed glue wastes being dumped into the on-site decorative pond. The pond and adjacent Pruitt Creek were sampled by the NCRWQCB on October 27, 1980. Phenol was present in the pond water and phenolic compounds were present in the pond soil. As a result, the NCRWQCB issued a Cleanup and Abatement Order (CAO) No 80-190 to the facility on October 1, 1980 to abate waste discharge to the pond and to remove the pond waste and close the pond. On June 3, 1981, the NCRWQCB rescinded the CAO under Order No. 81-140 because all cleanup and abatement activities were completed and had been assessed.
- In January 1990, under the authority of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 (CERCLA) and the Superfund Amendments and Reauthorization Act of 1986 (SARA) the US Environmental Protection Agency (EPA) tasked Ecology and Environment, Inc's Field Investigation Team (FIT) to conduct a Screening Site Inspection of the Standard Structures site. During the Site Screening soil and groundwater samples were collected. The sample results were found to be inconclusive, and the final assessment concluded that further assessment was unnecessary. However, in 1991, the EPA revised the Hazard Ranking System (HRS)

and asked Ecology and Environment Inc., to reassess the Standard Structures Site. The site re-assessment concluded that no further remedial action was to be planned under CERCLA. The basis for the assessment stated that the predominant hazardous substances utilized at SSI were phenol, resorcinol, methylene chloride, and paraformaldehyde, which all have low toxicity values. In addition, an observed release to groundwater had not been documented at the site.

- According to the HES report, the no current or former ASTs or USTs were identified for the subject property.
- The SSI facility was formerly serviced by onsite sewage disposal system that consisted of several septic tanks and two (2) sewage evaporation ponds. The facility has since been connected to city sewer and water service and the sewage ponds have been abandoned. Partner notes that the ponds did not appear to be located on the 790 Shiloh Road parcel.
- Waste oil was observed within drums in the subject property building. According to the HES report, no leaks, spills or staining was observed around any of the stored materials.

HES identified the following RECs and environmental concerns:

- The former glue evaporation pond on the subject property is considered to be a REC but is not considered to be a concern the subject property due to the results of the EPA investigation.
- The subject property has had a history of hazardous material use and storage activities, however, there is no indication that significant release has occurred.
- A former irrigation well on the western adjacent property to the west may have drawn in contaminants from the former Ecodyne wood treatment plant to the west.

HES recommended that the former irrigation well be tested for glue related chemicals formerly used on the subject property and for the chemicals identified by the former Ecodyne site investigations.

Phase II Environmental Site Assessment, Standard Industrial – 5900 Pruitt Avenue, Hurvitz Environmental Services Inc (April 4, 2013)

HES) prepared this report on behalf of Currie Properties. The assessment was performed in order to "further investigate concerns identified during the Phase 1 ESA." The assessment was performed on the parcel of land adjacent to the west of the subject property (APN 059-271-104). Pertinent information contained in this report is summarized below:

- According to the 2013 HES report, one groundwater sample was collected from the irrigation well on the adjacent property to the west (APN 059-271-104).
- According to the HES report, the well has been out of operation since at least 2011. HES measured the depth to groundwater using an oil/water interface probe. HES measured groundwater approximately 16 feet below grade and no free-floating petroleum products were identified.
- One groundwater sample was collected and analyzed for total petroleum hydrocarbons as gasoline/diesel/motor oil, benzene/toluene/ ethylbenzene/ xylene (BTEX), methyl tert butyl ether (MTBE), formaldehyde, chromium VI, lead, phenols, and polynuclear aromatic hydrocarbons.

- According to the HES report, lead was the only contaminant measured above the detection limit with a concentration of 18 micrograms/liter which is above the EPA limits for drinking water. HES did not consider the concentrations of lead to be a concern because the well is not used for drinking water. HES attributed the lead contamination to the corrosion of the plumbing system and did not appear to be resulting from on-site or off-site sources.

HES concluded that the sampling of the well did not identify contaminants of concern in groundwater at the site and recommended no further investigation.

Copies of pertinent pages reviewed are included in **Appendix B** of this report.

6.0 SITE RECONNAISSANCE

The weather at the time of the site visit was sunny and clear. Refer to **Section 1.5** for limitations encountered during the field reconnaissance and **Sections 2.1** and **2.2** for subject property operations. The table below provides the site assessment details:

Site Assessment Data	
Site Assessment Performed By:	Zachary Oretsky
Site Assessment Conducted On:	November 30, 2021

The table below provides the subject property personnel interviewed during the field reconnaissance:

Site Visit Personnel for 790 Shiloh Road (Subject Property)			
Name	**Title/Role**	**Contact Number**	**Site Walk***
Mr. Tim Gudim	Key Site Manager	(310) 625-9339	Yes
Mr. Ozzy Pulido	Site Contact for Client	(707) 396-1564	No

* Accompanied Partner during the field reconnaissance activities and provided information pertaining to the current operations and maintenance of the subject property

No potential environmental concerns were identified during the onsite reconnaissance.

6.1 General Site Characteristics

6.1.1 Solid Waste Disposal

Solid waste generated at the subject property is disposed of in commercial dumpsters located north of the building on the subject property. Independent solid waste disposal contractors: Pacific Sanitation, Sonoma County Resource Recovery, and Big Sky Enterprise, remove solid waste from the subject property. No evidence of illegal dumping of solid waste was observed during the Partner site reconnaissance.

6.1.2 Sewage Discharge and Disposal

Sanitary discharges on the subject property are directed into the municipal sanitary sewer system. The Town of Windsor services the subject property vicinity. No wastewater treatment facilities or septic systems are observed or reported on the subject property.

6.1.3 Surface Water Drainage

Storm water is removed from the subject property primarily by soil infiltration of exposed grassland and unimproved surfaces, fluvial runoff through Pruitt Creek, and sheet flow action across the paved surfaces towards storm water drains located in the public right of way. The subject property is connected to a municipal owned and maintained sewer system.

The subject property does not appear to be a designated wetland area, based on information obtained from the United States Fish & Wildlife Service. No surface impoundments, wetlands, natural catch basins, settling ponds, or lagoons are located on the subject property. No drywells were identified on the subject property.

6.1.4 Source of Heating and Cooling

The cooling system within the subject property building consists of portable fans located throughout the main welding and fabrication area. Electricity and natural gas are provided by Pacific Gas and Electric (PG&E). Hot water is provided by an individual natural gas hot water heater.

6.1.5 Wells and Cisterns

No aboveground evidence of wells or cisterns was observed during the site reconnaissance.

6.1.6 Wastewater

Domestic wastewater generated at the subject property is disposed by means of the sanitary sewer system.

6.1.7 Septic Systems

No septic systems were observed or reported on the subject property.

6.1.8 Additional Site Observations

No additional general site characteristics were observed during the site reconnaissance.

6.2 Potential Environmental Hazards

6.2.1 Hazardous Substances and Petroleum Products Used or Stored at the Site

Partner observed multiple 55-gallon steel drums containing waste oil, acetone and solid metal waste, as well as multiple pails of paints and Carboline 236E thinner throughout the building. De minimis staining was observed on the concrete floor in the immediate vicinity of the waste oil drums stored in the northeast corner of the building. Many of the drums were not labeled or stored in secondary containment. According to subject property personnel, hazardous waste generated at the subject property is routinely transferred offsite by Big Sky Enterprise. Based on the small surface area and localized nature of the staining and the lack of violations on file with local regulatory agencies, these materials are not expected to represent an environmental concern.

6.2.2 Aboveground & Underground Hazardous Substance or Petroleum Product Storage Tanks (ASTs/USTs)

Partner observed one aboveground storage tank (AST) for the storage of propane on the subject property. The AST is located to the west of the building. No staining, leaks or spills were noted in the vicinity of the AST, and no releases have been reported to the local regulatory agencies.

No evidence of current or former USTs was observed during the site reconnaissance.

6.2.3 Evidence of Releases

No spills, stains or other indications that a surficial release has occurred at the subject property were observed.

6.2.4 Polychlorinated Biphenyls (PCBs)

Older transformers and other electrical equipment could contain PCBs at a level that subjects them to regulation by the U.S. EPA. PCBs in electrical equipment are controlled by United States Environmental Protection Agency regulations 40 CFR, Part 761. Under the regulations, there are three categories into which electrical equipment can be classified: 1) Less than 50 parts per million (ppm) of PCBs – "*Non-PCB;*" 2) 50 ppm-500 ppm – "*PCB-Contaminated;*" and, 3) Greater than 500 ppm – "*PCB-Containing.*" The manufacture, process, or distribution in commerce or use of any PCB in any manner other than in a totally enclosed manner was prohibited after January 1, 1977.

The on-site reconnaissance addressed indoor and outdoor transformers that may contain PCBs. Three pad-mounted transformers were observed on the subject property. The transformers are not labeled indicating PCB content. No staining or leakage was observed in the vicinity of the transformers. Based on the good condition of the equipment, the transformers are not expected to represent an environmental concern.

Additionally, no other potential PCB-containing equipment (interior transformers, oil-filled switches, hoists, lifts, dock levelers, hydraulic elevators, balers, etc.) was observed on the subject property during Partner's reconnaissance.

6.2.5 Strong, Pungent or Noxious Odors

No strong, pungent or noxious odors were evident during the site reconnaissance.

6.2.6 Pools of Liquid

No pools of liquid were observed on the subject property during the site reconnaissance.

6.2.7 Drains, Sumps and Clarifiers

No drains, sumps, or clarifiers, other than those associated with storm water removal, were observed on the subject property during the site reconnaissance.

6.2.8 Pits, Ponds and Lagoons

No pits, ponds or lagoons were observed on the subject property.

6.2.9 Stressed Vegetation

No stressed vegetation was observed on the subject property.

6.2.10 Additional Potential Environmental Hazards

No additional environmental hazards, including landfill activities or radiological hazards, were observed.

6.3 Non-ASTM Services

6.3.1 Asbestos-Containing Materials (ACMs)

Asbestos is the name given to a number of naturally occurring, fibrous silicate minerals mined for their useful properties such as thermal insulation, chemical and thermal stability, and high tensile strength. The Occupational Safety and Health Administration (OSHA) regulation 29 CFR 1926.1101 requires certain construction materials to be *presumed* to contain asbestos, for purposes of this regulation. All thermal

system insulation (TSI), surfacing material, and asphalt/vinyl flooring that are present in a building constructed prior to 1981 and have not been appropriately tested are "presumed asbestos-containing material" (PACM).

The subject property building was constructed in 1978. Partner has conducted a limited, visual evaluation of accessible areas for the presence of suspect ACMs at the subject property. The objective of this visual survey was to note the presence and condition of suspect ACM observed. Please refer to the table below for identified suspect ACMs:

Suspect ACMs			
Suspect ACM	**Location**	**Friable**	**Physical Condition**
Drywall Systems	Throughout Building Interior	No	Good
Spray-Applied Acoustical Material	Throughout Building Interior	Yes	Good

The limited visual survey consisted of noting observable materials (materials which were readily accessible and visible during the course of the site reconnaissance) that are commonly known to potentially contain asbestos. This activity was not designed to discover all sources of suspect ACM, PACM, or asbestos at the site; or to comply with any regulations and/or laws relative to planned disturbance of building materials such as renovation or demolition, or any other regulatory purpose. Rather, it is intended to give the User an indication if significant (significant due to quantity, accessibility, or condition) potential sources of ACM or PACM are present at the subject property. Additional sampling, assessment, and evaluation will be warranted for any other use.

According to the US EPA, ACM and PACM that is intact and in good condition can, in general, be managed safely in-place under an Operations and Maintenance (O&M) Program until removal is dictated by renovation, demolition, or deteriorating material condition. Prior to any disturbance of the construction materials within this facility, a comprehensive ACM survey is recommended.

6.3.2 Lead-Based Paint (LBP)

Lead is a highly toxic metal that affects virtually every system of the body. LBP is defined as any paint, varnish, stain, or other applied coating that has 1 mg/cm^2 (or 5,000 ug/g or 0.5% by weight) or more of lead. Congress passed the Residential Lead-Based Paint Hazard Reduction Act of 1992, also known as "Title X", to protect families from exposure to lead from paint, dust, and soil. Under Section 1017 of Title X, intact LBP on most walls and ceilings is not considered a "hazard," although the condition of the paint should be monitored and maintained to ensure that it does not become deteriorated. Further, Section 1018 of this law directed the Housing and Urban Development (HUD) and the US EPA to require the disclosure of known information on LBP and LBP hazards before the sale or lease of most housing built before 1978.

It is unlikely that LBP is present in buildings constructed after 1977. Therefore, due to the age of the subject property building, it is unlikely that LBP is present.

6.3.3 Radon

Radon is a colorless, odorless, naturally occurring, radioactive, inert, gaseous element formed by radioactive decay of radium (Ra) atoms. The US EPA has prepared a map to assist National, State, and local organizations to target their resources and to implement radon-resistant building codes. The map divides the country into three Radon Zones, according to the table below:

EPA Radon Zones		
EPA Zones	**Average Predicted Radon Levels**	**Potential**
Zone 1	Exceed 4.0 pCi/L	Highest
Zone 2	Between 2.0 and 4.0 pCi/L	Moderate
Zone 3	Less than 2.0 pCi/L	Low

It is important to note that the EPA has found homes with elevated levels of radon in all three zones, and the US EPA recommends site-specific testing in order to determine radon levels at a specific location. However, the map does give a valuable indication of the propensity of radon gas accumulation in structures.

Radon sampling was not conducted as part of this assessment. Review of the US EPA Map of Radon Zones places the subject property in Zone 3. Based upon the radon zone classification, radon is not considered to be an environmental concern.

6.3.4 Lead in Drinking Water

According to available information, a public water system operated by the Town of Windsor serves the subject property vicinity. According to a representative, shallow groundwater beneath the subject property is not utilized for domestic purposes. The sources of public water for Windsor are groundwater from wells near the Russian River and is purchased from the Sonoma County Water Agency. According to the Windsor and the 2018 Annual Water Quality Report, water supplied to the subject property is in compliance with all State and Federal regulations pertaining to drinking water standards, including lead and copper. Water sampling was not conducted to verify water quality.

6.3.5 Mold

Molds are microscopic organisms found virtually everywhere, indoors and outdoors. Mold will grow and multiply under the right conditions, needing only sufficient moisture (e.g.in the form of very high humidity, condensation, or water from a leaking pipe, etc.) and organic material (e.g., ceiling tile, drywall, paper, or natural fiber carpet padding).

Partner observed accessible, interior areas for the subject property building for significant evidence of mold growth with the exceptions detailed in **Section 1.5** of this report; however, this ESA should not be used as a mold survey or inspection. Additionally, this limited assessment was not designed to assess all areas of potential mold growth that may be affected by mold growth on the subject property. Rather, it is intended to give the client an indication as to whether or not conspicuous (based on observed areas) mold growth is present at the subject property. This evaluation did not include a review of pipe chases, mechanical systems, or areas behind enclosed walls and ceilings.

No obvious indications of water damage or potential mold growth were observed during Partner's visual assessment.

6.4 Adjacent Property Reconnaissance

The adjacent property reconnaissance consisted of observing the adjacent properties from the subject property premises.

6.4.1 PCBs

Two pole-mounted transformers were observed on the adjacent properties. No staining or leakage was observed in the vicinity of the transformers. Based on these observations, the presence of adjacent transformers is not expected to represent an environmental concern.

No other items of environmental concern were identified on the adjacent properties during the site assessment, including hazardous substances, petroleum products, ASTs, USTs, evidence of releases, strong or noxious odors, pools of liquids, sumps or clarifiers, pits or lagoons, stressed vegetation, or any other potential environmental hazards.

7.0 FINDINGS AND CONCLUSIONS

Findings

A *recognized environmental condition (REC)* refers to the presence or likely presence of any hazardous substances or petroleum products in, on, or at a property: due to release to the environment; under conditions indicative of a release to the environment; or under conditions that pose a material threat of a future release to the environment. The following was identified during the course of this assessment:

- Partner did not identify recognized environmental conditions during the course of this assessment.

A *controlled recognized environmental condition (CREC)* refers to a REC resulting from a past release of hazardous substances or petroleum products that has been addressed to the satisfaction of the applicable regulatory authority, with hazardous substances or petroleum products allowed to remain in place subject to the implementation of required controls. The following was identified during the course of this assessment:

- Partner did not identify controlled recognized environmental conditions during the course of this assessment.

A *historical recognized environmental condition (HREC)* refers to a past release of any hazardous substances or petroleum products that has occurred in connection with the property and has been addressed to the satisfaction of the applicable regulatory authority or meeting unrestricted use criteria established by a regulatory authority, without subjecting the property to any required controls. The following was identified during the course of this assessment:

- Partner reviewed a previous Phase 1 ESA for the subject property by Hurvitz Environmental Services Inc (HES) dated March 29, 2013. The assessment was performed on a larger parcel of land that included the subject property. According to the 2013 HES report, the subject property was formerly occupied by Standard Structures Inc (SSI) from 1978 to 2012 for industrial use. The subject property building was historically used for the manufacture of glue laminated trusses. According to a Site Screening performed at the site in 1991 by Ecology and Environment Inc, two glue wastewater settling ponds previously existed at the northwest end of the site (at least one of the former ponds is located onsite east of the subject building). The North Coast Regional Water Quality Control Board (NCRWQCB) issued the facility waste discharge requirements under order # 74-83 in 1974 which prohibited the drainage of glue waste to any holding or disposal pond. SSI eliminated the use of the ponds at that time and added a decorative pond adjacent to the State Highway 101. In 1980, the NCRWQCB observed glue wastes being dumped into the on-site decorative pond. The pond and adjacent Pruitt Creek were sampled by the NCRWQCB on October 27, 1980. Phenol was present in the pond water and phenolic compounds were present in the pond soil. As a result, the NCRWQCB issued a Cleanup and Abatement Order (CAO) No 80-190 to the facility on October 1, 1980 to abate waste discharge to the pond and to remove the pond waste and close the pond. On June 3, 1981, the NCRWQCB rescinded the CAO under Order No. 81-140 because all cleanup and abatement activities were completed and had been assessed.

In January 1990, under the authority of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 (CERCLA) and the Superfund Amendments and Reauthorization Act of 1986 (SARA) the US Environmental Protection Agency (EPA) tasked Ecology and Environment, Inc's Field Investigation Team (FIT) to conduct a Screening Site Inspection of the Standard Structures site. During the Site Screening soil and groundwater samples were collected. The sample results were found to be inconclusive, and the final assessment concluded that further assessment was unnecessary. However, in 1991, the EPA revised the Hazard Ranking System (HRS) and asked Ecology and Environment Inc., to reassess the Standard Structures Site. The site re-assessment concluded that no further remedial action was to be planned under CERCLA. The basis for the assessment stated that the predominant hazardous substances utilized at SSI were phenol, resorcinol, methylene chloride, and paraformaldehyde, which all have low toxicity values. In addition, an observed release to groundwater had not been documented at the site.

Partner opines that although the CAO was rescinded and the EPA concluded that further remedial action was not required, if development of the property is to occur, evaluation of the soil within the vicinity of the former pond should be considered for characterization.

An *environmental issue* refers to environmental concerns identified by Partner, which do not qualify as RECs; however, warrant further discussion. The following was identified during the course of this assessment:

- Due to the age of the subject property building, there is a potential that asbestos-containing materials (ACM) are present. Overall, all suspect ACMs were observed in good condition and do not pose a health and safety concern to the occupants of the subject property at this time. Should these materials be replaced, the identified suspect ACMs would need to be sampled to confirm the presence or absence of asbestos prior to any renovation or demolition activities to prevent potential exposure to workers and/or building occupants.

Conclusions and Opinions

Partner has performed a Phase I ESA in conformance with the scope and limitations of ASTM Practice E1527-13 of 790 Shiloh Road in the City of Windsor, Sonoma County, California (the "subject property"). Any exceptions to, or deletions from, this practice are described in **Section 1.5** of this report.

This assessment has revealed evidence of a historical recognized environmental condition and environmental issues in connection with the subject property. Based on the conclusions of this assessment, Partner makes the following conclusions:

- An Operations and Maintenance (O&M) Program should be implemented in order to safely manage the suspect ACMs located at the subject property.
- Evaluation of the soil conditions within the vicinity of the former glue evaporation pond should be considered if development of the property is to occur.

8.0 SIGNATURES OF ENVIRONMENTAL PROFESSIONALS

Partner has performed a Phase I ESA of the property located at 790 Shiloh Road, Town of Windsor, Sonoma County, California in conformance with the scope and limitations of the protocol and the limitations stated earlier in this report. Exceptions to or deletions from this protocol are discussed earlier in this report.


By signing below, Partner declares that, to the best of our professional knowledge and belief, we meet the definition of *Environmental Professional* as defined in §312.10 of 40 CFR §312. Partner has the specific qualifications based on education, training, and experience to assess a *property* of the nature, history, and setting of the subject *property*. Partner has developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.

Prepared By:



Zachary Oretsky
Environmental Scientist

Reviewed By:



Rebecca Howard
Senior Author

9.0 REFERENCES

Reference Documents

American Society for Testing and Materials, Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process, ASTM Designation: E1527-13.

Environmental Data Resources (EDR), Radius Report, November 2021

Federal Emergency Management Agency, Federal Insurance Administration, National Flood Insurance Program, Flood Insurance Map, accessed via internet, November 2021

United States Department of Agriculture, Natural Resources Conservation Service, accessed via internet, November 2021

United States Department of Agriculture, Natural Resources Conservation Service, Web Soil Survey, accessed via the internet, November 2021

United States Environmental Protection Agency, EPA Map of Radon Zones (Document EPA-402-R-93-071), accessed via the internet, November 2021

United States Geological Survey, accessed via the Internet, November 2021

United States Geological Survey Topographic Map 2015, 7.5-minute series, accessed via internet, November 2021


FIGURES

1 SITE LOCATION MAP

2 SITE PLAN

3 TOPOGRAPHIC MAP

PARTNER



N

Drawing Not To Scale

KEY:
Subject Property

FIGURE 1: SITE LOCATION MAP-WINDSOR CA
Project No. 21-347251.1

PARTNER



N


GROUNDWATER FLOW

------	Subject Property Boundary	T	Transformer
D	Chemical/Drum Storage	A	Aboveground Storage Tank

FIGURE 2: SITE PLAN-WINDSOR CA

Project No. 21-347251.1

PARTNER



N

USGS 7.5 Minute *Healdsburg, California* Quadrangle
Created: 2015/Revised: 2021

KEY:
Subject Property

FIGURE 3: TOPOGRAPHIC MAP-WINDSOR CA
Project No. 21-347251.1

PARTNER

APPENDIX A: SITE PHOTOGRAPHS



1. Dirt road entrance to southern portion of subject property.



2. North side of subject property building.



3. South side of subject property building.



4. East side of subject property building.



5. West side of subject property building, view to the north.



6. West side of subject property building, view to the south.



7. One of three pad-mounted transformers.



8. Propane AST adjacent to the west of the building.



9. Bridge crane adjacent to the southwest of the building.



10. Gas cannisters on the eastern exterior of the building.



11. Interior view looking north of the building.



12. Interior view looking south of the building.



13. Sandblasting booth in the southeast corner of the building.



14. Interior view of sanding booth.



15. Sanding booth mechanical equipment.



16. Steel drums containing solid waste from the sanding booth.



17. Paint booth located in the west side of the building.




18. Interior view of paint booth.



19. Portable air compressors located throughout the building.



20. Welding and assembly area.



21. Bridge crane inside the building.



22. Unlabeled hazardous waste drums.




23. Parts washer draining into waste drum.



24. De minimis staining seen in the immediate vicinity of waste drums.




25. Stored paint cans and thinner in the southwest portion of the building.




26. Close-up of thinner label.



27. Additional paint cans stored in the building.



28. Entrance to employee break room.



29. Employee break room.




30. Restroom adjacent to employee break room.



31. Unlabeled waste drums stored in steel trough.




32. Close-up view – no staining or leaking.



33. Storage area on west side of building.



34. Multiple air compressors in storage area.



35. Interior view of mezzanine office area.



36. Representative view of grassland on east side of subject property building.




37. Small channel on southern portion of subject property and adjacent FedEx to the southwest



38. Pruitt Creek on east side of subject property and adjacent vineyards across Highway 101.



39. View to the east of former glue evaporation pond.



40. View of wooded area on northern portion of subject property.



41. Adjacent gas station and pole-mounted transformer across Shiloh Road.



42. Adjacent commercial building to the west.



43. Adjacent commercial building to the west.



44. Adjacent Northgate Ready Mix property to the west.



45. Adjacent multi-tenant industrial property to the west.



46. Pole-mounted transformer on western adjacent property.



47. Southern adjacent Sonoma County Day Care.



48. Southern adjacent vineyard in distance.

APPENDIX B: HISTORICAL/REGULATORY DOCUMENTATION

PARTNER




Year: 1942
Source: ASCS
Scale: 1" = 600'
Comment:

Address: 790 Shiloh Road, WINDSOR, CA
Approx Center: -122.78749577,38.52072644

Order No: 21111700210

ERIS



Year: 1952
Source: USGS
Scale: 1" = 600'
Comment:

Address: 790 Shiloh Road, WINDSOR, CA
Approx Center: -122.78749577,38.52072644

Order No: 21111700210

ERIS



Year: 1956
Source: USGS
Scale: 1" = 600'
Comment:

Address: 790 Shiloh Road, WINDSOR, CA
Approx Center: -122.78749577,38.52072644

Order No: 21111700210

ERIS




Year: 1965
Source: CAS
Scale: 1" = 600'
Comment:

Address: 790 Shiloh Road, WINDSOR, CA
Approx Center: -122.78749577,38.52072644

Order No: 21111700210

ERIS




Year: 1968
Source: USGS
Scale: 1" = 600'
Comment:

Address: 790 Shiloh Road, WINDSOR, CA
Approx Center: -122.78749577,38.52072644

Order No: 21111700210

ERIS



Year: 1973
Source: USGS
Scale: 1" = 600'
Comment:

Address: 790 Shiloh Road, WINDSOR, CA
Approx Center: -122.78749577,38.52072644

Order No: 21111700210

ERIS




Year: 1976
Source: USGS
Scale: 1" = 600'
Comment:

Address: 790 Shiloh Road, WINDSOR, CA
Approx Center: -122.78749577,38.52072644

Order No: 21111700210

ERIS



Year: 1983
Source: USGS
Scale: 1" = 600'
Comment:

Address: 790 Shiloh Road, WINDSOR, CA
Approx Center: -122.78749577,38.52072644

Order No: 21111700210

ERIS



Year: 1993
Source: USGS
Scale: 1" = 600'
Comment:

Address: 790 Shiloh Road, WINDSOR, CA
Approx Center: -122.78749577,38.52072644

Order No: 21111700210

ERIS



Year: 1998
Source: USGS
Scale: 1" = 600'
Comment: Best Copy Available

Address: 790 Shiloh Road, WINDSOR, CA
Approx Center: -122.78749577,38.52072644

Order No: 21111700210

ERIS



Year: 2004
Source: USDA
Scale: 1" = 600'
Comment:

Address: 790 Shiloh Road, WINDSOR, CA
Approx Center: -122.78749577,38.52072644

Order No: 21111700210

ERIS



Year: 2005
Source: USDA
Scale: 1" = 600'
Comment:

Address: 790 Shiloh Road, WINDSOR, CA
Approx Center: -122.78749577,38.52072644

Order No: 21111700210

ERIS



Year: 2006
Source: USDA
Scale: 1" = 600'
Comment:

Address: 790 Shiloh Road, WINDSOR, CA
Approx Center: -122.78749577,38.52072644

Order No: 21111700210

ERIS



Year: 2009
Source: USDA
Scale: 1" = 600'
Comment:

Address: 790 Shiloh Road, WINDSOR, CA
Approx Center: -122.78749577,38.52072644

Order No: 21111700210

ERIS



Year: 2010
Source: USDA
Scale: 1" = 600'
Comment:

Address: 790 Shiloh Road, WINDSOR, CA
Approx Center: -122.78749577,38.52072644

Order No: 21111700210

ERIS



Year: 2012
Source: USDA
Scale: 1" = 600'
Comment:

Address: 790 Shiloh Road, WINDSOR, CA
Approx Center: -122.78749577,38.52072644

Order No: 21111700210

ERIS



Year: 2014
Source: USDA
Scale: 1" = 600'
Comment:

Address: 790 Shiloh Road, WINDSOR, CA
Approx Center: -122.78749577,38.52072644

Order No: 21111700210

ERIS



Year: 2016
Source: USDA
Scale: 1" = 600'
Comment:

Address: 790 Shiloh Road, WINDSOR, CA
Approx Center: -122.78749577,38.52072644

Order No: 21111700210

ERIS



Year: 2018
Source: USDA
Scale: 1" = 600'
Comment:

Address: 790 Shiloh Road, WINDSOR, CA
Approx Center: -122.78749577,38.52072644

Order No: 21111700210

ERIS



Year: 2020
Source: USDA
Scale: 1" = 600'
Comment:

Address: 790 Shiloh Road, WINDSOR, CA
Approx Center: -122.78749577,38.52072644

Order No: 21111700210

ERIS

FIRE INSURANCE MAPS

Project Property:	790 Shiloh Road 790 Shiloh Road WINDSOR CA 95492
Project No:	21-347251.1
Requested By:	Partner Engineering and Science, Inc.
Order No:	21111700210
Date Completed:	November 18, 2021

Please note that no information was found for your site or adjacent properties.

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

CITY DIRECTORY

Project Property:	*790 Shiloh Road* *790 Shiloh Road* *Windsor, CA 95492*
Project No:	*21-347251.1*
Requested By:	*Partner Engineering and Science, Inc.*
Order No:	*21111700210*
Date Completed:	*November 23, 2021*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

November 23, 2021
RE: CITY DIRECTORY RESEARCH
790 Shiloh Road
790 Shiloh Road Windsor, CA

Thank you for contacting ERIS for an City Directory Search for the site described above. Our staff has conducted a reverse listing City Directory search to determine prior occupants of the subject site and adjacent properties. We have provided the nearest addresses(s) when adjacent addresses are not listed. If we have searched a range of addresses, all addresses in that range found in the Directory are included.

Note: Reverse Listing Directories generally are focused on more highly developed areas. Newly developed areas may be covered in the more recent years, but the older directories will tend to cover only the "central" parts of the city. To complete the search, we have either utilized the ACPL, Library of Congress, State Archives, and/or a regional library or history center as well as multiple digitized directories. These do not claim to be a complete collection of all reverse listing city directories produced.

ERIS has made every effort to provide accurate and complete information but shall not be held liable for missing, incomplete or inaccurate information. To complete this search we used the general range(s) below to search for relevant findings. If you believe there are additional addresses or streets that require searching please contact us at 866-517-5204.

Search Criteria:

ALL of Day School Place
750-930 of Shiloh Road
ALL of Caletti Avenue
ALL of Pruitt Avenue

Search Results Summary

Date	Source	Comment
2020	DIGITAL BUSINESS DIRECTORY	
2016	DIGITAL BUSINESS DIRECTORY	
2012	DIGITAL BUSINESS DIRECTORY	
2008	DIGITAL BUSINESS DIRECTORY	
2006	HAINES	
2000	HAINES	
1995	HAINES	
1990	HAINES	
1985	HAINES	
1981	HAINES	
1975	HAINES	
1972	HAINES	

2020 CALETTI AVENUE

SOURCE: DIGITAL BUSINESS DIRECTORY

470	**INDUSTRIAL CHOPPERS**...*Motorcycles & Motor Scooters-rpr & Svc*
470	**MOBILE MINI INC**...*Storage Systems Portable*
470	**WEST COAST METALS**...*Recycling Centers (whls)*
470	**WEST COAST METALS INC**...*Federal Government Contractors*
470	**WEST COAST METALS INC**...*Metals-base (whls)*
510	**QUALITY STAINLESS TANKS**...*Tanks-metal (whls)*
510	**QUALITY STAINLESS TANKS**...*Tank Testing & Inspection*
510	**QUALITY STAINLESS TANKS**...*Tanks-manufacturers*
510	**RICHARD DAPELO**...*Nonclassified Establishments*
550	**GUY'S FENCING**...*Fence Contractors*
550	**GUY'S FENCING**...*Fence Contractors*
564	**IMAGE TREE SVC**...*Tree Service*
590	**M & M SVC**...*Garbage Collection*
590	**M & M SVC**...*Federal Government Contractors*
600	**BEST TRUCK BODY TRAILER INC**...*Truck Bodies-manufacturers*
600	**BEST TRUCK BODY & TRAILER INC**...*Truck Bodies-manufacturers*
600	**BEST TRUCK BODY-TRAILER RPRS**...*Nonclassified Establishments*
610	**PACIFIC BRACING CO**...*Mobile Homes-anchoring Service*

2020 DAY SCHOOL PLACE

SOURCE: DIGITAL BUSINESS DIRECTORY

NO LISTING FOUND FOR THIS YEAR...

5873 **ELITE CONCRETE CONSTR INC**...*Concrete Contractors*
5885 **S B K W CONCRETE INC**...*Poured Concrete Foundation & Structure Contractors*
5892 **INVESTMENTS SOCO**...*Industrial Parks*
5900 **DENNIS GROVE CONCRETE PUMPING**...*Concrete Pumping Service*
5900 **DISEL PERFORMANCE ALLIED**...*Nonclassified Establishments*
5900 **NEW METAL COACHWORKS LLC**...*Metal Goods-manufacturers*
5900 **NORTHBAY BOTTLING**...*Bottlers (mfrs)*
5900 **NORTHBAY BOTTLING**...*Water-distilled (whls)*
5900 **REYNOLDS PACKAGING KAMA**...*Federal Government Contractors*
5900 **REYNOLDS PACKAGING KAMA**...*Plastics & Plastic Products (mfrs)*
5900 **REYNOLDS PACKAGING KAMA**...*Packaging Materials-manufacturers*
5900 **REYNOLDS PACKAGING KAMA**...*Industrial Equipment & Supplies (whls)*
5900 **SONOMA SOIL BUILDERS**...*Building Contractors*
5900 **TRUE LIBERTY BAGS**...*Handbags-wholesale*
5900 **VINTAGE PERFORMANCE**...*Automotive Body Paint & Interior Repair/maint*
5900 **WESTERN TREE**...*Landscaping Services*
5901 **STANDARD INDUSTRIAL EAST LLC**...*Fence Contractors*
5910 **RICHARD C CALETTI CONSULTING**...*Logistics*
5910 **STANDARD UNIT STRUCTURES**...*Nonclassified Establishments*
5922 **NORTHGATE READY MIX**...*Building Materials*
5922 **NORTHGATE READY MIX**...*Concrete Mixers (whls)*
5922 **NORTHGATE READY MIX**...*Lumberretail*
5922 **NORTHGATE READY MIX**...*Concrete-ready Mixed*
5937 **J L MODULAR INC**...*Nonclassified Establishments*
5937 **JL MODULAR**...*Building Contractors*

930 **ACORN RANCH**...*Ranches*
930 **ADVANCE TECH TOWING**...*Automobile Repairing & Service*
930 **ADVANCE TECH TOWING**...*Automobile Dismantling/recycling (whls)*
930 **ADVANCE VITICULTURE**...*Agricultural Consultants*
930 **ALDRICH PLASTERING**...*Plastering Contractors*
930 **ALL AROUND AUTO REPAIR**...*Automobile Repairing & Service*
930 **BACCHUS VINEYARD MANAGEMENT**...*Vineyard Consultants*
930 **BACCHUS VINEYARD MANAGEMENT**...*Vineyards*
930 **BATTERY SYSTEMS**...*Batteries-storage-retail*
930 **CAMERON**...*Oil & Gas-field Machinery/equip (mfrs)*
930 **COMMUNICATIONS WORKERS-AMERICA**...*Labor Organizations*
930 **DATA INSTINCTS ONE TO ONE**...*Unclassified Establishments*
930 **DECK SUPPLY WAREHOUSE**...*Patio Equipment & Supplies*
930 **DVPRO PAINTING INC**...*Painters*
930 **FARMER'S SEPTIC**...*Septic Tanks/systems-cleaning/repairing*
930 **GUY'S BARBER SHOP**...*Barbers*
930 **HERB W HANS LAW OFFICES**...*Attorneys*
930 **JOHN LEE SOLUTIONS LLC**...*Clinics*
930 **KADON TRUCKING INC**...*Trucking*
930 **KADON TRUCKING INC**...*Wrecker Service*
930 **LATINO SERVICE PROVIDERS**...*Social Service & Welfare Organizations*
930 **MENDOCINO MASONRY INC**...*Concrete Blocks & Shapes (whls)*
930 **MIDWEST TOWERS**...*Cooling Towers*
930 **MIDWEST TOWERS**...*Pumps (whls)*
930 **MIRACLE BOOKKEEPING**...*Accounting & Bookkeeping General Svc*
930 **NORTH BAY CONCRETE INC**...*Construction Companies*
930 **NORTH BAY CONCRETE INC**...*Concrete Contractors*
930 **NORTH COAST STEEL**...*Commercial & Institutional Building Construction*
930 **PORTOSAN**...*Toilets-portable*
930 **PRECISION WIRELESS SVC**...*Cellular Telephones (services)*
930 **PRO-TECH COMPUTERS**...*Computer & Equipment Dealers*
930 **PRO-TECH COMPUTERS**...*Computers-service & Repair*
930 **RIGDELINE ROOFING**...*Roofing Contractors*
930 **SHILOH GROUP LLC**...*Rental Service-stores & Yards*
930 **SHILOH GROUP LLC**...*Industrial Developments*
930 **SNYDER CONSTRUCTION**...*Construction Companies*
930 **SONOMA COUNTY FARM TRAILS**...*Grocers-wholesale*
930 **STRAIGHT LINE FENCE CO**...*Fence Contractors*
930 **STRAIGHT LINE FENCE CO**...*Fencemanufacturers*
930 **THUNDERSTAR CHARTER**...*Tours-operators & Promoters*
930 **TJ NELSON & ASSOC INC**...*Real Estate*
930 **TRANS TECH CONSULTANTS**...*Engineers-consulting*
930 **TRANS TECH CONSULTANTS**...*Machine Shops (mfrs)*
930 **TRANS TECH CONSULTANTS**...*Environmental & Ecological Services*
930 **TRANS TECH CONSULTANTS**...*Laboratoriesanalytical*
930 **TRU GREEN**...*Garden Centers*
930 **TRU GREEN**...*Lawn & Grounds Maintenance*
930 **VISIQUATE**...*Computer Programming Services*
930 **WATERWORKS INDUSTRIES INC**...*Contractors*
930 **WEINSTEIN SECURITY INC**...*Security Control Equip & Systemswhls*
930 **WEINSTEIN SECURITY INC**...*Burglar Alarm Systems (whls)*
930 **WEINSTEIN SECURITY INC**...*Wildlife Services*
930 **WEINSTEIN SECURITY INC**...*Security Guard & Patrol Service*
930 **WEINSTEIN SERCURITY INC**...*Security Systems Consultants*
930 **WEINSTEIN SERCURITY INC**...*Security Guard & Patrol Service*
930 **WEINSTEIN, MAUREEN CPA**...*Tax Return Preparation & Filing*
930 **WEINSTEIN, MAUREEN CPA**...*Accountants*
930 **WHITEHEAD SAM**...*Nonclassified Establishments*

2016 CALETTI AVENUE
SOURCE: DIGITAL BUSINESS DIRECTORY

470	**GARBAGE REINCARNATION INC**...*Thrift Shops*
470	**INDUSTRIAL CHOPPERS**...*Motorcycles & Motor Scooters-rpr & Svc*
470	**WEST COAST METALS INC**...*Metals-base (whls)*
510	**QUALITY STAINLESS TANKS**...*Tanks-manufacturers*
510	**QUALITY STAINLESS TANKS**...*Tanks-metal (whls)*
550	**GUY'S FENCING**...*Fence Contractors*
550	**GUY'S FENCING**...*Deck Builders*
564	**IMAGE FIREWOOD SVC**...*Firewood*
584	**BATT'S TIP TOP SVC INC**...*Tree Service*
590	**M & M SVC**...*Garbage Collection*
600	**BEST TRUCK BODY & TRAILER INC**...*Truck Bodies-manufacturers*
610	**PACIFIC BRACING CO**...*Other Heavy & Civil Engineering Construction*

2016 DAY SCHOOL PLACE
SOURCE: DIGITAL BUSINESS DIRECTORY

NO LISTING FOUND FOR THIS YEAR...

5885 **S B K W CONCRETE INC**...*Poured Concrete Foundation & Structure Contractors*
5897 **PACIFIC CREST FENCE CO**...*Fence Contractors*
5897 **STANDARD INDUSTRIAL EAST**...*Nonclassified Establishments*
5900 **ALPINE SPRINGS DISTRIBUTING**...*Distribution Services*
5900 **BIG SHOTS SCREEN PRINTING**...*Commercial Screen Printing*
5900 **CALI KUSTOMZ**...*Unclassified Establishments*
5900 **DENNIS GROVE CONCRETE PUMPING**...*Concrete Pumping Service*
5900 **OLDE WORLD WORKSHOPS**...*Kitchen Cabinets & Equipment-household*
5900 **REYNOLDS PACKAGING KAMA**...*Packaging Materials-manufacturers*
5900 **REYNOLDS PACKAGING KAMA**...*Plastics & Plastic Products (mfrs)*
5900 **SONOMA SOIL BUILDERS**...*Building Contractors*
5900 **STANDARD STRUCTURES**...*Real Estate*
5900 **TRUE LIBERTY BAGS**...*Handbags-wholesale*
5900 **VINTAGE PERFORMANCE**...*Automotive Body Paint & Interior Repair/maint*
5900 **WESTERN TREE**...*Landscaping Services*
5910 **STANDARD UNIT STRUCTURES**...*Nonclassified Establishments*
5922 **NORTHGATE READY MIX**...*Building Materials*
5922 **NORTHGATE READY MIX**...*Concrete-ready Mixed*
5937 **J L MODULAR INC**...*Nonclassified Establishments*

930 **ADVANCE TECH TOWING**...*Automobile Dismantling/recycling (whls)*
930 **ADVANCE VITICULTURE**...*Agricultural Consultants*
930 **ALL AROUND AUTO REPAIR**...*Automobile Repairing & Service*
930 **BACCHUS VINEYARD MANAGEMENT**...*Vineyards*
930 **BACCHUS VINEYARD MANAGEMENT**...*Vineyard Consultants*
930 **BATTERY SYSTEMS**...*Batteries-dry Cell-wholesale*
930 **BATTERY SYSTEMS**...*Batteries-storage-retail*
930 **BLACK POINT ENVIRONMENTAL**...*Environmental & Ecological Services*
930 **CAMERON**...*Oil & Gas-field Machinery/equip (mfrs)*
930 **COMMUNICATIONS WORKERS-AMERICA**...*Labor Organizations*
930 **D V PRO PAINTING INC**...*Painters*
930 **DATA INSTINCTS ONE TO ONE**...*Unclassified Establishments*
930 **DECK SUPPLY WAREHOUSE**...*Patio Equipment & Supplies*
930 **DGT NETWORKS**...*Information Technology Services*
930 **DVPRO PAINTING INC**...*Painters*
930 **GUY'S BARBER SHOP**...*Barbers*
930 **HERB W HANS LAW OFFICES**...*Offices Of Lawyers*
930 **KADON TRUCKING INC**...*Trucking*
930 **LATINO SERVICE PROVIDERS**...*Social Service & Welfare Organizations*
930 **LEE, JOHN MD**...*Physicians & Surgeons*
930 **LEE, JOHN MD**...*Physicians & Surgeons*
930 **LOVE YOUR NEIGHBOR**...*Unclassified Establishments*
930 **MENDOCINO MASONRY INC**...*Concrete Blocks & Shapes (whls)*
930 **MIDWEST TOWERS**...*Cooling Towers*
930 **MIRACLE BOOKKEEPING**...*Accounting & Bookkeeping General Svc*
930 **NORCAL VETERINARY PRACTICES**...*Veterinarians*
930 **NORTH BAY CONCRETE INC**...*Concrete Contractors*
930 **NORTH COAST STEEL**...*Welding & Steel Fabrication*
930 **NORTH COAST STEEL**...*Commercial & Institutional Building Construction*
930 **PAULSON EXCAVATING**...*Contractors-engineering General*
930 **PRECISION WIRELESS SVC**...*Cellular Telephones (services)*
930 **PRO-TECH COMPUTERS**...*Computer & Equipment Dealers*
930 **PRO-TECH COMPUTERS**...*Computers-service & Repair*
930 **RIDGELINE ROOFING CO**...*Roofing Contractors*
930 **RIGDELINE ROOFING**...*Roofing Contractors*
930 **SCIENTIFIC SANITATION SYSTEMS**...*Septic Tanks*
930 **SHILOH GROUP LLC**...*Industrial Developments*
930 **SONOMA COUNTY FARM TRAILS**...*Grocers-wholesale*
930 **STRAIGHT LINE FENCE CO**...*Fence Contractors*
930 **TILLETT TOOL & SUPPLY**...*Tools (whls)*
930 **TILLETT TOOL & SUPPLY**...*Drilling & Boring Equip & Supls (whls)*
930 **TJ NELSON ASSOC INC**...*Offices Of Real Estate Agents & Brokers*
930 **TJ NELSON & ASSOC INC**...*Real Estate*
930 **TRANS TECH CONSULTANTS**...*Environmental & Ecological Services*
930 **TRANS TECH CONSULTANTS**...*Engineers-consulting*
930 **TRU GREEN**...*Lawn & Grounds Maintenance*
930 **WEINSTEIN SECURITY INC**...*Security Guard & Patrol Service*
930 **WEINSTEIN SECURITY INC**...*Burglar Alarm Systems (whls)*
930 **WEINSTEIN SERCURITY INC**...*Security Systems Consultants*
930 **WEINSTEIN, MAUREEN CPA**...*Tax Return Preparation & Filing*
930 **WEINSTEIN, MAUREEN CPA**...*Accountants*

2012
SOURCE: DIGITAL BUSINESS DIRECTORY

CALETTI AVENUE

510 **QUALITY STAINLESS TANKS**...*Tanks-manufacturers*
584 **BATT'S TIP TOP SVC INC**...*Tree Service*
590 **KER PLUNK SANITARY**...*Toilets-portable*
590 **M & M SVC**...*Garbage Collection*

2012
SOURCE: DIGITAL BUSINESS DIRECTORY

DAY SCHOOL PLACE

NO LISTING FOUND FOR THIS YEAR...

5891 **WINDSOR PRESBYTERIAN CHURCH**...*Churches*
5900 **STANDARD STRUCTURES**...*Metal Finishers (mfrs)*
5900 **WINEWOOD PRODUCTS**...*Remodeling & Repairing Bldg Contractors*
5922 **NORTHGATE READY MIX**...*Concrete Contractors*

930 **ACCESS BOOKKEEPING CONSULTING**...*Accounting & Bookkeeping General Svc*
930 **BLACK POINT ENVIRONMENTAL**...*Environmental & Ecological Services*
930 **CAMERON**...*Oil Well Services*
930 **COMMUNICATIONS WORKERS-AMERICA**...*Labor Organizations*
930 **DGT NETWORKS**...*Information Technology Services*
930 **GRAVENSTEIN APPLE FAIR**...*Carnivals*
930 **GUY'S BARBER SHOP**...*Barbers*
930 **GUY'S FENCING**...*Fence Contractors*
930 **KADON TRUCKING INC**...*Trucking*
930 **LANDESIGN CONSTRUCTION & MNTNC**...*General Contractors*
930 **LATINO SERVICE PROVIDERS**...*Social Service & Welfare Organizations*
930 **MENDOCINO MASONRY INC**...*Concrete Blocks & Shapes (whls)*
930 **MIRACLE BOOKKEEPING**...*Accounting & Bookkeeping General Svc*
930 **NORCAL VETERINARY PRACTICES**...*Veterinarians*
930 **NORTH BAY CONCRETE INC**...*Concrete Breaking Cutting & Sawing & Etc*
930 **NORTH COAST STEEL**...*Welding & Steel Fabrication*
930 **PRECISION WIRELESS SVC**...*Radio Communication Equip & Systems-whls*
930 **PRO-TECH COMPUTERS**...*Computer & Equipment Dealers*
930 **RKA LUGGAGE**...*Motorcycles & Motor Scooters-accessories*
930 **TILLETT TOOL & SUPPLY**...*Drilling & Boring Equip & Supls (whls)*
930 **TRANS TECH CONSULTANTS**...*Engineers-consulting*
930 **VOYAGER & CARAVAN SPECIALTIES**...*Automobile Repairing & Service*
930 **WEINSTEIN SECURITY INC**...*Security Guard & Patrol Service*
930 **WEINSTEIN, MAUREEN CPA**...*Accountants*

2008
SOURCE: DIGITAL BUSINESS DIRECTORY

CALETTI AVENUE

510 **QUALITY STAINLESS TANKS**...*Tanks-manufacturers*
510 **QUALITY STAINLESS TANKS**...*Fabricated Plate Wk*
590 **GRIABB LEASING INC**...*Eqp Rental, Leasing*
590 **KER PLUNK SANITARY**...*Eqp Rental, Leasing*
590 **KER PLUNK SANITATION**...*Waste Disposal*
590 **M & M SVC**...*Refuse Coll/disp Svcs*
590 **M & M SVC**...*Landscape Contractors*

2008
SOURCE: DIGITAL BUSINESS DIRECTORY

DAY SCHOOL PLACE

NO LISTING FOUND FOR THIS YEAR...

5900 **STANDARD STRUCTURES**...*Real Estate Agt,mgr*
5900 **WINDSOR PRESBYTERIAN CHURCH**...*Presbyterian Church*

68 total records. *Part 1 of 2*

930 **ACCOUNTING PLUS**...*Accountants*
930 **BATTERY SYSTEMS**...*Elc Apparatus & Eqp*
930 **BATTERY SYSTEMS**...*Batteries-dry Cell-wholesale*
930 **BLACK POINT ENVIRONMENTAL**...*Coml Physical Resch*
930 **BORG FENCES**...*Fence Contractors*
930 **CAMERON**...*Oil Well Services*
930 **CAMERON**...*Oil Field Svcs Nec*
930 **CARAVAN & VOYOGER SPECIALTIES**...*Automobile Repairing & Service*
930 **CARAVAN & VOYOGER SPECIALTIES**...*General Auto Repair*
930 **COKAS DIKO WAREHOUSE**...*Warehouses-merchandise & Self Storage*
930 **COMMUNICATIONS WORKERS-AMERICA**...*Labor Organizations*
930 **COMMUNICATIONS WORKERS-AMERICA**...*Labor Organizations*
930 **COOPER CAMERON CORPORATION**...*Mfg Oil & Gas Drilling Equipment*
930 **DATA INSTINCTS ONE TO ONE MKTG**...*Marketing Consultants*
930 **FARMERS SEPTIC**...*Septic Tanks Consultants*
930 **FCI**...*Construction Consultants*
930 **FCI**...*Comm/off Bldg New Con*
930 **HANS HERB LAW OFFICES**...*Attorneys*
930 **HUN INC**...*Commodity Brokers*
930 **JOHN EVERS PRECISION WIRELESS**...*Radio Communication Equip & Systems-whol*
930 **KADON TRUCKING INC**...*Trucking*
930 **KADON TRUCKING INC**...*Trucking*
930 **MAUREEN WEINSTEIN CPA**...*Accountants*
930 **MAUREEN WEINSTEIN CPA**...*Acctg audit bkkeep*
930 **MC CLURES CONSTRUCTION ELCTRC**...*Electrical Work*
930 **MC CLURES CONSTRUCTION ELEC**...*Electric Contractors*
930 **MENDOCINO MASONRY INC**...*Concr cinder Bldg Pds*
930 **MIDWEST TOWERS INC**...*Plbg Htg Ac Contr*
930 **MIRACLE BOOKKEEPING**...*Accounting & Bookkeeping General Svc*
930 **MIRACLE BOOKKEEPING**...*Calculat & Stat Ser*
930 **NORTHBAY VEHICLE REGISTRATION**...*License Services*
930 **PACIFIC COOLING SVC**...*Cooling Towers*
930 **PACIFIC TEC PROGRESSIVE SLTNS**...*Nonclassified Establishments*
930 **PAULSON EXCAVATING**...*Excavation Work*
930 **PERMANENT COSEMTICS BY CAROL**...*Beauty Salons*
930 **PRECISION WIRELESS SVC**...*Radio Comm Eqp/supps*
930 **PRO-TECH COMPUTERS**...*Computer softwr Str*
930 **RAMSEY STUDIOS INC**...*Photo Studio*
930 **RANCHO FELIZ VINEYARDS**...*Vineyards*
930 **RIP READ**...*Unclassified*
930 **RKA LUGGAGE**...*Motorcycle Parts acc*
930 **RLS FIRE PROTECTION SYSTEMS**...*Fire Departments*
930 **RON HOGNESTAD CONSTRUCTION SVC**...*Const civil Engineers*
930 **RON HOGNESTAD CONSTRUCTION SVC**...*Contractors-engineering General*
930 **SCIENTIFIC SANITATION SYSTEMS**...*Septic Tanks Consultants*
930 **SCIENTIFIC SANITATION SYSTEMS**...*Plbg Htg Ac Contr*
930 **SHILOH GROUP LLC**...*Real Estate Agent/manager*
930 **SPORT UTILITY TRAILERS COM**...*Recreational Vehicles-equip/parts/svc*
930 **STRAIGHT LINE FENCE CO**...*Fence Contractors*
930 **SUPERIOR PLANT SVC**...*Business Svs Nec*
930 **T J NELSON & ASSOC INC**...*Real Estate Agt mgr*
930 **T J NELSON & ASSOC INC**...*Real Estate*
930 **TCM**...*Machine Shops*

2008
SOURCE: DIGITAL BUSINESS DIRECTORY

SHILOH ROAD

Part 2 of 2

930 **TILLETT TOOL & SUPPLY**...*Tools (wholesale)*
930 **TILLETT TOOL SUPPLY**...*Mats Handling Machnry*
930 **TRANS TECH CONSULTANTS**...*Consulting Engineer*
930 **TRANS TECH CONSULTANTS**...*Environmental & Ecological Services*
930 **TRU GREEN CORP**...*Lawn & Garden Svs*
930 **TRUGREEN LANDCARE**...*Landscape Contractors*
930 **VOYAGER & CARAVAN SPECIALTIES**...*General Auto Repair*
930 **WEINSTEIN SECURITY INC**...*Security Guard & Patrol Service*
930 **WEINSTEIN SECURITY INC**...*Guard & Patrol Serv*
930 **WESCO DISTRIBUTING INC**...*Conduits & Conduit Fittings (wholesale)*
930 **WESCO DISTRIBUTING INC**...*Elc Apparatus & Eqp*
930 **WESTERN WINDOWS & DOORS INC**...*Ret And Whol Building Material*
930 **WINDOW HAVEN**...*Door,window Products*
930 **WINDOW HAVEN**...*Windows-plastic*
930 **WOLF WEITZMAN STUDIOS**...*Mfg Precious Metal Jewelry*

2006
SOURCE: HAINES

CALETTI AVENUE

584 **BAITS TIP TOP SERVICE INC**
584 **TIP TOP SERVICE INC**
584 **TIP TOP TREE SERVICE**
590 **M & M SERVICES INC**

2006
SOURCE: HAINES

DAY SCHOOL PLACE

STREET NOT LISTED

2006
SOURCE: HAINES

PRUITT AVENUE

STREET NOT LISTED

2006
SOURCE: HAINES

SHILOH ROAD

705	DESAI NITIN
895	OLUFS HERBERT
899	OLUFS RICK
920	HENDERSON BILL
926	ALAN PRECISION MACHINE & TOOL CO
926	INNERSPACE DIVE & TRAVEL
930	ALLPHASE CONCRETE
930	BUILDING
930	CAMERON
930	COMNCTN WRKRS OF AM UN LCL
930	FCI
930	H & H EXCAVATION
930	HERNING UNDERGROUND SUPPLY
930	KADON TRUCKING
930	LAW OFFICES OF HANS HERB
930	MAGEE KEN PLASTERING & GENL BLDG
930	MCCLURES CONSTRUCTION ELECTRIC
930	MIDWEST TOWERS
930	MIDWEST TOWERS INC
930	MIRACLE BOOKKEEPING
930	NELSON T J & ASSOCIATES RL EST
930	NELSONT J & ASSOCIATES INC
930	NORCAL VETERINARY PRACTICES
930	PRECISION WRELESS SERVICE
930	RANCHO FELIZ VINEYARDS
930	RKA LUGGAGE
930	SCIENTIFIC SANITATION SYSTEMS
930	SHAMROCK MATERIALE INC WINDSOR
930	SHILOH CEMETERY DISTRICT
930	SHILOH GROUP LLC
930	TILLETT TOOL & SUPPLY
930	TILLETT TOOLS SUPPLY INC
930	VOYAGER & CARAVAN SPECIALTIES
930	WEINSTEIN MAUREEN CPA
930	WEINSTEIN SECURITY INC
930	WINDOW HAVEN
1010	WINE ALLIANCE

2000
SOURCE: HAINES

CALETTI AVENUE

510	QUALITY STAINLESS TANKS
590	LOUIE'S IRON WORKS

2000
SOURCE: HAINES

DAY SCHOOL PLACE

STREET NOT LISTED

2000
SOURCE: HAINES

PRUITT AVENUE

STREET NOT LISTED

2000
SOURCE: HAINES

SHILOH ROAD

701	XXXX
895	OLUFS HERBERT
899	QUES RICK
912	XXXX
914	XXXX
916	KENWOOD FENCE CO
918	XXXX
920	ADAMS ENTERPRISES
922	XXXX
926	ALAN PRECISION MACHIN & STOOL CO
928	XXXX
930	B A C E ANALYTICAL & FLD SRV INC
930	B A C E GEOTECHNICAL
930	BACE ANALYTICAL & RELD SERV INC
930	BRUNSING ASSOCIATES INC
930	BUILDING
930	COM TRANSPORTATION
930	DEN BESTE TRANSPORTANON INC
930	EMPIRE TOWING SERVICE
930	FIRE PROTECTION UNLIMITED
930	FORMATIVE FERTILIZER INC
930	H U N INC
930	KADON TRUCKING
930	MARTIN'S TRUCK REPAIR
930	PAC COOLING SERVICES
930	REOWD SANITARY SERVICE
930	SCIENTIFIC SANITATION SYSTEMS
930	WARREN'S WELDING & REPAIR INC
930	WINDOW HAVEN
960	XXXX

1995
SOURCE: HAINES

CALETTI AVENUE

960	SOCO STEEL FBRCTRS

1995
SOURCE: HAINES

DAY SCHOOL PLACE

STREET NOT LISTED

1995
SOURCE: HAINES

PRUITT AVENUE

STREET NOT LISTED

1995
SOURCE: HAINES

SHILOH ROAD

701	XXXX
706	XXXX
895	OLUFS HORBERT
899	OLUFS RICK
912	PAC CONCRETE PRDCTS
914	XXXX
918	COUSINS AUTOMOTIVE
920	BUTCHER BLOCK TABLE
922	XXXX
926	ALAN PRCSN MACH CO
928	XXXX
930	ADAMS ENTERPRISES
930	B A C E ANAL {&} FLD SV
930	B A C E GEOTECHNICL
930	BACE ANLYTCLAFLD SV
930	BRUNSING ASSOCIATES
930	BUILDING
930	CARPENTER DONALDO
930	EVANS RALPH
930	KADON TRUCKING
930	NORTH CST STRUCTURE
930	PAC COOLING SERVICE
930	R A D AUTO SALES
930	REDWD SANITARY SERV
930	RELIANCE PAINTING
930	SHAMROCK MTRLS INC
960	XXXX

1990
SOURCE: HAINES

CALETTI AVENUE

STREET NOT LISTED

1990
SOURCE: HAINES

DAY SCHOOL PLACE

STREET NOT LISTED

1990
SOURCE: HAINES

PRUITT AVENUE

STREET NOT LISTED

1990
SOURCE: HAINES

SHILOH ROAD

371	XXXX
701	VICS AUTOWTV RPR
705	XXXX
895	OLUFS HERBERT
899	OLUFS RICK
912	PAC CONCRETE PROCTS
914	XXXX
918	MINI G AUTO RSTRTN
920	XXXX
922	COUSINS VNTG MOTORS
924	RESAW CITY CO
926	ALAN PRCSN MACH CO
928	XXXX
930	AUTO VISION
930	AVENDT GROUP THE
930	BIG SKY SUNROOMS
930	BUILDING
930	CALVARY CHAPEL
930	CLEAR WTR ENYRNMNTL
930	EDDIE RALPH
930	HUDSON CONSOLIDATED
930	HUDSON HOMES INC
930	HUDSON PLASTERING
930	NAIL COUNTY LENCI
930	NEW HOPE CHRISTIAN
930	REDWD CONCRETE INC
930	REDWD EMP CONST INC
930	ROYAL COMFORT DSGNS
930	RURAL HEALTH EDCTN
930	SCIENTIFIC SANITATN
930	SHAMROCK MTRLS INC
930	SHILOH INDSTRL PARK
930	SPIFFY JANITRL SERV
930	STAMCO INC
930	THERMAL SUN GLASS
930	VALLEY ENGINEERS
930	WESTRN FIBERGLASS
1010	XXXX

1985
SOURCE: HAINES

CALETTI AVENUE

STREET NOT LISTED

1985
SOURCE: HAINES

DAY SCHOOL PLACE

STREET NOT LISTED

1985
SOURCE: HAINES

PRUITT AVENUE

STREET NOT LISTED

1985 *SOURCE: HAINES*

SHILOH ROAD

371	**KINYON JAS**
705	**XXXX**
895	**OLUFS HERBERT**
899	**OLUFS RICK**
920	**SIERRA WESTERN RAIL**
922	**WOOD ROOF STRUCTURS**
928	**XXXX**
930	**ECODYNE COOLING**
1010	**PIOMBO CORP HOTPLNT**
1010	**PIOMBO CORPORATION**

1981 *SOURCE: HAINES*

CALETTI AVENUE

STREET NOT LISTED

1981
SOURCE: HAINES

DAY SCHOOL PLACE

STREET NOT LISTED

1981
SOURCE: HAINES

PRUITT AVENUE

STREET NOT LISTED

1981
SOURCE: HAINES

SHILOH ROAD

371	**DAVIS KODENKAN**
705	**MURPHY PATRICIA D**
895	**OLUFS HEABEAT**
920	**WOOD ROOF STAUCTURE**
928	**EILERS J J LMBR PRD**
930	**ECODYNE COOLING DIV**
1010	**PIOMBO CORPORATION**

1975
SOURCE: HAINES

CALETTI AVENUE

STREET NOT LISTED

1975
SOURCE: HAINES

DAY SCHOOL PLACE

STREET NOT LISTED

1975
SOURCE: HAINES

PRUITT AVENUE

STREET NOT LISTED

1975
SOURCE: HAINES

SHILOH ROAD

371 **XXXX**
705 **REARDEN ROBT M**
705 **STURGIS & SONS MBL SV**
895 **OLUFS HERBERT**
920 **POTLATCH FORESTS**
920 **SPEEDSPACE CORP**
928 **EILERS J J LMBR PRD**
930 **ECODYNE COOLING PRD**
1010 **XXXX**

1972
SOURCE: HAINES

CALETTI AVENUE

STREET NOT LISTED

1972
SOURCE: HAINES

DAY SCHOOL PLACE

STREET NOT LISTED


1972
SOURCE: HAINES

PRUITT AVENUE

STREET NOT LISTED

371 **EDSELL J MRS**
705 **FORD VERNON E**
895 **OLUFS HERBERT**
920 **POTLATCH FORESTS**
920 **SPEEDSPACE CORP**
930 **ECODYNE COOLING PRD**
930 **FLUOR PRODUCTS CO**
1010 **LOAMITE CORPORATION**

--- END REPORT ---




1933

Quadrangle(s): Healdsburg, CA

Order No. 21111700210

Source: USGS 15 Minute Topographic Map




1940

Quadrangle(s): Healdsburg, CA

Order No. 21111700210

Source: USGS 15 Minute Topographic Map




1955 [1] *Aerial Photo Year: 1953*

Quadrangle(s): Healdsburg, CA[1]

Order No. 21111700210

Source: USGS 15 Minute Topographic Map




1980 [1]
Aerial Photo Year: 1976
Photo Revision Year: 1980

Quadrangle(s): Healdsburg, CA[1]

Order No. 21111700210

Source: USGS 7.5 Minute Topographic Map




1993 (1) *Aerial Photo Year: 1987*

Quadrangle(s): Healdsburg, CA(1)

Order No. 21111700210

Source: USGS 7.5 Minute Topographic Map



2015

Quadrangle(s): Healdsburg, CA

Order No. 21111700210

Source: USGS 7.5 Minute Topographic Map

COMMUNITY DEVELOPMENT DEPARTMENT
DIVISION OF BUILDING INSPECTION

9291 Old Redwood Highway, Bldg. 400
Windsor, CA 95492-0100
Inspection Request Line: 707-522-8346
Clif Castle, Building Official, 707-838-5341

PERMIT NUMBER

B10-0139

790 SHILOH

LICENSED CONTRACTOR'S DECLARATION

I hereby affirm under penalty of perjury that I am licensed under provisions of Chapter 9 (commencing with Section 7000) of Division 3 of the Business and Professions Code, and my license is in full force and effect.
Contractor Name and Address: WIRELESS ALCHEMY

License Class: ___ Lic. No.: _____ Signature: _____

OWNER BUILDER DECLARATION

(__) I hereby afirm under penalty of perjury that I am exempt from the Contractor's License Law for the following reason (Section 7031.5, Business and Professions Code: Any city or county that requires a permit to construct, alter, improve, demolish, or repair any structure, prior to its issuance, also requires the applicant for the permit to file a signed statement that he or she is licensed pursuant to the provisions of the Contractors License Law (Chapter 9 (commencing with Section 7000) of Division 3 of the Business and Professions Code) or that he or she is exempt therefrom and the basis for the alleged exemption. Any violation of Section 7031.5 by any applicant for a permit subjects the applicant to a civil penalty of not more that five hundred dollars ($500).):

(__) I, as owner of the property, or my employees with wages as their sole compensation, will do **(__)** all of or **(__)** portions of the work, and the structure is not intended or offered for sale (Section 7044, Business and Professions Code: The Contractor's License Law does not apply to an owner of property who builds or improves thereon, and who does the work himself or herself or through his or her own employees, provided that the improvements are not intended or offered for sale. If, however, the building or improvement is sold within one year of completion, the owner-builder will have the burden of proving that he or she did not build or improve for the purpose of sale.)

(__) I, as owner, of the property, am exclusively contracting with licensed contractors to construct the project (Section 7044, Business and Professions Code: The Contractor's License Law does not apply to an owner of property who builds or improves thereon and who contracts for such projects with a contractor(s) licensed pursuant to the Contractor's License Law.)

(__) I am exempt from licensure under the Contractors' State License Law for the following reason:

By my signature below I acknowledge that, except for my personal residence in which I must have resided for at least one year prior to completion of the improvements covered by this permit, I cannot legally sell a structure that I have built as an owner-builder if it has not been constructed in its entirety by licensed contractors. I understand that a copy of the applicable law, Section 7044 of the Business and Professions Code, is available upon request when this application is submitted or at the following Web site: http://www.leginfo.ca.gov/calaw.html.

Property Owner or Authorized Agent signature: _____

WARNING: FAILURE TO SECURE WORKERS' COMPENSATION COVERAGE IS UNLAWFUL, AND SHALL SUBJECT AN EMPLOYER TO CRIMINAL PENALTIES AND CIVIL FINES UP TO ONE HUNDRED THOUSAND DOLLARS ($100,000), IN ADDITION TO THE COST OF COMPENSATION, DAMAGES AS PROVIDED FOR IN SECTION 3706 OF THE LABOR CODE, INTEREST, AND ATTORNEY'S FEES.

WORKER'S COMPENSATION DECLARATIONS

I hereby affirm under penalty of perjury one of the following declarations:

(__) I have and will maintain a certificate of consent to self-insure, for workers' compensation, as provided for by Section 3700 of the Labor Code, for the performance of the work for which this permit is issued. Policy No.

(__) I have and will maintain workers' compensation insurance, as required by Section 3700 of the Labor Code, for the performance of the work for which this permit is issued. My workers' compensation insurance carrier and policy number are:
Carrier: _____ Policy No.: _____ Expiration Date: _____

Name of Agent: _____ Telephone No: _____

(__) I certify that, in the performance of the work for which this permit is issued, I shall not employ any person in any manner so as to become subject to the workers' s compensation laws of California, and agree that, if I should become subject to the workers' compensation provisions of Section 3700 of the Labor Code, I shall forthwith comply with those provisions.

DECLARATION REGARDING CONSTRUCTION LENDING AGENCY

I hereby affirm under penalty of perjury that there is a construction lending agency for the performance of the work for which this permit is issued (Sec. 3097, Civil. Code).
Lender's Name and Address: _____

DECLARATION BY CONSTRUCTION PERMIT APPLICANT

By my signature below, I certify to each of the following:

I am **(__)** a California Licensed contractor or **(__)** the property owner or **(__)** authorized to act on the property owner's behalf.
I have read this construction permit application and the information I have provided is correct.
I agree to comply with all applicable city and county ordinances and state laws related to building construction.
I authorize representatives of the Town of Windsor to enter the above-identified property for inspection purposes.

Signature _____ **Date** _____

BUILDING DEPARTMENT

Date Issued	Valuation	Lot	APN
4/22/2010	$5,000.00		059-271-084

790 SHILOH

OWNER:
CALETTI, RICHARD C & FLORAMAY
PO BOX K
SANTA ROSA CA CA 95402013

CONTRACTOR:
WIRELESS ALCHEMY

DESCRIPTION OF WORK:
INSTALL FIBER BOX ON (E) CELL FACILITY

Effective July 1, 2011, California Law requires all residential home owners to install carbon monoxide detectors.

1. This permit SHALL EXPIRE (2) two years from the date of issuance.
2. Request inspections for each phase of the work prior to the commencement of the next stage. All work must be left exposed for inspection and approved before covering.
3. Request inspections by calling **(707) 522-8346** at least 24 hours in advance from the Building Inspection Division for each phase of work.
4. Keep the approved plans on the job for inspection.

PERMIT ISSUED SUBJECT TO CONDITIONS:

DESCRIPTION AND FEES:

BUILDING PERMIT FEE - 1	010-62-00-0000-3220-000	$61.60
ELECTRICAL PERMIT FEE	010-62-00-0000-3220-000	$24.16
SCANNING FEE- 3801	010-62-00-0000-3801-000	$15.80

Total Fees	$101.56
Paid	$101.56
Total Due	$0.00

PSR
PHYSICAL SETTING REPORT

Property Information

Order Number:		21111700210p
Date Completed:		November 18, 2021
Project Number:		21-347251.1
Project Property:		790 Shiloh Road 790 Shiloh Road WINDSOR CA 95492
Coordinates:		
	Latitude:	38.52072644
	Longitude:	-122.78749577
	UTM Northing:	4263614.66355 Meters
	UTM Easting:	518524.615008 Meters
	UTM Zone:	UTM Zone 10S
	Elevation:	120.00 ft
	Slope Direction:	W

Topographic Information....2
Hydrologic Information....12
Geologic Information....15
Soil Information....17
Wells and Additional Sources....26
  Summary....31
  Detail Report....43
Radon Information....253
Appendix....254
Liability Notice....256


The ERIS ***Physical Setting Report - PSR*** provides comprehensive information about the physical setting around a site and includes a complete overview of topography and surface topology, in addition to hydrologic, geologic and soil characteristics. The location and detailed attributes of oil and gas wells, water wells, public water systems and radon are also included for review.

The compilation of both physical characteristics of a site and additional attribute data is useful in assessing the impact of migration of contaminants and subsequent impact on soils and groundwater.

Disclaimer

This Report does not provide a full environmental evaluation for the site or adjacent properties. Please see the terms and disclaimer at the end of the Report for greater detail.

Topographic Information



Current USGS Topo (2015)


0 0.2 0.4 0.8 1.2 1.6 Miles

N

Quadrangle(s): Camp Meeker,CA; Guerneville,CA; Healdsburg,CA; Mark West Springs,CA; Santa Rosa,CA; Sebastopol,CA

Source: USGS 7.5 Minute Topographic Map

Topographic Information



Current USGS Topo - Page 1


0 0.2 0.4 0.8 Miles

N

Quadrangle(s): Healdsburg,CA

Source: USGS 7.5 Minute Topographic Map

Topographic Information



Current USGS Topo - Page 2


0 0.2 0.4 0.8 Miles

N

Quadrangle(s): Healdsburg,CA; Mark West Springs,CA

Source: USGS 7.5 Minute Topographic Map

Topographic Information



Current USGS Topo - Page 3


0 0.2 0.4 0.8 Miles

N

Quadrangle(s): Healdsburg,CA

Source: USGS 7.5 Minute Topographic Map

Topographic Information



Current USGS Topo - Page 4

0 0.2 0.4 0.8 Miles

N

Quadrangle(s): Healdsburg,CA; Mark West Springs,CA


Source: USGS 7.5 Minute Topographic Map

Topographic Information


The previous topographic map(s) are created by seamlessly merging and cutting current USGS topographic data. Below are shaded relief map(s), derived from USGS elevation data to show surrounding topography in further detail.

Topographic information at project property:


Elevation:	120.00 ft
Slope Direction:	W




Topographic Information




Topographic Information




Topographic Information



Topographic Information



Hydrologic Information



Wetland

Miles
0 0.1 0.2 0.4


N

This map shows wetland existence using data from US Fish & Wildlife.
Data coverage is shown to the right. Gray indicates no data available in the area.

- Estuarine and Marine Deepwater
- Estuarine and Marine Wetland
- Freshwater Emergent Wetland
- Freshwater Forested/Shrub Wetland
- Freshwater Pond
- Lake
- Other
- Riverine

ERIS

Hydrologic Information




Flood Hazard Zones

This map shows FEMA flood hazard zones. FIRM panels are shown to the right, and blank indicates no data is available.

Miles
0 0.2 0.4

A	AO	X
A99	V	OPEN WATER
AE	VE	NOT POPULATED
AH	D	AREA NOT INCLUDED

N



ERIS

Hydrologic Information

The Wetland Type map shows wetland existence overlaid on an aerial imagery. The Flood Hazard Zones map shows FEMA flood hazard zones overlaid on an aerial imagery. Relevant FIRM panels and detailed zone information is provided below.
For detailed Zone descriptions please click the link: https://floodadvocate.com/fema-zone-definitions

Available FIRM Panels in area:	06097C0568E(effective:2008-12-02) 06097C0569E(effective:2008-12-02) 06097C0566E(effective:2008-12-02) 06097C0567E(effective:2008-12-02)

Flood Zone AE-01

Zone:	AE
Zone subtype:	

Flood Zone AE-11

Zone:	AE
Zone subtype:	FLOODWAY


Flood Zone X-01

Zone:	X
Zone subtype:	0.2 PCT ANNUAL CHANCE FLOOD HAZARD

Flood Zone X-12

Zone:	X
Zone subtype:	AREA OF MINIMAL FLOOD HAZARD

Geologic Information



Miles
0 0.2 0.4

N

Geologic Units

This maps shows geologic units in the area. Please refer to the report for detailed descriptions.

ERIS

Geologic Information

The previous page shows USGS geology information. Detailed information about each unit is provided below.


Geologic Unit Q

Unit Name:	Quaternary alluvium and marine deposits
Unit Age:	Pliocene to Holocene
Primary Rock Type:	alluvium
Secondary Rock Type:	terrace
Unit Description:	Alluvium, lake, playa, and terrace deposits; unconsolidated and semi-consolidated. Mostly nonmarine, but includes marine deposits near the coast.

Geologic Unit QPc

Unit Name:	Plio-Pleistocene and Pliocene loosely consolidated deposits
Unit Age:	Miocene to Pleistocene
Primary Rock Type:	sandstone
Secondary Rock Type:	conglomerate
Unit Description:	Pliocene and/or Pleistocene sandstone, shale, and gravel deposits; in part Miocene.

Soil Information



SSURGO Soils

0 0.2 0.4 Miles

N

This maps shows SSURGO soil units around the target property. Please refer to the report for detailed soil descriptions.

ERIS

Soil Information

The previous page shows a soil map using SSURGO data from USDA Natural Resources Conservation Service. Detailed information about each unit is provided below.

Map Unit AeA (0.6%)

Map Unit Name:	Alluvial land, clayey
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	
Drainage Class - Dominant:	Well drained
Hydrologic Group - Dominant:	
Major components are printed below	
Alluvial land(85%)	
horizon H1(0cm to 25cm)	Clay loam
horizon H2(25cm to 76cm)	Stratified clay loam to clay
horizon H3(76cm to 152cm)	Stratified very gravelly sand to sand

Component Description:

Minor map unit components are excluded from this report.

Map Unit: AeA - Alluvial land, clayey

Component: Alluvial land (85%)
Generated brief soil descriptions are created for major soil components. The Alluvial land is a miscellaneous area.

Component: Unnamed (15%)
Generated brief soil descriptions are created for major soil components. The Unnamed soil is a minor component.

Map Unit CeA (0.84%)

Map Unit Name:	Clear Lake clay, sandy substratum, 0 to 2 percent slopes, MLRA 14
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	91cm
Drainage Class - Dominant:	Poorly drained
Hydrologic Group - Dominant:	D - Soils in this group have high runoff potential when thoroughly wet. Water movement through the soil is restricted or very restricted.
Major components are printed below	
Clear Lake(85%)	
horizon Apg1(0cm to 5cm)	Clay
horizon Apg2(5cm to 20cm)	Clay
horizon Assg(20cm to 63cm)	Clay
horizon Bssg1(63cm to 99cm)	Clay
horizon Bssg2(99cm to 117cm)	Clay
horizon Bkssg(117cm to 132cm)	Clay
horizon 2Bkg(132cm to 152cm)	Clay loam
horizon 2Btg(152cm to 183cm)	Fine sandy loam
horizon 2C(183cm to 213cm)	Loamy coarse sand

Component Description:

Minor map unit components are excluded from this report.

Map Unit: CeA - Clear Lake clay, sandy substratum, drained, 0 to 2 percent slopes, MLRA 14

Soil Information

Component: Clear Lake (85%)
The Clear Lake, drained, sandy substratum component makes up 85 percent of the map unit. Slopes are 0 to 2 percent. This component is on flood basin floors on valleys. The parent material consists of basin alluvium derived from volcanic and sedimentary rock over fan alluvium derived from volcanic and sedimentary rock. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is poorly drained. Water movement in the most restrictive layer is moderately low. Available water to a depth of 60 inches (or restricted depth) is high. Shrink-swell potential is high. This soil is not flooded. It is frequently ponded. A seasonal zone of water saturation is at 36 inches during January, February. Organic matter content in the surface horizon is about 2 percent. Nonirrigated land capability classification is 3e. Irrigated land capability classification is 2e. This soil meets hydric criteria. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 4 within 30 inches of the soil surface.

Component: Haire (5%)
Generated brief soil descriptions are created for major soil components. The Haire soil is a minor component.

Component: Whight (5%)
Generated brief soil descriptions are created for major soil components. The Whight soil is a minor component.

Component: Reyes (5%)
Generated brief soil descriptions are created for major soil components. The Reyes soil is a minor component.

Map Unit CfA (4.47%)

Map Unit Name:	Clear Lake clay, ponded, 0 to 2 percent slopes
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	0cm
Drainage Class - Dominant:	Poorly drained
Hydrologic Group - Dominant:	C/D - These soils have moderately high runoff potential when drained and high runoff potential when undrained.

Major components are printed below

Clear Lake(85%)

horizon H1(0cm to 33cm)	Clay
horizon H2(33cm to 152cm)	Clay

Component Description:

Minor map unit components are excluded from this report.

Map Unit: CfA - Clear Lake clay, ponded, 0 to 2 percent slopes

Component: Clear Lake (85%)
The Clear Lake component makes up 85 percent of the map unit. Slopes are 0 to 2 percent. This component is on river valleys, basin floors. The parent material consists of alluvium derived from sedimentary rock. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is poorly drained. Water movement in the most restrictive layer is moderately low. Available water to a depth of 60 inches (or restricted depth) is moderate. Shrink-swell potential is high. This soil is not flooded. It is frequently ponded. A seasonal zone of water saturation is at 0 inches during January, February, March, April, November, December. Organic matter content in the surface horizon is about 3 percent. Nonirrigated land capability classification is 3w. Irrigated land capability classification is 3w. This soil meets hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 3 percent. There are no saline horizons within 30 inches of the soil surface.

Component: Whight (6%)
Generated brief soil descriptions are created for major soil components. The Whight soil is a minor component.

Component: Huichica (6%)
Generated brief soil descriptions are created for major soil components. The Huichica soil is a minor component.

Component: Zamora (3%)
Generated brief soil descriptions are created for major soil components. The Zamora soil is a minor component.

Map Unit HtA (29.2%)

Soil Information

Map Unit Name:	Huichica loam, 0 to 2 percent slopes
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	
Drainage Class - Dominant:	Moderately well drained
Hydrologic Group - Dominant:	C - Soils in this group have moderately high runoff potential when thoroughly wet. Water transmission through the soil is somewhat restricted.

Major components are printed below

Huichica(85%)

horizon H1(0cm to 36cm)	Loam
horizon H2(36cm to 58cm)	Sandy clay loam
horizon H3(58cm to 76cm)	Clay
horizon H4(76cm to 145cm)	Cemented

Component Description:

Minor map unit components are excluded from this report.

Map Unit: HtA - Huichica loam, 0 to 2 percent slopes

Component: Huichica (85%)
The Huichica component makes up 85 percent of the map unit. Slopes are 0 to 2 percent. This component is on uplifted terraces, hills. The parent material consists of alluvium derived from igneous, metamorphic and sedimentary rock. Depth to a root restrictive layer, duripan, is 20 to 40 inches. The natural drainage class is moderately well drained. Water movement in the most restrictive layer is low. Available water to a depth of 60 inches (or restricted depth) is low. Shrink-swell potential is moderate. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 1 percent. Nonirrigated land capability classification is 3s. Irrigated land capability classification is 3s. This soil does not meet hydric criteria.

Component: Unnamed (5%)
Generated brief soil descriptions are created for major soil components. The Unnamed soil is a minor component.

Component: Wright (3%)
Generated brief soil descriptions are created for major soil components. The Wright soil is a minor component.

Component: Haire (3%)
Generated brief soil descriptions are created for major soil components. The Haire soil is a minor component.

Component: Clear Lake (2%)
Generated brief soil descriptions are created for major soil components. The Clear Lake soil is a minor component.

Component: Zamora (2%)
Generated brief soil descriptions are created for major soil components. The Zamora soil is a minor component.

Map Unit HuB (18.28%)

Map Unit Name:	Huichica loam, ponded, 0 to 5 percent slopes
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	0cm
Drainage Class - Dominant:	Moderately well drained
Hydrologic Group - Dominant:	D - Soils in this group have high runoff potential when thoroughly wet. Water movement through the soil is restricted or very restricted.

Major components are printed below

Huichica(85%)

horizon H1(0cm to 36cm)	Loam
horizon H2(36cm to 58cm)	Sandy clay loam
horizon H3(58cm to 97cm)	Clay
horizon H4(97cm to 145cm)	Cemented

Component Description:

Soil Information

Minor map unit components are excluded from this report.

Map Unit: HuB - Huichica loam, ponded, 0 to 5 percent slopes

Component: Huichica (85%)
The Huichica component makes up 85 percent of the map unit. Slopes are 0 to 5 percent. This component is on hills, uplifted terraces. The parent material consists of alluvium derived from igneous, metamorphic and sedimentary rock. Depth to a root restrictive layer, duripan, is 20 to 40 inches. The natural drainage class is moderately well drained. Water movement in the most restrictive layer is low. Available water to a depth of 60 inches (or restricted depth) is low. Shrink-swell potential is moderate. This soil is not flooded. It is frequently ponded. A seasonal zone of water saturation is at 0 inches during January, February, March, April, November, December. Organic matter content in the surface horizon is about 1 percent. Nonirrigated land capability classification is 3w. Irrigated land capability classification is 3w. This soil meets hydric criteria.

Component: Clear Lake (5%)
Generated brief soil descriptions are created for major soil components. The Clear Lake soil is a minor component.

Component: Zamora (5%)
Generated brief soil descriptions are created for major soil components. The Zamora soil is a minor component.

Component: Wright (5%)
Generated brief soil descriptions are created for major soil components. The Wright soil is a minor component.

Map Unit HvC (8.43%)

Map Unit Name:	Huichica loam, shallow, 0 to 9 percent slopes
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	
Drainage Class - Dominant:	Moderately well drained
Hydrologic Group - Dominant:	D - Soils in this group have high runoff potential when thoroughly wet. Water movement through the soil is restricted or very restricted.

Major components are printed below

Huichica(85%)

horizon H1(0cm to 30cm)	Loam
horizon H2(30cm to 76cm)	Clay
horizon H3(76cm to 145cm)	Cemented

Component Description:

Minor map unit components are excluded from this report.

Map Unit: HvC - Huichica loam, shallow, 0 to 9 percent slopes

Component: Huichica (85%)
The Huichica component makes up 85 percent of the map unit. Slopes are 0 to 9 percent. This component is on hills, uplifted terraces. The parent material consists of alluvium derived from igneous, metamorphic and sedimentary rock. Depth to a root restrictive layer, duripan, is 20 to 40 inches. The natural drainage class is moderately well drained. Water movement in the most restrictive layer is low. Available water to a depth of 60 inches (or restricted depth) is very low. Shrink-swell potential is high. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 1 percent. Nonirrigated land capability classification is 4e. Irrigated land capability classification is 4e. This soil does not meet hydric criteria.

Component: Wright (7%)
Generated brief soil descriptions are created for major soil components. The Wright soil is a minor component.

Component: Zamora (6%)
Generated brief soil descriptions are created for major soil components. The Zamora soil is a minor component.

Component: Clear Lake (2%)
Generated brief soil descriptions are created for major soil components. The Clear Lake soil is a minor component.

Soil Information

Map Unit HwB (12.3%)

Map Unit Name:	Huichica loam, shallow, ponded, 0 to 5 percent slopes
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	0cm
Drainage Class - Dominant:	Moderately well drained
Hydrologic Group - Dominant:	D - Soils in this group have high runoff potential when thoroughly wet. Water movement through the soil is restricted or very restricted.

Major components are printed below

Huichica(85%)

horizon H1(0cm to 30cm)	Loam
horizon H2(30cm to 76cm)	Clay
horizon H3(76cm to 145cm)	Cemented

Component Description:

Minor map unit components are excluded from this report.

Map Unit: HwB - Huichica loam, shallow, ponded, 0 to 5 percent slopes

Component: Huichica (85%)
The Huichica component makes up 85 percent of the map unit. Slopes are 0 to 5 percent. This component is on hills, uplifted terraces. The parent material consists of alluvium derived from igneous, metamorphic and sedimentary rock. Depth to a root restrictive layer, duripan, is 20 to 40 inches. The natural drainage class is moderately well drained. Water movement in the most restrictive layer is low. Available water to a depth of 60 inches (or restricted depth) is very low. Shrink-swell potential is high. This soil is not flooded. It is frequently ponded. A seasonal zone of water saturation is at 0 inches during January, February, March, April, November, December. Organic matter content in the surface horizon is about 1 percent. Nonirrigated land capability classification is 4w. Irrigated land capability classification is 4w. This soil meets hydric criteria.

Component: Wright (7%)
Generated brief soil descriptions are created for major soil components. The Wright soil is a minor component.

Component: Zamora (6%)
Generated brief soil descriptions are created for major soil components. The Zamora soil is a minor component.

Component: Clear Lake (2%)
Generated brief soil descriptions are created for major soil components. The Clear Lake soil is a minor component.

Map Unit RnA (1.12%)

Map Unit Name:	Riverwash
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	0cm
Drainage Class - Dominant:	Excessively drained
Hydrologic Group - Dominant:	

Major components are printed below

Riverwash(85%)

horizon H1(0cm to 15cm)	Very gravelly sand
horizon H2(15cm to 152cm)	Stratified very gravelly coarse sand to very gravelly sand

Component Description:

Minor map unit components are excluded from this report.

Map Unit: RnA - Riverwash

Component: Riverwash (85%)
Generated brief soil descriptions are created for major soil components. The Riverwash is a miscellaneous area.

Soil Information

Component: Unnamed (15%)
Generated brief soil descriptions are created for major soil components. The Unnamed soil is a minor component.

Map Unit W (0.59%)

Map Unit Name: Water

No more attributes available for this map unit

Component Description:

Minor map unit components are excluded from this report.

Map Unit: W - Water

Component: Water (100%)
Generated brief soil descriptions are created for major soil components. The Water is a miscellaneous area.

Map Unit YoB (2.32%)

Map Unit Name: Yolo loam, overwash, 0 to 5 percent slopes

Bedrock Depth - Min:

Watertable Depth - Annual Min:

Drainage Class - Dominant: Well drained

Hydrologic Group - Dominant: B - Soils in this group have moderately low runoff potential when thoroughly wet. Water transmission through the soil is unimpeded.

Major components are printed below

Yolo(85%)

horizon H1(0cm to 20cm)	Loam
horizon H2(20cm to 152cm)	Loam

Component Description:

Minor map unit components are excluded from this report.

Map Unit: YoB - Yolo loam, overwash, 0 to 5 percent slopes

Component: Yolo (85%)
The Yolo component makes up 85 percent of the map unit. Slopes are 0 to 5 percent. This component is on alluvial fans, river valleys. The parent material consists of alluvium derived from sedimentary rock. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is moderately high. Available water to a depth of 60 inches (or restricted depth) is high. Shrink-swell potential is low. This soil is occasionally flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 3 percent. Nonirrigated land capability classification is 3w. Irrigated land capability classification is 2w. This soil does not meet hydric criteria. There are no saline horizons within 30 inches of the soil surface.

Component: Cortina (5%)
Generated brief soil descriptions are created for major soil components. The Cortina soil is a minor component.

Component: Zamora (5%)
Generated brief soil descriptions are created for major soil components. The Zamora soil is a minor component.

Component: Pleasanton (4%)
Generated brief soil descriptions are created for major soil components. The Pleasanton soil is a minor component.

Component: Unnamed (1%)
Generated brief soil descriptions are created for major soil components. The Unnamed soil is a minor component.

Map Unit YsA (7.64%)

Soil Information

Map Unit Name:	Yolo silt loam, 0 to 2 percent slopes
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	
Drainage Class - Dominant:	Well drained
Hydrologic Group - Dominant:	B - Soils in this group have moderately low runoff potential when thoroughly wet. Water transmission through the soil is unimpeded.

Major components are printed below

Yolo(85%)

horizon H1(0cm to 20cm)	Silt loam
horizon H2(20cm to 152cm)	Silt loam

Component Description:

Minor map unit components are excluded from this report.

Map Unit: YsA - Yolo silt loam, 0 to 5 percent slopes, MLRA 14

Component: Yolo (85%)
The Yolo component makes up 85 percent of the map unit. Slopes are 0 to 5 percent. This component is on alluvial fans on valleys. The parent material consists of alluvium derived from volcanic and sedimentary rock. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is moderately high. Available water to a depth of 60 inches (or restricted depth) is high. Shrink-swell potential is low. This soil is rarely flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 2 percent. Nonirrigated land capability classification is 3c. Irrigated land capability classification is 1 This soil does not meet hydric criteria. There are no saline horizons within 30 inches of the soil surface.

Component: Pleasanton (5%)
Generated brief soil descriptions are created for major soil components. The Pleasanton soil is a minor component.

Component: Pajaro (5%)
Generated brief soil descriptions are created for major soil components. The Pajaro soil is a minor component.

Component: Cortina (5%)
Generated brief soil descriptions are created for major soil components. The Cortina soil is a minor component.

Map Unit ZaA (14.22%)

Map Unit Name:	Zamora silty clay loam, 0 to 2 percent slopes
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	
Drainage Class - Dominant:	Well drained
Hydrologic Group - Dominant:	C - Soils in this group have moderately high runoff potential when thoroughly wet. Water transmission through the soil is somewhat restricted.

Major components are printed below

Zamora(85%)

horizon H1(0cm to 13cm)	Silty clay loam
horizon H2(13cm to 74cm)	Clay loam
horizon H3(74cm to 104cm)	Clay loam
horizon H4(104cm to 140cm)	Sandy clay loam
horizon H5(140cm to 152cm)	Gravelly clay

Component Description:

Minor map unit components are excluded from this report.

Map Unit: ZaA - Zamora silty clay loam, moist, 0 to 2 percent slopes, MLRA 14

Component: Zamora (85%)
The Zamora component makes up 85 percent of the map unit. Slopes are 0 to 2 percent. This component is on alluvial fans on

valleys, stream terraces on valleys. The parent material consists of alluvium derived from volcanic and sedimentary rock. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is moderately low. Available water to a depth of 60 inches (or restricted depth) is high. Shrink-swell potential is moderate. This soil is rarely flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 3 percent. Nonirrigated land capability classification is 3c. Irrigated land capability classification is 1 This soil does not meet hydric criteria. There are no saline horizons within 30 inches of the soil surface.

Component: Cole (4%)
Generated brief soil descriptions are created for major soil components. The Cole soil is a minor component.


Component: Yolo (4%)
Generated brief soil descriptions are created for major soil components. The Yolo soil is a minor component.

Component: Pajaro (3%)
Generated brief soil descriptions are created for major soil components. The Pajaro soil is a minor component.

Component: Cortina (3%)
Generated brief soil descriptions are created for major soil components. The Cortina soil is a minor component.

Component: Unnamed (1%)
Generated brief soil descriptions are created for major soil components. The Unnamed soil is a minor component.

Wells and Additional Sources



Wells & Additional Sources


N

0 0.3 0.6 1.2 Miles

- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- OGW Sites with Higher Elevation
- OGW Sites with Same Elevation
- OGW Sites with Lower Elevation
- OGW Sites with Unknown Elevation

ERIS

Wells and Additional Sources



Wells & Additional Sources - Page 1


N

0 0.15 0.3 0.6 Miles

- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- OGW Sites with Higher Elevation
- OGW Sites with Same Elevation
- OGW Sites with Lower Elevation
- OGW Sites with Unknown Elevation

ERIS

Wells and Additional Sources



Wells & Additional Sources - Page 2


N

0 0.15 0.3 0.6 Miles

- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- OGW Sites with Higher Elevation
- OGW Sites with Same Elevation
- OGW Sites with Lower Elevation
- OGW Sites with Unknown Elevation

ERIS

Wells and Additional Sources



Wells & Additional Sources - Page 3


N

0 0.15 0.3 0.6 Miles

- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- OGW Sites with Higher Elevation
- OGW Sites with Same Elevation
- OGW Sites with Lower Elevation
- OGW Sites with Unknown Elevation

ERIS

Wells and Additional Sources



Wells & Additional Sources - Page 4

N

0 0.15 0.3 0.6 Miles

- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- OGW Sites with Higher Elevation
- OGW Sites with Same Elevation
- OGW Sites with Lower Elevation
- OGW Sites with Unknown Elevation

ERIS

Wells and Additional Sources Summary

Federal Sources

Public Water Systems Violations and Enforcement Data

Map Key	PWS ID	Distance (ft)	Direction
18	CA4901231	1176.15	SSE
18	CA4901248	1176.15	SSE
18	CA4901254	1176.15	SSE
24	CA4910020	1608.72	SSE
29	CA4901129	1755.90	S
48	CA4901311	2515.43	ENE
49	CA4900720	2519.19	E
50	CA4900885	2611.21	ESE
61	CA4900723	3424.42	N
74	CA4901033	4526.30	ESE
89	CA4900724	5038.86	ESE

Safe Drinking Water Information System (SDWIS)

Map Key	PWS ID	Distance (ft)	Direction
1	CA4901057	0.00	-
50	CA4900885	2611.21	ESE

USGS National Water Information System

Map Key	Monitoring Loc Identifier	Distance (ft)	Direction
78	USGS-383111122455701	4648.82	E
83	USGS-11465500	4872.70	SE
85	USGS-383138122461401	4926.74	ENE
95	USGS-383220122480501	5266.32	NNW

State Sources

Oil and Gas Wells

Map Key	ID	Distance (ft)	Direction
	No records found		

Periodic Groundwater Level Measurement Locations

Map Key	Site Code	Distance (ft)	Direction
40	383882N1228050W002	2193.38	S
40	385117N1227863W002	2193.38	S
40	385117N1227863W001	2193.38	S
51	385131N1227761W002	2617.05	SE
55	385171N1227717W001	3155.73	ESE
75	385137N1227675W001	4534.93	ESE
76	385194N1227666W001	4617.96	E

Well Completion Reports

Wells and Additional Sources Summary

Map Key	WCR No	Distance (ft)	Direction
1	WCR2013-004867	0.00	-
1	WCR2013-004866	0.00	-
2	WCR2013-005290	18.40	NW
3	WCR0158752	25.48	NW
4	WCR2013-005293	126.20	NW
4	WCR2013-005292	126.20	NW
4	WCR2013-005294	126.20	NW
5	WCR2013-004865	133.27	NW
5	WCR2013-005291	133.27	NW
5	WCR2013-004863	133.27	NW
6	WCR2020-000030	269.00	NW
7	WCR2020-000029	354.73	NW
8	WCR1985-001061	440.16	N
8	WCR2001-001913	440.16	N
8	WCR0096419	440.16	N
8	WCR0173301	440.16	N
8	WCR0127852	440.16	N
8	WCR0205960	440.16	N
8	WCR0173813	440.16	N
8	WCR0013658	440.16	N
8	WCR0068841	440.16	N
8	WCR0053807	440.16	N
8	WCR0319382	440.16	N
8	WCR1994-003436	440.16	N
8	WCR1994-000192	440.16	N
8	WCR2002-006315	440.16	N
8	WCR0001919	440.16	N
8	WCR0231720	440.16	N
8	WCR1996-001515	440.16	N
8	WCR1985-004290	440.16	N
8	WCR0118644	440.16	N
8	WCR0250737	440.16	N
8	WCR2004-005168	440.16	N
8	WCR2004-003785	440.16	N
8	WCR2004-005166	440.16	N
8	WCR2004-003782	440.16	N
8	WCR0015518	440.16	N
8	WCR2004-003730	440.16	N
8	WCR0075842	440.16	N
8	WCR0121418	440.16	N
8	WCR0149249	440.16	N
8	WCR0038033	440.16	N
8	WCR0037099	440.16	N
8	WCR0285817	440.16	N
8	WCR0038031	440.16	N
8	WCR0194229	440.16	N
8	WCR0116058	440.16	N
8	WCR1998-001070	440.16	N
8	WCR0225262	440.16	N
8	WCR0093627	440.16	N
8	WCR0116063	440.16	N
8	WCR0149252	440.16	N
8	WCR0001920	440.16	N
8	WCR0205968	440.16	N
8	WCR0068840	440.16	N
8	WCR0024424	440.16	N
8	WCR0261293	440.16	N
8	WCR0118645	440.16	N
8	WCR0001927	440.16	N
8	WCR0199405	440.16	N
8	WCR0093621	440.16	N
8	WCR2003-006689	440.16	N
8	WCR0258841	440.16	N

8	WCR0191716	440.16	N
8	WCR0194231	440.16	N
8	WCR0149250	440.16	N
8	WCR1994-000193	440.16	N
8	WCR2004-003732	440.16	N
8	WCR0147735	440.16	N
8	WCR2002-002415	440.16	N
8	WCR0222212	440.16	N
8	WCR2001-001107	440.16	N
8	WCR2003-003780	440.16	N
8	WCR1999-006228	440.16	N
8	WCR2009-004684	440.16	N
8	WCR2009-004672	440.16	N
8	WCR1998-000344	440.16	N
8	WCR2003-003781	440.16	N
8	WCR2004-003780	440.16	N
8	WCR0237424	440.16	N
8	WCR0029614	440.16	N
8	WCR1981-003705	440.16	N
8	WCR0202759	440.16	N
8	WCR0048227	440.16	N
8	WCR0230220	440.16	N
8	WCR1987-003638	440.16	N
8	WCR0293199	440.16	N
8	WCR0006965	440.16	N
8	WCR0013659	440.16	N
8	WCR0178937	440.16	N
8	WCR0178932	440.16	N
8	WCR0120301	440.16	N
8	WCR0304621	440.16	N
8	WCR0319381	440.16	N
8	WCR0241645	440.16	N
8	WCR0163185	440.16	N
8	WCR0076774	440.16	N
8	WCR0194230	440.16	N
8	WCR0278487	440.16	N
8	WCR0121660	440.16	N
8	WCR0328076	440.16	N
8	WCR0171924	440.16	N
8	WCR0001921	440.16	N
8	WCR2003-003782	440.16	N
8	WCR2003-003783	440.16	N
8	WCR0261292	440.16	N
8	WCR2003-003785	440.16	N
8	WCR2003-003779	440.16	N
8	WCR2004-003783	440.16	N
8	WCR1990-013385	440.16	N
8	WCR2009-004686	440.16	N
8	WCR0250735	440.16	N
8	WCR0169218	440.16	N
8	WCR2004-005167	440.16	N
8	WCR2010-002872	440.16	N
8	WCR1985-001062	440.16	N
8	WCR0226964	440.16	N
8	WCR0138851	440.16	N
8	WCR0250734	440.16	N
8	WCR0115327	440.16	N
8	WCR1986-006341	440.16	N
8	WCR0250736	440.16	N
8	WCR1998-004197	440.16	N
8	WCR0222213	440.16	N
8	WCR0051735	440.16	N
8	WCR0218340	440.16	N
8	WCR0111082	440.16	N
8	WCR0051739	440.16	N
8	WCR0121416	440.16	N

8	WCR0135671	440.16	N
8	WCR0148215	440.16	N
8	WCR0038032	440.16	N
8	WCR0191715	440.16	N
8	WCR0171923	440.16	N
8	WCR0295608	440.16	N
8	WCR0085226	440.16	N
8	WCR0194236	440.16	N
8	WCR0205961	440.16	N
8	WCR0285818	440.16	N
8	WCR0297057	440.16	N
8	WCR0173303	440.16	N
8	WCR0046542	440.16	N
8	WCR0128502	440.16	N
8	WCR0226963	440.16	N
8	WCR1998-000345	440.16	N
8	WCR1994-003435	440.16	N
8	WCR0312247	440.16	N
8	WCR0142107	440.16	N
8	WCR1998-000346	440.16	N
8	WCR0138852	440.16	N
8	WCR2003-003784	440.16	N
8	WCR2004-003731	440.16	N
8	WCR2010-002874	440.16	N
8	WCR2010-002873	440.16	N
8	WCR0203732	440.16	N
8	WCR0171925	440.16	N
8	WCR1983-001038	440.16	N
8	WCR0319383	440.16	N
8	WCR0266926	440.16	N
8	WCR0093622	440.16	N
8	WCR0160190	440.16	N
8	WCR0135672	440.16	N
8	WCR0021895	440.16	N
8	WCR2003-003777	440.16	N
8	WCR0192559	440.16	N
8	WCR0245776	440.16	N
8	WCR2004-003729	440.16	N
8	WCR0085233	440.16	N
8	WCR0267906	440.16	N
8	WCR0024423	440.16	N
8	WCR0127853	440.16	N
8	WCR0247210	440.16	N
8	WCR0020056	440.16	N
8	WCR0241644	440.16	N
8	WCR2004-003784	440.16	N
8	WCR1998-003279	440.16	N
8	WCR1994-000194	440.16	N
8	WCR0169219	440.16	N
8	WCR2001-001912	440.16	N
8	WCR0231719	440.16	N
8	WCR1994-000416	440.16	N
8	WCR1984-000701	440.16	N
8	WCR2005-003755	440.16	N
8	WCR2003-003778	440.16	N
8	WCR1998-005751	440.16	N
8	WCR0205959	440.16	N
8	WCR0202760	440.16	N
8	WCR0213581	440.16	N
8	WCR0046549	440.16	N
8	WCR0266924	440.16	N
8	WCR0278643	440.16	N
8	WCR0312795	440.16	N
8	WCR2000-007310	440.16	N
8	WCR1983-000975	440.16	N
8	WCR2004-003781	440.16	N

8	WCR2004-005169	440.16	N
9	WCR2020-000028	471.56	WNW
10	WCR2020-000031	549.19	WNW
11	WCR2020-000026	555.48	WNW
12	WCR2020-000027	579.41	WNW
13	WCR2015-007002	617.27	WNW
13	WCR2015-006946	617.27	WNW
13	WCR2015-007013	617.27	WNW
13	WCR2015-007025	617.27	WNW
13	WCR2015-006942	617.27	WNW
13	WCR2015-007029	617.27	WNW
13	WCR2015-007008	617.27	WNW
13	WCR2015-006972	617.27	WNW
13	WCR2015-007017	617.27	WNW
13	WCR2015-006992	617.27	WNW
13	WCR2015-006968	617.27	WNW
13	WCR2015-006956	617.27	WNW
13	WCR2015-006967	617.27	WNW
13	WCR2015-006984	617.27	WNW
13	WCR2015-006955	617.27	WNW
13	WCR2015-007027	617.27	WNW
13	WCR2015-006987	617.27	WNW
13	WCR2015-007026	617.27	WNW
13	WCR2015-007001	617.27	WNW
13	WCR2015-007012	617.27	WNW
13	WCR2015-006993	617.27	WNW
13	WCR2015-006977	617.27	WNW
13	WCR2015-006981	617.27	WNW
13	WCR2015-007022	617.27	WNW
13	WCR2015-006990	617.27	WNW
13	WCR2015-006952	617.27	WNW
13	WCR2015-006988	617.27	WNW
13	WCR2015-006980	617.27	WNW
13	WCR2015-007000	617.27	WNW
13	WCR2015-006975	617.27	WNW
13	WCR2015-007015	617.27	WNW
13	WCR2015-007014	617.27	WNW
13	WCR2015-006951	617.27	WNW
13	WCR2015-006948	617.27	WNW
13	WCR2015-006978	617.27	WNW
13	WCR2015-007018	617.27	WNW
13	WCR2015-006986	617.27	WNW
13	WCR2015-007004	617.27	WNW
13	WCR2015-007009	617.27	WNW
13	WCR2015-006945	617.27	WNW
13	WCR2015-007019	617.27	WNW
13	WCR2015-006971	617.27	WNW
13	WCR2015-006989	617.27	WNW
13	WCR2015-006976	617.27	WNW
13	WCR2015-006994	617.27	WNW
13	WCR2015-007007	617.27	WNW
13	WCR2015-006995	617.27	WNW
13	WCR2015-007023	617.27	WNW
13	WCR2015-006949	617.27	WNW
13	WCR2015-007016	617.27	WNW
13	WCR2015-006985	617.27	WNW
13	WCR2015-006947	617.27	WNW
13	WCR2015-006943	617.27	WNW
13	WCR2015-006944	617.27	WNW
13	WCR2015-007003	617.27	WNW
13	WCR2015-006973	617.27	WNW
13	WCR2015-007028	617.27	WNW
13	WCR2015-006999	617.27	WNW
13	WCR2015-006983	617.27	WNW
13	WCR2015-007024	617.27	WNW
13	WCR2015-007021	617.27	WNW

13	WCR2015-006979	617.27	WNW
13	WCR2015-006998	617.27	WNW
13	WCR2015-007030	617.27	WNW
13	WCR2015-006954	617.27	WNW
13	WCR2015-007005	617.27	WNW
13	WCR2015-006970	617.27	WNW
13	WCR2015-007011	617.27	WNW
13	WCR2015-006974	617.27	WNW
13	WCR2015-006950	617.27	WNW
13	WCR2015-006966	617.27	WNW
13	WCR2015-007006	617.27	WNW
13	WCR2015-007010	617.27	WNW
13	WCR2015-006982	617.27	WNW
13	WCR2015-007032	617.27	WNW
13	WCR2015-006991	617.27	WNW
13	WCR2015-007038	617.27	WNW
13	WCR2015-006953	617.27	WNW
14	WCR2020-000025	653.37	WNW
15	WCR2004-008695	657.88	NW
15	WCR2004-008654	657.88	NW
15	WCR2004-008659	657.88	NW
15	WCR2004-008444	657.88	NW
15	WCR2004-008293	657.88	NW
15	WCR2004-008943	657.88	NW
15	WCR2004-008649	657.88	NW
15	WCR2004-008651	657.88	NW
15	WCR2004-008696	657.88	NW
15	WCR2004-008658	657.88	NW
15	WCR2004-008647	657.88	NW
15	WCR2004-008698	657.88	NW
15	WCR2004-008982	657.88	NW
15	WCR2004-008981	657.88	NW
15	WCR2004-008815	657.88	NW
15	WCR2004-008652	657.88	NW
15	WCR2004-008291	657.88	NW
15	WCR2004-008648	657.88	NW
15	WCR2004-008656	657.88	NW
15	WCR2004-008657	657.88	NW
15	WCR2004-009005	657.88	NW
15	WCR2004-008292	657.88	NW
15	WCR2004-008673	657.88	NW
15	WCR2004-008655	657.88	NW
15	WCR2004-008650	657.88	NW
15	WCR2004-008944	657.88	NW
15	WCR2004-008653	657.88	NW
15	WCR2004-008697	657.88	NW
15	WCR2004-009006	657.88	NW
15	WCR2004-008660	657.88	NW
15	WCR2004-008980	657.88	NW
15	WCR2004-008984	657.88	NW
16	WCR2011-006972	1093.78	WNW
17	WCR2011-006973	1166.68	WNW
19	WCR2019-010748	1225.26	SSE
20	WCR0297338	1401.61	NW
21	WCR0138608	1446.22	ESE
22	WCR0085227	1528.11	NNE
23	WCR2018-002970	1544.20	N
25	WCR0149251	1614.23	NNW
26	WCR2018-002971	1680.90	NNW
27	WCR2019-013430	1686.02	ESE
27	WCR2019-008919	1686.02	ESE
28	WCR2017-009089	1723.98	ESE
30	WCR0231721	1784.45	N
31	WCR2013-000658	1792.08	SE
32	WCR2011-005740	1800.31	ESE
33	WCR2014-000257	1860.98	SE

34	WCR0111081	1984.62	NW
34	WCR0149225	1984.62	NW
35	WCR2017-012990	2024.28	SE
36	WCR2014-015608	2054.86	NE
37	WCR0090821	2082.28	ENE
38	WCR0288286	2147.14	S
39	WCR2020-004041	2185.39	ESE
41	WCR2013-000653	2210.22	SSE
42	WCR2021-005694	2214.62	SSW
43	WCR2012-000757	2258.63	NE
44	WCR2021-003449	2353.92	ESE
45	WCR2017-009357	2394.30	NW
46	WCR0221974	2419.15	S
46	WCR0008243	2419.15	S
46	WCR0196591	2419.15	S
46	WCR0084995	2419.15	S
46	WCR0169173	2419.15	S
46	WCR2005-000294	2419.15	S
46	WCR0088081	2419.15	S
46	WCR0030968	2419.15	S
46	WCR0173311	2419.15	S
46	WCR0030969	2419.15	S
46	WCR0221976	2419.15	S
46	WCR0118585	2419.15	S
46	WCR0216774	2419.15	S
46	WCR0292966	2419.15	S
46	WCR0205624	2419.15	S
46	WCR0278146	2419.15	S
46	WCR2008-003921	2419.15	S
46	WCR1984-004013	2419.15	S
46	WCR2008-003760	2419.15	S
46	WCR0128796	2419.15	S
46	WCR0258788	2419.15	S
46	WCR0292965	2419.15	S
46	WCR2010-003590	2419.15	S
46	WCR2010-003588	2419.15	S
46	WCR0076720	2419.15	S
46	WCR2011-000181	2419.15	S
46	WCR2010-003789	2419.15	S
46	WCR2008-003759	2419.15	S
46	WCR0258787	2419.15	S
46	WCR2008-003756	2419.15	S
46	WCR0024655	2419.15	S
46	WCR2006-006219	2419.15	S
46	WCR2008-003758	2419.15	S
46	WCR2011-000179	2419.15	S
46	WCR0292964	2419.15	S
46	WCR2011-000178	2419.15	S
46	WCR2008-003755	2419.15	S
46	WCR2010-003589	2419.15	S
46	WCR2003-003072	2419.15	S
46	WCR0186006	2419.15	S
46	WCR0013606	2419.15	S
46	WCR0244891	2419.15	S
46	WCR0193878	2419.15	S
46	WCR0278147	2419.15	S
46	WCR2010-004637	2419.15	S
46	WCR2010-003790	2419.15	S
46	WCR0246858	2419.15	S
46	WCR0076719	2419.15	S
46	WCR0051393	2419.15	S
46	WCR0258789	2419.15	S
46	WCR0040739	2419.15	S
46	WCR2008-003754	2419.15	S
46	WCR0093297	2419.15	S
46	WCR0205623	2419.15	S

46	WCR0030967	2419.15	S
46	WCR0229970	2419.15	S
46	WCR0159864	2419.15	S
46	WCR0096365	2419.15	S
46	WCR0178883	2419.15	S
46	WCR0322152	2419.15	S
46	WCR0102668	2419.15	S
46	WCR0169172	2419.15	S
46	WCR0115525	2419.15	S
46	WCR0221975	2419.15	S
46	WCR0199648	2419.15	S
46	WCR0253363	2419.15	S
46	WCR0212336	2419.15	S
46	WCR0252363	2419.15	S
46	WCR1989-010257	2419.15	S
46	WCR2011-000180	2419.15	S
46	WCR1985-003531	2419.15	S
46	WCR0051392	2419.15	S
46	WCR2008-003757	2419.15	S
46	WCR2006-006220	2419.15	S
46	WCR0102870	2419.15	S
46	WCR1999-003915	2419.15	S
46	WCR0138613	2419.15	S
46	WCR2010-003587	2419.15	S
46	WCR0246857	2419.15	S
46	WCR0244892	2419.15	S
46	WCR0002619	2419.15	S
46	WCR2010-003585	2419.15	S
46	WCR2010-003586	2419.15	S
46	WCR1990-012727	2419.15	S
46	WCR2006-006221	2419.15	S
47	WCR2008-001538	2503.98	E
52	WCR0169223	2689.07	E
53	WCR2013-005925	2746.90	S
54	WCR0081966	2837.50	S
56	WCR0261657	3263.75	NW
57	WCR2019-008793	3264.35	ESE
58	WCR2019-004021	3278.02	ESE
59	WCR2014-000452	3295.66	ESE
60	WCR0202771	3322.82	ESE
62	WCR0325428	3490.81	NNE
63	WCR2012-004505	3611.20	SE
64	WCR0040733	3613.35	ESE
65	WCR2012-005327	3668.28	SE
66	WCR0178949	3692.16	W
67	WCR2006-002846	3830.04	N
68	WCR0171941	3876.34	WNW
68	WCR0187847	3876.34	WNW
68	WCR2000-006480	3876.34	WNW
68	WCR0173551	3876.34	WNW
68	WCR0074675	3876.34	WNW
68	WCR0178956	3876.34	WNW
68	WCR0013875	3876.34	WNW
68	WCR2000-006481	3876.34	WNW
68	WCR1986-003267	3876.34	WNW
68	WCR2000-004616	3876.34	WNW
68	WCR2004-004910	3876.34	WNW
68	WCR2000-006483	3876.34	WNW
68	WCR0122059	3876.34	WNW
68	WCR2000-006482	3876.34	WNW
68	WCR0157251	3876.34	WNW
68	WCR0250754	3876.34	WNW
68	WCR2007-003863	3876.34	WNW
68	WCR0021919	3876.34	WNW
68	WCR1983-000982	3876.34	WNW
68	WCR1984-003700	3876.34	WNW

68	WCR1999-006265	3876.34	WNW
68	WCR1982-002159	3876.34	WNW
68	WCR0247234	3876.34	WNW
68	WCR0304830	3876.34	WNW
68	WCR0178955	3876.34	WNW
68	WCR0258862	3876.34	WNW
68	WCR0171942	3876.34	WNW
68	WCR0247233	3876.34	WNW
68	WCR0096621	3876.34	WNW
68	WCR0231745	3876.34	WNW
68	WCR2004-000428	3876.34	WNW
68	WCR0024449	3876.34	WNW
68	WCR0247232	3876.34	WNW
68	WCR1994-002336	3876.34	WNW
68	WCR0194249	3876.34	WNW
68	WCR2000-006427	3876.34	WNW
68	WCR0122060	3876.34	WNW
68	WCR0247239	3876.34	WNW
68	WCR2007-003862	3876.34	WNW
68	WCR0205978	3876.34	WNW
68	WCR2000-006484	3876.34	WNW
68	WCR0261314	3876.34	WNW
68	WCR0178954	3876.34	WNW
68	WCR1999-006264	3876.34	WNW
68	WCR1985-005308	3876.34	WNW
68	WCR0021920	3876.34	WNW
69	WCR2014-000258	3892.31	W
70	WCR0222004	3907.58	NNW
71	WCR0327725	4492.88	SE
71	WCR2001-003275	4492.88	SE
71	WCR0222230	4492.88	SE
71	WCR0205621	4492.88	SE
71	WCR0321648	4492.88	SE
71	WCR0076714	4492.88	SE
71	WCR0319406	4492.88	SE
71	WCR0193867	4492.88	SE
71	WCR0252359	4492.88	SE
71	WCR0258489	4492.88	SE
71	WCR0304564	4492.88	SE
71	WCR0051761	4492.88	SE
71	WCR1981-002436	4492.88	SE
71	WCR0261624	4492.88	SE
71	WCR2008-001271	4492.88	SE
71	WCR1982-001593	4492.88	SE
71	WCR1988-011346	4492.88	SE
71	WCR2003-004792	4492.88	SE
71	WCR2003-004788	4492.88	SE
71	WCR2003-004200	4492.88	SE
71	WCR2003-004786	4492.88	SE
71	WCR1990-013386	4492.88	SE
71	WCR0278503	4492.88	SE
71	WCR2000-007472	4492.88	SE
71	WCR1988-011347	4492.88	SE
71	WCR0231744	4492.88	SE
71	WCR0193868	4492.88	SE
71	WCR0149192	4492.88	SE
71	WCR2004-003761	4492.88	SE
71	WCR0246853	4492.88	SE
71	WCR0021560	4492.88	SE
71	WCR0076712	4492.88	SE
71	WCR0304565	4492.88	SE
71	WCR0090829	4492.88	SE
71	WCR0178878	4492.88	SE
71	WCR0278502	4492.88	SE
71	WCR0090828	4492.88	SE
71	WCR0138609	4492.88	SE

71	WCR0048236	4492.88	SE
71	WCR0067702	4492.88	SE
71	WCR1998-005119	4492.88	SE
71	WCR2009-002539	4492.88	SE
71	WCR0253181	4492.88	SE
71	WCR1986-003388	4492.88	SE
71	WCR0002613	4492.88	SE
71	WCR0040801	4492.88	SE
71	WCR0122057	4492.88	SE
71	WCR0118297	4492.88	SE
71	WCR0231743	4492.88	SE
71	WCR0199428	4492.88	SE
71	WCR0244911	4492.88	SE
71	WCR0145488	4492.88	SE
71	WCR0048555	4492.88	SE
71	WCR0093643	4492.88	SE
71	WCR0117860	4492.88	SE
71	WCR0276258	4492.88	SE
71	WCR0192776	4492.88	SE
71	WCR0258491	4492.88	SE
71	WCR0278144	4492.88	SE
71	WCR2003-004202	4492.88	SE
71	WCR2001-003276	4492.88	SE
71	WCR1988-011348	4492.88	SE
71	WCR2007-002755	4492.88	SE
71	WCR2003-004791	4492.88	SE
71	WCR2003-004787	4492.88	SE
71	WCR0149191	4492.88	SE
71	WCR2003-004199	4492.88	SE
71	WCR2001-003278	4492.88	SE
71	WCR2003-004825	4492.88	SE
71	WCR1980-001511	4492.88	SE
71	WCR0106089	4492.88	SE
71	WCR2000-007474	4492.88	SE
71	WCR1998-005118	4492.88	SE
71	WCR1995-005986	4492.88	SE
71	WCR0222231	4492.88	SE
71	WCR0261313	4492.88	SE
71	WCR0067964	4492.88	SE
71	WCR0064184	4492.88	SE
71	WCR1989-001154	4492.88	SE
71	WCR2008-001270	4492.88	SE
71	WCR0146870	4492.88	SE
71	WCR0193866	4492.88	SE
71	WCR0328100	4492.88	SE
71	WCR0261626	4492.88	SE
71	WCR0205985	4492.88	SE
71	WCR0118296	4492.88	SE
71	WCR0186005	4492.88	SE
71	WCR1995-004695	4492.88	SE
71	WCR0037105	4492.88	SE
71	WCR0077079	4492.88	SE
71	WCR0193869	4492.88	SE
71	WCR0304829	4492.88	SE
71	WCR0188158	4492.88	SE
71	WCR0080178	4492.88	SE
71	WCR0037131	4492.88	SE
71	WCR0076713	4492.88	SE
71	WCR0246854	4492.88	SE
71	WCR0118295	4492.88	SE
71	WCR0218357	4492.88	SE
71	WCR0221969	4492.88	SE
71	WCR0205984	4492.88	SE
71	WCR0188159	4492.88	SE
71	WCR0221970	4492.88	SE
71	WCR0110733	4492.88	SE

71	WCR0304566	4492.88	SE
71	WCR1992-004092	4492.88	SE
71	WCR0067703	4492.88	SE
71	WCR2001-006840	4492.88	SE
71	WCR0261623	4492.88	SE
71	WCR1996-003015	4492.88	SE
71	WCR2009-000506	4492.88	SE
71	WCR1991-009830	4492.88	SE
71	WCR2005-003748	4492.88	SE
71	WCR2007-005413	4492.88	SE
71	WCR0021559	4492.88	SE
71	WCR1998-005120	4492.88	SE
71	WCR1985-004291	4492.88	SE
71	WCR2001-003277	4492.88	SE
71	WCR2001-006467	4492.88	SE
71	WCR2000-007471	4492.88	SE
71	WCR0327724	4492.88	SE
71	WCR2003-004790	4492.88	SE
71	WCR2003-004789	4492.88	SE
71	WCR0269748	4492.88	SE
71	WCR0261625	4492.88	SE
71	WCR0084988	4492.88	SE
71	WCR0013601	4492.88	SE
71	WCR2004-003754	4492.88	SE
71	WCR1998-005121	4492.88	SE
71	WCR0276240	4492.88	SE
71	WCR0183146	4492.88	SE
71	WCR0197537	4492.88	SE
71	WCR0171865	4492.88	SE
71	WCR2003-004785	4492.88	SE
71	WCR0002612	4492.88	SE
71	WCR0093292	4492.88	SE
71	WCR0285498	4492.88	SE
71	WCR0149285	4492.88	SE
71	WCR0292958	4492.88	SE
71	WCR2004-006184	4492.88	SE
71	WCR2003-004201	4492.88	SE
71	WCR2000-007473	4492.88	SE
71	WCR0202774	4492.88	SE
71	WCR0013600	4492.88	SE
71	WCR0149190	4492.88	SE
71	WCR1990-009995	4492.88	SE
71	WCR0024650	4492.88	SE
71	WCR0258490	4492.88	SE
71	WCR0319335	4492.88	SE
72	WCR0024651	4518.27	ESE
73	WCR0229667	4526.07	NNW
77	WCR2013-006882	4627.96	SE
79	WCR2013-006883	4673.19	SE
80	WCR2013-006881	4711.86	SE
81	WCR1989-004015	4737.65	ENE
81	WCR2002-007257	4737.65	ENE
81	WCR0205969	4737.65	ENE
81	WCR1995-001678	4737.65	ENE
81	WCR0194237	4737.65	ENE
81	WCR0118652	4737.65	ENE
81	WCR0149261	4737.65	ENE
81	WCR0005383	4737.65	ENE
81	WCR0085234	4737.65	ENE
81	WCR0258842	4737.65	ENE
81	WCR0171930	4737.65	ENE
81	WCR0021900	4737.65	ENE
81	WCR2002-001980	4737.65	ENE
81	WCR0138860	4737.65	ENE
81	WCR0019200	4737.65	ENE
81	WCR1986-006952	4737.65	ENE

Wells and Additional Sources Summary

81	WCR1983-003182	4737.65	ENE
81	WCR0160195	4737.65	ENE
81	WCR1989-006095	4737.65	ENE
81	WCR1996-005535	4737.65	ENE
81	WCR1989-004013	4737.65	ENE
81	WCR0024426	4737.65	ENE
81	WCR0040789	4737.65	ENE
81	WCR2000-007305	4737.65	ENE
81	WCR1995-004700	4737.65	ENE
81	WCR1995-005650	4737.65	ENE
81	WCR0171931	4737.65	ENE
81	WCR0096610	4737.65	ENE
81	WCR0178939	4737.65	ENE
81	WCR0138859	4737.65	ENE
81	WCR1983-003181	4737.65	ENE
81	WCR0222214	4737.65	ENE
81	WCR0111088	4737.65	ENE
81	WCR0024425	4737.65	ENE
81	WCR0120305	4737.65	ENE
81	WCR0051740	4737.65	ENE
81	WCR0067947	4737.65	ENE
81	WCR0117859	4737.65	ENE
81	WCR0019201	4737.65	ENE
81	WCR0013669	4737.65	ENE
81	WCR0250742	4737.65	ENE
81	WCR0258843	4737.65	ENE
81	WCR2003-006546	4737.65	ENE
81	WCR2000-006152	4737.65	ENE
81	WCR1985-004267	4737.65	ENE
81	WCR1986-002373	4737.65	ENE
81	WCR0085235	4737.65	ENE
81	WCR1985-003812	4737.65	ENE
81	WCR1982-000799	4737.65	ENE
81	WCR0160194	4737.65	ENE
81	WCR0005382	4737.65	ENE
81	WCR0178938	4737.65	ENE
81	WCR1996-003087	4737.65	ENE
81	WCR0278488	4737.65	ENE
82	WCR2016-010251	4866.24	ESE
82	WCR2016-010249	4866.24	ESE
84	WCR2014-015503	4905.41	N
86	WCR0093650	4955.14	ESE
87	WCR2020-004824	5009.67	SE
88	WCR2020-005532	5010.86	SE
90	WCR2019-001358	5071.74	N
91	WCR0090827	5078.81	SE
92	WCR2011-007004	5156.71	ESE
93	WCR2019-001357	5164.31	N
94	WCR2018-012874	5165.36	ESE
94	WCR2018-012873	5165.36	ESE

Public Water Systems Violations and Enforcement Data

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
18	SSE	0.22	1,176.15	122.76	PWSV

Address Line 2:
State Code: CA
Zip Code: 95403
City Name: SANTA ROSA
Address Line 1: 425 Aviation Boulevard
PWS ID: CA4901231
PWS Type Code: TNCWS
PWS Type Description: Transient Non-Community Water System
Primary Source Code: GW
Primary Source Desc: Groundwater
PWS Activity Code: A
PWS Activity Description: Active
PWS Deactivation Date:
Phone Number: 707-836-2046

--Details--
Population Served Count: 40
City Served:
County Served: Sonoma
State Served: CA
Zip Code Served:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
18	SSE	0.22	1,176.15	122.76	PWSV

Address Line 2:
State Code: CA
Zip Code: 95403
City Name: SANTA ROSA
Address Line 1: 425 Aviation Boulevard
PWS ID: CA4901248
PWS Type Code: NTNCWS
PWS Type Description: Non-Transient Non-Community Water System
Primary Source Code: GW
Primary Source Desc: Groundwater
PWS Activity Code: A
PWS Activity Description: Active
PWS Deactivation Date:
Phone Number: 707-836-2046

Wells and Additional Sources Detail Report

--Details--
Population Served Count: 35
City Served:
County Served: Sonoma
State Served: CA
Zip Code Served:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
18	SSE	0.22	1,176.15	122.76	PWSV

Address Line 2:
State Code: CA
Zip Code: 95403
City Name: SANTA ROSA
Address Line 1: 425 Aviation Boulevard
PWS ID: CA4901254
PWS Type Code: NTNCWS
PWS Type Description: Non-Transient Non-Community Water System
Primary Source Code: GW
Primary Source Desc: Groundwater
PWS Activity Code: A
PWS Activity Description: Active
PWS Deactivation Date:
Phone Number: 707-836-2046

--Details--
Population Served Count: 100
City Served:
County Served: Sonoma
State Served: CA
Zip Code Served:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
24	SSE	0.30	1,608.72	123.16	PWSV

Address Line 2:
State Code: CA
Zip Code: 95403
City Name: SANTA ROSA
Address Line 1: 404 Aviation Boulevard
PWS ID: CA4910020
PWS Type Code: CWS
PWS Type Description: Community Water System
Primary Source Code: GW
Primary Source Desc: Groundwater
PWS Activity Code: A

PWS Activity Description: Active
PWS Deactivation Date:
Phone Number: 707-547-1911

--Details--
Population Served Count: 500
City Served:
County Served: Sonoma
State Served: CA
Zip Code Served:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
29	S	0.33	1,755.90	120.32	PWSV

Address Line 2:
State Code: CA
Zip Code: 95403
City Name: SANTA ROSA
Address Line 1: 205 Concourse Boulevard
PWS ID: CA4901129
PWS Type Code: NTNCWS
PWS Type Description: Non-Transient Non-Community Water System
Primary Source Code: GW
Primary Source Desc: Groundwater
PWS Activity Code: A
PWS Activity Description: Active
PWS Deactivation Date:
Phone Number: 877-289-9463

--Details--
Population Served Count: 200
City Served:
County Served: Sonoma
State Served: CA
Zip Code Served:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
48	ENE	0.48	2,515.43	136.05	PWSV

Address Line 2:
State Code: CA
Zip Code: 95403
City Name: SANTA ROSA
Address Line 1: 5901 Old Redwood Highway
PWS ID: CA4901311
PWS Type Code: TNCWS

PWS Type Description: Transient Non-Community Water System
Primary Source Code: GW
Primary Source Desc: Groundwater
PWS Activity Code: A
PWS Activity Description: Active
PWS Deactivation Date:
Phone Number: 707-838-9136

--Details--
Population Served Count: 60
City Served:
County Served: Sonoma
State Served: CA
Zip Code Served:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
49	E	0.48	2,519.19	134.76	PWSV

Address Line 2:
State Code: CA
Zip Code: 95403
City Name: SANTA ROSA
Address Line 1: 5761 Old Redwood Highway North
PWS ID: CA4900720
PWS Type Code: CWS
PWS Type Description: Community Water System
Primary Source Code: GW
Primary Source Desc: Groundwater
PWS Activity Code: A
PWS Activity Description: Active
PWS Deactivation Date:
Phone Number: 707-576-0377

--Details--
Population Served Count: 320
City Served:
County Served: Sonoma
State Served: CA
Zip Code Served:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
50	ESE	0.49	2,611.21	132.76	PWSV

Address Line 2: 270 MARK WEST STATION ROAD
State Code: CA
Zip Code: 95492

Wells and Additional Sources Detail Report

City Name: WINDSOR
Address Line 1: DURELLE FINSTER
PWS ID: CA4900885
PWS Type Code: NTNCWS
PWS Type Description: Non-Transient Non-Community Water System
Primary Source Code: GW
Primary Source Desc: Groundwater
PWS Activity Code: N
PWS Activity Description: Non-public
PWS Deactivation Date: 09/06/2009
Phone Number:

--Details--
Population Served Count: 25
City Served:
County Served:
State Served: CA
Zip Code Served:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
61	N	0.65	3,424.42	132.54	PWSV

Address Line 2:
State Code: CA
Zip Code: 95403
City Name: SANTA ROSA
Address Line 1: 6418 North Old Redwood Highway
PWS ID: CA4900723
PWS Type Code: CWS
PWS Type Description: Community Water System
Primary Source Code: GW
Primary Source Desc: Groundwater
PWS Activity Code: A
PWS Activity Description: Active
PWS Deactivation Date:
Phone Number: 707-838-4389

--Details--
Population Served Count: 188
City Served:
County Served: Sonoma
State Served: CA
Zip Code Served:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
74	ESE	0.86	4,526.30	141.32	PWSV

Address Line 2:	5433 OLD REDWOOD HWY
State Code:	CA
Zip Code:	95476
City Name:	SONOMA
Address Line 1:	EAGLE RIDGE WINERY
PWS ID:	CA4901033
PWS Type Code:	TNCWS
PWS Type Description:	Transient Non-Community Water System
Primary Source Code:	GW
Primary Source Desc:	Groundwater
PWS Activity Code:	N
PWS Activity Description:	Non-public
PWS Deactivation Date:	09/06/2009
Phone Number:	707-795-3100

--Details--

Population Served Count:	25
City Served:	
County Served:	
State Served:	CA
Zip Code Served:	

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
89	ESE	0.95	5,038.86	143.54	PWSV

Address Line 2:	301 AIRPORT BLV
State Code:	CA
Zip Code:	95401
City Name:	SANTA ROSA
Address Line 1:	REDWOOD VILLAGE
PWS ID:	CA4900724
PWS Type Code:	CWS
PWS Type Description:	Community Water System
Primary Source Code:	GW
Primary Source Desc:	Groundwater
PWS Activity Code:	N
PWS Activity Description:	Non-public
PWS Deactivation Date:	09/06/2009
Phone Number:	

--Details--

Population Served Count:	0
City Served:	
County Served:	
State Served:	CA

Wells and Additional Sources Detail Report

Zip Code Served:

Safe Drinking Water Information System (SDWIS)

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
1	-	0.00	0.00	114.94	SDWIS

PWS ID:	CA4901057
PWS Type:	Transient non-community system
No of Facilities:	2
No of Violations:	0
No of Site Visits:	0
Cities Served:	-
Counties Served:	Sonoma
Population Served Count:	100
Primacy Agency:	California
EPA Region:	Region 9

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
50	ESE	0.49	2,611.21	132.76	SDWIS

PWS ID:	CA4900885
PWS Type:	Non-Transient non-community system
No of Facilities:	4
No of Violations:	7
No of Site Visits:	2
Cities Served:	-
Counties Served:	Sonoma
Population Served Count:	25
Primacy Agency:	California
EPA Region:	Region 9

USGS National Water Information System

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
78	E	0.88	4,648.82	141.65	FED USGS

Organiz Identifier:	USGS-CA	Formation Type:	
Organiz Name:	USGS California Water Science Center	Aquifer Name:	California Coastal Basin aquifers
Well Depth:	312	Aquifer Type:	
Well Depth Unit:	ft	Country Code:	US
Well Hole Depth:	312	Provider Name:	NWIS
W Hole Depth Unit:	ft	County:	SONOMA
Construction Date:	19500527	Latitude:	38.5196326
Source Map Scale:	24000	Longitude:	-122.7669331
Monitoring Loc Name:	008N008W20Q001M		

Monitoring Loc Identifier:	USGS-383111122455701
Monitoring Loc Type:	Well
Monitoring Loc Desc:	
HUC Eight Digit Code:	18010110
Drainage Area:	
Drainage Area Unit:	
Contrib Drainage Area:	
Contrib Drainage Area Unit:	
Horizontal Accuracy:	5
Horizontal Accuracy Unit:	seconds
Horizontal Collection Mthd:	Interpolated from MAP.
Horiz Coord Refer System:	NAD83
Vertical Measure:	139
Vertical Measure Unit:	feet
Vertical Accuracy:	10
Vertical Accuracy Unit:	feet
Vertical Collection Mthd:	Interpolated from topographic map.
Vert Coord Refer System:	NGVD29

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
83	SE	0.92	4,872.70	143.64	FED USGS

Organiz Identifier:	USGS-CA	Formation Type:	
Organiz Name:	USGS California Water Science Center	Aquifer Name:	
Well Depth:		Aquifer Type:	
Well Depth Unit:		Country Code:	US
Well Hole Depth:		Provider Name:	NWIS
W Hole Depth Unit:		County:	SONOMA
Construction Date:		Latitude:	38.509355
Source Map Scale:	24000	Longitude:	-122.7697109
Monitoring Loc Name:	MARK WEST C NR WINDSOR CA		
Monitoring Loc Identifier:	USGS-11465500		
Monitoring Loc Type:	Stream		
Monitoring Loc Desc:			
HUC Eight Digit Code:	18010110		
Drainage Area:	43		
Drainage Area Unit:	sq mi		
Contrib Drainage Area:			
Contrib Drainage Area Unit:			
Horizontal Accuracy:	1		
Horizontal Accuracy Unit:	seconds		
Horizontal Collection Mthd:	Interpolated from MAP.		
Horiz Coord Refer System:	NAD83		

Vertical Measure:	140
Vertical Measure Unit:	feet
Vertical Accuracy:	10
Vertical Accuracy Unit:	feet
Vertical Collection Mthd:	Interpolated from topographic map.
Vert Coord Refer System:	NGVD29

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
85	ENE	0.93	4,926.74	155.94	FED USGS

Organiz Identifier:	USGS-CA	Formation Type:	
Organiz Name:	USGS California Water Science Center	Aquifer Name:	
Well Depth:	200	Aquifer Type:	
Well Depth Unit:	ft	Country Code:	US
Well Hole Depth:	204	Provider Name:	NWIS
W Hole Depth Unit:	ft	County:	SONOMA
Construction Date:	20000428	Latitude:	38.5274444
Source Map Scale:	24000	Longitude:	-122.7707222
Monitoring Loc Name:	008N008W20F001M		
Monitoring Loc Identifier:	USGS-383138122461401		
Monitoring Loc Type:	Well		
Monitoring Loc Desc:			
HUC Eight Digit Code:	18010110		
Drainage Area:			
Drainage Area Unit:			
Contrib Drainage Area:			
Contrib Drainage Area Unit:			
Horizontal Accuracy:	.5		
Horizontal Accuracy Unit:	seconds		
Horizontal Collection Mthd:	Mapping grade GPS unit (handheld accuracy range 12 to 40 ft)		
Horiz Coord Refer System:	NAD83		
Vertical Measure:	165		
Vertical Measure Unit:	feet		
Vertical Accuracy:	2.5		
Vertical Accuracy Unit:	feet		
Vertical Collection Mthd:	Interpolated from Digital Elevation Model		
Vert Coord Refer System:	NAVD88		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
95	NNW	1.00	5,266.32	116.25	FED USGS

Organiz Identifier:	USGS-CA	Formation Type:	
Organiz Name:	USGS California Water Science Center	Aquifer Name:	California Coastal Basin aquifers

Well Depth:	400	Aquifer Type:	
Well Depth Unit:	ft	Country Code:	US
Well Hole Depth:	400	Provider Name:	NWIS
W Hole Depth Unit:	ft	County:	SONOMA
Construction Date:	19711115	Latitude:	38.5389444
Source Map Scale:	24000	Longitude:	-122.8015556
Monitoring Loc Name:	008N009W13J002M		
Monitoring Loc Identifier:	USGS-383220122480501		
Monitoring Loc Type:	Well		
Monitoring Loc Desc:			
HUC Eight Digit Code:	18010110		
Drainage Area:			
Drainage Area Unit:			
Contrib Drainage Area:			
Contrib Drainage Area Unit:			
Horizontal Accuracy:	.5		
Horizontal Accuracy Unit:	seconds		
Horizontal Collection Mthd:	Mapping grade GPS unit (handheld accuracy range 12 to 40 ft)		
Horiz Coord Refer System:	NAD83		
Vertical Measure:	115		
Vertical Measure Unit:	feet		
Vertical Accuracy:	5		
Vertical Accuracy Unit:	feet		
Vertical Collection Mthd:	Interpolated from topographic map.		
Vert Coord Refer System:	NGVD29		

Periodic Groundwater Level Measurement Locations

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
40	S	0.42	2,193.38	122.92	MONITOR WELLS

Site Code:	383882N1228050W002	Basin ID:	
State Well No:		Basin Code:	1-055.01
Station ID:	48753	Basin Name:	Santa Rosa Plain
WCR No:		Basin Region Code:	1
Well Depth:	60	Basin Region Desc:	North Coast
Well Use:	Observation	Basin Region Actv:	Y
Well Type:	Part of a nested/multi-completion well	Basin Region Order:	1
Well Name:	SRP-15	County Name:	Sonoma
Latitude:	38.5117	WLM Method:	Surveyed to a benchmark
Longitude:	-122.786	WLM Accuracy:	0.1 ft.

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
40	S	0.42	2,193.38	122.92	MONITOR WELLS

Site Code:	385117N1227863W002	Basin ID:	
State Well No:		Basin Code:	1-055.01
Station ID:	48755	Basin Name:	Santa Rosa Plain
WCR No:		Basin Region Code:	1
Well Depth:	360	Basin Region Desc:	North Coast
Well Use:	Observation	Basin Region Actv:	Y
Well Type:	Part of a nested/multi-completion well	Basin Region Order:	1
Well Name:	SRP-17	County Name:	Sonoma
Latitude:	38.5117	WLM Method:	Surveyed to a benchmark
Longitude:	-122.786	WLM Accuracy:	0.1 ft.

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
40	S	0.42	2,193.38	122.92	MONITOR WELLS

Site Code:	385117N1227863W001	Basin ID:	
State Well No:		Basin Code:	1-055.01
Station ID:	48754	Basin Name:	Santa Rosa Plain
WCR No:		Basin Region Code:	1
Well Depth:	140	Basin Region Desc:	North Coast
Well Use:	Observation	Basin Region Actv:	Y
Well Type:	Part of a nested/multi-completion well	Basin Region Order:	1
Well Name:	SRP-16	County Name:	Sonoma
Latitude:	38.5117	WLM Method:	Surveyed to a benchmark
Longitude:	-122.786	WLM Accuracy:	0.1 ft.

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
51	SE	0.50	2,617.05	132.74	MONITOR WELLS

Site Code:	385131N1227761W002	Basin ID:	
State Well No:		Basin Code:	1-055.01
Station ID:	48765	Basin Name:	Santa Rosa Plain
WCR No:		Basin Region Code:	1
Well Depth:		Basin Region Desc:	North Coast
Well Use:	Unknown	Basin Region Actv:	Y
Well Type:	Single Well	Basin Region Order:	1
Well Name:	SRP-27	County Name:	Sonoma
Latitude:	38.5131	WLM Method:	Unknown
Longitude:	-122.776	WLM Accuracy:	Unknown

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
55	ESE	0.60	3,155.73	135.71	MONITOR WELLS

Site Code:	385171N1227717W001	Basin ID:	
State Well No:	08N08W29C003M	Basin Code:	1-055.01

Wells and Additional Sources Detail Report

Station ID:	9302	Basin Name:	Santa Rosa Plain
WCR No:	61082	Basin Region Code:	1
Well Depth:	95	Basin Region Desc:	North Coast
Well Use:	Residential	Basin Region Actv:	Y
Well Type:	Single Well	Basin Region Order:	1
Well Name:	08N08W29C003M	County Name:	Sonoma
Latitude:	38.5171	WLM Method:	Unknown
Longitude:	-122.772	WLM Accuracy:	Unknown

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
75	ESE	0.86	4,534.93	141.95	MONITOR WELLS

Site Code:	385137N1227675W001	Basin ID:	
State Well No:	08N08W29B001M	Basin Code:	1-055.01
Station ID:	30677	Basin Name:	Santa Rosa Plain
WCR No:	13260	Basin Region Code:	1
Well Depth:	64	Basin Region Desc:	North Coast
Well Use:	Residential	Basin Region Actv:	Y
Well Type:	Single Well	Basin Region Order:	1
Well Name:	08N08W29B001M	County Name:	Sonoma
Latitude:	38.5137	WLM Method:	Unknown
Longitude:	-122.768	WLM Accuracy:	Unknown

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
76	E	0.87	4,617.96	141.31	MONITOR WELLS

Site Code:	385194N1227666W001	Basin ID:	
State Well No:	08N08W20Q001M	Basin Code:	1-055.01
Station ID:	9301	Basin Name:	Santa Rosa Plain
WCR No:	140	Basin Region Code:	1
Well Depth:	312	Basin Region Desc:	North Coast
Well Use:	Irrigation	Basin Region Actv:	Y
Well Type:	Single Well	Basin Region Order:	1
Well Name:	08N08W20Q001M	County Name:	Sonoma
Latitude:	38.5194	WLM Method:	Unknown
Longitude:	-122.767	WLM Accuracy:	Unknown

Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
1	-	0.00	0.00	113.40	WATER WELLS

WCR No:	WCR2013-004867	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.5255556
Decimal Latitude:	38.5255556	Decim Long(OSWCR):	-122.7930556

Decimal Longitude: -122.7930556
Location: 705 SHILOH RD
Location(OSWCR): 705 SHILOH RD
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
1	-	0.00	0.00	112.96	WATER WELLS

WCR No: WCR2013-004866
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.5255556
Decimal Longitude: -122.7933333
Location: 705 SHILOH RD
Location(OSWCR): 705 SHILOH RD
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.5255556
Decim Long(OSWCR): -122.7933333
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
2	NW	0.00	18.40	112.74	WATER WELLS

WCR No: WCR2013-005290
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.5258333
Decimal Longitude: -122.7933333
Location: 705 SHILOH RD
Location(OSWCR): 705 SHILOH RD
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.5258333
Decim Long(OSWCR): -122.7933333
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
3	NW	0.00	25.48	113.46	WATER WELLS

WCR No: WCR0158752
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.52583333
Decimal Longitude: -122.79305556
Location: 705 SHILOH ROAD
Location(OSWCR): 705 SHILOH ROAD
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52583333
Decim Long(OSWCR): -122.79305556
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	NW	0.02	126.20	113.14	WATER WELLS

Wells and Additional Sources Detail Report

WCR No:	WCR2013-005293	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.5261111
Decimal Latitude:	38.5261111	Decim Long(OSWCR):	-122.7930556
Decimal Longitude:	-122.7930556		
Location:	705 SHILOH RD		
Location(OSWCR):	705 SHILOH RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	NW	0.02	126.20	113.14	WATER WELLS

WCR No:	WCR2013-005292	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.5261111
Decimal Latitude:	38.5261111	Decim Long(OSWCR):	-122.7930556
Decimal Longitude:	-122.7930556		
Location:	705 SHILOH RD		
Location(OSWCR):	705 SHILOH RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	NW	0.02	126.20	113.14	WATER WELLS

WCR No:	WCR2013-005294	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.5261111
Decimal Latitude:	38.5261111	Decim Long(OSWCR):	-122.7930556
Decimal Longitude:	-122.7930556		
Location:	705 SHILOH RD		
Location(OSWCR):	705 SHILOH RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
5	NW	0.03	133.27	113.88	WATER WELLS

WCR No:	WCR2013-004865	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.5261111
Decimal Latitude:	38.5261111	Decim Long(OSWCR):	-122.7927778
Decimal Longitude:	-122.7927778		
Location:	705 SHILOH RD		

Location(OSWCR): 705 SHILOH RD
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
5	NW	0.03	133.27	113.88	WATER WELLS

WCR No: WCR2013-005291
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.5261111
Decimal Longitude: -122.7927778
Location: 705 SHILOH RD
Location(OSWCR): 705 SHILOH RD
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.5261111
Decim Long(OSWCR): -122.7927778
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
5	NW	0.03	133.27	113.88	WATER WELLS

WCR No: WCR2013-004863
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.5261111
Decimal Longitude: -122.7927778
Location: 705 SHILOH RD
Location(OSWCR): 705 SHILOH RD
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.5261111
Decim Long(OSWCR): -122.7927778
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
6	NW	0.05	269.00	113.00	WATER WELLS

WCR No: WCR2020-000030
City: Windsor
County: Sonoma
Decimal Latitude: 38.5245536
Decimal Longitude: -122.7938429
Location: 930 Shiloh RD
Location(OSWCR): 930 Shiloh RD
City(OSWCR): Windsor
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.5245536
Decim Long(OSWCR): -122.7938429
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
7	NW	0.07	354.73	111.67	WATER WELLS

Wells and Additional Sources Detail Report

WCR No:	WCR2020-000029	City(OSWCR):	Windsor
City:	Windsor	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52451124
Decimal Latitude:	38.52451124	Decim Long(OSWCR):	-122.7942272
Decimal Longitude:	-122.7942272		
Location:	930 Shiloh RD		
Location(OSWCR):	930 Shiloh RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR1985-001061	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR2001-001913	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	705 SHILOH RD_		
Location(OSWCR):	705 SHILOH RD_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0096419	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water		

Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0173301	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0127852	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0205960	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0173813	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma

County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0013658	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	SAME		
Location(OSWCR):	SAME		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0068841	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0053807	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0319382	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	6900 HEMBREE LANE		
Location(OSWCR):	6900 HEMBREE LANE		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR1994-003436	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	6199 OLD REDWOOD HWY_		
Location(OSWCR):	6199 OLD REDWOOD HWY_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR1994-000192	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	705 SHILOH RD_		
Location(OSWCR):	705 SHILOH RD_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR2002-006315	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859

Decimal Longitude: -122.78859
Location: 222 E SHILOH RD
Location(OSWCR): 222 E SHILOH RD
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR0001919
City: SANTA ROSA
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: 6101 OLD REDWOOD HWY NO
Location(OSWCR): 6101 OLD REDWOOD HWY NO
City(OSWCR): SANTA ROSA
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR0231720
City: SANTA ROSA
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: 6011 OLD REDWOOD HWY
Location(OSWCR): 6011 OLD REDWOOD HWY
City(OSWCR): SANTA ROSA
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR1996-001515
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: 2598 LAUGHLIN RD_
Location(OSWCR): 2598 LAUGHLIN RD_
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

Wells and Additional Sources Detail Report

WCR No:	WCR1985-004290	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0118644	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0250737	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	PRIVET ROAD		
Location(OSWCR):	PRIVET ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR2004-005168	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	6301 HEMBREE LANE		

Location(OSWCR): 6301 HEMBREE LANE
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR2004-003785
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: 1145 KITTY HAWK
Location(OSWCR): 1145 KITTY HAWK
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR2004-005166
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: 6301 HEMBREE LANE
Location(OSWCR): 6301 HEMBREE LANE
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR2004-003782
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: 1145 KITTY HAWK
Location(OSWCR): 1145 KITTY HAWK
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0015518	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR2004-003730	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	1145 KITTY HAWK		
Location(OSWCR):	1145 KITTY HAWK		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0075842	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0121418	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water		

Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0149249	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0038033	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0037099	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0285817	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma

County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0038031	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0194229	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	5900 REDWOOD HWY N		
Location(OSWCR):	5900 REDWOOD HWY N		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0116058	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR1998-001070	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	283 SHILOH RD_		
Location(OSWCR):	283 SHILOH RD_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0225262	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0093627	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0116063	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859

Decimal Longitude: -122.78859
Location: None
Location(OSWCR): None
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR0149252
City: None
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: SAME AS ABOVE ADDRESS NEAR SHILO ROAD
Location(OSWCR): SAME AS ABOVE ADDRESS NEAR SHILO ROAD
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR0001920
City: None
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: AT PLANT ON SHILOH RD
Location(OSWCR): AT PLANT ON SHILOH RD
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR0205968
City: None
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: None
Location(OSWCR): None
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0068840	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0024424	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0261293	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0118645	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		

Location(OSWCR): None
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR0001927
City: None
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: None
Location(OSWCR): None
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR0199405
City: None
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: None
Location(OSWCR): None
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR0093621
City: None
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: None
Location(OSWCR): None
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

Wells and Additional Sources Detail Report

WCR No:	WCR2003-006689	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	1175 KITTYHAWK BLVD		
Location(OSWCR):	1175 KITTYHAWK BLVD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0258841	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0191716	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0194231	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water		

Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0149250	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR1994-000193	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	705 SHILOH RD_		
Location(OSWCR):	705 SHILOH RD_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR2004-003732	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	1145 KITTY HAWK		
Location(OSWCR):	1145 KITTY HAWK		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0147735	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma

County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	1175 KITTYHAWK BLVD		
Location(OSWCR):	1175 KITTYHAWK BLVD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR2002-002415	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	6285 OLD REDWOOD HWY_		
Location(OSWCR):	6285 OLD REDWOOD HWY_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0222212	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	OLD REDWOOD HWY		
Location(OSWCR):	OLD REDWOOD HWY		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR2001-001107	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	909 SHILOH VISTA		
Location(OSWCR):	909 SHILOH VISTA		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR2003-003780	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	1175 KITTYHAWK BLVD_		
Location(OSWCR):	1175 KITTYHAWK BLVD_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR1999-006228	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	500 SHILOH MEADOW RD		
Location(OSWCR):	500 SHILOH MEADOW RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR2009-004684	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	705 SHILOH RD		
Location(OSWCR):	705 SHILOH RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR2009-004672	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859

Decimal Longitude: -122.78859
Location: 705 SHILOH RD
Location(OSWCR): 705 SHILOH RD
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR1998-000344
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: None
Location(OSWCR): None
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR2003-003781
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: 1175 KITTYHAWK BLVD_
Location(OSWCR): 1175 KITTYHAWK BLVD_
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR2004-003780
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: 1145 KITTY HAWK
Location(OSWCR): 1145 KITTY HAWK
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0237424	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0029614	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR1981-003705	City(OSWCR):	FULTON
City:	FULTON	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0202759	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	SAME		

Location(OSWCR): SAME
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR0048227
City: None
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: SAME
Location(OSWCR): SAME
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR0230220
City: None
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: None
Location(OSWCR): None
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR1987-003638
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: None
Location(OSWCR): None
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0293199	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0006965	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0013659	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0178937	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water		

Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0178932	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0120301	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	AS ABOVE		
Location(OSWCR):	AS ABOVE		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0304621	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	PRIVET ROAD		
Location(OSWCR):	PRIVET ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0319381	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma

County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0241645	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0163185	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0076774	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	SAME		
Location(OSWCR):	SAME		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0194230	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0278487	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0121660	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0328076	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859

Decimal Longitude: -122.78859
Location: None
Location(OSWCR): None
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR0171924
City: None
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: None
Location(OSWCR): None
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR0001921
City: None
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: None
Location(OSWCR): None
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR2003-003782
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: 1175 KITTYHAWK BLVD_
Location(OSWCR): 1175 KITTYHAWK BLVD_
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR2003-003783	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	1175 KITTYHAWK BLVD_		
Location(OSWCR):	1175 KITTYHAWK BLVD_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0261292	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	6290 OLD REDWOOD HWY		
Location(OSWCR):	6290 OLD REDWOOD HWY		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR2003-003785	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	1175 KITTYHAWK BLVD_		
Location(OSWCR):	1175 KITTYHAWK BLVD_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR2003-003779	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	1175 KITTYHAWK BLVD_		

Location(OSWCR): 1175 KITTYHAWK BLVD_
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR2004-003783
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: 1145 KITTY HAWK
Location(OSWCR): 1145 KITTY HAWK
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR1990-013385
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: 300 WILSON LN_
Location(OSWCR): 300 WILSON LN_
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR2009-004686
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: 705 SHILOH RD
Location(OSWCR): 705 SHILOH RD
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0250735	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	SHILOH RD		
Location(OSWCR):	SHILOH RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0169218	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR2004-005167	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	6301 HEMBREE LANE		
Location(OSWCR):	6301 HEMBREE LANE		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR2010-002872	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	600 OLD REDWOOD HWY		
Location(OSWCR):	600 OLD REDWOOD HWY		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water		

Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR1985-001062	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0226964	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0138851	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0250734	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma

County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	6285 REDWOOD HIWAY NORTH		
Location(OSWCR):	6285 REDWOOD HIWAY NORTH		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0115327	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR1986-006341	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0250736	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	6286 OLD RED WOOD WHY		
Location(OSWCR):	6286 OLD RED WOOD WHY		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR1998-004197	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	1170 KITTYHAWK BLVD_		
Location(OSWCR):	1170 KITTYHAWK BLVD_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0222213	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0051735	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0218340	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859

Decimal Longitude: -122.78859
Location: 6130 TAMARA LANE
Location(OSWCR): 6130 TAMARA LANE
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR0111082
City: None
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: None
Location(OSWCR): None
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR0051739
City: None
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: None
Location(OSWCR): None
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR0121416
City: None
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: None
Location(OSWCR): None
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0135671	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0148215	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0038032	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0191715	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		

Location(OSWCR): None
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR0171923
City: None
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: None
Location(OSWCR): None
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR0295608
City: None
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: None
Location(OSWCR): None
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR0085226
City: None
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: PRIVET ROAD
Location(OSWCR): PRIVET ROAD
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0194236	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0205961	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	AS ABOVE		
Location(OSWCR):	AS ABOVE		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0285818	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0297057	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	5913 OLD REDWOOD HWY		
Location(OSWCR):	5913 OLD REDWOOD HWY		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water		

Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0173303	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	SHILO ROAD		
Location(OSWCR):	SHILO ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0046542	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0128502	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0226963	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma

County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR1998-000345	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR1994-003435	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	6199 OLD REDWOOD HWY_		
Location(OSWCR):	6199 OLD REDWOOD HWY_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0312247	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0142107	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR1998-000346	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0138852	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	6284 OLD REDWOOD HWY		
Location(OSWCR):	6284 OLD REDWOOD HWY		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR2003-003784	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859

Decimal Longitude: -122.78859
Location: 1175 KITTYHAWK BLVD_
Location(OSWCR): 1175 KITTYHAWK BLVD_
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR2004-003731
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: 1145 KITTY HAWK
Location(OSWCR): 1145 KITTY HAWK
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR2010-002874
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: 600 OLD REDWOOD HWY
Location(OSWCR): 600 OLD REDWOOD HWY
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR2010-002873
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: 600 OLD REDWOOD HWY
Location(OSWCR): 600 OLD REDWOOD HWY
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0203732	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0171925	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	HWY 101 AND SHILO ROAD		
Location(OSWCR):	HWY 101 AND SHILO ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR1983-001038	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0319383	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	5925 LAFAYETTE DRIVE		

Location(OSWCR): 5925 LAFAYETTE DRIVE
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR0266926
City: None
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: None
Location(OSWCR): None
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR0093622
City: None
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: None
Location(OSWCR): None
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR0160190
City: SANTA ROSA
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: 6030 OLD REDWOOD HIGHWAY NORTH
Location(OSWCR): 6030 OLD REDWOOD HIGHWAY NORTH
City(OSWCR): SANTA ROSA
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0135672	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0021895	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR2003-003777	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	1175 KITTYHAWK BLVD_		
Location(OSWCR):	1175 KITTYHAWK BLVD_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0192559	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water		

Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0245776	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR2004-003729	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	1145 KITTYHAWK		
Location(OSWCR):	1145 KITTYHAWK		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0085233	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0267906	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma

County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0024423	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0127853	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0247210	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0020056	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0241644	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR2004-003784	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	1145 KITTY HAWK		
Location(OSWCR):	1145 KITTY HAWK		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR1998-003279	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859

Decimal Longitude: -122.78859
Location: 900 WILSON LN_
Location(OSWCR): 900 WILSON LN_
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR1994-000194
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: 705 SHILOH RD_
Location(OSWCR): 705 SHILOH RD_
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR0169219
City: None
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: SAME
Location(OSWCR): SAME
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR2001-001912
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: 705 SHILOH RD_
Location(OSWCR): 705 SHILOH RD_
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0231719	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR1994-000416	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	930 SHILOH RD_		
Location(OSWCR):	930 SHILOH RD_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR1984-000701	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR2005-003755	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	930 SHILOH RD		

Location(OSWCR): 930 SHILOH RD
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR2003-003778
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: 1175 KITTYHAWK BLVD_
Location(OSWCR): 1175 KITTYHAWK BLVD_
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR1998-005751
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: 190 SHILOH RD
Location(OSWCR): 190 SHILOH RD
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No: WCR0205959
City: None
County: Sonoma
Decimal Latitude: 38.52572
Decimal Longitude: -122.78859
Location: None
Location(OSWCR): None
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52572
Decim Long(OSWCR): -122.78859

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0202760	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0213581	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0046549	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0266924	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water		

Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0278643	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR0312795	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR2000-007310	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	376 SHILOH RD_		
Location(OSWCR):	376 SHILOH RD_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR1983-000975	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma

County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR2004-003781	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	1145 KITTY HAWK		
Location(OSWCR):	1145 KITTY HAWK		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.08	440.16	122.93	WATER WELLS

WCR No:	WCR2004-005169	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52572
Decimal Latitude:	38.52572	Decim Long(OSWCR):	-122.78859
Decimal Longitude:	-122.78859		
Location:	6301 HEMBREE LANE		
Location(OSWCR):	6301 HEMBREE LANE		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
9	WNW	0.09	471.56	112.66	WATER WELLS

WCR No:	WCR2020-000028	City(OSWCR):	Windsor
City:	Windsor	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.5242667
Decimal Latitude:	38.5242667	Decim Long(OSWCR):	-122.7944922
Decimal Longitude:	-122.7944922		
Location:	930 Shiloh RD		
Location(OSWCR):	930 Shiloh RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
10	WNW	0.10	549.19	112.72	WATER WELLS

WCR No:	WCR2020-000031	City(OSWCR):	Windsor
City:	Windsor	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.5237536
Decimal Latitude:	38.5237536	Decim Long(OSWCR):	-122.7941265
Decimal Longitude:	-122.7941265		
Location:	930 Shiloh RD		
Location(OSWCR):	930 Shiloh RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
11	WNW	0.11	555.48	113.09	WATER WELLS

WCR No:	WCR2020-000026	City(OSWCR):	Windsor
City:	Windsor	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52398315
Decimal Latitude:	38.52398315	Decim Long(OSWCR):	-122.7945331
Decimal Longitude:	-122.7945331		
Location:	930 Shiloh RD		
Location(OSWCR):	930 Shiloh RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
12	WNW	0.11	579.41	112.74	WATER WELLS

WCR No:	WCR2020-000027	City(OSWCR):	Windsor
City:	Windsor	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.524123
Decimal Latitude:	38.524123	Decim Long(OSWCR):	-122.7948504
Decimal Longitude:	-122.7948504		
Location:	930 Shiloh RD		
Location(OSWCR):	930 Shiloh RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-007002	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722

Decimal Longitude: -122.794722
Location: 930 SHILOH ROAD
Location(OSWCR): 930 SHILOH ROAD
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No: WCR2015-006946
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.523889
Decimal Longitude: -122.794722
Location: 930 SHILOH ROAD
Location(OSWCR): 930 SHILOH ROAD
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.523889
Decim Long(OSWCR): -122.794722
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No: WCR2015-007013
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.523889
Decimal Longitude: -122.794722
Location: 930 SHILOH ROAD
Location(OSWCR): 930 SHILOH ROAD
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.523889
Decim Long(OSWCR): -122.794722
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No: WCR2015-007025
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.523889
Decimal Longitude: -122.794722
Location: 930 SHILOH ROAD
Location(OSWCR): 930 SHILOH ROAD
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.523889
Decim Long(OSWCR): -122.794722
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-006942	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-007029	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-007008	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-006972	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		

Location(OSWCR): 930 SHILOH ROAD
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No: WCR2015-007017
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.523889
Decimal Longitude: -122.794722
Location: 930 SHILOH ROAD
Location(OSWCR): 930 SHILOH ROAD
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.523889
Decim Long(OSWCR): -122.794722
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No: WCR2015-006992
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.523889
Decimal Longitude: -122.794722
Location: 930 SHILOH ROAD
Location(OSWCR): 930 SHILOH ROAD
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.523889
Decim Long(OSWCR): -122.794722
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No: WCR2015-006968
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.523889
Decimal Longitude: -122.794722
Location: 930 SHILOH ROAD
Location(OSWCR): 930 SHILOH ROAD
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.523889
Decim Long(OSWCR): -122.794722
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

Wells and Additional Sources Detail Report

WCR No:	WCR2015-006956	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-006967	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-006984	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-006955	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water		

Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-007027	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-006987	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-007026	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-007001	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma

Wells and Additional Sources Detail Report

County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-007012	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-006993	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-006977	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-006981	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-007022	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-006990	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-006952	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722

Decimal Longitude: -122.794722
Location: 930 SHILOH ROAD
Location(OSWCR): 930 SHILOH ROAD
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No: WCR2015-006988
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.523889
Decimal Longitude: -122.794722
Location: 930 SHILOH ROAD
Location(OSWCR): 930 SHILOH ROAD
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.523889
Decim Long(OSWCR): -122.794722
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No: WCR2015-006980
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.523889
Decimal Longitude: -122.794722
Location: 930 SHILOH ROAD
Location(OSWCR): 930 SHILOH ROAD
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.523889
Decim Long(OSWCR): -122.794722
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No: WCR2015-007000
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.523889
Decimal Longitude: -122.794722
Location: 930 SHILOH ROAD
Location(OSWCR): 930 SHILOH ROAD
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.523889
Decim Long(OSWCR): -122.794722
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-006975	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-007015	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-007014	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-006951	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		

Location(OSWCR): 930 SHILOH ROAD
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No: WCR2015-006948
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.523889
Decimal Longitude: -122.794722
Location: 930 SHILOH ROAD
Location(OSWCR): 930 SHILOH ROAD
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.523889
Decim Long(OSWCR): -122.794722
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No: WCR2015-006978
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.523889
Decimal Longitude: -122.794722
Location: 930 SHILOH ROAD
Location(OSWCR): 930 SHILOH ROAD
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.523889
Decim Long(OSWCR): -122.794722
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No: WCR2015-007018
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.523889
Decimal Longitude: -122.794722
Location: 930 SHILOH ROAD
Location(OSWCR): 930 SHILOH ROAD
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.523889
Decim Long(OSWCR): -122.794722
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

Wells and Additional Sources Detail Report

WCR No:	WCR2015-006986	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-007004	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-007009	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-006945	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water		

Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-007019	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-006971	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-006989	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-006976	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma

County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-006994	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-007007	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-006995	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-007023	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-006949	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-007016	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-006985	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722

Decimal Longitude: -122.794722
Location: 930 SHILOH ROAD
Location(OSWCR): 930 SHILOH ROAD
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No: WCR2015-006947
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.523889
Decimal Longitude: -122.794722
Location: 930 SHILOH ROAD
Location(OSWCR): 930 SHILOH ROAD
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.523889
Decim Long(OSWCR): -122.794722
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No: WCR2015-006943
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.523889
Decimal Longitude: -122.794722
Location: 930 SHILOH ROAD
Location(OSWCR): 930 SHILOH ROAD
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.523889
Decim Long(OSWCR): -122.794722
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No: WCR2015-006944
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.523889
Decimal Longitude: -122.794722
Location: 930 SHILOH ROAD
Location(OSWCR): 930 SHILOH ROAD
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.523889
Decim Long(OSWCR): -122.794722
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-007003	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-006973	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-007028	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-006999	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		

Location(OSWCR): 930 SHILOH ROAD
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No: WCR2015-006983
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.523889
Decimal Longitude: -122.794722
Location: 930 SHILOH ROAD
Location(OSWCR): 930 SHILOH ROAD
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.523889
Decim Long(OSWCR): -122.794722
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No: WCR2015-007024
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.523889
Decimal Longitude: -122.794722
Location: 930 SHILOH ROAD
Location(OSWCR): 930 SHILOH ROAD
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.523889
Decim Long(OSWCR): -122.794722
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No: WCR2015-007021
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.523889
Decimal Longitude: -122.794722
Location: 930 SHILOH ROAD
Location(OSWCR): 930 SHILOH ROAD
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.523889
Decim Long(OSWCR): -122.794722
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

Wells and Additional Sources Detail Report

WCR No:	WCR2015-006979	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-006998	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-007030	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-006954	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water		

Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-007005	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-006970	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-007011	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-006974	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma

Wells and Additional Sources Detail Report

County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-006950	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-006966	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-007006	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-007010	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-006982	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-007032	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722
Decimal Longitude:	-122.794722		
Location:	930 SHILOH ROAD		
Location(OSWCR):	930 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No:	WCR2015-006991	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.523889
Decimal Latitude:	38.523889	Decim Long(OSWCR):	-122.794722

Decimal Longitude: -122.794722
Location: 930 SHILOH ROAD
Location(OSWCR): 930 SHILOH ROAD
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No: WCR2015-007038
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.523889
Decimal Longitude: -122.794722
Location: 930 SHILOH ROAD
Location(OSWCR): 930 SHILOH ROAD
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.523889
Decim Long(OSWCR): -122.794722
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.12	617.27	113.08	WATER WELLS

WCR No: WCR2015-006953
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.523889
Decimal Longitude: -122.794722
Location: 930 SHILOH ROAD
Location(OSWCR): 930 SHILOH ROAD
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.523889
Decim Long(OSWCR): -122.794722
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
14	WNW	0.12	653.37	113.42	WATER WELLS

WCR No: WCR2020-000025
City: Sonoma
County: Sonoma
Decimal Latitude: 38.5234606
Decimal Longitude: -122.7942072
Location: 930 Shiloh RD
Location(OSWCR): 930 Shiloh RD
City(OSWCR): Sonoma
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.5234606
Decim Long(OSWCR): -122.7942072
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	NW	0.12	657.88	105.53	WATER WELLS

WCR No:	WCR2004-008695	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	
Decimal Latitude:		Decim Long(OSWCR):	
Decimal Longitude:			
Location:	930 SHILOH RD		
Location(OSWCR):	930 SHILOH RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	NW	0.12	657.88	105.53	WATER WELLS

WCR No:	WCR2004-008654	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	
Decimal Latitude:		Decim Long(OSWCR):	
Decimal Longitude:			
Location:	930 SHILOH RD		
Location(OSWCR):	930 SHILOH RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	NW	0.12	657.88	105.53	WATER WELLS

WCR No:	WCR2004-008659	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	
Decimal Latitude:		Decim Long(OSWCR):	
Decimal Longitude:			
Location:	930 SHILOH RD		
Location(OSWCR):	930 SHILOH RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	NW	0.12	657.88	105.53	WATER WELLS

WCR No:	WCR2004-008444	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	
Decimal Latitude:		Decim Long(OSWCR):	
Decimal Longitude:			
Location:	930 SHILOH RD		

Location(OSWCR): 930 SHILOH RD
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	NW	0.12	657.88	105.53	WATER WELLS

WCR No: WCR2004-008293
City: WINDSOR
County: Sonoma
Decimal Latitude:
Decimal Longitude:
Location: 930 SHILOH RD
Location(OSWCR): 930 SHILOH RD
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR):
Decim Long(OSWCR):

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	NW	0.12	657.88	105.53	WATER WELLS

WCR No: WCR2004-008943
City: WINDSOR
County: Sonoma
Decimal Latitude:
Decimal Longitude:
Location: 930 SHILOH RD
Location(OSWCR): 930 SHILOH RD
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR):
Decim Long(OSWCR):

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	NW	0.12	657.88	105.53	WATER WELLS

WCR No: WCR2004-008649
City: WINDSOR
County: Sonoma
Decimal Latitude:
Decimal Longitude:
Location: 930 SHILOH RD
Location(OSWCR): 930 SHILOH RD
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR):
Decim Long(OSWCR):

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	NW	0.12	657.88	105.53	WATER WELLS

WCR No:	WCR2004-008651	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	
Decimal Latitude:		Decim Long(OSWCR):	
Decimal Longitude:			
Location:	930 SHILOH RD		
Location(OSWCR):	930 SHILOH RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	NW	0.12	657.88	105.53	WATER WELLS

WCR No:	WCR2004-008696	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	
Decimal Latitude:		Decim Long(OSWCR):	
Decimal Longitude:			
Location:	930 SHILOH RD		
Location(OSWCR):	930 SHILOH RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	NW	0.12	657.88	105.53	WATER WELLS

WCR No:	WCR2004-008658	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	
Decimal Latitude:		Decim Long(OSWCR):	
Decimal Longitude:			
Location:	930 SHILOH RD		
Location(OSWCR):	930 SHILOH RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	NW	0.12	657.88	105.53	WATER WELLS

WCR No:	WCR2004-008647	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	
Decimal Latitude:		Decim Long(OSWCR):	
Decimal Longitude:			
Location:	930 SHILOH RD		
Location(OSWCR):	930 SHILOH RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water		

Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	NW	0.12	657.88	105.53	WATER WELLS

WCR No:	WCR2004-008698	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	
Decimal Latitude:		Decim Long(OSWCR):	
Decimal Longitude:			
Location:	930 SHILOH RD		
Location(OSWCR):	930 SHILOH RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	NW	0.12	657.88	105.53	WATER WELLS

WCR No:	WCR2004-008982	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	
Decimal Latitude:		Decim Long(OSWCR):	
Decimal Longitude:			
Location:	930 SHILOH RD		
Location(OSWCR):	930 SHILOH RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	NW	0.12	657.88	105.53	WATER WELLS

WCR No:	WCR2004-008981	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	
Decimal Latitude:		Decim Long(OSWCR):	
Decimal Longitude:			
Location:	930 SHILOH RD		
Location(OSWCR):	930 SHILOH RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	NW	0.12	657.88	105.53	WATER WELLS

WCR No:	WCR2004-008815	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma

County: Sonoma
Decimal Lat(OSWCR):
Decimal Latitude:
Decim Long(OSWCR):
Decimal Longitude:
Location: 930 SHILOH RD
Location(OSWCR): 930 SHILOH RD
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	NW	0.12	657.88	105.53	WATER WELLS

WCR No: WCR2004-008652
City(OSWCR): WINDSOR
City: WINDSOR
County(OSWCR): Sonoma
County: Sonoma
Decimal Lat(OSWCR):
Decimal Latitude:
Decim Long(OSWCR):
Decimal Longitude:
Location: 930 SHILOH RD
Location(OSWCR): 930 SHILOH RD
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	NW	0.12	657.88	105.53	WATER WELLS

WCR No: WCR2004-008291
City(OSWCR): WINDSOR
City: WINDSOR
County(OSWCR): Sonoma
County: Sonoma
Decimal Lat(OSWCR):
Decimal Latitude:
Decim Long(OSWCR):
Decimal Longitude:
Location: 930 SHILOH RD
Location(OSWCR): 930 SHILOH RD
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	NW	0.12	657.88	105.53	WATER WELLS

WCR No: WCR2004-008648
City(OSWCR): WINDSOR
City: WINDSOR
County(OSWCR): Sonoma
County: Sonoma
Decimal Lat(OSWCR):
Decimal Latitude:
Decim Long(OSWCR):
Decimal Longitude:
Location: 930 SHILOH RD
Location(OSWCR): 930 SHILOH RD
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	NW	0.12	657.88	105.53	WATER WELLS

WCR No:	WCR2004-008656	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	
Decimal Latitude:		Decim Long(OSWCR):	
Decimal Longitude:			
Location:	930 SHILOH RD		
Location(OSWCR):	930 SHILOH RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	NW	0.12	657.88	105.53	WATER WELLS

WCR No:	WCR2004-008657	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	
Decimal Latitude:		Decim Long(OSWCR):	
Decimal Longitude:			
Location:	930 SHILOH RD		
Location(OSWCR):	930 SHILOH RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	NW	0.12	657.88	105.53	WATER WELLS

WCR No:	WCR2004-009005	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	
Decimal Latitude:		Decim Long(OSWCR):	
Decimal Longitude:			
Location:	930 SHILOH RD		
Location(OSWCR):	930 SHILOH RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	NW	0.12	657.88	105.53	WATER WELLS

WCR No:	WCR2004-008292	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	
Decimal Latitude:		Decim Long(OSWCR):	

Decimal Longitude:
Location: 930 SHILOH RD
Location(OSWCR): 930 SHILOH RD
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	NW	0.12	657.88	105.53	WATER WELLS

WCR No: WCR2004-008673
City: WINDSOR
County: Sonoma
Decimal Latitude:
Decimal Longitude:
Location: 930 SHILOH RD
Location(OSWCR): 930 SHILOH RD
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR):
Decim Long(OSWCR):
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	NW	0.12	657.88	105.53	WATER WELLS

WCR No: WCR2004-008655
City: WINDSOR
County: Sonoma
Decimal Latitude:
Decimal Longitude:
Location: 930 SHILOH RD
Location(OSWCR): 930 SHILOH RD
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR):
Decim Long(OSWCR):
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	NW	0.12	657.88	105.53	WATER WELLS

WCR No: WCR2004-008650
City: WINDSOR
County: Sonoma
Decimal Latitude:
Decimal Longitude:
Location: 930 SHILOH RD
Location(OSWCR): 930 SHILOH RD
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR):
Decim Long(OSWCR):
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	NW	0.12	657.88	105.53	WATER WELLS

WCR No:	WCR2004-008944	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	
Decimal Latitude:		Decim Long(OSWCR):	
Decimal Longitude:			
Location:	930 SHILOH RD		
Location(OSWCR):	930 SHILOH RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	NW	0.12	657.88	105.53	WATER WELLS

WCR No:	WCR2004-008653	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	
Decimal Latitude:		Decim Long(OSWCR):	
Decimal Longitude:			
Location:	930 SHILOH RD		
Location(OSWCR):	930 SHILOH RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	NW	0.12	657.88	105.53	WATER WELLS

WCR No:	WCR2004-008697	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	
Decimal Latitude:		Decim Long(OSWCR):	
Decimal Longitude:			
Location:	930 SHILOH RD		
Location(OSWCR):	930 SHILOH RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	NW	0.12	657.88	105.53	WATER WELLS

WCR No:	WCR2004-009006	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	
Decimal Latitude:		Decim Long(OSWCR):	
Decimal Longitude:			
Location:	930 SHILOH RD		

Location(OSWCR): 930 SHILOH RD
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	NW	0.12	657.88	105.53	WATER WELLS

WCR No: WCR2004-008660
City: WINDSOR
County: Sonoma
Decimal Latitude:
Decimal Longitude:
Location: 930 SHILOH RD
Location(OSWCR): 930 SHILOH RD
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR):
Decim Long(OSWCR):

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	NW	0.12	657.88	105.53	WATER WELLS

WCR No: WCR2004-008980
City: WINDSOR
County: Sonoma
Decimal Latitude:
Decimal Longitude:
Location: 930 SHILOH RD
Location(OSWCR): 930 SHILOH RD
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR):
Decim Long(OSWCR):

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	NW	0.12	657.88	105.53	WATER WELLS

WCR No: WCR2004-008984
City: WINDSOR
County: Sonoma
Decimal Latitude:
Decimal Longitude:
Location: 930 SHILOH RD
Location(OSWCR): 930 SHILOH RD
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR):
Decim Long(OSWCR):

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
16	WNW	0.21	1,093.78	113.35	WATER WELLS

WCR No:	WCR2011-006972	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.5222222
Decimal Latitude:	38.5222222	Decim Long(OSWCR):	-122.7944444
Decimal Longitude:	-122.7944444		
Location:	930 SHILOH RD		
Location(OSWCR):	930 SHILOH RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
17	WNW	0.22	1,166.68	113.64	WATER WELLS

WCR No:	WCR2011-006973	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.5219444
Decimal Latitude:	38.5219444	Decim Long(OSWCR):	-122.7941667
Decimal Longitude:	-122.7941667		
Location:	930 SHILOH RD		
Location(OSWCR):	930 SHILOH RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
19	SSE	0.23	1,225.26	124.87	WATER WELLS

WCR No:	WCR2019-010748	City(OSWCR):	Santa Rosa
City:	Santa Rosa	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.5143611
Decimal Latitude:	38.5143611	Decim Long(OSWCR):	-122.7828639
Decimal Longitude:	-122.7828639		
Location:	849 Airport BLVD		
Location(OSWCR):	849 Airport BLVD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
20	NW	0.27	1,401.61	103.48	WATER WELLS

WCR No:	WCR0297338	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52703803
Decimal Latitude:	38.52703803	Decim Long(OSWCR):	-122.79846736
Decimal Longitude:	-122.79846736		
Location:	7215 CONDE LANE		
Location(OSWCR):	7215 CONDE LANE		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water		

Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
21	ESE	0.27	1,446.22	129.87	WATER WELLS

WCR No:	WCR0138608	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51660684
Decimal Latitude:	38.51660684	Decim Long(OSWCR):	-122.77815272
Decimal Longitude:	-122.77815272		
Location:	417 DONNA DRIVE		
Location(OSWCR):	417 DONNA DRIVE		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
22	NNE	0.29	1,528.11	127.47	WATER WELLS

WCR No:	WCR0085227	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52669189
Decimal Latitude:	38.52669189	Decim Long(OSWCR):	-122.78477635
Decimal Longitude:	-122.78477635		
Location:	295 SHILOH ROAD		
Location(OSWCR):	295 SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
23	N	0.29	1,544.20	120.36	WATER WELLS

WCR No:	WCR2018-002970	City(OSWCR):	Windsor
City:	Windsor	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.5296877
Decimal Latitude:	38.5296877	Decim Long(OSWCR):	-122.7891172
Decimal Longitude:	-122.7891172		
Location:	6816 Hembre LN		
Location(OSWCR):	6816 Hembre LN		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
25	NNW	0.31	1,614.23	113.30	WATER WELLS

WCR No:	WCR0149251	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma

Wells and Additional Sources Detail Report

County:	Sonoma	Decimal Lat(OSWCR):	38.53014207
Decimal Latitude:	38.53014207	Decim Long(OSWCR):	-122.79201924
Decimal Longitude:	-122.79201924		
Location:	6842 HEMBREE LANE		
Location(OSWCR):	6842 HEMBREE LANE		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
26	NNW	0.32	1,680.90	111.67	WATER WELLS

WCR No:	WCR2018-002971	City(OSWCR):	Windsor
City:	Windsor	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.5303519
Decimal Latitude:	38.5303519	Decim Long(OSWCR):	-122.7923894
Decimal Longitude:	-122.7923894		
Location:	6842 Hembre LN		
Location(OSWCR):	6842 Hembre LN		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
27	ESE	0.32	1,686.02	130.88	WATER WELLS

WCR No:	WCR2019-013430	City(OSWCR):	Windsor
City:	Windsor	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.5160715
Decimal Latitude:	38.5160715	Decim Long(OSWCR):	-122.7774984
Decimal Longitude:	-122.7774984		
Location:	496 Donna DR		
Location(OSWCR):	496 Donna DR		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
27	ESE	0.32	1,686.02	130.88	WATER WELLS

WCR No:	WCR2019-008919	City(OSWCR):	Windsor
City:	Windsor	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.5160715
Decimal Latitude:	38.5160715	Decim Long(OSWCR):	-122.7774984
Decimal Longitude:	-122.7774984		
Location:	496 Donna DR		
Location(OSWCR):	496 Donna DR		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
28	ESE	0.33	1,723.98	131.15	WATER WELLS

WCR No:	WCR2017-009089	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.516389
Decimal Latitude:	38.516389	Decim Long(OSWCR):	-122.777222
Decimal Longitude:	-122.777222		
Location:	381 DONNA DRIVE		
Location(OSWCR):	381 DONNA DRIVE		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
30	N	0.34	1,784.45	119.28	WATER WELLS

WCR No:	WCR0231721	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.53038436
Decimal Latitude:	38.53038436	Decim Long(OSWCR):	-122.78922452
Decimal Longitude:	-122.78922452		
Location:	6816 HEMBREE LANE		
Location(OSWCR):	6816 HEMBREE LANE		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
31	SE	0.34	1,792.08	130.37	WATER WELLS

WCR No:	WCR2013-000658	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.5144444
Decimal Latitude:	38.5144444	Decim Long(OSWCR):	-122.7783333
Decimal Longitude:	-122.7783333		
Location:	464 MARK WEST STATION RD		
Location(OSWCR):	464 MARK WEST STATION RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
32	ESE	0.34	1,800.31	131.44	WATER WELLS

WCR No:	WCR2011-005740	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.5163889
Decimal Latitude:	38.5163889	Decim Long(OSWCR):	-122.7769444

Decimal Longitude: -122.7769444
Location: 377 DONNA DR
Location(OSWCR): 377 DONNA DR
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
33	SE	0.35	1,860.98	130.51	WATER WELLS

WCR No: WCR2014-000257
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.5141667
Decimal Longitude: -122.7783333
Location: 464 MARK WEST STATION
Location(OSWCR): 464 MARK WEST STATION
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.5141667
Decim Long(OSWCR): -122.7783333
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
34	NW	0.38	1,984.62	112.96	WATER WELLS

WCR No: WCR0111081
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.53094133
Decimal Longitude: -122.7961863
Location: 7500 CONDE LANE
Location(OSWCR): 7500 CONDE LANE
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.53094133
Decim Long(OSWCR): -122.7961863
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
34	NW	0.38	1,984.62	112.96	WATER WELLS

WCR No: WCR0149225
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.53094133
Decimal Longitude: -122.7961863
Location: 7500 C ONDE LANE
Location(OSWCR): 7500 C ONDE LANE
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.53094133
Decim Long(OSWCR): -122.7961863
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
35	SE	0.38	2,024.28	131.39	WATER WELLS

WCR No:	WCR2017-012990	City(OSWCR):	WINDSOR, CA 95492
City:	WINDSOR, CA 95492	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	
Decimal Latitude:		Decim Long(OSWCR):	
Decimal Longitude:			
Location:	383 MARK WEST STATION RD		
Location(OSWCR):	383 MARK WEST STATION RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
36	NE	0.39	2,054.86	132.16	WATER WELLS

WCR No:	WCR2014-015608	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.526111
Decimal Latitude:	38.526111	Decim Long(OSWCR):	-122.781944
Decimal Longitude:	-122.781944		
Location:	159 SHILOH RD		
Location(OSWCR):	159 SHILOH RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
37	ENE	0.39	2,082.28	131.71	WATER WELLS

WCR No:	WCR0090821	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52443404
Decimal Latitude:	38.52443404	Decim Long(OSWCR):	-122.78025254
Decimal Longitude:	-122.78025254		
Location:	5929 OLD REDWOOD HWY (LAFAYETTE DRIVE)		
Location(OSWCR):	5929 OLD REDWOOD HWY (LAFAYETTE DRIVE)		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
38	S	0.41	2,147.14	122.45	WATER WELLS

WCR No:	WCR0288286	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51182702
Decimal Latitude:	38.51182702	Decim Long(OSWCR):	-122.78692173
Decimal Longitude:	-122.78692173		
Location:	1315 AIRPORT BLVD		

Location(OSWCR): 1315 AIRPORT BLVD
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
39	ESE	0.41	2,185.39	132.76	WATER WELLS

WCR No: WCR2020-004041
City: Windsor
County: Sonoma
Decimal Latitude: 38.5163889
Decimal Longitude: -122.7755556
Location: 335 Donna DR
Location(OSWCR): 335 Donna DR
City(OSWCR): Windsor
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.5163889
Decim Long(OSWCR): -122.7755556
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
41	SSE	0.42	2,210.22	126.54	WATER WELLS

WCR No: WCR2013-000653
City: SANTA ROSA
County: Sonoma
Decimal Latitude: 38.5116667
Decimal Longitude: -122.7825
Location: 400 AVIATION BLVD
Location(OSWCR): 400 AVIATION BLVD
City(OSWCR): SANTA ROSA
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.5116667
Decim Long(OSWCR): -122.7825
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
42	SSW	0.42	2,214.62	116.71	WATER WELLS

WCR No: WCR2021-005694
City: Santa Rosa
County: Sonoma
Decimal Latitude: 38.5122944
Decimal Longitude: -122.7919444
Location: 1821 Airport BLVD
Location(OSWCR):
City(OSWCR):
County(OSWCR):
Decimal Lat(OSWCR):
Decim Long(OSWCR):
Original Source: California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
43	NE	0.43	2,258.63	132.59	WATER WELLS

WCR No: WCR2012-000757
City(OSWCR): WINDSOR

City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.5252778
Decimal Latitude:	38.5252778	Decim Long(OSWCR):	-122.7802778
Decimal Longitude:	-122.7802778		
Location:	64 SHILOH RD		
Location(OSWCR):	64 SHILOH RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
44	ESE	0.45	2,353.92	133.78	WATER WELLS

WCR No:	WCR2021-003449	City(OSWCR):	Windsor
City:	Windsor	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.516075
Decimal Latitude:	38.516075	Decim Long(OSWCR):	-122.7750472
Decimal Longitude:	-122.7750472		
Location:	5497 Kay DR		
Location(OSWCR):	5497 Kay DR		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
45	NW	0.45	2,394.30	102.93	WATER WELLS

WCR No:	WCR2017-009357	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.529722
Decimal Latitude:	38.529722	Decim Long(OSWCR):	-122.800556
Decimal Longitude:	-122.800556		
Location:	1200 AMERICAN WAY		
Location(OSWCR):	1200 AMERICAN WAY		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0221974	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0008243	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0196591	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0084995	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0169173	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108

Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	1604 AIRPORT BLVD		
Location(OSWCR):	1604 AIRPORT BLVD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR2005-000294	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	3621 COPPERHILL LANE		
Location(OSWCR):	3621 COPPERHILL LANE		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0088081	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0030968	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0173311	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0030969	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0221976	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0118585	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		

Location: None
Location(OSWCR): None
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No: WCR0216774
City: None
County: Sonoma
Decimal Latitude: 38.51108
Decimal Longitude: -122.78852
Location: None
Location(OSWCR): None
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.51108
Decim Long(OSWCR): -122.78852
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No: WCR0292966
City: None
County: Sonoma
Decimal Latitude: 38.51108
Decimal Longitude: -122.78852
Location: None
Location(OSWCR): None
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.51108
Decim Long(OSWCR): -122.78852
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No: WCR0205624
City: None
County: Sonoma
Decimal Latitude: 38.51108
Decimal Longitude: -122.78852
Location: None
Location(OSWCR): None
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.51108
Decim Long(OSWCR): -122.78852
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0278146	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	FULTON NE COR OF AIRPORT		
Location(OSWCR):	FULTON NE COR OF AIRPORT		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR2008-003921	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	404 AVIATION BLVD		
Location(OSWCR):	404 AVIATION BLVD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR1984-004013	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR2008-003760	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	1534 COOPERHILL PKWY		
Location(OSWCR):	1534 COOPERHILL PKWY		

Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0128796	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0258788	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0292965	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR2010-003590	City(OSWCR):	SANTA ROSA

Wells and Additional Sources Detail Report

City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	2500 MENDOCINO AVE		
Location(OSWCR):	2500 MENDOCINO AVE		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR2010-003588	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	2500 MENDOCINO AVE		
Location(OSWCR):	2500 MENDOCINO AVE		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0076720	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	NONE OWNER AT 540 BORHOM AVE		
Location(OSWCR):	NONE OWNER AT 540 BORHOM AVE		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR2011-000181	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	1315 AIRPORT BLVD		
Location(OSWCR):	1315 AIRPORT BLVD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR2010-003789	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	2500 MENDOCINO AVE		
Location(OSWCR):	2500 MENDOCINO AVE		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR2008-003759	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	1534 COOPERHILL PKWY		
Location(OSWCR):	1534 COOPERHILL PKWY		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0258787	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	1516 AIRPORT BLVD		
Location(OSWCR):	1516 AIRPORT BLVD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR2008-003756	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108

Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	1534 COOPERHILL PKWY		
Location(OSWCR):	1534 COOPERHILL PKWY		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0024655	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR2006-006219	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	3507 WESTWIND BLV		
Location(OSWCR):	3507 WESTWIND BLV		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR2008-003758	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	1534 COOPERHILL PKWY		
Location(OSWCR):	1534 COOPERHILL PKWY		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR2011-000179	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	1315 AIRPORT BLVD		
Location(OSWCR):	1315 AIRPORT BLVD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0292964	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR2011-000178	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	1315 AIRPORT BLVD		
Location(OSWCR):	1315 AIRPORT BLVD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR2008-003755	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		

Location: 1534 COOPERHILL PKWY
Location(OSWCR): 1534 COOPERHILL PKWY
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No: WCR2010-003589
City: SANTA ROSA
County: Sonoma
Decimal Latitude: 38.51108
Decimal Longitude: -122.78852
Location: 2500 MENDOCINO AVE
Location(OSWCR): 2500 MENDOCINO AVE
City(OSWCR): SANTA ROSA
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.51108
Decim Long(OSWCR): -122.78852
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No: WCR2003-003072
City: SANTA ROSA
County: Sonoma
Decimal Latitude: 38.51108
Decimal Longitude: -122.78852
Location: 421 AVIATION BLVD
Location(OSWCR): 421 AVIATION BLVD
City(OSWCR): SANTA ROSA
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.51108
Decim Long(OSWCR): -122.78852
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No: WCR0186006
City: SANTA ROSA
County: Sonoma
Decimal Latitude: 38.51108
Decimal Longitude: -122.78852
Location: 1534 COOPERHILL PKWY
Location(OSWCR): 1534 COOPERHILL PKWY
City(OSWCR): SANTA ROSA
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.51108
Decim Long(OSWCR): -122.78852
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0013606	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	FULTON W OF #2		
Location(OSWCR):	FULTON W OF #2		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0244891	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0193878	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0278147	City(OSWCR):	FULTON
City:	FULTON	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	3965 BISORDI LANE		
Location(OSWCR):	3965 BISORDI LANE		

Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR2010-004637	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	1534 COPPERHILL PKWY		
Location(OSWCR):	1534 COPPERHILL PKWY		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR2010-003790	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	2500 MENDOCINO AVE		
Location(OSWCR):	2500 MENDOCINO AVE		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0246858	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0076719	City(OSWCR):	None

City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	MAP ON BACK		
Location(OSWCR):	MAP ON BACK		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0051393	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	SAME		
Location(OSWCR):	SAME		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0258789	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	XXX		
Location(OSWCR):	XXX		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0040739	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR2008-003754	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	1534 COOPERHILL PKWY		
Location(OSWCR):	1534 COOPERHILL PKWY		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0093297	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0205623	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0030967	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108

Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0229970	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0159864	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0096365	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0178883	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0322152	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0102668	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0169172	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		

Location: None
Location(OSWCR): None
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No: WCR0115525
City: None
County: Sonoma
Decimal Latitude: 38.51108
Decimal Longitude: -122.78852
Location: None
Location(OSWCR): None
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.51108
Decim Long(OSWCR): -122.78852
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No: WCR0221975
City: None
County: Sonoma
Decimal Latitude: 38.51108
Decimal Longitude: -122.78852
Location: None
Location(OSWCR): None
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.51108
Decim Long(OSWCR): -122.78852
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No: WCR0199648
City: None
County: Sonoma
Decimal Latitude: 38.51108
Decimal Longitude: -122.78852
Location: None
Location(OSWCR): None
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.51108
Decim Long(OSWCR): -122.78852
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0253363	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	1534 COOPERHILL PKWY		
Location(OSWCR):	1534 COOPERHILL PKWY		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0212336	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	1534 COOPERHILL PKWY		
Location(OSWCR):	1534 COOPERHILL PKWY		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0252363	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	1514 AIRPORT BLVD		
Location(OSWCR):	1514 AIRPORT BLVD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR1989-010257	City(OSWCR):	HEALDSBURG
City:	HEALDSBURG	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	None		
Location(OSWCR):	None		

Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR2011-000180	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	1315 AIRPORT BLVD		
Location(OSWCR):	1315 AIRPORT BLVD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR1985-003531	City(OSWCR):	FULTON
City:	FULTON	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0051392	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	1388 AIRPORT BLVD		
Location(OSWCR):	1388 AIRPORT BLVD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR2008-003757	City(OSWCR):	SANTA ROSA

Wells and Additional Sources Detail Report

City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	1534 COOPERHILL PKWY		
Location(OSWCR):	1534 COOPERHILL PKWY		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR2006-006220	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	3507 WESTWIND BLVD		
Location(OSWCR):	3507 WESTWIND BLVD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0102870	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	3507 WESTWIND BL		
Location(OSWCR):	3507 WESTWIND BL		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR1999-003915	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	3405 WESTWIND BLVD		
Location(OSWCR):	3405 WESTWIND BLVD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0138613	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	SAME		
Location(OSWCR):	SAME		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR2010-003587	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	2500 MENDOCINO AVE		
Location(OSWCR):	2500 MENDOCINO AVE		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0246857	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	1502 LANE REDWOOD RD		
Location(OSWCR):	1502 LANE REDWOOD RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0244892	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108

Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	SAME		
Location(OSWCR):	SAME		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR0002619	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR2010-003585	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	2500 MENDOCINO AVE		
Location(OSWCR):	2500 MENDOCINO AVE		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR2010-003586	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	2500 MENDOCINO AVE		
Location(OSWCR):	2500 MENDOCINO AVE		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR1990-012727	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	847 AIRPORT BLVD		
Location(OSWCR):	847 AIRPORT BLVD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	S	0.46	2,419.15	120.99	WATER WELLS

WCR No:	WCR2006-006221	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51108
Decimal Latitude:	38.51108	Decim Long(OSWCR):	-122.78852
Decimal Longitude:	-122.78852		
Location:	3507 WESTWIND BLVD		
Location(OSWCR):	3507 WESTWIND BLVD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
47	E	0.47	2,503.98	133.01	WATER WELLS

WCR No:	WCR2008-001538	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.5191667
Decimal Latitude:	38.5191667	Decim Long(OSWCR):	-122.7744444
Decimal Longitude:	-122.7744444		
Location:	175 AIRPOOL BLVD		
Location(OSWCR):	175 AIRPOOL BLVD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
52	E	0.51	2,689.07	133.41	WATER WELLS

WCR No:	WCR0169223	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52120131
Decimal Latitude:	38.52120131	Decim Long(OSWCR):	-122.77470903
Decimal Longitude:	-122.77470903		

Wells and Additional Sources Detail Report

Location: 5720 OLD REDWOOD HWY
Location(OSWCR): 5720 OLD REDWOOD HWY
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
53	S	0.52	2,746.90	119.01	WATER WELLS

WCR No: WCR2013-005925
City: SANTA ROSA
County: Sonoma
Decimal Latitude: 38.5102778
Decimal Longitude: -122.79
Location: 1400 AIRPORT BLVD
Location(OSWCR): 1400 AIRPORT BLVD
City(OSWCR): SANTA ROSA
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.5102778
Decim Long(OSWCR): -122.79
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
54	S	0.54	2,837.50	121.21	WATER WELLS

WCR No: WCR0081966
City: SANTA ROSA
County: Sonoma
Decimal Latitude: 38.50993066
Decimal Longitude: -122.78802369
Location: 1350 AIRPORT BLVD
Location(OSWCR): 1350 AIRPORT BLVD
City(OSWCR): SANTA ROSA
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.50993066
Decim Long(OSWCR): -122.78802369
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
56	NW	0.62	3,263.75	113.12	WATER WELLS

WCR No: WCR0261657
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.53378424
Decimal Longitude: -122.79905155
Location: 7667 CONDE LANE
Location(OSWCR): 7667 CONDE LANE
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.53378424
Decim Long(OSWCR): -122.79905155
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
57	ESE	0.62	3,264.35	136.38	WATER WELLS

WCR No:	WCR2019-008793	City(OSWCR):	Windsor
City:	Windsor	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.5145127
Decimal Latitude:	38.5145127	Decim Long(OSWCR):	-122.7723492
Decimal Longitude:	-122.7723492		
Location:	120 Mark West Station RD		
Location(OSWCR):	120 Mark West Station RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
58	ESE	0.62	3,278.02	136.41	WATER WELLS

WCR No:	WCR2019-004021	City(OSWCR):	Windsor
City:	Windsor	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.5145484
Decimal Latitude:	38.5145484	Decim Long(OSWCR):	-122.7722808
Decimal Longitude:	-122.7722808		
Location:	120 Mark West station RD		
Location(OSWCR):	120 Mark West station RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
59	ESE	0.62	3,295.66	136.53	WATER WELLS

WCR No:	WCR2014-000452	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.5161111
Decimal Latitude:	38.5161111	Decim Long(OSWCR):	-122.7716667
Decimal Longitude:	-122.7716667		
Location:	143 MEADOW PL		
Location(OSWCR):	143 MEADOW PL		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
60	ESE	0.63	3,322.82	136.74	WATER WELLS

WCR No:	WCR0202771	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51432728
Decimal Latitude:	38.51432728	Decim Long(OSWCR):	-122.77222225
Decimal Longitude:	-122.77222225		
Location:	120 MARK WEST STATION ROAD		
Location(OSWCR):	120 MARK WEST STATION ROAD		

Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
62	NNE	0.66	3,490.81	134.35	WATER WELLS

WCR No:	WCR0325428	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.53262299
Decimal Latitude:	38.53262299	Decim Long(OSWCR):	-122.78216587
Decimal Longitude:	-122.78216587		
Location:	6288 OLD REDWOOD HWY		
Location(OSWCR):	6288 OLD REDWOOD HWY		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
63	SE	0.68	3,611.20	138.00	WATER WELLS

WCR No:	WCR2012-004505	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.5122222
Decimal Latitude:	38.5122222	Decim Long(OSWCR):	-122.7725
Decimal Longitude:	-122.7725		
Location:	651 AIRPORT BLVD		
Location(OSWCR):	651 AIRPORT BLVD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
64	ESE	0.68	3,613.35	137.84	WATER WELLS

WCR No:	WCR0040733	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51565792
Decimal Latitude:	38.51565792	Decim Long(OSWCR):	-122.77064845
Decimal Longitude:	-122.77064845		
Location:	5503 REDWOOD HIGHWAY NO		
Location(OSWCR):	5503 REDWOOD HIGHWAY NO		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
65	SE	0.69	3,668.28	138.33	WATER WELLS

WCR No:	WCR2012-005327	City(OSWCR):	SANTA ROSA

City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.5119444
Decimal Latitude:	38.5119444	Decim Long(OSWCR):	-122.7725
Decimal Longitude:	-122.7725		
Location:	651 AIRPORT BLVD		
Location(OSWCR):	651 AIRPORT BLVD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
66	W	0.70	3,692.16	103.34	WATER WELLS

WCR No:	WCR0178949	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52303412
Decimal Latitude:	38.52303412	Decim Long(OSWCR):	-122.80623502
Decimal Longitude:	-122.80623502		
Location:	6858 DAY ROAD		
Location(OSWCR):	6858 DAY ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
67	N	0.73	3,830.04	132.76	WATER WELLS

WCR No:	WCR2006-002846	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.5361111
Decimal Latitude:	38.5361111	Decim Long(OSWCR):	-122.79
Decimal Longitude:	-122.79		
Location:	6422 OLD REDWOOD HWY		
Location(OSWCR):	6422 OLD REDWOOD HWY		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR0171941	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR0187847	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	SAME		
Location(OSWCR):	SAME		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR2000-006480	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	930 SHILOH RD		
Location(OSWCR):	930 SHILOH RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR0173551	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR0074675	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556

Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR0178956	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR0013875	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	SAME		
Location(OSWCR):	SAME		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR2000-006481	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	930 SHILOH RD		
Location(OSWCR):	930 SHILOH RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR1986-003267	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR2000-004616	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	1655 SANDERS RD		
Location(OSWCR):	1655 SANDERS RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR2004-004910	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	900 WILSON LN		
Location(OSWCR):	900 WILSON LN		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR2000-006483	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		

Wells and Additional Sources Detail Report

Location: 930 SHILOH RD
Location(OSWCR): 930 SHILOH RD
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No: WCR0122059
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.52556
Decimal Longitude: -122.80737
Location: None
Location(OSWCR): None
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52556
Decim Long(OSWCR): -122.80737
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No: WCR2000-006482
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.52556
Decimal Longitude: -122.80737
Location: 930 SHILOH RD
Location(OSWCR): 930 SHILOH RD
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52556
Decim Long(OSWCR): -122.80737
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No: WCR0157251
City: None
County: Sonoma
Decimal Latitude: 38.52556
Decimal Longitude: -122.80737
Location: None
Location(OSWCR): None
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52556
Decim Long(OSWCR): -122.80737
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR0250754	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR2007-003863	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	7215 CONDE LANE		
Location(OSWCR):	7215 CONDE LANE		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR0021919	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	ON SHILO ROAD OFF OLD REDWOOD HWY		
Location(OSWCR):	ON SHILO ROAD OFF OLD REDWOOD HWY		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR1983-000982	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	None		
Location(OSWCR):	None		

Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR1984-003700	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR1999-006265	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	2000 SANDERS RD		
Location(OSWCR):	2000 SANDERS RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR1982-002159	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR0247234	City(OSWCR):	None

City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR0304830	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	SAME		
Location(OSWCR):	SAME		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR0178955	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	SAME		
Location(OSWCR):	SAME		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR0258862	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR0171942	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR0247233	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR0096621	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	SANDERS ROAD		
Location(OSWCR):	SANDERS ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR0231745	City(OSWCR):	FULTON
City:	FULTON	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556

Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR2004-000428	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	1750 SHILOH RD		
Location(OSWCR):	1750 SHILOH RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR0024449	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR0247232	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	6820 DAY ROAD		
Location(OSWCR):	6820 DAY ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR1994-002336	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	7649 CONDE LN		
Location(OSWCR):	7649 CONDE LN		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR0194249	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR2000-006427	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	1480 SANDERS RD		
Location(OSWCR):	1480 SANDERS RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR0122060	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		

Location: None
Location(OSWCR): None
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No: WCR0247239
City: SANTA ROSA
County: Sonoma
Decimal Latitude: 38.52556
Decimal Longitude: -122.80737
Location: None
Location(OSWCR): None
City(OSWCR): SANTA ROSA
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52556
Decim Long(OSWCR): -122.80737
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No: WCR2007-003862
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.52556
Decimal Longitude: -122.80737
Location: 7215 CONDE LANE
Location(OSWCR): 7215 CONDE LANE
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52556
Decim Long(OSWCR): -122.80737
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No: WCR0205978
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.52556
Decimal Longitude: -122.80737
Location: None
Location(OSWCR): None
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52556
Decim Long(OSWCR): -122.80737
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR2000-006484	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	930 SHILOH RD		
Location(OSWCR):	930 SHILOH RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR0261314	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR0178954	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR1999-006264	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	2000 SANDERS RD		
Location(OSWCR):	2000 SANDERS RD		

Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR1985-005308	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	WNW	0.73	3,876.34	100.56	WATER WELLS

WCR No:	WCR0021920	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52556
Decimal Latitude:	38.52556	Decim Long(OSWCR):	-122.80737
Decimal Longitude:	-122.80737		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
69	W	0.74	3,892.31	108.22	WATER WELLS

WCR No:	WCR2014-000258	City(OSWCR):	GEYSERVILLE
City:	GEYSERVILLE	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.5222222
Decimal Latitude:	38.5222222	Decim Long(OSWCR):	-122.8066667
Decimal Longitude:	-122.8066667		
Location:	8766 DRY CREEK RD.		
Location(OSWCR):	8766 DRY CREEK RD.		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
70	NNW	0.74	3,907.58	123.60	WATER WELLS

WCR No:	WCR0222004	City(OSWCR):	WINDSOR

Wells and Additional Sources Detail Report

City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.53646512
Decimal Latitude:	38.53646512	Decim Long(OSWCR):	-122.79553745
Decimal Longitude:	-122.79553745		
Location:	7893 HEMBREE LN		
Location(OSWCR):	7893 HEMBREE LN		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0327725	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR2001-003275	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	5321 OLD REDWOOD HWY_		
Location(OSWCR):	5321 OLD REDWOOD HWY_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0222230	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0205621	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	SAME		
Location(OSWCR):	SAME		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0321648	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0076714	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	2938 MARK STATION RD		
Location(OSWCR):	2938 MARK STATION RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0319406	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109

Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	SAME		
Location(OSWCR):	SAME		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0193867	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0252359	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	5215 REDWOOD HI NORTH OPPOSITE FAUGHT RO		
Location(OSWCR):	5215 REDWOOD HI NORTH OPPOSITE FAUGHT RO		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0258489	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0304564	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	DONNA DRIVE		
Location(OSWCR):	DONNA DRIVE		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0051761	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR1981-002436	City(OSWCR):	FULTON
City:	FULTON	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0261624	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		

Location: None
Location(OSWCR): None
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No: WCR2008-001271
City: SANTA ROSA
County: Sonoma
Decimal Latitude: 38.51109
Decimal Longitude: -122.76976
Location: 5379 OLD REDWOOD HWY
Location(OSWCR): 5379 OLD REDWOOD HWY
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports
City(OSWCR): SANTA ROSA
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.51109
Decim Long(OSWCR): -122.76976

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No: WCR1982-001593
City: SANTA ROSA
County: Sonoma
Decimal Latitude: 38.51109
Decimal Longitude: -122.76976
Location: None
Location(OSWCR): None
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports
City(OSWCR): SANTA ROSA
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.51109
Decim Long(OSWCR): -122.76976

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No: WCR1988-011346
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.51109
Decimal Longitude: -122.76976
Location: None
Location(OSWCR): None
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.51109
Decim Long(OSWCR): -122.76976

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR2003-004792	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	5321 OLD REDWOOD HWY_		
Location(OSWCR):	5321 OLD REDWOOD HWY_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR2003-004788	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	5321 OLD REDWOOD HWY_		
Location(OSWCR):	5321 OLD REDWOOD HWY_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR2003-004200	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	5321 OLD REDWOOD HWY_		
Location(OSWCR):	5321 OLD REDWOOD HWY_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR2003-004786	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	5321 OLD REDWOOD HWY_		
Location(OSWCR):	5321 OLD REDWOOD HWY_		

Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR1990-013386	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	5215 OLD REDWOOD HWY		
Location(OSWCR):	5215 OLD REDWOOD HWY		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0278503	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	77 DONNA DR		
Location(OSWCR):	77 DONNA DR		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR2000-007472	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	5321 OLD REDWOOD HWY_		
Location(OSWCR):	5321 OLD REDWOOD HWY_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR1988-011347	City(OSWCR):	WINDSOR

Wells and Additional Sources Detail Report

City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0231744	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0193868	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0149192	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR2004-003761	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	5321 OLD REDWOOD HIGHWAY		
Location(OSWCR):	5321 OLD REDWOOD HIGHWAY		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0246853	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0021560	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	MAP ON BACK		
Location(OSWCR):	MAP ON BACK		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0076712	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109

Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	255 DONNA DR		
Location(OSWCR):	255 DONNA DR		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0304565	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0090829	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0178878	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0278502	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	SAME		
Location(OSWCR):	SAME		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0090828	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	SAME		
Location(OSWCR):	SAME		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0138609	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0048236	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		

Location: None
Location(OSWCR): None
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No: WCR0067702
City: None
County: Sonoma
Decimal Latitude: 38.51109
Decimal Longitude: -122.76976
Location: None
Location(OSWCR): None
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.51109
Decim Long(OSWCR): -122.76976
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No: WCR1998-005119
City: SANTA ROSA
County: Sonoma
Decimal Latitude: 38.51109
Decimal Longitude: -122.76976
Location: 5321 OLD REDWOOD HWY_
Location(OSWCR): 5321 OLD REDWOOD HWY_
City(OSWCR): SANTA ROSA
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.51109
Decim Long(OSWCR): -122.76976
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No: WCR2009-002539
City: SANTA ROSA
County: Sonoma
Decimal Latitude: 38.51109
Decimal Longitude: -122.76976
Location: 5472 OLD PLACERVILLE RD
Location(OSWCR): 5472 OLD PLACERVILLE RD
City(OSWCR): SANTA ROSA
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.51109
Decim Long(OSWCR): -122.76976
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0253181	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR1986-003388	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0002613	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	330 MARK WEST STATION ROAD		
Location(OSWCR):	330 MARK WEST STATION ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0040801	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		

Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0122057	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0118297	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	MARK WEST STATION RD		
Location(OSWCR):	MARK WEST STATION RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0231743	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0199428	City(OSWCR):	None

City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0244911	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0145488	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0048555	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0093643	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	SAME		
Location(OSWCR):	SAME		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0117860	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0276258	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0192776	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109

Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0258491	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	SAME AS ABOVE		
Location(OSWCR):	SAME AS ABOVE		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0278144	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR2003-004202	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	5321 OLD REDWOOD HWY_		
Location(OSWCR):	5321 OLD REDWOOD HWY_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR2001-003276	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	5321 OLD REDWOOD HWY_		
Location(OSWCR):	5321 OLD REDWOOD HWY_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR1988-011348	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR2007-002755	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	5271 FAUGHT RD		
Location(OSWCR):	5271 FAUGHT RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR2003-004791	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		

Wells and Additional Sources Detail Report

Location: 5321 OLD REDWOOD HWY_
Location(OSWCR): 5321 OLD REDWOOD HWY_
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No: WCR2003-004787
City: SANTA ROSA
County: Sonoma
Decimal Latitude: 38.51109
Decimal Longitude: -122.76976
Location: 5321 OLD REDWOOD HWY_
Location(OSWCR): 5321 OLD REDWOOD HWY_
City(OSWCR): SANTA ROSA
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.51109
Decim Long(OSWCR): -122.76976
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No: WCR0149191
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.51109
Decimal Longitude: -122.76976
Location: DONNA DRIVE 1
Location(OSWCR): DONNA DRIVE 1
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.51109
Decim Long(OSWCR): -122.76976
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No: WCR2003-004199
City: SANTA ROSA
County: Sonoma
Decimal Latitude: 38.51109
Decimal Longitude: -122.76976
Location: 5321 OLD REDWOOD HWY_
Location(OSWCR): 5321 OLD REDWOOD HWY_
City(OSWCR): SANTA ROSA
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.51109
Decim Long(OSWCR): -122.76976
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR2001-003278	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	5321 OLD REDWOOD HWY_		
Location(OSWCR):	5321 OLD REDWOOD HWY_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR2003-004825	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	5321 OLD REDWOOD HWY_		
Location(OSWCR):	5321 OLD REDWOOD HWY_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR1980-001511	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0106089	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	SAME 5454 OLD REDWOOD HWY		
Location(OSWCR):	SAME 5454 OLD REDWOOD HWY		

Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR2000-007474	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	5321 OLD REDWOOD HWY_		
Location(OSWCR):	5321 OLD REDWOOD HWY_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR1998-005118	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	5321 OLD REDWOOD HWY_		
Location(OSWCR):	5321 OLD REDWOOD HWY_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR1995-005986	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0222231	City(OSWCR):	None

City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0261313	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	TRAILON COURT FULTON RD & 101 HIGHWAY		
Location(OSWCR):	TRAILON COURT FULTON RD & 101 HIGHWAY		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0067964	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0064184	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR1989-001154	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR2008-001270	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	301 AIRPORT BLVD		
Location(OSWCR):	301 AIRPORT BLVD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0146870	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0193866	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109

Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0328100	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0261626	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0205985	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	SAME		
Location(OSWCR):	SAME		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0118296	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0186005	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR1995-004695	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	5495 OLD REDWOOD HWY_		
Location(OSWCR):	5495 OLD REDWOOD HWY_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0037105	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		

Location: SAME
Location(OSWCR): SAME
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No: WCR0077079
City: None
County: Sonoma
Decimal Latitude: 38.51109
Decimal Longitude: -122.76976
Location: None
Location(OSWCR): None
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.51109
Decim Long(OSWCR): -122.76976
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No: WCR0193869
City: None
County: Sonoma
Decimal Latitude: 38.51109
Decimal Longitude: -122.76976
Location: None
Location(OSWCR): None
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.51109
Decim Long(OSWCR): -122.76976
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No: WCR0304829
City: None
County: Sonoma
Decimal Latitude: 38.51109
Decimal Longitude: -122.76976
Location: None
Location(OSWCR): None
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.51109
Decim Long(OSWCR): -122.76976
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0188158	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0080178	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0037131	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	RED HWY NO		
Location(OSWCR):	RED HWY NO		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0076713	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	SAME		
Location(OSWCR):	SAME		

Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0246854	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	270 MARK WEST STATION RD		
Location(OSWCR):	270 MARK WEST STATION RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0118295	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0218357	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0221969	City(OSWCR):	None

City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	SAME		
Location(OSWCR):	SAME		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0205984	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	MARK WEST STATION ROAD		
Location(OSWCR):	MARK WEST STATION ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0188159	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	64 DONNA DR		
Location(OSWCR):	64 DONNA DR		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0221970	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0110733	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0304566	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	SAME		
Location(OSWCR):	SAME		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR1992-004092	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	350 DONNA DR		
Location(OSWCR):	350 DONNA DR		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0067703	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109

Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	SHORT STOP MARKET OLD REDWOOD HWY NO		
Location(OSWCR):	SHORT STOP MARKET OLD REDWOOD HWY NO		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR2001-006840	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	417 DONNA DR		
Location(OSWCR):	417 DONNA DR		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0261623	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	401 DONNA DRIVE		
Location(OSWCR):	401 DONNA DRIVE		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR1996-003015	City(OSWCR):	SEBASTOPOL
City:	SEBASTOPOL	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	5230 OLD REDWOOD HWY_		
Location(OSWCR):	5230 OLD REDWOOD HWY_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR2009-000506	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	151 MEADOW PL		
Location(OSWCR):	151 MEADOW PL		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR1991-009830	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	5360 OLD REDWOOD HWY		
Location(OSWCR):	5360 OLD REDWOOD HWY		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR2005-003748	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	5352 OLD REDWOOD HWY		
Location(OSWCR):	5352 OLD REDWOOD HWY		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR2007-005413	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		

Wells and Additional Sources Detail Report

Location: 5229 FAUGHT RD
Location(OSWCR): 5229 FAUGHT RD
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No: WCR0021559
City: SANTA ROSA
County: Sonoma
Decimal Latitude: 38.51109
Decimal Longitude: -122.76976
Location: None
Location(OSWCR): None
City(OSWCR): SANTA ROSA
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.51109
Decim Long(OSWCR): -122.76976
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No: WCR1998-005120
City: SANTA ROSA
County: Sonoma
Decimal Latitude: 38.51109
Decimal Longitude: -122.76976
Location: 5321 OLD REDWOOD HWY_
Location(OSWCR): 5321 OLD REDWOOD HWY_
City(OSWCR): SANTA ROSA
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.51109
Decim Long(OSWCR): -122.76976
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No: WCR1985-004291
City: SANTA ROSA
County: Sonoma
Decimal Latitude: 38.51109
Decimal Longitude: -122.76976
Location: None
Location(OSWCR): None
City(OSWCR): SANTA ROSA
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.51109
Decim Long(OSWCR): -122.76976
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR2001-003277	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	5321 OLD REDWOOD HWY_		
Location(OSWCR):	5321 OLD REDWOOD HWY_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR2001-006467	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	830 AIRPORT BLVD		
Location(OSWCR):	830 AIRPORT BLVD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR2000-007471	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	5321 OLD REDWOOD HWY_		
Location(OSWCR):	5321 OLD REDWOOD HWY_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0327724	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	NONE		
Location(OSWCR):	NONE		

Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR2003-004790	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	5321 OLD REDWOOD HWY_		
Location(OSWCR):	5321 OLD REDWOOD HWY_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR2003-004789	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	5321 OLD REDWOOD HWY_		
Location(OSWCR):	5321 OLD REDWOOD HWY_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0269748	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0261625	City(OSWCR):	None

Wells and Additional Sources Detail Report

City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0084988	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	MARK WEST STA RD		
Location(OSWCR):	MARK WEST STA RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0013601	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	MARK WEST STATION ROAD		
Location(OSWCR):	MARK WEST STATION ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR2004-003754	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	5321 OLD GOODYEAR ROAD BLDG C		
Location(OSWCR):	5321 OLD GOODYEAR ROAD BLDG C		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR1998-005121	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	5321 OLD REDWOOD HWY_		
Location(OSWCR):	5321 OLD REDWOOD HWY_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0276240	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	RED HWY NO		
Location(OSWCR):	RED HWY NO		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0183146	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0197537	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109

Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0171865	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR2003-004785	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	5321 OLD REDWOOD HWY_		
Location(OSWCR):	5321 OLD REDWOOD HWY_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0002612	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0093292	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	SAME		
Location(OSWCR):	SAME		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0285498	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	XXX		
Location(OSWCR):	XXX		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0149285	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0292958	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		

Wells and Additional Sources Detail Report

Location: MAP ON CREEK MARK WEST STATION
Location(OSWCR): MAP ON CREEK MARK WEST STATION
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No: WCR2004-006184
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.51109
Decimal Longitude: -122.76976
Location: 349 MARK WEST STATION RD
Location(OSWCR): 349 MARK WEST STATION RD
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.51109
Decim Long(OSWCR): -122.76976
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No: WCR2003-004201
City: SANTA ROSA
County: Sonoma
Decimal Latitude: 38.51109
Decimal Longitude: -122.76976
Location: 5321 OLD REDWOOD HWY_
Location(OSWCR): 5321 OLD REDWOOD HWY_
City(OSWCR): SANTA ROSA
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.51109
Decim Long(OSWCR): -122.76976
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No: WCR2000-007473
City: SANTA ROSA
County: Sonoma
Decimal Latitude: 38.51109
Decimal Longitude: -122.76976
Location: 5321 OLD REDWOOD HWY_
Location(OSWCR): 5321 OLD REDWOOD HWY_
City(OSWCR): SANTA ROSA
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.51109
Decim Long(OSWCR): -122.76976
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0202774	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	5898 REDWOOD HWY NO		
Location(OSWCR):	5898 REDWOOD HWY NO		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0013600	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	FULTON RD		
Location(OSWCR):	FULTON RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0149190	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR1990-009995	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	63, 69, 75 DONNA DR		
Location(OSWCR):	63, 69, 75 DONNA DR		

Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0024650	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0258490	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	SAME		
Location(OSWCR):	SAME		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.85	4,492.88	143.60	WATER WELLS

WCR No:	WCR0319335	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51109
Decimal Latitude:	38.51109	Decim Long(OSWCR):	-122.76976
Decimal Longitude:	-122.76976		
Location:	MAP ON BACK		
Location(OSWCR):	MAP ON BACK		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
72	ESE	0.86	4,518.27	141.65	WATER WELLS

WCR No:	WCR0024651	City(OSWCR):	SANTA ROSA

Wells and Additional Sources Detail Report

City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51520118
Decimal Latitude:	38.51520118	Decim Long(OSWCR):	-122.76753767
Decimal Longitude:	-122.76753767		
Location:	5490 REDWOOD HIWAY NO		
Location(OSWCR):	5490 REDWOOD HIWAY NO		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
73	NNW	0.86	4,526.07	121.55	WATER WELLS

WCR No:	WCR0229667	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.53773273
Decimal Latitude:	38.53773273	Decim Long(OSWCR):	-122.79833405
Decimal Longitude:	-122.79833405		
Location:	7975 HEMBREE LANE		
Location(OSWCR):	7975 HEMBREE LANE		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
77	SE	0.88	4,627.96	137.76	WATER WELLS

WCR No:	WCR2013-006882	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.5072222
Decimal Latitude:	38.5072222	Decim Long(OSWCR):	-122.7738889
Decimal Longitude:	-122.7738889		
Location:	5007 FULTON RD		
Location(OSWCR):	5007 FULTON RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
79	SE	0.89	4,673.19	138.31	WATER WELLS

WCR No:	WCR2013-006883	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.5072222
Decimal Latitude:	38.5072222	Decim Long(OSWCR):	-122.7736111
Decimal Longitude:	-122.7736111		
Location:	5007 FULTON RD		
Location(OSWCR):	5007 FULTON RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
80	SE	0.89	4,711.86	137.67	WATER WELLS

WCR No:	WCR2013-006881	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.5069444
Decimal Latitude:	38.5069444	Decim Long(OSWCR):	-122.7738889
Decimal Longitude:	-122.7738889		
Location:	5007 FULTON RD		
Location(OSWCR):	5007 FULTON RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR1989-004015	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR2002-007257	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	66 COLONIAL PARK DR		
Location(OSWCR):	66 COLONIAL PARK DR		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR0205969	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567

Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR1995-001678	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	5775 OLD REDWOOD HWY_		
Location(OSWCR):	5775 OLD REDWOOD HWY_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR0194237	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR0118652	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR0149261	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	REDW HWY NO		
Location(OSWCR):	REDW HWY NO		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR0005383	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR0085234	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR0258842	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		

Location: SAME
Location(OSWCR): SAME
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No: WCR0171930
City: None
County: Sonoma
Decimal Latitude: 38.52567
Decimal Longitude: -122.76988
Location: None
Location(OSWCR): None
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52567
Decim Long(OSWCR): -122.76988
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No: WCR0021900
City: None
County: Sonoma
Decimal Latitude: 38.52567
Decimal Longitude: -122.76988
Location: 5811 FAUGHT RD
Location(OSWCR): 5811 FAUGHT RD
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52567
Decim Long(OSWCR): -122.76988
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No: WCR2002-001980
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.52567
Decimal Longitude: -122.76988
Location: 226 MERNER DR
Location(OSWCR): 226 MERNER DR
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52567
Decim Long(OSWCR): -122.76988
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR0138860	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	129 E SHILOH RD		
Location(OSWCR):	129 E SHILOH RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR0019200	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR1986-006952	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR1983-003182	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	None		
Location(OSWCR):	None		

Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR0160195	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR1989-006095	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR1996-005535	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	257 E SHILOH		
Location(OSWCR):	257 E SHILOH		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR1989-004013	City(OSWCR):	WINDSOR

City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR0024426	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	REDWOOD HWY NO		
Location(OSWCR):	REDWOOD HWY NO		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR0040789	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	127 EAST SHILO RD		
Location(OSWCR):	127 EAST SHILO RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR2000-007305	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	5899 CAPORALE CT		
Location(OSWCR):	5899 CAPORALE CT		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR1995-004700	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	230 E SHILOH RD		
Location(OSWCR):	230 E SHILOH RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR1995-005650	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	238 MERNER DR		
Location(OSWCR):	238 MERNER DR		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR0171931	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR0096610	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567

Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	5951 FAUGHT ROAD		
Location(OSWCR):	5951 FAUGHT ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR0178939	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	5913 OLD REDWOOD HWY		
Location(OSWCR):	5913 OLD REDWOOD HWY		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR0138859	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	5951 FAUGHT ROAD		
Location(OSWCR):	5951 FAUGHT ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR1983-003181	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR0222214	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	169 E SHILOH RD		
Location(OSWCR):	169 E SHILOH RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR0111088	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR0024425	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR0120305	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		

Location: None
Location(OSWCR): None
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No: WCR0051740
City: None
County: Sonoma
Decimal Latitude: 38.52567
Decimal Longitude: -122.76988
Location: None
Location(OSWCR): None
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52567
Decim Long(OSWCR): -122.76988
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No: WCR0067947
City: None
County: Sonoma
Decimal Latitude: 38.52567
Decimal Longitude: -122.76988
Location: SAME
Location(OSWCR): SAME
City(OSWCR): None
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52567
Decim Long(OSWCR): -122.76988
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No: WCR0117859
City: WINDSOR
County: Sonoma
Decimal Latitude: 38.52567
Decimal Longitude: -122.76988
Location: 189 EAST SHILO RD
Location(OSWCR): 189 EAST SHILO RD
City(OSWCR): WINDSOR
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.52567
Decim Long(OSWCR): -122.76988
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR0019201	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR0013669	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR0250742	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR0258843	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	SAME		
Location(OSWCR):	SAME		

Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR2003-006546	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	5917 OLD REDWOOD HWY_		
Location(OSWCR):	5917 OLD REDWOOD HWY_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR2000-006152	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	106 LAFAYETTE DR		
Location(OSWCR):	106 LAFAYETTE DR		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR1985-004267	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR1986-002373	City(OSWCR):	WINDSOR

City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR0085235	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	EAST SHILOH ROAD		
Location(OSWCR):	EAST SHILOH ROAD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR1985-003812	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR1982-000799	City(OSWCR):	WINDSOR
City:	WINDSOR	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR0160194	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	None		
Location(OSWCR):	None		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR0005382	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	5706 REDWOOD HI NORTH		
Location(OSWCR):	5706 REDWOOD HI NORTH		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR0178938	City(OSWCR):	None
City:	None	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	SAME COLONIAL PARK MOBILE HOME ESTATES		
Location(OSWCR):	SAME COLONIAL PARK MOBILE HOME ESTATES		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR1996-003087	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567

Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	5780 OLD REDWOOD HWY_		
Location(OSWCR):	5780 OLD REDWOOD HWY_		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ENE	0.90	4,737.65	162.00	WATER WELLS

WCR No:	WCR0278488	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.52567
Decimal Latitude:	38.52567	Decim Long(OSWCR):	-122.76988
Decimal Longitude:	-122.76988		
Location:	5530 REDWOOD HWY NO		
Location(OSWCR):	5530 REDWOOD HWY NO		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
82	ESE	0.92	4,866.24	144.31	WATER WELLS

WCR No:	WCR2016-010251	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.512222
Decimal Latitude:	38.512222	Decim Long(OSWCR):	-122.7675
Decimal Longitude:	-122.7675		
Location:	SIDESTREET WITHIN TRAILER PARK AT 301 AI		
Location(OSWCR):	SIDESTREET WITHIN TRAILER PARK AT 301 AI		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
82	ESE	0.92	4,866.24	144.31	WATER WELLS

WCR No:	WCR2016-010249	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.512222
Decimal Latitude:	38.512222	Decim Long(OSWCR):	-122.7675
Decimal Longitude:	-122.7675		
Location:	SIDESTREET WITHIN TRAILER PARK AT 301 AI		
Location(OSWCR):	SIDESTREET WITHIN TRAILER PARK AT 301 AI		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

84	N	0.93	4,905.41	141.53	WATER WELLS

WCR No:	WCR2014-015503	City(OSWCR):	WINDSOR, CA 95492
City:	WINDSOR, CA 95492	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.538889
Decimal Latitude:	38.538889	Decim Long(OSWCR):	-122.787778
Decimal Longitude:	-122.787778		
Location:	6557 EMMERSON ST.		
Location(OSWCR):	6557 EMMERSON ST.		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
86	ESE	0.94	4,955.14	142.96	WATER WELLS

WCR No:	WCR0093650	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51479313
Decimal Latitude:	38.51479313	Decim Long(OSWCR):	-122.76608694
Decimal Longitude:	-122.76608694		
Location:	5434 REDWOOD HWY NO		
Location(OSWCR):	5434 REDWOOD HWY NO		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
87	SE	0.95	5,009.67	144.82	WATER WELLS

WCR No:	WCR2020-004824	City(OSWCR):	Santa Rosa
City:	Santa Rosa	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.5086546
Decimal Latitude:	38.5086546	Decim Long(OSWCR):	-122.7698335
Decimal Longitude:	-122.7698335		
Location:	5184 Fulton RD		
Location(OSWCR):	5184 Fulton RD		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
88	SE	0.95	5,010.86	144.70	WATER WELLS

WCR No:	WCR2020-005532	City(OSWCR):	Santa Rosa
City:	Santa Rosa	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.508725
Decimal Latitude:	38.508725	Decim Long(OSWCR):	-122.76975
Decimal Longitude:	-122.76975		

Wells and Additional Sources Detail Report

Location: 4555 Lavell RD
Location(OSWCR): 4555 Lavell RD
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
90	N	0.96	5,071.74	146.31	WATER WELLS

WCR No: WCR2019-001358
City: Santa Rosa
County: Sonoma
Decimal Latitude: 38.5388861
Decimal Longitude: -122.7852111
Location: 230 Pleasant AVE
Location(OSWCR): 230 Pleasant AVE
City(OSWCR): Santa Rosa
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.5388861
Decim Long(OSWCR): -122.7852111
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
91	SE	0.96	5,078.81	143.41	WATER WELLS

WCR No: WCR0090827
City: SANTA ROSA
County: Sonoma
Decimal Latitude: 38.50932651
Decimal Longitude: -122.76882649
Location: 5200 FULTON RD
Location(OSWCR): 5200 FULTON RD
City(OSWCR): SANTA ROSA
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.50932651
Decim Long(OSWCR): -122.76882649
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
92	ESE	0.98	5,156.71	145.98	WATER WELLS

WCR No: WCR2011-007004
City: SANTA ROSA
County: Sonoma
Decimal Latitude: 38.5127778
Decimal Longitude: -122.7661111
Location: 5321 OLD REDWOOD HWY
Location(OSWCR): 5321 OLD REDWOOD HWY
City(OSWCR): SANTA ROSA
County(OSWCR): Sonoma
Decimal Lat(OSWCR): 38.5127778
Decim Long(OSWCR): -122.7661111
Original Source: California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
93	N	0.98	5,164.31	146.56	WATER WELLS

Wells and Additional Sources Detail Report

WCR No:	WCR2019-001357	City(OSWCR):	Santa Rosa
City:	Santa Rosa	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.5392028
Decimal Latitude:	38.5392028	Decim Long(OSWCR):	-122.7854278
Decimal Longitude:	-122.7854278		
Location:	230 Pleasant AVE		
Location(OSWCR):	230 Pleasant AVE		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
94	ESE	0.98	5,165.36	146.50	WATER WELLS

WCR No:	WCR2018-012874	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51263
Decimal Latitude:	38.51263	Decim Long(OSWCR):	-122.76615
Decimal Longitude:	-122.76615		
Location:	5321 OLD REDWOOD HIGHWAY		
Location(OSWCR):	5321 OLD REDWOOD HIGHWAY		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
94	ESE	0.98	5,165.36	146.50	WATER WELLS

WCR No:	WCR2018-012873	City(OSWCR):	SANTA ROSA
City:	SANTA ROSA	County(OSWCR):	Sonoma
County:	Sonoma	Decimal Lat(OSWCR):	38.51263
Decimal Latitude:	38.51263	Decim Long(OSWCR):	-122.76615
Decimal Longitude:	-122.76615		
Location:	5321 OLD REDWOOD HIGHWAY		
Location(OSWCR):	5321 OLD REDWOOD HIGHWAY		
Original Source:	California Department of Water Resources - OSWCR(Well Numbers); California Department of Water Resources - Well Completion Reports		

Radon Information

This section lists any relevant radon information found for the target property.

Federal EPA Radon Zone for *SONOMA* County: **3**

Zone 1: Counties with predicted average indoor radon screening levels greater than 4 pCi/L
Zone 2: Counties with predicted average indoor radon screening levels from 2 to 4 pCi/L
Zone 3: Counties with predicted average indoor radon screening levels less than 2 pCi/L

Federal Area Radon Information for *SONOMA* County

No Measures/Homes:	82
Geometric Mean:	0.3
Arithmetic Mean:	0.6
Median:	0.3
Standard Deviation:	0.9
Maximum:	4.1
% >4 pCi/L:	1
% >20 pCi/L:	0
Notes on Data Table:	TABLE 1. Screening indoor radon data from the EPA/State Residential Radon Survey of California conducted during 1989-90. Data represent 2-7 day charcoal canister measurements from the lowest level of each home tested.

Appendix

Federal Sources

FEMA National Flood Hazard Layer — **FEMA FLOOD**

The National Flood Hazard Layer (NFHL) data incorporates Flood Insurance Rate Map (FIRM) databases published by the Federal Emergency Management Agency (FEMA), and any Letters Of Map Revision (LOMRs) that have been issued against those databases since their publication date. The FIRM Database is the digital, geospatial version of the flood hazard information shown on the published paper FIRMs. The FIRM Database depicts flood risk information and supporting data used to develop the risk data. The FIRM Database is derived from Flood Insurance Studies (FISs), previously published FIRMs, flood hazard analyses performed in support of the FISs and FIRMs, and new mapping data, where available.

Indoor Radon Data — **INDOOR RADON**

Indoor radon measurements tracked by the Environmental Protection Agency(EPA) and the State Residential Radon Survey.

Public Water Systems Violations and Enforcement Data — **PWSV**

List of drinking water violations and enforcement actions from the Safe Drinking Water Information System (SDWIS) made available by the Drinking Water Protection Division of the US EPA's Office of Groundwater and Drinking Water. Enforcement sensitive actions are not included in the data released by the EPA. Address information provided in SWDIS may correspond either with the physical location of the water system, or with a contact address.

Radon Zone Level — **RADON ZONE**

Areas showing the level of Radon Zones (level 1, 2 or 3) by county. This data is maintained by the Environmental Protection Agency (EPA).

Safe Drinking Water Information System (SDWIS) — **SDWIS**

The Safe Drinking Water Information System (SDWIS) contains information about public water systems as reported to US Environmental Protection Agency (EPA) by the states. Addresses may correspond with the location of the water system, or with a contact address.

Soil Survey Geographic database — **SSURGO**

The Soil Survey Geographic database (SSURGO) contains information about soil as collected by the National Cooperative Soil Survey at the Natural Resources Conservation Service (NRCS). Soil maps outline areas called map units. The map units are linked to soil properties in a database. Each map unit may contain one to three major components and some minor components.

U.S. Fish & Wildlife Service Wetland Data — **US WETLAND**

The U.S. Fish & Wildlife Service Wetland layer represents the approximate location and type of wetlands and deepwater habitats in the United States.

USGS Current Topo — **US TOPO**

US Topo topographic maps are produced by the National Geospatial Program of the U.S. Geological Survey (USGS). The project was launched in late 2009, and the term "US Topo" refers specifically to quadrangle topographic maps published in 2009 and later.

USGS Geology — **US GEOLOGY**

Seamless maps depicting geological information provided by the United States Geological Survey (USGS).

USGS National Water Information System — **FED USGS**

The U.S. Geological Survey (USGS)'s National Water Information System (NWIS) is the nation's principal repository of water resources data. This database includes comprehensive information of well-construction details, time-series data for gage height, streamflow, groundwater level, and precipitation and water use data.

State Sources

Oil and Gas Wells — **OGW**

A list of Oil and Gas well locations. This is provided by California's Department of Conservation Division of

Appendix

Oil, Gas and Geothermal Resources.

Periodic Groundwater Level Measurement Locations **MONITOR WELLS**

Locations of groundwater level monitoring wells in the Department of Water Resources (DWR)'s Periodic Groundwater Levels dataset. The DWR Periodic Groundwater Levels dataset contains seasonal and long-term groundwater level measurements collected by the Department of Water Resources and cooperating agencies.

Well Completion Reports **WATER WELLS**

List of wells from the Well Completion Reports data made available by the California Department of Water Resources' (DWR) Online System for Well Completion Reports (OSWCR). Please note that the majority of well completion reports have been spatially registered to the center of the 1x1 mile Public Land Survey System section that the well is located in.

Liability Notice

Reliance on information in Report: The Physical Setting Report (PSR) DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as a review of environmental databases and physical characteristics for the site or adjacent properties.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.


No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Inc. ("ERIS") using various sources of information, including information provided by Federal and State government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS Information Inc. disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report(s) are protected by copyright owned by ERIS Information Inc. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

Handler Profile

CAL000456688 - AHLBORN STRUCTURAL STEEL INC

Status: INACTIVE



ID Number Profile

ID Number:	CAL000456688
Facility Name:	AHLBORN STRUCTURAL STEEL INC
Status:	INACTIVE (expired: 6/30/2021)
ID Type:	PERMANENT
ID Category:	STATE
Entity Types:	GENERATOR
Issued Date:	9/9/2020
Last Updated:	11/1/2021

Facility Address

5937 PRUITT AVE
WINDSOR, CA 95492
SONOMA County
(38.52358796,
-122.79059425)

Mailing Address

1230 CENTURY CT
SANTA ROSA, CA 95403

Owner

AHLBORN STRUCTURAL STEEL INC
1230 CENTURY CT
SANTA ROSA, CA 95403
(707) 573-0742

Contact

JESSE HUSTON
1230 CENTURY CT
SANTA ROSA, CA 95403
(707) 495-5456

CalEnviroScreen 3.0 Results

Census Tract:	6097152702	CES Percentile:	45-50%
Hazardous Waste:	74	Pollution Burden:	77

NAICS Codes

332323	Ornamental and Architectural Metal Work Manufacturing

Annual ID Number Verification History


Year	Status	Method	VQ Number (VQ)	Confirmation Date	Signed By

No results found matching your search criteria.


Page Size: 10 | 0 to 0 of 0 | Page 0 of 0

Manifests

Manifest Per Year by Handler Type



Tonnage Handled Per Year by Handler Type



Manifest Counts and Total Tonnage

Export CSV

	Generator		Transporter		TSDF	
Year	Count	Tons	Count	Tons	Count	Tons
2021	1	1	0	0	0	0

Waste Code Matrix

Copyright © 2021 State of California

Oretsky, Z

From: Public Records <PublicRecords@baaqmd.gov>
Sent: Wednesday, November 17, 2021 1:10 PM
To: Oretsky, Z
Subject: Public Records Request No. 2021-11-0234

Dear Zachary Oretsky,

Thank you for your request. We have searched our records and have no records that respond to your below request for:

790 Shiloh Road
Windsor

If you have any questions or concerns, please call or e-mail me.


Sincerely,

Rochele Henderson
Public Records Section
BAAQMD
415-516-1916

Property Address: **790 SHILOH RD WINDSOR CA 95492-9743**

General Information

Parcel # (APN):	**059-271-095-000** Open Map
Owner:	See Full Detail
Mailing Address:	**5895 PRUITT AVE WINDSOR CA 95492**
Legal Description:	**2007 FM REM 059-271-094 & OPEN TO RD PER DEED**
Use Type:	**INDUSTRIAL**
Tax Rate Area:	**009-023**



Full Detail $14.95 Add to Cart

PLEASE NOTE: If a field is empty on this page, there is no data available, and the field will also be empty on the Full Detail property report.

Assessment

Total Value:	**$2,287,675**	Year Assd:	**2021**
Land:	**$862,727**	Zoning:	
Structures:	**$1,424,948**	Use Code:	See Full Detail
Other:		Census Tract:	See Full Detail
% Improved:	See Full Detail	Price/SqFt:	See Full Detail
Exempt Amt:			
HO Exempt:	**N**		

Sale History

	Sale 1	Sale 2	Sale 3	Transfer
Document Date:	**02/21/2020**			See Full Detail
Document Number:	**2020R013339**			See Full Detail
Document Type:	See Full Detail			
Transfer Amount:	**$2,000,000**			
Seller (Grantor):	See Full Detail			

Property Characteristics

Bedrooms:		Fireplace:		Units:	
Baths (Full):		A/C:		Stories:	See Full Detail
Baths (Half):		Heating:		Quality:	See Full Detail
Total Rooms:		Pool:	See Full Detail	Building Class:	See Full Detail
Bldg/Liv Area:	**42,040**	Park Type:		Condition:	
Lot Acres:	**45.090**	Spaces:		Site Influence:	
Lot SqFt:	**1,964,120**	Garage SqFt:		Timber Preserve:	
Year Built:	**1978**			Ag Preserve:	
Effective Year:	See Full Detail				

**The information provided here is deemed reliable, but is not guaranteed.

Additional reports on this property

© 2021 **ParcelQuest** | www.parcelquest.com | Privacy Policy | Refund Policy | Disclaimer | Usage Limits


Well Finder


CalGEM GIS

- Well Status and Well Type Filter
- Search
- Zoom to Field
- Measurement
- Layers

  - [ ] Notice and Permit
  - [x] Well
    - [x] Well
    - [x] Geothermal Well
  - [x] Facility
    - [x] Tank
    - [x] Pit/Sump
    - [x] Setting
    - [x] Facility Boundary (non-wellstar)
  - [x] Underground Gas Storage
  - [ ] Well Stimulation
  - [ ] TR26 Onshore Seep Count
  - [x] Oil/Gas Field
  - [x] CalGEM District
  - [ ] Public Land Survey System
  - [ ] City
  - [ ] Legislative Districts
  - [ ] County
  - [ ] California Geologic Map

Powered by WellSTAR






SITES CURRENTLY VISIBLE ON MAP — 5 SITES LISTED — EXPORT THIS LIST TO EXCEL

PROJECT NAME	STATUS	PROJECT TYPE	ADDRESS	CITY
CALETTI AVE	ACTIVE	VOLUNTARY CLEANUP	590 CALETTI AVE	WINDSOR
ECODYNE COOLING	REFER: RWQCB	STATE RESPONSE	SHILOH ROAD	WINDSOR
ECODYNE POND	ACTIVE	STATE RESPONSE	930 SHILOH RD	WINDSOR
LAKEWOOD ENTERPRISES	INACTIVE - NEEDS EVALUATION	TIERED PERMIT	930 SHILOH ROAD	WINSOR
THE SHILOH GROUP PROPERTY	ACTIVE	VOLUNTARY CLEANUP	930 SHILOH ROAD	WINDSOR

National Flood Hazard Layer FIRMette

FEMA

122°47'53"W 38°31'48"N



122°47'16"W 38°31'20"N

0 250 500 1,000 1,500 2,000 Feet

1:6,000

Basemap: USGS National Map: Orthoimagery: Data refreshed October, 2020

Legend

SEE FIS REPORT FOR DETAILED LEGEND AND INDEX MAP FOR FIRM PANEL LAYOUT

SPECIAL FLOOD HAZARD AREAS
- Without Base Flood Elevation (BFE) *Zone A, V, A99*
- With BFE or Depth *Zone AE, AO, AH, VE, AR*
- Regulatory Floodway

OTHER AREAS OF FLOOD HAZARD
- 0.2% Annual Chance Flood Hazard, Areas of 1% annual chance flood with average depth less than one foot or with drainage areas of less than one square mile *Zone X*
- Future Conditions 1% Annual Chance Flood Hazard *Zone X*
- Area with Reduced Flood Risk due to Levee. See Notes. *Zone X*
- Area with Flood Risk due to Levee *Zone D*

OTHER AREAS
- NO SCREEN Area of Minimal Flood Hazard *Zone X*
- Effective LOMRs
- Area of Undetermined Flood Hazard *Zone D*

GENERAL STRUCTURES
- Channel, Culvert, or Storm Sewer
- Levee, Dike, or Floodwall

OTHER FEATURES
- 20.2 Cross Sections with 1% Annual Chance
- 17.5 Water Surface Elevation
- Coastal Transect
- Base Flood Elevation Line (BFE)
- Limit of Study
- Jurisdiction Boundary
- Coastal Transect Baseline
- Profile Baseline
- Hydrographic Feature

MAP PANELS
- Digital Data Available
- No Digital Data Available
- Unmapped

N

The pin displayed on the map is an approximate point selected by the user and does not represent an authoritative property location.

This map complies with FEMA's standards for the use of digital flood maps if it is not void as described below. The basemap shown complies with FEMA's basemap accuracy standards


The flood hazard information is derived directly from the authoritative NFHL web services provided by FEMA. This map was exported on 11/17/2021 at 2:01 PM and does not reflect changes or amendments subsequent to this date and time. The NFHL and effective information may change or become superseded by new data over time.

This map image is void if the one or more of the following map elements do not appear: basemap imagery, flood zone labels, legend, scale bar, map creation date, community identifiers, FIRM panel number, and FIRM effective date. Map images for unmapped and unmodernized areas cannot be used for regulatory purposes.

National Flood Hazard Layer FIRMette

FEMA

122°47'35"W 38°31'27"N



122°46'58"W 38°30'59"N

Feet 1:6,000

0 250 500 1,000 1,500 2,000

Basemap: USGS National Map: Orthoimagery: Data refreshed October, 2020

Legend

SEE FIS REPORT FOR DETAILED LEGEND AND INDEX MAP FOR FIRM PANEL LAYOUT

SPECIAL FLOOD HAZARD AREAS
- Without Base Flood Elevation (BFE) *Zone A, V, A99*
- With BFE or Depth *Zone AE, AO, AH, VE, AR*
- Regulatory Floodway

OTHER AREAS OF FLOOD HAZARD
- 0.2% Annual Chance Flood Hazard, Areas of 1% annual chance flood with average depth less than one foot or with drainage areas of less than one square mile *Zone X*
- Future Conditions 1% Annual Chance Flood Hazard *Zone X*
- Area with Reduced Flood Risk due to Levee. See Notes. *Zone X*
- Area with Flood Risk due to Levee *Zone D*

OTHER AREAS
- NO SCREEN Area of Minimal Flood Hazard *Zone X*
- Effective LOMRs
- Area of Undetermined Flood Hazard *Zone D*

GENERAL STRUCTURES
- Channel, Culvert, or Storm Sewer
- Levee, Dike, or Floodwall

OTHER FEATURES
- 20.2 Cross Sections with 1% Annual Chance
- 17.5 Water Surface Elevation
- Coastal Transect
- 513 Base Flood Elevation Line (BFE)
- Limit of Study
- Jurisdiction Boundary
- Coastal Transect Baseline
- Profile Baseline
- Hydrographic Feature

MAP PANELS
- Digital Data Available
- No Digital Data Available
- Unmapped

N

The pin displayed on the map is an approximate point selected by the user and does not represent an authoritative property location.

This map complies with FEMA's standards for the use of digital flood maps if it is not void as described below. The basemap shown complies with FEMA's basemap accuracy standards

The flood hazard information is derived directly from the authoritative NFHL web services provided by FEMA. This map was exported on 11/17/2021 at 1:57 PM and does not reflect changes or amendments subsequent to this date and time. The NFHL and effective information may change or become superseded by new data over time.

This map image is void if the one or more of the following map elements do not appear: basemap imagery, flood zone labels, legend, scale bar, map creation date, community identifiers, FIRM panel number, and FIRM effective date. Map images for unmapped and unmodernized areas cannot be used for regulatory purposes.

Oretsky, Z

From: PRMD-2024-Hazmat <PRMD-2024-Hazmat@sonoma-county.org>
Sent: Tuesday, November 23, 2021 12:04 PM
To: Oretsky, Z
Cc: Nicole Watson
Subject: RE: Public Records Request 790 Shiloh Road

Good afternoon,

After researching the address 790 Shiloh Road, Windsor, Ca, I have found that Sonoma County Fire Prevention and Hazardous Material Division archive systems has no records of a CUPA file for this address. If I can assist you with anything else, please let me know.

Best Regards,

Nicole Watson
Senior Office Assistant
Fire Prevention Division
www.PermitSonoma.org
2300 County Center Drive #B220
Santa Rosa, CA 95403
Direct: 707-565-3707
Office: 707-565-2024 | Fax: 707-565-1172

Due to the Public Health Orders, online tools remain the best way to access Permit Sonoma's services like permitting, records, scheduling inspections, and general questions. You can find out more about our extensive online services at PermitSonoma.org.

The Permit Center has reopened with limited capacity Monday, Tuesday, Thursday, Friday from 8:00 AM – 4:00 PM; Wednesday, 10:30 AM – 4:00 PM.

Thank you for your patience as we work to keep staff and the community safe.

From: Nicole Watson <Nicole.Watson@sonoma-county.org>
Sent: Tuesday, November 23, 2021 12:01 PM
To: PRMD-2024-Hazmat <PRMD-2024-Hazmat@sonoma-county.org>
Subject: FW: Public Records Request 790 Shiloh Road

From: PRMD-2024-Hazmat <PRMD-2024-Hazmat@sonoma-county.org>
Sent: Wednesday, November 17, 2021 10:31 AM

To: 'Oretsky, Z' <zoretsky@partneresi.com>
Cc: Nicole Watson <Nicole.Watson@sonoma-county.org>
Subject: RE: Public Records Request 790 Shiloh Road

Good morning,

We have received your request for records applicable to 790 Shiloh Road, Windsor, Ca. We will begin searching our databases and get back to you soon.

Best Regards,

Nicole Watson
Senior Office Assistant
Fire Prevention Division
www.PermitSonoma.org
2300 County Center Drive #B220
Santa Rosa, CA 95403
Direct: 707-565-3707
Office: 707-565-2024 | Fax: 707-565-1172

Due to the Public Health Orders, online tools remain the best way to access Permit Sonoma's services like permitting, records, scheduling inspections, and general questions. You can find out more about our extensive online services at PermitSonoma.org.

The Permit Center has reopened with limited capacity Monday, Tuesday, Thursday, Friday from 8:00 AM – 4:00 PM; Wednesday, 10:30 AM – 4:00 PM.

Thank you for your patience as we work to keep staff and the community safe.

From: Oretsky, Z <zoretsky@partneresi.com>
Sent: Wednesday, November 17, 2021 10:00 AM
To: PRMD-2024-Hazmat <PRMD-2024-Hazmat@sonoma-county.org>
Subject: Public Records Request 790 Shiloh Road

EXTERNAL

Hello,

We would like to review any UST, HAZMAT, AST, dry-cleaning operations, septic tank systems, groundwater wells, chemical spills/cleanups, and soil/groundwater investigations for the following property:

790 Shiloh Road, Windsor, California 95492
APN 059-271-095

Thank you,

Zachary “Z” Oretsky, M.S.

Staff Scientist

PARTNER ENGINEERING AND SCIENCE, INC.
1544 Eureka Road, Roseville, CA 95661

C: 209-843-3567

More Than Just Assessments. *Solutions* – For a complete list of services, click here.

THIS EMAIL ORIGINATED OUTSIDE OF THE SONOMA COUNTY EMAIL SYSTEM.
Warning: If you don’t know this email sender or the email is unexpected,
do not click any web links, attachments, and never give out your user ID or password.

Oretsky, Z

From: Cyndi Foreman <cforeman@sonomacountyfd.org>
Sent: Wednesday, November 17, 2021 10:26 AM
To: Oretsky, Z
Subject: RE: EXT: Public Records Request 790 Shiloh Road

Please reach out the County of Sonoma CUPA regulator at: 707-565-2024

Cyndi Foreman
Division Chief/Fire Marshal
Office 707-892-2003
Cell 707-696-7503

From: Oretsky, Z <zoretsky@partneresi.com>
Sent: Wednesday, November 17, 2021 10:21 AM
To: Info <Info@sonomacountyfd.org>
Subject: EXT: Public Records Request 790 Shiloh Road

Hello,

We would like to review any UST, HAZMAT, AST, dry-cleaning operations, septic tank systems, groundwater wells, chemical spills/cleanups, and soil/groundwater investigations for the following property:

790 Shiloh road, Windsor, CA 95492
APN 059-271-095

Thank you,

Zachary “Z” Oretsky, M.S.

Staff Scientist

PARTNER ENGINEERING AND SCIENCE, INC.
1544 Eureka Road, Roseville, CA 95661

C: 209-843-3567

More Than Just Assessments. *Solutions* – For a complete list of services, click here.

Caution: ---Warning: THIS EMAIL IS FROM OUTSIDE OUR EMAIL SYSTEM.--- DO NOT click links or open attachments unless you recognize the sender and know the content is safe. NEVER provide your User ID or password.'.

PLEASE NOTE, my email address has changed, please update your contact list.



LEGEND - CHOOSE MORE SITES ×

- LUST Cleanup Sites - REMOVE
- Cleanup Program Sites - REMOVE
- Military Cleanup Sites - REMOVE
- Military Privatized Sites - REMOVE
- Military UST Sites - REMOVE
- Field Points - REMOVE

☒ *Signifies a Closed Site*

ACTIVE MAP COVERAGES:

• Military Bases - REMOVE

LIST SITES VISIBLE ON MAP

Map data ©2021 Imagery ©2021 , CNES / Airbus, Maxar Technologies, USDA Farm Service Agency

Sites Shown on Map: 11 Total Sites | 1 Open Sites | 10 Closed Sites | 2 Sites w/Water Quality Data

Town of Windsor

INSPECTION ACTIVITY REPORT

Permit No. B09-0156 **Site Address** 790 SHILOH

Applied	6/8/2009	**Applicant**	SDG ARCHITECTS, INC.	**Lot**	
Approved	6/8/2009	**Owner**	CALETTI, RICHARD C & FLORAMAY	**Block**	
Issued	7/7/2009	**Contractor**	NORCAL CONSTRUCTION	**Tract**	
Parent Permit No.		**Description**	REPLACE 2 EXISTING T-MOBILE ANTENNAS; NEW EQUIP. CABINET		
		Notes			

Requested Time / By	Scheduled Completed	Inspection Type	Inspector	Result Remarks	Notes
7/14/2009 07:30 JB	7/14/2009 7/14/2009	BUILDING FINAL	KL	APPROVED	

CRW SYSTEMS

Town of Windsor

INSPECTION ACTIVITY REPORT

Permit No. B10-0139 **Site Address** 790 SHILOH

Applied	4/22/2010	**Applicant**	CHAD CHRISTIE	**Lot**	
Approved	4/22/2010	**Owner**	CALETTI, RICHARD C & FLORAMAY	**Block**	
Issued	4/22/2010	**Contractor**	WIRELESS ALCHEMY	**Tract**	
Parent Permit No.		**Description**	INSTALL FIBER BOX ON (E) CELL FACILITY		
		Notes			

Requested Time / By	Scheduled Completed	Inspection Type	Inspector	Result Remarks	Notes
5/4/2010	5/4/2010 2:30	ELECTRICAL	KL	APPROVED	
08:31 KL	5/4/2010	FINAL			

CRW SYSTEMS

Oretsky, Z

From: Oretsky, Z
Sent: Wednesday, November 17, 2021 10:14 AM
To: eh@sonoma-county.org
Subject: Public Records Request 790 Shiloh Road
Attachments: SCEHS Request Windsor.pdf

Hello,

Attached is a public records request form. Please let me know if you have any questions or issues reading the document.

Thank you,

Zachary "Z" Oretsky, M.S.

Staff Scientist

PARTNER ENGINEERING AND SCIENCE, INC.
1544 Eureka Road, Roseville, CA 95661

C: 209-843-3567

More Than Just Assessments. *Solutions* – For a complete list of services, click here.

Oretsky, Z

From: EH <EH@sonoma-county.org>
Sent: Tuesday, November 23, 2021 9:42 AM
To: Oretsky, Z
Subject: RE: Public Records Request 790 Shiloh Road

Good morning Zachary,

Your request for public information has been managed in accordance with the California Public Records Act, Cal. Govt. Code §§ 6250-6270. Environmental Health and Safety (EHS) has completed its search for this information and does not have any records for the following addresses:

- **790 Shiloh Rd**

***OUR RECORDS ARE NOW SCANNED AND AVAILABLE ON OUR PUBLIC ACCESS VIEWER*. The majority of our records are located on this viewer.**

Records may now be accessed via our Public Access Viewer on our web site. Please go to this web address; http://sonomacounty.ca.gov/Health/Environmental-Health/Public-Records-Requests/

*Please follow the directions on the website to view our records. We recommend searching an address by typing an * before and after the street number and street name – i.e. type* ****1234 N Petaluma*, and/or *1234 Petaluma****. *Do not use Rd, Ave, St, etc.*

Environmental Health and Safety (EHS) does not have jurisdiction for some of the programs listed in your request. We recommend you submit a records request to the local CUPA and Code Enforcement for these addresses. The CUPA's and Code Enforcements located in Sonoma County are listed below;

- For all records – Geotracker; http://geotracker.waterboards.ca.gov/
- USTs, Hazardous materials/waste, Non-leaking underground storage tanks, above ground storage tanks, well and septic;

  - **CUPA – PRMD** – hazmat@sonoma-county.org or 707-565-2613
  - Santa Rosa Fire – cupa@srcity.org or 707-543-3537
  - Petaluma Fire – http://cityofpetaluma.net/firedept/hazmat.html
  - Healdsburg Fire for Sebastopol – jboaz@ci.healdsburg.ca.us or 707-431-3360
  -
  - **Code Enforcement**
  - Sonoma County Permit and Resource Management (PRMD) – 707-565-1992
  - Santa Rosa – 707-543-3198
  - Petaluma – 707-778-4469
  - Sebastopol – 707-823-8597

Please let me know if you require anything further.

Thank you,

Environmental Health
County of Sonoma
Department of Health Services
625 5th Street
Santa Rosa, CA 95404
Office 707-565-6565
Fax 707-565-6525
EH@sonoma-county.org



Warning : The information contained in this message may be privileged and confidential and protected from disclosure. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this communication in error, please notify us immediately by replying to this message and then destroy this communication in a manner appropriate for privileged information.

Please consider the environment before printing this e-mail, or opt to print on both sides of the paper.

From: Oretsky, Z <zoretsky@partneresi.com>
Sent: Wednesday, November 17, 2021 10:14 AM
To: EH <EH@sonoma-county.org>
Subject: Public Records Request 790 Shiloh Road

EXTERNAL

Hello,

Attached is a public records request form. Please let me know if you have any questions or issues reading the document.

Thank you,

Zachary "Z" Oretsky, M.S.

Staff Scientist

PARTNER ENGINEERING AND SCIENCE, INC.
1544 Eureka Road, Roseville, CA 95661

C: 209-843-3567

More Than Just Assessments. *Solutions* – For a complete list of services, click here.

THIS EMAIL ORIGINATED OUTSIDE OF THE SONOMA COUNTY EMAIL SYSTEM.
Warning: If you don't know this email sender or the email is unexpected,
do not click any web links, attachments, and never give out your user ID or password.

Oretsky, Z

From: Oretsky, Z
Sent: Wednesday, November 17, 2021 10:21 AM
To: info@sonomacountyfd.org
Subject: Public Records Request 790 Shiloh Road

Hello,

We would like to review any UST, HAZMAT, AST, dry-cleaning operations, septic tank systems, groundwater wells, chemical spills/cleanups, and soil/groundwater investigations for the following property:

790 Shiloh road, Windsor, CA 95492
APN 059-271-095

Thank you,

Zachary "Z" Oretsky, M.S.

Staff Scientist

PARTNER ENGINEERING AND SCIENCE, INC.
1544 Eureka Road, Roseville, CA 95661

C: 209-843-3567

More Than Just Assessments. *Solutions* – For a complete list of services, click here.

Oretsky, Z

From: Oretsky, Z
Sent: Wednesday, November 17, 2021 10:00 AM
To: hazmat@sonoma-county.org
Subject: Public Records Request 790 Shiloh Road

Hello,

We would like to review any UST, HAZMAT, AST, dry-cleaning operations, septic tank systems, groundwater wells, chemical spills/cleanups, and soil/groundwater investigations for the following property:

790 Shiloh Road, Windsor, California 95492
APN 059-271-095

Thank you,

Zachary "Z" Oretsky, M.S.

Staff Scientist

PARTNER ENGINEERING AND SCIENCE, INC.
1544 Eureka Road, Roseville, CA 95661


C: 209-843-3567

More Than Just Assessments. *Solutions* – For a complete list of services, click here.

Handler Profile

CAL000160715 - STANDARD STRUCTURES INC

Status: INACTIVE



ID Number Profile

ID Number:	CAL000160715
Facility Name:	STANDARD STRUCTURES INC
Status:	INACTIVE (expired: 6/30/2011)
ID Type:	PERMANENT
ID Category:	STATE
Entity Types:	GENERATOR
Issued Date:	10/4/1996
Last Updated:	3/15/2012

Facility Address

920 SHILOH
WINDSOR, CA 95492
SONOMA County
(38.525793, -122.797194)

Mailing Address

PO BOX K
SANTA ROSA, CA 95402

Owner

STANDARD STRUCTURES
PO BOX K
SANTA ROSA, CA 95402
(707) 836-8100

Contact

JOHN ROSENBLAD
P O BOX K
SANTA ROSA, CA 95402
(707) 837-2216

CalEnviroScreen 3.0 Results ⓘ

Census Tract:	6097152702	CES Percentile:	45-50%
Hazardous Waste:	74	Pollution Burden:	77

NAICS Codes ⓘ

321214	Truss Manufacturing

Annual ID Number Verification History


Year	Status	Method	VQ Number (eVQ)	Completion Date	Signed By
2010	COMPLETE	PAPER		4/5/2011	
2009	COMPLETE	PAPER		10/6/2009	
2008	COMPLETE	PAPER		4/15/2009	
2007	COMPLETE	PAPER		2/5/2008	
2006	COMPLETE	PAPER		11/2/2006	
2005	COMPLETE	PAPER		9/27/2005	

2004	COMPLETE	PAPER	10/25/2004
2003	COMPLETE	PAPER	10/23/2003
2001	COMPLETE	PAPER	3/14/2002
2000	COMPLETE	PAPER	3/14/2002


Page Size: 10 1 to 10 of 13 Page 1 of 2

Manifests

Manifest Per Year by Handler Type



Tonnage Handled Per Year by Handler Type



Manifest Counts and Total Tonnage

Export CSV

	Generator		Transporter		TSDF	
Year	Count	Tons	Count	Tons	Count	Tons
2008	1	0.12238	0	0	0	0
2007	4	9.02325	0	0	0	0
2005	2	0.79	0	0	0	0
2004	2	0.78587	0	0	0	0
2003	2	1.23019	0	0	0	0
2002	4	3.85954	0	0	0	0
2001	9	9.05456	0	0	0	0
2000	5	24.75812	0	0	0	0
1999	7	31.26997	0	0	0	0

Waste Code Matrix

Copyright © 2021 State of California

Handler Profile

CAL000360840 - STANDARD STRUCTURES INC

Status: INACTIVE



ID Number Profile

ID Number:	CAL000360840
Facility Name:	STANDARD STRUCTURES INC
Status:	INACTIVE (expired: 6/30/2012)
ID Type:	PERMANENT
ID Category:	STATE
Entity Types:	GENERATOR
Issued Date:	2/4/2011
Last Updated:	4/2/2013

Facility Address

5910 PRUITT AVE
WINDSOR, CA 95492
SONOMA County
(38.52361, -122.79103)

Mailing Address

5910 PRUITT AVE
WINDSOR, CA 95492

Owner

STANDARD STRUCTURES INC
PO BOX K
SANTA ROSA, CA 95402
(707) 837-2206

Contact

JOHN ROSENBLAD
5910 PRUITT AVE
WINDSOR, CA 95492
(707) 837-2216

CalEnviroScreen 3.0 Results ⓘ

Census Tract:	6097152702	CES Percentile:	45-50%
Hazardous Waste:	74	Pollution Burden:	77

NAICS Codes ⓘ

99999	Not Otherwise Specified

Annual ID Number Verification History

Year	Status	Method	VQ Number (EVQ)	Completion Date	Signed By

No results found matching your search criteria.

Page Size: 10 | 0 to 0 of 0 | Page 0 of 0

Manifests

No Manifest Data for this ID Number.

Waste Code Matrix

Copyright © 2021 State of California

Handler Profile

CAC002691312 - STANDARD STRUCTURES INC

Status: INACTIVE



ID Number Profile

ID Number:	CAC002691312
Facility Name:	STANDARD STRUCTURES INC
Status:	INACTIVE (expired: 10/17/2012)
ID Type:	TEMPORARY
ID Category:	STATE
Entity Types:	GENERATOR
Issued Date:	4/19/2012
Last Updated:	4/19/2012

Facility Address

5910 PRUITT AVE
WINDSOR, CA 95492
SONOMA County
(38.523592, -122.79109)

Mailing Address

5910 PRUITT AVE
WINDSOR, CA 95492

Owner

STANDARD STRUCTURES INC
5910 PRUITT AVE
WINDSOR, CA 95492
(707) 837-1970

Contact

DICK CALETTI
5910 PRUITT AVE
WINDSOR, CA 95492
(707) 837-1970

CalEnviroScreen 3.0 Results

Census Tract:	6097152702	CES Percentile:	45-50%
Hazardous Waste:	74	Pollution Burden:	77

NAICS Codes

Annual ID Number Verification History


Year	Status	Method	VQ Number (EVQ)	Completion Date	Signed By

No results found matching your search criteria.


Page Size: 10 | 0 to 0 of 0 | Page 0 of 0

Manifests

Manifest Per Year by Handler Type



Tonnage Handled Per Year by Handler Type



Manifest Counts and Total Tonnage

Export CSV

	Generator		Transporter		TSDF	
Year	Count	Tons	Count	Tons	Count	Tons
2012	2	10.26	0	0	0	0

Waste Code Matrix

Copyright © 2021 State of California

Oretsky, Z

From: Courtney Rider <crider@townofwindsor.com>
Sent: Thursday, November 18, 2021 7:06 AM
To: Oretsky, Z
Subject: Re: 790 Shiloh Road
Attachments: 790 SHILOH RD; B09-0156.pdf; Inspection Report for B09-0156.pdf; 790 SHILOH RD; B10-0139.pdf; Inspection Report for B10-0139.pdf

Hello,

Attached please find the permits on file with the Town for 790 Shiloh Road. The building was constructed prior to the Town's incorporation in 1992 so the certificate of occupancy is not on file.

Best,

Courtney Rider | Community Development Technician
Town of Windsor | 9291 Old Redwood Highway Bldg. 400 | Windsor, CA 95492
707-838-1105 Direct | 707-838-7349 Fax |
crider@townofwindsor.com
www.townofwindsor.com
Town of Windsor Office Hours: Monday – Thursday, 7 a.m. – 6 p.m.

U.S. Fish and Wildlife Service

National Wetlands Inventory

790 Shiloh



November 17, 2021

Wetlands

- Estuarine and Marine Deepwater
- Estuarine and Marine Wetland
- Freshwater Emergent Wetland
- Freshwater Forested/Shrub Wetland
- Freshwater Pond
- Lake
- Other
- Riverine

This map is for general reference only. The US Fish and Wildlife Service is not responsible for the accuracy or currentness of the base data shown on this map. All wetlands related data should be used in accordance with the layer metadata found on the Wetlands Mapper web site.


SHILOH RD
PRUITT AVE
STANDARD AVE
101
KITTYHAWK BLVD
CALETTI AVE
AIRPORT CREEK

DEPARTMENT OF THE ARMY
SAN FRANCISCO DISTRICT, U.S. ARMY CORPS OF ENGINEERS
1455 MARKET STREET, 16TH FLOOR
SAN FRANCISCO, CALIFORNIA 94103-1398

DECEMBER 12, 2017

Regulatory Division

Subject: File Number 2016-00047

Douglas Spicher
WRA, Incorporated
2169 East Francisco Boulevard, Suite G
San Rafael, California 94901

Dear Mr. Spicher:

This correspondence is in reference to your submittal of May 2, 2016, on behalf of Standard Industrial East, LLC, concerning Department of the Army (DA) authorization to construct the Standard Industrial East, LLC Storm Water Management Project located at 5910 Pruitt Avenue in the Town of Windsor, Sonoma County, California (38.52°N and 122.80°W; APN: 009-023-095).

Work within U.S. Army Corps of Engineers' (Corps) jurisdiction will include realigning and widening an existing 1,195-foot long and 2-foot wide drainage channel to manage storm water, increase flood capacity, and create riparian habitat. The realigned channel will run on the south side of the project site and will be approximately 1,850-feet long by 12-feet wide. Work will require placement of 177 cubic yards of clean fill into 1,195 linear feet (0.05 acre) of intermittent drainage channel tributary to Redwood Creek. All work shall be completed in accordance with the plans and drawings titled "USACE File #2016-00047, Standard Industrial East, LLC Storm Water Management Project, Windsor, Sonoma County," in 2 sheets, dated November 6, 2017, provided as enclosure 1.

Section 404 of the Clean Water Act (CWA) generally regulates the discharge of dredged or fill material below the plane of ordinary high water in non-tidal waters of the United States, below the high tide line in tidal waters of the United States, and within the lateral extent of wetlands adjacent to these waters. Section 10 of the Rivers and Harbors Act generally regulates construction of structures and work, including excavation, dredging, and discharges of dredged or fill material, occurring below the plane of mean high water in tidal waters of the United States; in former diked baylands currently below mean high water; outside the limits of mean high water but affecting the navigable capacity of tidal waters; or below the plane of ordinary high water in non-tidal waters designated as navigable waters of the United States. Navigable waters of the United States generally include all waters subject to the ebb and flow of the tide; and/or all waters presently used, or have been used in the past, or may be susceptible for future use to transport interstate or foreign commerce. A Preliminary Jurisdictional Determination (JD) has been completed for your site. Preliminary JDs are written indications that there may be waters of the U.S. on a parcel or indications of the approximate location(s) of waters of the U.S. on a parcel. Preliminary JDs are advisory in nature and may not be appealed. While this

preliminary jurisdictional determination was conducted pursuant to Regulatory Guidance Letter No. 16-01, *Jurisdictional Determinations*, it may be subject to future revision if new information or a change in field conditions becomes subsequently apparent. The basis for this preliminary jurisdictional determination is fully explained in the *Preliminary Jurisdictional Determination Form*, which has been signed and dated by you and this office.

Based on a review of the information in your submittal and the current condition of the site, as verified during a field investigation on July 13, 2016, the project qualifies for authorization under Department of the Army Nationwide Permit (NWP) 43 for Stormwater Management Facilities, 82 Fed. Reg. 1860, January 6, 2017, pursuant to Section 404 of the CWA of 1972, as amended (33 U.S.C. § 1344 *et seq.*). The project must be in compliance with the terms of the NWP cited on our website: www.spn.usace.army.mil/Portals/68/docs/regulatory/NWP/NWP17_43.pdf, the general conditions of the Nationwide Permit Program (www.spn.usace.army.mil/Portals/68/docs/regulatory/NWP/NWP17_GC.pdf), and the San Francisco District regional conditions (www.spn.usace.army.mil/Portals/68/docs/regulatory/NWP/NWP17_RC.pdf). You must also be in compliance with any special conditions specified in this letter for the NWP authorization to remain valid. Non-compliance with any term or condition could result in the revocation of the NWP authorization for your project, thereby requiring you to obtain an Individual Permit from the Corps. This NWP authorization does not obviate the need to obtain other State or local approvals required by law.

This verification will remain valid until March 18, 2022, unless the NWP authorization is modified, suspended, or revoked. Activities which have commenced (i.e., are under construction) or are under contract to commence in reliance upon a NWP will remain authorized provided the activity is completed within 12 months of the date of a NWP's expiration, modification, or revocation, unless discretionary authority has been exercised on a case-by-case basis to modify, suspend, or revoke the authorization in accordance with 33 C.F.R. § 330.4(e) and 33 C.F.R. § 330.5 (c) or (d). This verification will remain valid if, during the time period between now and March 18, 2022, the activity complies with any subsequent modification of the NWP authorization. The Chief of Engineers will periodically review NWPs and their conditions and will decide to modify, reissue, or revoke the permits. If a NWP is not modified or reissued within five years of its effective date, it automatically expires and becomes null and void. It is incumbent upon you to remain informed of any changes to the NWPs. Changes to the NWPs would be announced by Public Notice posted on our website (www.spn.usace.army.mil/Missions/Regulatory/Public-Notices.aspx). Upon completion of the project and all associated mitigation requirements, you shall sign and return the Certification of Compliance, enclosure 2, verifying that you have complied with the terms and conditions of the permit.

This authorization will not be effective until you have obtained a Section 401 water quality certification from the North Coast Regional Water Quality Control Board (RWQCB). If the RWQCB fails to act on a valid request for certification within 60 days after receipt of a complete application, the Corps will presume a waiver of water quality certification has been obtained. You shall submit a copy of the certification to the Corps prior to the commencement of work.

General Condition 18 stipulates that project authorization under a NWP does not allow for the incidental take of any federally-listed species in the absence of a biological opinion with incidental take provisions. As the principal federal lead agency for this project, the Corps initiated consultation with the United States Fish and Wildlife Service (USFWS) to address project related impacts to listed species, pursuant to Section 7(a) of the Endangered Species Act of 1973, as amended (16 U.S.C. § 1531 *et seq*). By email of June 16, 2017, USFWS concurred with the determination that the project was not likely to adversely affect California tiger salamander (*Ambystoma californiense*) and designated critical habitat for this species.

In order to ensure compliance with this NWP authorization, the following special conditions shall be implemented:

1. All standard Best Management Practices shall be implemented to prevent the movement of sediment downstream. No debris, soil, silt, sand, bark, slash, sawdust, cement, concrete, washings, petroleum products, or other organic or earthen material shall be allowed to enter into or be placed where it may be washed by rainfall or runoff into the waterways.


2. A post construction report shall be submitted 45 days after the conclusion of construction activities. The report shall document construction activities and contain as-built drawings (if different from drawings submitted with application) and include before and after photos.

You may refer any questions on this matter to Bryan Matsumoto of my Regulatory staff by telephone at 415-503-6786 or by e-mail at Bryan.T.Matsumoto@usace.army.mil. All correspondence should be addressed to the Regulatory Division, North Branch, referencing the file number at the head of this letter.

The San Francisco District is committed to improving service to our customers. My Regulatory staff seeks to achieve the goals of the Regulatory Program in an efficient and cooperative manner, while preserving and protecting our nation's aquatic resources. If you would like to provide comments on our Regulatory Program, please complete the Customer

Service Survey Form available on our website: http://www.spn.usace.army.mil/Missions/Regulatory.aspx

Sincerely,



Rick M. Bottoms, Ph.D.
Chief, Regulatory Division

Enclosures


Copies Furnished (w/o encls):

USFWS, Sacramento, CA (Attn: Vincent Griego)
RWQCB, Santa Rosa, CA (Attn: Stephen Bargsten)
Standard Industrial East, LLC, Windsor, CA (Attn: Richard Caletti)

Enclosure 1


U.S. Army Corps of Engineers
San Francisco District
Regulatory Division

USACE File #2016-00047
Standard Industrial East, LLC Storm Water Management Project
Windsor, Sonoma County
November 6, 2017 2 sheets total



UNIT NO.	STANDARD INDUSTRIAL EAST	DRAWN BY: AFK	Figure 3. Map showing the location of existing drainage ditch, proposed realignment of channel, and connection to channel widened in 2007.
SHEET NO. 1 OF 1	EXISTING PROPERTY LINES WINDSOR, CALIFORNIA	DATE: 12/16//15	
		CHECKER:	STANDARD INDUSTRIAL EAST 5910 PRUITT AVENUE WINDSOR, CA 95492 (707) 837-1970

Standard Industrial East, LLC
Storm Water Management Project



* - Subject to confirmation during final grade design

PUBLIC DRAINAGE CHANNEL SECTION A

NOT TO SCALE

Enclosure 2

Permittee: Standard Industrial East, LLC

File Number: 2016-00047

Certification of Compliance
for
Nationwide Permit

"I hereby certify that the work authorized by the above referenced File Number and all required mitigation have been completed in accordance with the terms and conditions of this Nationwide Permit authorization."

_____ _____

(Permittee) (Date)

Return to:

Bryan Matsumoto
U.S. Army, Corps of Engineers
San Francisco District
Regulatory Division, CESPN-R-N
1455 Market Street
San Francisco, CA 94103-1398

790 Shiloh Road, Windsor – APN: 059-271-095
Due Diligence Materials from Seller to Buyer

1. Brelje & Race 1837.03 - Land Use – Scenario 2
2. Brelje & Race 1837.03 – Land Use – Scenario 3
3. Assessor's Parcel Map
4. Nationwide Commercial General Liability, Property & Umbrella Liability Insurance effective 10/1/2020
5. Easement & Maintenance Agreement
6. JL Modular, Inc. Commercial Lease & Deposit Receipt fully executed on May 22, 2014
7. JL Modular, Inc. Lease Renewal Addendum dated June 7, 2017
8. JL Modular, Inc. Lease Renewal Addendum #2 dated January 15, 2020
9. JL Modular, Inc. Lease Renewal Addendum #3 dated March 19, 2021
10. Master Plan Map
11. Master Storm Drain Map
12. Master Water Plan Map
13. 2019-2020 Property Tax Bill
14. Statement of Property Condition – ***to come***
15. Phase I
16. Phase II
17. US Army Corps of Engineers Letter dated December 12, 2017
18. US Army Corps of Engineers Letter & Wetlands Delineation Report dated August 27, 2020
19. Appraisal from Ward Levy Appraisal Group, Inc. dated January 16, 2018
20. Easement Map and Boundary Map dated June 19, 2018
21. 2020 Statement of Income
22. 2021 Projected Statement of Income
23. 790 Shiloh – USACE Drawing – Storm Water Management Project Map dated November 6, 2017


Buyer's Agent: **Ryan Gallagher, Touchstone Commercial**

By: _____ Date: _____

Buyer: **Brennan Investment Group, LLC**

By: _____ Date: _____

Enclosure 1



U.S. Army Corps of Engineers
San Francisco District
Regulatory Division

USACE File #2016-00047


Standard Industrial East, LLC Storm Water Management Project
Windsor, Sonoma County

November 6, 2017 — 2 sheets total

UNIT NO.	**STANDARD INDUSTRIAL EAST**	DRAWN BY: AFK	Figure 3. Map showing the location of existing drainage ditch, proposed realignment of channel, and connection to channel widened in 2007.
SHEET NO. 1 OF 1	EXISTING PROPERTY LINES WINDSOR, CALIFORNIA	DATE: 12/16//15	
		CHECKER:	STANDARD INDUSTRIAL EAST 5910 PRUITT AVENUE WINDSOR, CA 95492 (707) 837-1970

Enclosure 1

Standard Industrial East, LLC
Storm Water Management Project



* - Subject to confirmation during final grade design

PUBLIC DRAINAGE CHANNEL SECTION A

NOT TO SCALE

Enclosure 2

Permittee: Standard Industrial East, LLC

File Number: 2016-00047

Certification of Compliance
for
Nationwide Permit

"I hereby certify that the work authorized by the above referenced File Number and all required mitigation have been completed in accordance with the terms and conditions of this Nationwide Permit authorization."

_____ _____

(Permittee) (Date)

Return to:

Bryan Matsumoto
U.S. Army, Corps of Engineers
San Francisco District
Regulatory Division, CESPN-R-N
1455 Market Street
San Francisco, CA 94103-1398

LEGAL DESCRIPTION

PARCEL ONE:

ALL THAT REAL PROPERTY SITUATE, LYING AND BEING IN THE COUNTY OF SONOMA, STATE OF CALIFORNIA, AND FURTHER DESCRIBED AS BEING A PORTION OF THE SOUTHWEST QUARTER OF SECTION 19, LYING NORTHERLY OF THE RIGHT-OF-WAY OF THE NORTHWESTERN PACIFIC RAILWAY COMPANY, ALL IN TOWNSHIP 8 NORTH, RANGE 8 WEST, MOUNT DIABLO BASE & MERIDIAN, AND BEING MORE PARTICULARLY DESCRIBED AS FOLLOWS:

BEGINNING AT A POINT AS SHOWN ON A MAP ENTITLED "STATE HIGHWAY IN SONOMA COUNTY, BETWEEN 0.6 MILES SOUTH OF MENDOCINO AVENUE IN SANTA ROSA AND GRANT CREEK RIGHT-OF-WAY RECORD MAP R119.12", HAVING COORDINATES Y 313,851.95, X 1,773,317.75 CALIFORNIA COORDINATES, SYSTEM ZONE 2, AND ON FILE AT THE SONOMA COUNTY RECORDER'S OFFICE; THENCE NORTH 84° 56' 10" WEST ALONG THE SOUTHERLY LINE OF SHILOH ROAD, A DISTANCE OF 36.53 FEET TO POINT; THENCE SOUTH 3° 08' 20" EAST, A DISTANCE OF 53.79 FEET; THENCE ON A CURVE TO THE LEFT WITH A RADIUS OF 57.00 FEET, FOR A DISTANCE OF 81.58 FEET; THENCE SOUTH 85° 08' 20" EAST, A DISTANCE OF 504.22 FEET: THENCE ON A CURVE TO THE RIGHT WITH A RADIUS OF 103.00 FEET, FOR A DISTANCE OF 153.40 FEET TO A 1/2" DIAMETER IRON PIN; THENCE SOUTH 57° 05' 30" EAST, A DISTANCE OF 544.61 FEET; THENCE SOUTH 0° 36' WEST, A DISTANCE OF 141.76 FEET; THENCE SOUTH 35° 6' EAST, A DISTANCE OF 667.41 FEET TO THE EAST LINE OF THE PARCEL OF LAND DESCRIBED IN DEED DATED SEPTEMBER 20, 1972 FROM POTLATCH FOREST, INC., A DELAWARE CORPORATION TO STANDARD STRUCTURES, INC., RECORDED UNDER SERIAL NO. M-95874 IN LIBER 2668 OF OFFICIAL RECORDS, PAGE 498, SONOMA COUNTY RECORDS; THENCE NORTH 0° 40' 40" EAST LONG THE EAST LINE OF SAID STANDARD STRUCTURES, INC PARCEL, A DISTANCE OF 432.25 FEET TO THE SOUTHERLY RIGHT-OF-WAY LINE OF THE STATE HIGHWAY, MARKED BY A 1/2" IRON PIPE; THENCE NORTH 35° 16' WEST, A DISTANCE OF 180.51 FEET; THENCE NORTH 37° 32' 05" WEST, A DISTANCE OF 510.49 FEET; THENCE CURVING TO THE LEFT WITH A RADIUS OF 345 FEET, FOR A DISTANCE OF 266.26 FEET; THENCE NORTH 81° 45' 14" WEST, A DISTANCE OF 830.75 FEET TO THE POINT OF BEGINNING.

EXCEPTING THEREFROM ALL THAT REAL PROPERTY SITUATED IN THE TOWN OF WINDSOR, COUNTY OF SONOMA, STATE OF CALIFORNIA, AND BEING A PORTION OF THE LAND OF RICHARD C. CALETTI AND FLORAMAY CALETTI, AS TRUSTEES OF THE RICHARD C. CALETTI AND FLORAMAY CALETTI TRUST AGREEMENT, DATED OCTOBER 27, 1998, AS DESCRIBED BY DEED RECORDED UNDER DOCUMENT NUMBER 1998 0129510, SONOMA COUNTY RECORDS, DESCRIBED AS FOLLOWS:

BEGINNING AT A POINT ON THE EASTERLY LINE OF LOT 1 AS SHOWN ON THAT MAP ENTITLED "PARCEL MAP NO. MNS 94-06" FILED IN BOOK 529 OF MAPS, AT PAGES 4 THROUGH 6 SONOMA COUNTY RECORDS, FROM WHICH THE SOUTHEAST CORNER OF SAID LOT BEARS SOUTH, 35° 19' 01" (MAP SOUTH 35° 15' 31" EAST) EAST 6.63 FEET; THENCE LEAVING SAID LINE. NORTH 88° 41' 00" EAST 16.08 FEET; THENCE ALONG A TANGENT CURVE TO THE LEFT, HAVING A RADIUS OF 30.00 FEET, THROUGH A CENTRAL ANGLE OF 29° 50' 03", A DISTANCE OF 15.62 FEET; THENCE ALONG A TANGENT CURVE TO THE RIGHT, HAVING A RADIUS OF 53.00 FEET, THROUGH A CENTRAL ANGLE OF 66° 24' 57", A DISTANCE OF 61.44 FEET; THENCE NORTH 54° 44' 06" WEST, 19.17 FEET; THENCE NORTH 57° 30' 07" WEST 75.14 FEET; THENCE LONG A TANGENT CURVE TO THE LEFT, HAVING A RADIUS OF 10.00 FEET, THROUGH A CENTRAL ANGLE OF 31° 14 19", A DISTANCE OF 5.45 FEET; THENCE ALONG A TANGENT CURVE TO THE RIGHT, HAVING A RADIUS OF 60.00 FEET, THROUGH A CENTRAL ANGLE OF 8° 16 30", A DISTANCE OF 40.08 FEET; THENCE NORTH 50° 27' 55" WEST 18.72 FEET TO A POINT ON SAID LINE OF LOT 1; THENCE ALONG SAID LINE, SOUTH 00° 34' 52" WEST 15.29 FEET; THENCE SOUTH 35° 19' 01" EAST 80.82 FEET TO THE POINT OF BEGINNING. SAID PARCEL HAVING BEEN GRANTED PURSUANT TO LLA 01-048 IN GRANT DEED RECORDED SEPTEMBER 12, 2002, INSTRUMENT NO. 2002-137499, SONOMA COUNTY RECORDS.

EXCEPTING THEREFROM ALL THAT PORTION CONVEYED TO THE TOWN OF WINDSOR, A MUNICIPAL CORPORATION BY DEED RECORDED AUGUST 1, 2005, AS DOCUMENT NO. 2005-111328 AND RE-RECORDED OCTOBER 9, 2006 AS DOCUMENT NO. 2006-124557, SONOMA COUNTY RECORDS.

ALSO EXCEPTING THEREFROM ALL THAT PORTION CONVEYED TO THE TOWN OF WINDSOR, A MUNICIPAL CORPORATION BY DEED RECORDED MARCH 20, 2006, AS DOCUMENT NO. 2006-032114, SONOMA COUNTY RECORDS.

ALSO EXCEPTING THEREFROM ALL THAT PORTION CONVEYED TO THE TOWN OF WINDSOR, A MUNICIPAL CORPORATION BY DEED RECORDED SEPTEMBER 21, 2006 IN DOCUMENT NO. 2006-0117024, SONOMA COUNTY RECORDS.

ALSO EXCEPTING THEREFROM ALL THAT PORTION CONVEYED TO THE TOWN OF WINDSOR, A MUNICIPAL CORPORATION BY DEED RECORDED SEPTEMBER 21, 2006 IN DOCUMENT NO. 2004-067800, SONOMA COUNTY RECORDS.

PARCEL TWO:

BEGINNING AT THE QUARTER CORNER COMMON TO SECTION 19 AND SECTION 30, TOWNSHIP 8 NORTH, RANGE 8 WEST, MOUNT DIABLO BASE & MERIDIAN, MARKED BY A 3/4" IRON PIPE AS SHOWN ON RECORD OF SURVEY IN BOOK 210 OF MAPS, 44; THENCE NORTH 0° 40' 40" EAST, 1833.33 FEET TO A 1/2" GALVANIZED PIPE AND TAG LS 2798 AND TO THE SOUTHERLY RIGHT- OF-WAY OF THE STATE HIGHWAY SHOWN ON MAP ENTITLED "STATE HIGHWAY IN SONOMA COUNTY, BETWEEN 0.6 MILES SOUTH OF MENDOCINO AVENUE IN SANTA ROSA AND GRANT CREEK RIGHT-OF-WAY RECORD MAP R119.12"; THENCE SOUTH 35° 6' EAST ALONG THE SOUTHERLY RIGHT-OF-WAY LINE OF SAID STATE HIGHWAY, 2132.67 FEET TO A SET 1" IRON PIPE AND TAG; THENCE SOUTH 0° 27' 27" WEST, 83.55 FEET TO A FOUND 1" DIAMETER IRON PIPE MARKING THE SOUTHEAST CORNER OF THE LANDS OF THE FLUOR CORPORATION, LTD., DESCRIBED IN BOOK 1683, AT PAGE 588, OFFICIAL RECORDS OF SONOMA COUNTY; THENCE SOUTH 89° 37' 51" WEST ALONG THE LINE BETWEEN SAID SECTIONS 19 AND 30, A DISTANCE OF 1251.99 FEET TO THE POINT OF BEGINNING; BASIS OF BEARINGS: STATE HIGHWAY.

PARCEL THREE:

A NON-EXCLUSIVE EASEMENT FOR A RAILROAD SPUR AND UTILITIES OVER AND ACROSS THE LANDS, MORE PARTICULARLY DESCRIBED AS FOLLOWS:

BEING A PORTION OF THE LANDS OF ECODYNE COOLING PRODUCTS COMPANY, RECORDED MAY 22, 1968 IN BOOK 2332 OF OFFICIAL RECORDS, PAGE 180, SONOMA COUNTY RECORDS, AND BEING MORE PARTICULARLY DESCRIBED AS FOLLOWS:

A STRIP OF LAND OF A UNIFORM WIDTH OF 30 FEET, THE CENTER LINE OF WHICH IS COINCIDENT WITH THE CENTER LINE OF AN EXISTING RAILROAD SPUR TRACT BEGINNING AT A POINT IN THE WESTERN LINE OF THE LANDS OF POTLATCH, SAID POINT IS ESTABLISHED BY COMMENCING AT A 3/4 INCH DIAMETER IRON PIPE MARKING THE QUARTER SECTION BETWEEN SECTIONS 19 AND 30, IN TOWNSHIP 8 NORTH, RANGE 8 WEST, MOUNT DIABLO BASE & MERIDIAN; THENCE NORTH 9° 40' 40" EAST, 196.57 FEET; THENCE NORTH 89° 24' WEST 770.60 FEET; THENCE NORTH 0° 36' EAST, 259.84 FEET; THENCE NORTH 89° 24' WEST, 75 FEET THENCE NORTH 0° 36' EAST, 52.61 FEET TO THE POINT OF INTERSECTION OF SAID WESTERN LINE AND THE CENTER LINE OF SAID RAILROAD SPUR; THENCE NORTHWESTERLY ALONG THE CENTER LINE OF SAID RAILROAD SPUR TO ITS INTERSECTION WITH THE CENTER LINE OF THE NORTHWESTERN PACIFIC RAILROAD, SAID INTERSECTION BEING THE TERMINUS OF THE 30 FOOT EASEMENT.

EXCEPTING THEREFROM ANY PORTION THEREOF LYING WITHIN THE ABOVE DESCRIBED PARCEL TWO.

THE ABOVE DESCRIBED EASEMENTS ARE APPURTENANT TO THAT PARCEL OF LAND DESCRIBED IN DEED DATED AUGUST 14, 1978 FROM ECODYNE CORPORATION, A CORPORATION, TO STANDARD STRUCTURES, INC., RECORDED OCTOBER 13, 1978 IN BOOK 3466 OF OFFICIAL RECORDS, PAGE 932, RECORDER'S SERIAL NO. T-41506, SONOMA COUNTY RECORDS.

PARCEL FOUR:

A TWENTY FOOT WIDE EASEMENT FOR GENERAL RAILROAD PURPOSES OVER A PORTION OF LAND LYING WITHIN SECTION 19, TOWNSHIP 8 NORTH, RANGE 8 WEST, MOUNT DIABLO BASE & MERIDIAN, AND BEING MORE PARTICULARLY DESCRIBED AS A STRIP OF LAND LYING 10 FEET ON EACH SIDE OF THE FOLLOWING DESCRIBED CENTERLINE:

COMMENCING AT A 1/2" IRON PIN MARKING THE MOST SOUTHWESTERLY CORNER OF THE LANDS OF STANDARD STRUCTURES, INC., DESCRIBED BY DEED RECORDED IN BOOK 2668 OF OFFICIAL RECORDS PAGE 498, SONOMA COUNTY RECORDS, SAID IRON PIN BEARS SOUTH 89° 23' 15" EAST, 265.83 FEET FROM A 1" IRON PIPE TAGGED LS 2798, AS SHOWN UPON THAT CERTAIN RECORD OF SURVEY FILED IN BOOK 279 OF MAPS, PAGES 10 AND 11, SONOMA COUNTY RECORDS THENCE FROM SAID POINT OF COMMENCEMENT AND ALONG THE WESTERLY LINE OF SAID LANDS, THE FOLLOWING COURSES: NORTH 0° 36' 45" EAST, 259.84 FEET TO A 1/2" IRON PIN THENCE NORTH 89° 23' 15" WEST, 75.00 FEET TO A 1/2" IRON PIN, THENCE NORTH 0° 36' 45" EAST 52.5 FEET MORE OR LESS, TO A POINT IN SAID WESTERLY LINE, SAID POINT ALSO BEING A POINT IN THE CENTERLINE OF AN EXISTING RAILROAD SPUR AND MARKING THE TRUE POINT OF BEGINNING OF THE CENTER TO BE HEREIN DESCRIBED; THENCE FROM SAID POINT OF BEGINNING AND ALONG THE CENTERLINE OF THE EXISTING TRACKS AND THE PROJECTION THEREOF SOUTH 89° 53' 43" EAST, 610.0 FEET, MORE OR LESS, TO THE BEGINNING OF A TANGENT CURVE TO THE RIGHT OF A 400 FOOT RADIUS WHOSE CENTER BEARS SOUTH 0° 06' 17" WEST; THENCE SOUTHEASTERLY THROUGH A CENTRAL ANGLE OF 36° 00' 00" AN ARC DISTANCE OF 251.33 FEET, MORE OR LESS, TO THE POINT OF TERMINATION OF THE CENTERLINE HEREIN DESCRIBED, SAID POINT OF TERMINATION BEING A POINT IN THE EAST LINE OF SAID LANDS OF STANDARD STRUCTURES, INC., WHICH BEARS NORTH 0° 40' 40" EAST, 243.5 FEET, MORE OR LESS, FROM A 1/2' IRON PIN MARKING THE SOUTHEAST CORNER OF SAID LANDS.

THE BASIS OF BEARINGS FOR THIS DESCRIPTION IS THE ABOVE MENTIONED RECORD OF SURVEY.

SAID EASEMENT TO BE APPURTENANT TO PARCELS ONE AND TWO ABOVE DESCRIBED.

PARCEL FIVE:

ALL THAT CERTAIN PARCEL OF LAND AS CONTAINED IN THE DEED FROM STANDARD STRUCTURES, INC., RECORDED MAY 15, 1986 UNDER DOCUMENT NO. 86033909 OF OFFICIAL RECORDS OF SONOMA COUNTY, AND BEING MORE PARTICULARLY DESCRIBED AS FOLLOWS:

COMMENCING AT A POINT ON THE SOUTHERLY LINE OF THAT PARCEL OF LAND DESCRIBED IN THE DEED NO. 19365 TO THE STATE OF CALIFORNIA, RECORDED OCTOBER 23,1958 IN VOLUME 1623, AT PAGE 113 OF OFFICIAL RECORDS OF SONOMA COUNTY, DISTANT THEREON NORTH 85° 29' 38" WEST, 247.25 FEET FROM THE SOUTHEASTERLY CORNER OF SAID PARCEL; THENCE FROM A TANGENT THAT BEARS NORTH 38° 07' 42" WEST ALONG A CURVE TO THE RIGHT WITH A RADIUS OF 7590, THROUGH A CENTRAL ANGLE OF 2° 51' 42", FOR AN ARC LENGTH OF 379.09 FEET; THENCE NORTH 35° 16' 00" WEST, 850.56 FEET TO THE POINT OF BEGINNING; THENCE NORTH 35° 16' 00" WEST, 460.28 FEET TO THE WESTERLY LINE OF THAT PARCEL OF LAND DESCRIBED IN THE DEED NO. 19366 TO THE STATE OF CALIFORNIA, RECORDED OCTOBER 6, 1958 IN VOLUME 1620, AT PAGE 16, OF OFFICIAL RECORDS OF SAID COUNTY; THENCE ALONG LAST SAID LINE, SOUTH 0° 27' 27" WEST, 84.06 FEET TO THE NORTHERLY TERMINUS OF THE WESTERLY LINE OF FIRST SAID PARCEL (1623 OF OFFICIAL RECORDS, PAGE 113); THENCE ALONG LAST SAID WESTERLY LINE, SOUTH 0° 22' 26" WEST, 290.00 FEET; THENCE SOUTH 89° 37' 34" EAST, 286.32 FEET TO THE POINT OF BEGINNING.

PARCEL SIX:

ALL THAT CERTAIN PARCEL OF LAND AS CONTAINED IN THE DEED FROM AIRPORT BLVD BUSINESS PARK, RECORDED MAY 15, 1986 UNDER DOCUMENT NO. 86-033913 OF OFFICIAL RECORDS OF SONOMA COUNTY, AND BEING MORE PARTICULARLY DESCRIBED AS FOLLOWS:

BEING A PORTION OF THE LANDS OF AIRPORT BLVD. BUSINESS PARK, A CALIFORNIA LIMITED PARTNERSHIP, AS DESCRIBED UNDER DOCUMENT NO. 85-052686, SONOMA COUNTY RECORDS, AND MORE PARTICULARLY DESCRIBED AS FOLLOWS: A 290 FOOT STRIP OF LAND ALONG THE MOST NORTHERLY BOUNDARY OF SAID LANDS, RUNNING PARALLEL AND CONTINUOUS TO SAID NORTHERLY BOUNDARY.

THE SOUTHERLY LINE OF SAID STRIP SHALL, BE LENGTHENED OR SHORTENED AS REQUIRED AT PROPERTY LINE INTERSECTIONS.

PARCEL SEVEN:

ALL THAT REAL PROPERTY SITUATED IN THE TOWN OF WINDSOR, COUNTY OF SONOMA, STATE OF CALIFORNIA, AND BEING A PORTION OF THE LANDS OF HELEN H. CALETTI AND RICHARD C. CALETTI, CO-TRUSTEES OF THE TRUST SET FORTH UNDER THE LAST WILL OF CARLOS W. CALETTI, AS DESCRIBED BY DEED RECORDED AS DOCUMENT NUMBER 87-100180, SONOMA COUNTY RECORDS, AND ALSO BEING DESIGNATED REMAINDER "B" AS SHOWN ON PARCEL MAP 94-06, FILED IN BOOK 529 OF MAPS, AT PAGES 4-7, SONOMA COUNTY RECORDS, MORE PARTICULARLY. DESCRIBED AS FOLLOWS:

BEGINNING AT THE MOST NORTHWESTERLY CORNER OF LOT ONE AS SHOWN ON SAID PARCEL MAP 94-06; THENCE ALONG THE NORTH LINE OF SAID LOT ONE, SOUTH 89° 50' 38" EAST 44.00 FEET TO AN ANGLE POINT ON THE NORTH LINE OF SAID LOT ONE, ALSO BEING A POINT ON THE EAST LINE OF PARCEL FIVE ;'AS DESCRIBED IN SAID DOCUMENT NUMBER 87-100180: THENCE ALONG THE NORTHERLY LINE OF SAID PARCEL FIVE ALONG A CURVE TO THE LEFT HAVING A RADIUS THAT BEARS NORTH 89° 48' 16" WEST, 102.97 FEET, THROUGH A CENTRAL ANGLE OF 85° 20 18", A DISTANCE OF 153.37 FEET; THENCE NORTH 85° 08' 20" WEST, 444.26 FEET TO THE NORTHWEST CORNER OF SAID PARCEL FIVE; THENCE LEAVING THE NORTHERLY LINE OF SAID PARCEL FIVE, SOUTH 35° 16' 32" EAST, 113.35 FEET; THENCE SOUTH 85° 07' 48" EAST, 79.35 FEET; THENCE ALONG A CURVE TO THE RIGHT HAVING A RADIUS THAT BEARS SOUTH 06° 05' 02" WEST, 350.00 FEET, THROUGH A CENTRAL ANGLE OF 19° 08' 27", A DISTANCE OF 116.92 FEET; THENCE SOUTH 65° 06' 32" EAST, 90.56 FEET; THENCE ALONG A CURVE TO THE LEFT HAVING A RADIUS THAT BEARS NORTH 24° 34' 39" EAST, 00.00 FEET, THROUGH A CENTRAL ANGLE OF 22° 57' 43", A DISTANCE OF 120.23 FEET; THENCE SOUTH 88° 23' 04" EAST, 37.68 FEET TO THE WEST LINE OF SAID LOT 1; THENCE ALONG SAID WEST LINE, NORTH 00° 11' 40" EAST, 56.44 FEET TO THE POINT OF BEGINNING.

PARCEL AA:

FOR THE PURPOSE OF SERVING AND BENEFITTING THE CALETTI PARCEL, A NONEXCLUSIVE EASEMENT FOR INGRESS AND EGRESS, AND ULITITIES (INCLUDING BUT NOT LIMITED TO, ELECTRICAL, WATER, TELEPHONE, GAS, TELECOMMUNICATION, SANITARY SEWER, STORM DRAIN LINES): ALL THAT REAL PROPERTY SITUATED IN SECTION 19, TOWNSHIP 8 NORTH, RANGE 8 WEST, MDM, IN THE COUNTY OF SONOMA, STATE OF CALIFORNIA, AND BEING A PORTION OF THE LAND OF SHILOH OAKS LLC, AS DESCRIBED IN DEED RECORDED AS DOCUMENT NUMBER 2004-109294, OFFICIAL RECORDS OF SONOMA COUNTY, DESCRIBED AS FOLLOWS:

COMMENCING AT A FOUND 1/2" REBAR TAGGED LS 2798 LOCATED ON THE WEST BOUNDARY LINE OF LANDS OF SHILOH OAKS LLC AND THE NORTHEASTERLY LINE OF THE NORTH WEST PACIFIC RAILROAD RIGHT-OF-WAY, AS SHOWN ON RECORD OF SURVEY RECORDED APRIL 17, 1986 IN BOOK 381 OF MAPS PAGES 39-40 SONOMA COUNTY RECORDS; THENCE ALONG THE COMMON LINE OF SAID LANDS OF SHILOH OAKS LLC AND SHILOH GROUP LLC DESCRIBED IN DOCUMENT NUMBER 2002-0137495 NORTH 00°33'16" EAST 188.11 FEET TO THE SOUTHWEST CORNER OF SHILOH ROAD LLC DESCRIBED IN DOCUMENT NUMBER 2004-062232; THENCE ALONG THE COMMON LINE OF SAID SHILOH ROAD LLC AND SAID SHILOH OAKS LLC ON A NON-TANGENT CURVE TO THE RIGHT HAVING A RADIUS THAT BEARS SOUTH 27°37'54" WEST 400.00 FEET, THROUGH A CENTRAL ANGLE OF 05°19'08", A DISTANCE OF 37.13 FEET TO A POINT IN THE NORTHEASTERLY LINE OF CALETTI AVENUE; THENCE LEAVING SAID COMMON LINE AND ALONG SAID NORTHEASTERLY LINE SOUTH 09°33'19" EAST 27.76 FEET TO THE TRUE POINT OF BEGINNING OF THE HEREIN DESCRIBED PARCEL; THENCE ALONG A NON-TANGENT CURVE TO THE RIGHT HAVING A RADIUS THAT BEARS SOUTH 35°46'46" WEST 380.00 FEET, THROUGH A CENTRAL ANGLE OF 11°17'11", A DISTANCE OF 74.85 FEET; THENCE SOUTH 42°56'03" EAST 82.61 FEET; THENCE ALONG A TANGENT CURVE TO THE LEFT, HAVING A RADIUS OF 395.00 FEET, THROUGH A CENTRAL ANGLE OF 47°01'50", A DISTANCE OF 324.23 FEET; THENCE SOUTH 89°57'50" EAST 476.56 FEET; THENCE ALONG A TANGENT CURVE TO THE RIGHT, HAVING A RADIUS OF 232.00 FEET, THROUGH A CENTRAL ANGLE OF 49°58'05", A DISTANCE OF 202.33 FEET; THENCE ALONG A TANGENT CURVE TO THE LEFT, HAVING A RADIUS OF 168.00 FEET, THROUGH A CENTRAL ANGLE OF 49°22'21", A DISTANCE OF 144.77 FEET TO A POINT IN THE WESTERLY LINE OF THE FUTURE PRUITT AVENUE; THENCE ALONG SAID WESTERLY LINE SOUTH 00°37'39" WEST 74.00 FEET; THENCE LEAVING SAID WESTERLY LINE ALONG A NON-TANGENT CURVE TO THE RIGHT HAVING A RADIUS THAT BEARS NORTH 00°37'49" EAST 242.00 FEET, THROUGH A CENTRAL ANGLE OF 49°22'26", A DISTANCE OF 208.54 FEET; THENCE ALONG A TANGENT CURVE TO THE LEFT, HAVING A RADIUS OF 158.00 FEET, THROUGH A CENTRAL ANGLE OF 49°58'05", A DISTANCE OF 137.79 FEET; THENCE LEAVING SAID EAST LINE NORTH 89°57'50" WEST 476.56 FEET; THENCE ALONG A TANGENT CURVE TO THE RIGHT, HAVING A RADIUS OF 469.00 FEET, THROUGH A CENTRAL ANGLE OF 47°01'47", A DISTANCE OF 384.97 FEET; THENCE NORTH 42°56'03" EAST 29.94 FEET TO A POINT IN THE NORTHEASTERLY LINE OF CALETTI AVENUE; THENCE ALONG SAID NORTHEASTERLY LINE ON A NON-TANGENT CURVE TO THE RIGHT HAVING A RADIUS THAT BEARS NORTH 61°30'09" EAST 263.00 FEET THROUGH A CENTRAL ANGLE OF 18°56'32", A DISTANCE OF 86.95 FEET; THENCE CONTINUING ALONG SAID NORTHEASTERLY LINE NORTH 09°33'19" WEST 57.39 FEET MORE OR LESS TO THE POINT OF BEGINNING.

CONTAINING 2.26 ACRES MORE OR LESS

PARCEL BB:

PRUITT AVENUE (PRIVATE) INGRESS EGRESS AND PRIVATE UTILITY EASEMENT
ALL THAT REAL PROPERTY SITUATED IN SECTION 19, TOWNSHIP 8 NORTH, RANGE 8 WEST, MDM, IN THE COUNTY OF SONOMA, STATE OF CALIFORNIA, AND BEING A PORTION OF THE LAND OF SHILOH OAKS LLC, AS DESCRIBED IN DEED RECORDED AS DOCUMENT NUMBER 2004-109294, OFFICIAL RECORDS OF SONOMA COUNTY, DESCRIBED AS FOLLOWS:

COMMENCING AT A BENT REBAR WITH NO TAG LOCATED ON THE NORTHEASTLY BOUNDARY LINE OF SAID LANDS OF SHILOH OAKS LLC, AS SHOWN ON RECORD OF SURVEY RECORDED ON AUGUST 15, 1994, FOUND IN BOOK 529 OF MAPS PAGES 4-7 SONOMA COUNTY RECORDS; THENCE ALONG SAID LINE NORTH 35°19'01" WEST 21.15 FEET TO THE TRUE POINT OF BEGINNING OF THE HEREIN DESCRIBED PARCEL; THENCE LEAVING SAID LINE SOUTH 00°37'39" WEST 436.74 FEET; THENCE SOUTH 89°22'21" EAST 5.00 FEET; THENCE SOUTH 00°37'39" WEST 628.24 FEET; THENCE NORTH 89°22'21" WEST 5.00 FEET; THENCE SOUTH 00°37'39" WEST 222.70 FEET; THENCE ALONG A TANGENT CURVE TO THE LEFT, HAVING A RADIUS OF 20.00 FEET, THROUGH A CENTRAL ANGLE OF 67°35'20", A DISTANCE OF 23.59 FEET TO THE EAST LINE OF SAID LANDS; THENCE ALONG SAID EAST LINE SOUTH 00°37'45" WEST 72.69 FEET; THENCE ALONG A NON-TANGENT CURVE TO THE RIGHT HAVING A RADIUS THAT BEARS NORTH 34°19'26" WEST 60.00 FEET, THROUGH A CENTRAL ANGLE OF 159°51'59", A DISTANCE OF 167.41 FEET; THENCE ALONG A TANGENT CURVE TO THE LEFT, HAVING A RADIUS OF 40.00 FEET, THROUGH A CENTRAL ANGLE OF 34°54'55", A DISTANCE OF 24.38 FEET; THENCE NORTH 00°37'39" EAST 207.47 FEET; THENCE ALONG A NON-TANGENT CURVE TO THE RIGHT HAVING A RADIUS THAT BEARS NORTH N00°37'54" WEST 168.00 FEET, THROUGH A CENTRAL ANGLE OF 01°42'20", A DISTANCE OF 5.00 FEET; THENCE NORTH 00°37'39" EAST 1065.94 FEET; THENCE SOUTH 89°22'21" EAST 5.00 FEET; THENCE ALONG A NON-TANGENT CURVE TO THE LEFT HAVING A RADIUS THAT BEARS NORTH 89°22'32" WEST 168.00 FEET, THROUGH A CENTRAL ANGLE OF 64°42'38", A DISTANCE OF 189.74 FEET; THENCE ALONG A TANGENT CURVE TO THE RIGHT, HAVING A RADIUS OF 232.00 FEET, THROUGH A CENTRAL ANGLE OF 55°08'33", A DISTANCE OF 223.28 FEET TO THE NORTH EASTERLY LINE OF SAID LANDS; THENCE ALONG SAID LANDS NORTH 89°56'29" EAST 54.44 FEET; THENCE CONTINUING ALONG SAID LANDS SOUTH 35°19'01" EAST 32.59 FEET; THENCE LEAVING SAID LANDS ALONG A NON-TANGENT CURVE TO THE LEFT HAVING A RADIUS THAT BEARS NORTH 68°07'14" EAST 168.00 FEET, THROUGH A CENTRAL ANGLE OF 26°52'31", A DISTANCE OF 78.80 FEET TO THE EASTERLY LINE OF SAID LANDS; THENCE ALONG SAID EASTERLY LINE SOUTH 35°19'01" EAST 290.48 FEET; TO THE POINT OF BEGINNING.

CONTAINING 2.69 ACRES MORE OR LESS.

PARCEL CC:

A NONEXCLUSIVE AND PERPETUAL INGRESS AND EGRESS EASEMENT AND UTILITY EASEMENT FOR MAINTENANCE, CONSTRUCTION AND ACCESS TO ABOVE-GROUND AND UNDERGROUND PUBLIC UTILITIES (E.G., ELECTRICAL, TELEPHONE, GAS, SANITARY SEWER, STORM DRAIN LINES).

COMMENCING AT THE NORTHWEST CORNER OF LOT 20 AS SHOWN ON THE MAP ENTITLED "AIRPORT CORPORATE CENTER I", FILED IN BOOK 432 OF MAPS AT PAGES 48 THROUGH 52, SONOMA COUNTY RECORDS, FROM WHICH AN ANGLE POINT ON THE NORTHERLY LINE OF SAID LOT BEARS NORTH 89°36'18" EAST 1251.65 FEET: THENCE ALONG SAID NORTHERLY LINE NORTH 89°36'18" EAST 875.00 FEET TO THE POINT OF BEGINNING; THENCE LEAVING SAID LINE, SOUTH 00°23'42" EAST 764.88 FEET TO THE NORTHERLY LINE OF LOT 8 AS SHOWN ON SAID MAP, THENCE ALONG SAID NORTHERLY LINE, NORTH 47°49'07" WEST 59.07 FEET; THENCE
NORTH 71°59'47" WEST 12.56 FEET; THENCE LEAVING SAID LINE
NORTH 11°53'50" EAST 20.71 FEET; THENCE ALONG A TANGENT CURVE TO THE LEFT, HAVING A RADIUS OF 480.00 FEET, THROUGH A CENTRAL ANGLE OF 12°17'32", A DISTANCE OF 102.98 FEET; THENCE NORTH 00°23'42" WEST 598.53 FEET TO THE NORTHERLY LINE OF SAID LOT 20; THENCE ALONG SAID LINE NORTH 89°36'18" 40.00 FEET TO THE POINT OF BEGINNING.

CONTAINING 0.70 ACRES MORE OR LESS.

TOGETHER WITH THE FOLLOWING:

BEGINNING AT AN ANGLE POINT ON THE NORTHERLY LINE OF LOT 8 OF SAID AIRPORT ORPORATE CENTER I, FROM WHICH THE MOST NORTHERLY CORNER OF LOT 8 AS SHOWN ON SAID MAP BEARS NORTH 71°59'47" EAST 174.80 FEET; THENCE
SOUTH 47°49'07" EAST 31.80 FEET TO THE EASTERLY LINE OF THE HEREIN DESCRIBED EASEMENT; THENCE ALONG SAID EASTERLY LINE ALONG A CURVE TO THE RIGHT HAVING A RADIUS THAT BEARS NORTH 78°53'07" WEST 520.00 FEET, THROUGH A CENTRAL ANGLE OF 00°46'57" A DISTANCE OF 7.10 FEET; THENCE
SOUTH 11°53'50" WEST 141.50 FEET; THENCE ALONG A TANGENT CURVE TO THE RIGHT, HAVING A RADIUS OF 270.00 FEET, THROUGH A CENTRAL ANGLE OF 26°10'01", A DISTANCE OF 123.31 FEET; THENCE ALONG A TANGENT CURVE TO THE LEFT, HAVING A RADIUS of 45.00 FEET THROUGH A CENTRAL ANGLE OF 83°25'44" A DISTANCE OF 65.52 FEET TO THE NORTHERLY LINE OF AVIATION BOULEVARD; THENCE ALONG SAID NORTHERLY LINE ALONG A CURVE TO THE LEFT HAVING A RADIUS THAT BEARS
SOUTH 44°38'07" WEST 523.00 FEET,THROUGH A CENTRAL ANGLE OF 13°08'32", A DISTANCE OF 119.96 FEET; THENCE LEAVING SAID LINE ALONG A CURVE TO THE LEFT HAVING A RADIUS THAT BEARS NORTH 31°29'35" EAST 45.00 FEET, THROUGH A CENTRAL ANGLE OF 83°25'44", A DISTANCE OF 65.52 FEET; THENCE ALONG A TANGENT CURVE TO THE LEFT HAVING A RADIUS of 230.00 THROUGH A CENTRAL ANGLE OF 26°10'01", A DISTANCE OF 105.04 FEET; THENCE NORTH 11°53'50" EAST 141.50 FEET; THENCE ALONG A TANGENT CURVE TO THE LEFT, HAVING A RADIUS of 480.00 FEET THROUGH A CENTRAL ANGLE OF 02°55'51", A DISTANCE OF 24.55 FEET TO THE NORTHERLY LINE OF SAID LOT 8; THENCE SOUTH 71°59'47" EAST 13.19 FEET TO THE POINT OF BEGINNING.

CONTAINING 0.31 ACRES MORE OR LESS.

PARCEL DD:

ACCESS EASEMENT

ALL THAT REAL PROPERTY SITUATED IN THE COUNTY OF SONOMA, STATE OF CALIFORNIA, AND BEING A PORTION OF THE LANDS OF SONOMA COUNTRY DAY SCHOOL, A CALIFORNIA NONPROFIT CORPORATION SHOWN AS LOT 2 ON THAT MAP ENTITLED "PARCEL MAP NO. MJS 95-1005" FILED IN BOOK 572 OF MAPS AT PAGES 1 THROUGH 4, SONOMA COUNTY RECORDS AND DESCRIBED BY DEED RECORDED AS DOCUMENT NUMBER 1997-0096275, OFFICIAL RECORDS OF SONOMA COUNTY, STATE OF CALIFORNIA, MORE PARTICULARLY DESCRIBED AS FOLLOWS: BEGINNING AT A POINT ON THE NORTHERLY LINE OF AVIATION BOULEVARD AT THE SOUTHWESTERLY CORNER OF LOT 2 AS SHOWN ON SAID "PARCEL MAP NO. MJS 95-1005"; THENCE ALONG THE WESTERLY LINE OF SAID LOT 2, NORTH 33°58'14" WEST 45.65 FEET; THENCE NORTH 00°19'29" EAST 799.17 FEET TO THE NORTHWEST CORNER OF A 46' ACCESS AND UTILITY EASEMENT AS DESCRIBED BY DEED RECORDED AS DOCUMENT NUMBER 1997-119248, SONOMA COUNTY RECORDS AND SHOWN ON THAT SAID MAP ENTITLED "PARCEL MAP NO. MJS 95-1005", AS 45' ACCESS AND UTILITY EASEMENT; THENCE CONTINUING ALONG THE WESTERLY LINE OF SAID LOT 2, NORTH 00°19'29" EAST 20.00 FEET; THENCE LEAVING SAID LINE SOUTH 89°40'31" EAST 46.00 FEET; THENCE SOUTH 00°19'29" WEST 20.00 FEET TO THE NORTHEASTERLY CORNER OP SAID 46' ACCESS EASEMENT; THENCE ALONG THE EASTERLY LINE OF SAID ACCESS EASEMENT, SOUTH 00°19'29" WEST 612.84 FEET; THENCE SOUTH 10026158" EAST 120.90 FEET; THENCE ALONG A TANGENT CURVE TO THE LEFT, HAVING A RADIUS OF 45.00 FEET, THROUGH A CENTRAL ANGLE OF 112°14'26", A DISTANCE OF 88.15 FEET TO THE NORTHERLY LINEOF AVIATION BOULEVARD; THENCE ALONG SAID NORTHERLY LINE ON A NON -TANGENT CURVE TO THE LEFT HAVING A RADIUS THAT BEARS SOUTH 32°41'24" EAST 523.00 FEET, THROUGH A CENTRAL ANGLE OF 010164491*, A DISTANCE OF 11.69 FEET; THENCE SOUTH 56°01'46" WEST 123.31 FEET TO THE POINT OF BEGINNING. CONTAINING 1.0 ACRES, MORE OR LESS.

ALL DISTANCES AND DIMENSIONS ARE GIVEN IN FEET AND DECIMALS THEREOF.

EXCEPTIONS

THE LOCATION OF EACH EASEMENT, RIGHT OF WAY, SERVITUDE, AND OTHER MATTER (ABOVE OR BELOW GROUND) AFFECTING THE SUBJECT PROPERTY AND LISTED IN THE TITLE INSURANCE COMMITMENT NO. FSNX-TO2002717S-CC, DATE SEPTEMBER 16, 2020 ISSUED BY CHICAGO TITLE COMPANY WITH RESPECT TO THE SUBJECT PROPERTY HAS BEEN SHOWN ON THE SURVEY, TOGETHER WITH APPROPRIATE RECORDING REFERENCES, TO THE EXTENT THAT SUCH MATTERS CAN BE LOCATED.

AT THE DATE HEREOF, EXCEPTIONS TO COVERAGE IN ADDITION TO THE PRINTED EXCEPTIONS AND EXCLUSIONS IN SAID POLICY FORM WOULD BE AS FOLLOWS:

EXCEPTION#1 PROPERTY TAXES, INCLUDING ANY PERSONAL PROPERTY TAXES AND ANY ASSESSMENTS COLLECTED WITH TAXES ARE AS FOLLOWS:

CODE AREA: 009023
TAX IDENTIFICATION NO.: 059-271-095-000
FISCAL YEAR: 2020-2021
1ST INSTALLMENT: $17,604.97 OPEN
2ND INSTALLMENT: $17,604.97 OPEN
LAND: $853,881.00
IMPROVEMENTS: $1,410,337.00

EXCEPTION#2 PRIOR TO CLOSE OF ESCROW, PLEASE CONTACT THE TAX COLLECTOR'S OFFICE TO CONFIRM ALL AMOUNTS OWING, INCLUDING CURRENT FISCAL YEAR TAXES, SUPPLEMENTAL TAXES, ESCAPED ASSESSMENTS AND ANY DELINQUENCIES.

EXCEPTION#3 THE LIEN OF SUPPLEMENTAL OR ESCAPED ASSESSMENTS OF PROPERTY TAXES, IF ANY, MADE PURSUANT TO THE PROVISIONS OF CHAPTER 3.5 (COMMENCING WITH SECTION 75) OR PART 2, CHAPTER 3, ARTICLES 3 AND 4, RESPECTIVELY, OF THE REVENUE AND TAXATION CODE OF THE STATE OF CALIFORNIA AS A RESULT OF THE TRANSFER OF TITLE TO THE VESTEE NAMED IN SCHEDULE A OR AS A RESULT OF CHANGES IN OWNERSHIP OR NEW CONSTRUCTION OCCURRING PRIOR TO DATE OF POLICY.

EXCEPTION#4 THE HEREIN DESCRIBED PROPERTY LIES WITHIN THE TOWN OF WINDSOR, MITCHELL/SHILOH/CONDE ASSESSMENT DISTRICT, AND IS SUBJECT TO ALL ASSESSMENTS THEREOF, AS DISCLOSED BY NOTICE OF ASSESSMENT RECORDED JULY 23, 2004, INSTRUMENT NO. 2004113943, OF OFFICIAL RECORDS.

EXCEPTION#5 WATER RIGHTS, CLAIMS OR TITLE TO WATER, WHETHER OR NOT DISCLOSED BY THE PUBLIC RECORDS.

EXCEPTION#6 ANY ADVERSE CLAIM BASED UPON THE ASSERTION THAT:

A. SOME PORTION OF SAID LAND HAS BEEN CREATED BY ARTIFICIAL MEANS, OR HAS ACCRETED TO SUCH PORTION SO CREATED.

A. SOME PORTION OF SAID LAND HAS BEEN BROUGHT WITHIN THE BOUNDARIES THEREOF BY AN AVULSIVE MOVEMENT OF PRUITT CREEK OR HAS BEEN FORMED BY ACCRETION TO ANY SUCH PORTION.

EXCEPTION#7 RIGHTS AND EASEMENTS FOR NAVIGATION AND FISHERY WHICH MAY EXIST OVER THAT PORTION OF SAID LAND LYING BENEATH THE WATERS OF PRUITT CREEK.

EXCEPTION#8 ANY RIGHTS IN FAVOR OF THE PUBLIC WHICH MAY EXIST ON SAID LAND IF SAID LAND OR PORTIONS THEREOF ARE OR WERE AT ANY TIME USED BY THE PUBLIC.

EXCEPTION#9 INTENTIONALLY DELETED.

EXCEPTION#10 THE OWNERSHIP OF SAID LAND DOES NOT INCLUDE RIGHTS OF ACCESS TO OR FROM THE STREET, HIGHWAY, OR FREEWAY ABUTTING SAID LAND, SUCH RIGHTS HAVING BEEN RELINQUISHED BY THE DOCUMENT,

RECORDING DATE: OCTOBER 6, 1958
RECORDING NO.: BOOK 1620, PAGE 16, OF OFFICIAL RECORDS.

EXCEPTION#11 WAIVER OF ANY CLAIMS FOR DAMAGES TO SAID LAND BY REASON OF THE LOCATION, CONSTRUCTION, LANDSCAPING OR MAINTENANCE OF THE STREET OR HIGHWAY ADJOINING SAID LAND, AS CONTAINED IN THE DEED TO

COUNTY/CITY/STATE: STATE OF CALIFORNIA
RECORDING DATE: OCTOBER 6, 1958
RECORDING NO.: BOOK 1620, PAGE 16, OF OFFICIAL RECORDS.

EXCEPTION#12 THE OWNERSHIP OF SAID LAND DOES NOT INCLUDE RIGHTS OF ACCESS TO OR FROM THE STREET, HIGHWAY, OR FREEWAY ABUTTING SAID LAND, SUCH RIGHTS HAVING BEEN RELINQUISHED BY THE DOCUMENT,

RECORDING DATE: OCTOBER 23, 1958
RECORDING NO.: BOOK 1623, PAGE 113, OF OFFICIAL RECORDS.

EXCEPTION#13 WAIVER OF ANY CLAIMS FOR DAMAGES TO SAID LAND BY REASON OF THE LOCATION, CONSTRUCTION, LANDSCAPING OR MAINTENANCE OF THE STREET OR HIGHWAY ADJOINING SAID LAND, AS CONTAINED IN THE DEED TO
COUNTY/CITY/STATE: STATE OF CALIFORNIA
RECORDING DATE: OCTOBER 23, 1958
RECORDING NO.: BOOK 1623, PAGE 113, OF OFFICIAL RECORDS.

EXCEPTION#14 THE OWNERSHIP OF SAID LAND DOES NOT INCLUDE RIGHTS OF ACCESS TO OR FROM THE STREET, HIGHWAY, OR FREEWAY ABUTTING SAID LAND, SUCH RIGHTS HAVING BEEN RELINQUISHED BY THE DOCUMENT,

RECORDING DATE: APRIL 14, 1960
RECORDING NO.: BOOK 1748, PAGE 617, OF OFFICIAL RECORDS.

EXCEPTION#15 WAIVER OF ANY CLAIMS FOR DAMAGES TO SAID LAND BY REASON OF THE LOCATION, CONSTRUCTION, LANDSCAPING OR MAINTENANCE OF THE STREET OR HIGHWAY ADJOINING SAID LAND, AS CONTAINED IN THE DEED TO

COUNTY/CITY/STATE: STATE OF CALIFORNIA
RECORDING DATE: APRIL 14, 1960
RECORDING NO.: BOOK 1748, PAGE 617, OF OFFICIAL RECORDS.

EXCEPTION#16 EASEMENT(S) FOR THE PURPOSE(S) SHOWN BELOW AND RIGHTS INCIDENTAL THERETO, AS GRANTED IN A DOCUMENT:

GRANTED TO: FLUOR PRODUCTS COMPANY, INC. AND SPEEDSPACE CORPORATION
PURPOSE: ROADWAY PURPOSES AND UNDERGROUND UTILITIES (10 FEET IN WIDTH)
RECORDING DATE: MAY 21, 1968
RECORDING NO.: BOOK 2333, PAGE 798, OF OFFICIAL RECORDS
AFFECTS: PARCELS ONE AND SEVEN.

EXCEPTION#17 EASEMENT(S) FOR THE PURPOSE(S) SHOWN BELOW AND RIGHTS INCIDENTAL THERETO, AS GRANTED IN A DOCUMENT:

GRANTED TO: PACIFIC GAS AND ELECTRIC COMPANY, A CALIFORNIA CORPORATION
PURPOSE: INSTALLATION AND MAINTENANCE OF AN UNDERGROUND GAS PIPELINE, TOGETHER WITH INGRESS AND EGRESS
RECORDING DATE: AUGUST 26, 1968
RECORDING NO.: BOOK 2348, PAGE 620, OF OFFICIAL RECORDS
AFFECTS: PARCEL ONE

LIMITATIONS ON THE USE, BY THE OWNERS OF SAID LAND, OF THE EASEMENT AREA AS SET FORTH IN THE EASEMENT DOCUMENT SHOWN HEREIN ABOVE.

REFERENCE IS HEREBY MADE TO SAID DOCUMENT FOR FULL PARTICULARS.

EXCEPTION#18 MATTERS CONTAINED IN THAT CERTAIN DOCUMENT

ENTITLED: COVENANT LIMITED IMPROVEMENT TO LAND
DATED: OCTOBER 9, 1968
EXECUTED BY: SONOMA COUNTY PLANNING DEPARTMENT
RECORDING DATE: DECEMBER 26, 1968
RECORDING NO.: BOOK 2369, PAGE 903, OF OFFICIAL RECORDS

REFERENCE IS HEREBY MADE TO SAID DOCUMENT FOR FULL PARTICULARS.

EXCEPTION#19 EASEMENT(S) FOR THE PURPOSE(S) SHOWN BELOW AND RIGHTS INCIDENTAL THERETO, AS GRANTED IN A DOCUMENT:

PURPOSE: GENERAL ROAD AND UTILITY
RECORDING DATE: MAY 4, 1978
RECORDING NO.: BOOK 3391, AT PAGE 600, OFFICIAL RECORDS
AFFECTS: THE SOUTHERLY 40 FEET OF PARCEL TWO.

EXCEPTION#20 MATTERS CONTAINED IN THAT CERTAIN DOCUMENT

ENTITLED: RECIPROCAL EASEMENT AGREEMENT
DATED: SEPTEMBER 19, 1972
EXECUTED BY: ECODYNE COOLING PRODUCTS COMPANY, A CALIFORNIA CORPORATION FORMERLY KNOWN AS FLUOR PRODUCTS COMPANY, INC. AND POTLATCH FORESTS, INC., A DELAWARE CORPORATION
RECORDING DATE: OCTOBER 2, 1972
RECORDING NO.: BOOK 2668, PAGE 493, OF OFFICIAL RECORDS REFERENCE IS HEREBY MADE TO SAID DOCUMENT FOR FULL PARTICULARS.
AFFECTS: PARCELS THREE AND FOUR.

EXCEPTION#21 EASEMENT(S) FOR THE PURPOSE(S) SHOWN BELOW AND RIGHTS INCIDENTAL THERETO AS RESERVED IN A DOCUMENT;

RESERVED BY: STANDARD STRUCTURES, INC.
PURPOSE: ROADWAY, PUBLIC UTILITIES AND SANITARY SEWER FACILITIES
RECORDING DATE: OCTOBER 1, 1979
RECORDING NO.: BOOK 3630, PAGE 861, OF OFFICIAL RECORDS
AFFECTS: PARCEL TWO

AS MODIFIED BY THE FOLLOWING RECORDED INSTRUMENTS OF OFFICIAL RECORDS:
RECORDED: INSTRUMENT NO.:
B. JULY 29, 2013 2013077418, OF OFFICIAL RECORDS
C. JULY 29, 2013 2013077419, OF OFFICIAL RECORDS
D. JULY 29, 2013 2013077420, OF OFFICIAL RECORDS
E. JULY 29, 2013 2013077421, OF OFFICIAL RECORDS
F. JANUARY 3, 2014 2014000581, OF OFFICIAL RECORDS
G. JANUARY 3, 2014 2014000582, OF OFFICIAL RECORDS
H. MARCH 4, 2015 2015017184, OF OFFICIAL RECORDS

EXCEPTION#22 MATTERS CONTAINED IN THAT CERTAIN DOCUMENT

ENTITLED: EASEMENT AGREEMENT
DATED: DECEMBER 20, 1985
EXECUTED BY: STANDARD STRUCTURES, INC., A CALIFORNIA CORPORATION AND SIDDHARTH SHAH, A MARRIED MAN
RECORDING DATE: DECEMBER 24, 1985
RECORDING NO.: 85-086593, OF OFFICIAL RECORDS

REFERENCE IS HEREBY MADE TO SAID DOCUMENT FOR FULL PARTICULARS.

AS MODIFIED BY THE FOLLOWING RECORDED INSTRUMENTS OF OFFICIAL RECORDS:
RECORDED: INSTRUMENT NO.:
A. JULY 29, 2013, DOC NO 2013-077418, OF OFFICIAL RECORDS
B. JULY 29, 2013 2013077419, OF OFFICIAL RECORDS
C. JULY 29, 2013 2013077420, OF OFFICIAL RECORDS
D. JULY 29, 2013 2013077421, OF OFFICIAL RECORDS
E. JANUARY 3, 2014 2014000581, OF OFFICIAL RECORDS
F. JANUARY 3, 2014 2014000582, OF OFFICIAL RECORDS
G. MARCH 4, 2015 2015017184, OF OFFICIAL RECORDS

EXCEPTION#23 EASEMENT FOR PROVIDING ACCESS TO PROPERTY FOR SOIL AND GROUND WATER INVESTIGATION AND RIGHTS INCIDENTAL THERETO AS SET FORTH IN A DOCUMENT RECORDED NOVEMBER 17, 1986, AS INSTRUMENT 86-094532 OF OFFICIAL RECORDS.
BY TERMS CONTAINED IN SAID DOCUMENT THIS EASEMENT EXPIRED NOVEMBER 15, 1987

AFFECTS: PARCELS THREE AND SEVEN CONDITIONS CONTAINED THEREIN.

AS MODIFIED BY THE FOLLOWING RECORDED INSTRUMENTS OF OFFICIAL RECORDS:
RECORDED: INSTRUMENT NO.:
A. JULY 29, 2013 2013077418, OF OFFICIAL RECORDS
B. JULY 29, 2013 2013077419, OF OFFICIAL RECORDS
C. JULY 29, 2013 2013077420, OF OFFICIAL RECORDS
D. JULY 29, 2013 2013077421, OF OFFICIAL RECORDS
E. JANUARY 3, 2014 2014000581, OF OFFICIAL RECORDS
F. JANUARY 3, 2014 2014000582, OF OFFICIAL RECORDS
G. MARCH 4, 2015 2015017184, OF OFFICIAL RECORDS

EXCEPTION#24 INTENTIONALLY DELETED.

EXCEPTION#25 INTENTIONALLY DELETED.

EXCEPTION#26 EASEMENT FOR ROADWAY AND UTILITIES AND RIGHTS INCIDENTAL THERETO AS SET FORTH IN A DOCUMENT RECORDED SEPTEMBER 18, 1992, AS INSTRUMENT NO. 1992-0115413, OF OFFICIAL RECORDS.

AFFECTS: PARCEL ONE

AS MODIFIED BY THE FOLLOWING RECORDED INSTRUMENTS OF OFFICIAL RECORDS:
RECORDED: INSTRUMENT NO.:
A. JULY 29, 2013 2013077418, OF OFFICIAL RECORDS
B. JULY 29, 2013 2013077419, OF OFFICIAL RECORDS
C. JULY 29, 2013 2013077420, OF OFFICIAL RECORDS
D. JULY 29, 2013 2013077421, OF OFFICIAL RECORDS
E. JANUARY 3, 2014 2014000581, OF OFFICIAL RECORDS
F. JANUARY 3, 2014 2014000582, OF OFFICIAL RECORDS
G. MARCH 4, 2015 2015017184, OF OFFICIAL RECORDS

EXCEPTION#27 EASEMENT(S) FOR THE PURPOSE(S) SHOWN BELOW AND RIGHTS INCIDENTAL THERETO, AS GRANTED IN A DOCUMENT:
GRANTED TO: SONOMA COUNTY WATER AGENCY
PURPOSE: CHANNEL CAPACITY MAINTENANCE, ACCESS AND PERMANENT ACCESS
RECORDING DATE: MAY 4, 1993
RECORDING NO.: 1993-0054910, OF OFFICIAL RECORDS
AFFECTS: PARCELS ONE AND SEVEN.

EXCEPTION#28 MATTERS CONTAINED IN THAT CERTAIN DOCUMENT ENTITLED: CONDITIONAL USE AGREEMENT
DATED: JULY 18, 1996
EXECUTED BY: RICHARD C. CALETTI ET US AND PACIFIC BELL MOBILE SERVICES, A CALIFORNIA CORPORATION
RECORDING DATE: JULY 24, 1996
RECORDING NO.: 1996-0065960, OF OFFICIAL RECORDS

REFERENCE IS HEREBY MADE TO SAID DOCUMENT FOR FULL PARTICULARS.

NOT A SURVEY MATTER

EXCEPTION#29 NOTICE OF VOLUNTARY MERGER, MERGING THE HEREIN DESCRIBED PROPERTY

EXECUTED BY: TOWN OF WINDSOR
RECORDING DATE: JANUARY 28, 1997
RECORDING NO.: 1997-0007460, OF OFFICIAL RECORDS
AND ALSO RECORDED: JUNE 17, 1997, AS INSTRUMENT 1997-0051032, OF OFFICIAL RECORDS.

EXCEPTION#30 MATTERS CONTAINED IN THAT CERTAIN DOCUMENT

ENTITLED: GRANT DEED OF OPEN SPACE EASEMENTS AND ABANDONMENT OF OPEN SPACE EASEMENTS
DATED: SEPTEMBER 4, 1997
EXECUTED BY: SONOMA COUNTY DAY SCHOOL, A CALIFORNIA NONPROFIT CORPORATION; AIRPORT 101 PROPERTY, A PARTNERSHIP; RICHARD AND FLORAMAY CALETTI, HUSBAND AND WIFE; SONOMA LAND TRUST, A CALIFORNIA NONPROFIT CORPORATION AND THE COUNTY OF SONOMA, A POLITICAL SUBDIVISION OF THE STATE OF CALIFORNIA
RECORDING DATE: OCTOBER 17, 1997
RECORDING NO.: 1997-0096276, OF OFFICIAL RECORDS

REFERENCE IS HEREBY MADE TO SAID DOCUMENT FOR FULL PARTICULARS.

EXCEPTION#31 MATTERS CONTAINED IN THAT CERTAIN DOCUMENT

ENTITLED: INGRESS, EGRESS AND UTILITY EASEMENT AGREEMENT
DATED: JANUARY 30, 1998
EXECUTED BY: SONOMA COUNTY DAY SCHOOL, STANDARD STRUCTURES, INC., HELEN M. CALETTI AND RICHARD C. CALETTI, CO-TRUSTEES OF THE TRUST SET FORTH UNDER THE LAST WILL OF CARLO W. CALETTI, AND RICHARD C. CALETTI AND FLORAMAY CALETTI
RECORDING DATE: AUGUST 28, 1998
RECORDING NO.: 1998-0099681, OF OFFICIAL RECORDS

REFERENCE IS HEREBY MADE TO SAID DOCUMENT FOR FULL PARTICULARS.

EXCEPTION#32 MATTERS CONTAINED IN THAT CERTAIN DOCUMENT:

ENTITLED: EMERGENCY VEHICLE ACCESS EASEMENT AGREEMENT
DATED: AUGUST 28, 1998
EXECUTED BY: SONOMA COUNTY DAY SCHOOL, STANDARD STRUCTURES, INC., HELEN M. CALETTI AND RICHARD C. CALETTI, CO-TRUSTEES OF THE TRUST SET FORTH UNDER THE LAST WILL OF CARLO W. CALETTI, AND RICHARD C. CALETTI AND FLORAMAY CALETTI
RECORDING DATE: AUGUST 28, 1998
RECORDING NO.: 1998-0099682, OF OFFICIAL RECORDS REFERENCE IS HEREBY MADE TO SAID DOCUMENT FOR FULL PARTICULARS.

EXCEPTION#33 MATTERS CONTAINED IN THAT CERTAIN DOCUMENT

ENTITLED: INGRESS, EGRESS AND UTILITY EASEMENT AGREEMENT
DATED: NOVEMBER 18, 1998
EXECUTED BY: SONOMA COUNTY DAY SCHOOL, STANDARD STRUCTURES, INC., HELEN M. CALETTI AND RICHARD C. CALETTI, CO-TRUSTEES OF THE TRUST SET FORTH UNDER THE LAST WILL OF CARLO W. CALETTI, AND RICHARD C. CALETTI AND FLORAMAY CALETTI
RECORDING DATE: DECEMBER 30, 1998
RECORDING NO.: 1998-0157292, OF OFFICIAL RECORDS

REFERENCE IS HEREBY MADE TO SAID DOCUMENT FOR FULL PARTICULARS.

AS MODIFIED BY THE FOLLOWING RECORDED INSTRUMENTS OF OFFICIAL RECORDS:
RECORDED: INSTRUMENT NO.:
A. JULY 29, 2013 2013077418, OF OFFICIAL RECORDS
B. JULY 29, 2013 2013077419, OF OFFICIAL RECORDS
C. JULY 29, 2013 2013077420, OF OFFICIAL RECORDS
D. JULY 29, 2013 2013077421, OF OFFICIAL RECORDS
E. JANUARY 3, 2014 2014000581, OF OFFICIAL RECORDS
F. JANUARY 3, 2014 2014000582, OF OFFICIAL RECORDS
G. MARCH 4, 2015 2015017184, OF OFFICIAL RECORDS

EXCEPTION#34 EASEMENT FOR ROADWAY, PUBLIC UTILITIES AND SANITARY SEWER AND RIGHTS INCIDENTAL THERETO AS SET FORTH IN A DOCUMENT RECORDED NOVEMBER 2, 1998, AS INSTRUMENT 1998-0129510, OF OFFICIAL RECORDS.

AFFECTS: PORTIONS OF PARCEL TWO

EXCEPTION#35 INTENTIONALLY DELETED.

EXCEPTION#36 INTENTIONALLY DELETED.

EXCEPTION#37 MATTERS CONTAINED IN THAT CERTAIN DOCUMENT

ENTITLED: EASEMENT, ROAD AND EVA MAINTENANCE AGREEMENT
DATED: JULY 18, 1996
EXECUTED BY: SHILOH OAKS, LLC AND RICHARD C. AND FLORAMAY CALETTI
RECORDING DATE: NOVEMBER 30, 2007
RECORDING NO.: 2007-127026, OF OFFICIAL RECORDS

REFERENCE IS HEREBY MADE TO SAID DOCUMENT FOR FULL PARTICULARS.

EXCEPTION#38 MATTERS CONTAINED IN THAT CERTAIN DOCUMENT

ENTITLED: WIRELESS COMMUNICATION EASEMENT AND ASSIGNMENT AGREEMENT
DATED: OCTOBER 18, 2011
EXECUTED BY: RICHARD C. CALETTI, SUCCESSOR TO TRUSTEE OF THE RICHARD C. CALETTI AND FLORAMAY CALETTI TRUST AGREEMENT DATED OCTOBER 27, 1998, STANDARD STRUCTURES, INC., A CALIFORNIA CORPORATION AND T10 UNISON SITE MANAGEMENT LLC
RECORDING DATE: NOVEMBER 7, 2011
RECORDING NO.: 2011098471, OF OFFICIAL RECORDS

REFERENCE IS HEREBY MADE TO SAID DOCUMENT FOR FULL PARTICULARS.

AN AGREEMENT TO MODIFY THE TERMS AND PROVISIONS OF THE SAID DOCUMENT, AS THEREIN PROVIDED

EXECUTED BY: STANDARD INDUSTRIAL EAST, LLC, A CALIFORNIA LIMITED LIABILITY COMPANY AND T10 MELTEL LLC, A DELAWARE LIMITED LIABILITY COMPANY
RECORDING DATE: SEPTEMBER 27, 2018
RECORDING NO.: 2018067726, OF OFFICIAL RECORDS.

EXCEPTION#39 A DEED OF TRUST TO SECURE AN INDEBTEDNESS IN THE AMOUNT SHOWN BELOW,
AMOUNT: $3,310,000.00
DATED: OCTOBER 10, 2012
TRUSTOR/GRANTOR: RICHARD C. CALETTI, NOT PERSONALLY BUT AS TRUSTEE ON BEHALF OF RICHARD C. CALETTI, SUCCESSOR TRUSTEE OF THE RICHARD C. CALETTI AND FLORAMAY CALETTI TRUST DATED OCTOBER 27, 1998
TRUSTEE: FIDELITY NATIONAL TITLE COMPANY
BENEFICIARY: ALTAPACIFIC BANK
LOAN NO.: 40021300
RECORDING DATE: NOVEMBER 15, 2012
RECORDING NO.: 2012114050, OF OFFICIAL RECORDS

MATTERS CONTAINED IN THAT CERTAIN DOCUMENT:

ENTITLED: LOAN ASSUMPTION AGREEMENT
DATED: JULY 15, 2013
EXECUTED BY: ALTPACIFIC BANK (LENDER); RICHARD C. CALETTI, SUCCESSOR TRUSTEE OF THE RICHARD C. CALETTI AND FLORAMAY FAMILY TRUST UTD DATED OCTOBER 27, 1998 (BORROWER) AND STANDARD EAST, LLC (ASSUMING PARTY)
RECORDING DATE: JULY 30, 2013
RECORDING NO.: 2013077623, OF OFFICIAL RECORDS

REFERENCE IS HEREBY MADE TO SAID DOCUMENT FOR FULL PARTICULARS.
AN AGREEMENT TO MODIFY THE TERMS AND PROVISIONS OF SAID DEED OF TRUST AS THEREIN PROVIDED

EXECUTED BY: RICHARD C. CALETTI, NOT PERSONALLY BUT AS TRUSTEE ON BEHALF OF RICHARD C. CALETTI, SUCCESSOR TRUSTEE OF THE RICHARD C. CALETTI AND FLORAMAY FAMILY TRUST UTD DATED OCTOBER 27, 1998; STANDARD EAST, LLC AND ALTAPACIFIC BANK
RECORDING DATE: JULY 30, 2013
RECORDING NO.: 2013077624, OF OFFICIAL RECORDS

A SUBSTITUTION OF TRUSTEE UNDER SAID DEED OF TRUST WHICH NAMES, AS THE SUBSTITUTED TRUSTEE, THE FOLLOWING

TRUSTEE: UPF WASHINGTON, INCORPORATED
RECORDING DATE: JUNE 25, 2020
RECORDING NO.: 2020050766, OF OFFICIAL RECORDS.

EXCEPTION#40 AN ASSIGNMENT OF ALL MONEYS DUE, OR TO BECOME DUE AS RENTAL OR OTHERWISE FROM SAID LAND, TO SECURE PAYMENT OF AN INDEBTEDNESS, SHOWN BELOW AND UPON THE TERMS AND CONDITIONS THEREIN

DATED: $3,310,000.00
ASSIGNED TO: ALTAPACIFIC BANK
ASSIGNED BY: RICHARD C. CALETTI, NOT PERSONALLY BUT AS TRUSTEE ON BEHALF OF RICHARD C. CALETTI, SUCCESSOR TRUSTEE OF THE RICHARD C. CALETTI AND FLORAMAY CALETTI TRUST DATED OCTOBER 27, 1998
RECORDING DATE: NOVEMBER 15, 2012
RECORDING NO.: 2012114051, OF OFFICIAL RECORDS.

EXCEPTION#41 MATTERS CONTAINED IN THAT CERTAIN DOCUMENT

ENTITLED: HAZARDOUS SUBSTANCES CERTIFICATE AND INDEMNITY AGREEMENT
DATED: OCTOBER 10, 2012
EXECUTED BY: RICHARD C. CALETTI, SUCCESSOR TRUSTEE OF THE RICHARD C. CALETTI AND FLORAMAY CALETTI TRUST DATED OCTOBER 27, 1998 AND ALTAPACIFIC BANK
RECORDING DATE: NOVEMBER 15, 2012
RECORDING NO.: 2012-114052, OF OFFICIAL RECORDS

REFERENCE IS HEREBY MADE TO SAID DOCUMENT FOR FULL PARTICULARS.

EXCEPTION#42 MATTERS CONTAINED IN THAT CERTAIN DOCUMENT

ENTITLED: SUBORDINATION, NONDISTURBANCE AND ATTORNMENT AGREEMENT
DATED: JULY 15, 2013
EXECUTED BY: SHOOK & WALLER CONSTRUCTION AND RICHARD C. CALETTI
RECORDING DATE: NOVEMBER 15, 2012
RECORDING NO.: 2012114053, OF OFFICIAL RECORDS

REFERENCE IS HEREBY MADE TO SAID DOCUMENT FOR FULL PARTICULARS.

EXCEPTION#43 AN UNRECORDED LEASE WITH CERTAIN TERMS, COVENANTS, CONDITIONS AND PROVISIONS SET FORTH THEREIN AS DISCLOSED BY THE DOCUMENT

ENTITLED: SUBORDINATION, NON-DISTURBANCE AND ATTORNMENT AGREEMENT AND ESTOPPEL CERTIFICATE
LESSOR: RICHARD C. CALETTI
LESSEE: SHOOK & WALLER CONSTRUCTION RECORDING
DATE: NOVEMBER 15, 2012
RECORDING NO.: 2012-114053, OF OFFICIAL RECORDS

AN AGREEMENT RECORDED NOVEMBER 15, 2012 AT INSTRUMENT NO. 2012114053, OF OFFICIAL RECORDS WHICH STATES THAT THIS INSTRUMENT WAS SUBORDINATED TO THE DOCUMENT OR INTEREST DESCRIBED IN THE INSTRUMENT

RECORDING DATE: NOVEMBER 15, 2012
RECORDING NO.: 2012114050, OF OFFICIAL RECORDS

THE PRESENT OWNERSHIP OF THE LEASEHOLD CREATED BY SAID LEASE AND OTHER MATTERS AFFECTING THE INTEREST OF THE LESSEE ARE NOT SHOWN HEREIN.

EXCEPTION#44 MATTERS CONTAINED IN THAT CERTAIN DOCUMENT

ENTITLED: SUBORDINATION, NONDISTURBANCE AND ATTORNMENT AGREEMENT
DATED: JULY 15, 2013
EXECUTED BY: REDBUILT LLC, A DELAWARE LIMITED LIABILITY COMPANY AND RICHARD C. CALETTI
RECORDING DATE: NOVEMBER 15, 2012
RECORDING NO.: 2012114054, OF OFFICIAL RECORDS

REFERENCE IS HEREBY MADE TO SAID DOCUMENT FOR FULL PARTICULARS.

EXCEPTION#45 AN UNRECORDED LEASE WITH CERTAIN TERMS, COVENANTS, CONDITIONS AND PROVISIONS SET FORTH THEREIN AS DISCLOSED BY THE DOCUMENT

ENTITLED: SUBORDINATION, NON-DISTURBANCE AND ATTORNMENT AGREEMENT AND ESTOPPEL CERTIFICATE
LESSOR: RICHARD C. CALETTI
LESSEE: REDBUILT LLC, A DELAWARE LIMITED LIABILITY COMPANY
RECORDING DATE: NOVEMBER 15, 2012
RECORDING NO.: 2012114054, OF OFFICIAL RECORDS

AN AGREEMENT RECORDED NOVEMBER 15, 2012 AT INSTRUMENT NO. 2012114054, OF OFFICIAL RECORDS WHICH STATES THAT THIS INSTRUMENT WAS SUBORDINATED TO THE DOCUMENT OR INTEREST DESCRIBED IN THE INSTRUMENT:

RECORDING DATE: NOVEMBER 15, 2012
RECORDING NO.: 2012114050, OF OFFICIAL RECORDS

THE PRESENT OWNERSHIP OF THE LEASEHOLD CREATED BY SAID LEASE AND OTHER MATTERS AFFECTING THE INTEREST OF THE LESSEE ARE NOT SHOWN HEREIN.

EXCEPTION#46 MATTERS CONTAINED IN THAT CERTAIN DOCUMENT

ENTITLED: SUBORDINATION, NONDISTURBANCE AND ATTORNMENT AGREEMENT
DATED: JULY 15, 2013
EXECUTED BY: LEGACY PHOTO STUDTIO, INC. AND RICHARD C. CALETTI
RECORDING DATE: NOVEMBER 15, 2012
RECORDING NO.: 2012114055, OF OFFICIAL RECORDS

REFERENCE IS HEREBY MADE TO SAID DOCUMENT FOR FULL PARTICULARS.

EXCEPTION#47 AN UNRECORDED LEASE WITH CERTAIN TERMS, COVENANTS, CONDITIONS AND PROVISIONS SET FORTH THEREIN AS DISCLOSED BY THE DOCUMENT

ENTITLED: SUBORDINATION, NON-DISTURBANCE AND ATTORNMENT AGREEMENT AND ESTOPPEL CERTIFICATE
LESSOR: RICHARD C. CALETTI
LESSEE: LEGACY PHOTO STUDIO, INC.
RECORDING DATE: NOVEMBER 15, 2012
RECORDING NO.: 2012114055, OF OFFICIAL RECORDS

AN AGREEMENT RECORDED NOVEMBER 15, 2012 AT INSTRUMENT NO. 2012114055, OF OFFICIAL RECORDS WHICH STATES THAT THIS INSTRUMENT WAS SUBORDINATED TO THE DOCUMENT OR INTEREST DESCRIBED IN THE INSTRUMENT

RECORDING DATE: NOVEMBER 15, 2012
RECORDING NO.: 2012114050, OF OFFICIAL RECORDS

THE PRESENT OWNERSHIP OF THE LEASEHOLD CREATED BY SAID LEASE AND OTHER MATTERS AFFECTING THE INTEREST OF THE LESSEE ARE NOT SHOWN HEREIN.

EXCEPTION#48 MATTERS CONTAINED IN THAT CERTAIN DOCUMENT

ENTITLED: NOTICE OF ASSIGNMENT
DATED: APRIL 10, 2014
EXECUTED BY: CCTM1 LLC, A DELAWARE LIMITED LIABILITY COMPANY FORMERLY KNOWN AS T3 TOWER1 LLC
RECORDING DATE: SEPTEMBER 8, 2014
RECORDING NO.: 2014062608, OF OFFICIAL RECORDS

REFERENCE IS HEREBY MADE TO SAID DOCUMENT FOR FULL PARTICULARS.

EXCEPTION#49 EASEMENT(S) FOR THE PURPOSE(S) SHOWN BELOW AND RIGHTS INCIDENTAL THERETO, AS GRANTED IN A DOCUMENT:

GRANTED TO: PACIFIC GAS AND ELECTRIC COMPANY, A CALIFORNIA CORPORATION
PURPOSE: PUBLIC UTILITIES AND RIGHT OF WAY
RECORDING DATE: OCTOBER 3, 2016
RECORDING NO.: 2016087755, OF OFFICIAL RECORDS
AFFECTS: AS DESCRIBED AND DELINEATED THEREIN

LIMITATIONS ON THE USE, BY THE OWNERS OF SAID LAND, OF THE EASEMENT AREA AS SET FORTH IN THE EASEMENT DOCUMENT SHOWN HEREINABOVE.

REFERENCE IS HEREBY MADE TO SAID DOCUMENT FOR FULL PARTICULARS.

EXCEPTION#50 EASEMENT(S) FOR THE PURPOSE(S) SHOWN BELOW AND RIGHTS INCIDENTAL THERETO, AS GRANTED IN A DOCUMENT:

GRANTED TO: KATHLEEN K. KURZ, TRUSTEE OF THE KURZ FAMILY TRUST DATED 4/27/1981
PURPOSE: USE AND ENJOYMENT
RECORDING DATE: FEBRUARY 21, 2020
RECORDING NO.: 2020013339, OF OFFICIAL RECORDS.

EXCEPTION#51 MATTERS CONTAINED IN THAT CERTAIN DOCUMENT

ENTITLED: AGREEMENT TO COMPLETE LOT LINE ADJUSTMENT
DATED: FEBRUARY 9, 2020
EXECUTED BY: STANDARD INDUSTRIAL EAST, LLC, A CALIFORNIA LIMITED LIABILITY COMPANY AND KATHLEEN K. KURZ, TRUSTEE OF THE KURZ FAMILY TRUST DATED 4/27/1981
RECORDING DATE: FEBRUARY 21, 2020
RECORDING NO.: 2020013341, OF OFFICIAL RECORDS

REFERENCE IS HEREBY MADE TO SAID DOCUMENT FOR FULL PARTICULARS.

EXCEPTION#AA A PUBLIC UTILITY EASEMENT GRANTED TO THE TOWN OF WINDSOR, 5/6/2004 AS DOCUMENT NUMBER 2004-067799

PRELIMINARY
FOR STUDY PURPOSES ONLY
DATE 12-14-20

ALTA/NSPS LAND TITLE SURVEY
APN 059-271-095
790 SHILOH ROAD

LYING WITHIN SECTION 19, TOWNSHIP 8 NORTH RANGE 9 WEST, M.D.B.&M. AND BEING THE LANDS OF STANDARD STRUCTURES AS DESCRIBED IN DOCUMENT NUMBER 2013-077622, OFFICIAL RECORDS OF SONOMA COUNTY.

COUNTY OF SONOMA, STATE OF CALIFORNIA

Brelje & Race
CONSULTING ENGINEERS
475 Aviation Blvd. • Suite 120 • Santa Rosa, CA 95403 • 707-576-1322
www.brce.com

DECEMBER 2020

12-14-20 henry \4623\map\4623.01 ALTA-Notes Sheet 1.dwg

SURVEYOR'S CERTIFICATE:

TO **KASHIA BAND OF POMO INDIANS;**

THIS IS TO CERTIFY THAT THIS MAP OR PLAT AND THE SURVEY ON WHICH IT IS BASED WERE MADE IN ACCORDANCE WITH THE 2016 MINIMUM STANDARD DETAIL REQUIREMENTS FOR ALTA/NSPS LAND TITLE SURVEYS, JOINTLY ESTABLISHED AND ADOPTED BY ALTA AND NSPS, AND INCLUDES ITEMS **2,7a,7b1,8,13,19** OF TABLE A THEREOF. THE FIELDWORK WAS COMPLETED ON **11/16/20.**

THE USE OF THE WORDS "CERTIFY," "CERTIFICATION," "CERTIFIES" AND "CERTIFICATE" ONLY CONSTITUTES AN EXPRESSION OF PROFESSIONAL OPINION REGARDING THOSE FACTS OR FINDINGS WHICH ARE THE SUBJECT OF THIS DOCUMENT AND DOES NOT CONSTITUTE A WARRANTY OR GUARANTEE, EITHER EXPRESSED OR IMPLIED, IN ACCORDANCE WITH PROVISIONS OF CALIFORNIA BUSINESS AND PROFESSIONS CODE SECTIONS 6735.5 AND 8770.6."

JOHN S. LOCEY RCE 31909 DATE

PRELIMINARY
NOT FOR CONSTRUCTION OR RECORDATION
DATE: 12-14-20

BASIS OF BEARING

THE BEARING N86°30'28"E OF THE LINE BETWEEN TWO FOUND CALTRANS DISKS, S-126 AND S-125, SHOWN ON CALTRANS R119.12 WAS TAKEN AS THE BASIS OF BEARING FOR THIS MAP

REFERENCES

CALTRANS R119.12
210 MAPS 44
279 MAPS 10-11
432 MAPS 50-52
PARCEL MAP NO. MNS 91-919 510 MAPS 41-46
PARCEL MAP NO. MNS 94-06 529 MAPS 4-7
PARCEL MAP NO. MJS 95-1005 572 MAPS 1-4
PARCEL MAP NO. MJS 05-24 716 MAPS 1-5
AMENDED PARCEL MAP NO. MJS 05-24 739 MAPS 40-44

LAND AREA

AREA: 45.62 ACRES±

LEGEND

BOUNDARY LINE	———
CENTER LINE	———
EASEMENT	- - - -
FENCE	—X—X—X—
FIRE LINE	—F—
IRRIGATION LINE	—IRR—
RIGHT OF WAY LINE	———
SETBACK LINE	— — —
SEWER LINE	—SS—
WATER LINE	—W—
FOUND MONUMENT	●
FOUND WELL MONUMENT AS NOTED	◉
HANDICAP PARKING SPACE	♿
VAULT	⊠

AC	ASPHALT CONCRETE
APN	ASSESSOR PARCEL NUMBER
BFP	BACK FLOW PREVENTER
CONC	CONCRETE
DDCV	DOUBLE DETECTOR CHECK VALVE
DOC	DOCUMENT
EBOX	ELECTRICAL BOX
EL	ELECTRICAL
EP	EDGE OF PAVEMENT
EW	EDGE OF WALK
EX	EXISTING
FND	FOUND
FH	FIRE HYDRANT
GTIC	GREASE TRAP INTERCEPTOR
ICB	IRRIGATION CHECK BOX
ICV	IRRIGATION CONTROL VALVE
INFO	IN FAVOR OF
NO	NUMBER
NTS	NOT TO SCALE
OHL	OVERHEAD LINE
POC	POINT OF COMMENCEMENT
POB	POINT OF BEGINNING
PUE	PUBLIC UTILITY EASEMENT
SDDI	STORM DRAIN DROP INLET
SSCO	SANITARY SEWER CLEANOUT
SSMH	SANITARY SEWER MANHOLE
STLT	STREET LIGHT
T	TRASH
TBOX	TELEPHONE BOX
TC	TOP OF CURB
TYP	TYPICAL
WM	WATER METER
WV	WATER VALVE
(IN)	INSIDE BOUNDARY
(OUT)	OUTSIDE BOUNDARY



LOCATION MAP
NOT TO SCALE

U. S. FREEWAY NO. 101

SEE BELOW LEFT

SEE ABOVE MIDDLE

PARCEL ONE
7.31 ACRES

PARCEL SEVEN
1.31 ACRES

PARCEL TWO
27.51 ACRES

PARCEL FIVE
1.14 ACRES

PARCEL SIX
8.33 ACRES

PARCEL FOUR
CENTERLINE OF 20' WIDE RAILROAD SPUR

PARCEL BB
(EXCEPTION #37)
FUTURE PRUITT AVE
DOC NO 2007-127026

PARCEL CC
(EXCEPTION #31)
ACCESS & UTILITY EASEMENT
DOC NO 1998-0099681

PARCEL DD
EVA EASEMENT
DOC NO 1998-0099682

PARCEL AA
(EXCEPTION #37)
74' WIDE EAST/WEST CONNECTOR
DOC NO 2007-127026

PRUITT AVENUE (PUBLIC)

FUTURE PRUITT AVENUE (PRIVATE)

AVIATION BLVD (PUBLIC)

SHILOH ROAD

CALETTI AVENUE PUBLIC

FUTURE PRUITT AVE AS SHOWN ON AN UNRECORDED PLAT BY BRELJE & RACE

KURZ
DOC NO 2020-013339
APN 059-271-082

STORAGE PRO OF WINDSOR LLC
DOC NO 2017-021361
APN 059-271-110

NEW SHILOH LLC
DOC NO 2020-018913
APN 059-271-103

TOWN OF WINDSOR
DOC NO 2008-107978
APN 059-271-102

SOCO INVESTMENTS
DOC NO 2017-068596
APN 059-271-104

TOWN OF WINDSOR
PER 739 MAPS 40-44
APN 059-271-101

WINDSOR EXPRESS
DOC NO 2010-073006
APN 059-271-097

AIRPOT BUSINESS CENTER
DOC NO 1992-045660
APN 059-350-111

JACKSON FAMILY WINES INC.
DOC NO 2017-93532
APN 059-350-076

KENDALL-JACKSON WINERY LTD
DOC NO 1996-44342
APN 059-350-075

SONOMA COUNTY DAY SCHOOL
DOC NO 2001-142584
APN 059-350-094

SONOMA COUNTY EMPLOYEES RETIREMENT ASSOCIATION
DOC NO 2003-254766
APN 059-350-053

LYTTON RANCHERIA OF CALIFORNIA
DOC NO 2010-003461
APN 059-350-095

FND CALTRANS DISK S-125

FND CALTRANS DISK S-126

BASIS OF BEARINGS N86°30'28"E 718.37'

N35°15'48"W 776.05'

S35°15'48"E 2136.19' TOTAL 2771.06'

N35°15'48"W 455.87'

S35°11'32"E 422.31'

S89°37'57"E 267.41'

N89°37'57"E 1251.79'

N82°37'37"E 1252.98'

N00°36'07"E 433.26'

S00°36'07"W 1400.46

N00°37'18"E 290.04'

N00°33'50"E 290.04'

81.27'

S00°27'12"E 765.39'

S00°27'12"E 598.34'

PT A

S17°46'08"E 28.02'

S11°53'50"W 141.50'

S11°53'50"W 20.71'

S11°53'50"W 141.50'

Δ=12°17'32" R=480.00' L=102.98'

Δ=26°10'01" R=270.00' L=123.31'

Δ=25°56'24" R=230.00' L=104.13'

Δ=83°25'44" R=45.00' L=65.52'

Δ=82°05'51" R=53.00' L=75.94'

Δ=29°50'05" R=53.00' L=15.82'

A=181.82'' R=315.00' L=33.00'

Δ=31°14'19" R=10.00' L=5.45'

Δ=38°16'30" R=60.00' L=40.08'

126.43' S00°30'28"W

N50°26'19"W 18.70'

N01°17'32"W 20.29'

S89°58'57"W 10.61'

Δ=44°37'09" R=343.00' L=266.96'

S07°11'02"E 544.81'

Δ=85°19'54" R=103.00' L=153.40'

S00°09'45"W 57.41'

M_80+56.89N 55.5'

S88°26'34"E 317.72'

Δ=22°57'43" R=300.00' L=120.23'

S65°10'02"E 80.06'

S65°13'54"E 444.38'

Δ=19°08'27" R=350.00' L=116.92'

S65°11'18"E 80.00'

S35°16'44"E 114.12'

N89°34'40"E 187.19'

N83°20'06"W 45.34'

S00°30'01"W 3.91'

Δ=76°32'04" R=30.00' L=40.07'

N30°43'07"W 7.45'

Δ=52°56'19" R=65.00' L=59.89'

S35°11'32"E 422.31'

N35°15'48"W 776.05'

N01°17'32"W 20.29'

N50°26'19"W 18.70'

S89°58'57"W 10.61'

TAB: SHT 2-Overall Site 1005C

12-14-20 navarro \4623\map\4623.01 ALTA.dwg

100 0 100 200

SCALE IN FEET
1" = 100 Ft.

ALL DISTANCES AND DIMENSIONS ARE GIVEN IN FEET AND DECIMALS THEREOF.


ALTA/NSPS LAND TITLE SURVEY
APN 059-271-095
790 SHILOH ROAD

LYING WITHIN SECTION 19, TOWNSHIP 8 NORTH RANGE 9 WEST, M.D.B.&M. AND BEING THE LANDS OF STANDARD STRUCTURES AS DESCRIBED IN DOCUMENT NUMBER 2013-077622, OFFICIAL RECORDS OF SONOMA COUNTY.

COUNTY OF SONOMA, STATE OF CALIFORNIA

Brelje & Race CONSULTING ENGINEERS
475 Aviation Blvd. • Suite 320 • Santa Rosa, CA 95403 • 707-576-1322
www.brelje.com

DECEMBER 2020



LEGEND

BOUNDARY LINE	
CENTER LINE	
EASEMENT	
FENCE	X X X
FIRE LINE	F
IRRIGATION LINE	IRR
RIGHT OF WAY LINE	
SETBACK LINE	
SEWER LINE	SS
WATER LINE	W
FOUND MONUMENT	●
FOUND WELL MONUMENT AS NOTED	◉
HANDICAP PARKING SPACE	
VAULT	

AC	ASPHALT CONCRETE
APN	ASSESSOR PARCEL NUMBER
BFP	BACK FLOW PREVENTER
CONC	CONCRETE
DDCV	DOUBLE DETECTOR CHECK VALVE
DOC	DOCUMENT
EBOX	ELECTRICAL BOX
EL	ELECTRICAL
EP	EDGE OF PAVEMENT
EW	EDGE OF WALK
EX	EXISTING
FND	FOUND
FH	FIRE HYDRANT
GTIC	GREASE TRAP INTERCEPTOR
ICB	IRRIGATION CHECK BOX
ICV	IRRIGATION CONTROL VALVE
INFO	IN FAVOR OF
NO	NUMBER
NTS	NOT TO SCALE
OHL	OVERHEAD LINE
POC	POINT OF COMMENCEMENT
POB	POINT OF BEGINNING
PUE	PUBLIC UTILITY EASEMENT
SDDI	STORM DRAIN DROP INLET
SSCO	SANITARY SEWER CLEANOUT
SSMH	SANITARY SEWER MANHOLE
STLT	STREET LIGHT
T	TRASH
TBOX	TELEPHONE BOX
TC	TOP OF CURB
TYP	TYPICAL
WM	WATER METER
WV	WATER VALVE
(IN)	INSIDE BOUNDARY
(OUT)	OUTSIDE BOUNDARY

PRELIMINARY
FOR REVIEW ONLY
DATE 12-14-20

ALTA/NSPS LAND TITLE SURVEY
APN 059-271-095
790 SHILOH ROAD

LYING WITHIN SECTION 19, TOWNSHIP 8 NORTH RANGE 9 WEST, M.D.B.&M. AND BEING THE LANDS OF STANDARD STRUCTURES AS DESCRIBED IN DOCUMENT NUMBER 2013-077622, OFFICIAL RECORDS OF SONOMA COUNTY.

COUNTY OF SONOMA, STATE OF CALIFORNIA

Brelje & Race
CONSULTING ENGINEERS
475 Aviation Blvd. - Suite 120 - Santa Rosa, CA 95403 - 707-576-1322
www.brje.com

DECEMBER 2020

ALL DISTANCES AND DIMENSIONS ARE GIVEN IN FEET AND DECIMALS THEREOF.

12-14-20 henry \4623\mapv\4623.01 ALTA.dwg TAB: SHT-3 Site 505C

SEE SHEET 3

NOTE:
ADJOINING STORM DRAIN APPEARS TO ENCROACH ONTO PARCEL ONE

EXCEPTION #18
4' LIMITING OVERHEAD WIRE
BOOK 2369, PAGE 903 (1)

EXCEPTION #50&51
ESMT & LLA AGREEMENT
DOC. NO. 2020-013339
DOC. NO. 2020-013341

EXCEPTION AA
P.U.E.
DOC. NO. 2004067799

EXCEPTION #49
PG&E ESMT
DOC. NO. 2016087755

EXCEPTION #18
OVERHEAD LIGHTING IMPROVEMENT
BOOK 2369 PAGE 903 (1)

EXCEPTION #18
OVERHEAD LIGHTING IMPROVEMENT
BOOK 2369 PAGE 903 (2)

EXCEPTION #14 & 15
RECIPROCAL RIGHTS OF WAY
BOOK 1749 PAGE 617

EXCEPTION #40
OPEN SPACE ESMT
DOC. NO. 1987-0089278

PARCEL BB
FUTURE PRUITT AVENUE
DOC. NO. 2007-127026

PRUITT AVENUE
(PUBLIC)

FUTURE PRUITT AVENUE (PRIVATE)

U. S. FREEWAY NO. 101

FUTURE PRUITT AVENUE AS SHOWN ON UNRECORDED PLAT IN THE OFFICE OF BRELJE & RACE JOB NO. 1873.3 DATED 5/16/2016

FUTURE PRUITT AVENUE AS SHOWN ON UNRECORDED PLAT IN THE OFFICE OF BRELJE & RACE JOB NO. 1873.3 DATED 5/16/2016

NOTE:
DRAINAGE FLOWS ACROSS ADJOINING PARCEL 2

N50°26'19"W 18.70'
Δ=38°16'30" R=60.00' L=40.08'
Δ=31°14'19" R=10.00' L=5.45'
N57°28'31"W 75.14'
N54°38'45"W 20.25'
Δ=82°05'51" R=53.00' L=75.94'
N01°17'00"W 20.29'
Δ=11°15'22" R=168.00' L=33.00'
S89°58'23"W 10.61'
S25°11'32"E 423.31'
N00°36'07"E 433.26'
S00°36'07"W 1460.46'
S25°15'46"W 74.03'
S25°15'49"E 21.38'
S25°15'49"E 277.98' (DTAL)

SD FL36"CMP INV 107.62
SD FL36"HDP INV 109.94
SD FL24"CMP INV 109.47
SD FL24"DIP TG 110.75
SD FL24"DIP TG 110.52
SSCO RIM 114.96
SSCO RIM 115.30
SSCO RIM 116.05

2.5' FENCE (IN)
0.3' FENCE (IN)
0.2' FENCE (IN)
0.4' FENCE (OUT)
0.2' FENCE (IN)
0.4' FENCE (IN)
0.2' FENCE (IN)
0.3' FENCE (OUT)
5.5' FENCE (OUT)
0.5' FENCE (OUT)
0.2' FENCE (OUT)
0.6' FENCE (OUT)
0.3' FENCE (OUT)
0.2' FENCE (IN)
0.3' FENCE (IN)
0.4' FENCE (IN)
0.4' FENCE (IN)
0.8' FENCE (OUT)
1.0' FENCE (OUT)
0.5' FENCE (OUT)
0.3' FENCE (OUT)
FENCE (OUT)

PARCEL BB
FUTURE PRUITT AVENUE DOC. NO. 2007-127026

PARCEL TWO
27.51 ACRES

SOCO INVESTMENTS
DOC NO 2017-068596
APN 059-271-104

SEE SHEET 5

LEGEND

BOUNDARY LINE
CENTER LINE
EASEMENT
FENCE
FIRE LINE
IRRIGATION LINE
RIGHT OF WAY LINE
SETBACK LINE
SEWER LINE
WATER LINE
FOUND MONUMENT
FOUND WELL MONUMENT AS NOTED
HANDICAP PARKING SPACE
VAULT

AC	ASPHALT CONCRETE
APN	ASSESSOR PARCEL NUMBER
BFP	BACK FLOW PREVENTER
CONC	CONCRETE
DDCV	DOUBLE DETECTOR CHECK VALVE
DOC	DOCUMENT
EBOX	ELECTRICAL BOX
EL	ELECTRICAL
EP	EDGE OF PAVEMENT
EW	EDGE OF WALK
EX	EXISTING
FND	FOUND
FH	FIRE HYDRANT
GTIC	GREASE TRAP INTERCEPTOR
ICB	IRRIGATION CHECK BOX
ICV	IRRIGATION CONTROL VALVE
INFO	IN FAVOR OF
NO	NUMBER
NTS	NOT TO SCALE
OHL	OVERHEAD LINE
POC	POINT OF COMMENCEMENT
POB	POINT OF BEGINNING
PUE	PUBLIC UTILITY EASEMENT
SDDI	STORM DRAIN DROP INLET
SSCO	SANITARY SEWER CLEANOUT
SSMH	SANITARY SEWER MANHOLE
STLT	STREET LIGHT
T	TRASH
TBOX	TELEPHONE BOX
TC	TOP OF CURB
TYP	TYPICAL
WM	WATER METER
WV	WATER VALVE
(IN)	INSIDE BOUNDARY
(OUT)	OUTSIDE BOUNDARY

50 0 50 100
SCALE IN FEET
1" = 50 Ft.

PRELIMINARY
NOT TO BE USED FOR CONSTRUCTION OR FINAL DESIGN PURPOSES
DATE: 12-14-20

ALTA/NSPS LAND TITLE SURVEY
APN 059-271-095
790 SHILOH ROAD

LYING WITHIN SECTION 19, TOWNSHIP 8 NORTH RANGE 9 WEST, M.D.B.&M. AND BEING THE LANDS OF STANDARD STRUCTURES AS DESCRIBED IN DOCUMENT NUMBER 2013-077622, OFFICIAL RECORDS OF SONOMA COUNTY.

COUNTY OF SONOMA, STATE OF CALIFORNIA

Brelje & Race CONSULTING ENGINEERS
475 Aviation Blvd. - Suite 120 - Santa Rosa, CA 95403 - 707 576-1322
www.brce.com

DECEMBER 2020

ALL DISTANCES AND DIMENSIONS ARE GIVEN IN FEET AND DECIMALS THEREOF.

12-14-20 henry \4623\Y\map\4623.01 ALTA.dwg TAB: SHT 4-Site SOSC

SEE SHEET 4

SEE SHEET 6

PARCEL BB
FUTURE PRUITT AVENUE DOC. NO. 2007-127026

0.4' FENCE (IN)

4" W RISER
PIV
PIV
GATE
2" BOLLARD
SLAB
GAS RISERS

SOCO INVESTMENTS
DOC NO 2017-068596
APN 059-271-104

FUTURE PRUITT AVENUE (PRIVATE)

S03°36'07"W 1400.46'

4" BOLLARD (TYP)
SSCO RIM 116.05
3" BOLLARD (TYP. OF 4)
PIV
WM
GATE
BUILDING
UTIL VAULT
ELEC RISER
ELEC VAULT
LIGHTS
4" BOLLARD (TYP. OF 20)
ELEC SLAB

PARCEL THREE
CENTERLINE OF 30' WIDE RAILROAD SPUR & UTILITY ESMT

2" BOLLARD (TYP. OF 4)
PIV
GAS RISER
4" BOLLARD (TYP. OF 3)
WV (TYP. OF 2)
WM

PARCEL FOUR
CENTERLINE OF 20' WIDE RAILROAD SPUR

GAS RISER
PIV
GATE
POST EXIT (TYP. OF 3)
FH
2" BOLLARD
2" BOLLARD

2.4' FENCE (IN)

PARCEL AA
74' WIDE EAST/WEST CONNECTOR DOC NO 2007-127026

HOSE BIB
LIGHT
HOSE BIB
HOSE BIB
HOSE BIB
LIGHT
2"BOLLARD

PARCEL BB
FUTURE PRUITT AVENUE

SOCO INVESTMENTS
DOC NO 2017-068596
APN 059-271-104

PUBLIC TURN AROUND EASEMENT

FND 1/2" IP
RCE 31909

TOWN OF WINDSOR
PER 739 MAPS 40-44
APN 059-271-101

FND 1/2" IP
RCE 31909

N00°37'18"E 290.04'

WINDSOR EXPRESS
DOC NO 2010-073006
APN 059-271-097

PARCEL SIX
8.33 ACRES

EXCEPTION #33
ACCESS & UTILITY EASEMENT
DOC. NO. 1998-0157292

FND 1/2" IP
RCE 31909

N89°37'37"E
1252.08'

PARCEL DD
EVA EASEMENT
DOC NO 1998-0099682

SONOMA COUNTY DAY SCHOOL
DOC NO 2001-142584
APN 059-350-094

PARCEL CC
ACCESS & UTILITY EASEMENT
DOC NO 1998-0099681

PARCEL TWO
27.51 ACRES

2'±
1.0' FENCE
0.9' FENCE (OUT)
S35°15'48"E
2371.08' TOTAL
0.3' FENCE (OUT)
0.8' FENCE (OUT)
WIRE FENCE
1.1' FENCE (OUT)
0.7' FENCE (OUT)
1" RISER

EXCEPTION #14 & 15
RELINQUISHMENT OF ACCESS RIGHTS
BOOK 1748 PAGE 617

EXCEPTION #30
OPEN SPACE
DOC. NO. 1997-0096276

U. S. FREEWAY NO. 101

EXCEPTION #10 & 11
RELINQUISHMENT OF ACCESS RIGHTS
BOOK 1623 PAGE 113

EXCEPTION #30
OPEN SPACE
DOC. NO. 1997-0096276

N35°15'48"W 455.87'

EXCEPTION #12 & 13
RELINQUISHMENT OF ACCESS RIGHTS
BOOK 1620 PAGE 16

PARCEL FIVE
1.14 ACRES

AIRPOT BUSINESS CENTER
DOC NO 1992-046660
APN 059-350-111

267.41'
S89°37'52"E

LEGEND

BOUNDARY LINE	
CENTER LINE	
EASEMENT	
FENCE	X X X
FIRE LINE	F
IRRIGATION LINE	IRR
RIGHT OF WAY LINE	
SETBACK LINE	
SEWER LINE	SS
WATER LINE	W
FOUND MONUMENT	●
FOUND WELL MONUMENT AS NOTED	◉
HANDICAP PARKING SPACE	
VAULT	

AC	ASPHALT CONCRETE
APN	ASSESSOR PARCEL NUMBER
BFP	BACK FLOW PREVENTER
CONC	CONCRETE
DDCV	DOUBLE DETECTOR CHECK VALVE
DOC	DOCUMENT
EBOX	ELECTRICAL BOX
EL	ELECTRICAL
EP	EDGE OF PAVEMENT
EW	EDGE OF WALK
EX	EXISTING
FND	FOUND
FH	FIRE HYDRANT
GTIC	GREASE TRAP INTERCEPTOR
ICB	IRRIGATION CHECK BOX
ICV	IRRIGATION CONTROL VALVE
INFO	IN FAVOR OF
NO	NUMBER
NTS	NOT TO SCALE
OHL	OVERHEAD LINE
POC	POINT OF COMMENCEMENT
POB	POINT OF BEGINNING
PUE	PUBLIC UTILITY EASEMENT
SDDI	STORM DRAIN DROP INLET
SSCO	SANITARY SEWER CLEANOUT
SSMH	SANITARY SEWER MANHOLE
STLT	STREET LIGHT
T	TRASH
TBOX	TELEPHONE BOX
TC	TOP OF CURB
TYP	TYPICAL
WM	WATER METER
WV	WATER VALVE
(IN)	INSIDE BOUNDARY
(OUT)	OUTSIDE BOUNDARY

PRELIMINARY
NOT FOR CONSTRUCTION OR RECORDATION
FOR REVIEW PURPOSES ONLY
DATE 12-14-20

N

50 0 50 100
SCALE IN FEET
1" = 50 Ft.

ALTA/NSPS LAND TITLE SURVEY
APN 059-271-095
790 SHILOH ROAD

LYING WITHIN SECTION 19, TOWNSHIP 8 NORTH RANGE 9 WEST, M.D.B.&M. AND BEING THE LANDS OF STANDARD STRUCTURES AS DESCRIBED IN DOCUMENT NUMBER 2013-077622, OFFICIAL RECORDS OF SONOMA COUNTY.

COUNTY OF SONOMA, STATE OF CALIFORNIA

Brelje & Race
CONSULTING ENGINEERS
475 Aviation Blvd. • Suite 130 • Santa Rosa, CA 95403 • 707.576.1322
www.brce.com

DECEMBER 2020

ALL DISTANCES AND DIMENSIONS ARE GIVEN IN FEET AND DECIMALS THEREOF.

12-14-20 henry \4623\map\4623.01 ALTA.dwg TAB: SHT 5-Site SOSC

LEGEND

BOUNDARY LINE
CENTER LINE
EASEMENT
FENCE — X — X — X —
FIRE LINE — F — F —
IRRIGATION LINE — IRR — IRR —
RIGHT OF WAY LINE
SETBACK LINE
SEWER LINE — SS — SS —
WATER LINE — W — W —
FOUND MONUMENT ●
FOUND WELL MONUMENT AS NOTED ◉
HANDICAP PARKING SPACE
VAULT

AC	ASPHALT CONCRETE
APN	ASSESSOR PARCEL NUMBER
BFP	BACK FLOW PREVENTER
CONC	CONCRETE
DDCV	DOUBLE DETECTOR CHECK VALVE
DOC	DOCUMENT
EBOX	ELECTRICAL BOX
EL	ELECTRICAL
EP	EDGE OF PAVEMENT
EW	EDGE OF WALK
EX	EXISTING
FND	FOUND
FH	FIRE HYDRANT
GTIC	GREASE TRAP INTERCEPTOR
ICB	IRRIGATION CHECK BOX
ICV	IRRIGATION CONTROL VALVE
INFO	IN FAVOR OF
NO	NUMBER
NTS	NOT TO SCALE
OHL	OVERHEAD LINE
POC	POINT OF COMMENCEMENT
POB	POINT OF BEGINNING
PUE	PUBLIC UTILITY EASEMENT
SDDI	STORM DRAIN DROP INLET
SSCO	SANITARY SEWER CLEANOUT
SSMH	SANITARY SEWER MANHOLE
STLT	STREET LIGHT
T	TRASH
TBOX	TELEPHONE BOX
TC	TOP OF CURB
TYP	TYPICAL
WM	WATER METER
WV	WATER VALVE
(IN)	INSIDE BOUNDARY
(OUT)	OUTSIDE BOUNDARY

PRELIMINARY
NOT FOR CONSTRUCTION
FOR REVIEW ONLY
DATE 12-14-20

SHILOH GROUP LLC
DOC NO 1987-070364
APN 059-271-105

TOWN OF WINDSOR
DOC NO 2008-107978
APN 059-271-102

NEW SHILOH
APN 059-271-103

SOCO INVESTMENTS
DOC NO 2017-068596
APN 059-271-104

PARCEL THREE
CENTERLINE OF 30' WIDE RAILROAD SPUR AND UTILITIES EASEMENT BOOK 2332 PAGE 180

PARCEL AA
74' WIDE EAST/WEST CONNECTOR
DOC NO 2007-127026

SONOMA MARIN AREA RAIL TRANSIT

CALETTI AVENUE (PUBLIC)

PARCEL FOUR
CENTERLINE OF 20' WIDE RAILROAD SPUR

EXCEPTION #20
30' EASEMENT FOR RIGHT OF WAY AND RAILROAD PURPOSES BOOK 2668 PAGE 495

20' EVA 716 MAPS 1-4

WILDEASL LLC
DOC NO 2015-023581
APN 059-271-098

SOCO INVESTMENTS
DOC NO 2017-068596
APN 059-271-104

N

50 0 50 100
SCALE IN FEET
1" = 50 Ft.

ALL DISTANCES AND DIMENSIONS ARE GIVEN IN FEET AND DECIMALS THEREOF.

AVENUE DOC. NO. 2007-127026
0.4' FENCE (IN)
4" W RISER
PIV
GATE
SLAB
4" BOLLARD (TYP OF 2)
GAS RISERS
FH
SSCO RIM 116.05
3" BOLLARD (TYP OF 4)
S00°26'07"W 1450.46'
WV
GAS
FUTURE PRUITT AVENUE (PRIVATE)
UTIL VAULT
ELEC RISER
BUILDING
JP
JP DOOR
ELEC VAULT
LIGHT
4" BOLLARD (TYP OF 20)
ELEC SLAB
2" BOLLARD (TYP OF 4)
GATE
PIV
GAS RISER
4" BOLLARD (TYP OF 3)
2" BOLLARD (TYP OF 3)
WV
FH
GAS RISER
PIV
GATE
POST BX6 (TYP OF 3)
FH
2" BOLLARD
2" BOLLARD
2.4' FENCE (IN)
HOSE BIB
LIGHT
HOSE BIB
HOSE BIB
HOSE BIB
LIGHT
2" BOLLARD

PARCEL BB
FUTURE PRUITT AVENUE

PUBLIC TURN AROUND EASEMENT
FND 1/2" IP RCE 31909

SEE SHEET 5

ALTA/NSPS LAND TITLE SURVEY
APN 059-271-095
790 SHILOH ROAD


LYING WITHIN SECTION 19, TOWNSHIP 8 NORTH RANGE 9 WEST, M.D.B.&M. AND BEING THE LANDS OF STANDARD STRUCTURES AS DESCRIBED IN DOCUMENT NUMBER 2013-077622, OFFICIAL RECORDS OF SONOMA COUNTY.

COUNTY OF SONOMA, STATE OF CALIFORNIA

Brelje & Race
CONSULTING ENGINEERS
475 Aviation Blvd. • Suite 120 • Santa Rosa, CA 95403 • 707-575-1322
www.brce.com

DECEMBER 2020

TAB: SHT 6-Site 505C
12-14-20 henry \4623\mcp\4623.01 ALTA.dwg


SSESSOR'S PARCEL MAP
TAX RATE AREA
9-023 9-024 9-032
120-002 120-009 120-01
120-018 120-03
SHILOH ROAD
CALIF. COORD. ZONE 2
DETAIL "A"
± 30.84 ac.
R/S 461/20
PM05-24
LS 936
R/S 381-39/40
14.02 Ac.
271
Lot 3
30.67 Ac.
SOCO.
1.63 Ac.
1.61 Ac.
Lot 2
Pcl A
120-032
A.C.C.V
Lot 1
6.92 Ac.
PM96-4
6.73 Ac.
7.23 Ac.
5.57 Ac.
6.05 Ac.
6.13 Ac.
3.87 Ac.
Lot 2
Lot 3
PM99-11
R/S 455/13
12.92 Ac.
7.28 Ac.
± 24.89 Ac.
12.31 Ac.
43.18 Ac
45.09 Ac.
R/S 279-10
R/S 285-47
Ag. Pres. 1-233
91-17635
19.53 Ac
9-023
120-018
120-009
R/S 210/44
AVIATION
BLVD.
AIRPORT
CORPORATE
CENTER
I
CONCOURSE
AIRPORT
HARBOUR
120-002
120-018
9-024
Assessor's Ma
Sonoma C
HYBRID

HURVITZ ENVIRONMENTAL

GEOLOGIC & ENVIRONMENTAL CONSULTING

PHASE I ENVIRONMENTAL SITE ASSESSMENT

Standard Industrial – 5900 Pruitt Avenue
Windsor, California

PREPARED FOR:

Currie Properties
P.O. Box 9361, San Rafael, Ca. 94912
San Rafael, CA

March 29, 2013

PREPARED BY:

HURVITZ ENVIRONMENTAL SERVICES INC.
105 Morris Street, Suite 188
Sebastopol, California 95472



Lee S. Hurvitz, PG # 7573
Principal Geologist

PROJECT NO. 3062.01

This Report is for the exclusive use of Currie Properties, his affiliates, designates and assignees, and no other party shall have any right to rely on any service provided by Hurvitz Environmental Services without prior written consent.

March 29, 2013
Currie Properties
P.O. Box 9361
San Rafael, CA

RE: Phase I Environmental Site Assessment
5885, 5887, 5891, 5895, 5900, 5937 Pruitt Avenue & 920 Shiloh Road
APN#'s 059-271-104, 059-271-098, 059-271-095, 059-271-082
Windsor, California
Project No. 3062.01

Dear Currie Properties:

Hurvitz Environmental Services Inc. (HES) is pleased to submit this Phase I Environmental Site Assessment (ESA) report for the above referenced property (the subject site). The primary objective of this ESA was to identify **recognized environmental conditions** in connection with the subject property. Recognized environmental conditions are defined as the presence or likely presence of any hazardous substances or petroleum products on a property under conditions that indicate an existing release, a past release, or a material threat of a release of any hazardous substances or petroleum products into structures on the property or into the ground, ground water, or surface water of the property.

This ESA was conducted in accordance with the E 1527-05 ASTM document entitled "Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment (ESA) Process" for commercial real estate, published November 2005. HES performed this ESA with the Best Practices and Highest Professional Standards currently employed by environmental professionals and has followed the Scope of Work outlined in our Proposal, dated February 26, 2013.

We appreciate the opportunity to provide you with these services. Please do not hesitate to contact us at your convenience, should have any questions or comments regarding this report or our recommendations.

Sincerely,
HURVITZ ENVIRONMENTAL SERVICES

Lee S. Hurvitz, PG# 7573
Principal Geologist

TABLE OF CONTENTS

LETTER OF TRANSMITTAL ii

EXECUTIVE SUMMARY **1**

1.0 INTRODUCTION AND SCOPE OF SERVICES **6**

2.0 PROPERTY DESCRIPTION **8**

2.1 Site Description 8
2.2 Site Hydrogeology 10

3.0 HISTORICAL RECORDS REVIEW **12**

3.1 Prior Ownership and Site Land Use 12
3.2 Valuation Reduction for Environmental Issues 13
3.3 Sanborn Fire Insurance Maps 13
3.4 U.S.G.S. 7.5-Minute Quadrangle Maps (Topographic Maps) 13
3.5 Aerial Photography 14
3.6 City Directories 15

4.0 REGULATORY AGENCY RECORDS SEARCH **16**

4.1 Federal Regulatory Records 18
4.2 State Regulatory Records 22
4.3 State and Local Agency File Reviews 36

5.0 ON-SITE ENVIRONMENTAL ASSESSMENT **39**

5.1 Underground Storage Tanks (USTs) 39
5.2 Aboveground Storage Tanks (ASTs) 39
5.3 Hazardous Material Storage 39
5.4 Solid (Non-Hazardous) Waste 39
5.5 Hazardous Waste 40
5.6 Polychlorinated Biphenyls (PCBs) Containing Equipment 40
5.7 Water/Storm Water/Wetlands/Wells 40
5.8 Air Emissions 41
5.9 Dry Cleaning Operations 41
5.10 Asbestos 41
5.11 Lead Based Paint 42
5.11 Radon Information 42

6.0 REVIEW OF NEARBY/ADJACENT PROPERTIES **43**

7.0 DATA GAPS **43**

8.0 DISCUSSION OF FINDINGS **44**

8.1 Major Findings 46
8.2 Conclusions 48

FIGURES

PLATE 1 – SITE VICINITY

PLATE 2 – SITE PLAN

PLATE 3 - ASSESSORS PARCEL MAP

APPENDICES

APPENDIX A: **STAFF QUALIFICATIONS**

APPENDIX B: **PHOTOGRAPHIC LOG**

APPENDIX C: **KNOWLEDGEABLE PERSONS INTERVIEWS**

APPENDIX D: **CHAIN-OF-TITLE REPORT**

APPENDIX E: **HISTORICAL MAPS, AERIAL PHOTOGRAPHS AND OTHER HISTORICAL DOCUMENTATION**

APPENDIX F: **ENVIRONMENTAL DATA RESOURCES REGULATORY DATABASE SEARCH REPORT**

APPENDIX G: **REGULATORY AGENCY FILE REVIEW DOCUMENTATION**

APPENDIX H: **LIST OF CURRENT PROPERTY TENANTS**

EXECUTIVE SUMMARY

Hurvitz Environmental Services performed a Phase I Environmental Site Assessment for the Standard Industrial property located at 5900 Pruitt Avenue in Windsor, CA. Additional addresses associated with the subject property include 5885, 5887, 5891, 5895 and 5937 Pruitt Avenue, as well as 920 Shiloh Road and 340 Standard Avenue. The site consists of four (4) contiguous parcels which create an irregularly shaped, approximately 88-acre property located on the south side of Shiloh Road and immediately west of State Highway 101. The Assessors Parcel numbers (APN) are as follows 059-271-082, 059-271-095, 059-271-098, 059-271-104.

The Standard Industrial site is currently utilized by several light industrial and manufacturing businesses. A complete list of the current tenants is attached in APPENDIX H. A large portion of the subject property was first developed in the late 1950's by Fluor Corporation as an engineered wood product manufacturing facility. Since 1972, the subject site has been occupied by Standard Structures Inc. (SSI). SSI owned and operated a laminated wood beam manufacturing facility at the site from 1972 to 2012. Although SSI is no longer in business, the former business owner, Mr. Richard Caletti, is still an owner of the property.

According to a Site Screening performed at the site in 1991 by Ecology and Environment Inc, two (2) glue waste water settling ponds previously existed at the northwest end of the site. The North Coast Regional Water Quality Control Board (NCRWQCB) issued the facility waste discharge requirements under order # 74-83 in 1974 which prohibited the drainage of glue waste to any holding or disposal pond. SSI eliminated the use of the ponds at that time and added a decorative pond adjacent to the State Highway 101. In 1980, the NCRWQCB observed glue wastes being dumped into the on-site decorative pond. The pond and adjacent Pruitt Creek were sampled by the NCRWQCB on October 27, 1980. Phenol was present in the pond water and phenolic compounds were present in the pond soil. As a result the NCRWQCB issued a Cleanup and Abatement Order (CAO) No 80-190 to the facility on October 1, 1980 to abate waste discharge to the pond and to remove the pond waste and close the pond. On June 3, 1981, the NCRWQCB rescinded the CAO under Order No. 81-140 because all cleanup and abatement activities were completed and had been assessed.

In January 1990, under the authority of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 (CERCLA) and the Superfund Amendments and Reauthorization Act of 1986 (SARA) the US Environmental Protection Agency (EPA) tasked Ecology and Environment, Inc's Field Investigation Team (FIT) to conduct a Screening Site Inspection of the Standard Structures site. During the Site Screening soil and groundwater samples were collected. The sample results were found to be inconclusive and the final assessment concluded that further assessment was unnecessary. However, in 1991, the EPA revised the Hazard Ranking System (HRS) and asked Ecology and Environment Inc., to re-assess the Standard Structures Site. The site re-assessment concluded that no further remedial action was to be planned under CERCLA. The basis for the assessment stated that the predominant hazardous substances utilized at SSI were phenol, resorcinol, methylene chloride, and paraformaldehyde, which all have low toxicity values (See FIT Report APPENDIX G). In addition an observed release to groundwater had not been documented at the site.

Since the mid1990's, the site operated under an industrial storm-water permit. The site utilizes an oil water separator near the vehicle maintenance area that separates the oil from the water before it is discharged. The permit called for periodic sampling at two (2) storm-water discharge points on the property. No significant contaminant detection occurred during the storm-water sampling events.

The site also has two (2) active 1,000-gallon above ground storage tanks (AST's) used to store gasoline and diesel fuel. The AST's are permitted and have a secondary containment system. There is also waste oil storage on the property within a contained and well maintained area. No significant hazardous material related violations were identified during our review of site inspection reports from local hazardous material inspectors.

An irrigation well exists on the subject site and was formerly used to fill a fire suppression pond on the property. The site is connected to Windsor Town Water and the well is currently out of use. In addition, a private sewage disposal system consisting of several septic tanks and two (2) sewage evaporation ponds formerly existed on the site. The ponds and tanks were abandoned once the Town of Windsor sewer service was provided to the site.

The adjacent property to the west is currently undergoing active remediation for activities related to Ecodyne Corporation wood treatment facility that formerly operated there. The facility has been divided into two (2) separate investigations in which one is regulated by the NCRWQCB and the other is regulated by the Department of Toxic Substance Control (DTSC). Ecodyne is the main responsible party identified for the investigation and cleanup. The contamination at the site has affected both soil and groundwater and consists primarily of Chromium VI, pentachlorophenol and polynuclear aromatic hydrocarbon (PAH's). The contamination at this site appears to be well contained and the local groundwater flow direction is away from the subject site. Although the potential for the former Ecodyne site to affect the subject property is considered low, previous use of the subject site's irrigation well may potentially have pulled Ecodyne related contaminants onto the site.

MAJOR FINDINGS

- The site was utilized for grazing land in the 1940's and early 1950's. Site development began in the mid to late 1950's and the site was utilized at that time for manufacturing engineered wood beams. Standard Structures Inc. (SSI) took over the site in 1972 and continued with the manufacture of glue laminated wood trusses. Additional development of the site occurred 1978. SSI operated there manufacturing business at the site until 2012. The site is currently utilized by several light industrial and manufacturing businesses who lease space at the former SSI facility.
- In 1990 and 1991, the site was investigated for glue waste being discharged to a surface pond on lot 059-271-095. Soil and water testing was performed and the Environmental Protection Agency (EPA) recommended no further action at the site.
- Review of regulatory agency files indicates that there is documented storage and handling of hazardous materials at the site. We did not find any evidence in the regulatory agency files reviewed that there has been mishandling of the hazardous materials onsite that would require a soil or groundwater investigation.
- Two (2) 1,000-gallon, fuel AST's exist on the subject property. The AST's contain gas and diesel and are located near the southwest corner of lot 059-271-104. Secondary spill containment is provided for the AST's and no evidence of a release was observed during our site inspection. Also, the Sonoma County Dept. of Emergency Services inspection records do not indicate any AST violations.
- The site was formerly serviced by onsite sewage disposal system that consisted of several septic tanks and two (2) sewage evaporation ponds. The site has since been connected to city sewer and water service and the sewage ponds have been abandoned.
- There is an irrigation well located on the lot 059-271-104. The irrigation well is currently out of use but was formerly used to fill the fire suppression ponds onsite.
- Several nearby sites were identified on the EDR Database Report to have ongoing investigations. While most of the sites are hydrologically down-gradient from the subject property there are adjacent sites that could pose a potential concern to the subject property. The former Ecodyne wood treatment plant is located to the west of the site and has an ongoing investigation and cleanup related to chromium VI and PAH's. The former Ecodyne site has been divided into several industrial lots that are rented to various industrial and manufacturing businesses. These businesses have included trucking companies, metal recyclers, steal tank manufacturing, battery storage facilities and commercial landscape operations among others. Some of these businesses have also been identified on various environmental agency databases.
- SSI operated an industrial storm water permit for 14 years that included managing runoff and performing testing from two (2) designated run-off areas. No significant contaminant detections were made during the sampling period.
- There is an oil water separator on the west side of lot 059-271-104. The oil water separator was managed by SSI and waste was reportedly picked up and disposed of as needed by Evergreen Environmental.
- No landfills or hazardous material disposal areas have been identified on the subject site.

Onsite Concerns**:**

The following onsite concerns have been identified at the subject property.

- While no significant evidence of site contamination has been identified, the site has had a long history of hazardous chemical usage and storage as well as former glue evaporation ponds that contained paraformaldehyde and phenols.
- An onsite irrigation well as historically been used at the site and several nearby sites have been identified with impacted groundwater. Therefore, the potential for off-site contamination to be drawn-in from adjacent facilities exists.

Mitigation for Onsite Concerns

In order to determine if past chemical storage, usage, or disposal has contaminated groundwater and to determine if the former use of the onsite irrigation well has lead to the impact of groundwater at the subject property from adjacent properties, we recommend that the onsite well be tested. The well should be tested for chemicals that were formerly used on the subject property and for chemicals identified in nearby groundwater investigation. These chemicals include, paraformadehyde, phenol, PAH's, diesel, gasoline, motor oil, lead, and chromium VI.

Off-Site Concerns**:**

Regulatory agency records reviewed for this ESA indicate that hazardous material releases mainly associated with petroleum hydrocarbons have occurred at several nearby locations. At most locations the contaminant source areas have been defined and remedial efforts are underway, ongoing, or completed. However, one (1) former wood treatment facility has been identified adjacent to the west of the subject site. The Ecodyne site is currently being investigated for Chromium VI and PAH contamination and the effected groundwater in the immediate area. The NCRWQCB and the DTSC are over-seeing the investigations and remediation at this former wood treatment facility. The groundwater flow at this site is southwesterly and away from the subject site. However, since the subject property operated an irrigation well at the site for many years it is possible that the well has drawn-in contamination from the former Ecodyne facility or other near-site petroleum contaminated sites.

Mitigation for Off-Site Concerns

In order to determine if off-site contamination has been drawn-in to the subject property through the former use of the onsite irrigation we recommend that the well be sampled and analyzed for off-site chemical concerns. These chemical include Chromium VI and PAH's.

Data Gaps

A fifty-Year Chain of Title was not reviewed for this ESA. Based on the other historical information available for the site and current owners length of ownership (40+ years) this data gap is not considered a concern to the investigation.

Conclusions and Recommendations

By definition the former glue evaporation ponds on the subject property are considered a recognized environmental condition (REC) however based on the results of the EPA investigation they are not considered a concern to this investigation. The site has also had a long history of hazardous material usage and storage activities, however, there has not been any indication that a significant release to the environment has occurred from these practices. Several off-site contaminant investigations have been identified proximate to the subject property. These sites are discussed in section 4.1 and 4.2 of this report. In general, these sites are not considered a threat to the subject property however there is some potential that the former irrigation well used at the subject site may have draw-in contaminants from these nearby sites. Therefore, we recommend that that the former irrigation well be tested for the glue related chemicals formerly used onsite, and for the chemicals identified in the near-site contaminant investigations.

These findings and all information provided in this report are subject to limitations defined in Section 9 of this report. This report and the interpretations, conclusions, and recommendations contained within are based in part on information presented in other documents that are cited in the text or listed as references. Therefore, this report is also subject to the limitations and qualifications presented in the referenced documents.

1.0 INTRODUCTION AND SCOPE OF SERVICES

On March 4, 2013 Hurvitz Environmental Services (HES) was contracted by Currie Properties to conduct a Phase I Environmental Site Assessment (ESA) of the property known as Standard Industrial located at 5885, 5887, 5891, 5895, 5900 and 5937 Pruitt Avenue (PLATE 1 – Site Vicinity). It is our understanding that additional addresses have been associated with the property in the past. The additional addresses include 920 Shiloh Road, 340 Standard Avenue and 360 Standard Avenue. It is our understanding that Currie Properties has requested this Phase I ESA since he plans to purchase a stake in the subject property.

HES conducted the ESA in accordance with the E 1527-05 ASTM document entitled "Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process" for commercial real estate, published November 2005. This ESA followed the Scope of Work outlined in the HES Proposal dated February 25, 2013.

According to ASTM E1527-05, the purpose of this practice is to define good commercial and customary practice in the United States of America for conducting an ESA of a commercial real estate parcel with respect to the range of contaminants within the scope of the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) (*42 U.S.C. §9601*), and petroleum products. As such, this practice is intended to permit a user to satisfy one of the requirements to qualify for the innocent landowner, contiguous property owner, or bona fide prospective purchaser limitation on CERCLA liability (i.e., landowner liability protections): that is, the practice that constitutes "all appropriate inquiry into the previous ownership and uses of the property consistent with good commercial or customary practice" as defined at *42 U.S.C. §9601(35) (B*).

The primary objective of this ESA was to identify **recognized environmental conditions** in connection with the subject property. Recognized environmental conditions are defined as the presence or likely presence of any hazardous substances or petroleum products on a property under conditions that indicate an existing release, a past release, or a material threat of a release of any hazardous substances or petroleum products into structures on the property or into the ground, ground water, or surface water of the property.

In accordance with the above-referenced agreement, HES performed a visual reconnaissance of the site, noted use of adjacent properties, and conducted historical and regulatory records research. The following provides a more detailed description of the scope of services:

- Visual inspection of the site buildings and grounds to identify potential for on-site hazardous substances or petroleum product release(s).

- Visual inspection of the site to confirm the presence or absence of on-site Polychlorinated Biphenyl's (PCBs).

- Visual inspection and categorization of the use of adjacent and nearby properties as potential off-site sources of contamination.

- Review of local records related to historical ownership, usage and site development.

- Interview local environmental authorities to identify complaints, violations, citations, or inspections related to the site.

- Interview current and previous property owners and/or site managers regarding their specialized knowledge of site history, and current land use.

- Review of published Federal, State and local agency databases and records related to on-site activities and potential off-site use, storage or release of hazardous substances or petroleum products.

- Review readily available historic site documents to assess the potential for on-site sources of hazardous substances or petroleum products.

- Review of readily available aerial photographs of the site and site vicinity to evaluate present and historical development, facility operations, and land use.

- Review readily available plans and documents relative to construction materials utilized at the site and historical renovation activities.

- Visual inspection of the interior and exterior of site structures to determine the potential presence or absence of suspect Asbestos Containing Materials (ACMs).

- Preparation of a Phase I Environmental Site Assessment Report.

This Phase I ESA was conducted under the supervision or responsible charge of an environmental professional with oversight from the undersigned HES registered professional. The work was conducted in accordance with ASTM E1527-05, generally accepted industry standards for environmental due diligence in place at the time of the preparation of this report, and according to HES quality-control policies.

We declare that, to the best of our professional knowledge and belief, we meet the definition of environmental professional as defined in §312.10 of 40 CFR 312 and we have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject property (APPENDIX A**)**. We have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.

2.0 PROPERTY DESCRIPTION

HES performed a Phase I Environmental Site Assessment at Standard Industrial located at 5900 Pruitt Avenue in Windsor, California (PLATE 1**)**. HES project manager, Mr. Lee S. Hurvitz, conducted a site inspection on March 12, 2013. During the March 12, 2013 site inspection, the weather was overcast and cool with temperatures at approximately 60 degrees Fahrenheit.

The Sonoma County Assessor's Office identified the site as Parcel Nos. 059-271-**104**, 059-271-**098**, 059-271-**095**, 059-271-**082**. For the purpose of this ESA we will refer to the parcels or lots by the last three digits of the Assessor's Parcel Number (APN). The Preliminary Title Report [1] identified the parcel addresses as 5885, 5887, 5891, 5895, 5900 and 5937 Pruitt Avenue, Windsor, CA. The zoning for subject property is listed as light manufacturing / heavy industrial/ light industrial and includes 88.68 acres.

2.1 Site Description

The subject site consists of four (4) contiguous parcels (lots 82, 95, 98, and 104) which create an irregularly shaped, approximately 89-acre property. The subject site is located on the south side of Shiloh Road just west of the California State Highway 101. A description of each lot is presented below.

APN# 059-271-104

The site has historically been occupied by the Standard Structures Inc (SSI). The parcel was formerly identified as APN # 059-271-038 and 059-271-056. Standard Structures occupied the facility from approximately 1972 to 2012. The site was originally developed in the 1950's by Flour Corporation but was expanded upon by SSI in the late 1970's. The site is improved with one (1) main building, two (2) smaller drying sheds, a building with a drying kiln, one (1) firewater pond, and two (2) smaller tenant occupied buildings. The total parcel size is 30.67 acres. The ground floor area of the two-story main manufacturing building for the former SSI is approximately 200,000 sq/ft. The building has wood frame construction with open sides and galvanized sheet metal exterior. The majority of the building was used for manufacturing operations and there are several small interior offices and machine shop areas. The building is surrounded by asphalt on the north, south, and east sides with a gravel road on the west side of the building. The Northwest Pacific Railroad tracks border the site to the southwest and there are two (2) railroad spurs from these tracks that enter onto the subject property. The main SSI building is currently divided and used for various light industrial operations including soil mixing, tile manufacturing, and vehicle maintenance. A list of current property tenants is provided in APPENDIX H. The northeastern portion of this lot is occupied by Northgate Redi-Mix which operates a cement plant at the site. The Redi-Mix plant has one office building and several modular offices are located adjacent to the Redi-Mix plant.

[1] Preliminary Title Report, Fidelity National Title Company, APN #'s 059-271-082; 059-271-095, Windsor, CA, dated May 4, 2013.

Parcel 104 is connected to Windsor City water and sewer. An irrigation well exists on the property but is currently not operational. Historical waste water was collected in on-site septic tanks and piped to two (2) sewer evaporation ponds. The ponds have since been abandoned. A site map is included as PLATE 2 and site photographs are presented in APPENDIX C.

APN# 059-271-098

This site has historically been operated as part of the SSI site and was the former home of Mead Clark Lumber. The total property size is 6.51 acres. Current property tenants include Guy's Fencing, Zanoni, Natural Dreams, PAR Electric, SR Towing, Image Tree Service, and Charter Peterbuilt. The site is portioned into several equipment yards and the main building on the site is used by PAR Electric and was the former location of the Mead Clark Lumber office. The ground surface on this site is covered with asphalt and the site is serviced by Windsor City water and sewer. No domestic wells or private sewage disposal systems exist on this site. The site is bordered to the west by Northwest Pacific Railroad tracks. A site map is included as PLATE 2 and site photographs are presented in APPENDIX C.

APN# 059-271-095

This parcel has historically been developed and operated by SSI. The total property size is 45.09 acres and has been developed with one building totaling approximately 46,000 square feet. The building was originally constructed in 1978 and was used by SSI in the manufacture of glue laminated trusses for construction. The building contained machinery that during the time of inspection was being removed by an out-of-state company for re-use at another manufacturing facility. The west, south, and north sides of the building are paved with asphalt and the east portion of the site is unpaved. The California Highway 101 borders this parcel to the east and vacant land borders the parcel to the south. Parcel 104 borders this site to the west and Shiloh Road borders the parcel to the north. This parcel once contained an evaporation pond that was used for glue settling in the 1970's. The pond was subsequently abandoned in 1980-81 under oversight from the North Coast Regional Water Quality Control Board (NCRWQCB). A site map is included as PLATE 2 and site photographs are presented in APPENDIX C.

This lot is serviced by Windsor City water and sewer and no domestic water supply wells or private sewage disposal systems were identified. Historically, this lot was connected to the on-site sewage disposal ponds that formerly existed on parcel 104.

APN# 059-271-082

This parcel consists of 4.10 acres and is developed with four (4) structures. The buildings are used primarily as office space. The first building on the parcel was constructed in 1965 and the last building in 1985. The total building square footage is approximately 12,000 sq/ft. The western most structure consists of a modular type building and totals approximately 6,000 sq/ft. The northern most structure is a dome type building made from custom trusses built by SSI. The building is vacant and consists of approximately 2,000 sq/ft. The southern-most building is a two story shake building totaling approximately 3,000 sq/ft. The eastern most building is a storage shed type structure with exterior wood shake details that total less than 1,000 sq/ft. In

addition to the structures, there is a storage yard on the eastern portion of the site where landscape type equipment is currently stored. The property was originally developed by Speedspace in 1965. Standard Structures took over ownership and occupancy in 1971. The property is bordered by parcel **095** and Shiloh Road to the north, California State Highway 101 to the east, Pruitt Avenue to the south, and Caletti Lane to the west. Pruitt Creek also borders this parcel to the north and generally signifies the boundary between lots **082** and **095.**

2.2 Site Hydrogeology

The latest United States Geological Survey (USGS) 7.5-minute topographic map depicting the location of the site was obtained and reviewed. The location of the site is shown on the 1993 USGS, Healdsburg California quadrangle map. According to the contour lines on the topographic map, the site is located at an average elevation of approximately 117 ft above mean sea level (MSL). Topography in the vicinity of the site is relatively flat with a very gradual southerly slope.

According to the Federal Emergency Management Agency (FEMA), Federal Insurance Rate Map (FIRM) 06097C, dated December 2, 2008 the site is located outside of the 100-year Flood Zone and within the 500-Year Flood Zone. According to the 2002 National Wetlands Inventory and the 2005 U.S. Fish and Wildlife Service database (EDR Radius Map Report) the site is not located within a designated wetland area.

The U.S. Department of Agriculture's Soil Conservation Service is responsible for collecting, storing, maintaining, and distributing soil survey information. Based on review of the soil maps prepared by the Soil Conservation Service provided in the attached EDR Report, the soils at the subject property are classified as the Huichica soil type; Huichica soils generally consist of silt and clay to a depth of at least three (3) ft below grade. The soils are further defined as having very slow infiltration rates, a high water table, and are shallow to an impervious layer. The southern portions of the site may also contain soils from the Clearlake group. The Clearlake soils have very slow infiltration rates. The soils are clayey, have a high water table, or are shallow to an impervious layer.

The site is located in the northern part of the center portion of the Santa Rosa Plain. Published geologic data indicate that the site is underlain by Quaternary alluvial deposits which consist of stream channel deposits, stream terrace deposits, alluvial fan deposits, and flood plain deposits. The principal water bearing units of the Santa Rosa Plain consist of the Pliocene and Pleistocene Glen Ellen Formation and younger alluvium. The stratigraphy of the Glen Ellen Formation is typically semi-consolidated sand, gravel and minor inter-bedded volcanic tuff and the alluvial fan deposits, typically composed of lenticular sand units interspersed in fine-grained silts and clays. Groundwater in both deposits is generally either unconfined or semi-confined. The depth of the alluvium in the vicinity of the subject property can reach depths of 100 ft.

The most obvious hydraulic influences on the direction of regional groundwater flow on the Santa Rosa Plain are associated with the Sonoma Mountains to the east and the Russian River to the west. Regional groundwater data from the California Department of Water Resources Bulletin 118-4 and the United States Geological Survey Water Supply Paper 1427 show that the shallow groundwater flow direction has a southwesterly to north-northwesterly orientation

at various times during the studies in the vicinity of the subject site. Regional groundwater in the Santa Rosa Plain has a very shallow gradient, and the movement of groundwater is typically slow. Gradients can change in orientation on a seasonal basis. Groundwater use in the Santa Rosa plain is high. Groundwater flow directions may also be influenced by nearby, high volume production wells. The depth to groundwater in the vicinity of the subject property has been reported in the referenced material to be approximately 15 ft below the existing surface grade.

3.0 HISTORICAL RECORDS REVIEW

Past land use at the subject site was investigated to identify historical practices or conditions that may have impacted the subject site. Several property disclosure documents were reviewed including two (2) Phase I Environmental Site Assessments[2] provided to HES by Mr. Richard Caletti for the current 104 and 098 parcels. HES also interviewed knowledgeable persons regarding the subject property including the current owner or operators knowledgeable about former site operation including, Mr. Richard Caletti (current owner and/or partner of all parcels in question), and Mr. Phil Wright (Real Estate Agent for Currie Properties, perspective buyer), the notes from the interviews are attached in APPENDIX D. Based on the records review and interview process we have presented a historical overview of the sites environmental and development history.

3.1 Prior Ownership and Site Land Use

HES reviewed a Preliminary Title Report[3] for lots 82 and 95 provided by Mr. Phil Wright (APPENDIX E**)**. The Title Report indicates that Richard Caletti is the current owner of the property. We also understand that Mr. Caletti is part of the ownership group that owns lots 104 and 098. Mr. Caletti was interviewed as part of this Phase I ESA.

On March 12, 2013 HES staff interviewed Mr. Richard Caletti, regarding the past use of the property. Mr. Caletti indicated that he originally purchased the property in 1972 and was also the owner of Standard Structure Inc. which operated at the site. The previous owner/ tenant was Fluor Products which was also a wood beam manufacturer. HES questioned Mr. Caletti about his knowledge of hazardous material usage and storage on the subject property. Mr. Caletti indicated that the former glue evaporation pond on lot 95 was investigated and closed by the NCRWQCB and that after that the facility began to dry the glue waste and dispose of it as non-hazardous at the Sonoma County Landfill. This practice was reportedly acceptable to the local regulatory agencies. Mr. Caletti indicated that the site operated two (2) permitted AST's that contain gasoline and diesel. Mr. Caletti also indicated that the site is serviced by Windsor City water and sewer but that an irrigation well and sewage evaporation pond once existed at the site. The ponds were abandoned when the city provided sewer service and the well use was also discontinued around the same time. Mr. Caletti indicated that SSI closed in 2012 and that the former SSI buildings have been divided and leased to various light industrial and manufacturing tenants. A tenant list was provided by Mr. Caletti and is attached in APPENDIX A. Mr. Caletti was not aware of any or illegal dumping areas on the property.

HES also reviewed historical city directories, historical topographic maps, Sanborn Fire Insurance Maps, and aerial photographs provided by EDR which are attached in APPENDIX E.

---

[2] Phase I Environmental Site Assessment Report, Standard Structures Property, 920 Shiloh Road Windsor, CA, prepared by National Assessment Corporation, dated September 23, 1999. Phase I Environmental Site Assessment, Standard Structures Inc., 340 Standard Avenue (APNs 59-271-31, -32, and -38) Windsor, CA, prepared by BACE Environmental, dated February 2, 1996.

[3] Preliminary Title Report, Fidelity National Title Company for APN # 059-271-082; 059-271-095, Windsor, CA.

3.2 Valuation Reduction for Environmental Issues

It is our understanding that this report is not being used for bank financing purposes. We further understand that the property is not being sold outright but that the user of this report will seek to become a partner in the sites ownership group. Therefore, valuation reduction for environmental issues is not relevant to this Phase I ESA.

3.3 Sanborn Fire Insurance Maps

HES requested that EDR search the Sanborn Fire Insurance Map Database to determine if historical maps for the subject exist. EDR reported that there was no coverage for the subject property in the Sanborn Map Database. A copy of the No Coverage letter is attached in APPENDIX F.

3.4 U.S.G.S. 7.5-Minute Quadrangle Maps (Topographic Maps)

EDR provided the following historical topographic maps: Sonoma dated 1940, 1955, 1980, and 1993. Adjoining topographic maps were also presented for the same years. A summary of the HES review of topographic maps is presented on TABLE 3-1. The Topographic Maps are attached in APPENDIX F.

Table 3-1 – SUMMARY OF HISTORICAL TOPOGRAPHIC MAPS

YEAR	SITE USE	SURROUNDING PROPERTY USE
1940 Healdsburg 15 Min. Series 1 : 62500	The site appears undeveloped. An east/west trending creek crosses the property.	Rural and slightly developed. California Highway 101 has not yet been built. The Northern Pacific train tracks are present to the west of the site.
1955 Healdsburg 7.5 Min. Series 1: 24000	The site appears undeveloped. An east/west trending creek crosses the property.	Rural and slightly developed. California Highway 101 has not yet been built. The train tracks are present to the west of the site. Some buildings are now seen along the railroad tracks and immediately west of the subject site.
1955 Healdsburg 15 Min. Series 1 : 62500	Same topographic map as before with less detail. The site appears undeveloped. An east/west trending creek crosses the property.	Same topographic map as before with less detail. Rural and slightly developed. California Highway 101 has not yet been built. The train tracks are present to the west of the site. Some buildings are now seen along the railroad tracks and immediately west of the subject site.
1980 Healdsburg 7.5 Min. Series 1 : 24000	The site is now developed. The Standard Structures building is present and three additional buildings to the south are also depicted. The roads Standard Ave. and Caletti Lane are also depicted. The creek still cuts through the northern portion of the site.	California Highway 101 is now shown immediately east of the site. The properties surrounding the railroad tracks to the west are further developed with roads and buildings.
1993 Healdsburg 7.5 Min. Series 1 : 24000	The site is further developed. The same structures are present however a new structure on the 95 parcel is now seen. In addition there are ponds now depicted on the Map	The surrounding area looks generally the same as in the 1980 map with further development to the east. Also a Burrow Pit is depicted west of the site on the west side of the train tracks

3.5 Aerial Photography

HES reviewed historical aerial photographs dated 1953, 1965, 1974, 1983, 1993, 1998, 2005, 2006, 2009, and 2010 obtained from EDR. A summary of the aerial photograph review is presented in TABLE 3-2. The aerial photographs are attached in APPENDIX F.

TABLE 3-2 – SUMMARY OF HISTORICAL AERIAL PHOTOGRAPHY

YEAR	SITE USE	SURROUNDING PROPERTY USE
1953 Pacific Air 1" = 500'	In this photo the property is vacant and undeveloped. An east west trending creek crosses the property.	The adjacent property to the west is developed. There appears to be some kind of industrial facility (Ecodyne) on this property which also borders the railroad tracks. Highway 101 has not yet been constructed and the properties to the north, south, and east are vacant and undeveloped.
1965 Cartwright 1" = 500	The property is now developed with an access road from Shiloh Road and the main building later used by Standard Structures. A pond and drainage feature are located to the east of the structure. A second pond is also located to the south of the onsite building. The site appears to be active with some sort of lumber related business (Fluor Products).	The adjacent property to the west is further developed with an industrial facility and also appears to be related to lumber (Ecodyne). Some development is also present immediately west of the railroad tracks and may represent a mining facility that was shown on historical topographic maps reviewed. Highway 101 is now present however the properties to the north, east, and south are primarily undeveloped.
1974 NASA 1" = 500	The site appears similar to the 1965 Photo. The pond that was located east of the building is now gone however there are three (3) additional ponds on the property. The current fire water pond is seen to the NE of the building on lot 104 and the former sewer evaporation ponds are located to the SE of the building on the same lot.	The adjacent property to the west appears as it did in the 1965 photo. Several ponds exist on this property as well. The properties to the north, south, and east also appear as they did in 1965 and remain primarily undeveloped.
1983 USGS 1" = 500	The site appears similar to the previous photo however a new structure is present on the eastern most parcel (95). In addition a new pond is located NE of the new building in a similar location to the former pond identified in the 1965 photo.	The site appears similar to the previous photo however there appears to be less activity on the adjacent property to the west and no longer appears to have the same industrial operations. The mine site located west of the railroad tracks appears to have expanded and a pond is now located on this property as well. The properties to the north, south, and east also appear as they did in 1965 and remain primarily undeveloped.
1993 EDR 1" = 500'	The site appears very similar to the 1983 photo. The same significant features seen in 1983 are still seen in 1993.	The surrounding properties appear very similar to how they appeared in the previous photo. The mine site to the west of the railroad tracks appears to have changed use.
1998 USGS 1" = 500'	The property looks similar to the last photo except that the pond to the NE of the new building (Glue Pond) and the pond directly south of the former Standard Structures building (Sewer Pond) are now gone.	The surrounding lots appear generally the same as in the previous photograph. The activity on the adjacent parcel to the west appears to have subsided and the development west of the tracks appears to be smaller (the pond is now gone). Some development to the south, southwest, and northeast is now occurring.

TABLE 3-2 – SUMMARY OF HISTORICAL AERIAL PHOTOGRAPHY		
YEAR	SITE USE	SURROUNDING PROPERTY USE
2005 EDR 1" = 500'	The sites look very similar to its current configuration.	Development to the north, south, and west has increased significantly.
2006 EDR 1" = 500'	The sites appear the same as they did in the 2005 Photograph.	The surrounding lots appear generally the same as in the previous photograph.
2009 EDR 1" = 500'	The site appears similar to the 2006 photo. The ponds formerly located southeast of the standard structures building are now gone.	The surrounding lots appear generally the same as in the previous photograph.
2010 EDR 1" = 500'	The site generally appears the same as it did in the 2009 photo.	The surrounding properties appear generally the same as they did in the 2009 photo.

3.6 City Directories

EDR provided limited city directory information for the site. A review of city directories was performed by HES for the years 1975, 1980, 1985, 1990, 1995, 2000, 2006 and 2011. The Pruitt Avenue address for Standard Structures is not shown until 2011. This is because the site operated under a Standard Avenue address from the 80's until the mid 2000's. No other businesses are listed at the subject site in the Historical City Directories reviewed.

The historical city directories were also reviewed for adjacent parcels to the subject site. The directories indicated that the Ecodyne Company was listed at the adjacent 930 Shiloh Road property from 1975 to 1985. Several other industrial type businesses are also listed on the adjacent properties. This is consistent with current property use proximate to the site. The Historical Directory Report is attached in APPENDIX F.

4.0 REGULATORY AGENCY RECORDS SEARCH

The discussion presented in this section is based on available information provided by government agencies and various database records compiled by Environmental Data Resources, Inc. (EDR). HES procured and reviewed an EDR database report dated March 5, 2013. The EDR report is included as APPENDIX F. A review of databases and files from Federal, State, and local environmental regulatory agencies was conducted to identify use, generation, storage, treatment or disposal of hazardous materials and chemicals, or release incidents of such materials, which may impact the site. The database search results discussed in the following section addresses ASTM requirements. Additional Federal and State databases were also reviewed. Please refer to the EDR report for a complete listing.

Included in the EDR report is an orphan summary, which identifies facilities that are contained on one of the above referenced databases or lists, but complete or accurate geographic data was not available. Consequently, EDR was unable to map the facilities in relation to the site. This list was reviewed during site reconnaissance to determine if the properties referenced are within ASTM search distances and identified properties were incorporated into HES review.

A summary of the EDR Database search is presented below in TABLE 4-1.

TABLE 4-1 – EDR DATABASE SUMMARY			
Database	**Radius**	**Target Property**	**Surrounding Facilities**
FEDERAL			
National Priorities List (NPL)	1 Mile	0	0
Proposed National Priorities List (Proposed NPL)	1 Mile	0	0
Delisted NPL	1 Mile	0	0
NPL Liens	Target Property	0	-
Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Sites	½ Mile	0	1
CERC-NFRAP No Further Remedial Action Planned Sites	½ Mile	0	1
Resource Conservation and Recovery Act (RCRA) Corrective Action Report (CORRACTS)	1 Mile	0	0
RCRA Treatment, Storage and Disposal (TSD) Facilities	½ Mile	0	0
RCRA Large Quantity Generators (LQG)	¼ Mile	0	0
RCRA Small Quantity Generators (SQG)	¼ Mile	0	7
RCRA – NonGen / NLR	¼ Mile	0	2
Emergency Response Notification System (ERNS)	Target Property	0	-
HMIRS	Target Property	8	8
FINDS	Target Property	0	-
STATE			
Equivalent NPR RESPONSE	1 Mile	0	3
Equivalent CERCLIS ENVIROSTR	1 Mile	0	9
Historical Cal-Sites	1 Mile	0	2
CA Bond Exp. Plan	1 Mile	0	2
CORTESE List	½ Mile	0	1
HIST CORTESE	½ Mile	0	5
CUPA Listings	¼ Mile	1	27
Notify 65	1 Mile	0	2
CHMIRS	Target Property	0	-
Toxic Pits	1 Mile	0	0
SLIC	½ Mile	0	7
State Landfill (SWF/LF)	½ Mile	0	2
NPDES	Target Property	0	-
Leaking Underground Storage Tank List (LUST)	½ Mile	0	7
Registered Underground Storage Tanks (UST)	¼ Mile	0	4
Historical Underground Storage Tanks (UST)	¼ Mile	0	1
Above Ground Storage Tank (AST)	¼ Mile	0	0
Dry Cleaners	¼ Mile	0	0
SWEEPS UST	¼ Mile	0	2
CA FID UST	¼ Mile	0	0
DEED*	½ Mile	0	0
HAZNET	Target Property	0	-
SWARCY	½ Mile	0	1
Emissions Inventory Data (EMI)	Target Property	0	-
EDR US Historical Auto Stat	¼ Mile	0	5

4.1 Federal Regulatory Records

The October 1, 2012 United States Environmental Protection Agency (USEPA) - National Priorities List (**NPL**), **Proposed NPL**, and **Delisted NPL** records were reviewed to identify facilities within one mile of the site which the USEPA has determined to represent a possible threat to public health or the environment. *The subject site was not identified in these records and no other properties within a 1.0-mile radius of the site were identified on this list.*

The October 15, 1991 USEPA – **NPL Liens** records (Federal Superfund Liens) was reviewed. The USEPA has authority to file liens against properties in order to recover remedial expenditures or when an owner received notice of potential liability. *The subject site was not identified on this list.*

The November 2, 2012 U.S.EPA - Comprehensive Environmental Response, Compensation and Liability Information System (**CERCLIS**) list of known, alleged, or potentially hazardous waste sites were reviewed. A site's presence on the CERCLIS list does not necessarily imply Federal activity at that site, nor does it indicate that hazardous conditions necessarily exist. *The subject site was not identified on this list and one other property within a 0.50-mile radius of the site was identified on this list.*

- **Ecodyne Cooling Prod Division – 930 Shiloh Rd., Windsor CA.**

This site is located approximately 0.15 miles west of the subject property. Ecodyne operated a wood treatment facility from July 1965 to January 1984, at this property. The discharger utilized chromic acid, sodium dichromate, and occasionally copper sulfate in the wood treatment process. The acid chromate copper was diluted with water and applied to lumber in a pressure vessel. The surplus chemical solution was pumped to an evaporation and settling pond, which was allowed to discharge to a ditch. The drainage ditch discharged to Pruitt Creek and eventually the Russian River. In 1989 the discharger started a groundwater extraction, treatment, and disposal system to remediate groundwater contaminated with hexavalent chromium (Chromium VI). The remediation effort was implemented pursuant to Cleanup and Abatement order No. 89-61 adopted April 14, 1989 and Waste Discharge Requirement Order No 92-39 adopted May 3, 1993. This system operated from March 1992 to September 1994. In 1997, the discharger started direct injection of calcium polysulfide using a direct-push drilling rig. Injection of calcium polysulfide was conducted during three (3) events from 1997 to 2002. These treatments were successful in lowering concentrations of chromium in the intermediate and deep groundwater. However, elevated concentrations persist in shallow groundwater near the source area and the injection treatment did not appear to be capable of achieving the remedial goals. In September and October of 2004 highly impacted soil was treated by mixing calcium polysulfide with the soil using a hydraulic backhoe. In April of 2007 additional injection of calcium polysulfide was performed in areas where Chromium VI was still present. An additional remedial phase occurred in 2012 and involved more targeted injection of calcium poly sulfide. The results of this investigation were presented in November of 2012. Currently the site is in a monitoring phase to evaluate the effects of the remedial actions performed to date.

Groundwater at the site is predominantly flowing to the south and west and the

NCRWQCB is providing regulatory oversight on the cleanup activities. *Based on the nature of the contamination at the site and the measured groundwater flow direction, Chromium VI contamination from this site would not be considered a concern to our investigation. However, due to historical well usage on the subject property there is some potential that contaminants from this site may have been drawn-into the subject site. Therefore, this site is considered a concern to the investigation.*

The November 2, 2012 U.S.EPA - CERCLIS No Further Remedial Action Planned Sites (**CERCL-NFRAP**) list was reviewed. As of February 1995, NFRAP sites have been removed from CERCLIS. NFRAP sites may be sites where no contamination was found, contamination was removed in a timely manner, or where the contamination was not serious enough to require Federal Superfund action or NPL consideration. *The subject site was identified on this list and no other property within a 0.50-mile radius of the site was identified on this list.*

- **Standard Structures Inc. – Hwy 101 between Shiloh Rd and Airport Blvd, Windsor CA.**

This site is located on the subject property (lot 95 and 104). In 1980, the NCRWQCB issued Cleanup and Abatement Order No. 80-190, stipulating that no more glue wastewater be discharged to an on-site evaporation pond and that the pond be properly abandoned. In June of 1981, Cleanup and Abatement Order No. 80-190 was rescinded after the pond removal had been completed and assessed. In September 1980 an EPA Field Inspection Team observed small pools of liquid beneath an above a ground storage tank that contained glue used in the manufacturing of products at Standard Structures (Phenol, resorcinol, and paraformaldehyde). In January 1990, the Field Inspection Team collected a total of seven (7) groundwater samples and eight (8) soil samples at various locations on the Standard Structure property. Based on a review of the analytical results, the Standard Structures site was evaluated using the EPA's Hazard Ranking System (HRS). Based on the outcome of the HRS, further sampling and analytical testing in regards to this matter was deemed unnecessary by the EPA. A copy of the Screening Site Inspection Reassessment document dated March 15, 1991 is enclosed in Appendix E. *Based on the assessments made by the EPA in 1980 and 1991 this listing is not considered a concern to the investigation. However, since the site assessment reportedly identified some paraformaldehyde in site soils and since we found no evidence that the irrigation well was ever tested for this substance, this listing is considered a concern to the investigation.*

The February 12, 2013 U.S. EPA - Resource Conservation and Recovery Act (RCRA) Corrective Action Report (**CORRACTS**) database identifies hazardous waste handlers with RCRA corrective action activity. *The subject site was not identified on this list and no other properties within a 1.0-mile radius of the site were identified on this list.*

The February 12, 2013 U.S. EPA's database supporting the RCRA identifies facilities which transport, store, or dispose of hazardous wastes (**RCRA-TSDF**s). *The subject site was not identified on this list and no other properties within a 0.5-mile radius of the site were identified on this list.*

The February 12, 2013 U.S. EPA – **RCRA LQG** database was reviewed. Large Quantity

Generators (LQGs) generate over 1,000 kilograms of hazardous waste or over 1 kilogram of acutely hazardous waste per month. *The subject site was not identified on this database and no additional site within a 1-mile radius was identified on this list.*

The February 12, 2013 U.S. EPA – **RCRA SQG** database was reviewed. Small Quantity Generators (SQG) generate between 100 and 1000 kilograms of hazardous waste per month. *The subject property was not identified on this list and seven (7) other properties within a 0.25-mile radius of the site were identified on this list.*

- **Walmart #2553 – 6650 Hembree Ln., Windsor CA**

This site is located approximately 0.13 miles to the north of the subject property. The listing on this database indicates that hazardous waste was handled here. The waste was primarily associated automobile and photo-processing chemicals. No violations were reported in the database. *Based on the lack of violations, this database listing is not considered a concern to the investigation.*

- **Shell Oil Products – 6301 Hembree, Windsor CA**

This site is located 0.20 miles north-northeast of the subject property. This site is also listed in the HAZNET database and is an active gasoline station. Chemicals disposed of from this site include benzene. No RCRA violations were found. *Based on the lack of identified violations this listing is not considered a concern to the investigation.*

- **Denbeste Transportation Inc. – 1145 Kitty Hawk Blvd., Windsor CA**

This site is located approximately 0.13 miles west of the subject site. The listing on this database is related to solvent disposal at the site. No violations are reported. *Based on the lack of RCRA related violations found this listing is not considered a concern to the investigation.*

- **Lakewood Enterprises – 930 Shiloh Rd., Windsor CA**

This site is located adjacent to the subject site to the west. This site is also listed on the FINDS database as well as the HAZNET database. The listing does not specify the chemical(s) disposed of from this site however, no RCRA violations are reported. *Based on the lack of identified RCRA violations, this listing is not considered a concern to the investigation.*

- **Flour Corp Ecodyne Pond – 930 Shiloh Rd. Ecodyne Pond, Windsor CA**

This site is located adjacent to the subject site to the west and is associated with the Ecodyne Cooling Production Div. site discussed in CERCLIS section of this Report. This site is also listed on the FINDS database. The RCRA SQG listing is from 1998 and is related to wood treatment chemicals. No RCRA violations are reported. *Based on the lack of identified violations this listing is not considered a concern to the investigation. However, this site does have ongoing remediation related to contamination from polynuclear aromatic hydrocarbons (PAH's). Details of the PAH investigation are discussed in the HIST Cal-Sites section of this Report.*

- **Kadon Trucking Inc. – 930 Shiloh Rd. No 15, Windsor, CA**

This site is located adjacent to the subject property to the west. This site is also listed on

the FINDS, NPDES, Cortese, SLIC, CUPA, ENF, RESPONSE, HAZNET and Envirostor databases. The RCRA SQG listing is related to cadmium, lead, benzene and 1,4-dichlorobenzene waste. No RCRA violations are reported. Additional database listings are discussed in the appropriate section of the ESA. *Based on the lack of identified violations this listing is not considered a concern to the investigation.*

- **Martins Truck Repair LLC – 930 Shiloh Rd. Bldg. 1, Windsor, CA**

This site is located adjacent to the subject property to the west. This site is also listed on the FINDS and EMI databases. The RCRA SQG listing is related to benzene, tetrachloroethelyene and trichloroethelyene waste. No RCRA violations are reported. Additional database listings are discussed in the appropriate section of the ESA. *Based on the lack of identified violations this listing is not considered a concern to the investigation.*

The February 12, 2013 U.S. EPA - Resource Conservation and Recovery Act (RCRA) Conditionally Exempt Small Quantity Generator (**CESQG**) database was reviewed. This database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the RCRA. CESQGs generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month. *The subject site was not identified on this list and no other properties within a 0.25-mile radius of the site were identified on this list.*

The December 31, 2012 USEPA – Emergency Response Notification System (**ERNS**) database provides information on reported releases of oil and hazardous substances. *The subject site was not identified on this list.*

The December 31, 2012 US Department of Transportation's Hazardous Materials Incident Report System (**HMIRS**) database contains information on reported hazardous material incidents (i.e., accidental releases or spills). *Two addresses within the subject site were listed eight (8) times on this list. Based on our review of this information we determined that these sites are discussed in other sections of this report and these listings are not considered a concern to the investigation*.

The December 19, 2012 USEPA – US Engineering Controls (**US Eng Controls**) database provides a list of properties with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners and treatment methods to eliminate pathways for regulated substance to enter environmental or affect human health. *The subject site was not identified on this list and no other properties located within a 0.50-mile radius of the site were identified on this list.*

The October 23, 2011 Facility Index System/Facility Registry System (**FINDS**) database contains both facility information and pointers to other database sources that contain more detail on regulatory compliance and enforcement. *The subject site was identified on this list.*

4.2 State Regulatory Records

The December 5, 2012 California DTSC – Response List (**RESPONSE**) identifies confirmed release sites where DTSC involved in remediation, either in a lead or oversight capacity. These confirmed release sites are generally high-priority and high potential risk. *The subject site was not identified on this list and three (3) properties located within 1.0- mile of the site were listed.*

- **Ecodyne Cooling – Shiloh Rd., Windsor CA**

This site is located adjacent to the subject property to the west. This site is also listed in the CERCLIS, LUST and FINDS databases. Details of this site were discussed in the CERCLIS section of this Report. *Based on the nature of the contamination at the site and the measured groundwater flow direction, Chromium VI contamination from this site is not considered a concern to our investigation. However, due to historical well usage on the subject property there is some potential that contaminants from this site may have been drawn-into the subject site. Therefore, this site is considered a concern to the investigation.*

- **Kadon Trucking Inc. – 930 Shiloh Rd. No 15, Windsor CA**

This site is located adjacent to the subject property to the west. This site is also listed in several other databases. The site is located at the former Ecodyne wood treatment facility and has ongoing site remediation related to former wood treatment activities. The RESPONSE listing is also related to the ongoing investigation and cleanup at the former Ecodyne pond site. A responsible party has been identified at this site and remediation efforts are ongoing. Groundwater flow at the site is south and westerly which is moving away from the subject site. *Based on the relative distance and direction to the subject site and the calculated groundwater flow direction, this listing is not considered a concern to the investigation. However, based on the documented use of an irrigation well at the subject property it is possible that groundwater contamination may have been drawn into the subject property. Therefore, this site is considered a concern to the investigation.*

- **Sonoma Aviation Fuel Ser. – 2240 Airport, Santa Rosa CA**

This site is located approximately 0.83 miles southwest of the subject site. This site is also listed in the NPDES, CA FID UST, CUPA, CHMIRS, and ENVIROSTOR databases. The listings are related to a Voluntary Cooperative Agreement for review of a Geophysical and soil sampling work plan that addresses the investigation of a 2 acre parcel on the former Santa Rosa Army Airfield formerly used as a defense site. The site was overseen by the California Department of Toxic Substance Control. The site was closed in 2010. *Based on the current status of the site investigation and the relative distance to the subject property, this listing is not considered a concern to the investigation.*

The December 5, 2011 DTSC's Site Mitigation and Brownsfield Reuse Programs (**ENVIROSTOR**) database was reviewed. The ENVIROSTOR database identifies sites that have known contamination or sites for which there may be reasons to investigate further. ENVIROSTOR provides information similar to what was available from Cal-Sites, and provides

additional site information, including, but not limited to, identification of formerly contaminated properties that have been released for reuse, properties where environmental deed restrictions have been recorded to prevent inappropriate land uses, and risk characterization data that is used to assess potential impacts to public health and the environment at contaminated sites. *The subject site was not identified on this list and nine (9) off-site facilities were identified within a 1.0-mile of the subject site. These sites are discussed below.*

- **Cream's Auto Dismantlers – 1588 Airport Blvd., Windsor CA**

This site is located approximately 0.5 miles south/southwest of the subject site. This site is also listed on CERLIS, FINDS, NPDES, Cortese, Hist Cortese, SLIC, ENF, HAZNET, and WDS databases. The site is an automobile dismantling facility. Surface discharges at this site from petroleum products have been documented and the site currently operates under an industrial discharge permit (NPDES). The releases that have occurred at this site have been investigated by the NCRWQCB and the SLIC case was closed in 2005. *Based on the currently regulatory status and the relative distance to the subject property, this site is not considered a concern to the subject property.*

- **Standard Structures – Hwy 101 Shiloh and Airport, Windsor CA**

This site is located on the subject property. The listing in this database is related to the site screening performed by the EPA in 1980 and the site was referred to the RWQCB in 1993. No significant findings were made in the EPA assessment and the NCRWQCB has not required any action at the site. *Based on the EPA assessment and the NCRWQCB case status this listing is not considered a concern to the investigation.*

- **M & M Services – 590 Caletti Ave., Windsor CA**

This site is located approximately 0.06 miles west of the subject site. This site is listed as active and is also listed in the SWF/LF, NPDES, CUPA, and HAZNET databases. This site is a waste bulking, storage, and transfer facility. M & M Services primarily accepts construction waste and provides waste disposal bins to contractors. The site operates under and industrial waste water discharge permit and also handles fuel and solvent waste products. No violations are reported in the database report. *Based on the regulatory status of this site and the down-gradient position relative to the subject property, this listing is not considered a concern to the investigation.*

- **Ecodyne Cooling – Shiloh Rd., Windsor, CA**

This site is located approximately 0.10 miles northwest of the subject site on the adjacent property to the west. This site is also listed in the CERCLIS, CA Bond Exp. Plan, and RESPONSE databases. Details of the site were discussed in the CECLIS section of this Report. *Based on the nature of the contamination at the site and the measured groundwater flow direction, Chromium VI contamination from this site would not be considered a concern to our investigation. However, due to historical well usage on the subject property there is some potential that contaminants from this site may have been drawn-into the subject site. Therefore, this site is considered a concern to the investigation.*

- **Kadon Trucking Inc. – 930 Shiloh Rd. No 15, Windsor, CA**

This site is located adjacent to the subject property to the west. This site is listed as active and also in the RCRA-SQG, FINDS, NPDES, Cortese, Hist Cortese, SLIC, CUPA, ENF, RESPONSE, and HAZNET databases. This site is located on the former Ecodyne Pond Site and has ongoing industrial waste water discharge requirements. Remediation efforts related to the former Ecodyne site are ongoing. *While it is unlikely that contamination from this site has impacted the subject property, the documented use of an industrial well at the subject site may have drawn-in contaminants identified at this site. Therefore, this site is considered a concern to the investigation.*

- **L & N Printing – 5577 Skylane Blvd., Santa Rosa, CA**

This site is located approximately 0.40 miles west-southwest of the subject site. This site is listed as inactive and also listed in the HAZNET database. This site is documented as generating photo-processing wastes. There is no data to suggest that problems have occurred however the site is listed as needing evaluation. The site is located down-gradient from the subject property. *Based on the relative distance to the subject property and the current regulatory status, this site is not considered a concern to the investigation.*

- **Weigh Tronix Inc. – 2320 Airport Blvd., Santa Rosa, CA**

This site is located approximately 0.79 miles southwest of the subject site. This site is listed as inactive and is also included in the RCRA-SQG, FINDS, SLIC, HAZNET, and EMI databases. The site was former RCRA LQG and had two (2) violations in 1985. Both violations were corrected later that year. The site has also been involved in a SLIC case related to solvents however the RWQCB closed the case in 2002. The site currently generates waste related to waste oil and halogenated compounds. *Based on the relative distance to the subject property and the current status of the SLIC case and RCRA violations this site is not considered a concern to the investigation.*

- **Sonoma Aviation Fuel Ser. – 2240 Airport, Santa Rosa, CA**

This site is located approximately 0.83 miles southwest of the subject site. This site is also listed in the NPDES, CA FID UST, CUPA, CHMIRS, and RESPONSE databases. Details of the site were discussed in the RESPONSE section of this Report. *Based on the current status of the site investigation and the relative distance to the subject property, this listing is not considered a concern to the investigation.*

- **Sonoma County Airport – 2232 Airport Blvd., Santa Rosa, CA**

This site is located approximately 0.83 miles southwest of the subject site. This site is listed as inactive and is also included in the HIST Cal-Sites, LUST, SLIC, and HAZNET databases. This site is a former Department of Defense training site that contained a sewage treatment pond as well as USTs. The site is currently used as the Sonoma County Airport. The contamination at the site is currently under investigation however the UST release investigation is listed as being eligible for case closure. *Based on the relative distance to the subject site and the nature of the contaminants identified, this site is not considered a concern to the investigation.*

The November 19, 2012 California Integrated Waste Management Board - Solid Waste Information System (SWIS) database (**SWF/LF**) was reviewed. This database identifies landfills or solid waste disposal facilities that may be active or inactive disposal facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites. *The subject site was not identified on this list and two (2) other properties located within a 0.50-mile radius of the site were identified on this list.*

- **Sonoma County IDS (2136) – 475 Aviation Blvd., Santa Rosa, CA**

This site is located approximately 0.24 miles south of the subject site. The site is a former unpermitted solid waste disposal site. The site was investigated by the Sonoma County Department of Health Services and is currently listed as a closed site. *Based on the relative distance to the subject property and the current regulatory status of the investigation, this site is not considered a concern to the investigation.*

- **M & M Services – 590 Caletti Ave., Windsor, CA**

This site is located 0.06 miles from the subject site on the adjacent property to the west. This site is a waste bulking, storage and transfer facility. The details of his site were discussed in the ENVIROSTOR section of this Report. *Based on the regulatory status of this site and the down-gradient position relative to the subject property, this listing is not considered a concern to the investigation.*

The August 8, 2005 California Department of Toxic Substances Control (DTSC) – Hazardous Waste Sites (**HIST CAL-SITES**) database was reviewed. The HIST CAL-SITES database lists known and potential hazardous waste sites. This database is no longer maintained and has been transferred to the ENVIROSTOR database. *The subject site was not identified on this list and two (2) other properties located within a 1.0-mile radius of the site were identified on this list.*

- **Ecodyne/Shiloh Industrial Park – 930 Shiloh Rd., Windsor, CA**

This site is located adjacent to the subject property to the west. This site is listed in the CA Bond Exp. Plan and WDS databases and is related to the Ecodyne cooling site discussed in the CERCLIS section of this ESA. This specific area of the site is being regulated by the Department of Toxic Substances Control (DTSC) while the Ecodyne Cooling site is being overseen by the NCRWQCB. The Ecodyne site controlled by the DTSC was formerly used as a dip treatment facility for wood and metal products until the early 1970's. During site operations pentachlorophenol (PCP), creosote, and lead were used to treat wood. Chemicals used in the operations were stored in above ground and below grade storage tanks. Surface soils have been measured to be contaminated with creosote, PCP, PAH's, dioxin and furan congeners. Low levels of PCP have also been detected in groundwater. Lead and zinc have also been detected in soil and low levels have also been detected in groundwater. According to reports, contaminants were routinely discharged into surface water systems and residual contaminants are still present. The site has been burmed, paved, and fenced to prevent migration via surface water runoff.

One of the past and current site owners and operators, Fluor Daniels Corporation, is funding the investigation and remediation activities. A pilot test was conducted to determine the effectiveness of in-situ ozonation to treat PCP and PAH's. The process

involved the injection of ozone to chemically oxidize organic compounds such as PCP and PAH's. Results from the study indicated that a successful reduction in PAH and PCP concentrations in both soil and groundwater is occurring. Currently, there are surface water, groundwater and soil remediation efforts being completed at the site. *Based on the proximity to the subject property and the documented use of an irrigation well on the subject site, it is possible that groundwater contaminants identified at this site may have been drawn to the subject site from the well usage. Therefore, this site is considered a concern to the investigation.*

- **Sonoma County Airport – 2232 Airport Blvd., Santa Rosa, CA**

This site is located 0.83 miles southwest of the subject site. This site is a former Department of Defense training site that contained a sewage treatment pond as well as USTs. The site is currently used as the Sonoma County Airport. The contamination at the site is currently under investigation however the UST release investigation is listed as being eligible for case closure. *Based on the relative distance to the subject site and the nature of the contaminants identified, this site is not considered a concern to the investigation.*

The January 1, 1989 California Department of Health Services' Bond Expenditure Plan (**CA BOND EXP PLAN**) was reviewed. The CA BOND EXP PLAN is no longer updated but lists site specific expenditure plans for the appropriation of Hazardous Substance Cleanup Bond Act funds. *The subject site was not identified on this list and two (2) other properties located within a 1.0-mile radius of the site were identified on this list.*

- **Ecodyne Cooling – Shiloh Rd., Windsor, CA**

This site is located 0.10 miles from the subject site on the adjacent property to the west. This site was discussed in the CERCLIS section of this ESA. *Based on the nature of the contamination at the site and the measured groundwater flow direction, Chromium VI contamination from this site would not be considered a concern to our investigation. However, due to historical well usage on the subject property there is some potential that contaminants from this site may have been drawn-into the subject site. Therefore, this site is considered a concern to the investigation.*

- **Ecodyne/Shiloh Industrial Park – 930 Shiloh Rd., Windsor, CA**

This site is located 0.10 miles from the subject site on the adjacent property to the west. This site was discussed in the HIST CAL Sites section of this ESA. *Based on the proximity to the subject property and the documented use of an irrigation well on the subject site, it is possible that groundwater contaminants identified at this site may have been drawn to the subject site from the well usage. Therefore, we recommend that groundwater samples be collected from the on-site domestic well and tested for the contaminants identified at this former Ecodyne site.*

The January 2, 2013, Hazardous Waste & Substances Sites List (**CORTESE)** was reviewed. The sites listed are designated by the State Water Resource Control Board, the Integrated Waste Board (SWF/LS), and the Department of Toxic Substances Control (Cal-Sites). This

listing is no longer updated by the state agency. *The subject property was not identified on this database and one other property within a 0.5 mile radius was identified on the list.*

- **Kadon Trucking Inc. – 930 Shiloh Rd. No 15, Windsor, CA**

This site is located 0.10 miles from the subject site on the adjacent property to the west. This site is located on the former Ecodyne Pond Site and has ongoing industrial waste water discharge requirements. Remediation efforts related to the former Ecodyne site are ongoing. *While it is unlikely that contamination from this site has impacted the subject property, the documented use of an industrial well at the subject site may have drawn in contaminants identified at this site. Therefore, we recommend that a groundwater sample be collected from the irrigation well and tested for the contaminants identified at the former Ecodyne Pond Site.*

The April 1, 2001 California EPA/Office of Emergency Protection – Hazardous Waste and Substance Site List (HIST **CORTESE**) was reviewed. This database provides information concerning hazardous substances sites selected for remedial action, sites with known toxic materials identified through the abandoned site assessment program, sites with underground storage tanks (USTs) having a reportable release, and all solid waste facilities from which there is confirmed off-site migration. *The subject site was not identified on this list. Five (5) properties located within a 0.5-mile radius of the site were also identified on this database.*

- **Soiland Co. Inc. - 1210 Airport Blvd., Santa Rosa, CA**

This property is located 0.47 miles south-southeast of the subject site. This site is also listed on the LUST database. This site was under investigation for former UST's that were used at the site since the 1950's. The site was listed as a soils only case and was closed by the NCRWQCB in 1998. *Based on the relative distance to the subject property and the current regulatory status, this site is not considered a concern to the investigation.*

- **K&C Trucking Corp. - 1514 Airport Blvd., Santa Rosa, CA**

This property is located 0.48 miles south of the subject site. A diesel UST was removed from this site under the oversight of the Sonoma County Environmental Health Department. Groundwater was impacted from the release however the case was closed in 2003. *Based on the relative distance to the subject property and the current regulatory status of the case, this site is not considered a concern to the investigation.*

- **Mobil, Gunderson, Ken – 705 Shiloh, Windsor, CA**

This property is located 0.10 miles north of the subject site. The site is also listed on the LUST database. The site operated as a retail Mobil service station since 1971. Since then, a variety of businesses have operated at the site including an auto repair facility, a towing company, and an electrical contractor. The site has been vacant since 1999.

In 1987, a 350-gallon used oil UST, a 10,000-gallon UST and an 8,000-gallon UST were removed from the site. In March of 1987, 100 cubic yards of soil were excavated from the UST pit and aerated on-site. Ten cubic yards of soil were excavated from beneath the used oil UST and removed from the site. In 2001, 120 ft. of steel product lines and approximately 150 cubic yards of excavated soil were removed from the site. A

groundwater pump and treatment system was installed in 2003. The system extracted groundwater from several wells on-site and treated it before being discharged to surface water under a NPDES permit. The NPDES permit expired in 2006. The groundwater treatment system removed approximately 13.7 lbs of gasoline, 2.5 lbs of benzene, and less than 0.5 lbs of methyl tert butyl ether (MTBE). A soil vapor extraction (SVE) system was installed at the site in 2004. The SVE system removed approximately 21,000 lbs of gasoline, 500 lbs of benzene and 100 lbs of MTBE. The SVE system was also shut down in 2006. In 2010, an additional 2,831 tons of soil were excavated from the site. In 2010, after the completion of the excavation activities, soil borings and monitoring wells were installed for verification monitoring purposes. The site is currently listed as being eligible for site closure. Through the various investigations and site monitoring it has been determined that contamination did not migrate across Shiloh Road onto the subject property. *Based on the regulatory status of this investigation and the site data reviewed, this site is not considered a concern to the investigation.*

- **Kadon Trucking Inc. – 930 Shiloh Rd. No 15, Windsor, CA**

This site is located 0.10 miles from the subject site on the adjacent property to the west. This site is located on the former Ecodyne Pond Site and has ongoing industrial waste water discharge requirements. Remediation efforts related to the former Ecodyne site are ongoing. *While it is unlikely that contamination from this site has impacted the subject property, the documented use of an industrial well at the subject site may have drawn in contaminants identified at this site. Therefore, we recommend that a groundwater sample be collected from the irrigation well and tested for the contaminants identified t the former Ecodyne Pond Site.*

- **C.A. Rasmussen Inc. – 1012 Shiloh, Windsor, CA**

This property is located 0.28 miles northwest of the subject site. A LUST existed at this site. Contamination to soil and groundwater from gasoline and diesel fuel was identified at this site. Cleanup activities were overseen by the Sonoma County Health Department and the site was ultimately closed by the NCRWQCB in 1999. *Based on the relative distance to the subject property and the current regulatory status of the investigation, this site is not considered a concern to the investigation.*

The January 10, 2013 Sonoma County **CUPA** Facility list was reviewed. *The subject site not was identified on this list and twenty-seven (27) properties located within a 0.25-mile radius of the site were also identified on this list. These sites are listed in the EDR and contain many of the same sites discussed previously under other listings. Of the sites identified uniquely on CUPA list one (1) site of interest is discussed below.*

- **Quality Stainless Tanks – 510 Caletti Avenue, Windsor, CA**

This site is located on the adjacent property to the west. Stainless steel tanks are manufactured at this facility. A domestic well at this site was found to contain TCE and other chlorinated solvents including vinyl chloride. Follow-up soil and groundwater testing at the site has not found elevated concentrations chlorinated solvents. The site is currently under review for case closure by the NCRWQCB. *Based on the data reviewed in the EDR Report and the current regulatory status of the case, this site is not considered a concern to the investigation.*

The October 21, 1993 California State Water Resources Control Board - **NOTIFY 65** database was reviewed. These records contain facility notifications about any release that could impact drinking water. *The subject site was not identified on this list and two (2) additional properties located within a 1.0-mile radius of the site were identified.*

- **Shiloh Industrial Park – 930 Shiloh Rd., Windsor, CA**

  This site is located adjacent to the subject property to the west. The site is an industrial facility and the former location of Ecodyne Corp. The Notify 65 listing indicates that chemicals known to the State of CA to cause cancer are found at this site. The site is listed on the Sweeps UST database. *While the Ecodyne facility is of potential concern to this investigation this specific listing is not considered a concern to the investigation.*

- **Shiloh Park Adams Enterprizes – 930 Shiloh Rd., Windsor, CA**

  This site is also listed as being adjacent to the subject property to the west. The site is listed as having several active UST's identified on the Sweeps UST database. In addition, the site is subject to waste discharge requirements (NPDES) for industrial storm-water and runoff. Hazardous waste is also generated or stored on this facility. The location and current status of the UST's at this site are unknown. *While the groundwater flow direction at this site is away from the subject property, there is uncertainty as to where these tanks occur on the property and whether or not they have leaked. Based on the proximity to the subject property and the uncertainty regarding the specific UST locations, this listing is considered a potential concern to the investigation.*

The March 28, 2012 Office of Emergency Services (OES) - California Hazardous Material Incident Report System (**CHMIRS**) was reviewed. The CHMIRS database contains information on reported hazardous material incidents (i.e., accidental releases or spills). *The subject site was not identified on this list.*

The July 1, 1995 State Water Resources Control Board - Toxic Pits Cleanup Act Sites (**TOXIC PITS**) database was reviewed. The **TOXIC PITS** database identifies sites suspected of containing hazardous substances where cleanup has not yet been completed. *The subject site was not identified on this list and no other properties located within a 1.0-mile radius of the site were identified on this list.*

The December 17, 2012 State Water Resources Control Board – Leaking Underground Storage Tank (**LUST**) database was reviewed. The LUST database contains information regarding reported fuel leaks from underground storage tanks. *The subject site was not identified on this list. Seven (7) off-site properties located within a 0.5-mile radius of the site were identified on this list.*

- **SCWA Ordinance Rd. Main Yard – 2260 Ordinance Rd., Santa Rosa, CA**

  This site is located approximately 0.34 miles south-southeast of the subject site. Three (3) UST's were removed from this site in 1987. Sonoma County Environmental Health Department provided regulatory oversight and closed the case in 2004. *Based on the relative distance to the subject property and the current regulatory case closed status, this site is not considered a concern to the investigation.*

- **Soiland Co. Inc. – 1210 Airport Blvd., Santa Rosa CA**

This property is located 0.47 miles south-southeast of the subject site. This site was under investigation for former UST's that were used since the 1950's. The site was listed as a soils only case and was closed by the NCRWQCB in 1998. *Based on the relative distance to the subject property and the current regulatory status, this site is not considered a concern to the investigation.*

- **K&C Trucking – 1514 Airport Blvd., Santa Rosa CA**

This property is located 0.48 miles south of the subject site. A diesel UST was removed from this site under the oversight of the Sonoma County Environmental Health Department. Groundwater was impacted from the release however the case was closed in 2003. *Based on the relative distance to the subject property and the current regulatory status of the case, this site is not considered a concern to the investigation.*

- **Mobil Station (Former) – 705 Shiloh Rd., Windsor CA**

This property is located 0.10 miles north of the subject site. The site is also listed on the Hist CORTESE database and was previously discussed in detail in this ESA. *Based on the regulatory status of this investigation and the site data reviewed, this site is not considered a concern to the investigation.*

- **Ecodyne Cooling – Shiloh Rd., Windsor, CA**

This site is located 0.10 miles from the subject site on the adjacent property to the west. This site was discussed in the CERCLIS section of this ESA. *Based on the nature of the contamination at the site and the measured groundwater flow direction, Chromium VI contamination from this site is not considered a concern to our investigation. However, due to historical well usage on the subject property there is some potential that contaminants from this site may have been drawn-into the subject site. Therefore, this site is considered a concern to the investigation.*

- **C.A. Rasmussen, Inc. – 1012 Shiloh, Windsor, CA**

This property is located 0.28 miles northwest of the subject site. A leaking underground storage tank existed at this site. Contamination to soil and groundwater from gasoline and diesel fuel was identified at this site. Cleanup activities were overseen by the Sonoma County Health Department and the site was ultimately closed by the NCRWQCB in 1999. *Based on the relative distance to the subject property and the current regulatory status of the investigation, this site is not considered a concern to the investigation.*

The December 17, 2012 California Regional Water Quality Control Board - Spills, Leaks, Investigation and Cleanups (**CA SLIC**) database was reviewed. The CA SLIC database contains information regarding unauthorized discharges from spills and leaks other than from USTs or other regulated sites. *The subject site was not identified on this list and seven (7) other properties within 0.5-miles of the site were identified.*

- **Shell Oil Products – 6301 Hembree, Windsor CA**

This site is located approximately 0.20 miles north-northeast of the subject site. A release was discovered at this site in 2003. The release was related to diesel fuel.

The case was overseen by the NCRWQCB and was closed in 2005. *Based on the relative distance to the subject site and the current case closed regulatory status, this site is not considered a concern to the investigation.*

- **Santa Rosa Stainless Steel Fab. – 1400 Airport Blvd., Santa Rosa CA**

This site is located approximately 0.48 miles south of the subject site. In a 2004 response to an anonymous complaint, groundwater from the on-site domestic well was sampled. TCE as well as several breakdown products of TCE were detected in the water sample. Specifically 1,1-Dichloroethane, 1,1-Dichloroethene, and vinyl Chloride all were detected at concentrations above the California Maximum Contaminant Level (MCL). These chemicals have also been detected in the domestic well to the south of the property and in monitoring wells located adjacent to the property. Site sampling and monitoring was been ongoing for several years and the site is currently being reviewed for regulatory case closure. *Based on the relative distance to the subject property and the current regulatory status of the investigation, this site is not considered a concern to the investigation.*

- **Redwood Sanitary Service Fire – 511 Shiloh Rd., Windsor CA**

This site is located approximately 0.02 miles north-northwest of the subject site. In 1999 a case was opened to evaluate the potential soil impact from releases at the site. Based on the results of the investigation the facility was subsequently closed in October of 2000 by the NCRWQCB. *Based on the regulatory closed status of this investigation, this site is not considered a concern to the investigation.*

- **Kadon Trucking Inc. – 930 Shiloh Rd. No 15, Windsor, CA**

This site is located 0.10 miles from the subject site on the adjacent property to the west. This site is located on the former Ecodyne Pond Site and is subject to ongoing industrial waste water discharge requirements. Remediation efforts related to the former Ecodyne site are ongoing. *While it is unlikely that contamination from this site has impacted the subject property, the documented use of an industrial well at the subject site may have drawn in contaminants identified at this site. Therefore, this site is considered a potential concern to the investigation.*

- **Ecodyne Cooling – Shiloh Rd., Windsor, CA**

This site is located 0.10 miles from the subject site on the adjacent property to the west. This site was discussed in the CERCLIS section of this ESA. *Based on the nature of the contamination at the site and the measured groundwater flow direction, Chromium VI contamination from this site is not considered a concern to our investigation. However, due to historical well usage on the subject property there is some potential that contaminants from this site may have been drawn-into the subject site. Therefore, this site is considered a concern to the investigation.*

- **Shiloh Aggregates – 1010 Shiloh Rd. , Windsor, CA**

This site is located approximately 0.28 miles northwest of the subject site. The site had a diesel release that was discovered in 1995. Subsequent cleanup activities were performed and the case was closed by the NCRWQCB in November of

1997. *Based on the relative distance to the subject property and the closed status of the investigation, this site is not considered a concern to the investigation.*

- **Airport Business Center – 1010 Shiloh Rd. , Windsor, CA**

This site is located approximately 0.28 miles northwest of the subject site. This site is also listed as Shiloh Aggregates. *Limited information regarding this site was available however, based on the information known about the Shiloh Aggregates site and the relative distance to the subject property, this site is not considered a concern to the investigation.*

The December 17, 2012 State Water Resources Control Board – Registered Underground Storage Tanks (**UST**) database was reviewed. The UST database identifies storage tanks regulated under Subtitle I of RCRA. *The subject site was not identified on this list and four (4) other properties located within a 0.25-mile radius of the site were identified on this list.*

- **Shiloh Center Shell – 6301 Hembree Ln., Windsor CA**

This site is located approximately 0.20 miles north-northeast of the subject site. The site is an active refueling station. A diesel fuel release was discovered at this site in 2003. The case was overseen by the NCRWQCB and was closed in 2005. *Based on the relative distance to the subject site and the current closed regulatory status, this site is not considered a concern to the investigation.*

- **Facility 49-000-005773 – 590 Caletti, Windsor CA**

This site is located approximately 0.06 miles west of the subject site. The site is also known as M&M Services which was listed in the HAZNET ENVIROSTOR, NPDES, and CUPA databases. The site is listed as having an active UST however no other information regarding the UST size or contents is available. *Based on the absence of this site from the LUST database, the lack of HAZNET or NPDES violations, and the down-gradient position of the site relative to the subject property, this site is not considered a concern to the investigation.*

- **Mobil Station (Former) – 705 Shiloh Rd., Windsor CA**

This property is located 0.10 miles north of the subject site. The site is also listed on the Hist CORTESE database and was previously discussed in detail in this ESA. *Based on the regulatory status of this investigation and the site data reviewed, this site is not considered a concern to the investigation.*

- **Facility 49-000-005968 – 1175 Kitty Hawk Blvd., Windsor CA**

This site is located approximately 0.24 miles south of the subject property. Based on our review of data in the EDR report, one (1) UST's existed on this property. No information regarding the tank contents was provided. *Based on the relative distance to the subject property and the absence of this site on other databases, this listing is not considered a concern to the investigation.*

The April 1, 2000 State Water Resources Control Board – Waste Management Unit Database System (**WMUDS**) was reviewed. This database is composed of numerous regulatory databases including the Solid Waste Assessment Test (**SWAT**) database. The State Water

Resources Control Board uses this database for program tracking and inventory of waste management units. *The subject site was not identified on this list and no other properties located within a 0.5-mile radius of the site were identified on this list.*

The November 19, 2012 State Water Resource Control Board's National Pollution Discharge Elimination System (**NPDES**) database was reviewed. The NPDES database lists sites that discharge highly treated groundwater to surface waters or storm drains. *The subject site was not identified on this list.*

The October 15, 1990 State Water Resources Control Board – Hazardous Substance Container database (**HIST UST**) was reviewed. The HIST UST database is a historical listing of UST sites. *The subject site was not identified on this list and one other property located within a 0.25-mile radius of the site was identified on this list.*

- **Texaco – 701 Shiloh Rd., Windsor CA**

  This site is located approximately 0.09 miles northwest of the subject property. The listing is for UST's that have formerly existed on the site. All UST's at the site have been removed. The site is also listed on the LUST database as a former Mobil Station. *Since UST's no longer exist at this site and since the site has been remediated by another responsible party, this site is not considered a concern to the investigation.*

The June 1, 1994 State Water Resource Control Boards Statewide Environmental Evaluation and Planning System (**SWEEPS**) list was reviewed. This UST listing was updated and maintained by a company contacted by the SWRCB in the early 1990's. The listing is no longer updated or maintained. The local agency is the contact for more information on a site on the SWEEPS list. *The subject property was not identified on this list and two (2) other properties within a ¼ mile radius were identified on this list.*

- **Hembree Lane Associates – 6842 Hembree Ln., Windsor CA**

  This site is located approximately 0.20 miles north-northwest of the subject property. Based on information reviewed in the EDR report there is one (1) 1,000-gallon gasoline UST at this site. *Based on the relative distance to the subject property and the absence of this site on any other databases, this site is not considered a concern to the investigation.*

- **Shiloh Park Adams Enterprizes – 930 Shiloh Rd., Windsor, CA**

  This site is also listed as being adjacent to the subject property to the west. The site is listed as having several active UST's identified on the SWEEPS UST database. In addition, the site is subject to waste discharge requirements (NPDES) for industrial storm-water and runoff. Hazardous waste is also generated or stored on this facility. The location and current status of the UST's at this site are unknown. *While the groundwater flow direction at this site is away from the subject property, there is uncertainty as to where these tanks occur on the property and whether or not they have leaked. Based on the proximity to the subject property, and the uncertainty regarding the specific UST locations, this listing is considered a potential concern to the investigation.*

The September 6, 2012 USEPA - Leaking Underground Storage Tank on Indian Land (**INDIAN LUST**) database was reviewed. The INDIAN LUST database identifies leaking USTs on Indian Land. *The subject site was not identified on this list and no other properties located within a 0.50-mile radius of the site were identified on this list.*

The September 6, 2012 USEPA - Registered Underground Storage Tank on Indian Land (**INDIAN UST**) database was reviewed. The INDIAN UST database identifies USTs on Indian Land. *The subject site was not identified on this list and no other properties located within a ¼ mile radius of the site were identified on this list.*

The October 31, 1994 State Water Resources Control Board – Facility Inventory Database (**CA FID**) records were reviewed. CA FID contains information regarding active and inactive UST locations. *The subject site was not identified on this list and no other properties within a ¼ mile radius were identified.*

The August 1, 2009, State Water Resources Control Boards Above Ground Storage Tank **(AST)** database was reviewed. The AST database identifies properties that have registered AST's. *The subject property was not identified on this database and no other properties within a ¼-mile radius were identified.*

The December 11, 2012 California DTSC – List of Dry Cleaning Facilities (**CLEANERS**) was reviewed. *The subject site was not identified on this list and no other properties located within a ¼ mile radius of the site were identified on this list.*

The December 10, 2012 California DTSC – **DEED** List was reviewed. This list contains information of recorded land use restrictions. *The subject site was not identified on this list and no other properties located within a 0.5-mile radius of the site were identified on this list*

The December 31, 2011 California DTSC – Facility and Manifest data (**HAZNET)** list was reviewed. This list contains information extracted from hazardous waste manifests. *The subject site was not identified on this list.*

The EDR proprietary database of Former Manufactured Gas (**EDR MGP**) sites was reviewed. *The subject site was not identified on this list and no other properties located within a 1.0-mile radius of the site were identified on this list.*

The December 31, 2008 Emissions Inventory database (**EMI**) was reviewed. Based on data collected by the Air Resources Board and local air pollution agencies, the EMI database identifies facilities where toxic and criteria pollutant emissions have been discharged. *The subject site was identified on this list.*

The December 18, 2012 Department of Conservation database of solid waste recyclers **SWRCY** was reviewed. The database identifies sites where permitted solid waste recycling occurs. *The subject site was not identified on this list and one (1) off-site facility was identified within 0.5 miles of the subject site.*

- **West Coast Metals Caletti – 470 Caletti Ave., Santa Rosa CA**

  This site is located 0.015 miles west-southwest of the subject site.
  The site is a metal recycling facility. The site is also listed on the NPDES and CUPA databases. The site is also in the industrial storm-water program managed by the NCRWQCB. *Based on the absence of identified regulatory violations and the down-gradient position relative to the subject property, this site is not considered a concern to the investigation.*

The February 12, 2013 EPA **RCRA-NonGen** database was reviewed. RCRAinfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery ACT (RCRA). Non-Generators do not presently generate hazardous waste. *The subject site was not identified on this list and two (2) off-site facilities were identified within a ¼ mile radius of the subject site.*

- **Clear Water Environ – 930 Shiloh Rd., Windsor CA**

  This site is located adjacent to the subject property to the west. This site no longer handles or generates hazardous waste. No violations were reported from past handling. *Based on the current status of the site and the lack of identified historical violations this site is not considered a concern to the investigation.*

- **H & H Excavation – 930 Shiloh Rd., Windsor CA**

  This site is located adjacent to the subject property to the west. This site no longer handles or generates hazardous waste. No violations were reported from past handling. *Based on the current status of the site and the lack of identified historical violations this site is not considered a concern to the investigation.*

The proprietary EDR Historic Gas Station list (**US Hist Auto Stat**) was reviewed. *The subject site was not identified on this list and five (5) off-site facilities were identified within a ¼ mile radius of the subject site. Based on our review of these sites we determined that these sites were either discussed within other database sections of this report or were determined to not be a concern to the investigation.*

HES reviewed the **Orphan List** provided by EDR. The **Orphan List** presents sites that appear on various federal, state and local environmental databases but for some reason could not be positively mapped in relation to the subject property. *A total of fourteen (14) sites were identified on the Orphan List. Based on our review of these sites we determined that these sites either fall outside the area of our investigation or are not considered a concern to the investigation.*

4.3 State and Local Agency File Reviews

HES conducted a review of records at various regulatory agencies. HES interviewed officials from these agencies to obtain specific information regarding reported environmental issues at locations on or near the subject site. Copies of documents found to relevant to this investigation are attached in APPENDIX G.

Sonoma County Environmental Health Department (SCEHD)
On March 6, 2013, HES contacted the SCEHD regarding the subject property. According to the SCEHD the only files for the subject site are related to a waste tire hauler that operates on the subject site. The Waste Tire Survey and Inspection Report reviewed did not indicate that any violations were identified.

Based on review of the Sonoma County Environmental Health Department files, no recognized environmental conditions were identified.

Town of Windsor Building and Planning Departments
The Building and Planning Departments are responsible for processing applications for new development and for long range planning of the City, including maintaining the General and Specific Plans. On March 13, 2013 HES meet with a Town of Windsor Building Department Technician and reviewed the property file. The following information was obtained about the subject site:

- The Town of Windsor identified the site as Parcel Nos. 056-271-082; 056-271-095; 056-221-098, and 056-271-104.
- There is a current Master Plan for the subject site. The Master Plan includes phasing of infrastructure improvements including roadways, drainage, and utilities. In addition, the Master Plan calls for subdividing some existing parcels.
- The zoning of the site is listed as "Light Industrial / Heavy Industrial and Light Manufacturing". The Master Plan on file with the Town of Windsor has added a "Planned Development District / Airport Safety / Floodplain" classification to the current zoning.
- Several permit related documents were identified for the FED EX facility that was recently constructed immediately south of the subject site on land formerly owned by SSI.
- Several permit related documents were also identified for parcel 082 which included bathroom remodels and electrical upgrades.

From review of Building and Planning Department files, HES did not identify any new information regarding hazardous materials at the site.

Windsor Fire Department – Hazardous Materials Division
On March 6, 2013 HES contacted the Town of Windsor Fire Department (WFD) to determine if any hazardous material files for the subject property were maintained by the WFD. Based on our conversation with WFD representatives, we understand Sonoma Soil Builders, a tenant at 5900 Pruitt Avenue, was inspected in October 2012. During the site inspection an unpermitted diesel AST was identified on the property. According to the WFD, the owner

was notified of the violation and the AST was subsequently removed from the property. No ASTs were identified at the Sonoma Soil Builders site during HES's site inspection. The WFD indicated that they contacted Sonoma Soil Builders a few weeks after the inspection and they indicated that the AST has been removed.

Based on our discussions with the WFD we did not identify any recognized environmental conditions at the site.

North Coast Regional Water Quality Control Board (NCRWQCB)

On March 13, 2013 HES reviewed files for the subject property at the NCRWQCB. Industrial storm water permits (NPDES) have been issued at for the subject site for approximately 14 years. As part of the permit requirements, SSI was required to collect storm water runoff samples at two (2) separate locations on the property. Sample data were reviewed at the NCRWQCB office and the data indicated that low levels of diesel, oil, and grease had been detected in the runoff at various times. The detections were considered low and the NCRWQCB did not take any action against SSI. In addition, the NCRQWCB files identified an oil/water separator that exists on the subject site. The oil/water separator was also identified during HES's site inspection and is located on the west side of the main SSI building located on parcel 104, as seen on the Site Plan, Figure2. Drains located in the equipment and maintenance area convey water to an oil/water separator. Water is discharged to the on-site stor-water collection system and the oil is pumped out as needed.

Historically, the site operated a glue evaporation pond on parcel 095. The NCRWQCB alleged that glue wastes were being discharged to this surface pond. Soil and groundwater samples were collected from around the pond and from Pruitt Creek. The NCRWQCB issued Clean-up and Abatement order No. 80-190 in October of 1980, stipulating that no more waste water be discharged to the pond and that the pond be properly abandoned. In June 1981, the Clean-up and Abatement Order was rescinded after the pond removal had been completed and assessed. In September 1980, an EPA Field Inspection Team (FIT) observed small pools of liquid beneath the above ground storage tanks that contained glue used in manufacturing of SSI products (phenol, resorcinol, and paraformaldehyde). In January 1990, the FIT collected a total of seven (7) groundwater samples and eight (8) soil samples at various locations on the SSI property. Based on a review of the analytical test results, and on an EPA Hazard Ranking System (HRS) evaluation, the EPA decided that further sampling and analytical testing was not necessary. A copy of the Screening Site Inspection Re-assessment document, by Ecology and Environment, Inc., dated March 15, 1991 is attached as APPENDIX G. *Information obtained from the NCRWQCB identified the presence of industrial storm water permits, however, the lack of identified violations indicates that these permits do not constitute recognized environmental conditions at the site. The glue pond that formerly existed on the property was considered a recognized environmental condition however based on the EPA's assessment no additional work is required.*

Sonoma County Water Agency

On March 25, 2013 HES spoke with an official at the Sonoma County Water Agency regarding the flow of water in Pruitt Creek. HES also discussed the surface water and stream flow with Town of Windsor officials. Based on these discussions HES understands that

surface water drains Pruitt Creek and Airport Creek and flows southwesterly until it intersects with the Russian River. Water is then transported westerly to the Pacific Ocean.

Sonoma County Recorder's Office

On March 26, 2013 HES reviewed files at the Sonoma County Recorder's Office to determine if any environmental liens had been placed on the subject site. *No environmental liens currently exist on file at the Sonoma County Recorder's office for the subject site.*

Sonoma County Department of Emergency Services

On March 18, 2013 HES reviewed files for the subject property at the Sonoma County Department of Emergency Services (SCDES). The SCDES maintains files regarding hazardous materials for the subject site. The SCDES also maintains historical files related to hazardous material permitting and inspections for the subject site. During our file review we encountered several hazardous material business plans (HMBP) for SSI. The HMBPs included the chemicals acetylene, auto oil, carbon dioxide, diesel, end seal, gasoline, gear oil, grease, hydraulic fluid, propane, resorabond (glue related product), transmission fluid, waste oil and others. The files indicate that the on-site ASTs are permitted and no AST violations were reported in the historical inspection reports reviewed. Photos from a 2004 site inspection indicate that the on-site storm water collection system was also inspected by the SCDES and that no obvious violations were present.

No new information was identified in these files related to the recognized environmental conditions that exist at the subject site. We were aware that the site was a RCRA SQG and that hazardous materials were handled at the site. We were also aware that ASTs exist on-site and did not identify any violations or spill documentation in the inspection reports reviewed.

5.0 ON-SITE ENVIRONMENTAL ASSESSMENT

5.1 Underground Storage Tanks (USTs)

No USTs have been identified on the subject property. *Based on the lack of USTs identified at the site, on-site USTs are not considered a concern to the investigation.*

5.2 Aboveground Storage Tanks (ASTs)

Two (2) 1,000-gallon ASTs were observed at the subject site during the site inspection, one diesel and one gasoline. The AST's are permitted and protected with a concrete, secondary spill containment berm. One fuel dispenser services the two (2) AST's and insignificant evidence of spillage was observed from the dispenser during our inspection. The ASTs are located on the southern portion of the site as shown on the Site Plan Figure 2. No permit violations were identified in the file at the Sonoma County Dept. of Emergency Services. *Based on the condition of the ASTs and the lack of identified fire department violations, the ASTs at this site are not considered a concern to the investigation.*

5.3 Hazardous Material Storage

During the time that SSI operated at the subject property (1972-2012) several hazardous materials were stored at the site. A complete hazardous materials inventory for past operations was reviewed at the Sonoma County Fire Department office. Hazardous materials identified included; acetylene, automobile oil, carbon dioxide, end seal, gear oil, grease, hydraulic fluid, propane, resorabond, transmission fluid, and wayoil. Historically, there has been waste oil stored in secondary containment areas located on the west side of the SSI building on lot 104. During the March 12, 2013 site visit there were no significant signs of surface staining proximate to the diesel and gasoline ASTs and dispenser, and no signs of surface soil staining proximate to the waste oil storage area. *Hazardous Material storage at the site is not considered a concern to the investigation.*

5.4 Solid (Non-Hazardous) Waste

No signs of significant non-hazardous solid waste were identified at the site during our March 12, 2013 site reconnaissance. Historically, glue waste was dried and disposed of as non-hazardous waste to offsite Class I disposal facilities *Non-hazardous waste at this site is not considered a concern to this investigation.*

5.5 Hazardous Waste

Hazardous waste at this site is generally limited to waste oils, solvents, and other automobile and engine related fluids. Historically, hazardous waste generated at the site was collected and disposed of under manifest by Evergreen Environmental Services every 30-90 days. Currently, hazardous waste storage has diminished and is picked up and disposed of on an as needed basis. *The hazardous waste identified at this site is primarily historical and generally refers to petroleum related products. These chemicals have not been shown to have impacted soil or groundwater at the site and are not considered a recognized environmental condition at this time. However, we have recommended that water samples be collected from the on-site irrigation well and tested for chemicals used both on-site and found off-site. If it is determined that chemicals used on-site are found in the groundwater then a compete assessment of hazardous material usage and handling should be performed.*

5.6 Polychlorinated Biphenyls (PCBs) Containing Equipment

No indication of PCB containing equipment was identified during the site inspection. *Due to the absence of PCB containing equipment at the site, PCBs are not considered a concern to this investigation.*

5.7 Water/Storm Water/Wetlands/Wells

Water

The Town of Windsor maintains storm sewers along Shiloh Road and adjacent to the subject property. HES did not observe evidence of stains or spills at nearby storm drains. A private irrigation well is located on the property and the Town of Windsor provides water for domestic use.

The EDR Database Report identified five (5) additional water supply wells that are located within a 1-mile radius of the site. The closest wells identified are between 1/4 and 1/2 mile north from the subject site. *Based on the distance to the water wells from the subject property, the wells are not considered a concern to the investigation. However, the on-site irrigation well is considered a potential concern to the investigation. Since the site has a history of hazardous material usage and storage, and since well usage has the potential to draw in contamination from other nearby sites, we recommend that the irrigation well be tested for potential impacts.*

Storm water

Storm water from the site flows through underground and aboveground conduits until it reaches either Airport or Pruitt Creek. These creeks flow southwesterly until they intersect the Russian River. The Russian River also flows south westerly until it drains into the Pacific Ocean near Jenner, CA.

Wetlands

Wetland areas are defined as those areas that are inundated or saturated by surface or ground water at a frequency and duration sufficient to support, and that under normal circumstances do support, a prevalence of vegetation typically adapted for life in saturated soil conditions. Wetlands generally include swamps, marshes, bogs, and similar areas. The USDA Soil Conservation Service classifies the soil at the site as "Huichica"; this soil does not meet the requirements for a hydric soil. According to FEMA, Federal Insurance Rate Map 06097C, dated December 2, 2008 the site is located outside of the 100-year Flood Zone and within the 500-Year Flood Zone. According to the National Wetlands Inventory Map referenced in the EDR Radius Map Report (APPENDIX F), the site is not located within a designated wetland area. During our limited site visit, HES did not observe obvious wetland conditions at the site.

5.8 Air Emissions

Historically, SSI was permitted by the Bay Area Air Management District (BAAQMD) for four (4) sources and one exempt source (Plant #4982). The permits are no longer active and no air emissions permits are currently active at the site. *Since the subject property is not currently listed on the Air Emissions database, and since no historical violations were identified, air emissions are not considered a concern to the investigation.*

5.9 Dry Cleaning Operations

HES conducted a limited inspection of the site and researched available historical records to identify evidence of on-site dry cleaning operations. HES did not identify any current or historical dry cleaning facilities at the subject site. No dry cleaning facilities were identified with the ASTM search radius. *Dry cleaning operations are not considered a concern to the investigation.*

5.10 Asbestos

HES performed an inspection of the on-site buildings on March 12, 2013. Our inspection included the inside of the former SSI buildings on lots 104 and 095. HES is not a licensed asbestos consultant, however, based on the age of the SSI structures (1970's or earlier) it is likely that asbestos containing materials (ACM) are present in some of the construction materials at this location. In addition, a previous Phase I ESA performed by NAC in 1999 identified ACM in the boiler insulation along with suspected ACM in piping coming in and out of the boiler[4].

From our review of available site history and based on the age of the structures we suspect that ACM exists at these locations. While the potential presence of these materials is not considered a recognized environmental condition it should be noted in case future site operations or development involves disturbance of the building materials.

[4] Phase I Environmental Site Assessment Report, Standard Structures Property, 920 Shiloh Road Windsor, CA, prepared by National Assessment Corporation, dated September 23, 1999.

5.11 Lead Based Paint

An assessment of lead based paint was not made. However, the dates of construction for the structures at the subject property (1960's and 1970's) are prior to lead based paints being outlawed in California in 1978. Therefore, it's possible that lead based paint was used on the painted surfaces of buildings at these locations.

5.11 Radon Information

Radon information was included in the Environmental Database Report provided by EDR. Based on the data presented, we understand that fifteen (15) radon samples have been collected in the 95492 area code and all sample results were below the EPA action level of 4pci/L. *Therefore radon is not considered a concern to the investigation.*

6.0 REVIEW OF NEARBY/ADJACENT PROPERTIES

The site is located in a mixed industrial and manufacturing area within the Town of Windsor, California.

North: The site is bounded to the north by Shiloh Road. On the north side of Shiloh Road is a former gasoline station. The station has been closed for several years and remediation related to former leaking underground storage tanks has occurred. The site is now eligible for regulatory site closure. A residential ranch property is located north of the former gasoline station.

South: The site is bounded to the south by vacant land and by agricultural fields. South of the vacant lands is a school and a residential subdivision.

West: The site is bounded to the east by a light industrial and commercial facility, 930 Shiloh Road. The site is the former location of the Ecodyne wood treatment company and is currently receiving remediation for wood treatment related soil and groundwater contamination. Immediately west of the former Ecodyne site is the northwest Pacific Railroad and west of the railroad are large office building developments.

East: The site is bordered to the east by California State Highway 101. East of the highway are vacant land and agricultural fields.

The inspection of the neighboring properties from curbside and a review of Federal, State and local regulatory agency files revealed that recognized environmental conditions exists on adjacent properties to the west and north. The subject property, formerly associated with SSI, also has recognized environmental conditions. Details of the nearby contaminated sites and the former SSI site are discussed in detail in section 4.2 of this Report.

7.0 DATA GAPS

A fifty-year Chain of Title was not reviewed for this ESA. Based on the other historical information available for the site and the current owners length of ownership (40+years) this data gap is not considered a concern to the investigation.

8.0 DISCUSSION OF FINDINGS

Hurvitz Environmental Services performed a Phase I Environmental Site Assessment for the Standard Industrial property located at 5900 Pruitt Avenue in Windsor, CA. Additional addresses associated with the subject property include 5885, 5887, 5891, 5895 and 5937 Pruitt Avenue, as well as 920 Shiloh Road and 340 Standard Avenue. The site consists of four (4) contiguous parcels which create an irregularly shaped, approximately 88-acre property located on the south side of Shiloh Road and immediately west of State Highway 101. The Assessors Parcel numbers (APN) are as follows 059-271-082, 059-271-095, 059-271-098, 059-271-104.

The Standard Industrial site is currently utilized by several light industrial and manufacturing businesses. A complete list of the current tenants is attached in Appendix A. A large portion of the subject property was first developed in the late 1950's by Fluor Corporation as an engineered wood product manufacturing facility. Since 1972, the subject site has been occupied by Standard Structures Inc. (SSI). SSI owned and operated a laminated wood beam manufacturing facility at the site from 1972 to 2012. SSI is no longer in business however the former business owner, Mr. Richard Caletti, is still an owner of the property.

According to a Site Screening performed at the site in 1991 by Ecology and Environment Inc, two (2) glue waste water settling ponds previously existed at the northwest end of the site. The NCRWQCB issued the facility waste discharge requirements under order # 74-83 in 1974 which prohibited the drainage of glue waste to any holding or disposal pond. SSI eliminated the use of the ponds at that time and added a decorative pond adjacent to the State Highway 101. In 1980, the NCRWQCB observed glue wastes being dumped into the on-site decorative pond. The pond and adjacent Pruitt Creek were sampled by the NCRWQCB on October 27, 1980. Phenol was present in the pond water and phenolic compounds were present in the pond soil. As a result the NCRWQCB issued a Cleanup and Abatement Order (CAO) No 80-190 to the facility on October 1, 1980 to abate waste discharge to the pond and to remove the pond waste and close the pond. On June3, 1981, the NCRWQCB rescinded the CAO under Order No. 81-140 because all cleanup and abatement activities were completed and had been assessed.

In January 1990, under the authority of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 (CERCLA) and the Superfund Amendments and Reauthorization Act of 1986 (SARA) the US Environmental Protection Agency (EPA) tasked Ecology and Environment, Inc's Field Investigation Team (FIT) to conduct a Screening Site Inspection of the Standard Structures site. During the Site Screening soil and groundwater samples were collected. The sample results were found to be inconclusive and the final assessment concluded that further assessment was unnecessary. However, in 1991 the EPA revised the Hazard Ranking System (HRS) and asked Ecology and Environment Inc., to re-assess the Standard Structures Site. The site re-assessment concluded that no further remedial action was to be planned under CERCLA. The basis for the assessment stated that the predominant hazardous substances utilized at SSI were phenol, resorcinol, methylene chloride, and paraformaldehyde, which all have low toxicity values. In addition, an observed release to groundwater had not been documented at the site.

Since the mid 1990's, the site operated under an industrial storm-water permit. The site utilizes an oil/water separator near the vehicle maintenance area that separates the oil from the water before it is discharged. The permit called for periodic sampling at two (2) storm-water discharge points on the property. No significant contaminant detection occurred during the storm-water sampling events.

The site also has two (2) active 1,000-gallon AST's used to store gasoline and diesel fuel. The AST's are permitted and have a secondary containment system. There is also waste oil storage on the property within a contained and well maintained area. No significant hazardous material related violations were identified during our review of site inspection reports from the local hazardous material inspectors.

An irrigation well exists on the subject site and was formerly used to fill a fire suppression pond on the property. The site is connected to Windsor Town water and the well is not currently in use. In addition, a private sewage disposal system consisting of several septic tanks and two (2) sewage evaporation ponds formerly exited on the site. The ponds and tanks were abandoned once the Town of Windsor sewer service was provided to the site.

The adjacent property to the west is currently undergoing active remediation for activities related to a wood treatment facility that formerly operated there (Ecodyne Corporation). The facility has been divided into two (2) separate investigation areas in which one is regulated by the NCRWQCB and the other is regulated by the DTSC. Ecodyne is the main responsible party identified for the investigation and cleanup. The contamination at the site has affected both soil and groundwater and consists primarily of Chromium VI, pentchlorophenol and PAHs. The contamination at this site appears to be fairly well contained and the local groundwater flow direction is away from the subject site. The potential for this site to affect the subject property is considered low. However, there is documented use of an irrigation well on the subject property. The use of the irrigation well may potentially have pulled contaminants onto the site from the former Ecodyne site.

8.1 Major Findings

MAJOR FINDINGS

- The site was utilized for grazing land in the 1940's and early 1950's. Site development began in the mid/late 1950's and the site was utilized at that time for manufacturing engineered wood beams. Standard Structures Inc. (SSI) took over the site in 1972 and continued with the manufacture of glue laminated wood trusses. Additional development of the site occurred 1978. SSI operated there manufacturing businesses at the site until 2012. The site is currently utilized by several light industrial and manufacturing businesses who lease space at the former SSI facility.
- In 1990 and 1991, the site was investigated for glue waste being discharged to a surface pond on lot 059-271-095. Soil and water testing was performed and the Environmental Protection agency (EPA) recommended no further action at the site.
- Review of regulatory agency files indicates that there has been, and currently is, documented storage and handling of hazardous materials at the site. We did not find any evidence in the regulatory agency files reviewed that there has been mishandling of the hazardous materials on-site that would require a soil or groundwater investigation.
- Two (2) 1,000-gallon, fuel AST's exist on the subject property. The AST's contain gas and diesel and are located near the southwest corner of lot 059-271-104. Secondary spill containment is provided for the AST's and no evidence of a release was observed during our site inspection. Also, the Sonoma County Dept. of Emergency Services inspection records do not indicate any AST violations.
- The site was formerly serviced by an on-site sewage disposal system that consisted of several septic tanks and two (2) sewage evaporation ponds. The site has since been connected to city sewer and water service and the sewage ponds have been abandoned.
- There is an irrigation well located on the lot 059-271-104. The irrigation well is currently out of use but was formerly used to fill the fire suppression ponds on-site.
- Several nearby sites were identified on the EDR database report that have ongoing investigations. While most of the sites are hydrologically down-gradient from the subject property, there are adjacent sites that could pose a potential concern to the subject property. The former Ecodyne wood treatment plant is located to the west and has an ongoing investigation and cleanup related to chromium VI and PAHs. The former Ecodyne site has been divided into several industrial lots that are rented to various industrial and manufacturing businesses. These businesses have included trucking companies, metal recyclers, steal tank manufacturing, battery storage facilities and commercial landscape operations among others. Some of these businesses have also been identified on various environmental agency databases.
- SSI operated an industrial storm water permit for 14 years that included managing runoff and performing testing from two (2) designated run-off areas. No significant contaminant detections were made during the sampling period.
- There is an oil/water separator on the west side of lot 059-271-104. The oil/water separator was managed by SSI and waste was reportedly picked up and disposed of as needed by Evergreen Environmental.
- No landfills or hazardous material disposal areas have been identified on the subject site.

Onsite Concerns**:**

The following onsite concerns have been identified at the subject property.

- While no significant evidence of site contamination has been identified, the site has had a long history of hazardous chemical usage and storage as well as former glue evaporation ponds that contained paraformaldehyde and phenols.
- An onsite irrigation well as historically been used at the site and several nearby sites have been identified with impacted groundwater. Therefore, the potential for off-site contamination to be drawn-in from adjacent facilities exists.

Mitigation for Onsite Concerns

In order to determine if past chemical storage, usage, or disposal has contaminated groundwater and to determine if the former use of the onsite irrigation well has lead to the impact of groundwater at the subject property from adjacent properties, we recommend that the onsite well be tested. The well should be tested for chemicals that were formerly used on the subject property and for chemicals identified in nearby groundwater investigation. These chemicals include, paraformadehyde, phenol, PAH's, diesel, gasoline, motor oil, lead, and chromium VI.

Off-Site Concerns**:**

Regulatory agency records reviewed for this ESA indicate that hazardous material releases mainly associated with petroleum hydrocarbons have occurred at several nearby locations. At most locations the contaminant source areas have been defined and remedial efforts are underway, ongoing, or completed. However, one (1) former wood treatment facility has been identified adjacent to the west of the subject site. The Ecodyne site is currently being investigated for Chromium VI and PAH contamination and the effected groundwater in the immediate area. The NCRWQCB and the DTSC are over-seeing the investigations and remediation at this former wood treatment facility. The groundwater flow at this site is southwesterly and away from the subject site. However, since the subject property operated an irrigation well at the site for many years it is possible that the well has drawn-in contamination from the former Ecodyne facility or other near-site petroleum contaminated sites.

Mitigation for Off-Site Concerns

In order to determine if off-site contamination has been drawn-in to the subject property through the former use of the onsite irrigation we recommend that the well be sampled and analyzed for off-site chemical concerns. These chemical include Chromium VI and PAH's.

Data Gaps

A fifty-Year Chain of Title was not reviewed for this ESA. Based on the other historical information available for the site and current owners length of ownership (40+ years) this data gap is not considered a concern to the investigation.

8.2 Conclusions

By definition the former glue evaporation ponds on the subject property are considered a recognized environmental condition, however, based on the results of the EPA investigation they are not considered a concern to this investigation. The site has also had a long history of hazardous material usage and storage, however, there has not been any indication that a significant release to the environment has occurred from these practices. Several off-site contaminant investigation sites have been identified proximate to the subject property. These sites are discussed in section 4.1 and 4.2 of this report. In general, these sites are not considered a threat to the subject property. There is some potential that the former irrigation well used at the subject site may have draw-in contaminants from these nearby sites. Therefore, we recommend that that the former irrigation well be tested for the glue related chemicals used on-site and for the chemicals identified in the near-site contaminant investigations.

These findings and all information provided in this report are subject to limitations defined in Section 9 of this report. This report and the interpretations, conclusions and recommendations contained within are based in part on information presented in other documents that are cited in the text or listed as references. Therefore, this report is also subject to the limitations and qualifications presented in the referenced documents.

9.0 LIMITATIONS


Our professional services have been performed, our findings obtained, and our recommendations prepared in accordance with customary principles and practices in the fields of environmental science and engineering. This warranty is in lieu of all other warranties either expressed or implied. HES is not responsible for the independent conclusions, opinions or recommendations made by others based on the records review, site inspection, field exploration, and laboratory test data presented in this report.

It should be noted that all surficial environmental assessments are inherently limited in the sense that conclusions are drawn and recommendations developed from information obtained from limited research and site evaluations. Subsurface conditions were not field investigated as part of this study and may differ from the conditions implied by the surficial observations. Additionally, the passage of time may result in a change in the environmental characteristics at this site and surrounding properties. This report does not warrant against future operations or conditions, nor does this warrant operations or conditions present of a type or at a location not investigated. This report is not a regulatory compliance audit.

This study is not intended to assess if any soil contamination, waste emplacement, or groundwater contamination exists by subsurface sampling through the completion of soil borings and the installation of monitoring wells. The scope of work, determined by the client, did not include these activities.

HES reviewed past ownership of the project site in an attempt to determine past site usage. HES is not a professional title insurance firm and makes no guarantee, explicit or implied, that the listing which was reviewed represented a comprehensive delineation of past site ownership or tenancy for legal purposes.

This Report is for the exclusive use of Currie Properties, his affiliates, designates and assignees and no other party shall have any right to rely on any service provided by Hurvitz Environmental Services without prior written consent.



HURVITZ ENVIRONMENTAL
6650 CHERIE LANE
SEBASTOPOL, CA 95472
PH: 707.824.1690
FX: 707.824.2675
HURVITZ.ENVIRONMENTAL@GMAIL.COM
CA PG# 7573

SITE LOCATION MAP

STANDARD INDUSTRIAL
5900 PRUITT AVENUE
WINDSOR, CALIFORNIA

JOB NUMBER: 3062.01
DATE: 3-22-13
PLATE: 1

920 Shiloh Rd, Windsor, CA

Shiloh Rd

930 SHILOH RD

FORMER ECODYNE SITE

VACANT STORAGE

LOT 82

STORAGE YARD

NORTHGATE REDI-MIX

Pruitt Ave

101

PRUITT CREEK

WEST COAST METALS RECYCLING

FORMER STANDARD STRUCTURES PLANT A

FIREWATER POND

STAINLESS STEEL TANK MFG

Gallon Ave

Emkay Dr

WASTE OIL STORAGE

LOT 104

RECYCLING FACILITY

IRRIGATION WELL

Bethart Blvd

Kittyhawk Blvd

LIGHT INDUSTRIAL FACILITY

FORMER STANDARD STRUCTURES PLANT B

Redwood Hwy

FORMER GLUE EVAPORATION POND

DIESEL/GASOLINE AST LOCATION

SR TOWING

LOT 98

LOT 95

IMAGE TREE SERVICE

PAR ELECTRIC

1055 ft

© 2013 Google

NOTE: ALL PROPERTY LINES ARE APPROXIMATE AND FOR REFERENCE ONLY

HURVITZ ENVIRONMENTAL
6650 CHERIE LANE
SEBASTOPOL, CA 95472
PH: 707.824.1690
FX: 707.824.2675
HURVITZ.ENVIRONMENTAL@GMAIL.COM
CA PG# 7573

SITE PLAN

STANDARD INDUSTRIAL
5900 PRUITT AVENUE
WINDSOR, CALIFORNIA

JOB NUMBER: 3062.01

DATE: 4-2-13

PLATE 2

HURVITZ ENVIRONMENTAL
GEOLOGIC & ENVIRONMENTAL CONSULTING

April 4, 2013
Job No. 3062.02

Currie Properties
P.O. Box 9361
San Rafael, CA 94912

Subject: Phase II Environmental Site Assessment
Standard Industrial – 5900 Pruitt Avenue

Dear Currie Properties:

Hurvitz Environmental Services (HES) prepared this Phase II Environmental Site Assessment (Phase II ESA) at the direction of Currie Properties, for the property identified as 5900 Pruitt Avenue in Windsor, California. The Phase II ESA was undertaken in support of due diligence conducted by Currie Properties, who plans to purchase a share in the subject property. The approximate location of the subject property is shown on the Site Location Map, Plate 1. The subject property is currently owned by Mr. Richard Caletti. This Phase II ESA was performed to document the condition of the property in regards to groundwater contamination and focuses on potential environmental impacts identified in a Phase I Environmental Site Assessment[1] (Phase I ESA). The identified potential impact includes groundwater contamination as a result of historical on-site and near-site activities.

In accordance with the recommendations outlined in the Phase I ESA, the following task was performed;

1. One (1) groundwater sample was collected from the irrigation well identified on-site.

This Phase II ESA report includes a detailed description of the groundwater sampling procedures, tabulated analytical data and our conclusions and recommendations. A Site Plan showing the general site features and the approximate boundaries of the areas of investigation is enclosed as Plate 2.

[1] Phase I Environmental Site Assessment, Standard Industrial; Windsor, Ca 95492, Prepared by Hurvitz Environmental Services, dated March 31, 2013.

SITE DESCRIPTION / BACKGROUND OVERVIEW

The site has historically been occupied by the Standard Structures Inc (SSI). SSI occupied the facility from approximately 1972 to 2012. The site was originally developed in the 1950's by Flour Corporation but was expanded upon by SSI in the late 1970's. The site is improved with one (1) main building, two (2) smaller drying sheds, a building with a drying kiln, one (1) firewater pond, and two (2) smaller tenant occupied buildings. The total parcel size is 30.67 acres. The ground floor area of the two-story main manufacturing building for the former SSI is approximately 200,000 sq/ft. The building has wood frame construction with open sides and galvanized sheet metal exterior. The majority of the building was used for manufacturing operations and there are several small interior offices and machine shop areas. The building is surrounded by asphalt on the north, south, and east sides with a gravel road on the west side of the building. The Northwest Pacific Railroad tracks border the site to the southwest and there are two (2) railroad spurs from these tracks that enter onto the subject property. The main SSI building is currently divided and used for various light industrial operations including soil mixing, tile manufacturing, and vehicle maintenance.

Parcel 104 is connected to Windsor City water and sewer. An irrigation well exists on the property but is currently not operational. Historical sewage waste water was collected in on-site septic tanks and piped to two (2) sewer evaporation ponds. The ponds have since been abandoned. A site map is included as PLATE 2.

INVESTIGATION METHODS AND RESULTS

In order to further investigate concerns identified during the Phase I ESA, HES collected a groundwater sample from the irrigation well located on-site. A detailed description of the work performed is provided below.

On March 20, 2013, HES was on-site to collect a groundwater sample from the irrigation well identified on parcel number 059-271-104. The well has a 12-inch diameter steel casing and reportedly extends to a depth of 100 feet below grade (BG). No power is currently supplied to the well and the well has reportedly been out of operation for 2 or more years. A surface mounted jet pump was located next to the well head and was the pump used to historically operate the well. Access to the well was made by removing a 4-inch diameter water pipe that extended out of from the well head. Upon removal of the piping, HES measured the depth to static groundwater using an oil/water interface probe. Static water was measured at approximately 16 feet BG and no free floating petroleum products were identified.

After the water level was measured, HES inserted a battery operated 2-inch diameter submersible well pump that was set at approximately 30 feet BG. HES pumped water from the well at a rate of 2-gallons per minute. After purging the well, the well pump was removed and groundwater samples collected. Groundwater samples were collected using a disposable bailer and then transferred to the appropriate containers supplied by the laboratory. Upon completion of the well

sampling, the sample containers were sealed, labeled, and stored under refrigerated conditions pending laboratory chemical analysis.

Laboratory Chemical Analysis

The groundwater sample collected was analyzed for, TPH as gasoline / diesel / motor oil, benzene, toluene, ethylbenzene, xylenes (BTEX), methyl tert butyl ether (MtBE), formaldehyde, chromium VI, lead, phenols and polynuclear aromatic hydrocarbons using EPA Test Methods, 8020, 8015, 8315, 218.6, 200.9, and 8270. The analytical results of the groundwater samples collected are presented below in Tables 1 and 2. Analytical Sciences Laboratories of Petaluma, California performed chemical analyses of the groundwater samples. The laboratory Reports including Chain-of-Custody documentation is provided in Appendix A.

Table 1: Groundwater Sample Fuel Component Results

Date	Sample ID	TPH-gasoline	TPH-diesel	TPH-motor oil	B	T	E	X	MtBE
		----------µg/L----------							
3-20-13	IW-1	<50	<50	<200	<0.5	<0.5	<0.5	<0.5	<2.5
< = Less than the indicated laboratory reporting limit									

Table 2: Groundwater Semi-Volatile and Metal Results

Date	Sample ID	Formaldehyde	Phenols	Polynuclear Aromatic Hydrocarbons (PAH's)	Chromium VI	Lead
		----------µg/L----------				
3-20-13	IW-1	<0.010	<50	<50	<1.0	18
< = Less than the indicated laboratory reporting limit						

SUMMARY OF FINDINGS

The analytical results of the irrigation well sampling indicates that lead was the only contaminant identified above the laboratory detection limit. The lead concentration of 18ug/L exceeds the Environmental Protection Agency's (EPA) "Action Level" of 15ug/L for drinking water. While lead was detected above the EPA action level for drinking water, it is not considered a concern to the investigation for the following reasons.

- The irrigation well sampled is not used for drinking water and the well has been out of use for two or more years.

- Lead detections in water systems are often the result of corrosion of the plumbing systems; and erosion of natural deposits. Lead leaches into water through corrosion which is a dissolving or wearing away of metal caused by a chemical reaction between water and your plumbing. Lead can leach into water from pipes, solder, fixtures and faucets (brass), and fittings. The amount of lead in your water also depends on the types and amounts of minerals in the water, how long the water stays in the pipes, the amount of wear in the pipes, the water's acidity and its temperature.


Since the well casing and plumbing are constructed of metal and since our purging of the well only minimally flushed the water in the well casing, we conclude that the lead detected is the result of corrosion of the plumbing system and does not appear to be resulting from on-site or off-site surficial sources.


CONCLUSIONS AND RECOMMENDATIONS

This Phase II investigation was performed to document the current site groundwater conditions and to evaluate the potential for contamination from both on-site and off-site sources. The analytical results of the sampling did not identify contaminants in the groundwater that are considered to be associated with known on-site or off-site sources. Therefore, based on these results we do not recommend any additional testing to evaluate the concerns identified in the March 29, 2013 Phase I ESA prepared by HES.

We appreciate the opportunity to be of service to you and trust that this provides the information you require at this time. If you have any questions or require any additional information please feel free to contact us at (707) 824-1690.


Sincerely,
HURVITZ ENVIRONMENTAL SERVICES





Lee S. Hurvitz, PG#7576
Principal Geologist

Attachments:
Plate 1, Site Location Map
Plate 2, Site Plan
Appendix A, Analytical Sciences Laboratory Report dated April 1, 2013



HURVITZ ENVIRONMENTAL
6650 CHERIE LANE
SEBASTOPOL, CA 95472
PH: 707.824.1690
FX: 707.824.2675
HURVITZ.ENVIRONMENTAL@GMAIL.COM
CA PG# 7573

SITE LOCATION MAP

STANDARD INDUSTRIAL
5900 PRUITT AVENUE
WINDSOR, CALIFORNIA

JOB NUMBER: 3062.01
DATE: 3-22-13
PLATE: 1

920 Shiloh Rd, Windsor, CA

Shiloh Rd

930 SHILOH RD

FORMER ECODYNE SITE

VACANT STORAGE

LOT 82

STORAGE YARD

NORTHGATE REDI-MIX

Pruitt Ave

101

PRUITT CREEK

WEST COAST METALS RECYCLING

FORMER STANDARD STRUCTURES PLANT A

FIREWATER POND

STAINLESS STEEL TANK MFG

Gallon Ave

Emkay Dr

WASTE OIL STORAGE

LOT 104

RECYCLING FACILITY

IRRIGATION WELL

Bethart Blvd

Kittyhawk Blvd

LIGHT INDUSTRIAL FACILITY

FORMER STANDARD STRUCTURES PLANT B

Redwood Hwy

FORMER GLUE EVAPORATION POND

DIESEL/GASOLINE AST LOCATION

SR TOWING

LOT 98

LOT 95

IMAGE TREE SERVICE

PAR ELECTRIC

1055 ft

© 2013 Google

NOTE: ALL PROPERTY LINES ARE APPROXIMATE AND FOR REFERENCE ONLY

HURVITZ ENVIRONMENTAL
6650 CHERIE LANE
SEBASTOPOL, CA 95472
PH: 707.824.1690
FX: 707.824.2675
HURVITZ.ENVIRONMENTAL@GMAIL.COM
CA PG# 7573

SITE PLAN

STANDARD INDUSTRIAL
5900 PRUITT AVENUE
WINDSOR, CALIFORNIA

JOB NUMBER: 3062.01

DATE: 4-2-13

PLATE 2

APPENDIX C: REGULATORY DATABASE REPORT

PARTNER

DATABASE REPORT

Project Property:	*790 Shiloh Road* *790 Shiloh Road* *WINDSOR CA 95492*
Project No:	*21-347251.1*
Report Type:	*Database Report*
Order No:	*21111700210*
Requested by:	*Partner Engineering and Science, Inc.*
Date Completed:	*November 18, 2021*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Table of Contents

Table of Contents.....2
Executive Summary.....3
Executive Summary: Report Summary.....4
Executive Summary: Site Report Summary - Project Property.....9
Executive Summary: Site Report Summary - Surrounding Properties.....11
Executive Summary: Summary by Data Source.....33
Map.....61
Aerial.....64
Topographic Map.....65
Detail Report.....66
Unplottable Summary.....626
Unplottable Report.....627
Appendix: Database Descriptions.....636
Definitions.....650

Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY

Reliance on information in Report: This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as database review of environmental records.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Inc. ("ERIS") using various sources of information, including information provided by Federal and State government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report (s) are protected by copyright owned by ERIS Information Inc. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

Executive Summary

Property Information:

Project Property:		*790 Shiloh Road* *790 Shiloh Road WINDSOR CA 95492*
Project No:		*21-347251.1*
Coordinates:		
	Latitude:	*38.52072644*
	Longitude:	*-122.78749577*
	UTM Northing:	*4,263,614.66*
	UTM Easting:	*518,524.62*
	UTM Zone:	*10S*
Elevation:		*120 FT*

Order Information:

Order No:	*21111700210*
Date Requested:	*November 17, 2021*
Requested by:	*Partner Engineering and Science, Inc.*
Report Type:	*Database Report*

Historicals/Products:

Aerial Photographs	*Historical Aerials (with Project Boundaries)*
City Directory Search	*Smart CD Search*
ERIS Xplorer	*ERIS Xplorer*
Excel Add-On	*Excel Add-On*
Fire Insurance Maps	*US Fire Insurance Maps*
Physical Setting Report (PSR)	*Physical Setting Report (PSR)*
Topographic Map	*Topographic Maps*
Vapor Screening Tool	*Vapor Screening Tool*

Executive Summary: Report Summary

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
Standard Environmental Records								
Federal								
DOE FUSRAP	Y	1	0	0	0	0	0	0
NPL	Y	1	0	0	0	0	0	0
PROPOSED NPL	Y	1	0	0	0	0	0	0
DELETED NPL	Y	0.5	0	0	0	0	-	0
SEMS	Y	0.5	0	0	0	0	-	0
ODI	Y	0.5	0	0	0	0	-	0
SEMS ARCHIVE	Y	0.5	0	0	0	0	-	0
CERCLIS	Y	0.5	0	0	0	0	-	0
IODI	Y	0.5	0	0	0	0	-	0
CERCLIS NFRAP	Y	0.5	0	0	0	0	-	0
CERCLIS LIENS	Y	PO	0	-	-	-	-	0
RCRA CORRACTS	Y	1	0	0	0	0	0	0
RCRA TSD	Y	0.5	0	**3**	**1**	**1**	-	**5**
RCRA LQG	Y	0.25	0	**2**	0	-	-	**2**
RCRA SQG	Y	0.25	0	**5**	**4**	-	-	**9**
RCRA VSQG	Y	0.25	0	0	0	-	-	0
RCRA NON GEN	Y	0.25	0	**26**	**18**	-	-	**44**
FED ENG	Y	0.5	0	0	0	0	-	0
FED INST	Y	0.5	0	0	0	0	-	0
LUCIS	Y	0.5	0	0	0	0	-	0
ERNS 1982 TO 1986	Y	PO	0	-	-	-	-	0
ERNS 1987 TO 1989	Y	PO	0	-	-	-	-	0
ERNS	Y	PO	0	-	-	-	-	0
FED BROWNFIELDS	Y	0.5	0	0	0	0	-	0
FEMA UST	Y	0.25	0	0	0	-	-	0
FRP	Y	0.25	0	0	0	-	-	0
HIST GAS STATIONS	Y	0.25	0	0	0	-	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
REFN	Y	0.25	0	0	0	-	-	0
BULK TERMINAL	Y	0.25	0	0	0	-	-	0
SEMS LIEN	Y	PO	0	-	-	-	-	0
SUPERFUND ROD	Y	1	0	0	0	0	0	0
State								
RESPONSE	Y	1	0	**1**	**1**	**1**	**1**	**4**
ENVIROSTOR	Y	1	0	**3**	**2**	**1**	**4**	**10**
DELISTED ENVS	Y	1	0	0	0	0	0	0
SWF/LF	Y	0.5	0	**11**	**3**	**1**	-	**15**
SWRCB SWF	Y	0.5	0	0	0	0	-	0
HWP	Y	1	0	0	0	0	0	0
SWAT	Y	0.5	0	0	0	0	-	0
C&D DEBRIS RECY	Y	0.5	0	**1**	**1**	**1**	-	**3**
RECYCLING	Y	0.5	0	**1**	0	0	-	**1**
PROCESSORS	Y	0.5	0	0	0	0	-	0
CONTAINER RECY	Y	0.5	0	0	0	0	-	0
LDS	Y	0.5	0	0	0	0	-	0
LUST	Y	0.5	0	**1**	0	**4**	-	**5**
DELISTED LST	Y	0.5	0	0	0	0	-	0
UST	Y	0.25	0	**1**	**1**	-	-	**2**
UST CLOSURE	Y	0.5	0	0	0	0	-	0
HHSS	Y	0.25	0	**1**	0	-	-	**1**
UST SWEEPS	Y	0.25	0	**1**	0	-	-	**1**
AST	Y	0.25	0	0	0	-	-	0
AST SWRCB	Y	0.25	0	0	0	-	-	0
TANK OIL GAS	Y	0.25	0	0	0	-	-	0
DELISTED TNK	Y	0.25	0	**2**	**1**	-	-	**3**
CERS TANK	Y	0.25	0	**3**	**2**	-	-	**5**
DELISTED CTNK	Y	0.25	0	0	0	-	-	0
HIST TANK	Y	0.25	0	**1**	0	-	-	**1**
LUR	Y	0.5	0	0	0	0	-	0
CALSITES	Y	0.5	0	**1**	0	0	-	**1**
HLUR	Y	0.5	0	0	0	0	-	0
DEED	Y	0.5	0	**1**	0	0	-	**1**

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
VCP	Y	0.5	0	**1**	**1**	0	-	**2**
CLEANUP SITES	Y	0.5	0	**3**	**1**	**4**	-	**8**
DELISTED COUNTY	Y	0.25	**2**	**10**	**10**	-	-	**22**
Tribal								
INDIAN LUST	Y	0.5	0	0	0	0	-	0
INDIAN UST	Y	0.25	0	0	0	-	-	0
DELISTED ILST	Y	0.5	0	0	0	0	-	0
DELISTED IUST	Y	0.25	0	0	0	-	-	0
County								
LOP SONOMA	Y	0.5	0	**1**	0	**4**	-	**5**
CUPA SONOMA	Y	0.25	0	**30**	**22**	-	-	**52**
CUPA PETALUMA	Y	0.25	0	0	0	-	-	0
Additional Environmental Records								
Federal								
PFAS NPL	Y	0.5	0	0	0	0	-	0
FINDS/FRS	Y	PO	**1**	**2**	-	-	-	**3**
TRIS	Y	PO	0	-	-	-	-	0
PFAS TRI	Y	0.5	0	0	0	0	-	0
PFAS WATER	Y	0.5	0	0	0	0	-	0
HMIRS	Y	0.125	**10**	**13**	-	-	-	**23**
NCDL	Y	0.125	0	0	-	-	-	0
TSCA	Y	0.125	0	0	-	-	-	0
HIST TSCA	Y	0.125	0	0	-	-	-	0
FTTS ADMIN	Y	PO	0	-	-	-	-	0
FTTS INSP	Y	PO	0	-	-	-	-	0
PRP	Y	PO	0	-	-	-	-	0
SCRD DRYCLEANER	Y	0.5	0	0	0	0	-	0
ICIS	Y	PO	0	-	-	-	-	0
FED DRYCLEANERS	Y	0.25	0	0	0	-	-	0
DELISTED FED DRY	Y	0.25	0	0	0	-	-	0
FUDS	Y	1	0	0	0	**1**	0	**1**
FORMER NIKE	Y	1	0	0	0	0	0	0
PIPELINE INCIDENT	Y	PO	0	-	-	-	-	0
MLTS	Y	PO	0	-	-	-	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
HIST MLTS	Y	PO	0	-	-	-	-	0
MINES	Y	0.25	0	0	0	-	-	0
SMCRA	Y	1	0	0	0	0	0	0
MRDS	Y	1	0	0	0	0	0	0
URANIUM	Y	1	0	0	0	0	0	0
ALT FUELS	Y	0.25	0	0	**1**	-	-	**1**
SSTS	Y	0.25	0	0	0	-	-	0
PCB	Y	0.5	0	0	0	0	-	0
State								
DRYCLEANERS	Y	0.25	0	0	0	-	-	0
DELISTED DRYCLEANERS	Y	0.25	0	0	0	-	-	0
DRYC GRANT	Y	0.25	0	0	0	-	-	0
PFAS	Y	0.5	0	0	0	0	-	0
PFAS GW	Y	0.5	0	0	0	0	-	0
HWSS CLEANUP	Y	0.5	0	0	0	**1**	-	**1**
DTSC HWF	Y	0.5	0	0	0	0	-	0
INSP COMP ENF	Y	1	0	0	0	0	0	0
SCH	Y	1	0	0	0	0	0	0
CHMIRS	Y	PO	0	-	-	-	-	0
HIST CHMIRS	Y	PO	0	-	-	-	-	0
HAZNET	Y	PO	**3**	**2**	-	-	-	**5**
HIST MANIFEST	Y	PO	0	-	-	-	-	0
HW TRANSPORT	Y	0.125	0	0	-	-	-	0
WASTE TIRE	Y	PO	0	-	-	-	-	0
MEDICAL WASTE	Y	0.25	0	0	0	-	-	0
HIST CORTESE	Y	0.5	0	**1**	0	0	-	**1**
CDO/CAO	Y	0.5	0	**5**	0	0	-	**5**
CERS HAZ	Y	0.125	0	**14**	-	-	-	**14**
DELISTED HAZ	Y	0.5	**1**	**9**	**1**	**5**	-	**16**
GEOTRACKER	Y	0.125	0	0	-	-	-	0
MINE	Y	1	0	0	0	0	0	0
LIEN	Y	PO	0	-	-	-	-	0
WASTE DISCHG	Y	0.25	0	0	0	-	-	0
EMISSIONS	Y	0.25	**1**	**10**	**8**	-	-	**19**
CDL	Y	0.125	0	0	-	-	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
Tribal	***No Tribal additional environmental record sources available for this State.***							
County	***No County additional environmental databases were selected to be included in the search.***							
Total:			***18***	***166***	***78***	***24***	***5***	***291***

**** PO – Property Only***
**** 'Property and adjoining properties' database search radii are set at 0.25 miles.***

Executive Summary: Site Report Summary - Project Property

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
1	FINDS/FRS	STANDARD STRUCTURES INC	920 SHILOH ROAD WINDSOR CA 95492 ***Registry ID:*** *110001177324*	NW	0.00 / 0.00	-6	66
1	HMIRS		920 SHILO RD WINDSOR CA	NW	0.00 / 0.00	-6	66
1	HMIRS		920 SHILOH RD SANTA ROSA CA	NW	0.00 / 0.00	-6	68
1	HMIRS		920 SHILOH RD #350 WINDSOR CA	NW	0.00 / 0.00	-6	70
1	HMIRS		920 SHILOH ROAD WINDSOR CA	NW	0.00 / 0.00	-6	71
1	HMIRS		920 SHILOH ROAD STE 350 WINDSOR CA	NW	0.00 / 0.00	-6	76
1	HAZNET	STANDARD STRUCTURES INC	920 SHILOH WINDSOR CA 954920000	NW	0.00 / 0.00	-6	78
1	HAZNET	FED EX GROUND	920 SHILOH RD UNIT 350 WINDSOR CA 95492	NW	0.00 / 0.00	-6	83
1	DELISTED HAZ	Standard Structures, Inc.	920 SHILOH RD WINDSOR CA 95492	NW	0.00 / 0.00	-6	84
1	EMISSIONS	STANDARD STRUCTURES INC	920 SHILOH ROAD WINDSOR CA 95492	NW	0.00 / 0.00	-6	84
1	HMIRS		920 SHILOH RD SANTA ROSA CA	NW	0.00 / 0.00	-6	92
1	HMIRS		920 SHILO RD WINDSOR CA	NW	0.00 / 0.00	-6	93
1	HMIRS		920 SHILOH ROAD STE 350 WINDSOR CA	NW	0.00 / 0.00	-6	95

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
1	HMIRS		920 SHILOH ROAD WINDSOR CA	NW	0.00 / 0.00	-6	97
1	HMIRS		920 SHILOH RD #350 WINDSOR CA	NW	0.00 / 0.00	-6	101
2	DELISTED COUNTY	MEED CLARK LUMBER	960 CALETTI WINDSOR, CA 95492 CA	NW	0.00 / 0.00	-8	103
2	DELISTED COUNTY	Mead Clark Lumber Company, Inc.	960 Caletti Av Windsor, CA 95492 CA	NW	0.00 / 0.00	-8	103
2	HAZNET	1X SOCO STEEL FABRICATIONS INC	960 CALETTI WINDSOR CA 954920000	NW	0.00 / 0.00	-8	103

Executive Summary: Site Report Summary - Surrounding Properties

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
3	FINDS/FRS	STANDARD STRUCTURESNA INC.	CA ***Registry ID:*** 110066178200	NW	0.00 / 2.41	-6	104
4	CLEANUP SITES	REDWOOD SANITARY SERVICE FIRE	511 SHILOH ROAD WINDSOR CA 95492 ***Status	Site Facility Type:*** COMPLETED - CASE CLOSED | CLEANUP PROGRAM SITE	NW	0.00 / 12.69	-7	104
5	HHSS	TEXACO	701 SHILOH RD WIMDSOR CA 95492	NW	0.00 / 20.90	-6	107
5	HAZNET	AUTO VISION OF WINDSOR	701 SHILOH RD WINDSOR CA 954920000	NW	0.00 / 20.90	-6	107
5	HAZNET	VIC'S AUTO REPAIR	701 SHILOH RD WINDSOR CA 954920000	NW	0.00 / 20.90	-6	107
5	HIST TANK	TEXACO	701 SHILOH RD. WINDSOR CA	NW	0.00 / 20.90	-6	108
6	HIST CORTESE	ECODYNE POND	930 SHILOH RD WINDSOR CA 95492	NW	0.01 / 64.11	-10	108
7	FINDS/FRS	REDWOOD SANITARY SERVICE FIRE	511 SHILOH ROAD WINDSOR CA 95492 ***Registry ID:*** 110066648792	NNW	0.02 / 93.91	2	108
8	SWF/LF	Windsor Oaks	899 Shiloh Road Windsor CA 95492	NW	0.02 / 115.85	-11	109
9	HMIRS		5900 Pruitt Ave. WINDSOR CA	NW	0.02 / 121.27	-6	109
9	SWF/LF	SCWS Emergency CDI Processing	5900 Pruitt Ave. Windsor CA 95492	NW	0.02 / 121.27	-6	116
9	SWF/LF	Pruitt Transload Facility	5900 Pruitt Ave. Windsor CA 95492 ***Act Opl Status	Activity:*** Active | Medium Volume Transfer/Processing Facility	NW	0.02 / 121.27	-6	116

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
9	SWF/LF	SCWS Wood Processing Operation	5900 Pruitt Ave. Windsor CA 95492	NW	0.02 / 121.27	-6	118
			***Act Opl Status	Activity:*** Active	Chipping and Grinding Facility/Operation		
9	SWF/LF	PRS Inert Debris Processing Operation	5900 Pruitt Ave. Windsor CA 95492	NW	0.02 / 121.27	-6	119
9	RCRA NON GEN	WESTERN TREE REMOVAL SPECIALISTS	5900 PRUITT AVE STE 532 WINDSOR CA 95492	NW	0.02 / 121.27	-6	120
			EPA Handler ID: CAL000429102				
9	SWF/LF	Atlas Tree Surgery Reduction Yard	5900 Pruitt Ave. Windsor CA 95492	NW	0.02 / 121.27	-6	121
9	SWF/LF	Atlas Tree Processing Yard	5900 Pruitt Ave. Windsor CA 95492	NW	0.02 / 121.27	-6	122
9	SWF/LF	PRS Direct Transfer Operation	5900 Pruitt Ave. Windsor CA 95492	NW	0.02 / 121.27	-6	123
10	DELISTED TNK	MOBIL STATION (FORMER)	705 SHILOH RD WINDSOR CA 95492	NW	0.03 / 142.75	-5	124
10	DELISTED TNK	MOBIL STATION (FORMER)	705 SHILOH ROAD WINDSOR CA 95492	NW	0.03 / 142.75	-5	124
10	LOP SONOMA	Mobil Station (former)	705 Shiloh Rd Windsor CA	NW	0.03 / 142.75	-5	124
			***LOP No	Status Desc:*** 00002581	Closed Site		
10	CUPA SONOMA	Windsor Valero	705 Shiloh Rd Windsor, CA 95492 CA	NW	0.03 / 142.75	-5	124
10	LUST	MOBIL STATION (FORMER)	705 SHILOH RD WINDSOR CA 95492	NW	0.03 / 142.75	-5	125
			***Global ID	Status	Status Date:*** T0609700081	COMPLETED - CASE CLOSED	8/16/2013		
10	DELISTED COUNTY	SHILOH UNION 76 GAS STATION	705 SHILOH ROAD WINDSOR, CA 95492- CA	NW	0.03 / 142.75	-5	146
10	CERS TANK	Windsor Valero	705 SHILOH RD WINDSOR CA 95492	NW	0.03 / 142.75	-5	146
			Site ID: 387408				

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
10	UST	Windsor Valero	705 Shiloh Rd Windsor CA 95492 ***Facility ID:*** 49-000-007981	NW	0.03 / 142.75	-5	155
10	EMISSIONS	FORMER MOBIL STATION 99-HLH C/	705 SHILOH ROAD WINDSOR CA 95492	NW	0.03 / 142.75	-5	156
10	RCRA NON GEN	EXXONMOBIL OIL CORPORATION #99HLH	705 SHILOH RD WINDSOR CA 95492-0000 ***EPA Handler ID:*** CAL921054218	NW	0.03 / 142.75	-5	157
10	RCRA NON GEN	B&B SERVICE STATION	705 SHILOH RD WINDSOR CA 95492 ***EPA Handler ID:*** CAL000395131	NW	0.03 / 142.75	-5	158
10	EMISSIONS	B & B SERVICE STATION	705 SHILOH RD WINDSOR CA 95492	NW	0.03 / 142.75	-5	159
10	RCRA NON GEN	SALKHI PETROLEUM INC DBA WINDSOR CHEVRON	705 SHILOH RD WINDSOR CA 95492 ***EPA Handler ID:*** CAL000449206	NW	0.03 / 142.75	-5	161
11	HMIRS		500 caletti ave WINDSOR CA	SSW	0.04 / 227.62	-1	162
11	CUPA SONOMA	FedEx Ground - ZSRO	500 Caletti Ave, Windsor, CA 95492 CA	SSW	0.04 / 227.62	-1	198
11	CERS HAZ	FedEx Ground - ZSRO	500 CALETTI AVE WINDSOR CA 95492	SSW	0.04 / 227.62	-1	198
11	HMIRS		500 caletti ave WINDSOR CA	SSW	0.04 / 227.62	-1	201
11	RCRA SQG	FEDEX GROUND PACKAGE SYSTEM INC	500 CALETTI AVE WINDSOR CA 95492 ***EPA Handler ID:*** CAR000239723	SSW	0.04 / 227.62	-1	239
12	CUPA SONOMA	West Coast Metals	470 Caletti Av Windsor, CA 95492 CA	WNW	0.05 / 256.88	-7	241
12	CERS TANK	West Coast Metals	470 CALETTI AV WINDSOR CA 95492 ***Site ID:*** 407501	WNW	0.05 / 256.88	-7	241

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
12	RCRA NON GEN	WEST COAST METALS	470 CALETTI AVE WINDSOR CA 95492-0000 ***EPA Handler ID:*** CAL000272499	WNW	0.05 / 256.88	-7	246
12	RECYCLING	BROGARD INC	470 CALETTI AVE WINDSOR CA 95492	WNW	0.05 / 256.88	-7	247
13	CERS HAZ	Ahlborn Structural Steel, Inc. -Pruitt	5937 PRUITT AVE WINDSOR CA 95492	NW	0.05 / 272.82	-6	248
13	CUPA SONOMA	Ahlborn Structural Steel, Inc. -Pruitt	5937 Pruitt Ave Windsor, CA 95492 CA	NW	0.05 / 272.82	-6	251
13	RCRA NON GEN	AHLBORN STRUCTURAL STEEL INC	5937 PRUITT AVE WINDSOR CA 95492 ***EPA Handler ID:*** CAL000456688	NW	0.05 / 272.82	-6	251
13	EMISSIONS	AHLBORN STEEL 4 FENCE	5937 PRUITT AVENUE WINDSOR CA 95492	NW	0.05 / 272.82	-6	252
14	CUPA SONOMA	Northgate Ready Mix	5922 Pruitt Ave Windsor, CA 95492 CA	NW	0.06 / 330.69	-6	253
14	DELISTED HAZ	Northgate Ready Mix	5922 PRUITT AVE WINDSOR CA 95492	NW	0.06 / 330.69	-6	253
14	EMISSIONS	NORTHGATE READY MIX	5922 PRUITT AVENUE WINDSOR CA 95492	NW	0.06 / 330.69	-6	254
14	CERS TANK	Northgate Ready Mix	5922 PRUITT AVE WINDSOR CA 95492 ***Site ID:*** 138858	NW	0.06 / 330.69	-6	257
14	RCRA NON GEN	NORTHGATE READY MIX	5922 PRUITT AVE WINDSOR CA 95492 ***EPA Handler ID:*** CAL000374302	NW	0.06 / 330.69	-6	264
15	SWF/LF	SMCI Windsor Fire Remediation Processing	5885 Pruitt Ave. Windsor CA 95492	NW	0.07 / 357.53	-6	265
15	SWF/LF	SMCI Windsor Receiving Yard	5885 Pruitt Ave. Windsor CA 95492	NW	0.07 / 357.53	-6	266

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
16	CUPA SONOMA	Quality Stainless Tanks	510 Caletti Ave, Windsor, CA 95492 CA	WNW	0.07 / 378.26	-7	266
16	DELISTED COUNTY	Quality Stainless Tanks	510 Caletti Ave. WINDSOR, CA 95492 CA	WNW	0.07 / 378.26	-7	267
16	CERS HAZ	Quality Stainless Tanks	510 CALETTI AVE WINDSOR CA 95492	WNW	0.07 / 378.26	-7	267
17	DELISTED COUNTY	Standard Structures, Inc.	5910 Pruitt Ave Windsor, CA 95492 CA	NW	0.07 / 393.04	-6	271
18	HMIRS		5900 pruiitt WINDSOR CA	NW	0.07 / 393.77	-6	271
18	DELISTED HAZ	TDE Equipment INC	5900 PRUITT AVE STE 710 WINDSOR CA 95492	NW	0.07 / 393.77	-6	273
18	HMIRS		5900 pruiitt WINDSOR CA	NW	0.07 / 393.77	-6	273
19	CUPA SONOMA	QUIZNO'S SUBS	6580 Hembree LN STE 260 Windsor, CA 95492 CA	NNW	0.07 / 395.03	-2	274
20	CUPA SONOMA	SHILOH OAKS COMPANY, LLC	5892 PRUITT AVE WINDSOR, CA 95492 CA	NW	0.08 / 397.07	-6	275
20	RCRA NON GEN	FRIEDMAN'S D.Y.	5892 PRUITT AVE NO 300 WINDSOR CA 95492 ***EPA Handler ID:*** CAL000463758	NW	0.08 / 397.07	-6	275
21	CUPA SONOMA	HIGH TECH BURRITO	6560 HEMBREE LN STE 178 WINDSOR, CA 95492 CA	NNW	0.09 / 451.10	1	276
21	RCRA NON GEN	SALLY BEAUTY SUPPLY #3859	6560 HEMBREE LN STE 186 WINDSOR CA 95492 ***EPA Handler ID:*** CAL000411992	NNW	0.09 / 451.10	1	276
21	CERS HAZ	Sally Beauty Supply #3859	6560 HEMBREE LN STE 186 WINDSOR CA 95492	NNW	0.09 / 451.10	1	278

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
21	CUPA SONOMA	Sally Beauty Supply #3859	6560 Hembree Ln Ste 186 Windsor, CA 95492 CA	NNW	0.09 / 451.10	1	280
22	CUPA SONOMA	O'Reilly Auto Parts #3553	6500 Hembree Ln 225, Windsor, CA 95492 CA	NNW	0.09 / 466.27	1	280
22	CUPA SONOMA	PIZZA GUYS	6500 Hembree LN STE # 202 Windsor, CA 95492 CA	NNW	0.09 / 466.27	1	281
22	CUPA SONOMA	WINGSTOP	6500 Hembree Ln Ste 205 Windsor, CA 95492 CA	NNW	0.09 / 466.27	1	281
22	CERS HAZ	O'Reilly Auto Parts #3553	6500 HEMBREE LN 225 WINDSOR CA 95492	NNW	0.09 / 466.27	1	281
22	CERS HAZ	WINGSTOP	6500 HEMBREE LN STE 205 WINDSOR CA 95492	NNW	0.09 / 466.27	1	283
22	C&D DEBRIS RECY	O'REILLY AUTO PARTS #3553	6500 HEMBREE LN STE 225 WINDSOR CA 95492	NNW	0.09 / 466.27	1	286
23	HMIRS		5900 PRUITT AVE #164 WINDSOR CA	NW	0.09 / 467.28	-6	286
23	HMIRS		5900 Pruitt Ave. Ste 164 WINDSOR CA	NW	0.09 / 467.28	-6	287
23	HMIRS		5900 pruitt ave # 164 SANTA ROSA CA	NW	0.09 / 467.28	-6	292
23	CUPA SONOMA	Sonoma Soil Builders	5900 Pruitt Ave Windsor, CA 95492 CA	NW	0.09 / 467.28	-6	294
23	CUPA SONOMA	KRISTAR	5900 Pruitt AVE STE 230 Windsor, CA 95492 CA	NW	0.09 / 467.28	-6	294
23	CUPA SONOMA	New Metal Coachworks, LLC	5900 Pruitt Ave # 104, Windsor, CA 95492 CA	NW	0.09 / 467.28	-6	294

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
23	CUPA SONOMA	Applied Chemical	5900 Pruitt Ave Ste 280 Windsor, CA 95492 CA	NW	0.09 / 467.28	-6	295
23	CUPA SONOMA	Siddiqui Rums Corporation	5900 Pruitt Ave Ste 404, Windsor, CA 95492 CA	NW	0.09 / 467.28	-6	295
23	CUPA SONOMA	West Coast Auto Craft	5900 PRUITT AVE STE 230 WINDSOR, CA 95492 CA	NW	0.09 / 467.28	-6	295
23	DELISTED HAZ	West Coast Auto Craft	590 PRUITT AVE STE 230 WINDSOR CA 95492	NW	0.09 / 467.28	-6	296
23	DELISTED HAZ	Applied Chemical	5900 PRUITT AVE STE 280 WINDSOR CA 95492	NW	0.09 / 467.28	-6	296
23	DELISTED HAZ	Shiloh Oaks Co., LLC	5900 PRUITT AVE WINDSOR CA 95492	NW	0.09 / 467.28	-6	296
23	DELISTED HAZ	Sonoma Soil Builders	5900 PRUITT AVE WINDSOR CA 95492	NW	0.09 / 467.28	-6	296
23	CERS HAZ	New Metal Coachworks, LLC	5900 PRUITT AVE # 104 WINDSOR CA 95492	NW	0.09 / 467.28	-6	297
23	CLEANUP SITES	SHILOH OAKS COMPANY	5900 PRUITT AVENUE WINDSOR CA 95492	NW	0.09 / 467.28	-6	300
			Status* | *Site Facility Type: COMPLETED - CASE CLOSED | CLEANUP PROGRAM SITE				
23	CUPA SONOMA	WESTERN TREE REMOVAL SPECIALISTS	5900 PRUITT AVE STE 530 WINDSOR, CA 95492 CA	NW	0.09 / 467.28	-6	308
23	EMISSIONS	REDBUILT LLC	5900 PRUITT AVENUE WINDSOR CA 95492	NW	0.09 / 467.28	-6	308
23	CUPA SONOMA	BamCore, LLC	5900 Pruitt Ave Ste 110, Windsor, CA 95492 CA	NW	0.09 / 467.28	-6	309
23	DEED	Shiloh Oaks Company	5900 Pruitt Avenue Windsor CA 95492	NW	0.09 / 467.28	-6	309

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
23	DELISTED HAZ	Western Tree Removal Specialists	5900 PRUITT AVE WINDSOR CA 95492	NW	0.09 / 467.28	-6	310
23	HMIRS		5900 pruitt ave # 164 SANTA ROSA CA	NW	0.09 / 467.28	-6	310
23	DELISTED HAZ	Oakland Packaging	5900 PRUITT AVE STE 100 WINDSOR CA 95492	NW	0.09 / 467.28	-6	312
23	CUPA SONOMA	Oakland Packaging	5900 Pruitt Ave Ste 100, Windsor, CA 95492 CA	NW	0.09 / 467.28	-6	312
23	RCRA NON GEN	ALLIED DIESEL PERFORMANCE	5900 PRUITT AVE STE 512 WINDSOR CA 95992 ***EPA Handler ID:*** CAL000440390	NW	0.09 / 467.28	-6	312
23	RCRA NON GEN	BAMCORE LLC	5900 PRUITT AVE STE 110 WINDSOR CA 95492 ***EPA Handler ID:*** CAL000404857	NW	0.09 / 467.28	-6	313
23	RCRA NON GEN	TDE EQUIPMENT INC	5900 PRUITT AVE WINDSOR CA 95492 ***EPA Handler ID:*** CAL000406695	NW	0.09 / 467.28	-6	314
23	RCRA NON GEN	NEW METAL COACHWORKS LLC	5900 PRUITT AVE STE 104 WINDSOR CA 94592 ***EPA Handler ID:*** CAL000423730	NW	0.09 / 467.28	-6	315
23	RCRA TSD	VINYARD OPS INC	5900 PRUITT AVE 150 WINDSOR CA 95492 ***EPA Handler ID:*** CAL000445045	NW	0.09 / 467.28	-6	316
23	RCRA NON GEN	VINYARD OPS INC	5900 PRUITT AVE 150 WINDSOR CA 95492 ***EPA Handler ID:*** CAL000445045	NW	0.09 / 467.28	-6	317
23	RCRA NON GEN	PRAXIS AUTOMOTIVE	5900 PRUITT AVE STE 202 WINDSOR CA 95492 ***EPA Handler ID:*** CAL000448951	NW	0.09 / 467.28	-6	318
23	HMIRS		5900 PRUITT AVE #164 WINDSOR CA	NW	0.09 / 467.28	-6	320
23	HMIRS		5900 Pruitt Ave. STE 164 WINDSOR CA	NW	0.09 / 467.28	-6	321
23	HMIRS		5900 pruitt ave WINDSOR CA	NW	0.09 / 467.28	-6	326

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
23	HMIRS		5900 pruitt ave # 164 SANTA ROSA CA	NW	0.09 / 467.28	-6	332
23	CERS HAZ	Sonoma Brothers Distilling	5900 PRUITT AVE STE 404 WINDSOR CA 95492	NW	0.09 / 467.28	-6	334
23	RCRA NON GEN	SELENES FRAME AND BODYWORKS	5900 PRUITT AVE STE 104 WINDSOR CA 95492 ***EPA Handler ID:*** CAL000451464	NW	0.09 / 467.28	-6	336
23	RCRA LQG	USEPA R9 SONOMA FIRE RESPONSE	5900 PRUITT AVENUE WINDSOR CA 95492 ***EPA Handler ID:*** CAP000216017	NW	0.09 / 467.28	-6	337
23	CUPA SONOMA	Sonoma Brothers Distilling	5900 Pruitt Ave Ste 404 Windsor, CA 95492 CA	NW	0.09 / 467.28	-6	338
23	SWF/LF	Atlas Tree Recycling Facility	5900 Pruitt Ave Windsor CA 95492 ***Act Opl Status | Activity:*** Active | Chipping and Grinding Facility/Operation	NW	0.09 / 467.28	-6	338
24	CUPA SONOMA	KFC/A&W	6610 Hembree Ln Windsor, CA 95492 CA	NNW	0.09 / 500.17	-5	340
24	CERS HAZ	KFC/A&W	6610 HEMBREE LN WINDSOR CA 95492	NNW	0.09 / 500.17	-5	340
25	DELISTED COUNTY	Best Truck Body & Trailer Repair, Inc.	610 Caletti Rd WINDSOR, CA 95492 CA	WNW	0.12 / 611.61	-7	343
26	RCRA NON GEN	IMAGE TREE SERVICE, INC.	564 CALETTI AVENUE WINDSOR CA 95492 ***EPA Handler ID:*** CAC002983223	WNW	0.12 / 629.02	-7	343
26	RCRA TSD	IMAGE TREE SERVICE, INC.	564 CALETTI AVENUE WINDSOR CA 95492 ***EPA Handler ID:*** CAC003009363	WNW	0.12 / 629.02	-7	344
26	RCRA NON GEN	IMAGE TREE SERVICE, INC.	564 CALETTI AVENUE WINDSOR CA 95492 ***EPA Handler ID:*** CAC003009363	WNW	0.12 / 629.02	-7	345
26	RCRA NON GEN	IMAGE TREE SERVICE, INC.	564 CALETTI AVENUE WINDSOR CA 95492	WNW	0.12 / 629.02	-7	346

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			EPA Handler ID: CAC003052512				
26	RCRA NON GEN	IMAGE TREE SERVICE INC	564 CALETTI AVE WINDSOR CA 95492 ***EPA Handler ID:*** CAL000461048	WNW	0.12 / 629.02	-7	347
27	DELISTED COUNTY	Best Truck Body Repair	600 Caletti Windsor, CA 95492 CA	WNW	0.12 / 631.88	-7	348
28	RCRA NON GEN	WATERWORKS INDUSTRIES INC	930 SHILOH RD BLDG 38 STE D WINDSOR CA 95492 ***EPA Handler ID:*** CAL000431223	WNW	0.12 / 645.61	-7	349
29	DELISTED COUNTY	ADAMS ENTERPRISES/LOUIE'S IRON WORKS	590 CALETTI WINDSOR, CA 95492 CA	WNW	0.12 / 652.15	-7	350
30	RCRA NON GEN	H AND H EXCAVATION	930 SHILOH RD STE 1A WINDSOR CA 95492 ***EPA Handler ID:*** CAR000162255	WNW	0.12 / 657.88	-14	350
30	RCRA NON GEN	CLEAR WATER ENVIRON	930 SHILOH RD WINDSOR CA 95492 ***EPA Handler ID:*** CAD982317638	WNW	0.12 / 657.88	-14	351
30	RCRA SQG	LAKEWOOD ENTERPRISES	930 SHILOH RD WINDSOR CA 95492 ***EPA Handler ID:*** CAD981385545	WNW	0.12 / 657.88	-14	352
30	RCRA SQG	KADON TRUCKING INC	930 SHILOH RD NO 15 WINDSOR CA 95492 ***EPA Handler ID:*** CAR000046862	WNW	0.12 / 657.88	-14	353
30	RCRA LQG	THE FLUOR CORPORATION	930 SHILOH RD WINDSOR CA 95492 ***EPA Handler ID:*** CAR000035162	WNW	0.12 / 657.88	-14	355
30	RCRA SQG	MARTINS TRUCK REPAIR L L C	930 SHILOH RD BLDG 1 WINDSOR CA 95492 ***EPA Handler ID:*** CAR000085415	WNW	0.12 / 657.88	-14	356
30	CUPA SONOMA	LandCare	930 Shiloh Rd Bldg 2, Yard 39 Windsor, CA 95492 CA	WNW	0.12 / 657.88	-14	357
30	CUPA SONOMA	Kadon Trucking, Inc.	930 Shiloh Rd Bldg 15 Windsor, CA 95492 CA	WNW	0.12 / 657.88	-14	358
30	CUPA SONOMA	All Around Auto Repair	930 Shiloh Rd Windsor, CA 95492	WNW	0.12 / 657.88	-14	358

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			CA				
30	CUPA SONOMA	North Bay Concrete, Inc.	930 Shiloh Rd Bldg 46 Windsor, CA 95492 CA	WNW	0.12 / 657.88	-14	359
30	CLEANUP SITES	ECODYNE	930 SHILOH ROAD WINDSOR CA 95492	WNW	0.12 / 657.88	-14	359
			Status* | *Site Facility Type: OPEN - VERIFICATION MONITORING | CLEANUP PROGRAM SITE				
30	ENVIROSTOR	LAKEWOOD ENTERPRISES	930 SHILOH ROAD WINSOR CA 94503	WNW	0.12 / 657.88	-14	393
			Estor/EPA ID* | *Cleanup Status: 71002776 | INACTIVE - NEEDS EVALUATION AS OF				
30	DELISTED COUNTY	EMPIRE TOWING	930 SHILOH ROAD WINDSOR, CA 95492 CA	WNW	0.12 / 657.88	-14	393
30	DELISTED COUNTY	BACE ANALYTICAL DIVISION OF BRUNSING & ASSOCIATES	930 SHILOH ROAD WINDSOR, CA 95492 CA	WNW	0.12 / 657.88	-14	393
30	DELISTED COUNTY	AUTO GRAPHIX	930 SHILOH RD WINDSOR, CA 95492 CA	WNW	0.12 / 657.88	-14	393
30	DELISTED COUNTY	Star Pools	930 Shiloh Road WINDSOR, CA 95492 CA	WNW	0.12 / 657.88	-14	394
30	VCP	THE SHILOH GROUP PROPERTY	930 SHILOH ROAD WINDSOR CA 95492	WNW	0.12 / 657.88	-14	394
			Estor/EPA ID* | *Cleanup Status: 60002191 | ACTIVE AS OF 5/12/2015				
30	CDO/CAO	Marmon Group Ecodyne/Shiloh Industrial Park	930 Shiloh Road Windsor CA 95492	WNW	0.12 / 657.88	-14	401
30	CDO/CAO	Marmon Group Ecodyne/Shiloh Industrial Park	930 Shiloh Road Windsor CA 95492	WNW	0.12 / 657.88	-14	403
30	CDO/CAO	Marmon Group Ecodyne/Shiloh Industrial Park	930 Shiloh Road Windsor CA 95492	WNW	0.12 / 657.88	-14	404

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
30	CDO/CAO	Marmon Group Ecodyne/Shiloh Industrial Park	930 Shiloh Road Windsor CA 95492	WNW	0.12 / 657.88	-14	406
30	CUPA SONOMA	The Fluor Corporation	930 Shiloh Rd Windsor, CA 95492 CA	WNW	0.12 / 657.88	-14	408
30	CERS HAZ	North Bay Concrete, Inc.	930 SHILOH RD BLDG 46 WINDSOR CA 95492	WNW	0.12 / 657.88	-14	408
30	CERS HAZ	LandCare	930 SHILOH RD BLDG 2, YARD 39 WINDSOR CA 95492	WNW	0.12 / 657.88	-14	412
30	CERS HAZ	Kadon Trucking, Inc.	930 SHILOH RD BLDG 15 WINDSOR CA 95492	WNW	0.12 / 657.88	-14	416
30	DELISTED HAZ	The Fluor Corporation	930 SHILOH RD WINDSOR CA 95492	WNW	0.12 / 657.88	-14	419
30	EMISSIONS	WESTERN FIBERGLASS	930 SHILOH RD, BLDG 2 WINDSOR CA 95492	WNW	0.12 / 657.88	-14	419
30	EMISSIONS	MARTIN'S TRUCK REPAIR	930 SHILOH RD, BLDG 2, STE B WINDSOR CA 95492	WNW	0.12 / 657.88	-14	420
30	EMISSIONS	MARTIN'S TRUCK REPAIR	930 SHILOH RD WINDSOR CA 95492	WNW	0.12 / 657.88	-14	421
30	EMISSIONS	RUIZ AUTOBODY	930 SHILOH RD, BLDG 2, STE B WINDSOR CA 95492	WNW	0.12 / 657.88	-14	421
30	EMISSIONS	IT CORPORATION	930 SHILOH ROAD WINDSOR CA 95492	WNW	0.12 / 657.88	-14	422
30	RESPONSE	ECODYNE DRAINAGE DITCH	930 SHILOH ROAD WINDSOR CA 95492	WNW	0.12 / 657.88	-14	423
			***Estor/EPA ID	Cleanup Status:*** 60002525	REFER: RWQCB AS OF 3/12/2018		
30	CERS HAZ	All Around Auto Repair	930 SHILOH RD WINDSOR CA 95492	WNW	0.12 / 657.88	-14	423

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
30	ENVIROSTOR	THE SHILOH GROUP PROPERTY	930 SHILOH ROAD WINDSOR CA 95492	WNW	0.12 / 657.88	-14	426
			***Estor/EPA ID	Cleanup Status:*** 60002191 | ACTIVE AS OF 5/12/2015			
30	ENVIROSTOR	ECODYNE DRAINAGE DITCH	930 SHILOH ROAD WINDSOR CA 95492	WNW	0.12 / 657.88	-14	434
			***Estor/EPA ID	Cleanup Status:*** 60002525 | REFER: RWQCB AS OF 3/12/2018			
30	RCRA NON GEN	NORTH BAY CONCRETE INC	930 SHILOH RD BLDG 46 WINDSOR CA 95492	WNW	0.12 / 657.88	-14	434
			EPA Handler ID: CAL000365272				
30	RCRA NON GEN	KADON TRUCKING INC	930 SHILOH BLDG #15 WINDSOR CA 95492-0000	WNW	0.12 / 657.88	-14	436
			EPA Handler ID: CAL000084470				
30	RCRA TSD	ATLAS VINEYARD MANAGEMENT INC	930 SHILOH RD BLDG 17 WINDSOR CA 95492	WNW	0.12 / 657.88	-14	437
			EPA Handler ID: CAL000444799				
30	RCRA NON GEN	ATLAS VINEYARD MANAGEMENT INC	930 SHILOH RD BLDG 17 WINDSOR CA 95492	WNW	0.12 / 657.88	-14	438
			EPA Handler ID: CAL000444799				
30	RCRA SQG	VIRAMONTES FAMILY GROUP - SHOP	930 SHILOH ROAD YARD 19 WINDSOR CA 95492	WNW	0.12 / 657.88	-14	439
			EPA Handler ID: CAR000302257				
30	UST SWEEPS	SHILOH PARK ADAMS ENTERPRIZES	930 SHILOH RD WINDSOR CA	WNW	0.12 / 657.88	-14	440
			***C C	Status:*** I49-000-1125 | INACTIVE ***Tank ID:*** 000001			
30	CALSITES	ECODYNE POND	930 SHILOH RD WINDSOR CA 95492	WNW	0.12 / 657.88	-14	440
30	CUPA SONOMA	Shiloh Shop	930 Shiloh Rd Bldg 17 Windsor, CA 95492 CA	WNW	0.12 / 657.88	-14	441
30	CERS HAZ	Shiloh Shop	930 SHILOH RD BLDG 17 WINDSOR CA 95492	WNW	0.12 / 657.88	-14	442
30	CDO/CAO	Marmon Group Ecodyne/Shiloh Industrial Park	930 Shiloh Road Windsor CA 95492	WNW	0.12 / 657.88	-14	443
31	DELISTED COUNTY	Batt's Tip Top Tree Service	584 Caletti Av WINDSOR, CA 95492 CA	WNW	0.13 / 664.31	-7	445

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
32	DELISTED COUNTY	Alan Precision & Dive Shop	580 Caletti Av WINDSOR, CA 95492 CA	WNW	0.13 / 672.42	-7	445
33	RCRA NON GEN	O'REILLY AUTO PARTS #3553	6500 HEMBREE LN # 109 WINDSOR CA 95492-6882 ***EPA Handler ID:*** CAL000393254	NNW	0.13 / 702.92	-1	445
34	SWF/LF	WMTF	586 Caletti Ave Windsor CA 95492 ***Act Opl Status | Activity:*** Active | Limited Volume Transfer Operation	WNW	0.13 / 712.39	-7	446
35	CUPA SONOMA	M&M Services, Inc	590 Caletti Ave Windsor, CA 95492 CA	WNW	0.14 / 727.67	-7	447
35	SWF/LF	Windsor Material Recovery Facility	590 Caletti Avenue Windsor CA 95492 ***Act Opl Status | Activity:*** Active | Medium Volume CDI Debris Processing Facility	WNW	0.14 / 727.67	-7	448
35	VCP	CALETTI AVE	590 CALETTI AVE WINDSOR CA 95492 ***Estor/EPA ID | Cleanup Status:*** 60001813 | ACTIVE AS OF 9/25/2018	WNW	0.14 / 727.67	-7	449
35	ENVIROSTOR	CALETTI AVE	590 CALETTI AVE WINDSOR CA 95492 ***Estor/EPA ID | Cleanup Status:*** 60001813 | ACTIVE AS OF 9/25/2018	WNW	0.14 / 727.67	-7	452
35	RCRA NON GEN	M & M SERVICES	590 CALETTI AVE WINDSOR CA 95492-8768 ***EPA Handler ID:*** CAL000257159	WNW	0.14 / 727.67	-7	456
35	C&D DEBRIS RECY	M AND M SERVICES INC	590 CALETTI AVE WINDSOR CA 95492	WNW	0.14 / 727.67	-7	457
36	RCRA SQG	WALMART #2553	6650 HEMBREE LN WINDSOR CA 95492 ***EPA Handler ID:*** CAR000205708	NNW	0.14 / 762.06	-7	457
36	CUPA SONOMA	Walmart #2553	6650 Hembree Ln Windsor, CA 95492 CA	NNW	0.14 / 762.06	-7	469
36	CERS TANK	Walmart #2553	6650 HEMBREE LN WINDSOR CA 95492 ***Site ID:*** 407239	NNW	0.14 / 762.06	-7	469
36	ALT FUELS	Walmart	6650 Hembree Ln Windsor CA 95492	NNW	0.14 / 762.06	-7	473

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			ID: 198738				
37	DELISTED COUNTY	Redwood Sanitary	930 Shiloh Rd. WINDSOR, CA 95492 CA	WNW	0.15 / 782.55	-14	473
37	DELISTED COUNTY	Battery Systems	930 Shiloh Rd., Bldg 1 Windsor, CA 95492 CA	WNW	0.15 / 782.55	-14	474
37	RCRA NON GEN	LANDCARE	930 SHILOH RD BLDG 44 STE B WINDSOR CA 95492 ***EPA Handler ID:*** CAL000367315	WNW	0.15 / 782.55	-14	474
38	CUPA SONOMA	Pacific Bracing Company	610 Caletti Ave Windsor, CA 95492 CA	WNW	0.15 / 803.40	-6	475
38	RCRA NON GEN	MANIAR CORPORATION DBA BEST TRUCK BODY & TRAILER REPAIR	610 CALETTI AVE WINDSOR CA 95492 ***EPA Handler ID:*** CAL000464661	WNW	0.15 / 803.40	-6	475
39	EMISSIONS	CARL'S READY MIX	340 STANDARD AVENUE WINDSOR CA 95492	W	0.16 / 835.49	-5	476
39	RCRA SQG	STANDARD STRUCTURES	340 STANDARD AVE WINDSOR CA 95492 ***EPA Handler ID:*** CAP000141747	W	0.16 / 835.49	-5	481
40	CUPA SONOMA	Panda Express #1598	6560 Hembree Lane, Pad 6 Building Windsor, CA 95492 CA	NNW	0.16 / 843.20	-1	482
41	CUPA SONOMA	SUBWAY	6400 Hembree LN STE 120 Windsor, CA 95492 CA	N	0.16 / 853.03	2	482
41	CUPA SONOMA	Former Office Depot #2208 (CLOSED)	6400 Hembree Ln Ste 100 Windsor, CA 95492 CA	N	0.16 / 853.03	2	482
41	RCRA NON GEN	OFFICE DEPOT 2208	6400 HEMBREE LANE SUITE 100 WINDSOR CA 95492 ***EPA Handler ID:*** CAL000420831	N	0.16 / 853.03	2	483
41	RCRA NON GEN	SAVNNICKSS INCORPORATED (GROCERY OUTLET OF WINDSOR)	6400 HEMBREE LN STE 100 WINDSOR CA 95492	N	0.16 / 853.03	2	484

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			EPA Handler ID: CAL000459613				
41	CUPA SONOMA	Grocery Outlet	6400 HEMBREE LN WINDSOR, CA 95492 CA	N	0.16 / 853.03	2	485
42	EMISSIONS	HOME DEPOT #6667	6280 HEMBREE LANE WINDSOR CA 95492	NNW	0.17 / 879.21	-6	485
43	CUPA SONOMA	Burger King	6351 Hembree Ln, Windsor, CA 95492 CA	N	0.17 / 919.49	3	488
43	DELISTED COUNTY	McDonalds- Walmart	6351 Hembree Lane Windsor, CA 95492 CA	N	0.17 / 919.49	3	489
44	CUPA SONOMA	Windsor Yard	550 Caletti Ave # 5, Windsor, CA 95492 CA	WSW	0.18 / 933.25	-4	489
44	RCRA NON GEN	WILDEASE LLC	550 CALETTI AVE WINDSOR CA 95492 ***EPA Handler ID:*** CAC002964519	WSW	0.18 / 933.25	-4	489
44	RCRA NON GEN	ELITE CONCRETE CONSTRUCTION INC	550 CALETTI AVE WINDSOR CA 95492 ***EPA Handler ID:*** CAL000451229	WSW	0.18 / 933.25	-4	490
45	CUPA SONOMA	Silara Medtech Inc.	451 Aviation Blvd., Suite 107A Santa Rosa, CA 95403 CA	SSW	0.18 / 956.85	-1	491
45	DELISTED COUNTY	MITRALIFE	451 AVIATION BLVD SANTA ROSA, CA 95403 CA	SSW	0.18 / 956.85	-1	492
45	RCRA TSD	HAISCO US MED TECH INC	451 AVIATION BLVD STE 107A SANTA ROSA CA 95404 ***EPA Handler ID:*** CAL000426304	SSW	0.18 / 956.85	-1	492
45	RCRA NON GEN	HAISCO US MED TECH INC	451 AVIATION BLVD STE 107A SANTA ROSA CA 95404 ***EPA Handler ID:*** CAL000426304	SSW	0.18 / 956.85	-1	493
45	RCRA NON GEN	SUTTER PACIFIC MEDICAL FOUNDATION	451 AVIATION BLVD SUITE 101 SANTA ROSA CA 95403 ***EPA Handler ID:*** CAC003129754	SSW	0.18 / 956.85	-1	494

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
46	CUPA SONOMA	Sonoma EO	428 Aviation Blvd Santa Rosa, CA 95403 CA	S	0.18 / 957.80	2	495
47	RESPONSE	ECODYNE COOLING	SHILOH ROAD WINDSOR CA 95442	WNW	0.19 / 993.02	-14	496
			***Estor/EPA ID	Cleanup Status:*** 49420002 | REFER: RWQCB AS OF 4/3/1992			
47	ENVIROSTOR	ECODYNE COOLING	SHILOH ROAD WINDSOR CA 95442	WNW	0.19 / 993.02	-14	496
			***Estor/EPA ID	Cleanup Status:*** 49420002 | REFER: RWQCB AS OF 4/3/1992			
48	CUPA SONOMA	Airport Health Club	432 Aviation Blvd Santa Rosa, CA 95403 CA	S	0.20 / 1,033.88	1	497
48	EMISSIONS	AIRPORT HEALTH CLUB	432 AVIATION BOULEVARD SANTA ROSA CA 95403	S	0.20 / 1,033.88	1	498
49	CUPA SONOMA	The Home Depot Store #6667	6280 Hembree Lane Windsor, CA 95492 CA	N	0.20 / 1,046.83	3	501
49	EMISSIONS	THE HOME DEPOT #6667	6280 HEMBREE LANE WINDSOR CA 95492	N	0.20 / 1,046.83	3	501
49	RCRA SQG	HOME DEPOT 6667	6280 HEMBREE LN WINDSOR CA 95492	N	0.20 / 1,046.83	3	504
			EPA Handler ID: CAR000168070				
50	CUPA SONOMA	Best Truck Body	600 Caletti Ave Windsor, CA 95492 CA	WNW	0.21 / 1,093.88	-6	507
50	RCRA NON GEN	BEST TRUCK BODY INC.	600 CALETTI AVE WINDSOR CA 95492	WNW	0.21 / 1,093.88	-6	508
			EPA Handler ID: CAC003054328				
51	CUPA SONOMA	Les Schwab Tire Center #635	6700 Hembree Ln Windsor, CA 95492 CA	NNW	0.21 / 1,093.99	-6	509
51	RCRA NON GEN	LES SCHWAB TIRES CENTERS OF CA, INC.	6700 HEMBREE LN WINDSOR CA 95492	NNW	0.21 / 1,093.99	-6	509
			EPA Handler ID: CAL000255334				
52	RCRA SQG	LITHOCRAFT INC	424 AVIATION BLVD SANTA ROSA CA 95403	SSE	0.22 / 1,146.01	3	510
			EPA Handler ID: CAD983635954				

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
52	DELISTED COUNTY	Lithocraft, Inc.	424 Aviation Blvd. SANTA ROSA, CA 95403 CA	SSE	0.22 / 1,146.01	3	511
52	DELISTED COUNTY	L-3 SONOMA EO	424 AVIATION BLVD SANTA ROSA, CA 95403 CA	SSE	0.22 / 1,146.01	3	511
52	CUPA SONOMA	L-3 SONOMA EO	424 AVIATION BLVD SANTA ROSA, CA 95403 CA	SSE	0.22 / 1,146.01	3	511
52	EMISSIONS	LITHOCRAFT, INC	424 AVIATION BOULEVARD SANTA ROSA CA 95403	SSE	0.22 / 1,146.01	3	512
52	RCRA NON GEN	SONOMA EO	424 AVIATION BLVD SANTA ROSA CA 95403-1069	SSE	0.22 / 1,146.01	3	515
			EPA Handler ID: CAL000298612				
53	DELISTED TNK	Shiloh Center Shell	6301 Hembree Ln Windsor CA 95492	NNE	0.22 / 1,147.56	4	516
53	CUPA SONOMA	Hembree Shell #130	6301 Hembree Ln Windsor, CA 95492 CA	NNE	0.22 / 1,147.56	4	517
53	CLEANUP SITES	SHELL SERVICE STATION	6301 HEMBREE LANE WINDSOR CA 95492	NNE	0.22 / 1,147.56	4	517
			Status | Site Facility Type: COMPLETED - CASE CLOSED | CLEANUP PROGRAM SITE				
53	CERS TANK	Hembree Shell #130	6301 HEMBREE LN WINDSOR CA 95492	NNE	0.22 / 1,147.56	4	522
			Site ID: 122176				
53	UST	Hembree Shell #130	6301 Hembree Ln Windsor CA 95492	NNE	0.22 / 1,147.56	4	529
			Facility ID: 49-000-005989				
53	RCRA NON GEN	AU ENERGY-HEMBREE SHELL	6301 HEMBREE LN WINDSOR CA 95492-6856	NNE	0.22 / 1,147.56	4	530
			EPA Handler ID: CAL000350865				
53	RCRA NON GEN	SHELL OIL PRODUCTS SAP 166257	6301 HEMBREE LN WINDSOR CA 95492	NNE	0.22 / 1,147.56	4	531
			EPA Handler ID: CAR000189530				
53	EMISSIONS	HEMBREE SHELL	6301 HEMBREE LN WINDSOR CA 95492	NNE	0.22 / 1,147.56	4	532

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
53	RCRA NON GEN	AU ENERGY HEMBREE SHELL #130	6301 HEMBREE LANE WINDSOR CA 95492 ***EPA Handler ID:*** CAC003076609	NNE	0.22 / 1,147.56	4	534
54	RCRA NON GEN	ICON GENERAL CONTRACTORS, INC.	451 AVIATION BLVD. SUITE 101 & 103 SANTA ROSA CA 95403 ***EPA Handler ID:*** CAC003076496	SSW	0.23 / 1,198.71	-2	535
55	CUPA SONOMA	Filtration Group	498 Aviation Blvd Santa Rosa, CA 95403 CA	SW	0.23 / 1,237.11	-3	536
56	SWF/LF	Sonoma County IDS (2136)	475 Aviation Blvd Santa Rosa CA 95403	SW	0.23 / 1,238.02	-4	536
57	CUPA SONOMA	Tonnellerie Radoux USA, Inc	480 Aviation Boulevard, Santa Rosa, CA 95403 CA	SSW	0.24 / 1,255.85	-2	537
58	CUPA SONOMA	Exchange Bank	440 Aviation Blvd, Santa Rosa, CA 95403 CA	SSW	0.24 / 1,260.00	-1	537
58	EMISSIONS	EXCHANGE BANK	440 AVIATION BOULEVARD SANTA ROSA CA 95403	SSW	0.24 / 1,260.00	-1	538
59	CUPA SONOMA	Bio-Rad Laboratories, Inc.	487 Aviation Blvd # 100 Santa Rosa, CA 95403 CA	SW	0.24 / 1,287.84	-4	542
59	DELISTED COUNTY	FMC Santa Rosa North	487 Aviation Blvd. SANTA ROSA, CA 95403 CA	SW	0.24 / 1,287.84	-4	543
59	DELISTED HAZ	FMC Dialysis	487 AVIATION BLVD, STE 110 SANTA ROSA CA 95403	SW	0.24 / 1,287.84	-4	543
59	RCRA NON GEN	BIO RAD LABORATORIES INC	487 AVIATION BLVD STE 100 SANTA ROSA CA 95403-1069 ***EPA Handler ID:*** CAL000389056	SW	0.24 / 1,287.84	-4	543
59	EMISSIONS	BIO-RAD LABORATORIES	487 AVIATION BLVD, STE 100 SANTA ROSA CA 95403	SW	0.24 / 1,287.84	-4	544
60	DELISTED COUNTY	Four Corners (under construction)	792 Caletti Santa Rosa, CA CA	W	0.24 / 1,287.87	-5	544

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
61	CUPA SONOMA	HILTON GARDEN INN	417 Aviation SANTA ROSA, CA 95403 CA	SSE	0.25 / 1,316.75	4	545
62	RESPONSE	ECODYNE POND	930 SHILOH RD WINDSOR CA 95492	W	0.26 / 1,355.29	-6	545
			***Estor/EPA ID*	*Cleanup Status:*** 49240001	ACTIVE AS OF 5/1/1986		
62	HWSS CLEANUP	ECODYNE POND	930 SHILOH RD WINDSOR CA 95492	W	0.26 / 1,355.29	-6	556
			***Estor/EPA ID*	*Cleanup Status:*** 49240001	ACTIVE AS OF 5/1/1986		
62	ENVIROSTOR	ECODYNE POND	930 SHILOH RD WINDSOR CA 95492	W	0.26 / 1,355.29	-6	570
			***Estor/EPA ID*	*Cleanup Status:*** 49240001	ACTIVE AS OF 5/1/1986		
63	CLEANUP SITES	AIRPORT BUSINESS CENTER (LOTS 15 & 16)	1010 SHILOH ROAD WINDSOR CA 95492	WNW	0.26 / 1,355.77	-11	581
			***Status*	*Site Facility Type:*** COMPLETED - CASE CLOSED	CLEANUP PROGRAM SITE		
63	CLEANUP SITES	AIRPORT BUSINESS CENTER, PHASE 5, LOT 9	1010 SHILOH ROAD WINDSOR CA 95492	WNW	0.26 / 1,355.77	-11	589
			***Status*	*Site Facility Type:*** COMPLETED - CASE CLOSED	CLEANUP PROGRAM SITE		
64	LOP SONOMA	Rasmussen, C.A., Inc.	1012 Shiloh Rd Windsor CA	WNW	0.26 / 1,390.94	-11	593
			***LOP No*	*Status Desc:*** 00001389	Closed Site		
64	LUST	RASMUSSEN, C.A., INC.	1012 SHILOH RD WINDSOR CA 95492	WNW	0.26 / 1,390.94	-11	593
			***Global ID*	*Status*	*Status Date:*** T0609700459	COMPLETED - CASE CLOSED	10/7/1999		
65	DELISTED HAZ	Kenwood Distribution Center	501 AVIATION BLVD SANTA ROSA CA 95403	SW	0.27 / 1,414.28	-5	595
66	C&D DEBRIS RECY	SONOMA COUNTY WATER AGENCY	404 AVIATION BLVD SANTA ROSA CA 95403	SSE	0.30 / 1,583.95	3	595
67	DELISTED HAZ	American Tank Company, Inc.	501 AMERICAN WAY WINDSOR CA 95492	NW	0.34 / 1,787.42	-12	595
68	DELISTED HAZ	Wine Country Autoworks	399 BUSINESS PARK CT STE 102 WINDSOR CA 95492	NNE	0.37 / 1,968.36	11	596
69	RCRA TSD	ENCORE EVENTS RENTALS INC	1101 AMERICAN WAY WINDSOR CA 95492	NW	0.40 / 2,095.94	-14	596

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			EPA Handler ID: CAL000446240				
70	DELISTED HAZ	Mi Burrito Mexican Restaurant & Bar	385 AVIATION BLVD STE D SANTA ROSA CA 95403	SE	0.41 / 2,144.19	9	597
71	FUDS	Santa Rosa Army Airfield	 WINDSOR CA	S	0.45 / 2,364.30	1	597
			FUDS Property No: J09CA0026				
72	LOP SONOMA	Soiland Co., Inc.	1210 Airport Blvd Santa Rosa CA	SSE	0.46 / 2,410.35	4	598
			LOP No **|** ***Status Desc:*** 00001821 | Closed Site				
72	LUST	SOILAND CO., INC.	1210 AIRPORT BLVD SANTA ROSA CA 95401	SSE	0.46 / 2,410.35	4	598
			Global ID **|** ***Status*** **|** ***Status Date:*** T0609700225 | COMPLETED - CASE CLOSED | 3/6/1998				
73	CLEANUP SITES	ROUND-TO-IT TIRE RECYCLERS	1070 AIRPORT BOULEVARD SANTA ROSA CA 95403	SSE	0.46 / 2,415.71	7	600
			Status **|** ***Site Facility Type:*** COMPLETED - CASE CLOSED | CLEANUP PROGRAM SITE				
74	DELISTED HAZ	slaight heavy haul yard	1060 AIRPORT BLVD SANTA ROSA CA 95403	SSE	0.46 / 2,419.05	8	602
75	SWF/LF	Round-TO-It Illegal Waste Tire TS	1050 Airport Blvd Santa Rosa CA 99999	SSE	0.46 / 2,427.01	8	603
76	CLEANUP SITES	SANTA ROSA STAINLESS STEEL	1400 AIRPORT BOULEVARD SANTA ROSA CA 95403	SSW	0.47 / 2,483.16	-1	603
			Status **|** ***Site Facility Type:*** COMPLETED - CASE CLOSED | CLEANUP PROGRAM SITE				
77	LOP SONOMA	Yolo Trucking	5807 Old Redwood Hwy Santa Rosa CA	ENE	0.47 / 2,507.72	14	615
			LOP No **|** ***Status Desc:*** 00002231 | Closed Site				
77	LUST	YOLO TRUCKING	5807 OLD REDWOOD HWY SANTA ROSA CA 95403	ENE	0.47 / 2,507.72	14	615
			Global ID **|** ***Status*** **|** ***Status Date:*** T0609700284 | COMPLETED - CASE CLOSED | 9/24/1997				
78	LOP SONOMA	K & C Trucking	1514 Airport Blvd Santa Rosa CA	SSW	0.49 / 2,565.09	-1	618
			LOP No **|** ***Status Desc:*** 00001239 | Closed Site				
78	LUST	K & C TRUCKING	1514 AIRPORT BLVD SANTA ROSA CA 95401-1010	SSW	0.49 / 2,565.09	-1	618
			Global ID **|** ***Status*** **|** ***Status Date:*** T0609700486 | COMPLETED - CASE CLOSED | 6/25/2003				
79	ENVIROSTOR	CREAMS DISMANTLING INC.	1588 AIRPORT BLVD WINDSOR CA 95492	SSW	0.51 / 2,713.31	-2	621

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			***Estor/EPA ID	Cleanup Status:*** 49500017 | REFER: RWQCB AS OF 9/27/1993			
80	ENVIROSTOR	DYNATEX INTERNATIONAL	5577 SKYLANE BOULEVARD SANTA ROSA CA 95403	WSW	0.62 / 3,260.24	-15	622
			***Estor/EPA ID	Cleanup Status:*** 71003406 | INACTIVE - NEEDS EVALUATION AS OF			
81	ENVIROSTOR	SANTA ROSA ARMY AIRFIELD	2232 AIRPORT BLVD SANTA ROSA CA 95403	SW	0.67 / 3,533.17	-6	622
			***Estor/EPA ID	Cleanup Status:*** 49450004 | NO FURTHER ACTION AS OF 9/18/2014			
82	RESPONSE	APEX AVIATION CORP.	2240 AIRPORT BLVD SANTA ROSA CA 94503	WSW	0.94 / 4,987.30	-5	624
			***Estor/EPA ID	Cleanup Status:*** 80001206 | NO FURTHER ACTION AS OF 8/18/2010			
82	ENVIROSTOR	APEX AVIATION CORP.	2240 AIRPORT BLVD SANTA ROSA CA 94503	WSW	0.94 / 4,987.30	-5	624
			***Estor/EPA ID	Cleanup Status:*** 80001206 | NO FURTHER ACTION AS OF 8/18/2010			

Executive Summary: Summary by Data Source

Standard

Federal

RCRA TSD - RCRA non-CORRACTS TSD Facilities

A search of the RCRA TSD database, dated Aug 30, 2021 has found that there are 5 RCRA TSD site(s) within approximately 0.50 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
VINYARD OPS INC	5900 PRUITT AVE 150 WINDSOR CA 95492 ***EPA Handler ID**: CAL000445045*	NW	0.09 / 467.28	23
IMAGE TREE SERVICE, INC.	564 CALETTI AVENUE WINDSOR CA 95492 ***EPA Handler ID**: CAC003009363*	WNW	0.12 / 629.02	26
ATLAS VINEYARD MANAGEMENT INC	930 SHILOH RD BLDG 17 WINDSOR CA 95492 ***EPA Handler ID**: CAL000444799*	WNW	0.12 / 657.88	30
HAISCO US MED TECH INC	451 AVIATION BLVD STE 107A SANTA ROSA CA 95404 ***EPA Handler ID**: CAL000426304*	SSW	0.18 / 956.85	45
ENCORE EVENTS RENTALS INC	1101 AMERICAN WAY WINDSOR CA 95492 ***EPA Handler ID**: CAL000446240*	NW	0.40 / 2,095.94	69

RCRA LQG - RCRA Generator List

A search of the RCRA LQG database, dated Aug 30, 2021 has found that there are 2 RCRA LQG site(s) within approximately 0.25 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
USEPA R9 SONOMA FIRE RESPONSE	5900 PRUITT AVENUE WINDSOR CA 95492 ***EPA Handler ID**: CAP000216017*	NW	0.09 / 467.28	23
THE FLUOR CORPORATION	930 SHILOH RD WINDSOR CA 95492 ***EPA Handler ID**: CAR000035162*	WNW	0.12 / 657.88	30

RCRA SQG - RCRA Small Quantity Generators List

A search of the RCRA SQG database, dated Aug 30, 2021 has found that there are 9 RCRA SQG site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
HOME DEPOT 6667	6280 HEMBREE LN WINDSOR CA 95492 ***EPA Handler ID**: CAR000168070*	N	0.20 / 1,046.83	49
LITHOCRAFT INC	424 AVIATION BLVD SANTA ROSA CA 95403 ***EPA Handler ID**: CAD983635954*	SSE	0.22 / 1,146.01	52

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
FEDEX GROUND PACKAGE SYSTEM INC	500 CALETTI AVE WINDSOR CA 95492 ***EPA Handler ID**: CAR000239723*	SSW	0.04 / 227.62	11
MARTINS TRUCK REPAIR L L C	930 SHILOH RD BLDG 1 WINDSOR CA 95492 ***EPA Handler ID**: CAR000085415*	WNW	0.12 / 657.88	30
VIRAMONTES FAMILY GROUP - SHOP	930 SHILOH ROAD YARD 19 WINDSOR CA 95492 ***EPA Handler ID**: CAR000302257*	WNW	0.12 / 657.88	30
KADON TRUCKING INC	930 SHILOH RD NO 15 WINDSOR CA 95492 ***EPA Handler ID**: CAR000046862*	WNW	0.12 / 657.88	30
LAKEWOOD ENTERPRISES	930 SHILOH RD WINDSOR CA 95492 ***EPA Handler ID**: CAD981385545*	WNW	0.12 / 657.88	30
WALMART #2553	6650 HEMBREE LN WINDSOR CA 95492 ***EPA Handler ID**: CAR000205708*	NNW	0.14 / 762.06	36
STANDARD STRUCTURES	340 STANDARD AVE WINDSOR CA 95492 ***EPA Handler ID**: CAP000141747*	W	0.16 / 835.49	39

RCRA NON GEN - RCRA Non-Generators

A search of the RCRA NON GEN database, dated Aug 30, 2021 has found that there are 44 RCRA NON GEN site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
SALLY BEAUTY SUPPLY #3859	6560 HEMBREE LN STE 186 WINDSOR CA 95492 ***EPA Handler ID**: CAL000411992*	NNW	0.09 / 451.10	21
OFFICE DEPOT 2208	6400 HEMBREE LANE SUITE 100 WINDSOR CA 95492 ***EPA Handler ID**: CAL000420831*	N	0.16 / 853.03	41

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
SAVNNICKSS INCORPORATED (GROCERY OUTLET OF WINDSOR)	6400 HEMBREE LN STE 100 WINDSOR CA 95492 ***EPA Handler ID**: CAL000459613*	N	0.16 / 853.03	41
SONOMA EO	424 AVIATION BLVD SANTA ROSA CA 95403-1069 ***EPA Handler ID**: CAL000298612*	SSE	0.22 / 1,146.01	52
AU ENERGY HEMBREE SHELL #130	6301 HEMBREE LANE WINDSOR CA 95492 ***EPA Handler ID**: CAC003076609*	NNE	0.22 / 1,147.56	53
SHELL OIL PRODUCTS SAP 166257	6301 HEMBREE LN WINDSOR CA 95492 ***EPA Handler ID**: CAR000189530*	NNE	0.22 / 1,147.56	53
AU ENERGY-HEMBREE SHELL	6301 HEMBREE LN WINDSOR CA 95492-6856 ***EPA Handler ID**: CAL000350865*	NNE	0.22 / 1,147.56	53

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
WESTERN TREE REMOVAL SPECIALISTS	5900 PRUITT AVE STE 532 WINDSOR CA 95492 ***EPA Handler ID**: CAL000429102*	NW	0.02 / 121.27	9
SALKHI PETROLEUM INC DBA WINDSOR CHEVRON	705 SHILOH RD WINDSOR CA 95492 ***EPA Handler ID**: CAL000449206*	NW	0.03 / 142.75	10
B&B SERVICE STATION	705 SHILOH RD WINDSOR CA 95492 ***EPA Handler ID**: CAL000395131*	NW	0.03 / 142.75	10
EXXONMOBIL OIL CORPORATION #99HLH	705 SHILOH RD WINDSOR CA 95492-0000 ***EPA Handler ID**: CAL921054218*	NW	0.03 / 142.75	10
WEST COAST METALS	470 CALETTI AVE WINDSOR CA 95492-0000 ***EPA Handler ID**: CAL000272499*	WNW	0.05 / 256.88	12
AHLBORN STRUCTURAL STEEL INC	5937 PRUITT AVE WINDSOR CA 95492 ***EPA Handler ID**: CAL000456688*	NW	0.05 / 272.82	13
NORTHGATE READY MIX	5922 PRUITT AVE WINDSOR CA 95492 ***EPA Handler ID**: CAL000374302*	NW	0.06 / 330.69	14

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
FRIEDMAN'S D.Y.	5892 PRUITT AVE NO 300 WINDSOR CA 95492 ***EPA Handler ID**: CAL000463758*	NW	0.08 / 397.07	20
ALLIED DIESEL PERFORMANCE	5900 PRUITT AVE STE 512 WINDSOR CA 95992 ***EPA Handler ID**: CAL000440390*	NW	0.09 / 467.28	23
BAMCORE LLC	5900 PRUITT AVE STE 110 WINDSOR CA 95492 ***EPA Handler ID**: CAL000404857*	NW	0.09 / 467.28	23
TDE EQUIPMENT INC	5900 PRUITT AVE WINDSOR CA 95492 ***EPA Handler ID**: CAL000406695*	NW	0.09 / 467.28	23
NEW METAL COACHWORKS LLC	5900 PRUITT AVE STE 104 WINDSOR CA 94592 ***EPA Handler ID**: CAL000423730*	NW	0.09 / 467.28	23
VINYARD OPS INC	5900 PRUITT AVE 150 WINDSOR CA 95492 ***EPA Handler ID**: CAL000445045*	NW	0.09 / 467.28	23
PRAXIS AUTOMOTIVE	5900 PRUITT AVE STE 202 WINDSOR CA 95492 ***EPA Handler ID**: CAL000448951*	NW	0.09 / 467.28	23
SELENES FRAME AND BODYWORKS	5900 PRUITT AVE STE 104 WINDSOR CA 95492 ***EPA Handler ID**: CAL000451464*	NW	0.09 / 467.28	23
IMAGE TREE SERVICE, INC.	564 CALETTI AVENUE WINDSOR CA 95492 ***EPA Handler ID**: CAC002983223*	WNW	0.12 / 629.02	26
IMAGE TREE SERVICE, INC.	564 CALETTI AVENUE WINDSOR CA 95492 ***EPA Handler ID**: CAC003009363*	WNW	0.12 / 629.02	26
IMAGE TREE SERVICE, INC.	564 CALETTI AVENUE WINDSOR CA 95492 ***EPA Handler ID**: CAC003052512*	WNW	0.12 / 629.02	26
IMAGE TREE SERVICE INC	564 CALETTI AVE WINDSOR CA 95492 ***EPA Handler ID**: CAL000461048*	WNW	0.12 / 629.02	26
WATERWORKS INDUSTRIES INC	930 SHILOH RD BLDG 38 STE D WINDSOR CA 95492 ***EPA Handler ID**: CAL000431223*	WNW	0.12 / 645.61	28

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
H AND H EXCAVATION	930 SHILOH RD STE 1A WINDSOR CA 95492 ***EPA Handler ID**: CAR000162255*	WNW	0.12 / 657.88	30
CLEAR WATER ENVIRON	930 SHILOH RD WINDSOR CA 95492 ***EPA Handler ID**: CAD982317638*	WNW	0.12 / 657.88	30
NORTH BAY CONCRETE INC	930 SHILOH RD BLDG 46 WINDSOR CA 95492 ***EPA Handler ID**: CAL000365272*	WNW	0.12 / 657.88	30
KADON TRUCKING INC	930 SHILOH BLDG #15 WINDSOR CA 95492-0000 ***EPA Handler ID**: CAL000084470*	WNW	0.12 / 657.88	30
ATLAS VINEYARD MANAGEMENT INC	930 SHILOH RD BLDG 17 WINDSOR CA 95492 ***EPA Handler ID**: CAL000444799*	WNW	0.12 / 657.88	30
O'REILLY AUTO PARTS #3553	6500 HEMBREE LN # 109 WINDSOR CA 95492-6882 ***EPA Handler ID**: CAL000393254*	NNW	0.13 / 702.92	33
M & M SERVICES	590 CALETTI AVE WINDSOR CA 95492-8768 ***EPA Handler ID**: CAL000257159*	WNW	0.14 / 727.67	35
LANDCARE	930 SHILOH RD BLDG 44 STE B WINDSOR CA 95492 ***EPA Handler ID**: CAL000367315*	WNW	0.15 / 782.55	37
MANIAR CORPORATION DBA BEST TRUCK BODY & TRAILER REPAIR	610 CALETTI AVE WINDSOR CA 95492 ***EPA Handler ID**: CAL000464661*	WNW	0.15 / 803.40	38
WILDEASE LLC	550 CALETTI AVE WINDSOR CA 95492 ***EPA Handler ID**: CAC002964519*	WSW	0.18 / 933.25	44
ELITE CONCRETE CONSTRUCTION INC	550 CALETTI AVE WINDSOR CA 95492 ***EPA Handler ID**: CAL000451229*	WSW	0.18 / 933.25	44
HAISCO US MED TECH INC	451 AVIATION BLVD STE 107A SANTA ROSA CA 95404 ***EPA Handler ID**: CAL000426304*	SSW	0.18 / 956.85	45
SUTTER PACIFIC MEDICAL FOUNDATION	451 AVIATION BLVD SUITE 101 SANTA ROSA CA 95403 ***EPA Handler ID**: CAC003129754*	SSW	0.18 / 956.85	45

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
BEST TRUCK BODY INC.	600 CALETTI AVE WINDSOR CA 95492 ***EPA Handler ID**: CAC003054328*	WNW	0.21 / 1,093.88	50
LES SCHWAB TIRES CENTERS OF CA, INC.	6700 HEMBREE LN WINDSOR CA 95492 ***EPA Handler ID**: CAL000255334*	NNW	0.21 / 1,093.99	51
ICON GENERAL CONTRACTORS, INC.	451 AVIATION BLVD. SUITE 101 & 103 SANTA ROSA CA 95403 ***EPA Handler ID**: CAC003076496*	SSW	0.23 / 1,198.71	54
BIO RAD LABORATORIES INC	487 AVIATION BLVD STE 100 SANTA ROSA CA 95403-1069 ***EPA Handler ID**: CAL000389056*	SW	0.24 / 1,287.84	59

State

RESPONSE - State Response Sites

A search of the RESPONSE database, dated Sep 15, 2021 has found that there are 4 RESPONSE site(s) within approximately 1.00 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
ECODYNE DRAINAGE DITCH	930 SHILOH ROAD WINDSOR CA 95492 ***Estor/EPA ID	Cleanup Status**: 60002525	REFER: RWQCB AS OF 3/12/2018*	WNW	0.12 / 657.88	30
ECODYNE COOLING	SHILOH ROAD WINDSOR CA 95442 ***Estor/EPA ID	Cleanup Status**: 49420002	REFER: RWQCB AS OF 4/3/1992*	WNW	0.19 / 993.02	47
ECODYNE POND	930 SHILOH RD WINDSOR CA 95492 ***Estor/EPA ID	Cleanup Status**: 49240001	ACTIVE AS OF 5/1/1986*	W	0.26 / 1,355.29	62
APEX AVIATION CORP.	2240 AIRPORT BLVD SANTA ROSA CA 94503 ***Estor/EPA ID	Cleanup Status**: 80001206	NO FURTHER ACTION AS OF 8/18/2010*	WSW	0.94 / 4,987.30	82

ENVIROSTOR - EnviroStor Database

A search of the ENVIROSTOR database, dated Sep 15, 2021 has found that there are 10 ENVIROSTOR site(s) within approximately 1.00 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
ECODYNE DRAINAGE DITCH	930 SHILOH ROAD WINDSOR CA 95492 ***Estor/EPA ID	Cleanup Status**: 60002525	REFER: RWQCB AS OF 3/12/2018*	WNW	0.12 / 657.88	30
THE SHILOH GROUP PROPERTY	930 SHILOH ROAD WINDSOR CA 95492	WNW	0.12 / 657.88	30

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
	***Estor/EPA ID	Cleanup Status**: 60002191	ACTIVE AS OF 5/12/2015*			
LAKEWOOD ENTERPRISES	930 SHILOH ROAD WINSOR CA 94503	WNW	0.12 / 657.88	30
	***Estor/EPA ID	Cleanup Status**: 71002776	INACTIVE - NEEDS EVALUATION AS OF*			
CALETTI AVE	590 CALETTI AVE WINDSOR CA 95492	WNW	0.14 / 727.67	35
	***Estor/EPA ID	Cleanup Status**: 60001813	ACTIVE AS OF 9/25/2018*			
ECODYNE COOLING	SHILOH ROAD WINDSOR CA 95442	WNW	0.19 / 993.02	47
	***Estor/EPA ID	Cleanup Status**: 49420002	REFER: RWQCB AS OF 4/3/1992*			
ECODYNE POND	930 SHILOH RD WINDSOR CA 95492	W	0.26 / 1,355.29	62
	***Estor/EPA ID	Cleanup Status**: 49240001	ACTIVE AS OF 5/1/1986*			
CREAMS DISMANTLING INC.	1588 AIRPORT BLVD WINDSOR CA 95492	SSW	0.51 / 2,713.31	79
	***Estor/EPA ID	Cleanup Status**: 49500017	REFER: RWQCB AS OF 9/27/1993*			
DYNATEX INTERNATIONAL	5577 SKYLANE BOULEVARD SANTA ROSA CA 95403	WSW	0.62 / 3,260.24	80
	***Estor/EPA ID	Cleanup Status**: 71003406	INACTIVE - NEEDS EVALUATION AS OF*			
SANTA ROSA ARMY AIRFIELD	2232 AIRPORT BLVD SANTA ROSA CA 95403	SW	0.67 / 3,533.17	81
	***Estor/EPA ID	Cleanup Status**: 49450004	NO FURTHER ACTION AS OF 9/18/2014*			
APEX AVIATION CORP.	2240 AIRPORT BLVD SANTA ROSA CA 94503	WSW	0.94 / 4,987.30	82
	***Estor/EPA ID	Cleanup Status**: 80001206	NO FURTHER ACTION AS OF 8/18/2010*			

SWF/LF - Solid Waste Information System (SWIS)

A search of the SWF/LF database, dated Nov 2, 2021 has found that there are 15 SWF/LF site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Round-TO-It Illegal Waste Tire TS	1050 Airport Blvd Santa Rosa CA 99999	SSE	0.46 / 2,427.01	75

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Windsor Oaks	899 Shiloh Road Windsor CA 95492	NW	0.02 / 115.85	8

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
SCWS Wood Processing Operation	5900 Pruitt Ave. Windsor CA 95492	NW	0.02 / 121.27	9
	***Act Opl Status | Activity**: Active | Chipping and Grinding Facility/Operation*			
Pruitt Transload Facility	5900 Pruitt Ave. Windsor CA 95492	NW	0.02 / 121.27	9
	***Act Opl Status | Activity**: Active | Medium Volume Transfer/Processing Facility*			
SCWS Emergency CDI Processing	5900 Pruitt Ave. Windsor CA 95492	NW	0.02 / 121.27	9
PRS Inert Debris Processing Operation	5900 Pruitt Ave. Windsor CA 95492	NW	0.02 / 121.27	9
Atlas Tree Surgery Reduction Yard	5900 Pruitt Ave. Windsor CA 95492	NW	0.02 / 121.27	9
Atlas Tree Processing Yard	5900 Pruitt Ave. Windsor CA 95492	NW	0.02 / 121.27	9
PRS Direct Transfer Operation	5900 Pruitt Ave. Windsor CA 95492	NW	0.02 / 121.27	9
SMCI Windsor Receiving Yard	5885 Pruitt Ave. Windsor CA 95492	NW	0.07 / 357.53	15
SMCI Windsor Fire Remediation Processing	5885 Pruitt Ave. Windsor CA 95492	NW	0.07 / 357.53	15
Atlas Tree Recycling Facility	5900 Pruitt Ave Windsor CA 95492	NW	0.09 / 467.28	23
	***Act Opl Status | Activity**: Active | Chipping and Grinding Facility/Operation*			
WMTF	586 Caletti Ave Windsor CA 95492	WNW	0.13 / 712.39	34
	***Act Opl Status | Activity**: Active | Limited Volume Transfer Operation*			
Windsor Material Recovery Facility	590 Caletti Avenue Windsor CA 95492	WNW	0.14 / 727.67	35
	***Act Opl Status | Activity**: Active | Medium Volume CDI Debris Processing Facility*			
Sonoma County IDS (2136)	475 Aviation Blvd Santa Rosa CA 95403	SW	0.23 / 1,238.02	56

C&D DEBRIS RECY - Construction and Demolition Debris Recyclers

A search of the C&D DEBRIS RECY database, dated Jun 20, 2018 has found that there are 3 C&D DEBRIS RECY site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
O'REILLY AUTO PARTS #3553	6500 HEMBREE LN STE 225 WINDSOR CA 95492	NNW	0.09 / 466.27	22
SONOMA COUNTY WATER AGENCY	404 AVIATION BLVD SANTA ROSA CA 95403	SSE	0.30 / 1,583.95	66

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
M AND M SERVICES INC	590 CALETTI AVE WINDSOR CA 95492	WNW	0.14 / 727.67	35

RECYCLING - Recycling Centers

A search of the RECYCLING database, dated Nov 2, 2020 has found that there are 1 RECYCLING site(s) within approximately 0.50 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
BROGARD INC	470 CALETTI AVE WINDSOR CA 95492	WNW	0.05 / 256.88	12

LUST - Leaking Underground Fuel Tank Reports

A search of the LUST database, dated Jun 22, 2021 has found that there are 5 LUST site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
SOILAND CO., INC.	1210 AIRPORT BLVD SANTA ROSA CA 95401	SSE	0.46 / 2,410.35	72
	Global ID* | *Status* | *Status Date: *T0609700225* | *COMPLETED - CASE CLOSED* | *3/6/1998*			
YOLO TRUCKING	5807 OLD REDWOOD HWY SANTA ROSA CA 95403	ENE	0.47 / 2,507.72	77
	Global ID* | *Status* | *Status Date: *T0609700284* | *COMPLETED - CASE CLOSED* | *9/24/1997*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
MOBIL STATION (FORMER)	705 SHILOH RD WINDSOR CA 95492	NW	0.03 / 142.75	10
	Global ID* | *Status* | *Status Date: *T0609700081* | *COMPLETED - CASE CLOSED* | *8/16/2013*			
RASMUSSEN, C.A., INC.	1012 SHILOH RD WINDSOR CA 95492	WNW	0.26 / 1,390.94	64

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
	Global ID* | *Status* | *Status Date: *T0609700459* | *COMPLETED - CASE CLOSED* | *10/7/1999*			
K & C TRUCKING	1514 AIRPORT BLVD SANTA ROSA CA 95401-1010	SSW	0.49 / 2,565.09	78
	Global ID* | *Status* | *Status Date: *T0609700486* | *COMPLETED - CASE CLOSED* | *6/25/2003*			

UST - Permitted Underground Storage Tank (UST) in GeoTracker

A search of the UST database, dated Oct 17, 2021 has found that there are 2 UST site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Hembree Shell #130	6301 Hembree Ln Windsor CA 95492	NNE	0.22 / 1,147.56	53
	Facility ID: *49-000-005989*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Windsor Valero	705 Shiloh Rd Windsor CA 95492	NW	0.03 / 142.75	10
	Facility ID: *49-000-007981*			

HHSS - Historical Hazardous Substance Storage Information Database

A search of the HHSS database, dated Aug 27, 2015 has found that there are 1 HHSS site(s) within approximately 0.25 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
TEXACO	701 SHILOH RD WIMDSOR CA 95492	NW	0.00 / 20.90	5

UST SWEEPS - Statewide Environmental Evaluation and Planning System

A search of the UST SWEEPS database, dated Oct 1, 1994 has found that there are 1 UST SWEEPS site(s) within approximately 0.25 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
SHILOH PARK ADAMS ENTERPRIZES	930 SHILOH RD WINDSOR CA	WNW	0.12 / 657.88	30
	C C* | *Status: *I49-000-1125* | *INACTIVE* ***Tank ID***: *000001*			

DELISTED TNK - Delisted Storage Tanks

A search of the DELISTED TNK database, dated Oct 26, 2021 has found that there are 3 DELISTED TNK site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Shiloh Center Shell	6301 Hembree Ln Windsor CA 95492	NNE	0.22 / 1,147.56	53

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
MOBIL STATION (FORMER)	705 SHILOH ROAD WINDSOR CA 95492	NW	0.03 / 142.75	10
MOBIL STATION (FORMER)	705 SHILOH RD WINDSOR CA 95492	NW	0.03 / 142.75	10

CERS TANK - California Environmental Reporting System (CERS) Tanks

A search of the CERS TANK database, dated Sep 24, 2021 has found that there are 5 CERS TANK site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Hembree Shell #130	6301 HEMBREE LN WINDSOR CA 95492 ***Site ID**: 122176*	NNE	0.22 / 1,147.56	53

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Windsor Valero	705 SHILOH RD WINDSOR CA 95492 ***Site ID**: 387408*	NW	0.03 / 142.75	10
West Coast Metals	470 CALETTI AV WINDSOR CA 95492 ***Site ID**: 407501*	WNW	0.05 / 256.88	12
Northgate Ready Mix	5922 PRUITT AVE WINDSOR CA 95492 ***Site ID**: 138858*	NW	0.06 / 330.69	14
Walmart #2553	6650 HEMBREE LN WINDSOR CA 95492 ***Site ID**: 407239*	NNW	0.14 / 762.06	36

HIST TANK - Historical Hazardous Substance Storage Container Information - Facility Summary

A search of the HIST TANK database, dated May 27, 1988 has found that there are 1 HIST TANK site(s) within approximately 0.25 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
TEXACO	701 SHILOH RD. WINDSOR CA	NW	0.00 / 20.90	5

CALSITES - CALSITES Database

A search of the CALSITES database, dated May 1, 2004 has found that there are 1 CALSITES site(s) within approximately 0.50 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
ECODYNE POND	930 SHILOH RD WINDSOR CA 95492	WNW	0.12 / 657.88	30

DEED - Deed Restrictions and Land Use Restrictions

A search of the DEED database, dated Jun 22, 2021 has found that there are 1 DEED site(s) within approximately 0.50 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Shiloh Oaks Company	5900 Pruitt Avenue Windsor CA 95492	NW	0.09 / 467.28	23

VCP - Voluntary Cleanup Program

A search of the VCP database, dated Sep 15, 2021 has found that there are 2 VCP site(s) within approximately 0.50 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
THE SHILOH GROUP PROPERTY	930 SHILOH ROAD WINDSOR CA 95492	WNW	0.12 / 657.88	30
	Estor/EPA ID* | *Cleanup Status: *60002191* | *ACTIVE AS OF 5/12/2015*			
CALETTI AVE	590 CALETTI AVE WINDSOR CA 95492	WNW	0.14 / 727.67	35
	Estor/EPA ID* | *Cleanup Status: *60001813* | *ACTIVE AS OF 9/25/2018*			

CLEANUP SITES - GeoTracker Cleanup Program Sites

A search of the CLEANUP SITES database, dated Jun 22, 2021 has found that there are 8 CLEANUP SITES site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
SHELL SERVICE STATION	6301 HEMBREE LANE WINDSOR CA 95492	NNE	0.22 / 1,147.56	53
	Status* | *Site Facility Type: *COMPLETED - CASE CLOSED* | *CLEANUP PROGRAM SITE*			
ROUND-TO-IT TIRE RECYCLERS	1070 AIRPORT BOULEVARD SANTA ROSA CA 95403	SSE	0.46 / 2,415.71	73
	Status* | *Site Facility Type: *COMPLETED - CASE CLOSED* | *CLEANUP PROGRAM SITE*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
REDWOOD SANITARY SERVICE FIRE	511 SHILOH ROAD WINDSOR CA 95492	NW	0.00 / 12.69	4
	Status* | *Site Facility Type: *COMPLETED - CASE CLOSED* | *CLEANUP PROGRAM SITE*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
SHILOH OAKS COMPANY	5900 PRUITT AVENUE WINDSOR CA 95492	NW	0.09 / 467.28	23
	***Status | Site Facility Type**: COMPLETED - CASE CLOSED | CLEANUP PROGRAM SITE*			
ECODYNE	930 SHILOH ROAD WINDSOR CA 95492	WNW	0.12 / 657.88	30
	***Status | Site Facility Type**: OPEN - VERIFICATION MONITORING | CLEANUP PROGRAM SITE*			
AIRPORT BUSINESS CENTER, PHASE 5, LOT 9	1010 SHILOH ROAD WINDSOR CA 95492	WNW	0.26 / 1,355.77	63
	***Status | Site Facility Type**: COMPLETED - CASE CLOSED | CLEANUP PROGRAM SITE*			
AIRPORT BUSINESS CENTER (LOTS 15 & 16)	1010 SHILOH ROAD WINDSOR CA 95492	WNW	0.26 / 1,355.77	63
	***Status | Site Facility Type**: COMPLETED - CASE CLOSED | CLEANUP PROGRAM SITE*			
SANTA ROSA STAINLESS STEEL	1400 AIRPORT BOULEVARD SANTA ROSA CA 95403	SSW	0.47 / 2,483.16	76
	***Status | Site Facility Type**: COMPLETED - CASE CLOSED | CLEANUP PROGRAM SITE*			

DELISTED COUNTY - Delisted County Records

A search of the DELISTED COUNTY database, dated Oct 8, 2021 has found that there are 22 DELISTED COUNTY site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
McDonalds- Walmart	6351 Hembree Lane Windsor, CA 95492 CA	N	0.17 / 919.49	43
Lithocraft, Inc.	424 Aviation Blvd. SANTA ROSA, CA 95403 CA	SSE	0.22 / 1,146.01	52
L-3 SONOMA EO	424 AVIATION BLVD SANTA ROSA, CA 95403 CA	SSE	0.22 / 1,146.01	52

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
MEED CLARK LUMBER	960 CALETTI WINDSOR, CA 95492 CA	NW	0.00 / 0.00	2
Mead Clark Lumber Company, Inc.	960 Caletti Av Windsor, CA 95492 CA	NW	0.00 / 0.00	2
SHILOH UNION 76 GAS STATION	705 SHILOH ROAD WINDSOR, CA 95492- CA	NW	0.03 / 142.75	10

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Quality Stainless Tanks	510 Caletti Ave. WINDSOR, CA 95492 CA	WNW	0.07 / 378.26	16
Standard Structures, Inc.	5910 Pruitt Ave Windsor, CA 95492 CA	NW	0.07 / 393.04	17
Best Truck Body & Trailer Repair, Inc.	610 Caletti Rd WINDSOR, CA 95492 CA	WNW	0.12 / 611.61	25
Best Truck Body Repair	600 Caletti Windsor, CA 95492 CA	WNW	0.12 / 631.88	27
ADAMS ENTERPRISES/LOUIE'S IRON WORKS	590 CALETTI WINDSOR, CA 95492 CA	WNW	0.12 / 652.15	29
Star Pools	930 Shiloh Road WINDSOR, CA 95492 CA	WNW	0.12 / 657.88	30
EMPIRE TOWING	930 SHILOH ROAD WINDSOR, CA 95492 CA	WNW	0.12 / 657.88	30
BACE ANALYTICAL DIVISION OF BRUNSING & ASSOCIATES	930 SHILOH ROAD WINDSOR, CA 95492 CA	WNW	0.12 / 657.88	30
AUTO GRAPHIX	930 SHILOH RD WINDSOR, CA 95492 CA	WNW	0.12 / 657.88	30
Batt's Tip Top Tree Service	584 Caletti Av WINDSOR, CA 95492 CA	WNW	0.13 / 664.31	31
Alan Precision & Dive Shop	580 Caletti Av WINDSOR, CA 95492 CA	WNW	0.13 / 672.42	32
Redwood Sanitary	930 Shiloh Rd. WINDSOR, CA 95492 CA	WNW	0.15 / 782.55	37
Battery Systems	930 Shiloh Rd., Bldg 1 Windsor, CA 95492 CA	WNW	0.15 / 782.55	37

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
MITRALIFE	451 AVIATION BLVD SANTA ROSA, CA 95403 CA	SSW	0.18 / 956.85	45
FMC Santa Rosa North	487 Aviation Blvd. SANTA ROSA, CA 95403 CA	SW	0.24 / 1,287.84	59
Four Corners (under construction)	792 Caletti Santa Rosa, CA CA	W	0.24 / 1,287.87	60

County

LOP SONOMA - Sonoma County - LOP Site List

A search of the LOP SONOMA database, dated Jun 30, 2021 has found that there are 5 LOP SONOMA site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Soiland Co., Inc.	1210 Airport Blvd Santa Rosa CA	SSE	0.46 / 2,410.35	72
	***LOP No** | **Status Desc**: 00001821 | Closed Site*			
Yolo Trucking	5807 Old Redwood Hwy Santa Rosa CA	ENE	0.47 / 2,507.72	77
	***LOP No** | **Status Desc**: 00002231 | Closed Site*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Mobil Station (former)	705 Shiloh Rd Windsor CA	NW	0.03 / 142.75	10
	***LOP No** | **Status Desc**: 00002581 | Closed Site*			
Rasmussen, C.A., Inc.	1012 Shiloh Rd Windsor CA	WNW	0.26 / 1,390.94	64
	***LOP No** | **Status Desc**: 00001389 | Closed Site*			
K & C Trucking	1514 Airport Blvd Santa Rosa CA	SSW	0.49 / 2,565.09	78
	***LOP No** | **Status Desc**: 00001239 | Closed Site*			

CUPA SONOMA - Sonoma County - CUPA Facilities List

A search of the CUPA SONOMA database, dated Jul 2, 2021 has found that there are 52 CUPA SONOMA site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
HIGH TECH BURRITO	6560 HEMBREE LN STE 178 WINDSOR, CA 95492 CA	NNW	0.09 / 451.10	21
Sally Beauty Supply #3859	6560 Hembree Ln Ste 186 Windsor, CA 95492 CA	NNW	0.09 / 451.10	21
O'Reilly Auto Parts #3553	6500 Hembree Ln 225, Windsor, CA 95492 CA	NNW	0.09 / 466.27	22
PIZZA GUYS	6500 Hembree LN STE # 202 Windsor, CA 95492 CA	NNW	0.09 / 466.27	22
WINGSTOP	6500 Hembree Ln Ste 205 Windsor, CA 95492 CA	NNW	0.09 / 466.27	22
SUBWAY	6400 Hembree LN STE 120 Windsor, CA 95492 CA	N	0.16 / 853.03	41
Former Office Depot #2208 (CLOSED)	6400 Hembree Ln Ste 100 Windsor, CA 95492 CA	N	0.16 / 853.03	41
Grocery Outlet	6400 HEMBREE LN WINDSOR, CA 95492 CA	N	0.16 / 853.03	41
Burger King	6351 Hembree Ln, Windsor, CA 95492 CA	N	0.17 / 919.49	43
Sonoma EO	428 Aviation Blvd Santa Rosa, CA 95403 CA	S	0.18 / 957.80	46
Airport Health Club	432 Aviation Blvd Santa Rosa, CA 95403 CA	S	0.20 / 1,033.88	48
The Home Depot Store #6667	6280 Hembree Lane Windsor, CA 95492 CA	N	0.20 / 1,046.83	49
L-3 SONOMA EO	424 AVIATION BLVD SANTA ROSA, CA 95403 CA	SSE	0.22 / 1,146.01	52

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Hembree Shell #130	6301 Hembree Ln Windsor, CA 95492 CA	NNE	0.22 / 1,147.56	53
HILTON GARDEN INN	417 Aviation SANTA ROSA, CA 95403 CA	SSE	0.25 / 1,316.75	61

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Windsor Valero	705 Shiloh Rd Windsor, CA 95492 CA	NW	0.03 / 142.75	10
FedEx Ground - ZSRO	500 Caletti Ave, Windsor, CA 95492 CA	SSW	0.04 / 227.62	11
West Coast Metals	470 Caletti Av Windsor, CA 95492 CA	WNW	0.05 / 256.88	12
Ahlborn Structural Steel, Inc. - Pruitt	5937 Pruitt Ave Windsor, CA 95492 CA	NW	0.05 / 272.82	13
Northgate Ready Mix	5922 Pruitt Ave Windsor, CA 95492 CA	NW	0.06 / 330.69	14
Quality Stainless Tanks	510 Caletti Ave, Windsor, CA 95492 CA	WNW	0.07 / 378.26	16
QUIZNO'S SUBS	6580 Hembree LN STE 260 Windsor, CA 95492 CA	NNW	0.07 / 395.03	19
SHILOH OAKS COMPANY, LLC	5892 PRUITT AVE WINDSOR, CA 95492 CA	NW	0.08 / 397.07	20
Sonoma Soil Builders	5900 Pruitt Ave Windsor, CA 95492 CA	NW	0.09 / 467.28	23
KRISTAR	5900 Pruitt AVE STE 230 Windsor, CA 95492 CA	NW	0.09 / 467.28	23

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
New Metal Coachworks, LLC	5900 Pruitt Ave # 104, Windsor, CA 95492 CA	NW	0.09 / 467.28	23
Applied Chemical	5900 Pruitt Ave Ste 280 Windsor, CA 95492 CA	NW	0.09 / 467.28	23
Siddiqui Rums Corporation	5900 Pruitt Ave Ste 404, Windsor, CA 95492 CA	NW	0.09 / 467.28	23
West Coast Auto Craft	5900 PRUITT AVE STE 230 WINDSOR, CA 95492 CA	NW	0.09 / 467.28	23
WESTERN TREE REMOVAL SPECIALISTS	5900 PRUITT AVE STE 530 WINDSOR, CA 95492 CA	NW	0.09 / 467.28	23
BamCore, LLC	5900 Pruitt Ave Ste 110, Windsor, CA 95492 CA	NW	0.09 / 467.28	23
Oakland Packaging	5900 Pruitt Ave Ste 100, Windsor, CA 95492 CA	NW	0.09 / 467.28	23
Sonoma Brothers Distilling	5900 Pruitt Ave Ste 404 Windsor, CA 95492 CA	NW	0.09 / 467.28	23
KFC/A&W	6610 Hembree Ln Windsor, CA 95492 CA	NNW	0.09 / 500.17	24
LandCare	930 Shiloh Rd Bldg 2, Yard 39 Windsor, CA 95492 CA	WNW	0.12 / 657.88	30
Kadon Trucking, Inc.	930 Shiloh Rd Bldg 15 Windsor, CA 95492 CA	WNW	0.12 / 657.88	30
All Around Auto Repair	930 Shiloh Rd Windsor, CA 95492 CA	WNW	0.12 / 657.88	30
North Bay Concrete, Inc.	930 Shiloh Rd Bldg 46 Windsor, CA 95492 CA	WNW	0.12 / 657.88	30

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
The Fluor Corporation	930 Shiloh Rd Windsor, CA 95492 CA	WNW	0.12 / 657.88	30
Shiloh Shop	930 Shiloh Rd Bldg 17 Windsor, CA 95492 CA	WNW	0.12 / 657.88	30
M&M Services, Inc	590 Caletti Ave Windsor, CA 95492 CA	WNW	0.14 / 727.67	35
Walmart #2553	6650 Hembree Ln Windsor, CA 95492 CA	NNW	0.14 / 762.06	36
Pacific Bracing Company	610 Caletti Ave Windsor, CA 95492 CA	WNW	0.15 / 803.40	38
Panda Express #1598	6560 Hembree Lane, Pad 6 Building Windsor, CA 95492 CA	NNW	0.16 / 843.20	40
Windsor Yard	550 Caletti Ave # 5, Windsor, CA 95492 CA	WSW	0.18 / 933.25	44
Silara Medtech Inc.	451 Aviation Blvd., Suite 107A Santa Rosa, CA 95403 CA	SSW	0.18 / 956.85	45
Best Truck Body	600 Caletti Ave Windsor, CA 95492 CA	WNW	0.21 / 1,093.88	50
Les Schwab Tire Center #635	6700 Hembree Ln Windsor, CA 95492 CA	NNW	0.21 / 1,093.99	51
Filtration Group	498 Aviation Blvd Santa Rosa, CA 95403 CA	SW	0.23 / 1,237.11	55
Tonnellerie Radoux USA, Inc	480 Aviation Boulevard, Santa Rosa, CA 95403 CA	SSW	0.24 / 1,255.85	57
Exchange Bank	440 Aviation Blvd, Santa Rosa, CA 95403 CA	SSW	0.24 / 1,260.00	58

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Bio-Rad Laboratories, Inc.	487 Aviation Blvd # 100 Santa Rosa, CA 95403 CA	SW	0.24 / 1,287.84	59

Non Standard

Federal

FINDS/FRS - Facility Registry Service/Facility Index

A search of the FINDS/FRS database, dated Nov 2, 2020 has found that there are 3 FINDS/FRS site(s) within approximately 0.02 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
REDWOOD SANITARY SERVICE FIRE	511 SHILOH ROAD WINDSOR CA 95492 ***Registry ID**: 110066648792*	NNW	0.02 / 93.91	7

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
STANDARD STRUCTURES INC	920 SHILOH ROAD WINDSOR CA 95492 ***Registry ID**: 110001177324*	NW	0.00 / 0.00	1
STANDARD STRUCTURESNA INC.	CA ***Registry ID**: 110066178200*	NW	0.00 / 2.41	3

HMIRS - Hazardous Materials Information Reporting System

A search of the HMIRS database, dated Sep 1, 2020 has found that there are 23 HMIRS site(s) within approximately 0.12 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
	920 SHILO RD WINDSOR CA	NW	0.00 / 0.00	1
	920 SHILOH RD SANTA ROSA CA	NW	0.00 / 0.00	1
	920 SHILOH RD #350 WINDSOR CA	NW	0.00 / 0.00	1
	920 SHILOH ROAD WINDSOR CA	NW	0.00 / 0.00	1

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
	920 SHILOH ROAD STE 350 WINDSOR CA	NW	0.00 / 0.00	1
	920 SHILOH RD SANTA ROSA CA	NW	0.00 / 0.00	1
	920 SHILO RD WINDSOR CA	NW	0.00 / 0.00	1
	920 SHILOH ROAD STE 350 WINDSOR CA	NW	0.00 / 0.00	1
	920 SHILOH ROAD WINDSOR CA	NW	0.00 / 0.00	1
	920 SHILOH RD #350 WINDSOR CA	NW	0.00 / 0.00	1
	5900 Pruitt Ave. WINDSOR CA	NW	0.02 / 121.27	9
	500 caletti ave WINDSOR CA	SSW	0.04 / 227.62	11
	500 caletti ave WINDSOR CA	SSW	0.04 / 227.62	11
	5900 pruiitt WINDSOR CA	NW	0.07 / 393.77	18
	5900 pruiitt WINDSOR CA	NW	0.07 / 393.77	18
	5900 Pruitt Ave. STE 164 WINDSOR CA	NW	0.09 / 467.28	23
	5900 pruitt ave WINDSOR CA	NW	0.09 / 467.28	23

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
	5900 pruitt ave # 164 SANTA ROSA CA	NW	0.09 / 467.28	23
	5900 PRUITT AVE #164 WINDSOR CA	NW	0.09 / 467.28	23
	5900 Pruitt Ave. Ste 164 WINDSOR CA	NW	0.09 / 467.28	23
	5900 pruitt ave # 164 SANTA ROSA CA	NW	0.09 / 467.28	23
	5900 pruitt ave # 164 SANTA ROSA CA	NW	0.09 / 467.28	23
	5900 PRUITT AVE #164 WINDSOR CA	NW	0.09 / 467.28	23

FUDS - Formerly Used Defense Sites

A search of the FUDS database, dated May 26, 2021 has found that there are 1 FUDS site(s) within approximately 1.00 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Santa Rosa Army Airfield	WINDSOR CA ***FUDS Property No**: J09CA0026*	S	0.45 / 2,364.30	71

ALT FUELS - Alternative Fueling Stations

A search of the ALT FUELS database, dated Oct 25, 2021 has found that there are 1 ALT FUELS site(s) within approximately 0.25 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Walmart	6650 Hembree Ln Windsor CA 95492 ***ID**: 198738*	NNW	0.14 / 762.06	36

State

HWSS CLEANUP - Hazardous Waste and Substances Site List - Site Cleanup

A search of the HWSS CLEANUP database, dated May 20, 2021 has found that there are 1 HWSS CLEANUP site(s) within approximately 0.50 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
ECODYNE POND	930 SHILOH RD WINDSOR CA 95492	W	0.26 / 1,355.29	62

***Estor/EPA ID | Cleanup Status**: 49240001 | ACTIVE AS OF 5/1/1986*

HAZNET - Hazardous Waste Manifest Data

A search of the HAZNET database, dated Oct 24, 2016 has found that there are 5 HAZNET site(s) within approximately 0.02 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
STANDARD STRUCTURES INC	920 SHILOH WINDSOR CA 954920000	NW	0.00 / 0.00	1
FED EX GROUND	920 SHILOH RD UNIT 350 WINDSOR CA 95492	NW	0.00 / 0.00	1
1X SOCO STEEL FABRICATIONS INC	960 CALETTI WINDSOR CA 954920000	NW	0.00 / 0.00	2
AUTO VISION OF WINDSOR	701 SHILOH RD WINDSOR CA 954920000	NW	0.00 / 20.90	5
VIC'S AUTO REPAIR	701 SHILOH RD WINDSOR CA 954920000	NW	0.00 / 20.90	5

HIST CORTESE - Historical Cortese List

A search of the HIST CORTESE database, dated Nov 13, 2008 has found that there are 1 HIST CORTESE site(s) within approximately 0.50 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
ECODYNE POND	930 SHILOH RD WINDSOR CA 95492	NW	0.01 / 64.11	6

CDO/CAO - Cease and Desist Orders and Cleanup and Abatement Orders

A search of the CDO/CAO database, dated Jul 19, 2020 has found that there are 5 CDO/CAO site(s) within approximately 0.50 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Marmon Group Ecodyne/Shiloh Industrial Park	930 Shiloh Road Windsor CA 95492	WNW	0.12 / 657.88	30
Marmon Group Ecodyne/Shiloh Industrial Park	930 Shiloh Road Windsor CA 95492	WNW	0.12 / 657.88	30

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Marmon Group Ecodyne/Shiloh Industrial Park	930 Shiloh Road Windsor CA 95492	WNW	0.12 / 657.88	30
Marmon Group Ecodyne/Shiloh Industrial Park	930 Shiloh Road Windsor CA 95492	WNW	0.12 / 657.88	30
Marmon Group Ecodyne/Shiloh Industrial Park	930 Shiloh Road Windsor CA 95492	WNW	0.12 / 657.88	30

CERS HAZ - California Environmental Reporting System (CERS) Hazardous Waste Sites

A search of the CERS HAZ database, dated Sep 24, 2021 has found that there are 14 CERS HAZ site(s) within approximately 0.12 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Sally Beauty Supply #3859	6560 HEMBREE LN STE 186 WINDSOR CA 95492	NNW	0.09 / 451.10	21
O'Reilly Auto Parts #3553	6500 HEMBREE LN 225 WINDSOR CA 95492	NNW	0.09 / 466.27	22
WINGSTOP	6500 HEMBREE LN STE 205 WINDSOR CA 95492	NNW	0.09 / 466.27	22

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
FedEx Ground - ZSRO	500 CALETTI AVE WINDSOR CA 95492	SSW	0.04 / 227.62	11
Ahlborn Structural Steel, Inc. - Pruitt	5937 PRUITT AVE WINDSOR CA 95492	NW	0.05 / 272.82	13
Quality Stainless Tanks	510 CALETTI AVE WINDSOR CA 95492	WNW	0.07 / 378.26	16
New Metal Coachworks, LLC	5900 PRUITT AVE # 104 WINDSOR CA 95492	NW	0.09 / 467.28	23
Sonoma Brothers Distilling	5900 PRUITT AVE STE 404 WINDSOR CA 95492	NW	0.09 / 467.28	23

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
KFC/A&W	6610 HEMBREE LN WINDSOR CA 95492	NNW	0.09 / 500.17	24
Shiloh Shop	930 SHILOH RD BLDG 17 WINDSOR CA 95492	WNW	0.12 / 657.88	30
All Around Auto Repair	930 SHILOH RD WINDSOR CA 95492	WNW	0.12 / 657.88	30
Kadon Trucking, Inc.	930 SHILOH RD BLDG 15 WINDSOR CA 95492	WNW	0.12 / 657.88	30
LandCare	930 SHILOH RD BLDG 2, YARD 39 WINDSOR CA 95492	WNW	0.12 / 657.88	30
North Bay Concrete, Inc.	930 SHILOH RD BLDG 46 WINDSOR CA 95492	WNW	0.12 / 657.88	30

DELISTED HAZ - Delisted Environmental Reporting System (CERS) Hazardous Waste Sites

A search of the DELISTED HAZ database, dated Nov 29, 2018 has found that there are 16 DELISTED HAZ site(s) within approximately 0.50 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Wine Country Autoworks	399 BUSINESS PARK CT STE 102 WINDSOR CA 95492	NNE	0.37 / 1,968.36	68
Mi Burrito Mexican Restaurant & Bar	385 AVIATION BLVD STE D SANTA ROSA CA 95403	SE	0.41 / 2,144.19	70
slaight heavy haul yard	1060 AIRPORT BLVD SANTA ROSA CA 95403	SSE	0.46 / 2,419.05	74

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Standard Structures, Inc.	920 SHILOH RD WINDSOR CA 95492	NW	0.00 / 0.00	1
Northgate Ready Mix	5922 PRUITT AVE WINDSOR CA 95492	NW	0.06 / 330.69	14

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
TDE Equipment INC	5900 PRUITT AVE STE 710 WINDSOR CA 95492	NW	0.07 / 393.77	18
Oakland Packaging	5900 PRUITT AVE STE 100 WINDSOR CA 95492	NW	0.09 / 467.28	23
Western Tree Removal Specialists	5900 PRUITT AVE WINDSOR CA 95492	NW	0.09 / 467.28	23
Sonoma Soil Builders	5900 PRUITT AVE WINDSOR CA 95492	NW	0.09 / 467.28	23
Shiloh Oaks Co., LLC	5900 PRUITT AVE WINDSOR CA 95492	NW	0.09 / 467.28	23
Applied Chemical	5900 PRUITT AVE STE 280 WINDSOR CA 95492	NW	0.09 / 467.28	23
West Coast Auto Craft	590 PRUITT AVE STE 230 WINDSOR CA 95492	NW	0.09 / 467.28	23
The Fluor Corporation	930 SHILOH RD WINDSOR CA 95492	WNW	0.12 / 657.88	30
FMC Dialysis	487 AVIATION BLVD, STE 110 SANTA ROSA CA 95403	SW	0.24 / 1,287.84	59
Kenwood Distribution Center	501 AVIATION BLVD SANTA ROSA CA 95403	SW	0.27 / 1,414.28	65
American Tank Company, Inc.	501 AMERICAN WAY WINDSOR CA 95492	NW	0.34 / 1,787.42	67


EMISSIONS - Toxic Pollutant Emissions Facilities

A search of the EMISSIONS database, dated Dec 31, 2019 has found that there are 19 EMISSIONS site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
AIRPORT HEALTH CLUB	432 AVIATION BOULEVARD SANTA ROSA CA 95403	S	0.20 / 1,033.88	48
THE HOME DEPOT #6667	6280 HEMBREE LANE WINDSOR CA 95492	N	0.20 / 1,046.83	49
LITHOCRAFT, INC	424 AVIATION BOULEVARD SANTA ROSA CA 95403	SSE	0.22 / 1,146.01	52
HEMBREE SHELL	6301 HEMBREE LN WINDSOR CA 95492	NNE	0.22 / 1,147.56	53

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
STANDARD STRUCTURES INC	920 SHILOH ROAD WINDSOR CA 95492	NW	0.00 / 0.00	1
B & B SERVICE STATION	705 SHILOH RD WINDSOR CA 95492	NW	0.03 / 142.75	10
FORMER MOBIL STATION 99-HLH C/	705 SHILOH ROAD WINDSOR CA 95492	NW	0.03 / 142.75	10
AHLBORN STEEL 4 FENCE	5937 PRUITT AVENUE WINDSOR CA 95492	NW	0.05 / 272.82	13
NORTHGATE READY MIX	5922 PRUITT AVENUE WINDSOR CA 95492	NW	0.06 / 330.69	14
REDBUILT LLC	5900 PRUITT AVENUE WINDSOR CA 95492	NW	0.09 / 467.28	23
WESTERN FIBERGLASS	930 SHILOH RD, BLDG 2 WINDSOR CA 95492	WNW	0.12 / 657.88	30
IT CORPORATION	930 SHILOH ROAD WINDSOR CA 95492	WNW	0.12 / 657.88	30
RUIZ AUTOBODY	930 SHILOH RD, BLDG 2, STE B WINDSOR CA 95492	WNW	0.12 / 657.88	30

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
MARTIN'S TRUCK REPAIR	930 SHILOH RD WINDSOR CA 95492	WNW	0.12 / 657.88	30
MARTIN'S TRUCK REPAIR	930 SHILOH RD, BLDG 2, STE B WINDSOR CA 95492	WNW	0.12 / 657.88	30
CARL'S READY MIX	340 STANDARD AVENUE WINDSOR CA 95492	W	0.16 / 835.49	39
HOME DEPOT #6667	6280 HEMBREE LANE WINDSOR CA 95492	NNW	0.17 / 879.21	42
EXCHANGE BANK	440 AVIATION BOULEVARD SANTA ROSA CA 95403	SSW	0.24 / 1,260.00	58
BIO-RAD LABORATORIES	487 AVIATION BLVD, STE 100 SANTA ROSA CA 95403	SW	0.24 / 1,287.84	59



Map: 1.0 Mile Radius


Order Number: 21111700210

Address: 790 Shiloh Road, WINDSOR, CA

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Eris Areas with Higher Elevation
- Eris Areas with Same Elevation
- Eris Areas with Lower Elevation
- Eris Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major & Minor Arterial
- Traffic Circle; Ramp
- Local Road
- Rail
- State
- Country
- National Priority List Sites
- National Wetland
- Indian Reserve Land
- Historic Fill
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas
- Plume

Source: © 2021 ESRI StreetMap Premium

© ERIS Information Inc.



Map: 0.5 Mile Radius


Order Number: 21111700210

Address: 790 Shiloh Road, WINDSOR, CA

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Eris Areas with Higher Elevation
- Eris Areas with Same Elevation
- Eris Areas with Lower Elevation
- Eris Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major & Minor Arterial
- Traffic Circle; Ramp
- Local Road
- Rail
- State
- Country
- National Priority List Sites
- National Wetland
- Indian Reserve Land
- Historic Fill
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas
- Plume

Source: © 2021 ESRI StreetMap Premium

© ERIS Information Inc.



Map: 0.25 Mile Radius

Order Number: 21111700210

Address: 790 Shiloh Road, WINDSOR, CA

- Project Property
- Buffer Outline
- Eris Sites with Higher Elevation
- Eris Sites with Same Elevation
- Eris Sites with Lower Elevation
- Eris Sites with Unknown Elevation
- Eris Areas with Higher Elevation
- Eris Areas with Same Elevation
- Eris Areas with Lower Elevation
- Eris Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major & Minor Arterial
- Traffic Circle; Ramp
- Local Road
- Rail
- State
- Country
- National Priority List Sites
- National Wetland
- Indian Reserve Land
- Historic Fill
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas
- Plume

Source: © 2021 ESRI StreetMap Premium

© ERIS Information Inc.




Aerial **Year: 2020**

Order Number: 21111700210

Address: 790 Shiloh Road, WINDSOR, CA

Source: ESRI World Imagery

© ERIS Information Inc.



Topographic Map

Year: 2015

Order Number: 21111700210

Address: 790 Shiloh Road, CA

Quadrangle(s): Sebastopol, CA; Healdsburg, CA; Mark West Springs, CA

Source: USGS Topographic Map

© ERIS Information Inc.

Detail Report

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	1 of 15	NW	0.00 / 0.00	114.25 / -6	STANDARD STRUCTURES INC 920 SHILOH ROAD WINDSOR CA 95492	FINDS/FRS

Registry ID: 110001177324
FIPS Code: 06097
HUC Code: 18010110
Site Type Name: STATIONARY
Location Description:
Supplemental Location:
Create Date: 01-MAR-00
Update Date: 01-JUN-17
Interest Types: HAZARDOUS AIR POLLUTANT MAJOR, STATE MASTER
SIC Codes: 2439
SIC Code Descriptions: STRUCTURAL WOOD MEMBERS, NOT ELSEWHERE CLASSIFIED
NAICS Codes:
NAICS Code Descriptions:
Conveyor: FRS-GEOCODE
Federal Facility Code:
Federal Agency Name:
Tribal Land Code:
Tribal Land Name:
Congressional Dist No: 01
Census Block Code: 060971538081024
EPA Region Code: 09
County Name: SONOMA
US/Mexico Border Ind:
Latitude: 38.525772
Longitude: -122.796182
Reference Point: ENTRANCE POINT OF A FACILITY OR STATION
Coord Collection Method: ADDRESS MATCHING-HOUSE NUMBER
Accuracy Value: 50
Datum: NAD83
Source:
Facility Detail Rprt URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110001177324
Program Acronyms:

CA-ENVIROVIEW:347697, EIS:2346911

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	2 of 15	NW	0.00 / 0.00	114.25 / -6	920 SHILO RD WINDSOR CA	HMIRS

Incident County: SONOMA

HMIR Historical Reports

Report No: I-1996080792
Report Type: A hazardous material incident
Date of Incident: 07/24/1996
Time of Incident: 0730
Haz Class Code: 3
Hazardous Class: FLAMMABLE - COMBUSTIBLE LIQUID
Commodity Short Nm: HEXANES
Commodity Long Nm: HEXANES
Trade Name:
Fed DOT Agency Nm:
Fed DOT Report No:
Report Submit Src: Paper
Inc Multiple Rows: No
Inc Non US State:
Mode Transport: Highway
Transport Phase: UNLOADING
Incident Occrrnce:
Mat Ship Approval?: No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

ID No:	UN1208	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	1	**CR Street Name:**	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	**CR City:**	CORAOPOLIS
What Failed:	109; 103	**CR State:**	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug); Basic Material	**CR Postal Code:**	15108-9373
How Failed Code:	;	**CR Non US State:**	
How Failed Desc:	;	**CR Fed DOT ID:**	265752
Failure Cause Code:	526; 538	**CR Hazmat Reg ID:**	
Failure Cause Desc:	Loose Closure Component or Device; Water Damage	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	BECKLEY-CARDY INC
Cont1 Pkging Type:		**Shipper Street Name:**	100 PARAGON PKWY
Cont1 Const Mat:		**Shipper City:**	MANSFIELD
Cont1 Head Type:		**Shipper State:**	OH
Cont1 Pkg Capacity:	1	**Shipper Postal:**	44903-8056
C1 Capacity UOM:	LGA	**Shipper Non US St:**	
Cont1 Pkg Amt:		**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	4491724455242
Cont1 Pkg No:	1	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	1	**Origin City:**	MANSFIELD
Cont1 Pkg Mnfctr:	COLUMBUS CHEMICAL	**Origin State:**	OHIO
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	44903
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:		**Destination City:**	SEBASTOPOL
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95472
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	
C1 Head Thick UOM:		**Cont2 Const Mat:**	
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	1
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	LGA
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	1
C1 Device Model:		**Cont2 Pkg No Failed:**	1
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:		**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	No	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	NANCY JENKINS
Damage > 500:	No	**Contact Title:**	HAZMAT COORDINATOR
Material Loss:	100	**Contact Business:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Carrier Damage:	0	**Contact Street:**	
Property Damage:	0	**Contact City:**	
Response Cost:	0	**Contact State:**	
Remediation Cost:	25	**Contact Postal:**	
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	125	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	4G
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: PACKAGE WAS UNLOADED WITH LEAKAGE NOTED ON THE BOX. EXAMINATION OF THE INNER CONTAINER REVEALED THAT THE CONTAINER(S) HAD LOOSE CAP(S) AND LEAKED. THE LEAKAGE WAS CONTAINED. THE CAP(S) WERE SECURED. CARTON WAS WET BUT OTHERWISE UNDAMAGED. PACKAGE WAS REPACKED FOR RETURN TO THE SHIPPER.

Recommend Actions Taken:

1	***3 of 15***	***NW***	***0.00 / 0.00***	***114.25 / -6***	***920 SHILOH RD SANTA ROSA CA***	***HMIRS***

Incident County: SONOMA

HMIR Historical Reports

Report No:	I-1996030657	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	02/15/1996	**Report Submit Src:**	Paper
Time of Incident:	0700	**Inc Multiple Rows:**	No
Haz Class Code:	8	**Inc Non US State:**	
Hazardous Class:	CORROSIVE MATERIAL	**Mode Transport:**	Highway
Commodity Short Nm:	CORROSIVE LIQUIDS N.O.S.	**Transport Phase:**	UNLOADING
Commodity Long Nm:	CORROSIVE LIQUIDS N.O.S.	**Incident Occrrnce:**	
Trade Name:	PHOSPHORIC ACID ZINC	**Mat Ship Approval?:**	No
ID No:	UN1760	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.0625	**CR Street Name:**	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	**CR City:**	CORAOPOLIS
What Failed:	103;	**CR State:**	PA
What Failed Desc:	Basic Material;	**CR Postal Code:**	15108-9373
How Failed Code:	309;	**CR Non US State:**	
How Failed Desc:	Punctured;	**CR Fed DOT ID:**	265752
Failure Cause Code:	511; 516	**CR Hazmat Reg ID:**	
Failure Cause Desc:	Dropped; Impact with Sharp or Protruding Object (e.g. nails)	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	NALCO COMPANY LLC
Cont1 Pkging Type:		**Shipper Street Name:**	7701 HIGHWAY 90A
Cont1 Const Mat:		**Shipper City:**	SUGAR LAND
Cont1 Head Type:		**Shipper State:**	TX
Cont1 Pkg Capacity:	5	**Shipper Postal:**	77478-2121
C1 Capacity UOM:	LGA	**Shipper Non US St:**	
Cont1 Pkg Amt:		**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	7757755450018135
Cont1 Pkg No:	1	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	1	**Origin City:**	SUGAR LAND

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Cont1 Pkg Mnfctr:	NAMPAC-PA	**Origin State:**	TEXAS
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	77478
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:		**Destination City:**	PETALUMA
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	94952
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	
C1 Head Thick UOM:		**Cont2 Const Mat:**	
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	
C1 Device Model:		**Cont2 Pkg No Failed:**	
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:		**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	No	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	NANCY JENKINS
Damage > 500:	No	**Contact Title:**	HAZMAT COORDINATOR
Material Loss:	100	**Contact Business:**	
Carrier Damage:	0	**Contact Street:**	
Property Damage:	0	**Contact City:**	
Response Cost:	0	**Contact State:**	
Remediation Cost:	25	**Contact Postal:**	
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	125	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	1H1
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Non-removable head plastic drum
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: PAIL WAS DROPPED AT UNLOAD. EXAMINATION REVEALED A SMALL PUNCTURE WHICH ALLOWED THE CONTENTS TO ESCAPE. THE LEAKAGE WAS CONTAINED. PAIL WAS REPACKED FOR RETURN TO THE SHIPPER.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Recommend Actions Taken:						
1	4 of 15	NW	0.00 / 0.00	114.25 / -6	920 SHILOH RD #350 WINDSOR CA	HMIRS

Incident County: SONOMA

HMIR Historical Reports

Report No:	I-2002060588	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	05/23/2002	**Report Submit Src:**	Paper
Time of Incident:	0730	**Inc Multiple Rows:**	No
Haz Class Code:	8	**Inc Non US State:**	
Hazardous Class:	CORROSIVE MATERIAL	**Mode Transport:**	Highway
Commodity Short Nm:	NITRIC ACID OTHER THAN R	**Transport Phase:**	LOADING
Commodity Long Nm:	NITRIC ACID OTHER THAN RED FUMING WITH AT LEAST 65 PERCENT BUT NOT MORE THAN 70 PERCENT NITRIC ACID	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN2031	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.25	**CR Street Name:**	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	**CR City:**	CORAOPOLIS
What Failed:	109; 103	**CR State:**	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug); Basic Material	**CR Postal Code:**	15108-9373
How Failed Code:	;	**CR Non US State:**	
How Failed Desc:	;	**CR Fed DOT ID:**	265752
Failure Cause Code:	526; 538	**CR Hazmat Reg ID:**	
Failure Cause Desc:	Loose Closure Component or Device; Water Damage	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	VULPINE INC.
Cont1 Pkging Type:		**Shipper Street Name:**	1127 57TH AVE
Cont1 Const Mat:		**Shipper City:**	OAKLAND
Cont1 Head Type:		**Shipper State:**	CA
Cont1 Pkg Capacity:	4	**Shipper Postal:**	94621-4427
C1 Capacity UOM:	LGA	**Shipper Non US St:**	
Cont1 Pkg Amt:		**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	094614500057977
Cont1 Pkg No:	1	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	1	**Origin City:**	OAKLAND
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	**Origin State:**	CALIFORNIA
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	94621
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:		**Destination City:**	SANTA ROSA
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95403
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	
C1 Head Thick UOM:		**Cont2 Const Mat:**	
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	1
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	LGA
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	4
C1 Device Model:		**Cont2 Pkg No Failed:**	1
NRC No:			
RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:		**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	No	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	SCOTT KERR
Damage > 500:	Yes	**Contact Title:**	HAZMAT MANAGER
Material Loss:	100	**Contact Business:**	
Carrier Damage:	0	**Contact Street:**	
Property Damage:	0	**Contact City:**	
Response Cost:	0	**Contact State:**	
Remediation Cost:	425	**Contact Postal:**	
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	525	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: THE PACKAGE WAS UNLOADED WITH LEAKAGE NOTED ON THE BOX. EXAMINATION OF THE INNER CONTAINER REVEALED THAT THE CONTAINER(S) HAD LOOSE CAP(S) AND LEAKED. THE LEAKAGE WAS CONTAINED. THE CAP(S) WERE SECURED. THE CARTON WAS WET BUT OTHERWISE UNDAMAGED. THE UNDAMAGED PORTION OF THE PACKAGE WAS REPACKED FOR RETURN TO SHIPPER.

Recommend Actions Taken:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	5 of 15	NW	0.00 / 0.00	114.25 / -6	920 SHILOH ROAD WINDSOR CA	HMIRS

Incident County: SONOMA

HMIR Historical Reports

Report No:	I-2005020768	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	01/13/2005	**Report Submit Src:**	Paper
Time of Incident:	2038	**Inc Multiple Rows:**	No
Haz Class Code:	3	**Inc Non US State:**	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID	**Mode Transport:**	Highway
Commodity Short Nm:	ETHYL ALCOHOL	**Transport Phase:**	UNLOADING
Commodity Long Nm:	ETHYL ALCOHOL	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1170	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No

Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	II
TIH Hazard Zone:		***Carrier Reporter:***	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.007813	***CR Street Name:***	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	***CR City:***	CORAOPOLIS
What Failed:	109	***CR State:***	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	***CR Postal Code:***	15108-9373
How Failed Code:		***CR Non US State:***	
How Failed Desc:		***CR Fed DOT ID:***	265752
Failure Cause Code:		***CR Hazmat Reg ID:***	062904001002M
Failure Cause Desc:		***CR Country:***	US
Ident. Markings:	4G/Y20/5/04 USA/M5431	***Shipper Name:***	AAPER ALCOHOL AND CHEMICAL CO
Cont1 Pkging Type:	Box	***Shipper Street Name:***	1101 ISAAC SHELBY DR
Cont1 Const Mat:	Fiberboard	***Shipper City:***	SHELBYVILLE
Cont1 Head Type:		***Shipper State:***	KY
Cont1 Pkg Capacity:	5	***Shipper Postal:***	40065-8171
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	5	***Shipper Country:***	US
C1 Pkg Amt UOM:	LGA	***Shipper Waybill:***	040250130056684
Cont1 Pkg No:	1	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	SHELBYVILLE
Cont1 Pkg Mnfctr:		***Origin State:***	KENTUCKY
Cont1 Pkg Mnfct Dt:		***Origin Postal:***	40065
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:		***Origin Country:***	US
C1 Test Const Mat:	Fiberboard	***Destination City:***	HEALDSBURG
C1 Pkg Dsign Pres.:		***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	95448
C1 Pkg Shell Thick:		***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:		***Cont2 Package Type:***	Bag
C1 Head Thick UOM:		***Cont2 Const Mat:***	Plastic
C1 Pkg Srvc Pres.:		***Cont2 Pkg Capacity:***	5
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	LGA
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	5
C1 Device Type:		***Cont2 Pkg Amt UOM:***	LGA
C1 Device Mnfctr:		***Cont2 Pkg No:***	1
C1 Device Model:		***Cont2 Pkg No Failed:***	1
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	0
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	0
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:		***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	Yes	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	DENISE HANCHULAK
Damage > 500:	No	***Contact Title:***	TSM MANAGER II - SAFETY
Material Loss:	0	***Contact Business:***	Fedex Ground Package System Inc.
Carrier Damage:	0	***Contact Street:***	1000 Fedex Drive
Property Damage:	0	***Contact City:***	MOON TOWNSHIP
Response Cost:	0	***Contact State:***	PA

Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	4G
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: THE PACKAGE WAS DROPPED IN HANDLING. EXAMINATION OF THE INNER CONTAINER REVEALED A RUPTURED SEAM WHICH ALLOWED THE CONTENTS TO ESCAPE. THE LEAKAGE WAS CONTAINED. THE UNDAMAGED PORTION OF THE PACKAGE WAS REPACKED FOR RETURN TO SHIPPER.

Recommend Actions Taken:

HMIR Historical Reports

Report No:	I-2005080037	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	05/24/2005	**Report Submit Src:**	Paper
Time of Incident:	0500	**Inc Multiple Rows:**	No
Haz Class Code:	3	**Inc Non US State:**	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID	**Mode Transport:**	Highway
Commodity Short Nm:	PAINT INCLUDING PAINT L	**Transport Phase:**	UNLOADING
Commodity Long Nm:	PAINT INCLUDING PAINT LACQUER ENAMEL STAIN SHELLAC SOLUTIONS VARNISH POLISH LIQUID FILLER AND LIQUID LACQUER BASE	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1263	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.50	**CR Street Name:**	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	**CR City:**	CORAOPOLIS
What Failed:	110; 110	**CR State:**	PA
What Failed Desc:	Cover; Cover	**CR Postal Code:**	15108-9373
How Failed Code:	308; 308	**CR Non US State:**	
How Failed Desc:	Leaked; Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	526; 517	**CR Hazmat Reg ID:**	062904001002M
Failure Cause Desc:	Loose Closure Component or Device; Improper Preparation for Transportation	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	AXALTA COATING SYSTEMS LLC
Cont1 Pkging Type:	Box	**Shipper Street Name:**	11535 PRODUCTION DR
Cont1 Const Mat:	Fiberboard	**Shipper City:**	RENO
Cont1 Head Type:		**Shipper State:**	NV
Cont1 Pkg Capacity:	4	**Shipper Postal:**	89506-2615
C1 Capacity UOM:	LGA	**Shipper Non US St:**	
Cont1 Pkg Amt:	4	**Shipper Country:**	US
C1 Pkg Amt UOM:	LGA	**Shipper Waybill:**	025525930055160
Cont1 Pkg No:	1	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	1	**Origin City:**	RENO
Cont1 Pkg Mnfctr:		**Origin State:**	NEVADA
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	89506
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:	Fiberboard	**Destination City:**	LAKEPORT
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95453

C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	Can
C1 Head Thick UOM:		**Cont2 Const Mat:**	Metal (any type)
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	2
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	LGA
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	2
C1 Device Type:		**Cont2 Pkg Amt UOM:**	LGA
C1 Device Mnfctr:		**Cont2 Pkg No:**	2
C1 Device Model:		**Cont2 Pkg No Failed:**	2
NRC No:			
RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	DENISE HANCHULAK
Damage > 500:	No	**Contact Title:**	TSM MANAGER II - SAFETY
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: THE PAIL WAS UNLOADED WITH LEAKAGE NOTED. EXAMINATION OF THE PAIL REVELAED THE PAIL HAD A LOOSE CAP/LID AND LEAKED. THE LEAKAGE WAS CONTAINED. THE CAP/LID WAS SECURED. UNDAMAGED PRODUCT WAS RETURNED TO THE SHIPPER. THE DAMAGED PRODUCT WAS PROPERLY DISPOSED OF IN A CCORDANCE WITH FEDERAL REGULATIONS.

Recommend Actions Taken:

HMIR Historical Reports

Report No: I-1999090829 **Fed DOT Agency Nm:**

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	08/20/1999	**Report Submit Src:**	Paper
Time of Incident:	0800	**Inc Multiple Rows:**	No
Haz Class Code:	8	**Inc Non US State:**	
Hazardous Class:	CORROSIVE MATERIAL	**Mode Transport:**	Highway
Commodity Short Nm:	CORROSIVE LIQUIDS N.O.S.	**Transport Phase:**	UNLOADING
Commodity Long Nm:	CORROSIVE LIQUIDS N.O.S.	**Incident Occrrnce:**	
Trade Name:	POTASSIUM HYDROXIDE	**Mat Ship Approval?:**	No
ID No:	UN1760	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.132086	**CR Street Name:**	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	**CR City:**	CORAOPOLIS
What Failed:	109; 103	**CR State:**	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug); Basic Material	**CR Postal Code:**	15108-9373
How Failed Code:	303; 310	**CR Non US State:**	
How Failed Desc:	Burst or Ruptured; Ripped or Torn	**CR Fed DOT ID:**	265752
Failure Cause Code:	511; 511	**CR Hazmat Reg ID:**	
Failure Cause Desc:	Dropped; Dropped	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	FUJIFILM HUNT CHEMICALS U.S.A. INC.
Cont1 Pkging Type:		**Shipper Street Name:**	14820 CARMENITA RD STE B
Cont1 Const Mat:		**Shipper City:**	NORWALK
Cont1 Head Type:		**Shipper State:**	CA
Cont1 Pkg Capacity:	0.528344	**Shipper Postal:**	90650-9201
C1 Capacity UOM:	LGA	**Shipper Non US St:**	
Cont1 Pkg Amt:		**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	024949500014530
Cont1 Pkg No:	1	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	1	**Origin City:**	CITY OF INDUSTRY
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	**Origin State:**	CALIFORNIA
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	91746
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:		**Destination City:**	SANTA ROSA
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95401
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	
C1 Head Thick UOM:		**Cont2 Const Mat:**	
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	0.132086
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	LGA
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	4
C1 Device Model:		**Cont2 Pkg No Failed:**	1
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:		**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	No	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	SCOTT KERR
Damage > 500:	No	**Contact Title:**	HAZMAT ADMINISTRATOR
Material Loss:	100	**Contact Business:**	
Carrier Damage:	0	**Contact Street:**	
Property Damage:	0	**Contact City:**	
Response Cost:	0	**Contact State:**	
Remediation Cost:	25	**Contact Postal:**	
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	125	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	4G
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: THE PACKAGE WAS DROPPED IN HANDLING. EXAMINATION OF THE INNER CONTAINER REVEALED A RUPTURED SEAM WHICH ALLOWED THE CONTENTS TO ESCAPE. THE LEAKAGE WAS CONTAINED. THE PACKAGE WAS REPACKED FOR RETURN TO SHIPPER.

Recommend Actions Taken:

1	6 of 15	NW	0.00 / 0.00	114.25 / -6	920 SHILOH ROAD STE 350 WINDSOR CA	HMIRS

Incident County: SONOMA

HMIR Historical Reports

Report No:	I-1998031278	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	03/12/1998	**Report Submit Src:**	Paper
Time of Incident:	1100	**Inc Multiple Rows:**	No
Haz Class Code:	8	**Inc Non US State:**	
Hazardous Class:	CORROSIVE MATERIAL	**Mode Transport:**	Highway
Commodity Short Nm:	CORROSIVE LIQUIDS N.O.S.	**Transport Phase:**	UNLOADING
Commodity Long Nm:	CORROSIVE LIQUIDS N.O.S.	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1760	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.031250	**CR Street Name:**	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	**CR City:**	CORAOPOLIS
What Failed:	109; 103	**CR State:**	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug); Basic Material	**CR Postal Code:**	15108-9373
How Failed Code:	;	**CR Non US State:**	
How Failed Desc:	;	**CR Fed DOT ID:**	265752
Failure Cause Code:	526; 538	**CR Hazmat Reg ID:**	
Failure Cause Desc:	Loose Closure Component or Device; Water Damage	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	P I P C
Cont1 Pkging Type:		**Shipper Street Name:**	584 CHESTNUT RDG
Cont1 Const Mat:		**Shipper City:**	SPRING VALLEY
Cont1 Head Type:		**Shipper State:**	NY

Cont1 Pkg Capacity:	4	**Shipper Postal:**	10977
C1 Capacity UOM:	LGA	**Shipper Non US St:**	
Cont1 Pkg Amt:		**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	106 8972047272
Cont1 Pkg No:	1	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	1	**Origin City:**	CHESTNUT RIDGE
Cont1 Pkg Mnfctr:	POLYCHEM	**Origin State:**	NEW YORK
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	10977
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:		**Destination City:**	HEALDSBURG
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	
C1 Head Thick UOM:		**Cont2 Const Mat:**	
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	1
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	LGA
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	4
C1 Device Model:		**Cont2 Pkg No Failed:**	1
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:		**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	No	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	NANCY JENKINS
Damage > 500:	No	**Contact Title:**	HAZMAT COORDINATOR
Material Loss:	100	**Contact Business:**	
Carrier Damage:	0	**Contact Street:**	
Property Damage:	0	**Contact City:**	
Response Cost:	0	**Contact State:**	
Remediation Cost:	25	**Contact Postal:**	
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	125	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: PACKAGE WAS UNLOADED WITH LEAKAGE NOTED ON THE BOX. EXAMINATION OF THE INNER CONTAINER REVEALED THAT THE CONTAINER(S) HAD LOOSE CAP(S) AND LEAKED. THE LEAAGE WAS CONTAINED. THE CAP(S) WERE SECURED. CARTON WAS WET BUT OTHERWISE UNDAMAGED. PACKAGE WAS REPACKED FOR RETURN TO THE SHIPPER.

Recommend Actions Taken:

1	7 of 15	NW	0.00 / 0.00	114.25 / -6	**STANDARD STRUCTURES INC** **920 SHILOH** **WINDSOR CA 954920000**	HAZNET

SIC Code:	2439	**Mailing City:**	SANTA ROSA
NAICS Code:	321214	**Mailing State:**	CA
EPA ID:	CAL000160715	**Mailing Zip:**	954020130
Create Date:	10/4/1996	**Region Code:**	2
Fac Act Ind:	No	**Owner Name:**	STANDARD STRUCTURES
Inact Date:	6/30/2011	**Owner Addr 1:**	PO BOX K
County Code:	49	**Owner Addr 2:**	
County Name:	Sonoma	**Owner City:**	SANTA ROSA
Mail Name:		**Owner State:**	CA
Mailing Addr 1:	PO BOX K	**Owner Zip:**	954020130
Mailing Addr 2:		**Owner Phone:**	7078368100
Owner Fax:	7078368199		

Contact Information

--	--
Contact Name:	JOHN ROSENBLAD
Street Address 1:	P O BOX K
Street Address 2:	
City:	SANTA ROSA
State:	CA
Zip:	954020000
Phone:	7078372216
--	--
--	--

Tanner Information

--	--
Generator EPA ID:	CAL000160715
Generator County Code:	49
Generator County:	Sonoma
TSD EPA ID:	CAD059494310
TSD County Code:	43
TSD County:	Santa Clara
State Waste Code:	151
State Waste Code Desc.:	Asbestos containing waste
Method Code:	H01
Method Description:	Transfer station
Tons:	0.1125
Year:	1999
--	--
Generator EPA ID:	CAL000160715
Generator County Code:	49
Generator County:	Sonoma
TSD EPA ID:	CAD980884183
TSD County Code:	34
TSD County:	Sacramento
State Waste Code:	214
State Waste Code Desc.:	Unspecified solvent mixture
Method Code:	D99
Method Description:	Disposal, other
Tons:	0.792
Year:	2001
--	--
Generator EPA ID:	CAL000160715
Generator County Code:	49
Generator County:	Sonoma

TSD EPA ID:	CAD980887418
TSD County Code:	01
TSD County:	Alameda
State Waste Code:	221
State Waste Code Desc.:	Waste oil and mixed oil
Method Code:	H01
Method Description:	Transfer station
Tons:	2.28
Year:	2001
--	--
Generator EPA ID:	CAL000160715
Generator County Code:	49
Generator County:	Sonoma
TSD EPA ID:	CAD980887418
TSD County Code:	01
TSD County:	Alameda
State Waste Code:	221
State Waste Code Desc.:	Waste oil and mixed oil
Method Code:	R01
Method Description:	Recycler
Tons:	2.755
Year:	1999
--	--
Generator EPA ID:	CAL000160715
Generator County Code:	49
Generator County:	Sonoma
TSD EPA ID:	CAD980887418
TSD County Code:	01
TSD County:	Alameda
State Waste Code:	221
State Waste Code Desc.:	Waste oil and mixed oil
Method Code:	R01
Method Description:	Recycler
Tons:	5.282
Year:	2001
--	--
Generator EPA ID:	CAL000160715
Generator County Code:	49
Generator County:	Sonoma
TSD EPA ID:	CAD059494310
TSD County Code:	43
TSD County:	Santa Clara
State Waste Code:	222
State Waste Code Desc.:	Oil/water separation sludge
Method Code:	H01
Method Description:	Transfer station
Tons:	7.506
Year:	2000
--	--
Generator EPA ID:	CAL000160715
Generator County Code:	49
Generator County:	Sonoma
TSD EPA ID:	CAD059494310
TSD County Code:	43
TSD County:	Santa Clara
State Waste Code:	222
State Waste Code Desc.:	Oil/water separation sludge
Method Code:	H01
Method Description:	Transfer station
Tons:	1.0425
Year:	2002
--	--
Generator EPA ID:	CAL000160715
Generator County Code:	49
Generator County:	Sonoma
TSD EPA ID:	CAD059494310
TSD County Code:	43
TSD County:	Santa Clara
State Waste Code:	222

State Waste Code Desc.:	Oil/water separation sludge
Method Code:	H01
Method Description:	Transfer station
Tons:	1.23015
Year:	2003
--	--
Generator EPA ID:	CAL000160715
Generator County Code:	49
Generator County:	Sonoma
TSD EPA ID:	CAT000613943
TSD County Code:	49
TSD County:	Sonoma
State Waste Code:	222
State Waste Code Desc.:	Oil/water separation sludge
Method Code:	R01
Method Description:	Recycler
Tons:	0.417
Year:	2002
--	--
Generator EPA ID:	CAL000160715
Generator County Code:	49
Generator County:	Sonoma
TSD EPA ID:	CAD980887418
TSD County Code:	01
TSD County:	Alameda
State Waste Code:	223
State Waste Code Desc.:	Unspecified oil-containing waste
Method Code:	H141
Method Description:	STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/REOVERY (H010-H129) OR (H131-H135)
Tons:	5.0874
Year:	2007
--	--
Generator EPA ID:	CAL000160715
Generator County Code:	49
Generator County:	Sonoma
TSD EPA ID:	NVD980895338
TSD County Code:	99
TSD County:	Unknown
State Waste Code:	223
State Waste Code Desc.:	Unspecified oil-containing waste
Method Code:	H141
Method Description:	STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/REOVERY (H010-H129) OR (H131-H135)
Tons:	0.6
Year:	2007
--	--
Generator EPA ID:	CAL000160715
Generator County Code:	49
Generator County:	Sonoma
TSD EPA ID:	CAD059494310
TSD County Code:	43
TSD County:	Santa Clara
State Waste Code:	223
State Waste Code Desc.:	Unspecified oil-containing waste
Method Code:	H01
Method Description:	Transfer station
Tons:	0.25
Year:	1999
--	--
Generator EPA ID:	CAL000160715
Generator County Code:	49
Generator County:	Sonoma
TSD EPA ID:	CAD982411993
TSD County Code:	01
TSD County:	Alameda
State Waste Code:	261
State Waste Code Desc.:	Polychlorinated biphenyls and material containing PCBs
Method Code:	H141

Method Description:	STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/REOVERY (H010-H129) OR (H131-H135)
Tons:	0.12232
Year:	2008
--	--
Generator EPA ID:	CAL000160715
Generator County Code:	49
Generator County:	Sonoma
TSD EPA ID:	AZ0000337360
TSD County Code:	99
TSD County:	Unknown
State Waste Code:	261
State Waste Code Desc.:	Polychlorinated biphenyls and material containing PCBs
Method Code:	H01
Method Description:	Transfer station
Tons:	0.3857
Year:	2004
--	--
Generator EPA ID:	CAL000160715
Generator County Code:	49
Generator County:	Sonoma
TSD EPA ID:	CAD059494310
TSD County Code:	43
TSD County:	Santa Clara
State Waste Code:	272
State Waste Code Desc.:	Polymeric resin waste
Method Code:	H01
Method Description:	Transfer station
Tons:	4.1908
Year:	1999
--	--
Generator EPA ID:	CAL000160715
Generator County Code:	49
Generator County:	Sonoma
TSD EPA ID:	CAD059494310
TSD County Code:	43
TSD County:	Santa Clara
State Waste Code:	272
State Waste Code Desc.:	Polymeric resin waste
Method Code:	H01
Method Description:	Transfer station
Tons:	17.0136
Year:	2000
--	--
Generator EPA ID:	CAL000160715
Generator County Code:	49
Generator County:	Sonoma
TSD EPA ID:	CAD980675276
TSD County Code:	15
TSD County:	Kern
State Waste Code:	272
State Waste Code Desc.:	Polymeric resin waste
Method Code:	T01
Method Description:	Treatment, tank
Tons:	13.761
Year:	1999
--	--
Generator EPA ID:	CAL000160715
Generator County Code:	49
Generator County:	Sonoma
TSD EPA ID:	CAD980884183
TSD County Code:	34
TSD County:	Sacramento
State Waste Code:	291
State Waste Code Desc.:	Latex waste
Method Code:	H141
Method Description:	STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/REOVERY (H010-H129) OR (H131-H135)
Tons:	1.02165

Year:	2007
--	--
Generator EPA ID:	CAL000160715
Generator County Code:	49
Generator County:	Sonoma
TSD EPA ID:	CAD980884183
TSD County Code:	34
TSD County:	Sacramento
State Waste Code:	343
State Waste Code Desc.:	Unspecified organic liquid mixture
Method Code:	H061
Method Description:	FUEL BLENDING PRIOR TO ENERGY RECOVERY AT ANOTHER SITE
Tons:	1.3515
Year:	2007
--	--
Generator EPA ID:	CAL000160715
Generator County Code:	49
Generator County:	Sonoma
TSD EPA ID:	CAT000646117
TSD County Code:	16
TSD County:	Kings
State Waste Code:	343
State Waste Code Desc.:	Unspecified organic liquid mixture
Method Code:	T01
Method Description:	Treatment, tank
Tons:	10.2
Year:	1999
--	--
Generator EPA ID:	CAL000160715
Generator County Code:	49
Generator County:	Sonoma
TSD EPA ID:	CAT080033681
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	352
State Waste Code Desc.:	Other organic solids
Method Code:	D80
Method Description:	Disposal, landfill
Tons:	0.4
Year:	2004
--	--
Generator EPA ID:	CAL000160715
Generator County Code:	49
Generator County:	Sonoma
TSD EPA ID:	CAD044429835
TSD County Code:	19
TSD County:	Los Angeles
State Waste Code:	352
State Waste Code Desc.:	Other organic solids
Method Code:	D99
Method Description:	Disposal, other
Tons:	2.4
Year:	2002
--	--
Generator EPA ID:	CAL000160715
Generator County Code:	49
Generator County:	Sonoma
TSD EPA ID:	CAD980884183
TSD County Code:	34
TSD County:	Sacramento
State Waste Code:	352
State Waste Code Desc.:	Other organic solids
Method Code:	H01
Method Description:	Transfer station
Tons:	0.5
Year:	2005
--	--
Generator EPA ID:	CAL000160715
Generator County Code:	49

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Generator County:	Sonoma
TSD EPA ID:	CAD980884183
TSD County Code:	34
TSD County:	Sacramento
State Waste Code:	551
State Waste Code Desc.:	Laboratory waste chemicals
Method Code:	H141
Method Description:	STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/REOVERY (H010-H129) OR (H131-H135)
Tons:	0.0905
Year:	2007
--	--
Generator EPA ID:	CAL000160715
Generator County Code:	49
Generator County:	Sonoma
TSD EPA ID:	CAD980884183
TSD County Code:	34
TSD County:	Sacramento
State Waste Code:	551
State Waste Code Desc.:	Laboratory waste chemicals
Method Code:	H01
Method Description:	Transfer station
Tons:	0.2525
Year:	2005
--	--
Generator EPA ID:	CAL000160715
Generator County Code:	49
Generator County:	Sonoma
TSD EPA ID:	CAT000613943
TSD County Code:	49
TSD County:	Sonoma
State Waste Code:	741
State Waste Code Desc.:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Code:	H01
Method Description:	Transfer station
Tons:	0.2375
Year:	2000
--	--
Generator EPA ID:	CAL000160715
Generator County Code:	49
Generator County:	Sonoma
TSD EPA ID:	CAT000613943
TSD County Code:	49
TSD County:	Sonoma
State Waste Code:	741
State Waste Code Desc.:	Liquids with halogenated organic compounds >= 1,000 Mg./L
Method Code:	H01
Method Description:	Transfer station
Tons:	0.7002
Year:	2001
--	--
Generator EPA ID:	CAL000160715
Generator County Code:	49
Generator County:	Sonoma
TSD EPA ID:	NVD980895338
TSD County Code:	99
TSD County:	Unknown
State Waste Code:	
State Waste Code Desc.:	
Method Code:	H141
Method Description:	STORAGE, BULKING, AND/OR TRANSFER OFF SITE--NO TREATMENT/REOVERY (H010-H129) OR (H131-H135)
Tons:	
Year:	2007
--	--

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	8 of 15	NW	0.00 / 0.00	114.25 / -6	FED EX GROUND 920 SHILOH RD UNIT 350	HAZNET

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					WINDSOR CA 95492	

SIC Code:		**Mailing City:**	WINDSOR
NAICS Code:		**Mailing State:**	CA
EPA ID:	CAC002552359	**Mailing Zip:**	95492
Create Date:	5/24/2002	**Region Code:**	2
Fac Act Ind:	No	**Owner Name:**	FEDERAL EXPRESS CORP
Inact Date:	3/18/2003	**Owner Addr 1:**	920 SHILOH RD UNIT 350
County Code:	49	**Owner Addr 2:**	
County Name:	Sonoma	**Owner City:**	WINDSOR
Mail Name:		**Owner State:**	CA
Mailing Addr 1:	920 SHILOH RD UNIT 350	**Owner Zip:**	95492
Mailing Addr 2:		**Owner Phone:**	
Owner Fax:			

Contact Information

--	--
Contact Name:	MIKE O'HARE/SVC MGR
Street Address 1:	920 SHILOH RD UNIT 350
Street Address 2:	
City:	WINDSOR
State:	CA
Zip:	95492
Phone:	7078378023
--	--
--	--

Tanner Information

--	--
Generator EPA ID:	CAC002552359
Generator County Code:	49
Generator County:	Sonoma
TSD EPA ID:	CAT080014079
TSD County Code:	07
TSD County:	Contra Costa
State Waste Code:	611
State Waste Code Desc.:	Contaminated soil from site clean-up
Method Code:	H01
Method Description:	Transfer station
Tons:	0.15
Year:	2002
--	--

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	9 of 15	NW	0.00 / 0.00	114.25 / -6	Standard Structures, Inc. 920 SHILOH RD WINDSOR CA 95492	DELISTED HAZ

Siteid:	383060
Latitude:	38.525763
Longitude:	-122.792960
Original Source:	CHAZ
Record Date:	30-MAY-2017

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	10 of 15	NW	0.00 / 0.00	114.25 / -6	STANDARD STRUCTURES INC 920 SHILOH ROAD WINDSOR CA 95492	EMISSIONS

1990 Criteria Data

Facility ID:	4982	**CERR Code:**	
Facility SIC Code:	1541	**TOGT:**	2.9
CO:	49	**ROGT:**	1.27165
Air Basin:	SF	**COT:**	36.8
District:	BA	**NOXT:**	2.6

COID:	SON	**SOXT:**	5.6
DISN:	BAY AREA AQMD	**PMT:**	13.9
CHAPIS:		**PM10T:**	13.2613

1990 Toxic Data

Facility ID:	4982	**COID:**	SON
Facility SIC Code:	1541	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

1993 Criteria Data

Facility ID:	4982	**CERR Code:**	
Facility SIC Code:	2439	**TOGT:**	4.3
CO:	49	**ROGT:**	2.48378
Air Basin:	SF	**COT:**	24.4
District:	BA	**NOXT:**	1.8
COID:	SON	**SOXT:**	3.7
DISN:	BAY AREA AQMD	**PMT:**	8.6
CHAPIS:		**PM10T:**	8.5742

1993 Toxic Data

Facility ID:	4982	**COID:**	SON
Facility SIC Code:	2439	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

1995 Criteria Data

Facility ID:	4982	**CERR Code:**	
Facility SIC Code:	1541	**TOGT:**	10.2
CO:	49	**ROGT:**	5.46108
Air Basin:	SF	**COT:**	35.8
District:	BA	**NOXT:**	2.6
COID:	SON	**SOXT:**	5.4
DISN:	BAY AREA AQMD	**PMT:**	13.6
CHAPIS:		**PM10T:**	12.9622

1995 Toxic Data

Facility ID:	4982	**COID:**	SON
Facility SIC Code:	1541	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

1996 Criteria Data

Facility ID:	4982	***CERR Code:***	
Facility SIC Code:	1541	***TOGT:***	9.5
CO:	49	***ROGT:***	5.20615
Air Basin:	SF	***COT:***	30.6
District:	BA	***NOXT:***	2.2
COID:	SON	***SOXT:***	4.7
DISN:	BAY AREA AQMD	***PMT:***	11.7
CHAPIS:		***PM10T:***	11.1276

1996 Toxic Data

Facility ID:	4982	***COID:***	SON
Facility SIC Code:	1541	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

1997 Criteria Data

Facility ID:	4982	***CERR Code:***	
Facility SIC Code:	1541	***TOGT:***	9.5
CO:	49	***ROGT:***	5.20615
Air Basin:	SF	***COT:***	30.6
District:	BA	***NOXT:***	2.2
COID:	SON	***SOXT:***	4.7
DISN:	BAY AREA AQMD	***PMT:***	11.7
CHAPIS:		***PM10T:***	11.1276

1997 Toxic Data

Facility ID:	4982	***COID:***	SON
Facility SIC Code:	1541	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

1998 Criteria Data

Facility ID:	4982	***CERR Code:***	
Facility SIC Code:	1541	***TOGT:***	10.9
CO:	49	***ROGT:***	6.4703
Air Basin:	SF	***COT:***	24.3
District:	BA	***NOXT:***	1.7
COID:	SON	***SOXT:***	3.7
DISN:	BAY AREA AQMD	***PMT:***	1.2
CHAPIS:		***PM10T:***	.8382

1998 Toxic Data

Facility ID:	4982	***COID:***	SON
Facility SIC Code:	1541	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	

District: BA
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

1999 Criteria Data

Facility ID:	4982	***CERR Code:***	
Facility SIC Code:	2439	***TOGT:***	10.865
CO:	49	***ROGT:***	8.2886545
Air Basin:	SF	***COT:***	23.49
District:	BA	***NOXT:***	1.691
COID:	SON	***SOXT:***	3.57
DISN:	BAY AREA AQMD	***PMT:***	1.224
CHAPIS:		***PM10T:***	.835263

1999 Toxic Data

Facility ID:	4982	***COID:***	SON
Facility SIC Code:	2439	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2000 Criteria Data

Facility ID:	4982	***CERR Code:***	
Facility SIC Code:	2439	***TOGT:***	10.865
CO:	49	***ROGT:***	8.3
Air Basin:	SF	***COT:***	23.49
District:	BA	***NOXT:***	1.691
COID:	SON	***SOXT:***	3.57
DISN:	BAY AREA AQMD	***PMT:***	1.224
CHAPIS:		***PM10T:***	.84

2000 Toxic Data

Facility ID:	4982	***COID:***	SON
Facility SIC Code:	2439	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2001 Criteria Data

Facility ID:	4982	***CERR Code:***	
Facility SIC Code:	2439	***TOGT:***	4.57
CO:	49	***ROGT:***	2.47
Air Basin:	SF	***COT:***	20.63
District:	BA	***NOXT:***	1.49
COID:	SON	***SOXT:***	3.14
DISN:	BAY AREA AQMD	***PMT:***	1.16
CHAPIS:	Y	***PM10T:***	.77

2001 Toxic Data

Facility ID:	4982	***COID:***	SON
Facility SIC Code:	2439	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	Y
Air Basin:	SF	***CERR Code:***	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2002 Criteria Data

Facility ID:	4982	***CERR Code:***	
Facility SIC Code:	1541	***TOGT:***	4.077
CO:	49	***ROGT:***	2.2378395
Air Basin:	SF	***COT:***	18.006
District:	BA	***NOXT:***	1.296
COID:	SON	***SOXT:***	2.737
DISN:	BAY AREA AQMD	***PMT:***	.444
CHAPIS:	Y	***PM10T:***	.442668

2002 Toxic Data

Facility ID:	4982	***COID:***	SON
Facility SIC Code:	1541	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	Y
Air Basin:	SF	***CERR Code:***	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2003 Criteria Data

Facility ID:	4982	***CERR Code:***	
Facility SIC Code:	1541	***TOGT:***	.921
CO:	49	***ROGT:***	.85
Air Basin:	SF	***COT:***	14.694
District:	BA	***NOXT:***	1.058
COID:	SON	***SOXT:***	2.233
DISN:	BAY AREA AQMD	***PMT:***	5.036
CHAPIS:	Y	***PM10T:***	3.09

2003 Toxic Data

Facility ID:	4982	***COID:***	SON
Facility SIC Code:	1541	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	Y
Air Basin:	SF	***CERR Code:***	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2004 Criteria Data

Facility ID:	4982	***CERR Code:***	
Facility SIC Code:	1541	***TOGT:***	1.222

CO:	49	**ROGT:**	.985922
Air Basin:	SF	**COT:**	77.438
District:	BA	**NOXT:**	5.576
COID:	SON	**SOXT:**	11.771
DISN:	BAY AREA AQMD	**PMT:**	12.766
CHAPIS:	Y	**PM10T:**	10.80178

2004 Toxic Data

Facility ID:	4982	**COID:**	SON
Facility SIC Code:	1541	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	Y
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2005 Criteria Data

Facility ID:	4982	**CERR Code:**	
Facility SIC Code:	1541	**TOGT:**	.856
CO:	49	**ROGT:**	.825431
Air Basin:	SF	**COT:**	1.163
District:	BA	**NOXT:**	.084
COID:	SON	**SOXT:**	.177
DISN:	BAY AREA AQMD	**PMT:**	3.369
CHAPIS:		**PM10T:**	1.432971

2005 Toxic Data

Facility ID:	4982	**COID:**	SON
Facility SIC Code:	1541	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2006 Criteria Data

Facility ID:	4982	**CERR Code:**	
Facility SIC Code:	1541	**TOGT:**	6.543
CO:	49	**ROGT:**	6.330447
Air Basin:	SF	**COT:**	1.236
District:	BA	**NOXT:**	.089
COID:	SON	**SOXT:**	18.791
DISN:	BAY AREA AQMD	**PMT:**	3.378
CHAPIS:	Y	**PM10T:**	1.441944

2006 Toxic Data

Facility ID:	4982	**COID:**	SON
Facility SIC Code:	1541	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	Y
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			

Non-Cancer Acute Haz Ind:

2007 Criteria Data

Facility ID:	4982	***CERR Code:***	
Facility SIC Code:	1541	***TOGT:***	20.974
CO:	49	***ROGT:***	20.299655
Air Basin:	SF	***COT:***	1.16
District:	BA	***NOXT:***	.084
COID:	SON	***SOXT:***	17.63
DISN:	BAY AREA AQMD	***PMT:***	3.369
CHAPIS:		***PM10T:***	1.432971

2007 Toxic Data

Facility ID:	4982	***COID:***	SON
Facility SIC Code:	1541	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2008 Criteria Data

Facility ID:	4982	***CERR Code:***	
Facility SIC Code:	1541	***TOGT:***	.282
CO:	49	***ROGT:***	.2483671
Air Basin:	SF	***COT:***	.361
District:	BA	***NOXT:***	.112
COID:	SON	***SOXT:***	13.718
DISN:	BAY AREA AQMD	***PMT:***	3.314
CHAPIS:		***PM10T:***	1.378136

2008 Toxic Data

Facility ID:	4982	***COID:***	SON
Facility SIC Code:	1541	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2009 Criteria Data

Facility ID:	4982	***CERR Code:***	
Facility SIC Code:	1541	***TOGT:***	.286
CO:	49	***ROGT:***	.2501211
Air Basin:	SF	***COT:***	.464
District:	BA	***NOXT:***	.143
COID:	SON	***SOXT:***	17.623
DISN:	BAY AREA AQMD	***PMT:***	3.340343029087261785356068204613841524 57
CHAPIS:		***PM10T:***	1.4044

2009 Toxic Data

Facility ID:	4982	**COID:**	SON
Facility SIC Code:	1541	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2010 Toxic Data

Facility ID:	4982	**COID:**	SON
Facility SIC Code:	1541	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2011 Criteria Data

Facility ID:	4982	**CERR Code:**	
Facility SIC Code:	1541	**TOGT:**	27.938
CO:	49	**ROGT:**	26.8138369
Air Basin:	SF	**COT:**	9.51
District:	BA	**NOXT:**	2.938
COID:	SON	**SOXT:**	1.807
DISN:	BAY AREA AQMD	**PMT:**	10.4020110330992978936810431293881644 9348
CHAPIS:		**PM10T:**	5.556

2011 Toxic Data

Facility ID:	4982	**COID:**	SON
Facility SIC Code:	1541	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2012 Criteria Data

Facility ID:	4982	**CERR Code:**	
Facility SIC Code:	1541	**TOGT:**	27.938
CO:	49	**ROGT:**	26.8138369
Air Basin:	SF	**COT:**	9.51
District:	BA	**NOXT:**	2.938
COID:	SON	**SOXT:**	1.807
DISN:	BAY AREA AQMD	**PMT:**	10.4020110330992978936810431293881644 9348
CHAPIS:		**PM10T:**	5.556

2012 Toxic Data

Facility ID:	4982	**COID:**	SON
Facility SIC Code:	1541	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	11 of 15	NW	0.00 / 0.00	114.25 / -6	920 SHILOH RD SANTA ROSA CA	HMIRS

Air Basin: SF
District: BA
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
CERR Code:

Incident County: SONOMA

HMIR Incident Reports

Report No:	I-1996030657	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	1996-02-15	**Report Submit Src:**	Paper
Time of Incident:	0700	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	8	**Mode Transport:**	Highway
Commodity Short Nm:	CORROSIVE LIQUIDS, N.O.S.	**Transport Phase:**	Unloading
Commodity Long Nm:	CORROSIVE LIQUIDS, N.O.S.	**Incident Occrrnce:**	
Trade Name:	PHOSPHORIC ACID ZINC	**Mat Ship Approval?:**	No
ID No:	UN1760	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	
TIH Hazard Zone:		**Carrier Reporter:**	ROADWAY PACKAGE SYSTEM INC
Qty Released:	0.0625	**CR Street Name:**	P O BOX 108
Unit of Measure:	Liquid - Gallon	**CR City:**	PITTSBURGH
What Failed:	103;	**CR State:**	PA
What Failed Desc:	Basic Material;	**CR Postal Code:**	15230
How Failed Code:	309;	**CR Non US State:**	
How Failed Desc:	Punctured;	**CR Fed DOT ID:**	265752
Failure Cause Code:	511; 516	**CR Hazmat Reg ID:**	
Failure Cause Desc:	Dropped; Impact with Sharp or Protruding Object (e.g., nails)	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	NALCO CHEMICAL CO
Cont1 Pkging Type:		**Shipper Street Name:**	7701 HWY 90 A
Cont1 Const Mat:		**Shipper City:**	SUGAR LAND
Cont1 Head Type:		**Shipper State:**	TX
Cont1 Pkg Capacity:	5	**Shipper Postal:**	77478
C1 Capacity UOM:	LGA	**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	7757755450018135
Cont1 Pkg No:	1	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	1	**Origin City:**	
Cont1 Pkg Mnfctr:	NAMPAC-PA	**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	US
C1 Test Const Mat:		**Destination City:**	PETALUMA
C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	94952
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	
C1 Head Thick UOM:		**Cont2 Const Mat:**	
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	0
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	0
C1 Device Model:		**Cont2 Pkg No Failed:**	0
NRC No:			
RAM Pkg Category:		**Haz NonHosp Public:**	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	No	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	NANCY JENKINS
Damage > 500:	No	**Contact Title:**	HAZMAT COORDINATOR
Material Loss:	100	**Contact Business:**	
Carrier Damage:	0	**Contact Street:**	
Property Damage:	0	**Contact City:**	
Response Cost:	0	**Contact State:**	
Remediation Cost:	25	**Contact Postal:**	
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	125	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	DRUM NON-METAL
Haz Hosp Old Form:	0	**HMIS Container Code:**	1H1
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Non-removable head plastic drum
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: PAIL WAS DROPPED AT UNLOAD. EXAMINATION REVEALED A SMALL PUNCTURE WHICH ALLOWED THE CONTENTS TO ESCAPE. THE LEAKAGE WAS CONTAINED. PAIL WAS REPACKED FOR RETURN TO THE SHIPPER.

Recommend Actions Taken:

1	*12 of 15*	*NW*	*0.00 / 0.00*	*114.25 / -6*	*920 SHILO RD WINDSOR CA*	*HMIRS*

Incident County: SONOMA

HMIR Incident Reports

Report No:	I-1996080792	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	1996-07-24	**Report Submit Src:**	Paper
Time of Incident:	0730	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	3	**Mode Transport:**	Highway
Commodity Short Nm:	HEXANES	**Transport Phase:**	Unloading
Commodity Long Nm:	HEXANES	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

ID No:	UN1208	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	
TIH Hazard Zone:		**Carrier Reporter:**	ROADWAY PACKAGE SYSTEM INC
Qty Released:	1	**CR Street Name:**	P O BOX 108
Unit of Measure:	Liquid - Gallon	**CR City:**	PITTSBURGH
What Failed:	109; 103	**CR State:**	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug); Basic Material	**CR Postal Code:**	152300108
How Failed Code:	;	**CR Non US State:**	
How Failed Desc:	;	**CR Fed DOT ID:**	265752
Failure Cause Code:	526; 538	**CR Hazmat Reg ID:**	
Failure Cause Desc:	Loose Closure, Component, or Device; Water Damage	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	BECKLEY CARDY CO
Cont1 Pkging Type:		**Shipper Street Name:**	100 PARAGON PKWY
Cont1 Const Mat:		**Shipper City:**	MANSFIELD
Cont1 Head Type:		**Shipper State:**	OH
Cont1 Pkg Capacity:	1	**Shipper Postal:**	44903
C1 Capacity UOM:	LGA	**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	4491724455242
Cont1 Pkg No:	1	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	1	**Origin City:**	
Cont1 Pkg Mnfctr:	COLUMBUS CHEMICAL	**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	US
C1 Test Const Mat:		**Destination City:**	SEBASTOPOL
C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95472
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	
C1 Head Thick UOM:		**Cont2 Const Mat:**	
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	1
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	LGA
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	1
C1 Device Model:		**Cont2 Pkg No Failed:**	1
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	No	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	NANCY JENKINS
Damage > 500:	No	**Contact Title:**	HAZMAT COORDINATOR

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Material Loss:	100	**Contact Business:**	
Carrier Damage:	0	**Contact Street:**	
Property Damage:	0	**Contact City:**	
Response Cost:	0	**Contact State:**	
Remediation Cost:	25	**Contact Postal:**	
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	125	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	BOX FIBER
Haz Hosp Old Form:	0	**HMIS Container Code:**	4G
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: PACKAGE WAS UNLOADED WITH LEAKAGE NOTED ON THE BOX. EXAMINATION OF THE INNER CONTAINER REVEALED THAT THE CONTAINER(S) HAD LOOSE CAP(S) AND LEAKED. THE LEAKAGE WAS CONTAINED. THE CAP(S) WERE SECURED. CARTON WAS WET BUT OTHERWISE UNDAMAGED. PACKAGE WAS REPACKED FOR RETURN TO THE SHIPPER.

Recommend Actions Taken:

1	13 of 15	NW	0.00 / 0.00	114.25 / -6	920 SHILOH ROAD STE 350 WINDSOR CA	HMIRS

Incident County: SONOMA

HMIR Incident Reports

Report No:	I-1998031278	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	1998-03-12	**Report Submit Src:**	Paper
Time of Incident:	1100	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	8	**Mode Transport:**	Highway
Commodity Short Nm:	CORROSIVE LIQUIDS, N.O.S.	**Transport Phase:**	Unloading
Commodity Long Nm:	CORROSIVE LIQUIDS, N.O.S.	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1760	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	
TIH Hazard Zone:		**Carrier Reporter:**	ROADWAY PACKAGE SYSTEM INC
Qty Released:	0.03125	**CR Street Name:**	P O BOX 108
Unit of Measure:	Liquid - Gallon	**CR City:**	PITTSBURGH
What Failed:	109; 103	**CR State:**	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug); Basic Material	**CR Postal Code:**	152300108
How Failed Code:	;	**CR Non US State:**	
How Failed Desc:	;	**CR Fed DOT ID:**	265752
Failure Cause Code:	526; 538	**CR Hazmat Reg ID:**	
Failure Cause Desc:	Loose Closure, Component, or Device; Water Damage	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	P I P C
Cont1 Pkging Type:		**Shipper Street Name:**	584 CHESTNUT RIDGE
Cont1 Const Mat:		**Shipper City:**	CHESTNUT RIDGE
Cont1 Head Type:		**Shipper State:**	NY
Cont1 Pkg Capacity:	4	**Shipper Postal:**	10977
C1 Capacity UOM:	LGA	**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	106 8972047272

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Cont1 Pkg No:	1	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	1	**Origin City:**	
Cont1 Pkg Mnfctr:	POLYCHEM	**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	US
C1 Test Const Mat:		**Destination City:**	HEALDSBURG
C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	
C1 Head Thick UOM:		**Cont2 Const Mat:**	
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	1
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	LGA
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	4
C1 Device Model:		**Cont2 Pkg No Failed:**	1
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	No	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	NANCY JENKINS
Damage > 500:	No	**Contact Title:**	HAZMAT COORDINATOR
Material Loss:	100	**Contact Business:**	
Carrier Damage:	0	**Contact Street:**	
Property Damage:	0	**Contact City:**	
Response Cost:	0	**Contact State:**	
Remediation Cost:	25	**Contact Postal:**	
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	125	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	BOX FIBER
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: PACKAGE WAS UNLOADED WITH LEAKAGE NOTED ON THE BOX. EXAMINATION OF THE INNER

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

CONTAINER REVEALED THAT THE CONTAINER(S) HAD LOOSE CAP(S) AND LEAKED. THE LEAAGE WAS CONTAINED. THE CAP(S) WERE SECURED. CARTON WAS WET BUT OTHERWISE UNDAMAGED. PACKAGE WAS REPACKED FOR RETURN TO THE SHIPPER.

Recommend Actions Taken:

1	14 of 15	NW	0.00 / 0.00	114.25 / -6	920 SHILOH ROAD WINDSOR CA	HMIRS

Incident County: SONOMA

HMIR Incident Reports

Report No:	I-1999090829	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	1999-08-20	***Report Submit Src:***	Paper
Time of Incident:	0800	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	8	***Mode Transport:***	Highway
Commodity Short Nm:	CORROSIVE LIQUIDS, N.O.S.	***Transport Phase:***	Unloading
Commodity Long Nm:	CORROSIVE LIQUIDS, N.O.S.	***Incident Occrrnce:***	
Trade Name:	POTASSIUM HYDROXIDE	***Mat Ship Approval?:***	No
ID No:	UN1760	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	ROADWAY PACKAGE SYSTEM INC
Qty Released:	0.132086	***CR Street Name:***	P O BOX 108
Unit of Measure:	Liquid - Gallon	***CR City:***	PITTSBURGH
What Failed:	109; 103	***CR State:***	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug); Basic Material	***CR Postal Code:***	15230
How Failed Code:	303; 310	***CR Non US State:***	
How Failed Desc:	Burst or Ruptured; Ripped or Torn	***CR Fed DOT ID:***	265752
Failure Cause Code:	511; 511	***CR Hazmat Reg ID:***	
Failure Cause Desc:	Dropped; Dropped	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	FUJI FILM PHOTO
Cont1 Pkging Type:		***Shipper Street Name:***	300 BALDWIN PARK BLVD
Cont1 Const Mat:		***Shipper City:***	CITY OF INDUSTRY
Cont1 Head Type:		***Shipper State:***	CA
Cont1 Pkg Capacity:	0.528344	***Shipper Postal:***	91746
C1 Capacity UOM:	LGA	***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	024949500014530
Cont1 Pkg No:	1	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	1	***Origin City:***	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:		***Destination City:***	SANTA ROSA
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	95401
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0.132086
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	LGA
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	4
C1 Device Model:		***Cont2 Pkg No Failed:***	1
NRC No:			
RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	

RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	No	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	SCOTT KERR
Damage > 500:	No	**Contact Title:**	HAZMAT ADMINISTRATOR
Material Loss:	100	**Contact Business:**	
Carrier Damage:	0	**Contact Street:**	
Property Damage:	0	**Contact City:**	
Response Cost:	0	**Contact State:**	
Remediation Cost:	25	**Contact Postal:**	
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	125	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	BOX FIBER
Haz Hosp Old Form:	0	**HMIS Container Code:**	4G
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: THE PACKAGE WAS DROPPED IN HANDLING. EXAMINATION OF THE INNER CONTAINER REVEALED A RUPTURED SEAM WHICH ALLOWED THE CONTENTS TO ESCAPE. THE LEAKAGE WAS CONTAINED. THE PACKAGE WAS REPACKED FOR RETURN TO SHIPPER.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	I-2005020768	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2005-01-13	**Report Submit Src:**	Paper
Time of Incident:	2038	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	3	**Mode Transport:**	Highway
Commodity Short Nm:	ETHYL ALCOHOL	**Transport Phase:**	Unloading
Commodity Long Nm:	ETHYL ALCOHOL	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1170	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM IN
Qty Released:	0.007813	**CR Street Name:**	1000 FEDEX DRIVE
Unit of Measure:	Liquid - Gallon	**CR City:**	MOON TOWNSHIP
What Failed:	109	**CR State:**	PA

What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	**CR Postal Code:**	15108
How Failed Code:		**CR Non US State:**	
How Failed Desc:		**CR Fed DOT ID:**	265752
Failure Cause Code:		**CR Hazmat Reg ID:**	062904001002M
Failure Cause Desc:		**CR Country:**	US
Ident. Markings:	4G/Y20/5/04,USA/M5431	**Shipper Name:**	AAPER ALCOHOL & CHEMICAL
Cont1 Pkging Type:	Box	**Shipper Street Name:**	1101 ISAAC SHELBY ROAD
Cont1 Const Mat:	Fiberboard	**Shipper City:**	SHELBYVILLE
Cont1 Head Type:		**Shipper State:**	KY
Cont1 Pkg Capacity:	5	**Shipper Postal:**	40065
C1 Capacity UOM:	LGA	**Shipper Non US St:**	
Cont1 Pkg Amt:	5	**Shipper Country:**	US
C1 Pkg Amt UOM:	LGA	**Shipper Waybill:**	040250130056684
Cont1 Pkg No:	1	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	1	**Origin City:**	
Cont1 Pkg Mnfctr:		**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	US
C1 Test Const Mat:	Fiberboard	**Destination City:**	HEALDSBURG
C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95448
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	Bag
C1 Head Thick UOM:		**Cont2 Const Mat:**	Plastic
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	5
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	LGA
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	5
C1 Device Type:		**Cont2 Pkg Amt UOM:**	LGA
C1 Device Mnfctr:		**Cont2 Pkg No:**	1
C1 Device Model:		**Cont2 Pkg No Failed:**	1
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	DENISE HANCHULAK
Damage > 500:	No	**Contact Title:**	TSM MANAGER II - SAFETY
Material Loss:	0	**Contact Business:**	Fedex Ground Package System, Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No

Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	BOX FIBER
Haz Hosp Old Form:	0	**HMIS Container Code:**	4G
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: THE PACKAGE WAS DROPPED IN HANDLING. EXAMINATION OF THE INNER CONTAINER REVEALED A RUPTURED SEAM WHICH ALLOWED THE CONTENTS TO ESCAPE. THE LEAKAGE WAS CONTAINED. THE UNDAMAGED PORTION OF THE PACKAGE WAS REPACKED FOR RETURN TO SHIPPER.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	I-2005080037	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2005-05-24	**Report Submit Src:**	Paper
Time of Incident:	0500	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	3	**Mode Transport:**	Highway
Commodity Short Nm:	PAINT INCLUDING PAINT, L	**Transport Phase:**	Unloading
Commodity Long Nm:	PAINT INCLUDING PAINT, LACQUER, ENAMEL, STAIN, SHELLAC SOLUTIONS, VARNISH, POLISH, LIQUID FILLER AND LIQUID LACQUER BASE	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1263	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM IN
Qty Released:	0.5	**CR Street Name:**	1000 FEDEX DRIVE
Unit of Measure:	Liquid - Gallon	**CR City:**	MOON TOWNSHIP
What Failed:	110; 110	**CR State:**	PA
What Failed Desc:	Cover; Cover	**CR Postal Code:**	15108
How Failed Code:	308; 308	**CR Non US State:**	
How Failed Desc:	Leaked; Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	526; 517	**CR Hazmat Reg ID:**	062904001002M
Failure Cause Desc:	Loose Closure, Component, or Device; Improper Preparation for Transportation	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	EI DUPONT
Cont1 Pkging Type:	Box	**Shipper Street Name:**	11535 PRODUCTION DR
Cont1 Const Mat:	Fiberboard	**Shipper City:**	RENO
Cont1 Head Type:		**Shipper State:**	NV
Cont1 Pkg Capacity:	4	**Shipper Postal:**	89506
C1 Capacity UOM:	LGA	**Shipper Non US St:**	
Cont1 Pkg Amt:	4	**Shipper Country:**	US
C1 Pkg Amt UOM:	LGA	**Shipper Waybill:**	025525930055160
Cont1 Pkg No:	1	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	1	**Origin City:**	
Cont1 Pkg Mnfctr:		**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	US
C1 Test Const Mat:	Fiberboard	**Destination City:**	LAKEPORT
C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95453
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	Can
C1 Head Thick UOM:		**Cont2 Const Mat:**	Metal (any type)
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	2
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	LGA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	2
C1 Device Type:		**Cont2 Pkg Amt UOM:**	LGA
C1 Device Mnfctr:		**Cont2 Pkg No:**	2
C1 Device Model:		**Cont2 Pkg No Failed:**	2
NRC No:			
RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	DENISE HANCHULAK
Damage > 500:	No	**Contact Title:**	TSM MANAGER II - SAFETY
Material Loss:	0	**Contact Business:**	Fedex Ground Package System, Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	BOX FIBER
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: THE PAIL WAS UNLOADED WITH LEAKAGE NOTED. EXAMINATION OF THE PAIL REVELAED THE PAIL HAD A LOOSE CAP/LID AND LEAKED. THE LEAKAGE WAS CONTAINED. THE CAP/LID WAS SECURED. UNDAMAGED PRODUCT WAS RETURNED TO THE SHIPPER. THE DAMAGED PRODUCT WAS PROPERLY DISPOSED OF IN A CCORDANCE WITH FEDERAL REGULATIONS.

Recommend Actions Taken:

1	15 of 15	NW	0.00 / 0.00	114.25 / -6	920 SHILOH RD #350 WINDSOR CA	HMIRS

Incident County: SONOMA

HMIR Incident Reports

Report No:	I-2002060588	**Fed DOT Agency Nm:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2002-05-23	**Report Submit Src:**	Paper
Time of Incident:	0730	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	8	**Mode Transport:**	Highway
Commodity Short Nm:	NITRIC ACID OTHER THAN R	**Transport Phase:**	Loading
Commodity Long Nm:	NITRIC ACID OTHER THAN RED FUMING, WITH AT LEAST 65 PERCENT, BUT NOT MORE THAN 70 PERCENT NITRIC ACID	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN2031	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM IN
Qty Released:	0.25	**CR Street Name:**	P O BOX 108
Unit of Measure:	Liquid - Gallon	**CR City:**	PITTSBURGH
What Failed:	109; 103	**CR State:**	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug); Basic Material	**CR Postal Code:**	152300108
How Failed Code:	;	**CR Non US State:**	
How Failed Desc:	;	**CR Fed DOT ID:**	265752
Failure Cause Code:	526; 538	**CR Hazmat Reg ID:**	
Failure Cause Desc:	Loose Closure, Component, or Device; Water Damage	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	SHAPE PRODUCTS
Cont1 Pkging Type:		**Shipper Street Name:**	1127 5TH ST
Cont1 Const Mat:		**Shipper City:**	OAKLAND
Cont1 Head Type:		**Shipper State:**	CA
Cont1 Pkg Capacity:	4	**Shipper Postal:**	94621
C1 Capacity UOM:	LGA	**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	094614500057977
Cont1 Pkg No:	1	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	1	**Origin City:**	
Cont1 Pkg Mnfctr:	NOT REPORTED BY CARRIER	**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	US
C1 Test Const Mat:		**Destination City:**	SANTA ROSA
C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95403
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	
C1 Head Thick UOM:		**Cont2 Const Mat:**	
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	1
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	LGA
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	4
C1 Device Model:		**Cont2 Pkg No Failed:**	1
NRC No:			
RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	No	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	SCOTT KERR
Damage > 500:	Yes	**Contact Title:**	HAZMAT MANAGER
Material Loss:	100	**Contact Business:**	
Carrier Damage:	0	**Contact Street:**	
Property Damage:	0	**Contact City:**	
Response Cost:	0	**Contact State:**	
Remediation Cost:	425	**Contact Postal:**	
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	525	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	BOX FIBER
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: THE PACKAGE WAS UNLOADED WITH LEAKAGE NOTED ON THE BOX. EXAMINATION OF THE INNER CONTAINER REVEALED THAT THE CONTAINER(S) HAD LOOSE CAP(S) AND LEAKED. THE LEAKAGE WAS CONTAINED. THE CAP(S) WERE SECURED. THE CARTON WAS WET BUT OTHERWISE UNDAMAGED. THE UNDAMAGED PORTION OF THE PACKAGE WAS REPACKED FOR RETURN TO SHIPPER.

Recommend Actions Taken:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
2	1 of 3	NW	0.00 / 0.00	111.80 / -8	**MEED CLARK LUMBER** **960 CALETTI WINDSOR, CA 95492** **CA**	**DELISTED COUNTY**

Original Source Facility ID:
Original Source Name: Sonoma County CUPA Facilities List
Record Date: 11-JAN-2016

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
2	2 of 3	NW	0.00 / 0.00	111.80 / -8	**Mead Clark Lumber Company, Inc.** **960 Caletti Av Windsor, CA 95492** **CA**	**DELISTED COUNTY**

Original Source Facility ID:
Original Source Name: Sonoma County CUPA Facilities List
Record Date: 11-JAN-2016

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
2	3 of 3	NW	0.00 / 0.00	111.80 / -8	**1X SOCO STEEL FABRICATIONS INC** **960 CALETTI** **WINDSOR CA 954920000**	**HAZNET**

SIC Code:		***Mailing City:***	WINDSOR
NAICS Code:		***Mailing State:***	CA
EPA ID:	CAC000896552	***Mailing Zip:***	954920000
Create Date:	11/8/1993	***Region Code:***	2
Fac Act Ind:	No	***Owner Name:***	--

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Inact Date:	10/25/2000	**Owner Addr 1:**	--
County Code:	49	**Owner Addr 2:**	
County Name:	Sonoma	**Owner City:**	--
Mail Name:		**Owner State:**	99
Mailing Addr 1:	960 CALETTI	**Owner Zip:**	--
Mailing Addr 2:		**Owner Phone:**	0000000000
Owner Fax:			

Contact Information

--	--
Contact Name:	DEBBIE BARTH
Street Address 1:	960 CALETTI
Street Address 2:	
City:	WINDSOR
State:	CA
Zip:	954920000
Phone:	7078388560
--	--

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
3	1 of 1	NW	0.00 / 2.41	114.23 / -6	STANDARD STRUCTURESNA INC. CA	FINDS/FRS

Registry ID:	110066178200
FIPS Code:	
HUC Code:	18010110
Site Type Name:	STATIONARY
Location Description:	
Supplemental Location:	
Create Date:	14-OCT-15
Update Date:	
Interest Types:	STATE MASTER
SIC Codes:	
SIC Code Descriptions:	
NAICS Codes:	
NAICS Code Descriptions:	
Conveyor:	CALEPA
Federal Facility Code:	
Federal Agency Name:	
Tribal Land Code:	
Tribal Land Name:	
Congressional Dist No:	01
Census Block Code:	060971527024000
EPA Region Code:	09
County Name:	SONOMA
US/Mexico Border Ind:	
Latitude:	38.525763
Longitude:	-122.79296
Reference Point:	
Coord Collection Method:	INTERPOLATION-MAP
Accuracy Value:	
Datum:	NAD83
Source:	
Facility Detail Rprt URL:	https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110066178200
Program Acronyms:	

CA-ENVIROVIEW:71084

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
4	1 of 1	NW	0.00 / 12.69	113.46 / -7	REDWOOD SANITARY SERVICE FIRE 511 SHILOH ROAD WINDSOR CA 95492	CLEANUP SITES

Global ID:	T0609793491	**Latitude:**	38.5217737282182
Status:	COMPLETED - CASE CLOSED	**Longitude:**	-122.794066719543
Status Date:	10/27/2000	**County:**	SONOMA

Site Facility Type: CLEANUP PROGRAM SITE
Data Source: Cleanup Program Sites from GeoTracker Search; Cleanup Sites from GeoTracker Cleanup Sites Data Download

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail

RB Case No: 1NSO751
Local Case No:
Begin Date: 9/30/1999
File Location: Regional Board
Lead Agency: NORTH COAST RWQCB (REGION 1)
Local Agency: SONOMA COUNTY
Potential COC:
Potential Media of Concern: Soil
How Discovered: Other Means
How Discovered Description:
Stop Description:
CalWater Watershed Name: Russian River - Middle Russian River - Mark West (114.23)
DWR GW Subbasin Name: Santa Rosa Valley - Santa Rosa Plain (1-055.01)
Disadvantaged Community:
CalEnviroScreen Score: 21-25%
Site History:
Stop Method:
CUF Case: NO
Case Worker: ZZZ

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity

Action Type: Other
Date: 1999-09-30 00:00:00
Action: Leak Discovery

Action Type: Other
Date: 1999-09-30 00:00:00
Action: Leak Reported

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History

Status: Open - Remediation
Status Date: 2000-10-27 00:00:00

Status: Completed - Case Closed
Status Date: 2000-10-27 00:00:00

Status: Open - Verification Monitoring
Status Date: 2000-10-27 00:00:00

Status: Open - Site Assessment
Status Date: 2000-10-27 00:00:00

Status: Open - Case Begin Date
Status Date: 1999-09-30 00:00:00

Status: Open - Site Assessment
Status Date: 1999-09-30 00:00:00

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts

Contact Type: Regional Board Caseworker
Contact Name: REGIONAL WATER BOARD SITE CLOSED
Phone No: 7075762220
Organization Name: NORTH COAST RWQCB (REGION 1)
Email:
Address: 5550 SKYLANE BOULEVARD, SUITE A
City: SANTA ROSA

Contact Type: Local Agency Caseworker
Contact Name: ENVIRON HEALTH STAFF (NON LOP-RB1)
Phone No:
Address: 625 5th Street
City: SANTA ROSA

Organization Name: SONOMA COUNTY
Email:

Cleanup Program Sites from GeoTracker Search - Regulatory Profile (as of May 29, 2021)

Project Status:
Cuf Claim No:
CUF Priority Assign:
CUF Amount Paid:
Composting Method:
File Location: REGIONAL BOARD
User Defined Beneficial Use:
Designated Beneficial Use: MUN, AGR, IND, PROC, FRSH, CUL, AQUA - Note: R1 BP- all gw same uses.
Designated Beneficl Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply, Freshwater Replenishment, Native American Culture, AQUA - Note: R1 BP- all gw same uses.
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T0609793491
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 10/27/2000
Potential COC: NA
Potential Media of Concern: SOIL
Groundwater Monitoring Frequen:
DWR GW Sub Basin: Santa Rosa Valley - Santa Rosa Plain (1-055.01)
CalWater Watershed Name: Russian River - Middle Russian River - Mark West (114.23)
Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: NORTH COAST RWQCB (REGION 1) (LEAD) - CASE #: 1NSO751
CASEWORKER: REGIONAL WATER BOARD SITE CLOSED
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0609793491&tabname=regulatoryhistory
Site History:

Facility Type:
WDR Place Type:
Wdr File No:
Wdr Order No:

No site history available

Sites from GeoTracker Search - Regulatory Activities (as of May 29, 2021)

Action Type: Leak Action
Action Date: 9/30/1999
Received Issue Date:
Action: Leak Discovery
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action Date: 9/30/1999
Received Issue Date:
Action: Leak Reported
Doc Link:
Title Description Comments:

Sites from GeoTracker Search - Cleanup Status History (as of May 29, 2021)

Status: Open - Verification Monitoring
Date: 10/27/2000

Status: Open - Site Assessment
Date: 10/27/2000

Status: Completed - Case Closed
Date: 10/27/2000

Status: Open - Remediation
Date: 10/27/2000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Status: Open - Site Assessment
Date: 9/30/1999

Status: Open - Case Begin Date
Date: 9/30/1999

---

5 *1 of 4* *NW* *0.00 / 20.90* *114.48 / -6*

TEXACO
701 SHILOH RD
WIMDSOR CA 95492

HHSS

County: Sonoma
Tank Details Microfiche: http://geotracker.waterboards.ca.gov/ustpdfs/pdf/000216e1.pdf

---

5 *2 of 4* *NW* *0.00 / 20.90* *114.48 / -6*

AUTO VISION OF WINDSOR
701 SHILOH RD
WINDSOR CA 954920000

HAZNET

SIC Code:
NAICS Code:
EPA ID: CAL000079301
Create Date: 12/21/1992
Fac Act Ind: No
Inact Date: 6/30/1998
County Code: 49
County Name: Sonoma
Mail Name:
Mailing Addr 1: 701 SHILOH RD
Mailing Addr 2:
Owner Fax:

Mailing City: WINDSOR
Mailing State: CA
Mailing Zip: 954929743
Region Code: 2
Owner Name: MAGLIETTA BRYAN-ASHCRAFT BREN
Owner Addr 1: --
Owner Addr 2:
Owner City: --
Owner State: 99
Owner Zip: --
Owner Phone: 0000000000

Contact Information
-- --
Contact Name: --
Street Address 1: INACT PER 98VQ FINAL NOTICE
Street Address 2: - BATCH 4/27
City: --
State: 99
Zip: --
Phone: --
-- --

---

5 *3 of 4* *NW* *0.00 / 20.90* *114.48 / -6*

VIC'S AUTO REPAIR
701 SHILOH RD
WINDSOR CA 954920000

HAZNET

SIC Code:
NAICS Code:
EPA ID: CAL000018285
Create Date: 11/14/1989
Fac Act Ind: No
Inact Date: 6/30/1996
County Code: 49
County Name: Sonoma
Mail Name:
Mailing Addr 1: 701 SHILOH RD
Mailing Addr 2:
Owner Fax:

Mailing City: WINDSOR
Mailing State: CA
Mailing Zip: 954920000
Region Code: 2
Owner Name: VINSICK VICTOR
Owner Addr 1: --
Owner Addr 2:
Owner City: --
Owner State: 99
Owner Zip: --
Owner Phone: 0000000000

Contact Information
-- --
Contact Name: UNDELIVERABLE 1996 FEES FORM
Street Address 1: --
Street Address 2:
City: --
State: 99

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Zip:		--				
Phone:		--				
--		--				

5	4 of 4	NW	0.00 / 20.90	114.48 / -6	TEXACO 701 SHILOH RD. WINDSOR CA	HIST TANK

Owner Name:	DAVID SUNDERLAND - WINDSOR TOW	No of Containers:	3
Owner Street:	943 POLARIS DR.	County:	SONOMA
Owner City:	WINDSOR	Facility State:	CA
Owner State:	CA	Facility Zip:	95492
Owner Zip:	95492		

6	1 of 1	NW	0.01 / 64.11	109.72 / -10	ECODYNE POND 930 SHILOH RD WINDSOR CA 95492	HIST CORTESE

Envirostor ID:	49240001
Status (Historical):	ACTIVE
Site Type:	STATE RESPONSE
Site Code:	200028

7	1 of 1	NNW	0.02 / 93.91	121.99 / 2	REDWOOD SANITARY SERVICE FIRE 511 SHILOH ROAD WINDSOR CA 95492	FINDS/FRS

Registry ID:	110066648792
FIPS Code:	
HUC Code:	18010110
Site Type Name:	STATIONARY
Location Description:	
Supplemental Location:	
Create Date:	14-OCT-15
Update Date:	
Interest Types:	STATE MASTER
SIC Codes:	
SIC Code Descriptions:	
NAICS Codes:	
NAICS Code Descriptions:	
Conveyor:	FRS-GEOCODE
Federal Facility Code:	
Federal Agency Name:	
Tribal Land Code:	
Tribal Land Name:	
Congressional Dist No:	01
Census Block Code:	060971538081024
EPA Region Code:	09
County Name:	SONOMA
US/Mexico Border Ind:	
Latitude:	38.52578
Longitude:	-122.793077
Reference Point:	ENTRANCE POINT OF A FACILITY OR STATION
Coord Collection Method:	ADDRESS MATCHING-HOUSE NUMBER
Accuracy Value:	50
Datum:	NAD83
Source:	
Facility Detail Rprt URL:	https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110066648792
Program Acronyms:	

CA-ENVIROVIEW:256694

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
8	1 of 1	NW	0.02 / 115.85	109.17 / -11	Windsor Oaks 899 Shiloh Road Windsor CA 95492	SWF/LF

SWIS No: 49-AA-0381
EPA Fed Registry ID:
Operational Status: Closed
Regulatory Status: Exempt
Site is Archived: Yes
Absorbed on:
Absorbed by:
Site Inert Debris Eng Fill: No
Closed Illegal Aband: Yes
Closed Illegal Aband Cat: D
Finance Assuran Responsible: No
Incorporated City: Windsor
Local Government: Windsor
Reporting Agency Legal Name: County of Sonoma
Reporting Agency Department: Department of Health Services, Environmental Health & Safety Section
Enforcing Agency Legal Name: County of Sonoma
Enforcing Agency Department: Department of Health Services, Environmental Health & Safety Section

Latitude: 38.55
Longitude: -122.81667
County: Sonoma
Site ZIP: 95492
ARB District: Bay Area
SWRCB Region: North Coast
Site Point of Contact: Dawn Liang

Site Owners

Site Type: Disposal Only
Owner Name: Olufs, Julius Herbert
Owner Address: 899 Shiloh Rd
Owner City: Windsor
Owner State: CA
Owner ZIP Code: 95492
Owner Phone: (707) 838-7588

Contact Name: Herbert Olufs
Contact First Name: Herbert
Contact Last Name: Olufs
Contact Title: Property Owner
Contact Email:
Started On:

Site Operators

Site Type: Disposal Only
Operator Name: Town Of San Anselmo
Operator Address: 525 San Anselmo Ave
Operator City: San Anselmo
Operator State: CA
Operator ZIP Code: 94960
Operator Phone: (415) 258-4616

Is Archived: Yes
Contact Name:
Contact First Name:
Contact Last Name:
Contact Title:
Contact Email:
Started on:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
9	1 of 9	NW	0.02 / 121.27	113.51 / -6	5900 Pruitt Ave. WINDSOR CA	HMIRS

Incident County: SONOMA

HMIR Historical Reports

Report No: X-2006030247
Report Type: A hazardous material incident
Date of Incident: 03/10/2006
Time of Incident: 0630
Haz Class Code: 8
Hazardous Class: CORROSIVE MATERIAL
Commodity Short Nm: CORROSIVE LIQUID ACIDIC
Commodity Long Nm: CORROSIVE LIQUID ACIDIC INORGANIC N. O.S.
Trade Name: SODIUM HYDROXIDE
ID No: UN3264
Haz Waste Ind: No
Haz Waste EPA No:
HMIS Tox Inhalation?: No

Fed DOT Agency Nm:
Fed DOT Report No:
Report Submit Src: XML
Inc Multiple Rows: No
Inc Non US State:
Mode Transport: Highway
Transport Phase: LOADING
Incident Occrrnce:
Mat Ship Approval?: No
Mat Ship Approv No:
Undecl Hazmat Ship?: No
Packaging Type: Non-Bulk
Packing Group:

TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	1	**CR Street Name:**	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	**CR City:**	CORAOPOLIS
What Failed:	135	**CR State:**	PA
What Failed Desc:	Loading or Unloading Lines	**CR Postal Code:**	15108-9373
How Failed Code:	309	**CR Non US State:**	
How Failed Desc:	Punctured	**CR Fed DOT ID:**	265752
Failure Cause Code:	511	**CR Hazmat Reg ID:**	062904001002M
Failure Cause Desc:	Dropped	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	BIRCHWOOD LABORATORIES LLC
Cont1 Pkging Type:	Box	**Shipper Street Name:**	7900 FULLER RD
Cont1 Const Mat:	Fiberboard	**Shipper City:**	EDEN PRAIRIE
Cont1 Head Type:		**Shipper State:**	MN
Cont1 Pkg Capacity:	0	**Shipper Postal:**	55344-2138
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	055404811430436
Cont1 Pkg No:		**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:		**Origin City:**	EDEN PRAIRIE
Cont1 Pkg Mnfctr:		**Origin State:**	MINNESOTA
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	55344
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:	Fiberboard	**Destination City:**	SANTA ROSA
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95401
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	Bottle
C1 Head Thick UOM:		**Cont2 Const Mat:**	Plastic
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	
C1 Device Model:		**Cont2 Pkg No Failed:**	
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	DENISE HANCHULAK
Damage > 500:	No	**Contact Title:**	TSM MANAGER II - SAFETY
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	

Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2006100106	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	08/22/2006	**Report Submit Src:**	XML
Time of Incident:	2027	**Inc Multiple Rows:**	No
Haz Class Code:	8	**Inc Non US State:**	
Hazardous Class:	CORROSIVE MATERIAL	**Mode Transport:**	Highway
Commodity Short Nm:	CORROSIVE LIQUID BASIC	**Transport Phase:**	IN TRANSIT STORAGE
Commodity Long Nm:	CORROSIVE LIQUID BASIC ORGANIC N.O. S.	**Incident Occrrnce:**	
Trade Name:	SODIUM HYDROXIDE	**Mat Ship Approval?:**	No
ID No:	UN3267	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	5	**CR Street Name:**	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	**CR City:**	CORAOPOLIS
What Failed:	104	**CR State:**	PA
What Failed Desc:	Body	**CR Postal Code:**	15108-9373
How Failed Code:	305	**CR Non US State:**	
How Failed Desc:	Crushed	**CR Fed DOT ID:**	265752
Failure Cause Code:	511	**CR Hazmat Reg ID:**	062904001002M
Failure Cause Desc:	Dropped	**CR Country:**	US
Ident. Markings:	NO MARKINGS GIVEN	**Shipper Name:**	LIGHTHOUSE FOR THE BLIND OF HOUSTON
Cont1 Pkging Type:		**Shipper Street Name:**	3530 W DALLAS ST
Cont1 Const Mat:		**Shipper City:**	HOUSTON
Cont1 Head Type:		**Shipper State:**	TX
Cont1 Pkg Capacity:		**Shipper Postal:**	77019-1702
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:		**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	032486030090539
Cont1 Pkg No:		**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:		**Origin City:**	HOUSTON
Cont1 Pkg Mnfctr:		**Origin State:**	TEXAS
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	77019
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:		**Destination City:**	WINDSOR
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95492
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	
C1 Head Thick UOM:		**Cont2 Const Mat:**	

C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	
C1 Device Model:		**Cont2 Pkg No Failed:**	
NRC No:			
RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	SCOTT KERR
Damage > 500:	No	**Contact Title:**	TSM MANAGER II - SAFETY
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	CONT
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Container no description given (do not use if at all possible)
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2006100416	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	07/05/2006	**Report Submit Src:**	XML
Time of Incident:	0600	**Inc Multiple Rows:**	No
Haz Class Code:	2.0	**Inc Non US State:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Hazardous Class:	COMBUSTIBLE LIQUID	**Mode Transport:**	Highway
Commodity Short Nm:	PAINT	**Transport Phase:**	LOADING
Commodity Long Nm:	PAINT	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1263	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.023438	**CR Street Name:**	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	**CR City:**	CORAOPOLIS
What Failed:	109	**CR State:**	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	**CR Postal Code:**	15108-9373
How Failed Code:	308	**CR Non US State:**	
How Failed Desc:	Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	511	**CR Hazmat Reg ID:**	062904001002M
Failure Cause Desc:	Dropped	**CR Country:**	US
Ident. Markings:	NO MARKINGS GIVEN	**Shipper Name:**	BASF CORPORATION
Cont1 Pkging Type:		**Shipper Street Name:**	6700 8TH ST
Cont1 Const Mat:		**Shipper City:**	BUENA PARK
Cont1 Head Type:		**Shipper State:**	CA
Cont1 Pkg Capacity:		**Shipper Postal:**	90620-1097
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:		**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	92544160022317
Cont1 Pkg No:		**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:		**Origin City:**	BUENA PARK
Cont1 Pkg Mnfctr:		**Origin State:**	CALIFORNIA
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	90620
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:		**Destination City:**	
C1 Pkg Dsign Pres.:		**Destination State:**	
C1 Dsign Press UOM:		**Destination Postal:**	
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	
C1 Head Thickness:		**Cont2 Package Type:**	
C1 Head Thick UOM:		**Cont2 Const Mat:**	
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	
C1 Device Model:		**Cont2 Pkg No Failed:**	
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No

Other Cleanup:	No	**Contact Name:**	DENISE HANCHULAK
Damage > 500:	No	**Contact Title:**	TSM MANAGER II - SAFETY
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	PAIL
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Pail open head capacity 10 gallons or less
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The pail was dropped during handling causing leakage. The leakage was contained and the package was repacked. Undamaged product was returned to the shipper. The damaged product was properly disposed of in accordance with Federal Regulations.

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2008050309	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	05/09/2008	**Report Submit Src:**	XML
Time of Incident:	1155	**Inc Multiple Rows:**	No
Haz Class Code:	5.1	**Inc Non US State:**	
Hazardous Class:	OXIDIZER	**Mode Transport:**	Highway
Commodity Short Nm:	HYDROGEN PEROXIDE AQUEO	**Transport Phase:**	UNLOADING
Commodity Long Nm:	HYDROGEN PEROXIDE AQUEOUS SOLUTIONS WITH NOT LESS THAN 20 PERCENT BUT NOT MORE THAN 40 PERCENT HYDROGEN PEROXIDE (STABILIZED AS NECESSARY)	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN2014	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.01	**CR Street Name:**	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	**CR City:**	CORAOPOLIS
What Failed:	134	**CR State:**	PA
What Failed Desc:	Liquid Valve	**CR Postal Code:**	15108-9373
How Failed Code:	309	**CR Non US State:**	
How Failed Desc:	Punctured	**CR Fed DOT ID:**	265752
Failure Cause Code:	517	**CR Hazmat Reg ID:**	062904001002M
Failure Cause Desc:	Improper Preparation for Transportation	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	NATIONAL DISCOUNT POOL SUPPLIES L.L.C.
Cont1 Pkging Type:	Box	**Shipper Street Name:**	8920 58TH PL STE 850
Cont1 Const Mat:	Fiberboard	**Shipper City:**	KENOSHA
Cont1 Head Type:		**Shipper State:**	WI
Cont1 Pkg Capacity:		**Shipper Postal:**	53144-7829
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:		**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	67871980285122
Cont1 Pkg No:		**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:		**Origin City:**	KENOSHA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Cont1 Pkg Mnfctr:		**Origin State:**	WISCONSIN
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	53144
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:	Fiberboard	**Destination City:**	HIDDEN VALLEY LAKE
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95467
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	Bottle
C1 Head Thick UOM:		**Cont2 Const Mat:**	Plastic
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	
C1 Device Model:		**Cont2 Pkg No Failed:**	
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:		**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	TRAVIS MCEWEN
Damage > 500:	No	**Contact Title:**	SAFETY SPECIALIST III - HAZMAT
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Recommend Actions Taken:						
9	2 of 9	NW	0.02 / 121.27	113.51 / -6	SCWS Emergency CDI Processing 5900 Pruitt Ave. Windsor CA 95492	SWF/LF

SWIS No: 49-AA-0423
EPA Fed Registry ID:
Operational Status: Active
Regulatory Status: Notification
Site is Archived: Yes
Absorbed on:
Absorbed by:
Site Inert Debris Eng Fill: No
Closed Illegal Aband: No
Closed Illegal Aband Cat:
Finance Assuran Responsible: No
Incorporated City: Windsor
Local Government: Windsor
Reporting Agency Legal Name: County of Sonoma
Reporting Agency Department: Department of Health Services, Environmental Health & Safety Section
Enforcing Agency Legal Name: County of Sonoma
Enforcing Agency Department: Department of Health Services, Environmental Health & Safety Section

Latitude: 38.52351
Longitude: -122.79096
County: Sonoma
Site ZIP: 95492
ARB District: Bay Area
SWRCB Region: North Coast
Site Point of Contact: Alyssa Williams

Site Owners

Site Type: Non-Disposal Only
Owner Name: SOCO Investments, Inc
Owner Address: P.O. Box 1878
Owner City: Windsor
Owner State: CA
Owner ZIP Code: 95492
Owner Phone: (707) 836-4336

Contact Name:
Contact First Name:
Contact Last Name:
Contact Title:
Contact Email:
Started On:

Site Operators

Site Type: Non-Disposal Only
Operator Name: Sonoma County Waste Solution, LLC
Operator Address: PO Box 630
Operator City: Ukiah
Operator State: CA
Operator ZIP Code: 95482
Operator Phone:

Is Archived: Yes
Contact Name: Kristyn Byrne
Contact First Name: Kristyn
Contact Last Name: Byrne
Contact Title:
Contact Email:
Started on:

Site Waste

Site Type: Non-Disposal Only
Waste Type: Inert
Activity Oper Status: Active
Act Regulatory Stat: Notification
Activity: Emergency CDI Debris Processing Operation

Activity Category: Transfer/Processing
Act Classification: Solid Waste Operation
Activity Is Archived: Yes

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
9	3 of 9	NW	0.02 / 121.27	113.51 / -6	Pruitt Transload Facility 5900 Pruitt Ave. Windsor CA 95492	SWF/LF

SWIS No: 49-AA-0426
EPA Fed Registry ID:
Operational Status: Active
Regulatory Status: Permitted
Site is Archived: No
Absorbed on:
Absorbed by:
Site Inert Debris Eng Fill: No

Latitude: 38.52335
Longitude: -122.79175
County: Sonoma
Site ZIP: 95492
ARB District: Bay Area
SWRCB Region: North Coast
Site Point of Contact: Alyssa Williams

Closed Illegal Abandon: No
Closed Illegal Abandon Cat:
Finance Assuran Responsible: No
Incorporated City: Windsor
Local Government: Windsor
Reporting Agency Legal Name: County of Sonoma
Reporting Agency Department: Department of Health Services, Environmental Health & Safety Section
Enforcing Agency Legal Name: County of Sonoma
Enforcing Agency Department: Department of Health Services, Environmental Health & Safety Section

Site Owners

Site Type: Non-Disposal Only
Owner Name: SOCO Investments, Inc
Owner Address: P.O. Box 1878
Owner City: Windsor
Owner State: CA
Owner ZIP Code: 95492
Owner Phone: (707) 836-4336
Contact Name:
Contact First Name:
Contact Last Name:
Contact Title:
Contact Email:
Started On:

Site Activities (Search Result)

ID: 5314
Act Opl Status: Active
Site Name: Pruitt Transload Facility
Activity: Medium Volume Transfer/Processing Facility
Act Regulatory Stat: Permitted
Activity Category: Transfer/Processing

Site Operators

Site Type: Non-Disposal Only
Operator Name: Sonoma County Waste Solutions, LLC
Operator Address: P.O. Box 1878
Operator City: Windor
Operator State: CA
Operator ZIP Code: 95482
Operator Phone:
Is Archived: No
Contact Name: Kyistyn Byrne
Contact First Name: Kyistyn
Contact Last Name: Byrne
Contact Title:
Contact Email:
Started on:

Site Waste

Site Type: Non-Disposal Only
Waste Type: Green Materials
Activity Oper Status: Active
Act Regulatory Stat: Permitted
Activity: Medium Volume Transfer/Processing Facility
Activity Category: Transfer/Processing
Act Classification: Solid Waste Facility
Activity Is Archived: No

Site Type: Non-Disposal Only
Waste Type: Wood waste
Activity Oper Status: Active
Act Regulatory Stat: Permitted
Activity: Medium Volume Transfer/Processing Facility
Activity Category: Transfer/Processing
Act Classification: Solid Waste Facility
Activity Is Archived: No

Extra Details

Enforcement Agency (LEA/EA): Sonoma County

Site Activities (Export)

WDR No:
WDR Landfill Class:
Act is Archived: No
Act Opl Status: Active
Act Regulatory Stat: Permitted
Remaining Capacity:
Remaining Cap Dt:
Max Permit Cap: 36135
Capacity UOM: Tons per year
Total Acreage: 0.60

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Activity Category:	Transfer/Processing	**Disposal Acreage:**	
Act Classification:	Solid Waste Facility	**Permitted Elev :**	
Cease Operation:		**Permitted Elev Tp:**	
Cease Operation Tp:		**Permitted Depth:**	
Insp Frequency:	Monthly	**Permitted Depth Tp:**	
Incorporated City:	Windsor	**Site Name:**	Pruitt Transload Facility
Site Point of Contact:	Alyssa Williams		
Activity:	Medium Volume Transfer/Processing Facility		
Max Permitted Throughput:	99		
Throughput UOM:	Tons per day		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
9	4 of 9	NW	0.02 / 121.27	113.51 / -6	SCWS Wood Processing Operation 5900 Pruitt Ave. Windsor CA 95492	SWF/LF

SWIS No:	49-AA-0425	**Latitude:**	38.52434
EPA Fed Registry ID:		**Longitude:**	-122.79242
Operational Status:	Active	**County:**	Sonoma
Regulatory Status:	Notification	**Site ZIP:**	95492
Site is Archived:	No	**ARB District:**	Bay Area
Absorbed on:		**SWRCB Region:**	North Coast
Absorbed by:		**Site Point of Contact:**	Alyssa Williams
Site Inert Debris Eng Fill:	No		
Closed Illegal Aband:	No		
Closed Illegal Aband Cat:			
Finance Assuran Responsible:	No		
Incorporated City:	Windsor		
Local Government:	Windsor		
Reporting Agency Legal Name:	County of Sonoma		
Reporting Agency Department:	Department of Health Services, Environmental Health & Safety Section		
Enforcing Agency Legal Name:	County of Sonoma		
Enforcing Agency Department:	Department of Health Services, Environmental Health & Safety Section		

Site Owners

Site Type:	Non-Disposal Only	**Contact Name:**	
Owner Name:	SOCO Investments, Inc	**Contact First Name:**	
Owner Address:	P.O. Box 1878	**Contact Last Name:**	
Owner City:	Windsor	**Contact Title:**	
Owner State:	CA	**Contact Email:**	
Owner ZIP Code:	95492	**Started On:**	
Owner Phone:	(707) 836-4336		

Site Activities (Search Result)

ID:	5211	**Act Regulatory Stat:**	Notification
Act Opl Status:	Active	**Activity Category:**	Composting
Site Name:	SCWS Wood Processing Operation		
Activity:	Chipping and Grinding Facility/Operation		

Site Operators

Site Type:	Non-Disposal Only	**Is Archived:**	No
Operator Name:	Sonoma County Waste Solutions, LLC	**Contact Name:**	Kyistyn Byrne
Operator Address:	P.O. Box 1878	**Contact First Name:**	Kyistyn
Operator City:	Windor	**Contact Last Name:**	Byrne
Operator State:	CA	**Contact Title:**	
Operator ZIP Code:	95482	**Contact Email:**	
Operator Phone:		**Started on:**	

Site Waste

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Site Type:	Non-Disposal Only	**Activity Category:**	Composting
Waste Type:	Green Materials	**Act Classification:**	Solid Waste Facility
Activity Oper Status:	Active	**Activity Is Archived:**	No
Act Regulatory Stat:	Notification		
Activity:	Chipping and Grinding Facility/Operation		

Site Type:	Non-Disposal Only	**Activity Category:**	Composting
Waste Type:	Wood waste	**Act Classification:**	Solid Waste Facility
Activity Oper Status:	Active	**Activity Is Archived:**	No
Act Regulatory Stat:	Notification		
Activity:	Chipping and Grinding Facility/Operation		

Extra Details

Enforcement Agency (LEA/EA): Sonoma County

Site Activities (Export)

WDR No:		**Remaining Capacity:**	
WDR Landfill Class:		**Remaining Cap Dt:**	
Act is Archived:	No	**Max Permit Cap:**	72996
Act Opl Status:	Active	**Capacity UOM:**	Tons per year
Act Regulatory Stat:	Notification	**Total Acreage:**	3.50
Activity Category:	Composting	**Disposal Acreage:**	
Act Classification:	Solid Waste Facility	**Permitted Elev :**	
Cease Operation:		**Permitted Elev Tp:**	
Cease Operation Tp:		**Permitted Depth:**	
Insp Frequency:	Quarterly	**Permitted Depth Tp:**	
Incorporated City:	Windsor	**Site Name:**	SCWS Wood Processing Operation
Site Point of Contact:	Alyssa Williams		
Activity:	Chipping and Grinding Facility/Operation		
Max Permitted Throughput:	199		
Throughput UOM:	Tons per day		

9	5 of 9	NW	0.02 / 121.27	113.51 / -6	**PRS Inert Debris Processing Operation** **5900 Pruitt Ave.** **Windsor CA 95492**	SWF/LF

SWIS No:	49-AA-0427	**Latitude:**	38.52434
EPA Fed Registry ID:		**Longitude:**	-122.79242
Operational Status:	Planned	**County:**	Sonoma
Regulatory Status:	Notification	**Site ZIP:**	95492
Site is Archived:	Yes	**ARB District:**	Bay Area
Absorbed on:		**SWRCB Region:**	North Coast
Absorbed by:		**Site Point of Contact:**	Alyssa Williams
Site Inert Debris Eng Fill:	No		
Closed Illegal Aband:	No		
Closed Illegal Aband Cat:			
Finance Assuran Responsible:	No		
Incorporated City:	Windsor		
Local Government:	Windsor		
Reporting Agency Legal Name:	County of Sonoma		
Reporting Agency Department:	Department of Health Services, Environmental Health & Safety Section		
Enforcing Agency Legal Name:	County of Sonoma		
Enforcing Agency Department:	Department of Health Services, Environmental Health & Safety Section		

Site Owners

Site Type:	Non-Disposal Only	**Contact Name:**	
Owner Name:	SOCO Investments, Inc	**Contact First Name:**	
Owner Address:	P.O. Box 1878	**Contact Last Name:**	
Owner City:	Windsor	**Contact Title:**	
Owner State:	CA	**Contact Email:**	
Owner ZIP Code:	95492	**Started On:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner Phone: (707) 836-4336

Site Operators

Site Type: Non-Disposal Only
Operator Name: Pacific Recycling Solutions, Inc.
Operator Address: P.O. Box 630
Operator City: Ukiah
Operator State: CA
Operator ZIP Code: 95482
Operator Phone: (707) 234-6400

Is Archived: Yes
Contact Name: Bruce McCracken
Contact First Name: Bruce
Contact Last Name: McCracken
Contact Title:
Contact Email:
Started on:

Site Waste

Site Type: Non-Disposal Only
Waste Type: Inert
Activity Oper Status: Planned
Act Regulatory Stat: Notification
Activity: Inert Debris Type A Processing Operation

Activity Category: Transfer/Processing
Act Classification: Solid Waste Operation
Activity Is Archived: Yes

9	6 of 9	NW	0.02 / 121.27	113.51 / -6	WESTERN TREE REMOVAL SPECIALISTS 5900 PRUITT AVE STE 532 WINDSOR CA 95492	RCRA NON GEN

EPA Handler ID: CAL000429102
Gen Status Universe: No Report
Contact Name: JUSTIN GREER
Contact Address: PO BOX 1418 , , WINDSOR , CA, 95492 ,
Contact Phone No and Ext: 707-332-7606
Contact Email: JUSTIN@WESTERNTREESPECIALISTS.COM
Contact Country:
County Name: SONOMA
EPA Region: 09
Land Type:
Receive Date: 20170712
Location Latitude: 38.521404
Location Longitude: -122.790713

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20170712
Handler Name: WESTERN TREE REMOVAL SPECIALISTS
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Other
Name: JUSTIN GREER
Date Became Current:
Date Ended Current:
Phone: 707-332-7606
Source Type: Implementer
Street No:
Street 1: PO BOX 1418
Street 2:
City: WINDSOR
State: CA
Country:
Zip Code: 95492

Owner/Operator Ind: Current Operator
Type: Other
Name: JUSTIN GREER
Date Became Current:
Date Ended Current:
Phone: 707-332-7606
Source Type: Implementer
Street No:
Street 1: PO BOX 1418
Street 2:
City: WINDSOR
State: CA
Country:
Zip Code: 95492

9	7 of 9	NW	0.02 / 121.27	113.51 / -6	***Atlas Tree Surgery Reduction Yard*** ***5900 Pruitt Ave.*** ***Windsor CA 95492***	***SWF/LF***

SWIS No: 49-AA-0441
EPA Fed Registry ID:
Operational Status: Closed
Regulatory Status: Notification
Site is Archived: Yes
Absorbed on:
Absorbed by:
Site Inert Debris Eng Fill: No
Closed Illegal Aband: No
Closed Illegal Aband Cat:
Finance Assuran Responsible: No
Incorporated City: Windsor
Local Government: Windsor
Reporting Agency Legal Name: County of Sonoma
Reporting Agency Department: Department of Health Services, Environmental Health & Safety Section
Enforcing Agency Legal Name: County of Sonoma
Enforcing Agency Department: Department of Health Services, Environmental Health & Safety Section
Latitude: 38.52237
Longitude: -122.7909
County: Sonoma
Site ZIP: 95492
ARB District: Bay Area
SWRCB Region: North Coast
Site Point of Contact: Alyssa Williams

Site Owners

Site Type: Non-Disposal Only
Owner Name: SOCO Investments, Inc
Owner Address: P.O. Box 1878
Owner City: Windsor
Owner State: CA
Owner ZIP Code: 95492
Owner Phone: (707) 836-4336
Contact Name:
Contact First Name:
Contact Last Name:
Contact Title:
Contact Email:
Started On:

Site Operators

Site Type: Non-Disposal Only
Operator Name: Atlas Tree Surgery
Operator Address: 1544 Ludwig Avenue
Is Archived: Yes
Contact Name:
Contact First Name:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Operator City:	Santa Rosa	**Contact Last Name:**	
Operator State:	CA	**Contact Title:**	
Operator ZIP Code:	95407	**Contact Email:**	
Operator Phone:	(707) 523-4399	**Started on:**	

Site Waste

Site Type:	Non-Disposal Only	**Activity Category:**	Transfer/Processing
Waste Type:	Green Materials	**Act Classification:**	Solid Waste Operation
Activity Oper Status:	Closed	**Activity Is Archived:**	Yes
Act Regulatory Stat:	Notification		
Activity:	Emergency Transfer/Processing Operation		

Site Type:	Non-Disposal Only	**Activity Category:**	Transfer/Processing
Waste Type:	Wood waste	**Act Classification:**	Solid Waste Operation
Activity Oper Status:	Closed	**Activity Is Archived:**	Yes
Act Regulatory Stat:	Notification		
Activity:	Emergency Transfer/Processing Operation		

9	8 of 9	NW	0.02 / 121.27	113.51 / -6	**Atlas Tree Processing Yard** **5900 Pruitt Ave.** **Windsor CA 95492**	SWF/LF

SWIS No:	49-AA-0442	**Latitude:**	38.52237
EPA Fed Registry ID:		**Longitude:**	-122.7909
Operational Status:	Closed	**County:**	Sonoma
Regulatory Status:	Notification	**Site ZIP:**	95492
Site is Archived:	Yes	**ARB District:**	Bay Area
Absorbed on:		**SWRCB Region:**	North Coast
Absorbed by:		**Site Point of Contact:**	Alyssa Williams

Site Inert Debris Eng Fill:	No
Closed Illegal Aband:	No
Closed Illegal Aband Cat:	
Finance Assuran Responsible:	No
Incorporated City:	Windsor
Local Government:	Windsor
Reporting Agency Legal Name:	County of Sonoma
Reporting Agency Department:	Department of Health Services, Environmental Health & Safety Section
Enforcing Agency Legal Name:	County of Sonoma
Enforcing Agency Department:	Department of Health Services, Environmental Health & Safety Section

Site Owners

Site Type:	Non-Disposal Only	**Contact Name:**	
Owner Name:	SOCO Investments, Inc	**Contact First Name:**	
Owner Address:	P.O. Box 1878	**Contact Last Name:**	
Owner City:	Windsor	**Contact Title:**	
Owner State:	CA	**Contact Email:**	
Owner ZIP Code:	95492	**Started On:**	
Owner Phone:	(707) 836-4336		

Site Operators

Site Type:	Non-Disposal Only	**Is Archived:**	Yes
Operator Name:	Atlas Tree Surgery	**Contact Name:**	
Operator Address:	1544 Ludwig Avenue	**Contact First Name:**	
Operator City:	Santa Rosa	**Contact Last Name:**	
Operator State:	CA	**Contact Title:**	
Operator ZIP Code:	95407	**Contact Email:**	
Operator Phone:	(707) 523-4399	**Started on:**	

Site Waste

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Site Type:	Non-Disposal Only	**Activity Category:**	Composting
Waste Type:	Wood waste	**Act Classification:**	Solid Waste Facility
Activity Oper Status:	Closed	**Activity Is Archived:**	Yes
Act Regulatory Stat:	Notification		
Activity:	Chipping and Grinding Facility/Operation		

Site Type:	Non-Disposal Only	**Activity Category:**	Composting
Waste Type:	Green Materials	**Act Classification:**	Solid Waste Facility
Activity Oper Status:	Closed	**Activity Is Archived:**	Yes
Act Regulatory Stat:	Notification		
Activity:	Chipping and Grinding Facility/Operation		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
9	9 of 9	NW	0.02 / 121.27	113.51 / -6	**PRS Direct Transfer Operation** **5900 Pruitt Ave.** **Windsor CA 95492**	SWF/LF

SWIS No:	49-AA-0420	**Latitude:**	38.52298
EPA Fed Registry ID:		**Longitude:**	-122.79008
Operational Status:	Closed	**County:**	Sonoma
Regulatory Status:	Surrendered	**Site ZIP:**	95492
Site is Archived:	Yes	**ARB District:**	Bay Area
Absorbed on:		**SWRCB Region:**	North Coast
Absorbed by:		**Site Point of Contact:**	Alyssa Williams
Site Inert Debris Eng Fill:	No		
Closed Illegal Aband:	No		
Closed Illegal Aband Cat:			
Finance Assuran Responsible:	No		
Incorporated City:	Windsor		
Local Government:	Windsor		
Reporting Agency Legal Name:	County of Sonoma		
Reporting Agency Department:	Department of Health Services, Environmental Health & Safety Section		
Enforcing Agency Legal Name:	County of Sonoma		
Enforcing Agency Department:	Department of Health Services, Environmental Health & Safety Section		

Site Owners

Site Type:	Non-Disposal Only	**Contact Name:**	
Owner Name:	SOCO Investments, Inc	**Contact First Name:**	
Owner Address:	P.O. Box 1878	**Contact Last Name:**	
Owner City:	Windsor	**Contact Title:**	
Owner State:	CA	**Contact Email:**	
Owner ZIP Code:	95492	**Started On:**	
Owner Phone:	(707) 836-4336		

Site Operators

Site Type:	Non-Disposal Only	**Is Archived:**	Yes
Operator Name:	Pacific Recycling Solutions	**Contact Name:**	Bruce McCraken
Operator Address:	P.O. Box 60	**Contact First Name:**	Bruce
Operator City:	Ukiah	**Contact Last Name:**	McCraken
Operator State:	CA	**Contact Title:**	
Operator ZIP Code:	95484	**Contact Email:**	bmcracken@candwaste.com
Operator Phone:	(707) 234-6400	**Started on:**	

Site Waste

Site Type:	Non-Disposal Only	**Activity Category:**	Transfer/Processing
Waste Type:	Mixed municipal	**Act Classification:**	Solid Waste Facility
Activity Oper Status:	Closed	**Activity Is Archived:**	Yes
Act Regulatory Stat:	Surrendered		
Activity:	Direct Transfer Facility		

Site Type:	Non-Disposal Only	**Activity Category:**	Transfer/Processing
Waste Type:	Other designated	**Act Classification:**	Solid Waste Facility
Activity Oper Status:	Closed	**Activity Is Archived:**	Yes

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Act Regulatory Stat: Surrendered
Activity: Direct Transfer Facility

10	1 of 13	NW	0.03 / 142.75	114.50 / -5	MOBIL STATION (FORMER) 705 SHILOH RD WINDSOR CA 95492	DELISTED TNK

Delisted Storage Tanks

Facility ID: 49-000-006237
Permitting Agency: SONOMA COUNTY
County: Sonoma
Latitude: 38.527466
Longitude: -122.791397
Original Source: UST
Record Date: 30-JAN-2017

10	2 of 13	NW	0.03 / 142.75	114.50 / -5	MOBIL STATION (FORMER) 705 SHILOH ROAD WINDSOR CA 95492	DELISTED TNK

Delisted Storage Tanks

Facility ID: 49-000-005848
Permitting Agency: SONOMA COUNTY
County: Sonoma
Latitude: 38.527466
Longitude: -122.791397
Original Source: UST
Record Date: 30-JAN-2017

10	3 of 13	NW	0.03 / 142.75	114.50 / -5	Mobil Station (former) 705 Shiloh Rd Windsor CA	LOP SONOMA

LOP No: 00002581
RB No: 1TSO111
Status: Y
Status Desc: Closed Site
Date: 8/16/2013
Global ID: T0609700081
APN: 163-130-013
Staff:
Staff Name:

10	4 of 13	NW	0.03 / 142.75	114.50 / -5	Windsor Valero 705 Shiloh Rd Windsor, CA 95492 CA	CUPA SONOMA

Facility ID: 49-000-007981
CERS ID: 10485172

Details

Program Type: HMBP
Permit Status: Active
Expiration Date: 8/30/2020
Fee Schedule: Range 4

Details

Program Type: Stormwater
Permit Status: Active

Expiration Date: 8/30/2020
Fee Schedule: Storm Water Permit

Details

Program Type: Hazardous Waste
Permit Status: Active
Expiration Date: 8/30/2020
Fee Schedule: SQG < 325 gallons/year

Details

Program Type: UST
Permit Status: Active
Expiration Date: 8/30/2020
Fee Schedule: Permit to Operate - 3 tanks

---

10 | ***5 of 13*** | ***NW*** | ***0.03 / 142.75*** | ***114.50 / -5*** | ***MOBIL STATION (FORMER)
705 SHILOH RD
WINDSOR CA 95492*** | ***LUST***

Global ID: T0609700081
Status: COMPLETED - CASE CLOSED
Status Date: 8/16/2013
Case Type: LUST CLEANUP SITE
Date Source: LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download
County: SONOMA
Latitude: 38.525990121
Longitude: -122.792833993

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail

RB Case No: 1TSO111
Local Case No: 00002581
Begin Date: 3/18/1987
Lead Agency: SONOMA COUNTY LOP
Local Agency: SONOMA COUNTY LOP
CUF Case: NO
Potential Media of Concern: Well used for drinking water supply
How Discovered Description:
Calwater Watershed Name: Russian River - Middle Russian River - Mark West (114.23)
DWR GW Subbasin Name: Santa Rosa Valley - Santa Rosa Plain (1-055.01)
Disadvantaged Community:
Calenviroscreen Score: 46-50%
Site History:
Potential COC: Gasoline, Waste Oil / Motor / Hydraulic / Lubricating, Diesel
How Discovered: Tank Closure
Stop Method: Close and Remove Tank
Stop Description:
Case Worker: LCW
File Location: Local Agency Warehouse

Excerpts from "Well Destruction and Excavation Report" (Environmental Resolutions, Inc., January 20, 2010) From 1968 to 1971, the site operated as a retail Mobil service station (Alton, 1998). Since 1971, a variety of businesses have operated at the site, including an auto repair facility, a towing company, and an electrical contractor (Alton, 1998). In 1987, a 350-gallon used-oil UST, a 10,OOO-galion UST, and an 8,000-gallon UST were removed from the site (Emcon, 1993). The site has been vacant since 1999 (TRC, 1999). Site Assessment Activities Soil and groundwater investigations have been conducted at the site since 1987. Well construction details are provided in Table 2. Soil sample analytical results are summarized in Tables 3A and 3B. Remediation Activities In March 1987, 100 cubic yards of soil were excavated from the UST pit and aerated on site. Ten cubic yards of soil were excavated from beneath the used-oil UST and removed from the site (Brunsing, 1991). In 2001, 120 feet of steel product lines and approximately 150 cubic yards of excavated soil were removed from the site (TRC, 2001). The GWPTS was started on July 18, 2003. The GWPTS extracted groundwater from wells MW4A, MW8, MW10, and MW11. ERI collected water samples monthly, quarterly, annually, or as necessary, at influent, intermediate, and effluent sample ports, and from the receiving waters, to ensure compliance with the NPDES permit and performance of the GWPTS. The NPDES permit expired in June 2006. The GWPTS treated 284,600 gallons of groundwater and removed approximately <13.7 pounds of TPHg, 2.5 pounds of benzene, and <0.05 pound of MTBE (ERI, 2007). The GWPTS was then shut down pending remedial evaluation. The SVE system was started on June 29, 2004. The SVE system extracted soil vapor from wells MW4A, MW8, MW10, and MW11. ERI collected vapor samples at influent and effluent sample ports on a monthly basis. The SVE system removed less than approximately 21,765 pounds of TPHg, 532 pounds of benzene, and 131 pounds of MTBE from the vapor stream (ERI, 2007). The SVE system was shut down in 2006 pending remedial evaluation. Remedial Excavation January 20, 2010 Between November 16 and 20, 2009, ERI observed Wayne Perry excavate soil containing petroleum hydrocarbons from the area shown on Plate 5 using a Komatsu PC300 LC excavator. ERI monitored the ambient air during the excavation activities with a PID and LEL to evaluate air quality in the workspace. Wayne Perry excavated approximately 2,831 tons of soil. The excavated material was loaded directly into 119 trucks and transported for disposal to the Clean Harbors Buttonwillow Landfill, in Buttonwillow, California. . . ERI collected samples from soils retrieved in the excavator bucket using glass jars provided by H&P Labs and brass sleeves and 5035 Sampling Kits for Calscience. The excavation was delineated by previous soil boring

analytical results, placement of the shoring, and the physical constraints of the site. The excavation extended to within approximately 5 feet of the planter curb along the southern side of the site and approximately 16 feet from the edge of the station building on the northern side of the site. The northern and southern sidewalls were delineated by the placement of shoring. The western and eastern sidewalls of the excavation were sloped at an approximate 1:1 ratio. At the completion of the excavation activities, the floor of the excavation was approximately 19 feet bgs. Additional Notes by LOP staff: Verification monitoring wells and borings were installed from Jun 14 to June 17, 2010. SITE OFFICIALLY CLOSED ON AUGUST 16, 2013.

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity

Action Type: RESPONSE
Date : 9/15/2013
Action: Well Destruction Report

Action Type: ENFORCEMENT
Date : 8/16/2013
Action: Closure/No Further Action Letter

Action Type: RESPONSE
Date : 8/8/2013
Action: Request for Closure - Regulator Responded

Action Type: RESPONSE
Date : 3/3/2013
Action: Well Destruction Workplan - Regulator Responded

Action Type: ENFORCEMENT
Date : 1/22/2013
Action: Staff Letter

Action Type: RESPONSE
Date : 1/18/2013
Action: Well Destruction Workplan - Regulator Responded

Action Type: ENFORCEMENT
Date : 1/2/2013
Action: Staff Letter

Action Type: RESPONSE
Date : 12/1/2012
Action: Correspondence

Action Type: ENFORCEMENT
Date : 11/1/2012
Action: LOP Case Closure Summary to RB

Action Type: ENFORCEMENT
Date : 11/1/2012
Action: Staff Letter

Action Type: ENFORCEMENT
Date : 11/1/2012
Action: Notification - Public Notice of Case Closure

Action Type: RESPONSE
Date : 9/12/2012
Action: Soil and Water Investigation Workplan

Action Type: ENFORCEMENT
Date : 7/12/2012
Action: Staff Letter

Action Type: ENFORCEMENT
Date : 6/28/2011
Action: Staff Letter

Action Type: RESPONSE
Date : 1/23/2011
Action: Monitoring Report - Quarterly

Action Type: ENFORCEMENT
Date : 11/17/2010
Action: Staff Letter

Action Type: RESPONSE
Date : 9/19/2010
Action: Well Installation Report

Action Type: ENFORCEMENT
Date : 7/26/2010
Action: Staff Letter

Action Type: ENFORCEMENT
Date : 3/18/2010
Action: Staff Letter

Action Type: RESPONSE
Date : 1/21/2010
Action: Final Remedial Action Report / Corrective Action Report

Action Type: REMEDIATION
Date : 11/16/2009
Action: Excavation

Action Type: ENFORCEMENT
Date : 9/21/2009
Action: Staff Letter

Action Type: ENFORCEMENT
Date : 7/20/2009
Action: Rescission of Enforcement Action

Action Type: RESPONSE
Date : 7/7/2009
Action: Corrective Action Plan / Remedial Action Plan - Addendum

Action Type: ENFORCEMENT
Date : 5/7/2009
Action: Staff Letter

Action Type: RESPONSE
Date : 1/26/2009
Action: Final Remedial Action Report / Corrective Action Report

Action Type: ENFORCEMENT
Date : 11/25/2008
Action: Staff Letter

Action Type: RESPONSE
Date : 9/18/2008
Action: Remedial Progress Report

Action Type: ENFORCEMENT
Date : 6/19/2008
Action: Staff Letter

Action Type: RESPONSE
Date : 2/14/2008
Action: Other Report / Document

Action Type: ENFORCEMENT
Date : 12/10/2007
Action: Staff Letter

Action Type: REMEDIATION
Date : 6/29/2004
Action: Soil Vapor Extraction (SVE)

Action Type: ENFORCEMENT
Date : 12/1/2003
Action: Staff Letter

Action Type: REMEDIATION
Date : 7/18/2003
Action: Pump & Treat (P&T) Groundwater

Action Type: Other
Date : 3/18/1987
Action: Leak Discovery

Action Type: Other
Date : 3/18/1987
Action: Leak Reported

Action Type: Other
Date : 3/17/1987
Action: Leak Stopped

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History

Status: Completed - Case Closed
Status Date: 8/16/2013

Status: Open - Eligible for Closure
Status Date: 11/14/2012

Status: Open - Remediation
Status Date: 7/1/2003

Status: Open - Site Assessment
Status Date: 10/9/1990

Status: Open - Case Begin Date
Status Date: 3/18/1987

LUST Sites from GeoTracker Search - Regulatory Profile

Site Facility Name: MOBIL STATION (FORMER)
Site Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Project Status:
WDR Place Type:
WDR File:
WDR Order:
CUF Priority Assig:
CUF Amount Paid:
Potential COC: DIESEL, GASOLINE, WASTE OIL / MOTOR / HYDRAULIC / LUBRICATING
Facility Type:
Composting Method:
Address: 705 SHILOH RD
City: WINDSOR
Zip: 95492
County: SONOMA
CUF Claim:
File Location: LOCAL AGENCY WAREHOUSE
Designated Beneficial Use: MUN, AGR, IND, PROC, FRSH, CUL, AQUA - Note: R1 BP- all gw same uses.
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T0609700081
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 8/16/2013
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0609700081&tabname=regulatoryhistory
Potential Media of Concern: WELL USED FOR DRINKING WATER SUPPLY
User Defined Beneficial Use:
DWR GW Sub Basin: Santa Rosa Valley - Santa Rosa Plain (1-055.01)
Calwater Watershed Name: Russian River - Middle Russian River - Mark West (114.23)
Post Closure Site Management:
Future Land Use: COMMERCIAL
Cleanup Oversight Agencies: SONOMA COUNTY LOP (LEAD) - CASE #: 00002581
CASEWORKER: LOP CLOSED IN RB01
NORTH COAST RWQCB (REGION 1) - CASE #: 1TSO111
CASEWORKER: SONOMA COUNTY LOP CLOSED SITE
Gndwater Monitoring Freque:
Designated Beneficial Use Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply,

Desc: Freshwater Replenishment, Native American Culture, AQUA - Note: R1 BP- all gw same uses.
Site History:

Excerpts from "Well Destruction and Excavation Report" (Environmental Resolutions, Inc., January 20, 2010)
From 1968 to 1971, the site operated as a retail Mobil service station (Alton, 1998). Since 1971, a variety of businesses have operated at the site, including an auto repair facility, a towing company, and an electrical contractor (Alton, 1998). In 1987, a 350-gallon used-oil UST, a 10,OOO-galion UST, and an 8,000-gallon UST were removed from the site (Emcon, 1993). The site has been vacant since 1999 (TRC, 1999).
Site Assessment Activities
Soil and groundwater investigations have been conducted at the site since 1987. Well construction details are provided in Table 2. Soil sample analytical results are summarized in Tables 3A and 3B.
Remediation Activities
In March 1987, 100 cubic yards of soil were excavated from the UST pit and aerated on site. Ten cubic yards of soil were excavated from beneath the used-oil UST and removed from the site (Brunsing, 1991).
In 2001, 120 feet of steel product lines and approximately 150 cubic yards of excavated soil were removed from the site (TRC, 2001).
The GWPTS was started on July 18, 2003. The GWPTS extracted groundwater from wells MW4A, MW8, MW10, and MW11. ERI collected water samples monthly, quarterly, annually, or as necessary, at influent, intermediate, and effluent sample ports, and from the receiving waters, to ensure compliance with the NPDES permit and performance of the GWPTS. The NPDES permit expired in June 2006. The GWPTS treated 284,600 gallons of groundwater and removed approximately <13.7 pounds of TPHg, 2.5 pounds of benzene, and <0.05 pound of MTBE (ERI, 2007). The GWPTS was then shut down pending remedial evaluation.
The SVE system was started on June 29, 2004. The SVE system extracted soil vapor from wells MW4A, MW8, MW10, and MW11. ERI collected vapor samples at influent and effluent sample ports on a monthly basis. The SVE system removed less than approximately 21,765 pounds of TPHg, 532 pounds of benzene, and 131 pounds of MTBE from the vapor stream (ERI, 2007). The SVE system was shut down in 2006 pending remedial evaluation.
Remedial Excavation
January 20, 2010
Between November 16 and 20, 2009, ERI observed Wayne Perry excavate soil containing petroleum hydrocarbons from the area shown on Plate 5 using a Komatsu PC300 LC excavator. ERI monitored the ambient air during the excavation activities with a PID and LEL to evaluate air quality in the workspace. Wayne Perry excavated approximately 2,831 tons of soil. The excavated material was loaded directly into 119 trucks and transported for disposal to the Clean Harbors Buttonwillow Landfill, in Buttonwillow, California. . .
ERI collected samples from soils retrieved in the excavator bucket using glass jars provided by H&P Labs and brass sleeves and 5035 Sampling Kits for Calscience. The excavation was delineated by previous soil boring analytical results, placement of the shoring, and the physical constraints of the site. The excavation extended to within approximately 5 feet of the planter curb along the southern side of the site and approximately 16 feet from the edge of the station building on the northern side of the site. The northern and southern sidewalls were delineated by the placement of shoring. The western and eastern sidewalls of the excavation were sloped at an approximate 1:1 ratio. At the completion of the excavation activities, the floor of the excavation was approximately 19 feet bgs.
Additional Notes by LOP staff:
Verification monitoring wells and borings were installed from Jun 14 to June 17, 2010.
SITE OFFICIALLY CLOSED ON AUGUST 16, 2013.

LUST Sites from GeoTracker Search - Cleanup Status History

Status: Completed - Case Closed
Date : 8/16/2013

Status: Open - Eligible for Closure
Date : 11/14/2012

Status: Open - Remediation
Date : 7/1/2003

Status: Open - Site Assessment
Date : 10/9/1990

Status: Open - Case Begin Date
Date : 3/18/1987

LUST Sites from GeoTracker Search - Cleanup Action Report (as of May 29, 2021)

Action Type: EXCAVATION
Begin Date: 11/16/2009
Phase: Soil, Water
End Date: 11/20/2009
Contaminant Mass Removed: 1,574 Pounds
Description: Excavation to 19 feet. 3300 lbs of RegenOx, 750 lbs of ORC. 2831 tons transported to Buttonwillow Landfill, Buttonwillow, CA 11/17-11/20/09 Water generated: 9700 g to 11k tank. Additional 41500 g pumped to vac trucks. 600 g rinsate from tanks. Total 51800 g disposed InStrat, Inc. Rio Vista, CA 11/19-11/24/2009

Action Type: SOIL VAPOR EXTRACTION (SVE)
Begin Date: 6/29/2004
Phase: Soil
End Date: 10/31/2006
Contaminant Mass Removed:
Description: Influent concentrations decreased to ND.

Action Type: PUMP & TREAT (P&T) GROUNDWATER
Begin Date: 7/18/2003
Phase: Water
End Date: 12/18/2006
Contaminant Mass Removed: 21,779 Pounds
Description: Dates are approximate. NPDES expired in 2006.

LUST Sites from GeoTracker Search - Regulatory Activities (as of May 29, 2021)

Action Type: Response Requested - Reports
Action Date: 9/15/2013
Received Issue Date: 8/9/2013
Action: Well Destruction Report
Doc Link:
Title Description Comments:

Action Type: Other Regulatory Actions
Action Date: 8/16/2013
Received Issue Date: 8/16/2013
Action: Closure/No Further Action Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700081&enforcement_id=6172065&temptable=ENFORCEMENT
Title Description Comments:

No Further Action

Action Type: Response Requested - Other
Action Date: 8/8/2013
Received Issue Date: 8/8/2013
Action: Request for Closure - Regulator Responded
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700081&doc_id=5778702
Title Description Comments:

Well Destruction Report and Request for NFA - Site officially closed today.

Action Type: Response Requested - Workplans
Action Date: 3/3/2013
Received Issue Date: 1/19/2013
Action: Well Destruction Workplan - Regulator Responded
Doc Link:
Title Description Comments:

Action Type: Other Regulatory Actions
Action Date: 1/22/2013
Received Issue Date: 1/22/2013
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700081&enforcement_id=6147695&temptable=ENFORCEMENT
Title Description Comments:

Well Destruction Approval

Action Type: Response Requested - Workplans

Action Date: 1/18/2013
Received Issue Date: 1/18/2013
Action: Well Destruction Workplan - Regulator Responded
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700081&doc_id=5767182
Title Description Comments:

Well Destruction Work Plan - See Staff Letter on 1/22/2013

Action Type: Other Regulatory Actions
Action Date: 1/2/2013
Received Issue Date: 1/2/2013
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700081&enforcement_id=6146050&temptable=ENFORCEMENT
Title Description Comments:

Well destruction directive

Action Type: Response Requested - Other
Action Date: 12/1/2012
Received Issue Date: 1/24/2013
Action: Correspondence
Doc Link:
Title Description Comments:

Letter confirming the notification of adjacent property occupants.

Action Type: Other Regulatory Actions
Action Date: 11/1/2012
Received Issue Date: 11/1/2012
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700081&enforcement_id=6141764&temptable=ENFORCEMENT
Title Description Comments:

Notification Letters

Action Type: Other Regulatory Actions
Action Date: 11/1/2012
Received Issue Date: 11/1/2012
Action: LOP Case Closure Summary to RB
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700081&enforcement_id=6141761&temptable=ENFORCEMENT
Title Description Comments:

Case Closure Summary and Recommendation Letter for Closure

Action Type: Notices
Action Date: 11/1/2012
Received Issue Date: 11/1/2012
Action: Notification - Public Notice of Case Closure
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700081&enforcement_id=6141763&temptable=ENFORCEMENT
Title Description Comments:

Notice of Pending Action-Closure

Action Type: Response Requested - Workplans
Action Date: 9/12/2012
Received Issue Date: 9/12/2012
Action: Soil and Water Investigation Workplan
Doc Link:
Title Description Comments:

Action Type: Other Regulatory Actions
Action Date: 7/12/2012
Received Issue Date: 7/12/2012
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700081&enforcement_id=6129815&temptable=ENFORCEMENT
Title Description Comments:

Case Closure Denial

Action Type: Other Regulatory Actions
Action Date: 6/28/2011
Received Issue Date: 6/28/2011
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700081&enforcement_id=6090690&temptable=ENFORCEMENT
Title Description Comments:

Concurrence letter to go to semi-annual sampling

Action Type: Response Requested - Reports
Action Date: 1/23/2011
Received Issue Date: 12/10/2010
Action: Monitoring Report - Quarterly
Doc Link:
Title Description Comments:

Verification sampling

Action Type: Other Regulatory Actions
Action Date: 11/17/2010
Received Issue Date: 11/17/2010
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700081&enforcement_id=6069488&temptable=ENFORCEMENT
Title Description Comments:

Directive to sample quarterly for one year as verification sampling

Action Type: Response Requested - Reports
Action Date: *9/19/2010
Received Issue Date: 9/17/2010
Action: Well Installation Report
Doc Link:
Title Description Comments:

Action Type: Other Regulatory Actions
Action Date: 7/26/2010
Received Issue Date: 7/26/2010
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700081&enforcement_id=6058819&temptable=ENFORCEMENT
Title Description Comments:

Concur with construction of MW for verification monitoring in backfill Compliance date previously established as 9/19/10

Action Type: Other Regulatory Actions
Action Date: 3/18/2010
Received Issue Date: 3/18/2010
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700081&enforcement_id=6045656&temptable=ENFORCEMENT
Title Description Comments:

Directive to install verification monitoring wells

Action Type: Response Requested - Reports
Action Date: 1/21/2010
Received Issue Date: 1/21/2010
Action: Final Remedial Action Report / Corrective Action Report
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700081&doc_id=5651028
Title Description Comments:

Well Destruction and Excavation Report

Action Type: Other Regulatory Actions
Action Date: 9/21/2009
Received Issue Date: 9/21/2009
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700081&enforcement_id=6030680&temptable=ENFORCEMENT
Title Description Comments:

Directive to implement CAP Excavation Plan

Action Type: Enforcement/Orders
Action Date: 7/20/2009
Received Issue Date: 7/20/2009
Action: Rescission of Enforcement Action
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700081&enforcement_id=6023129&temptable=ENFORCEMENT
Title Description Comments:

Termination of coverage under General NPDESs Order No. R1-2006-0048

Action Type: Response Requested - Workplans
Action Date: 7/7/2009
Received Issue Date: 7/7/2009
Action: Corrective Action Plan / Remedial Action Plan - Addendum
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700081&doc_id=5638359
Title Description Comments:

ADDENDUM TO FEASIBILITY STUDY AND REVISED CORRECTIVE ACTION PLAN

Action Type: Other Regulatory Actions
Action Date: 5/7/2009
Received Issue Date: 5/7/2009
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700081&enforcement_id=6012585&temptable=ENFORCEMENT
Title Description Comments:

5/7/2009 Directive to supplement the revised FS/CAP

Action Type: Response Requested - Reports
Action Date: 1/26/2009
Received Issue Date: 3/23/2009
Action: Final Remedial Action Report / Corrective Action Report
Doc Link:
Title Description Comments:

- SVE and GWE have not remediated site to cleanup objectives. Excavation is now proposed but it has not been compared with other alternatives and would remove components of SVE and GWE.

Action Type: Other Regulatory Actions
Action Date: 11/25/2008
Received Issue Date: 11/25/2008
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?

global_id=T0609700081&enforcement_id=5994573&temptable=ENFORCEMENT

Title Description Comments:

Directive to revise FS/CAP and justify excavation

Action Type: Response Requested - Reports
Action Date: *9/18/2008
Received Issue Date: 9/18/2008
Action: Remedial Progress Report
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700081&doc_id=5606420
Title Description Comments:

Response To Comments and Evaluation Of Remediation Efforts - Evaluate corrective action done and revise FS/CAP as necessary.

Action Type: Other Regulatory Actions
Action Date: 6/19/2008
Received Issue Date: 6/19/2008
Action: Staff Letter
Doc Link:
Title Description Comments:

Reject WP to excavate without evaluating previous CAP and revising if necessary.

Action Type: Response Requested - Other
Action Date: 2/14/2008
Received Issue Date: 2/14/2008
Action: Other Report / Document
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700081&doc_id=5753446
Title Description Comments:

Soil and Groundwater Management Plan

Action Type: Other Regulatory Actions
Action Date: 12/10/2007
Received Issue Date: 12/10/2007
Action: Staff Letter
Doc Link:
Title Description Comments:

Action Type: Other Regulatory Actions
Action Date: 12/1/2003
Received Issue Date: 12/1/2003
Action: Staff Letter
Doc Link:
Title Description Comments:

Comply with EDF reporting requirements. System startup notification is required.

Action Type: Cleanup Action
Action Date: 11/16/2009
Received Issue Date:
Action: Excavation
Doc Link:
Title Description Comments:

Excavation to 19 feet. 3300 lbs of RegenOx, 750 lbs of ORC. 2831 tons transported to Buttonwillow Landfill, Buttonwillow, CA 11/17-11/20/09 Water generated: 9700 g to 11k tank. Additional 41500 g pumped to vac trucks. 600 g rinsate from tanks. Total 51800 g disposed InStrat, Inc. Rio Vista, CA 11/19-11/24/2009

Action Type: Cleanup Action
Action Date: 6/29/2004
Received Issue Date:
Action: Soil Vapor Extraction (SVE)
Doc Link:

Title Description Comments:

Influent concentrations decreased to ND.

Action Type: Cleanup Action
Action Date: 7/18/2003
Received Issue Date:
Action: Pump & Treat (P&T) Groundwater
Doc Link:
Title Description Comments:

Dates are approximate. NPDES expired in 2006.

Action Type: Leak Action
Action Date: 3/18/1987
Received Issue Date:
Action: Leak Discovery
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action Date: 3/18/1987
Received Issue Date:
Action: Leak Reported
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action Date: 3/17/1987
Received Issue Date:
Action: Leak Stopped
Doc Link:
Title Description Comments:

LUST Sites from GeoTracker Search - Site Maps (as of May 29, 2021)

Title: GEO_MAP
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/6728509128/T0609700081.PDF
Size : 132 KB
Submitted By: CARDNO (AUTH_RP)
Submitted: 8/8/2013

Title: SB29 (SB29)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/8434457361/T0609700081.PDF
Size : 160 KB
Submitted By: CARDNO (AUTH_RP)
Submitted: 9/17/2010

Title: SB28 (SB28)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/1507715880/T0609700081.PDF
Size : 168 KB
Submitted By: CARDNO (AUTH_RP)
Submitted: 9/17/2010

Title: GEO_MAP
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/7779465675/T0609700081.PDF
Size : 93 KB
Submitted By: CARDNO (AUTH_RP)
Submitted: 9/16/2010

Title: SB27 (SB27)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/9125710904/T0609700081.PDF
Size : 168 KB
Submitted By: CARDNO (AUTH_RP)

Submitted: 9/16/2010

Title: MW13 (MW13)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/6987214088/T0609700081.PDF
Size : 152 KB
Submitted By: CARDNO (AUTH_RP)
Submitted: 9/16/2010

Title: SB24 (SB24)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/6379990935/T0609700081.PDF
Size : 181 KB
Submitted By: CARDNO (AUTH_RP)
Submitted: 9/16/2010

Title: SB25 (SB25)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/3281846404/T0609700081.PDF
Size : 170 KB
Submitted By: CARDNO (AUTH_RP)
Submitted: 9/16/2010

Title: SB26 (SB26)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/8799958229/T0609700081.PDF
Size : 180 KB
Submitted By: CARDNO (AUTH_RP)
Submitted: 9/16/2010

Title: MW14 (MW14)
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/3345041930/T0609700081.PDF
Size : 138 KB
Submitted By: CARDNO (AUTH_RP)
Submitted: 9/16/2010

Title: GEO_MAP
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/5129159390/T0609700081.PDF
Size : 88 KB
Submitted By: CARDNO (AUTH_RP)
Submitted: 1/21/2010

LUST Sites from GeoTracker Search - Documents (as of May 29, 2021)

Document Type: Site Documents **Size :** 78 KB
Document Date: 1/12/2021* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: HISTORICAL - REVIEW OF WORKPLAN CORRESPONDENCE DATED 02-2000
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8633113026/T0609700081.PDF

Document Type: Site Documents **Size :**
Document Date: 8/16/2013 **Submitted By:** MATT L. VILLABER (REGULATOR)
Type: CLOSURE/NO FURTHER ACTION LETTER **Submitted:**
Title: NO FURTHER ACTION
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700081&enforcement_id=6172065

Document Type: Site Documents **Size :** 3,907 KB
Document Date: 8/8/2013 **Submitted By:** CARDNO (AUTH_RP)
Type: REQUEST FOR CLOSURE **Submitted:**
Title: WELL DESTRUCTION REPORT AND REQUEST FOR NFA
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3303068041/T0609700081.PDF

Document Type: Site Documents **Size :**
Document Date: 8/8/2013 **Submitted By:** MATT L. VILLABER (REGULATOR)
Type: REQUEST FOR CLOSURE **Submitted:**
Title: WELL DESTRUCTION REPORT AND REQUEST FOR NFA - REGULATOR RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700081&document_id=5778702

Document Type: Site Documents **Size :** 209 KB
Document Date: 1/28/2013 **Submitted By:** CARDNO (AUTH_RP)
Type: CORRESPONDENCE **Submitted:**
Title: NOTIFICATION OF SCHEDULED ENVIRONMENTAL ACTIVITIES

Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4053440153/T0609700081.PDF

Document Type: Site Documents
Size :
Document Date: 1/22/2013
Submitted By: MATT L. VILLABER (REGULATOR)
Type: STAFF LETTER
Submitted:
Title: WELL DESTRUCTION APPROVAL
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700081&enforcement_id=6147695

Document Type: Site Documents
Size : 267 KB
Document Date: 1/18/2013
Submitted By: CARDNO (AUTH_RP)
Type: FACT SHEETS - PUBLIC PARTICIPATION
Submitted:
Title: PUBLIC NOTIFICATION REQUIREMENTS FOR PENDING SITE CLOSURE
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4984101772/T0609700081.PDF

Document Type: Site Documents
Size : 6,002 KB
Document Date: 1/16/2013
Submitted By: CARDNO (AUTH_RP)
Type: WELL DESTRUCTION WORKPLAN
Submitted:
Title: WELL DESTRUCTION WORK PLAN
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2035526335/T0609700081.PDF

Document Type: Site Documents
Size :
Document Date: 1/2/2013
Submitted By: MATT L. VILLABER (REGULATOR)
Type: STAFF LETTER
Submitted:
Title: WELL DESTRUCTION DIRECTIVE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700081&enforcement_id=6146050

Document Type: Site Documents
Size :
Document Date: 11/1/2012
Submitted By: MATT L. VILLABER (REGULATOR)
Type: LOP CASE CLOSURE SUMMARY TO RB
Submitted:
Title: CASE CLOSURE SUMMARY AND RECOMMENDATION LETTER FOR CLOSURE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700081&enforcement_id=6141761

Document Type: Site Documents
Size :
Document Date: 11/1/2012
Submitted By: MATT L. VILLABER (REGULATOR)
Type: NOTIFICATION - PUBLIC NOTICE OF CASE CLOSURE
Submitted:
Title: NOTICE OF PENDING ACTION-CLOSURE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700081&enforcement_id=6141763

Document Type: Site Documents
Size :
Document Date: 11/1/2012
Submitted By: MATT L. VILLABER (REGULATOR)
Type: STAFF LETTER
Submitted:
Title: NOTIFICATION LETTERS
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700081&enforcement_id=6141764

Document Type: Site Documents
Size : 6,621 KB
Document Date: 9/11/2012
Submitted By: CARDNO (AUTH_RP)
Type: CLOSURE REPORT
Submitted:
Title: RESPONSE TO COMMENTS AND EVALUATION FOR LOW THREAT CLOSURE
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5999936938/T0609700081.PDF

Document Type: Site Documents
Size :
Document Date: 7/12/2012
Submitted By: MATT L. VILLABER (REGULATOR)
Type: STAFF LETTER
Submitted:
Title: CASE CLOSURE DENIAL
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700081&enforcement_id=6129815

Document Type: Monitoring Reports
Size : 9,314 KB
Document Date: 6/18/2012
Submitted By: CARDNO (AUTH_RP)
Type: MONITORING REPORT - SEMI-ANNUALLY
Submitted:
Title: GROUNDWATER MONITORING REPORT, SECOND QUARTER 2012
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3011518359/T0609700081.PDF

Document Type: Site Documents
Size : 20,976 KB
Document Date: 5/29/2012
Submitted By: CARDNO (AUTH_RP)
Type: CLOSURE REPORT
Submitted:
Title: RECOMMENDATION FOR CASE CLOSURE
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9156583666/T0609700081.PDF

Document Type: Monitoring Reports **Size :** 4,407 KB
Document Date: 1/30/2012 **Submitted By:** CARDNO (AUTH_RP)
Type: MONITORING REPORT - SEMI-ANNUALLY **Submitted:**
Title: GROUNDWATER MONITORING REPORT, FOURTH QUARTER 2011
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4365598320/T0609700081.PDF

Document Type: Site Documents **Size :**
Document Date: 6/28/2011 **Submitted By:** MATT L. VILLABER (REGULATOR)
Type: STAFF LETTER **Submitted:**
Title: CONCURRENCE LETTER TO GO TO SEMI-ANNUAL SAMPLING
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700081&enforcement_id=6090690

Document Type: Monitoring Reports **Size :** 4,458 KB
Document Date: 5/20/2011 **Submitted By:** CARDNO (AUTH_RP)
Type: MONITORING REPORT - QUARTERLY **Submitted:**
Title: GROUNDWATER MONITORING REPORT, SECOND QUARTER 2011
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3270196497/T0609700081.PDF

Document Type: Monitoring Reports **Size :** 4,786 KB
Document Date: 3/24/2011 **Submitted By:** CARDNO (AUTH_RP)
Type: MONITORING REPORT - QUARTERLY **Submitted:**
Title: GROUNDWATER MONITORING REPORT, FIRST QUARTER 2011
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6558852434/T0609700081.PDF

Document Type: Monitoring Reports **Size :** 4,367 KB
Document Date: 12/8/2010 **Submitted By:** CARDNO (AUTH_RP)
Type: MONITORING REPORT - SEMI-ANNUALLY **Submitted:**
Title: SEMI-ANNUAL GROUNDWATER MONITORING REPORT, FOURTH QUARTER 2010
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2535050749/T0609700081.PDF

Document Type: Site Documents **Size :**
Document Date: 11/17/2010 **Submitted By:** (REGULATOR)
Type: STAFF LETTER **Submitted:**
Title: DIRECTIVE TO SAMPLE QUARTERLY FOR ONE YEAR AS VERIFICATION SAMPLING
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700081&enforcement_id=6069488

Document Type: Site Documents **Size :** 14,990 KB
Document Date: 9/17/2010 **Submitted By:** CARDNO (AUTH_RP)
Type: SITE ASSESSMENT REPORT **Submitted:**
Title: SITE ASSESSMENT REPORT
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2441666960/T0609700081.PDF

Document Type: Monitoring Reports **Size :** 4,587 KB
Document Date: 9/16/2010 **Submitted By:** CARDNO (AUTH_RP)
Type: MONITORING REPORT - SEMI-ANNUALLY **Submitted:**
Title: SEMI-ANNUAL GROUNDWATER MONITORING REPORT, THIRD QUARTER 2010
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8809159278/T0609700081.PDF

Document Type: Site Documents **Size :**
Document Date: 7/26/2010 **Submitted By:** (REGULATOR)
Type: STAFF LETTER **Submitted:**
Title: CONCUR WITH CONSTRUCTION OF MW FOR VERIFICATION MONITORING IN BACKFILL
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700081&enforcement_id=6058819

Document Type: Site Documents **Size :** 4,169 KB
Document Date: 7/9/2010 **Submitted By:** CARDNO (AUTH_RP)
Type: WELL INSTALLATION WORKPLAN **Submitted:**
Title: WORK PLAN FOR MONITORING WELL INSTALLATION
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1240174651/T0609700081.PDF

Document Type: Site Documents **Size :** 155 KB
Document Date: 6/4/2010 **Submitted By:** CARDNO (AUTH_RP)
Type: CORRESPONDENCE **Submitted:**
Title: NOTIFICATION OF ASSESSMENT ACTIVITIES
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6457307219/T0609700081.PDF

Document Type: Monitoring Reports **Size :** 4,423 KB
Document Date: 5/4/2010 **Submitted By:** CARDNO (AUTH_RP)
Type: MONITORING REPORT - SEMI-ANNUALLY **Submitted:**

Title: SEMI-ANNUAL GROUNDWATER MONITORING REPORT, FIRST QUARTER 2010
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4089777648/T0609700081.PDF

Document Type: Site Documents **Size :**
Document Date: 3/18/2010 **Submitted By:** (REGULATOR)
Type: STAFF LETTER **Submitted:**
Title: DIRECTIVE TO INSTALL VERIFICATION MONITORING WELLS
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700081&enforcement_id=6045656

Document Type: Site Documents **Size :** 4,768 KB
Document Date: 1/21/2010 **Submitted By:** CARDNO (AUTH_RP)
Type: WELL INSTALLATION WORKPLAN **Submitted:**
Title: WORK PLAN FOR REPLACEMENT WELL INSTALLATION
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3347489714/T0609700081.PDF

Document Type: Site Documents **Size :** 29,878 KB
Document Date: 1/21/2010 **Submitted By:** CARDNO (AUTH_RP)
Type: REMEDIAL INVESTIGATION REPORT **Submitted:**
Title: WELL DESTRUCTION AND EXCAVATION REPORT, PART II
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4207604944/T0609700081.PDF

Document Type: Site Documents **Size :** 16,995 KB
Document Date: 1/21/2010 **Submitted By:** CARDNO (AUTH_RP)
Type: REMEDIAL INVESTIGATION REPORT **Submitted:**
Title: WELL DESTRUCTION AND EXCAVATION REPORT, PART I
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7924689054/T0609700081.PDF

Document Type: Site Documents **Size :**
Document Date: 9/21/2009 **Submitted By:** (REGULATOR)
Type: STAFF LETTER **Submitted:**
Title: DIRECTIVE TO IMPLEMENT CAP EXCAVATION PLAN
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700081&enforcement_id=6030680

Document Type: Monitoring Reports **Size :** 6,979 KB
Document Date: 8/31/2009 **Submitted By:** CARDNO (AUTH_RP)
Type: MONITORING REPORT - QUARTERLY **Submitted:**
Title: GROUNDWATER MONITORING AND REMEDIATION STATUS REPORT, THIRD QUARTER 2009
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9005770027/T0609700081.PDF

Document Type: Site Documents **Size :**
Document Date: 7/20/2009 **Submitted By:** COLLEEN HUNT (REGULATOR)
Type: RESCISSION OF ENFORCEMENT ACTION **Submitted:**
Title: TERMINATION OF COVERAGE UNDER GENERAL NPDESS ORDER NO. R1-2006-0048
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700081&enforcement_id=6023129

Document Type: Site Documents **Size :** 679 KB
Document Date: 7/7/2009 **Submitted By:** CARDNO (AUTH_RP)
Type: CORRECTIVE ACTION PLAN / REMEDIAL ACTION PLAN - ADDENDUM **Submitted:**
Title: ADDENDUM TO FEASIBILITY STUDY AND REVISED CORRECTIVE ACTION PLAN
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2245856046/T0609700081.PDF

Document Type: Monitoring Reports **Size :** 5,498 KB
Document Date: 6/12/2009 **Submitted By:** CARDNO (AUTH_RP)
Type: MONITORING REPORT - QUARTERLY **Submitted:**
Title: GROUNDWATER MONITORING AND REMEDIATION STATUS REPORT, SECOND QUARTER 2009
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1317785978/T0609700081.PDF

Document Type: Site Documents **Size :**
Document Date: 5/7/2009 **Submitted By:** (REGULATOR)
Type: STAFF LETTER **Submitted:**
Title: 5/7/2009 DIRECTIVE TO SUPPLEMENT THE REVISED FS/CAP
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700081&enforcement_id=6012585

Document Type: Monitoring Reports **Size :** 5,869 KB
Document Date: 3/30/2009 **Submitted By:** CARDNO (AUTH_RP)
Type: MONITORING REPORT - QUARTERLY **Submitted:**
Title: GROUNDWATER MONITORING AND REMEDIATION STATUS REPORT, FIRST QUARTER 2009
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7352676868/T0609700081.PDF

Document Type: Site Documents **Size :** 10,509 KB
Document Date: 3/23/2009 **Submitted By:** CARDNO (AUTH_RP)
Type: CAP/RAP - FEASIBILITY STUDY REPORT **Submitted:**
Title: FEASIBILITY STUDY AND REVISED CORRECTIVE ACTION PLAN
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1790060758/T0609700081.PDF

Document Type: Monitoring Reports **Size :** 11,479 KB
Document Date: 1/20/2009 **Submitted By:** CARDNO (AUTH_RP)
Type: MONITORING REPORT - QUARTERLY **Submitted:**
Title: GROUNDWATER MONITORING AND REMEDIATION STATUS REPORT, FOURTH QUARTER 2008
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7375847935/T0609700081.PDF

Document Type: Site Documents **Size :**
Document Date: 11/25/2008 **Submitted By:** (REGULATOR)
Type: STAFF LETTER **Submitted:**
Title: DIRECTIVE TO REVISE FS/CAP AND JUSTIFY EXCAVATION
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700081&enforcement_id=5994573

Document Type: Monitoring Reports **Size :** 5,732 KB
Document Date: 10/15/2008 **Submitted By:** CARDNO (AUTH_RP)
Type: MONITORING REPORT - QUARTERLY **Submitted:**
Title: GROUNDWATER MONITORING AND REMEDIATION STATUS REPORT, THIRD QUARTER 2008
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1775313436/T0609700081.PDF

Document Type: Site Documents **Size :** 11,972 KB
Document Date: 9/18/2008 **Submitted By:** CARDNO (AUTH_RP)
Type: NPDES / WDR REPORTS **Submitted:**
Title: RESPONSE TO COMMENTS AND EVALUATION OF REMEDIATION EFFORTS
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4738979518/T0609700081.PDF

Document Type: Site Documents **Size :** 139 KB
Document Date: 6/19/2008 **Submitted By:** (REGULATOR)
Type: LETTER **Submitted:**
Title: DIRECTIVE
Title Link: https://geotracker.waterboards.ca.gov/site_documents/4247349381/705%20Shiloh%20Rd%2D080619%2Epdf

Document Type: Monitoring Reports **Size :** 4,349 KB
Document Date: 6/11/2008 **Submitted By:** CARDNO (AUTH_RP)
Type: MONITORING REPORT - QUARTERLY **Submitted:**
Title: QUARTERLY GROUNDWATER MONITORING AND REMEDIATION STATUS REPORT, SECOND QUARTER 2008
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6332951426/T0609700081.PDF

Document Type: Monitoring Reports **Size :** 4,571 KB
Document Date: 4/8/2008 **Submitted By:** CARDNO (AUTH_RP)
Type: MONITORING REPORT - QUARTERLY **Submitted:**
Title: QUARTERLY GROUNDWATER MONITORING AND REMEDIATION STATUS REPORT, FIRST QUARTER 2008
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6777251303/T0609700081.PDF

Document Type: Site Documents **Size :** 3,223 KB
Document Date: 4/4/2008 **Submitted By:** CARDNO (AUTH_RP)
Type: WORKPLANS - OTHER WP **Submitted:**
Title: EXCAVATION WORK PLAN
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2270796835/T0609700081.PDF

Document Type: Site Documents **Size :**
Document Date: 2/14/2008 **Submitted By:** MATT L. VILLABER (REGULATOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: SOIL AND GROUNDWATER MANAGEMENT PLAN - REGULATOR RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700081&document_id=5753446

Document Type: Monitoring Reports **Size :** 4,340 KB
Document Date: 1/31/2008 **Submitted By:** CARDNO (AUTH_RP)
Type: MONITORING REPORT - QUARTERLY **Submitted:**
Title: GROUNDWATER MONITORING AND REMEDIATION STATUS REPORT, FOURTH QUARTER 2007
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3133471429/T0609700081.PDF

Document Type: Monitoring Reports **Size :** 4,747 KB

Document Date: 10/19/2007 **Submitted By:** CARDNO (AUTH_RP)
Type: MONITORING REPORT - QUARTERLY **Submitted:**
Title: GROUNDWATER MONITORING AND REMEDIATION STATUS REPORT, THIRD QUARTER 2007
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5698078989/T0609700081.PDF

Document Type: Monitoring Reports **Size :** 4,571 KB
Document Date: 7/27/2007 **Submitted By:** CARDNO (AUTH_RP)
Type: MONITORING REPORT - QUARTERLY **Submitted:**
Title: GROUNDWATER MONITORING AND REMEDIATION STATUS REPORT, SECOND QUARTER 2007
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8685961663/T0609700081.PDF

Document Type: Monitoring Reports **Size :** 4,803 KB
Document Date: 4/3/2007 **Submitted By:** CARDNO (AUTH_RP)
Type: MONITORING REPORT - QUARTERLY **Submitted:**
Title: GROUNDWATER MONITORING AND REMEDIATION STATUS REPORT, FIRST QUARTER 2007
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4779264688/T0609700081.PDF

Document Type: Monitoring Reports **Size :** 9,599 KB
Document Date: 1/30/2007 **Submitted By:** CARDNO (AUTH_RP)
Type: MONITORING REPORT - QUARTERLY **Submitted:**
Title: GROUNDWATER MONITORING AND REMEDIATION STATUS REPORT, FOURTH QUARTER 2006
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4852323770/T0609700081.PDF

Document Type: Site Documents **Size :** 7,078 KB
Document Date: 12/29/2006 **Submitted By:** CARDNO (AUTH_RP)
Type: REPORTS - OTHER **Submitted:**
Title: NOTICE OF INTENT FOR RENEWAL OF AUTHORIZATION TO DISCHARGE TREATED GROUNDWATER
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4287213981/T0609700081.PDF

Document Type: Site Documents **Size :** 787 KB
Document Date: 12/26/2006 **Submitted By:** CARDNO (AUTH_RP)
Type: WORKPLANS - OTHER WP **Submitted:**
Title: TOXICITY REDUCTION EVALUATION WORK PLAN
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3090487420/T0609700081.PDF

Document Type: Monitoring Reports **Size :** 4,026 KB
Document Date: 10/31/2006 **Submitted By:** CARDNO (AUTH_RP)
Type: MONITORING REPORT - QUARTERLY **Submitted:**
Title: GROUNDWATER MONITORING AND REMEDIATION STATUS REPORT, THIRD QUARTER 2006
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2809512078/T0609700081.PDF

Document Type: Site Documents **Size :** 49 KB
Document Date: 10/30/2006 **Submitted By:** CARDNO (AUTH_RP)
Type: CORRESPONDENCE - OTHER **Submitted:**
Title: REQUEST FOR EXTENSION FOR NOTICE OF INTENT, 10-27-06
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7420652627/T0609700081.PDF

Document Type: Site Documents **Size :** 47 KB
Document Date: 9/15/2006 **Submitted By:** CARDNO (AUTH_RP)
Type: CORRESPONDENCE - OTHER **Submitted:**
Title: REQUEST FOR EXTENSION FOR NOTICE OF INTENT, 9-14-06
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9713636100/T0609700081.PDF

Document Type: Monitoring Reports **Size :** 9,782 KB
Document Date: 7/14/2006 **Submitted By:** CARDNO (AUTH_RP)
Type: MONITORING REPORT - QUARTERLY **Submitted:**
Title: GROUNDWATER MONITORING AND REMEDIATION STATUS REPORT, SECOND QUARTER 2006
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4783659219/T0609700081.PDF

Document Type: Monitoring Reports **Size :** 7,509 KB
Document Date: 4/13/2006 **Submitted By:** CARDNO (AUTH_RP)
Type: MONITORING REPORT - QUARTERLY **Submitted:**
Title: GROUNDWATER MONITORING AND REMEDIATION STATUS REPORT, FIRST QUARTER 2006
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7793598771/T0609700081.PDF

Document Type: Monitoring Reports **Size :** 5,808 KB
Document Date: 1/13/2006 **Submitted By:** CARDNO (AUTH_RP)
Type: MONITORING REPORT - QUARTERLY **Submitted:**
Title: GROUNDWATER MONITORING AND REMEMDIATION STATUS REPORT, FOURTH QUARTER 2005

Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3574750602/T0609700081.PDF

Document Type: Monitoring Reports — **Size :** 5,290 KB
Document Date: 10/17/2005 — **Submitted By:** CARDNO (AUTH_RP)
Type: MONITORING REPORT - QUARTERLY — **Submitted:**
Title: GROUNDWATER MONITORING AND REMEDIATION STATUS REPORT, THIRD QUARTER 2005
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5775998771/T0609700081.PDF

Document Type: Monitoring Reports — **Size :** 10,999 KB
Document Date: 7/14/2005 — **Submitted By:** CARDNO (AUTH_RP)
Type: MONITORING REPORT - QUARTERLY — **Submitted:**
Title: GROUNDWATER MONITORING AND REMEDIATION STATUS REPORT, SECOND QUARTER 2005
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6679074943/T0609700081.PDF

Document Type: Monitoring Reports — **Size :** 2,496 KB
Document Date: 4/14/2005 — **Submitted By:** CARDNO (AUTH_RP)
Type: MONITORING REPORT - QUARTERLY — **Submitted:**
Title: GROUNDWATER MONITORING AND REMEDIATION STATUS REPORT, FIRST QUARTER 2005
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3582656681/T0609700081.PDF

Document Type: Monitoring Reports — **Size :** 5,297 KB
Document Date: 4/6/2005 — **Submitted By:** CARDNO (AUTH_RP)
Type: MONITORING REPORT - QUARTERLY — **Submitted:**
Title: GROUNDWATER MONITORING AND REMEDIAL STATUS REPORT, FOURTH QUARTER 2004
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7444547891/T0609700081.PDF

Document Type: Site Documents — **Size :** 48 KB
Document Date: 12/1/2003* — **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT — **Submitted:**
Title: HISTORICAL - REVIEW OF 3Q 2003 REPORT CORRESPONDENCE DATED 12-2003
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8241482079/T0609700081.PDF

Document Type: Site Documents — **Size :** 904 KB
Document Date: 9/30/2003* — **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT — **Submitted:**
Title: HISTORICAL - WATER TREATMENT AND DISCHARGE REPORT DATED 09-2003
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7500285267/T0609700081.PDF

Document Type: Site Documents — **Size :** 60 KB
Document Date: 11/13/2001* — **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT — **Submitted:**
Title: HISTORICAL - REVIEW OF REMEDIAL ACTION PLAN CORRESPONDENCE DATED 11-2001
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2621330976/T0609700081.PDF

Document Type: Site Documents — **Size :** 59 KB
Document Date: 9/10/2001* — **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT — **Submitted:**
Title: HISTORICAL - REVIEW OF CAP CORRESPONDENCE DATED 09-2001
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3497004628/T0609700081.PDF

Document Type: Site Documents — **Size :** 550 KB
Document Date: 7/31/2001* — **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT — **Submitted:**
Title: HISTORICAL - WELL ABANDONMENT REPORT DATED 07-2001
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7018883466/T0609700081.PDF

Document Type: Site Documents — **Size :** 66 KB
Document Date: 6/14/2001* — **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT — **Submitted:**
Title: HISTORICAL - REVIEW OF CAP CORRESPONDENCE DATED 06-2001
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8217336833/T0609700081.PDF

Document Type: Site Documents — **Size :** 50 KB
Document Date: 5/4/2001* — **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT — **Submitted:**
Title: HISTORICAL - REVIEW OF WELL ABANDONMENT WORKPLAN DATED 05-2001
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1442730247/T0609700081.PDF

Document Type: Site Documents — **Size :** 782 KB

Document Date: 4/24/2001* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: HISTORICAL - WELL ABANDONMENT WORKPLAN DATED 04-2001
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2667593181/T0609700081.PDF

Document Type: Site Documents **Size :** 67 KB
Document Date: 2/6/2001* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: HISTORICAL - SITE ASSESSMENT REPORT DATED 02-2001
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2948100209/T0609700081.PDF

Document Type: Site Documents **Size :** 63 KB
Document Date: 10/31/2000* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: HISTORICAL - REVIEW OF WORKPLAN ADDENDUM DATED 10-2000
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9063311994/T0609700081.PDF

Document Type: Site Documents **Size :** 64 KB
Document Date: 10/31/2000* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: HISTORICAL - REVIEW OF SITE ASSESSMENT REPORT DATED 10-2000
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6507057905/T0609700081.PDF

Document Type: Site Documents **Size :** 80 KB
Document Date: 10/24/2000* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: HISTORICAL - ADDENDUM TO SITE ASSESSMENT DATED 10-2000
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7661509633/T0609700081.PDF

Document Type: Site Documents **Size :** 71 KB
Document Date: 12/17/1999* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: HISTORICAL - ADDENDUM TO SITE ASSESSMENT WORKPLAN DATED 12-1999
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8836856305/T0609700081.PDF

Document Type: Site Documents **Size :** 44 KB
Document Date: 11/18/1999* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: HISTORICAL - REVIEW OF WORKPLAN CORRESPONDENCE DATED 11-1999
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6863426923/T0609700081.PDF

Document Type: Site Documents **Size :** 87 KB
Document Date: 8/31/1999* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: HISTORICAL - RESPONSE TO WORKPLAN CORRESPONDENCE DATED 08-1999
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3435280561/T0609700081.PDF

Document Type: Site Documents **Size :** 867 KB
Document Date: 7/15/1999* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: HISTORICAL - 2Q 1999 GWM REPORT DATED 07-1999
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2890971302/T0609700081.PDF

Document Type: Site Documents **Size :** 708 KB
Document Date: 1/15/1999* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: HISTORICAL - 4Q 1998 PROGRESSS REPORT DATED 01-1999
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9881878197/T0609700081.PDF

Document Type: Site Documents **Size :** 35 KB
Document Date: 9/24/1998* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: HISTORICAL - REVIEW OF REMEDIAL ACTION WORKPLAN DATED 09-1998
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9549731671/T0609700081.PDF

Document Type: Site Documents **Size :** 1,589 KB
Document Date: 8/31/1998* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: HISTORICAL - REMEDIAL ACTION WORKPLAN DATED 08-1998

Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3671908795/T0609700081.PDF

Document Type: Site Documents **Size :** 1,133 KB
Document Date: 7/15/1998* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: HISTORICAL - 2Q 1998 PROGRESS REPORT DATED 07-1998
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6875522077/T0609700081.PDF

Document Type: Site Documents **Size :** 40 KB
Document Date: 4/24/1998* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: HISTORICAL - REQUEST FOR WORKPLAN CORRESPONDENCE DATED 04-1998
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6632365345/T0609700081.PDF

Document Type: Site Documents **Size :** 906 KB
Document Date: 4/16/1998* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: HISTORICAL - SUPPLEMENT SITE ASSESSMENT DATED 04-1998
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8451757609/T0609700081.PDF

Document Type: Site Documents **Size :** 1,151 KB
Document Date: 7/15/1997* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: HISTORICAL - 2Q 1997 GWM REPORT DATED 07-1997
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7921093285/T0609700081.PDF

Document Type: Site Documents **Size :** 800 KB
Document Date: 7/15/1996* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: HISTORICAL - 2Q 1996 GWM REPORT DATED 07-1996
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1408989667/T0609700081.PDF

Document Type: Site Documents **Size :** 486 KB
Document Date: 5/16/1995* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: HISTORICAL - 1Q 1995 GWM REPORT DATED 05-1995
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8975411176/T0609700081.PDF

Document Type: Site Documents **Size :** 581 KB
Document Date: 2/7/1995* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: HISTORICAL - 4Q 1994 GWM REPORT DATED 02-1995
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1937801659/T0609700081.PDF

Document Type: Site Documents **Size :** 575 KB
Document Date: 11/1/1994* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: HISTORICAL - 3Q 1994 GWM REPORT DATED 11-1994
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3681194603/T0609700081.PDF

Document Type: Site Documents **Size :** 611 KB
Document Date: 5/18/1994* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: HISTORICAL - 1Q 1994 GWM REPORT DATED 05-1994
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8657367169/T0609700081.PDF

Document Type: Site Documents **Size :** 362 KB
Document Date: 1/17/1994* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: HISTORICAL - 1Q 1993 GWM REPORT DATED 01-1994
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8670952558/T0609700081.PDF

Document Type: Site Documents **Size :** 353 KB
Document Date: 10/29/1993* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: HISTORICAL - 3Q 1993 GWM REPORT DATED 10-1993
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8058147728/T0609700081.PDF

Document Type: Site Documents **Size :** 1,227 KB

Document Date: 7/27/1993* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: HISTORICAL - 2Q1993 GWM REPORT DATED 07-1993
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6616198062/T0609700081.PDF

Document Type: Site Documents **Size :** 555 KB
Document Date: 4/14/1993* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: HISTORICAL - 1Q 1993 GWM REPORT DATED 04-1993
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8256038963/T0609700081.PDF

Document Type: Site Documents **Size :** 250 KB
Document Date: 1/12/1993* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: HISTORICAL - 4Q1992 GWM REPORT DATED 01-1993
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5266384422/T0609700081.PDF

Document Type: Site Documents **Size :** 32 KB
Document Date: 6/2/1992* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: HISTORICAL - REVIEW OF WORK PLAN CORRESPONDENCE DATED 06-1992
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6218941450/T0609700081.PDF

Document Type: Site Documents **Size :** 655 KB
Document Date: 5/22/1992* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: HISTORICAL - WORK PLAN FOR ENVIRONMENTAL SERVICES DATED 05-1992
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4256920576/T0609700081.PDF

Document Type: Site Documents **Size :** 21 KB
Document Date: 4/22/1992* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: HISTORICAL - DIRECTIVE FOR CORRECTIVE ACTION DATED 04-1992
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7138644635/T0609700081.PDF

Document Type: Site Documents **Size :** 29 KB
Document Date: 1/31/1992* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: HISTORICAL - REVIEWAL OF WORK PLAN CORRESPONDENCE DATED 01-1992
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8680713117/T0609700081.PDF

Document Type: Site Documents **Size :** 34 KB
Document Date: 10/21/1991* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: HISTORICAL - REVIEW OF WORKPLAN CORRESPONDENCE DATED 10-1991
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3375637352/T0609700081.PDF

Document Type: Site Documents **Size :** 171 KB
Document Date: 10/17/1991* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: HISTORICAL - WORK PLAN DATED 10-1991
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6202968895/T0609700081.PDF

Document Type: Site Documents **Size :** 24 KB
Document Date: 10/2/1991* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: 1991-10-02 HISTORICAL - DIRECTIVE FOR CORRECTIVE ACTION DATED 10-1991
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3636256337/T0609700081.PDF

Document Type: Site Documents **Size :** 136 KB
Document Date: 11/5/1990* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: \HISTORICAL - ADDENDUM TO PRELIMINARY SITE ASSESSMENT WORKPLAN DATED 11-1990
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9319895863/T0609700081.PDF

Document Type: Site Documents **Size :** 35 KB
Document Date: 10/17/1990* **Submitted By:** PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT **Submitted:**
Title: 1990-10-17 HISTORICAL - REVIEW OF PRELIMINARY SITE ASSESSMENT WORKPLAN DATED 10-1990

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9541766583/T0609700081.PDF

Document Type: Site Documents
Size : 1,376 KB
Document Date: 3/15/1990*
Submitted By: PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT
Submitted:
Title: 1990-03-15 HISTORICAL - PRELIMINARY SITE ASSESSMENT WORKPLAN DATED 03-1990
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7542307972/T0609700081.PDF

Document Type: Site Documents
Size : 23 KB
Document Date: 12/1/1989*
Submitted By: PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT
Submitted:
Title: 1989-12-01 HISTORICAL - DIRECTIVE FOR CORRECTIVE ACTION AND NOR DATED 12-1989
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7097985029/T0609700081.PDF

Document Type: Site Documents
Size : 39 KB
Document Date: 3/17/1987*
Submitted By: PINNACLE EMS (CONTRACTOR)
Type: OTHER REPORT / DOCUMENT
Submitted:
Title: HISTORICAL - URR DATED 03-1987
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3890315175/T0609700081.PDF

10	6 of 13	NW	0.03 / 142.75	114.50 / -5	SHILOH UNION 76 GAS STATION 705 SHILOH ROAD WINDSOR, CA 95492- CA	DELISTED COUNTY

Original Source Facility ID:
Original Source Name: Sonoma County CUPA Facilities List
Record Date: 11-JAN-2016

10	7 of 13	NW	0.03 / 142.75	114.50 / -5	Windsor Valero 705 SHILOH RD WINDSOR CA 95492	CERS TANK

Site ID: 387408
Latitude: 38.526115
Longitude: -122.792747

Regulated Programs

EI ID: 10485172
EI Description: Chemical Storage Facilities

EI ID: 10485172
EI Description: Underground Storage Tank

EI ID: 10485172
EI Description: Hazardous Waste Generator

Violations

Violation Date: 08/17/2017
Violation Source: CERS
Violation Program: UST
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: 23 CCR 16 2715(e) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2715(e)
Violation Notes:

Returned to compliance on 08/29/2017. The designated operator monthly reports for September and December 2016 were not available. The designated operator for the business changed in January 2017 due to issues and the D/O reports for September and December 2016 cannot be provided or duplicated. This violation cannot be corrected and is only being documented.

Violation Description:

Failure to maintain a copy of the designated operator monthly inspections for the last 12 months on-site or off-site at a readily available location, if approved by the UPA.

Violations

Violation Date: 08/17/2016 ***Violation Source:*** CERS
Violation Program: UST ***Violation Division:*** Sonoma County Fire & Emergency Services Department
Citation: 23 CCR 16 2715(i) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2715(i)
Violation Notes:

Returned to compliance on 08/17/2016. Facility failed to conduct annual monitoring certification testing in September, 2015.

Violation Description:

Failure to have a properly qualified service technician test leak detection equipment as required every 12 months (vapor, pressure, hydrostatic (VPH) system, sensors, line-leak detectors (LLD), automatic tank gauge (ATG), etc.).

Violations

Violation Date: 08/17/2016 ***Violation Source:*** CERS
Violation Program: UST ***Violation Division:*** Sonoma County Fire & Emergency Services Department
Citation: 23 CCR 16 2715(i) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2715(i)
Violation Notes:

Returned to compliance on 08/17/2016. Failure to test leak detection equipment as required every 12 months (VPH, sensor, LLD, ATG, etc.) and/or submit monitoring system certification to the CUPA within 30 days of completion of the test Test leak detection equipment as required every 12 months (VPH, sensor, LLD, ATG, etc.) and/or submit monitoring system certification to the CUPA within 30 days of completion of the test

Violation Description:

Failure to have a properly qualified service technician test leak detection equipment as required every 12 months (vapor, pressure, hydrostatic (VPH) system, sensors, line-leak detectors (LLD), automatic tank gauge (ATG), etc.).

Violations

Violation Date: 09/01/2020 ***Violation Source:*** CERS
Violation Program: UST ***Violation Division:*** Sonoma County Fire & Emergency Services Department
Citation: 23 CCR 16 2715(c)(4) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2715(c)(4)
Violation Notes:

Returned to compliance on 02/23/2021. Owner/Operator did not maintain a list of employees trained by the DO, or for training that occurs on or after 10/1/18, failure to maintain a copy of the "Facility Employee Training Certificate". Maintain list of employees trained by the DO and copies of "Facility Employee Training Certificate" for training that occurs on or after 10/1/18.

Violation Description:

Failure to maintain a list of employees trained by the designated operator on-site or off-site at a readily available location, if approved by the UPA. For training that occurs on or after October 1, 2018, failure to maintain a copy of the "Facility Employee Training Certificate" on-site or off-site at a readily available location, if approved by the UPA.

Violations

Violation Date: 08/22/2017 ***Violation Source:*** CERS
Violation Program: UST ***Violation Division:*** Sonoma County Fire & Emergency Services Department
Citation: 23 CCR 16 2715(e) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2715(e)
Violation Notes:

Returned to compliance on 12/05/2017. The D/O reports for September and December 2016 were missing. Maintain DO inspections for 12 months.

Violation Description:

Failure to maintain a copy of the designated operator monthly inspections for the last 12 months on-site or off-site at a readily available location, if approved by the UPA.

Violations

Violation Date: 08/17/2016
Violation Source: CERS
Violation Program: HMRRP
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: HSC 6.95 25507 - California Health and Safety Code, Chapter 6.95, Section(s) 25507
Violation Notes:

Returned to compliance on 08/22/2017. Failure to provide complete and accurate HMBP and UST documentation in CERS.

Violation Description:

Failure to adequately establish and implement a business plan when storing/handling a hazardous material at or above reportable quantities.

Violations

Violation Date: 08/17/2016
Violation Source: CERS
Violation Program: UST
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: 23 CCR 16 2641(j) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2641(j)
Violation Notes:

Returned to compliance on 08/17/2016. Diesel turbine sump sensor failed, was replaced and retested with passing results at time of inspection.

Violation Description:

Failure of the leak detection equipment to be installed, calibrated, operated, and/or maintained properly.

Violations

Violation Date: 08/29/2013
Violation Source: CERS
Violation Program: UST
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: 23 CCR 16 2637(e) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2637(e)
Violation Notes:

Returned to compliance on 09/16/2013.

Violation Description:

Failure to submit a copy of the secondary containment test results to the CUPA within 30 days after the test.

Violations

Violation Date: 08/20/2018
Violation Source: CERS
Violation Program: UST
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: 23 CCR 16 2636(f)(1) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)(1)
Violation Notes:

Returned to compliance on 09/12/2018. Audible and visual alarms not working Repair alarms

Violation Description:

Failure of the leak detection equipment to have an audible and visual alarm as required.

Violations

Violation Date: 08/17/2017 ***Violation Source:*** CERS
Violation Program: UST ***Violation Division:*** Sonoma County Fire & Emergency Services Department
Citation: 23 CCR 16 2641(j) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2641(j)
Violation Notes:

Returned to compliance on 10/02/2017. The vent transition lid could not be removed during the annual monitoring certification. The vent sump sensor, double walled vent sump liquid sensor and vacuum continuity could not be tested due to the vent lid issue. Repair or replace the vent transition lid.

Violation Description:

Failure of the leak detection equipment to be installed, calibrated, operated, and/or maintained properly.

Violations

Violation Date: 08/17/2016 ***Violation Source:*** CERS
Violation Program: UST ***Violation Division:*** Sonoma County Fire & Emergency Services Department
Citation: HSC 6.75 25299.30-25299.34 - California Health and Safety Code, Chapter 6.75, Section(s) 25299.30-25299.34
Violation Notes:

Returned to compliance on 09/13/2016. Failure to submit and maintain complete and current Certification of Financial Responsibility or other mechanism of financial assurance Submit and maintain complete and current Certification of Financial Responsibility or other mechanism of financial assurance

Violation Description:

Failure to submit and maintain complete and current Certification of Financial Responsibility or other mechanism of financial assurance.

Violations

Violation Date: 08/17/2016 ***Violation Source:*** CERS
Violation Program: UST ***Violation Division:*** Sonoma County Fire & Emergency Services Department
Citation: 23 CCR 16 2715(f) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2715(f)
Violation Notes:

Returned to compliance on 09/12/2016. Training record provided.

Violation Description:

Failure to have at least one employee present during operating hours that has been trained in the proper operation and maintenance of the UST system by a designated operator (DO).

Violations

Violation Date: 08/17/2016 ***Violation Source:*** CERS
Violation Program: UST ***Violation Division:*** Sonoma County Fire & Emergency Services Department
Citation: 23 CCR 16 2715(e) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2715(e)
Violation Notes:

Returned to compliance on 09/10/2016. The owner/operator has failed to comply with one or more of the following: to maintain a copy of the designated operator monthly inspections for the last 12 months and/or maintain a list of trained employees on-site or off-site at a readily available location. Maintain a copy of the designated operator monthly inspections for the last 12 months and maintain a list of trained employees on-site or off-site at a readily available location

Violation Description:

Failure to maintain a copy of the designated operator monthly inspections for the last 12 months on-site or off-site at a readily available location, if approved by the UPA.

Violations

Violation Date: 08/22/2017
Violation Source: CERS
Violation Program: UST
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: HSC 6.75 25299.30-25299.34 - California Health and Safety Code, Chapter 6.75, Section(s) 25299.30-25299.34
Violation Notes:

Returned to compliance on 08/24/2017. Complete and submit a copy of the financial responsibility by September 22, 2017.

Violation Description:

Failure to submit and maintain complete and current Certification of Financial Responsibility or other mechanism of financial assurance.

Violations

Violation Date: 08/17/2016
Violation Source: CERS
Violation Program: UST
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: 23 CCR 16 2715(e) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2715(e)
Violation Notes:

Returned to compliance on 09/10/2016. Missing monthly D/O reports for July and April, 2016.

Violation Description:

Failure to maintain a copy of the designated operator monthly inspections for the last 12 months on-site or off-site at a readily available location, if approved by the UPA.

Evaluations

Eval Date: 08/20/2018
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

No violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 08/14/2019
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: UST
Eval Source: CERS
Eval Notes:

See handwritten inspection copy; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 07/07/2017
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Conducted review of CERS and inspected Propane tank and training. No violations observed.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 09/12/2018
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: UST
Eval Source: CERS
Eval Notes:

All violations corrected; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 08/17/2016
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: UST
Eval Source: CERS
Eval Notes:

VPH system - all systems passed as required except diesel fill sump sensor (replaced, retested and passed at time of inspection); DO log reviewed - missing July & April reports and employee training has not been done since 1/15/2015.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 08/17/2017
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

No violations were observed during the inspection.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 08/22/2017
Violations Found: Yes
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: UST
Eval Source: CERS
Eval Notes:

The vent transition sump lid was stuck on and could not be removed for the inspection and testing of the vent transition sump sensors. Make repairs and test vent transition sump sensors. The clam shell from the secondary to primary product piping at UDC 7/8 did not have valves to test the continuity vacuum in this section of lines. Install valves on each clam shell to provide a way to test the vacuum and continuity.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 08/17/2016
Violations Found: Yes
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Incomplete CERS submittal of HMBP and UST documentation.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 08/17/2017
Violations Found: No
Eval General Type: Other/Unknown

Eval Type: Other, not routine, done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

No violations observed during the inspection.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 08/20/2018
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

No violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 07/07/2017
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: UST
Eval Source: CERS
Eval Notes:

Witnessed the proper operation of the Diesel STP sump sensor. All functions normal.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 09/13/2016
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: UST
Eval Source: CERS
Eval Notes:

Eval Date: 08/17/2017
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: UST
Eval Source: CERS
Eval Notes:

The vacuum continuity could not be confirmed in the product lines in UDC 7/8, no valves. Valves are required to be installed.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 09/16/2013
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: UST
Eval Source: CERS
Eval Notes:

Eval Date: 10/02/2013
Violations Found: No
Eval General Type: Compliance Evaluation Inspection

Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: UST
Eval Source: CERS
Eval Notes:

Eval Date: 09/15/2014
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Eval Date: 08/20/2018
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: UST
Eval Source: CERS
Eval Notes:

Eval Date: 09/01/2020
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: UST
Eval Source: CERS
Eval Notes:

Provide employee training records; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 02/23/2021
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: UST
Eval Source: CERS
Eval Notes:

Training record violation corrected; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 08/29/2013
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: UST
Eval Source: CERS
Eval Notes:

Eval Date: 09/15/2014
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: UST
Eval Source: CERS
Eval Notes:

Affiliations

Affil Type Desc: Operator
Entity Name: Salkhi Petroleum Inc
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone: (415) 710-4004

Affil Type Desc: Environmental Contact
Entity Name: Arash Salkhi
Entity Title:
Address: PO BOX 1678
City: San Leandro
State: CA
Country:
Zip Code: 94577
Phone:

Affil Type Desc: Document Preparer
Entity Name: Stantec Consulting Services Inc.
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: UST Property Owner Name
Entity Name: 705 Shiloh Rd Windsor LLC
Entity Title:
Address: PO BOX 1678
City: San Leandro
State: CA
Country: United States
Zip Code: 94577
Phone: (415) 710-4004

Affil Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title:
Address: PO BOX 1678
City: San Leandro
State: CA
Country:
Zip Code: 94577
Phone:

Affil Type Desc: Identification Signer
Entity Name: Arash Salkhi
Entity Title: Operations
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Legal Owner
Entity Name: Salkhi Petroleum Inc
Entity Title:
Address: PO BOX 1678
City: San Leandro

State: CA
Country: United States
Zip Code: 94577
Phone: (415) 710-4004

Affil Type Desc: UST Tank Owner
Entity Name: 705 Shiloh Rd Windsor LLC
Entity Title:
Address: PO BOX 1678
City: San Leandro
State: CA
Country: United States
Zip Code: 94577
Phone: (415) 710-4004

Affil Type Desc: CUPA District
Entity Name: Sonoma County Fire Prevention and Hazmat
Entity Title:
Address: 2300 County Center Drive, Suite 220-B
City: Santa Rosa
State: CA
Country:
Zip Code: 95403
Phone: (707) 565-2024

Affil Type Desc: UST Tank Operator
Entity Name: Salkhi Petroleum, Inc.
Entity Title:
Address: PO BOX 1678
City: San Leandro
State: CA
Country: United States
Zip Code: 94577
Phone: (415) 710-4004

Affil Type Desc: Parent Corporation
Entity Name: Salkhi Petroleum, Inc
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Property Owner
Entity Name: 705 Shiloh Rd Windsor
Entity Title:
Address: PO BOX 1678
City: San Leandro
State: CA
Country: United States
Zip Code: 94577
Phone: (415) 710-4004

Coordinates

Env Int Type Code: HMBP
Program ID: 10485172
Latitude: 38.527230
Longitude: -122.792750
Coord Name:
Ref Point Type Desc: Center of a facility or station.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
10	8 of 13	NW	0.03 / 142.75	114.50 / -5	Windsor Valero 705 Shiloh Rd Windsor CA 95492	UST

Facility ID: 49-000-007981
CERS ID: 10485172
Latitude: 38.52723
Longitude: -122.79275

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

County: Sonoma
Permitting Agency: Sonoma County Fire & Emergency Services Department
Note: Information related to facilities can be searched on Geo Tracker Website: https://geotracker.waterboards.ca.gov/search
Site Facility Type: PERMITTED UNDERGROUND STORAGE TANK (UST)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
10	9 of 13	NW	0.03 / 142.75	114.50 / -5	FORMER MOBIL STATION 99-HLH C/ 705 SHILOH ROAD WINDSOR CA 95492	EMISSIONS

2004 Criteria Data

Facility ID: 13618
Facility SIC Code: 4953
CO: 49
Air Basin: SF
District: BA
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:
TOGT: .068
ROGT: .0475048
COT:
NOXT:
SOXT:
PMT:
PM10T:

2004 Toxic Data

Facility ID: 13618
Facility SIC Code: 4953
CO: 49
Air Basin: SF
District: BA
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:

2005 Criteria Data

Facility ID: 13618
Facility SIC Code: 4953
CO: 49
Air Basin: SF
District: BA
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:
TOGT: .371
ROGT: .2591806
COT:
NOXT:
SOXT:
PMT:
PM10T:

2005 Toxic Data

Facility ID: 13618
Facility SIC Code: 4953
CO: 49
Air Basin: SF
District: BA
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:

2006 Criteria Data

Facility ID: 13618
CERR Code:

Facility SIC Code:	4953	**TOGT:**	.391
CO:	49	**ROGT:**	.2731526
Air Basin:	SF	**COT:**	
District:	BA	**NOXT:**	
COID:	SON	**SOXT:**	
DISN:	BAY AREA AQMD	**PMT:**	
CHAPIS:		**PM10T:**	

2006 Toxic Data

Facility ID:	13618	**COID:**	SON
Facility SIC Code:	4953	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2007 Criteria Data

Facility ID:	13618	**CERR Code:**	
Facility SIC Code:	4953	**TOGT:**	.391
CO:	49	**ROGT:**	.2731526
Air Basin:	SF	**COT:**	
District:	BA	**NOXT:**	
COID:	SON	**SOXT:**	
DISN:	BAY AREA AQMD	**PMT:**	
CHAPIS:		**PM10T:**	

2007 Toxic Data

Facility ID:	13618	**COID:**	SON
Facility SIC Code:	4953	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

---

10 | ***10 of 13*** | ***NW*** | ***0.03 / 142.75*** | ***114.50 / -5*** | ***EXXONMOBIL OIL CORPORATION #99HLH 705 SHILOH RD WINDSOR CA 95492-0000*** | ***RCRA NON GEN***

EPA Handler ID:	CAL921054218
Gen Status Universe:	No Report
Contact Name:	DONNA HYMES
Contact Address:	800 E. WASHINGTON STREET , , WEST CHESTER , PA, 19380 ,
Contact Phone No and Ext:	610-430-8151
Contact Email:	DHYMES@JD2ENV.COM
Contact Country:	
County Name:	SONOMA
EPA Region:	09
Land Type:	
Receive Date:	19920414
Location Latitude:	38.525808
Location Longitude:	-122.792974

Violation/Evaluation Summary

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19920414
Handler Name:	EXXONMOBIL OIL CORPORATION #99HLH
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Other	**Street 1:**	800 E. WASHINGTON STREET
Name:	DONNA HYMES	**Street 2:**	
Date Became Current:		**City:**	WEST CHESTER
Date Ended Current:		**State:**	PA
Phone:	610-430-8151	**Country:**	
Source Type:	Implementer	**Zip Code:**	19380
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Other	**Street 1:**	5959 LAS COLINAS BOULEVARD
Name:	EXXONMOBIL OIL CORPORATION	**Street 2:**	
Date Became Current:		**City:**	IRVING
Date Ended Current:		**State:**	TX
Phone:	972-444-1000	**Country:**	
Source Type:	Implementer	**Zip Code:**	75039-4202

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
10	11 of 13	NW	0.03 / 142.75	114.50 / -5	B&B SERVICE STATION 705 SHILOH RD WINDSOR CA 95492	RCRA NON GEN

EPA Handler ID:	CAL000395131
Gen Status Universe:	No Report
Contact Name:	MITRI H SHAMI
Contact Address:	3647 RUTHERFORD WAY , , SANTA ROSA , CA, 95404-0000 ,
Contact Phone No and Ext:	707-888-1156
Contact Email:	VALEROSHILOH@YAHOO.COM
Contact Country:	
County Name:	SONOMA
EPA Region:	09
Land Type:	
Receive Date:	20140319
Location Latitude:	38.525808

Location Longitude: -122.792974

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20140319
Handler Name: B&B SERVICE STATION
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Other
Name: MITRI H SHAMI
Date Became Current:
Date Ended Current:
Phone: 707-888-1156
Source Type: Implementer
Street No:
Street 1: 3647 RUTHERFORD WAY
Street 2:
City: SANTA ROSA
State: CA
Country:
Zip Code: 95404-0000

Owner/Operator Ind: Current Owner
Type: Other
Name: MITRI H SHAMI
Date Became Current:
Date Ended Current:
Phone: 707-888-1156
Source Type: Implementer
Street No:
Street 1: 3647 RUTHERFORD WAY
Street 2:
City: SANTA ROSA
State: CA
Country:
Zip Code: 95404-0000

10	12 of 13	NW	0.03 / 142.75	114.50 / -5	B & B SERVICE STATION 705 SHILOH RD WINDSOR CA 95492	EMISSIONS

2017 Criteria Data

Facility ID: 200007
Facility SIC Code: 5411
CO: 49
CERR Code:
TOGT: .30404623
ROGT: .30404623

Air Basin:	SF	**COT:**	
District:	BA	**NOXT:**	
COID:	SON	**SOXT:**	
DISN:	BAY AREA AQMD	**PMT:**	
CHAPIS:		**PM10T:**	

2017 Toxic Data

Facility ID:	200007	**COID:**	SON
Facility SIC Code:	5411	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2018 Criteria Data

Facility ID:	200007	**CERR Code:**	
Facility SIC Code:	5541	**TOGT:**	.304203582
CO:	49	**ROGT:**	.3040608794712
Air Basin:	SF	**COT:**	.000074535
District:	BA	**NOXT:**	.000015528
COID:	SON	**SOXT:**	.000000329
DISN:	BAY AREA AQMD	**PMT:**	.00001049798792756539235412474849094567404427
CHAPIS:		**PM10T:**	.000010435

2018 Toxic Data

Facility ID:	200007	**COID:**	SON
Facility SIC Code:	5541	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2019 Criteria Data

CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
Facility ID:	200007	**ROGT:**	.0000026022381
District:	BA	**COT:**	.000074535
Facility SIC Code:	5541	**NOXT:**	.000015531
CO ID:	SON	**SOXT:**	.000000328
DISN:	BAY AREA AQMD		
PM10T:	.000010442		
TOGT:	.000027951		
PMT:	.000010877		

2019 Toxic Data

CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
Faccility ID:	200007	**TS:**	
District:	BA	**Health Risk Asmt:**	
Facility SIC Code:	5541	**NonCncrChrnicHazInd**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

COID: SON
DISN: BAY AREA AQMD
:
NonCncrActeHazInd:

---

10 | **13 of 13** | **NW** | **0.03 / 142.75** | **114.50 / -5**

SALKHI PETROLEUM INC DBA
WINDSOR CHEVRON
705 SHILOH RD
WINDSOR CA 95492

RCRA NON GEN

EPA Handler ID: CAL000449206
Gen Status Universe: No Report
Contact Name: ARASH SALKHI
Contact Address: 705 SHILOH RD , , WINDSOR , CA, 95492 ,
Contact Phone No and Ext: 415-710-4004
Contact Email: ASALKHI@SALKHI.COM
Contact Country:
County Name: SONOMA
EPA Region: 09
Land Type:
Receive Date: 20190924
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20190924
Handler Name: SALKHI PETROLEUM INC DBA WINDSOR CHEVRON
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Other
Name: ARASH SALKHI
Date Became Current:
Date Ended Current:
Phone: 415-710-4004

Street No:
Street 1: 705 SHILOH RD
Street 2:
City: WINDSOR
State: CA
Country:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Source Type:	Implementer	**Zip Code:**	95492
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Other	**Street 1:**	PO BOX 1678
Name:	SALKHI PETROLEUM INC	**Street 2:**	
Date Became Current:		**City:**	SAN LEANDRO
Date Ended Current:		**State:**	CA
Phone:	415-710-4004	**Country:**	
Source Type:	Implementer	**Zip Code:**	94577

11	1 of 5	SSW	0.04 / 227.62	119.01 / -1	500 caletti ave WINDSOR CA	HMIRS

Incident County: SONOMA

HMIR Historical Reports

Report No:	X-2010010088	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	01/11/2010	**Report Submit Src:**	XML
Time of Incident:	0700	**Inc Multiple Rows:**	No
Haz Class Code:	8	**Inc Non US State:**	
Hazardous Class:	CORROSIVE MATERIAL	**Mode Transport:**	Highway
Commodity Short Nm:	SODIUM HYDROXIDE SOLUTI	**Transport Phase:**	UNLOADING
Commodity Long Nm:	SODIUM HYDROXIDE SOLUTION	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1824	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.264180	**CR Street Name:**	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	**CR City:**	CORAOPOLIS
What Failed:	117	**CR State:**	PA
What Failed Desc:	Fill Hole	**CR Postal Code:**	15108-9373
How Failed Code:	308	**CR Non US State:**	
How Failed Desc:	Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	526	**CR Hazmat Reg ID:**	051909552054R
Failure Cause Desc:	Loose Closure Component or Device	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	RICCA CHEMICAL COMPANY LLC
Cont1 Pkging Type:	Box	**Shipper Street Name:**	448 W FORK DR
Cont1 Const Mat:	Fiberboard	**Shipper City:**	ARLINGTON
Cont1 Head Type:		**Shipper State:**	TX
Cont1 Pkg Capacity:		**Shipper Postal:**	76012-3449
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:		**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	28376135066645
Cont1 Pkg No:		**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:		**Origin City:**	ARLINGTON
Cont1 Pkg Mnfctr:		**Origin State:**	TEXAS
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	76012
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:	Fiberboard	**Destination City:**	SANTA ROSA
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95401
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	Bottle
C1 Head Thick UOM:		**Cont2 Const Mat:**	Plastic
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	
C1 Device Model:		**Cont2 Pkg No Failed:**	

NRC No:

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:		**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	TRAVIS MCEWEN
Damage > 500:	No	**Contact Title:**	SAFETY SPECIALIST III - HAZMAT
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2013090103	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	08/13/2013	**Report Submit Src:**	XML
Time of Incident:	0435	**Inc Multiple Rows:**	No
Haz Class Code:	3	**Inc Non US State:**	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID	**Mode Transport:**	Highway
Commodity Short Nm:	HEXANES	**Transport Phase:**	UNLOADING
Commodity Long Nm:	HEXANES	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1208	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk

HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	1.056720	**CR Street Name:**	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	**CR City:**	CORAOPOLIS
What Failed:	104	**CR State:**	PA
What Failed Desc:	Body	**CR Postal Code:**	15108-9373
How Failed Code:	304	**CR Non US State:**	
How Failed Desc:	Cracked	**CR Fed DOT ID:**	265752
Failure Cause Code:	517	**CR Hazmat Reg ID:**	051910551007S
Failure Cause Desc:	Improper Preparation for Transportation	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	SEOH CORPORATION
Cont1 Pkging Type:	Box	**Shipper Street Name:**	808 FARQUHAR ST
Cont1 Const Mat:	Fiberboard	**Shipper City:**	NAVASOTA
Cont1 Head Type:		**Shipper State:**	TX
Cont1 Pkg Capacity:		**Shipper Postal:**	77868-3840
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:		**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	530781315178245
Cont1 Pkg No:		**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:		**Origin City:**	NAVASOTA
Cont1 Pkg Mnfctr:		**Origin State:**	TEXAS
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	77868
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:	Fiberboard	**Destination City:**	LARKFIELD
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95403
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	Bottle
C1 Head Thick UOM:		**Cont2 Const Mat:**	
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	
C1 Device Model:		**Cont2 Pkg No Failed:**	
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:		**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	No	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	GEORGE FETSKO
Damage > 500:	No	**Contact Title:**	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	Moon Township
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108

Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2009100107	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	09/15/2009	**Report Submit Src:**	XML
Time of Incident:	0500	**Inc Multiple Rows:**	No
Haz Class Code:	2.2	**Inc Non US State:**	
Hazardous Class:	NONFLAMMABLE COMPRESSED GAS	**Mode Transport:**	Highway
Commodity Short Nm:	FIRE EXTINGUISHERS CONTA	**Transport Phase:**	UNLOADING
Commodity Long Nm:	FIRE EXTINGUISHERS CONTAINING COMPRESSED OR LIQUEFIED GAS	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1044	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	2	**CR Street Name:**	1000 FED EX DR
Unit of Measure:	Solid - Pound	**CR City:**	CORAOPOLIS
What Failed:	128	**CR State:**	PA
What Failed Desc:	Inner Packaging	**CR Postal Code:**	15108-9373
How Failed Code:	303	**CR Non US State:**	
How Failed Desc:	Burst or Ruptured	**CR Fed DOT ID:**	265752
Failure Cause Code:	526	**CR Hazmat Reg ID:**	062904001002M
Failure Cause Desc:	Loose Closure Component or Device	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	FIRST ALERT
Cont1 Pkging Type:	Box	**Shipper Street Name:**	25 SPUR DR
Cont1 Const Mat:	Fiberboard	**Shipper City:**	EL PASO
Cont1 Head Type:		**Shipper State:**	TX
Cont1 Pkg Capacity:		**Shipper Postal:**	79906-5310
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:		**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	79909930365503
Cont1 Pkg No:		**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:		**Origin City:**	EL PASO
Cont1 Pkg Mnfctr:		**Origin State:**	TEXAS
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	79906
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:	Fiberboard	**Destination City:**	COTATI
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	94931
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	Cylinder
C1 Head Thick UOM:		**Cont2 Const Mat:**	Metal (any type)

C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	
C1 Device Model:		**Cont2 Pkg No Failed:**	
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:		**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	TRAVIS MCEWEN
Damage > 500:	No	**Contact Title:**	SAFETY SPECIALIST III - HAZMAT
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the Fire Extinguisher(s) had a loose pin(s) with allowed leakage. The pin(s) were secured. The package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2010020180	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	02/18/2010	**Report Submit Src:**	XML
Time of Incident:	0600	**Inc Multiple Rows:**	No
Haz Class Code:	5.1	**Inc Non US State:**	
Hazardous Class:	OXIDIZER	**Mode Transport:**	Highway

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Commodity Short Nm:	HYDROGEN PEROXIDE AND PE	**Transport Phase:**	UNLOADING
Commodity Long Nm:	HYDROGEN PEROXIDE AND PEROXYACETIC ACID MIXTURES STABILIZED WITH ACIDS WATER AND NOT MORE THAN 5 PERCENT PEROXYACETIC ACID	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN3149	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	Yes
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.01	**CR Street Name:**	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	**CR City:**	CORAOPOLIS
What Failed:	109	**CR State:**	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	**CR Postal Code:**	15108-9373
How Failed Code:	308	**CR Non US State:**	
How Failed Desc:	Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	522	**CR Hazmat Reg ID:**	051909552054R
Failure Cause Desc:	Inadequate Procedures	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	VETERINARY SERVICE INC.
Cont1 Pkging Type:	Box	**Shipper Street Name:**	1731 W 16TH ST
Cont1 Const Mat:	Fiberboard	**Shipper City:**	MERCED
Cont1 Head Type:		**Shipper State:**	CA
Cont1 Pkg Capacity:		**Shipper Postal:**	95348-4353
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:		**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	571218360401174
Cont1 Pkg No:		**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:		**Origin City:**	MERCED
Cont1 Pkg Mnfctr:		**Origin State:**	CALIFORNIA
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	95340
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:	Fiberboard	**Destination City:**	PETALUMA
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	94952
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	Can
C1 Head Thick UOM:		**Cont2 Const Mat:**	Plastic
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	
C1 Device Model:		**Cont2 Pkg No Failed:**	
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:		**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No

Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	TRAVIS MCEWEN
Damage > 500:	No	**Contact Title:**	SAFETY SPECIALIST III - HAZMAT
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	Yes

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2016010089	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	12/11/2015	**Report Submit Src:**	XML
Time of Incident:	0400	**Inc Multiple Rows:**	No
Haz Class Code:	8	**Inc Non US State:**	
Hazardous Class:	CORROSIVE MATERIAL	**Mode Transport:**	Highway
Commodity Short Nm:	ACETIC ACID GLACIAL OR	**Transport Phase:**	UNLOADING
Commodity Long Nm:	ACETIC ACID GLACIAL OR ACETIC ACID SOLUTION WITH MORE THAN 80 PERCENT ACID BY MASS	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN2789	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.007812	**CR Street Name:**	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	**CR City:**	CORAOPOLIS
What Failed:	109	**CR State:**	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	**CR Postal Code:**	15108-9373
How Failed Code:	308	**CR Non US State:**	
How Failed Desc:	Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	526	**CR Hazmat Reg ID:**	051910551007S
Failure Cause Desc:	Loose Closure Component or Device	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	GELSHMAL ENTERPRISES LLC
Cont1 Pkging Type:	Box	**Shipper Street Name:**	945 W HYDE PARK BLVD
Cont1 Const Mat:	Fiberboard	**Shipper City:**	INGLEWOOD
Cont1 Head Type:		**Shipper State:**	CA
Cont1 Pkg Capacity:		**Shipper Postal:**	90302-3307
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:		**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	164785621564825494
Cont1 Pkg No:		**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:		**Origin City:**	INGLEWOOD

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Cont1 Pkg Mnfctr:		**Origin State:**	CALIFORNIA
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	90302
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:	Fiberboard	**Destination City:**	SANTA ROSA
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95401
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	Bottle
C1 Head Thick UOM:		**Cont2 Const Mat:**	Plastic
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	
C1 Device Model:		**Cont2 Pkg No Failed:**	
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:		**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	GEORGE FETSKO
Damage > 500:	No	**Contact Title:**	HAZMAT - SAFETY ADVISOR
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	CORAOPOLIS
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2015070444	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	07/08/2015	***Report Submit Src:***	XML
Time of Incident:	0635	***Inc Multiple Rows:***	No
Haz Class Code:	5.1	***Inc Non US State:***	
Hazardous Class:	OXIDIZER	***Mode Transport:***	Highway
Commodity Short Nm:	HYDROGEN PEROXIDE AND PE	***Transport Phase:***	UNLOADING
Commodity Long Nm:	HYDROGEN PEROXIDE AND PEROXYACETIC ACID MIXTURES STABILIZED WITH ACIDS WATER AND NOT MORE THAN 5 PERCENT PEROXYACETIC ACID	***Incident Occrrnce:***	
Trade Name:	stabilized	***Mat Ship Approval?:***	No
ID No:	UN3149	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	II
TIH Hazard Zone:		***Carrier Reporter:***	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.016511	***CR Street Name:***	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	***CR City:***	CORAOPOLIS
What Failed:	109	***CR State:***	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	***CR Postal Code:***	15108-9373
How Failed Code:	308	***CR Non US State:***	
How Failed Desc:	Leaked	***CR Fed DOT ID:***	265752
Failure Cause Code:	526	***CR Hazmat Reg ID:***	051910551007S
Failure Cause Desc:	Loose Closure Component or Device	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	MEDIVATORS INC.
Cont1 Pkging Type:	Box	***Shipper Street Name:***	14605 28TH AVE N
Cont1 Const Mat:	Fiberboard	***Shipper City:***	MINNEAPOLIS
Cont1 Head Type:		***Shipper State:***	MN
Cont1 Pkg Capacity:		***Shipper Postal:***	55447-4822
C1 Capacity UOM:		***Shipper Non US St:***	
Cont1 Pkg Amt:		***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	91101234888487
Cont1 Pkg No:		***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:		***Origin City:***	MINNEAPOLIS
Cont1 Pkg Mnfctr:		***Origin State:***	MINNESOTA
Cont1 Pkg Mnfct Dt:		***Origin Postal:***	55447
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:		***Origin Country:***	US
C1 Test Const Mat:	Fiberboard	***Destination City:***	LARKFIELD
C1 Pkg Dsign Pres.:		***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	95403
C1 Pkg Shell Thick:		***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:		***Cont2 Package Type:***	Bottle
C1 Head Thick UOM:		***Cont2 Const Mat:***	Plastic
C1 Pkg Srvc Pres.:		***Cont2 Pkg Capacity:***	
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	
C1 Device Model:		***Cont2 Pkg No Failed:***	
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	0
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	0
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:		***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:		***Total Evacuation Hrs:***	0

RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	GEORGE FETSKO
Damage > 500:	No	**Contact Title:**	HAZMAT - SAFETY ADVISOR
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	CORAOPOLIS
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2009040161	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	03/25/2009	**Report Submit Src:**	XML
Time of Incident:	0700	**Inc Multiple Rows:**	No
Haz Class Code:	3	**Inc Non US State:**	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID	**Mode Transport:**	Highway
Commodity Short Nm:	GASOLINE INCLUDES GASOLI	**Transport Phase:**	UNLOADING
Commodity Long Nm:	GASOLINE INCLUDES GASOLINE MIXED WITH ETHYL ALCOHOL WITH NOT MORE THAN 10% ALCOHOL	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1203	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	Yes
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	1	**CR Street Name:**	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	**CR City:**	CORAOPOLIS
What Failed:	128	**CR State:**	PA
What Failed Desc:	Inner Packaging	**CR Postal Code:**	15108-9373
How Failed Code:	304	**CR Non US State:**	
How Failed Desc:	Cracked	**CR Fed DOT ID:**	265752
Failure Cause Code:	534	**CR Hazmat Reg ID:**	062904001002M

Failure Cause Desc:	Too Much Weight on Package	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	MIAMI CYCLES INC
Cont1 Pkging Type:	Drum	**Shipper Street Name:**	1885 NE 149TH ST
Cont1 Const Mat:	Plastic	**Shipper City:**	NORTH MIAMI
Cont1 Head Type:		**Shipper State:**	FL
Cont1 Pkg Capacity:	0	**Shipper Postal:**	33181-1167
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	839906310001406
Cont1 Pkg No:		**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:		**Origin City:**	MIAMI
Cont1 Pkg Mnfctr:		**Origin State:**	FLORIDA
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	33183
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:	Plastic	**Destination City:**	SANTA ROSA
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95407
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	
C1 Head Thick UOM:		**Cont2 Const Mat:**	
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	
C1 Device Model:		**Cont2 Pkg No Failed:**	
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	TRAVIS MCEWEN
Damage > 500:	No	**Contact Title:**	SAFETY SPECIALIST III - HAZMAT
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No

Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	DRUM PLS
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Plastic drum
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	Yes

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2016080218	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	07/13/2016	**Report Submit Src:**	XML
Time of Incident:	0415	**Inc Multiple Rows:**	No
Haz Class Code:	8	**Inc Non US State:**	
Hazardous Class:	CORROSIVE MATERIAL	**Mode Transport:**	Highway
Commodity Short Nm:	SULFURIC ACID WITH NOT M	**Transport Phase:**	UNLOADING
Commodity Long Nm:	SULFURIC ACID WITH NOT MORE THAN 51% ACID	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN2796	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.031250	**CR Street Name:**	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	**CR City:**	CORAOPOLIS
What Failed:	109	**CR State:**	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	**CR Postal Code:**	15108-9373
How Failed Code:	305	**CR Non US State:**	
How Failed Desc:	Crushed	**CR Fed DOT ID:**	265752
Failure Cause Code:	517	**CR Hazmat Reg ID:**	051910551007S
Failure Cause Desc:	Improper Preparation for Transportation	**CR Country:**	US
Ident. Markings:	4G/Y16.7/S/15USA/+CA0562	**Shipper Name:**	RICCA CHEMICAL COMPANY LLC
Cont1 Pkging Type:		**Shipper Street Name:**	448 W FORK DR
Cont1 Const Mat:		**Shipper City:**	ARLINGTON
Cont1 Head Type:		**Shipper State:**	TX
Cont1 Pkg Capacity:		**Shipper Postal:**	76012-3449
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:		**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	283761583491765620
Cont1 Pkg No:		**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:		**Origin City:**	ARLINGTON
Cont1 Pkg Mnfctr:		**Origin State:**	TEXAS
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	76012
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:		**Destination City:**	GEYSERVILLE
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95441
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	
C1 Head Thick UOM:		**Cont2 Const Mat:**	
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	
C1 Device Model:		**Cont2 Pkg No Failed:**	
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0

RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:		**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	GEORGE FETSKO
Damage > 500:	No	**Contact Title:**	HAZMAT - SAFETY ADVISOR
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	CORAOPOLIS
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	4G
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2016060118	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	05/04/2016	**Report Submit Src:**	XML
Time of Incident:	0530	**Inc Multiple Rows:**	No
Haz Class Code:	8	**Inc Non US State:**	
Hazardous Class:	CORROSIVE MATERIAL	**Mode Transport:**	Highway
Commodity Short Nm:	SODIUM HYDROXIDE SOLUTI	**Transport Phase:**	UNLOADING
Commodity Long Nm:	SODIUM HYDROXIDE SOLUTION	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1824	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.023438	**CR Street Name:**	1000 FED EX DR

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Unit of Measure:	Liquid - Gallon	**CR City:**	CORAOPOLIS
What Failed:	109	**CR State:**	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	**CR Postal Code:**	15108-9373
How Failed Code:	308	**CR Non US State:**	
How Failed Desc:	Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	521	**CR Hazmat Reg ID:**	051910551007S
Failure Cause Desc:	Inadequate Preparation for Transportation	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	AQUA SOLUTIONS INC.
Cont1 Pkging Type:	Box	**Shipper Street Name:**	6913 HIGHWAY 225
Cont1 Const Mat:	Fiberboard	**Shipper City:**	DEER PARK
Cont1 Head Type:		**Shipper State:**	TX
Cont1 Pkg Capacity:		**Shipper Postal:**	77536-2414
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:		**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	60695430
Cont1 Pkg No:		**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:		**Origin City:**	DEER PARK
Cont1 Pkg Mnfctr:		**Origin State:**	TEXAS
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	77536
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:	Fiberboard	**Destination City:**	SAINT HELENA
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	94574
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	Bottle
C1 Head Thick UOM:		**Cont2 Const Mat:**	Plastic
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	
C1 Device Model:		**Cont2 Pkg No Failed:**	
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:		**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	GEORGE FETSKO
Damage > 500:	No	**Contact Title:**	HAZMAT - SAFETY ADVISOR
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	CORAOPOLIS
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier

Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2010050131	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	05/07/2010	**Report Submit Src:**	XML
Time of Incident:	2130	**Inc Multiple Rows:**	No
Haz Class Code:	5.1	**Inc Non US State:**	
Hazardous Class:	OXIDIZER	**Mode Transport:**	Highway
Commodity Short Nm:	SODIUM CARBONATE PEROXHY	**Transport Phase:**	UNLOADING
Commodity Long Nm:	SODIUM CARBONATE PEROXHYDRATE	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN3378	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	1	**CR Street Name:**	1000 FED EX DR
Unit of Measure:	Solid - Pound	**CR City:**	CORAOPOLIS
What Failed:	128	**CR State:**	PA
What Failed Desc:	Inner Packaging	**CR Postal Code:**	15108-9373
How Failed Code:	303	**CR Non US State:**	
How Failed Desc:	Burst or Ruptured	**CR Fed DOT ID:**	265752
Failure Cause Code:	511	**CR Hazmat Reg ID:**	051909552054R
Failure Cause Desc:	Dropped	**CR Country:**	US
Ident. Markings:	5m2/y23/s/08/usa/4ac2609	**Shipper Name:**	BARREL BUILDERS INC
Cont1 Pkging Type:		**Shipper Street Name:**	990 VINTAGE AVE STE B
Cont1 Const Mat:		**Shipper City:**	SAINT HELENA
Cont1 Head Type:		**Shipper State:**	CA
Cont1 Pkg Capacity:		**Shipper Postal:**	94574-1418
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:		**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	28882562011702
Cont1 Pkg No:		**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:		**Origin City:**	CALISTOGA
Cont1 Pkg Mnfctr:		**Origin State:**	CALIFORNIA
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	94515
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:		**Destination City:**	BONNY DOON
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95060
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	
C1 Head Thick UOM:		**Cont2 Const Mat:**	
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	

C1 Device Mnfctr:		**Cont2 Pkg No:**	
C1 Device Model:		**Cont2 Pkg No Failed:**	
NRC No:			
RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:		**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	TRAVIS MCEWEN
Damage > 500:	No	**Contact Title:**	SAFETY SPECIALIST III - HAZMAT
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	5M2
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Multi-wall water-resistant paper bag
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2011090244	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	08/16/2011	**Report Submit Src:**	XML
Time of Incident:	0700	**Inc Multiple Rows:**	No
Haz Class Code:	8	**Inc Non US State:**	
Hazardous Class:	CORROSIVE MATERIAL	**Mode Transport:**	Highway
Commodity Short Nm:	CORROSIVE LIQUID ACIDIC	**Transport Phase:**	UNLOADING
Commodity Long Nm:	CORROSIVE LIQUID ACIDIC INORGANIC N. O.S.	**Incident Occrrnce:**	
Trade Name:	selenious nitric aci	**Mat Ship Approval?:**	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

ID No:	UN3264	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.10	**CR Street Name:**	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	**CR City:**	CORAOPOLIS
What Failed:	104	**CR State:**	PA
What Failed Desc:	Body	**CR Postal Code:**	15108-9373
How Failed Code:	308	**CR Non US State:**	
How Failed Desc:	Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	511	**CR Hazmat Reg ID:**	051910551007S
Failure Cause Desc:	Dropped	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	BIRCHWOOD LABORATORIES LLC
Cont1 Pkging Type:	Drum	**Shipper Street Name:**	7900 FULLER RD
Cont1 Const Mat:	Plastic	**Shipper City:**	EDEN PRAIRIE
Cont1 Head Type:		**Shipper State:**	MN
Cont1 Pkg Capacity:	0	**Shipper Postal:**	55344-2138
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	55404870010266
Cont1 Pkg No:		**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:		**Origin City:**	EDEN PRAIRIE
Cont1 Pkg Mnfctr:		**Origin State:**	MINNESOTA
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	55344
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:	Plastic	**Destination City:**	CLOVERDALE
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95425
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	
C1 Head Thick UOM:		**Cont2 Const Mat:**	
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	
C1 Device Model:		**Cont2 Pkg No Failed:**	
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	GEORGE FETSKO
Damage > 500:	No	**Contact Title:**	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive

Property Damage:	0	**Contact City:**	Moon Township
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	DRUM PLS
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Plastic drum
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2014120370	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	12/03/2014	**Report Submit Src:**	XML
Time of Incident:	0700	**Inc Multiple Rows:**	No
Haz Class Code:	8	**Inc Non US State:**	
Hazardous Class:	CORROSIVE MATERIAL	**Mode Transport:**	Highway
Commodity Short Nm:	CORROSIVE LIQUID ACIDIC	**Transport Phase:**	UNLOADING
Commodity Long Nm:	CORROSIVE LIQUID ACIDIC INORGANIC N. O.S.	**Incident Occrrnce:**	
Trade Name:	Nitric Acid Phospho	**Mat Ship Approval?:**	No
ID No:	UN3264	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.20	**CR Street Name:**	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	**CR City:**	CORAOPOLIS
What Failed:	109	**CR State:**	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	**CR Postal Code:**	15108-9373
How Failed Code:	308	**CR Non US State:**	
How Failed Desc:	Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	526	**CR Hazmat Reg ID:**	051910551007S
Failure Cause Desc:	Loose Closure Component or Device	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	DELAVAL MANUFACTURING
Cont1 Pkging Type:	Box	**Shipper Street Name:**	1855 S MOUNT PROSPECT RD
Cont1 Const Mat:	Fiberboard	**Shipper City:**	DES PLAINES
Cont1 Head Type:		**Shipper State:**	IL
Cont1 Pkg Capacity:		**Shipper Postal:**	60018-1805
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:		**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	540109502482
Cont1 Pkg No:		**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:		**Origin City:**	DES PLAINES
Cont1 Pkg Mnfctr:		**Origin State:**	ILLINOIS
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	60018
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:	Fiberboard	**Destination City:**	PETALUMA
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	94952
C1 Pkg Shell Thick:		**Destination Non US:**	

C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	Can
C1 Head Thick UOM:		**Cont2 Const Mat:**	Plastic
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	
C1 Device Model:		**Cont2 Pkg No Failed:**	
NRC No:			
RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:		**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	GEORGE FETSKO
Damage > 500:	No	**Contact Title:**	HAZMAT - SAFETY ADVISOR
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	CORAOPOLIS
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2016110571	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	10/26/2016	**Report Submit Src:**	XML

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Time of Incident:	0530	**Inc Multiple Rows:**	No
Haz Class Code:	8	**Inc Non US State:**	
Hazardous Class:	CORROSIVE MATERIAL	**Mode Transport:**	Highway
Commodity Short Nm:	SODIUM HYDROXIDE SOLUTI	**Transport Phase:**	UNLOADING
Commodity Long Nm:	SODIUM HYDROXIDE SOLUTION	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1824	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.007809	**CR Street Name:**	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	**CR City:**	CORAOPOLIS
What Failed:	109	**CR State:**	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	**CR Postal Code:**	15108-9373
How Failed Code:	308	**CR Non US State:**	
How Failed Desc:	Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	517	**CR Hazmat Reg ID:**	051910551007S
Failure Cause Desc:	Improper Preparation for Transportation	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	ECOLAB
Cont1 Pkging Type:	Drum	**Shipper Street Name:**	13277 SAN BERNARDINO AVE
Cont1 Const Mat:	Plastic	**Shipper City:**	FONTANA
Cont1 Head Type:		**Shipper State:**	CA
Cont1 Pkg Capacity:	0	**Shipper Postal:**	92335-5235
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	595080273768541
Cont1 Pkg No:		**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:		**Origin City:**	FONTANA
Cont1 Pkg Mnfctr:		**Origin State:**	CALIFORNIA
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	92335
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:	Plastic	**Destination City:**	SANTA ROSA
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95401
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	
C1 Head Thick UOM:		**Cont2 Const Mat:**	
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	
C1 Device Model:		**Cont2 Pkg No Failed:**	
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No

Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	GEORGE FETSKO
Damage > 500:	No	**Contact Title:**	HAZMAT - SAFETY ADVISOR
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	CORAOPOLIS
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	DRUM PLS
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Plastic drum
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2016060138	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	05/05/2016	**Report Submit Src:**	XML
Time of Incident:	0600	**Inc Multiple Rows:**	No
Haz Class Code:	3	**Inc Non US State:**	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID	**Mode Transport:**	Highway
Commodity Short Nm:	ETHANOL OR ETHYL ALCOHOL	**Transport Phase:**	UNLOADING
Commodity Long Nm:	ETHANOL OR ETHYL ALCOHOL OR ETHANOL SOLUTIONS OR ETHYL ALCOHOL SOLUTIONS	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1170	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.070312	**CR Street Name:**	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	**CR City:**	CORAOPOLIS
What Failed:	109	**CR State:**	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	**CR Postal Code:**	15108-9373
How Failed Code:	308	**CR Non US State:**	
How Failed Desc:	Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	526	**CR Hazmat Reg ID:**	051910551007S
Failure Cause Desc:	Loose Closure Component or Device	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	SAVE ON SCENT INC
Cont1 Pkging Type:	Jerrican	**Shipper Street Name:**	388 3RD AVE
Cont1 Const Mat:	Plastic	**Shipper City:**	BROOKLYN
Cont1 Head Type:		**Shipper State:**	NY
Cont1 Pkg Capacity:		**Shipper Postal:**	11215-2705
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:		**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	58316111
Cont1 Pkg No:		**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:		**Origin City:**	BROOKLYN
Cont1 Pkg Mnfctr:		**Origin State:**	NEW YORK

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Cont1 Pkg Mnfct Dt:		**Origin Postal:**	11215
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:	Plastic	**Destination City:**	SANTA ROSA
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95407
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	
C1 Head Thick UOM:		**Cont2 Const Mat:**	
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	
C1 Device Model:		**Cont2 Pkg No Failed:**	
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:		**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	GEORGE FETSKO
Damage > 500:	No	**Contact Title:**	HAZMAT - SAFETY ADVISOR
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	CORAOPOLIS
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	CONT
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Container no description given (do not use if at all possible)
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2016120667	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	12/16/2016	***Report Submit Src:***	XML
Time of Incident:	0400	***Inc Multiple Rows:***	No
Haz Class Code:	8	***Inc Non US State:***	
Hazardous Class:	CORROSIVE MATERIAL	***Mode Transport:***	Highway
Commodity Short Nm:	HYPOCHLORITE SOLUTIONS	***Transport Phase:***	UNLOADING
Commodity Long Nm:	HYPOCHLORITE SOLUTIONS	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1791	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	II
TIH Hazard Zone:		***Carrier Reporter:***	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.02	***CR Street Name:***	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	***CR City:***	CORAOPOLIS
What Failed:	109	***CR State:***	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	***CR Postal Code:***	15108-9373
How Failed Code:	309	***CR Non US State:***	
How Failed Desc:	Punctured	***CR Fed DOT ID:***	265752
Failure Cause Code:	526	***CR Hazmat Reg ID:***	051910551007S
Failure Cause Desc:	Loose Closure Component or Device	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	RMR SOLUTIONS LLC
Cont1 Pkging Type:	Box	***Shipper Street Name:***	201 APPIAN WAY DR STE 202
Cont1 Const Mat:	Fiberboard	***Shipper City:***	BRIGHTON
Cont1 Head Type:		***Shipper State:***	MI
Cont1 Pkg Capacity:		***Shipper Postal:***	48116-2478
C1 Capacity UOM:		***Shipper Non US St:***	
Cont1 Pkg Amt:		***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	7566618706142151320
Cont1 Pkg No:		***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:		***Origin City:***	BRIGHTON
Cont1 Pkg Mnfctr:		***Origin State:***	MICHIGAN
Cont1 Pkg Mnfct Dt:		***Origin Postal:***	48116
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:		***Origin Country:***	US
C1 Test Const Mat:	Fiberboard	***Destination City:***	SANTA ROSA
C1 Pkg Dsign Pres.:		***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	95407
C1 Pkg Shell Thick:		***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:		***Cont2 Package Type:***	Bottle
C1 Head Thick UOM:		***Cont2 Const Mat:***	Plastic
C1 Pkg Srvc Pres.:		***Cont2 Pkg Capacity:***	
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	
C1 Device Model:		***Cont2 Pkg No Failed:***	
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	0
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	0
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:		***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:		***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0

Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	GEORGE FETSKO
Damage > 500:	No	**Contact Title:**	HAZMAT - SAFETY ADVISOR
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	CORAOPOLIS
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2008120315	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	12/18/2008	**Report Submit Src:**	XML
Time of Incident:	0714	**Inc Multiple Rows:**	No
Haz Class Code:	8	**Inc Non US State:**	
Hazardous Class:	CORROSIVE MATERIAL	**Mode Transport:**	Highway
Commodity Short Nm:	SODIUM HYDROXIDE SOLUTI	**Transport Phase:**	UNLOADING
Commodity Long Nm:	SODIUM HYDROXIDE SOLUTION	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1824	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.184926	**CR Street Name:**	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	**CR City:**	CORAOPOLIS
What Failed:	117	**CR State:**	PA
What Failed Desc:	Fill Hole	**CR Postal Code:**	15108-9373
How Failed Code:	309	**CR Non US State:**	
How Failed Desc:	Punctured	**CR Fed DOT ID:**	265752
Failure Cause Code:	526	**CR Hazmat Reg ID:**	062904001002M
Failure Cause Desc:	Loose Closure Component or Device	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	LABCHEM INC.
Cont1 Pkging Type:	Box	**Shipper Street Name:**	1010 JACKSONS POINTE CT
Cont1 Const Mat:	Fiberboard	**Shipper City:**	ZELIENOPLE
Cont1 Head Type:		**Shipper State:**	PA
Cont1 Pkg Capacity:		**Shipper Postal:**	16063-2826

C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:		**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	15396431110558
Cont1 Pkg No:		**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:		**Origin City:**	PITTSBURGH
Cont1 Pkg Mnfctr:		**Origin State:**	PENNSYLVANIA
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	15238
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:	Fiberboard	**Destination City:**	WINDSOR
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95492
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	Bottle
C1 Head Thick UOM:		**Cont2 Const Mat:**	Plastic
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	
C1 Device Model:		**Cont2 Pkg No Failed:**	
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:		**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	TRAVIS MCEWEN
Damage > 500:	No	**Contact Title:**	SAFETY SPECIALIST III - HAZMAT
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton

Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2018080369	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	07/12/2018	**Report Submit Src:**	XML
Time of Incident:	2000	**Inc Multiple Rows:**	No
Haz Class Code:	5.1	**Inc Non US State:**	
Hazardous Class:	OXIDIZER	**Mode Transport:**	Highway
Commodity Short Nm:	HYDROGEN PEROXIDE AND PE	**Transport Phase:**	UNLOADING
Commodity Long Nm:	HYDROGEN PEROXIDE AND PEROXYACETIC ACID MIXTURES STABILIZED WITH ACIDS WATER AND NOT MORE THAN 5 PERCENT PEROXYACETIC ACID	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN3149	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.0010	**CR Street Name:**	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	**CR City:**	CORAOPOLIS
What Failed:	159	**CR State:**	PA
What Failed Desc:	Vent	**CR Postal Code:**	15108-9373
How Failed Code:	308	**CR Non US State:**	
How Failed Desc:	Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	535	**CR Hazmat Reg ID:**	051910551007S
Failure Cause Desc:	Valve Open	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	HORIZON INC.
Cont1 Pkging Type:	Box	**Shipper Street Name:**	1025 DELAWARE AVE UNIT C
Cont1 Const Mat:	Fiberboard	**Shipper City:**	LONGMONT
Cont1 Head Type:		**Shipper State:**	CO
Cont1 Pkg Capacity:		**Shipper Postal:**	80501-6115
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:		**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	178940416432337528
Cont1 Pkg No:		**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:		**Origin City:**	LONGMONT
Cont1 Pkg Mnfctr:		**Origin State:**	COLORADO
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	80501
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:	Fiberboard	**Destination City:**	SANTA ROSA
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95407
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	Bottle
C1 Head Thick UOM:		**Cont2 Const Mat:**	Plastic
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	
C1 Device Model:		**Cont2 Pkg No Failed:**	
NRC No:			
RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0

RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:		**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	GEORGE FETSKO
Damage > 500:	No	**Contact Title:**	HAZMAT - SAFETY ADVISOR
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	CORAOPOLIS
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	4G
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: Original comments: Outbound manager found on shelf on vehicle that the driver had brought back with orientation arrows not in the upright position. Item was leaking out of the release valve. New Comments:

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2015100341	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	09/28/2015	**Report Submit Src:**	XML
Time of Incident:	0700	**Inc Multiple Rows:**	No
Haz Class Code:	8	**Inc Non US State:**	
Hazardous Class:	CORROSIVE MATERIAL	**Mode Transport:**	Highway
Commodity Short Nm:	CORROSIVE LIQUID ACIDIC	**Transport Phase:**	LOADING
Commodity Long Nm:	CORROSIVE LIQUID ACIDIC ORGANIC N.O.S.	**Incident Occrrnce:**	
Trade Name:	(urea sulfate)	**Mat Ship Approval?:**	No
ID No:	UN3265	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	1	**CR Street Name:**	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	**CR City:**	CORAOPOLIS
What Failed:	109	**CR State:**	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	**CR Postal Code:**	15108-9373

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

How Failed Code:	308	**CR Non US State:**	
How Failed Desc:	Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	517	**CR Hazmat Reg ID:**	051910551007S
Failure Cause Desc:	Improper Preparation for Transportation	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	ECOLAB
Cont1 Pkging Type:	Box	**Shipper Street Name:**	13277 SAN BERNARDINO AVE
Cont1 Const Mat:	Fiberboard	**Shipper City:**	FONTANA
Cont1 Head Type:		**Shipper State:**	CA
Cont1 Pkg Capacity:		**Shipper Postal:**	92335-5235
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:		**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	595080272536073
Cont1 Pkg No:		**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:		**Origin City:**	FONTANA
Cont1 Pkg Mnfctr:		**Origin State:**	CALIFORNIA
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	92335
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:	Fiberboard	**Destination City:**	GEYSERVILLE
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95441
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	Bottle
C1 Head Thick UOM:		**Cont2 Const Mat:**	Plastic
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	
C1 Device Model:		**Cont2 Pkg No Failed:**	
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:		**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	GEORGE FETSKO
Damage > 500:	No	**Contact Title:**	HAZMAT - SAFETY ADVISOR
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	CORAOPOLIS
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No

Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2010030052	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	02/10/2010	**Report Submit Src:**	XML
Time of Incident:	0700	**Inc Multiple Rows:**	No
Haz Class Code:	3	**Inc Non US State:**	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID	**Mode Transport:**	Highway
Commodity Short Nm:	BUTYL ACETATES	**Transport Phase:**	UNLOADING
Commodity Long Nm:	BUTYL ACETATES	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1123	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.000264	**CR Street Name:**	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	**CR City:**	CORAOPOLIS
What Failed:	128	**CR State:**	PA
What Failed Desc:	Inner Packaging	**CR Postal Code:**	15108-9373
How Failed Code:	308	**CR Non US State:**	
How Failed Desc:	Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	526	**CR Hazmat Reg ID:**	051909552054R
Failure Cause Desc:	Loose Closure Component or Device	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	FISHER SCIENTIFIC COMPANY LLC
Cont1 Pkging Type:	Box	**Shipper Street Name:**	4500 TURNBERRY DR
Cont1 Const Mat:	Fiberboard	**Shipper City:**	HANOVER PARK
Cont1 Head Type:		**Shipper State:**	IL
Cont1 Pkg Capacity:		**Shipper Postal:**	60133-5491
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:		**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	39064679102146
Cont1 Pkg No:		**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:		**Origin City:**	BARTLETT
Cont1 Pkg Mnfctr:		**Origin State:**	ILLINOIS
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	60133
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:	Fiberboard	**Destination City:**	COTATI
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	94931
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	Bottle
C1 Head Thick UOM:		**Cont2 Const Mat:**	
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	
C1 Device Model:		**Cont2 Pkg No Failed:**	
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:		**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	TRAVIS MCEWEN
Damage > 500:	No	**Contact Title:**	SAFETY SPECIALIST III - HAZMAT
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2009040180	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	03/27/2009	**Report Submit Src:**	XML
Time of Incident:	0700	**Inc Multiple Rows:**	No
Haz Class Code:	2.2	**Inc Non US State:**	
Hazardous Class:	NONFLAMMABLE COMPRESSED GAS	**Mode Transport:**	Highway
Commodity Short Nm:	FIRE EXTINGUISHERS CONTA	**Transport Phase:**	IN TRANSIT
Commodity Long Nm:	FIRE EXTINGUISHERS CONTAINING COMPRESSED OR LIQUEFIED GAS	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1044	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk

HMIS Tox Inhalation?:	No	**Packing Group:**	
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	1	**CR Street Name:**	1000 FED EX DR
Unit of Measure:	Solid - Pound	**CR City:**	CORAOPOLIS
What Failed:	126	**CR State:**	PA
What Failed Desc:	Hose Adaptor or Coupling	**CR Postal Code:**	15108-9373
How Failed Code:	308	**CR Non US State:**	
How Failed Desc:	Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	521	**CR Hazmat Reg ID:**	062904001002M
Failure Cause Desc:	Inadequate Preparation for Transportation	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	HD SUPPLY INC.
Cont1 Pkging Type:	Box	**Shipper Street Name:**	3050 RAMCO ST
Cont1 Const Mat:	Fiberboard	**Shipper City:**	WEST SACRAMENTO
Cont1 Head Type:		**Shipper State:**	CA
Cont1 Pkg Capacity:		**Shipper Postal:**	95691-5873
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:		**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	13164997931182
Cont1 Pkg No:		**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:		**Origin City:**	WEST SACRAMENTO
Cont1 Pkg Mnfctr:		**Origin State:**	CALIFORNIA
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	95691
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:	Fiberboard	**Destination City:**	SAINT HELENA
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	94574
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	Cylinder
C1 Head Thick UOM:		**Cont2 Const Mat:**	Metal (any type)
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	
C1 Device Model:		**Cont2 Pkg No Failed:**	
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:		**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	TRAVIS MCEWEN
Damage > 500:	No	**Contact Title:**	SAFETY SPECIALIST III - HAZMAT
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108

Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the Fire Extinguisher(s) had a loose pin(s) with allowed leakage. The pin(s) were secured. The package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2016090017	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	08/03/2016	**Report Submit Src:**	XML
Time of Incident:	0700	**Inc Multiple Rows:**	No
Haz Class Code:	8	**Inc Non US State:**	
Hazardous Class:	CORROSIVE MATERIAL	**Mode Transport:**	Highway
Commodity Short Nm:	CORROSIVE LIQUID ACIDIC	**Transport Phase:**	UNLOADING
Commodity Long Nm:	CORROSIVE LIQUID ACIDIC INORGANIC N. O.S.	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN3264	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.023438	**CR Street Name:**	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	**CR City:**	CORAOPOLIS
What Failed:	109	**CR State:**	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	**CR Postal Code:**	15108-9373
How Failed Code:	308	**CR Non US State:**	
How Failed Desc:	Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	511	**CR Hazmat Reg ID:**	051910551007S
Failure Cause Desc:	Dropped	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	NUGENERATION TECHNOLOGIES LLC
Cont1 Pkging Type:	Box	**Shipper Street Name:**	1155 PARK AVE
Cont1 Const Mat:	Fiberboard	**Shipper City:**	EMERYVILLE
Cont1 Head Type:		**Shipper State:**	CA
Cont1 Pkg Capacity:		**Shipper Postal:**	94608-3631
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:		**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	76893877429
Cont1 Pkg No:		**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:		**Origin City:**	EMERYVILLE
Cont1 Pkg Mnfctr:		**Origin State:**	CALIFORNIA
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	94608
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:	Fiberboard	**Destination City:**	LARKFIELD
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95403
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	Bottle
C1 Head Thick UOM:		**Cont2 Const Mat:**	Plastic

C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	
C1 Device Model:		**Cont2 Pkg No Failed:**	
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:		**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	GEORGE FETSKO
Damage > 500:	No	**Contact Title:**	HAZMAT - SAFETY ADVISOR
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	CORAOPOLIS
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2010020073	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	01/25/2010	**Report Submit Src:**	XML
Time of Incident:	0700	**Inc Multiple Rows:**	No
Haz Class Code:	3	**Inc Non US State:**	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID	**Mode Transport:**	Highway

Commodity Short Nm:	ISOPROPYL ALCOHOL	**Transport Phase:**	LOADING
Commodity Long Nm:	ISOPROPYL ALCOHOL	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1219	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.01	**CR Street Name:**	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	**CR City:**	CORAOPOLIS
What Failed:	104	**CR State:**	PA
What Failed Desc:	Body	**CR Postal Code:**	15108-9373
How Failed Code:	309	**CR Non US State:**	
How Failed Desc:	Punctured	**CR Fed DOT ID:**	265752
Failure Cause Code:	511	**CR Hazmat Reg ID:**	051909552054R
Failure Cause Desc:	Dropped	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	BRAINERD CHEMICAL COMPANY INC.
Cont1 Pkging Type:	Drum	**Shipper Street Name:**	1200 N PEORIA AVE
Cont1 Const Mat:	Steel	**Shipper City:**	TULSA
Cont1 Head Type:		**Shipper State:**	OK
Cont1 Pkg Capacity:	0	**Shipper Postal:**	74106-4952
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	126243310030627
Cont1 Pkg No:		**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:		**Origin City:**	TULSA
Cont1 Pkg Mnfctr:		**Origin State:**	OKLAHOMA
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	74106
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:	Steel	**Destination City:**	ALAMEDA
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	94502
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	
C1 Head Thick UOM:		**Cont2 Const Mat:**	
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	
C1 Device Model:		**Cont2 Pkg No Failed:**	
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	TRAVIS MCEWEN

Damage > 500:	No	**Contact Title:**	SAFETY SPECIALIST III - HAZMAT
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	DRUM MTL
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Metal drum
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The pail was dropped during handling causing leakage. The leakage was contained and the package was repacked. Undamaged product was returned to the shipper. The damaged product was properly disposed of in accordance with Federal Regulations.

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2016080479	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	07/22/2016	**Report Submit Src:**	XML
Time of Incident:	0500	**Inc Multiple Rows:**	No
Haz Class Code:	8	**Inc Non US State:**	
Hazardous Class:	CORROSIVE MATERIAL	**Mode Transport:**	Highway
Commodity Short Nm:	CORROSIVE LIQUID BASIC	**Transport Phase:**	UNLOADING
Commodity Long Nm:	CORROSIVE LIQUID BASIC INORGANIC N. O.S.	**Incident Occrrnce:**	
Trade Name:	sodium toltraizole/s	**Mat Ship Approval?:**	No
ID No:	UN3266	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.007812	**CR Street Name:**	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	**CR City:**	CORAOPOLIS
What Failed:	104	**CR State:**	PA
What Failed Desc:	Body	**CR Postal Code:**	15108-9373
How Failed Code:	309	**CR Non US State:**	
How Failed Desc:	Punctured	**CR Fed DOT ID:**	265752
Failure Cause Code:	516	**CR Hazmat Reg ID:**	051910551007S
Failure Cause Desc:	Impact with Sharp or Protruding Object (e.g. nails)	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	NCH CORPORATION
Cont1 Pkging Type:	Jerrican	**Shipper Street Name:**	932 KIFER RD
Cont1 Const Mat:	Plastic	**Shipper City:**	SUNNYVALE
Cont1 Head Type:		**Shipper State:**	CA
Cont1 Pkg Capacity:		**Shipper Postal:**	94086-5206
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:		**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	95150272305698
Cont1 Pkg No:		**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:		**Origin City:**	ONIZUKA AFB
Cont1 Pkg Mnfctr:		**Origin State:**	CALIFORNIA
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	94088
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US

C1 Test Const Mat:	Plastic	**Destination City:**	GEYSERVILLE
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95441
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	
C1 Head Thick UOM:		**Cont2 Const Mat:**	
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	
C1 Device Model:		**Cont2 Pkg No Failed:**	
NRC No:			
RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:		**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	GEORGE FETSKO
Damage > 500:	No	**Contact Title:**	HAZMAT - SAFETY ADVISOR
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	CORAOPOLIS
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	CONT
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Container no description given (do not use if at all possible)
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
11	2 of 5	SSW	0.04 / 227.62	119.01 / -1	FedEx Ground - ZSRO 500 Caletti Ave, Windsor, CA 95492 CA	CUPA SONOMA

Facility ID: 49-000-008151 **CERS ID:** 10455049

Details

Program Type: Hazardous Waste
Permit Status: Active
Expiration Date: 8/10/2023
Fee Schedule: SQG < 325 gallons/year

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
11	3 of 5	SSW	0.04 / 227.62	119.01 / -1	FedEx Ground - ZSRO 500 CALETTI AVE WINDSOR CA 95492	CERS HAZ

Site ID: 29937
Latitude: 38.517693
Longitude: -122.789452
County:

Regulated Programs

EI ID: 10455049 **EI Description:** Hazardous Waste Generator

Violations

Violation Date: 08/21/2013 **Violation Source:** CERS
Violation Program: HMRRP **Violation Division:** Sonoma County Fire & Emergency Services Department
Citation: HSC 6.95 25503.5(a) - California Health and Safety Code, Chapter 6.95, Section(s) 25503.5(a)
Violation Notes:

Returned to compliance on 08/22/2013. No hazmats in RQs - HWG only & all HW < HMBP TPQs

Violation Description:

Owner/Operator failed to establish and implement a Hazardous Materials Business Plan when storing hazardous materials at or above the thresholds quantities of 55 gallons/500 lbs/200 cubic feet.

Violations

Violation Date: 07/22/2020 **Violation Source:** CERS
Violation Program: HMRRP **Violation Division:** Sonoma County Fire & Emergency Services Department
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Returned to compliance on 08/10/2020. The business failed to electronically submit and certify that the business plan is complete, accurate, and in compliance with EPCRA on or before the annual due date. Electronically submit and certify that the business plan is complete, accurate, and in compliance with EPCRA within 30 days. On an ongoing basis, electronically submit and certify the business plan annually on or before the annual due date.

Violation Description:

Failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date.

Violations

Violation Date: 07/22/2020
Violation Source: CERS
Violation Program: HW
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: 22 CCR 12 66262.12 - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.12
Violation Notes:

Returned to compliance on 08/10/2020. The generator has not obtained an active EPA ID number to manage hazardous waste. A hazardous waste generator shall not treat, store, dispose of, transport or offer for transportation, hazardous waste without an active EPA ID number. Submit documentation to the CUPA demonstrating that you have obtained an EPA ID number.

Violation Description:

Failure to obtain an Identification Number prior to treating, storing, disposing of, transporting or offering for transportation any hazardous waste.

Evaluations

Eval Date: 07/22/2020
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Complete your annual CERS submittal; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 08/22/2013
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

Eval Date: 08/21/2013
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Eval Date: 08/10/2020
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Violation corrected. CERS has been updated; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/14/2017
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

Reviewed employee training, inspection logs, manifests and disposal documents for HW/UW/oil/water separator; inspected HW storage and staging areas, UW storage area, and first aid/safety area. No violations noted.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 07/22/2020
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

Provide EPA ID number for Hazardous Waste Management; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 08/10/2020
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

EPA id updated. Violation corrected; Note: data in [EVAL Notes] field for some records is truncated from the source.

Affiliations

Affil Type Desc: Parent Corporation
Entity Name: FedEx Ground Package System, Inc.
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Legal Owner
Entity Name: FedEx Ground Package System, Inc.
Entity Title:
Address: 1000 FedEx Drive
City: Moon Township
State: PA
Country: United States
Zip Code: 15108
Phone: (412) 262-6291

Affil Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title:
Address: 1000 FedEx Drive, Attn: Environmental Affairs Dept.
City: Moon Township
State: PA
Country:
Zip Code: 15108
Phone:

Affil Type Desc: Identification Signer
Entity Name: Debra Gehm
Entity Title: Senior Environmental Compliance Specialist
Address:
City:
State:
Country:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Zip Code:
Phone:

Affil Type Desc: CUPA District
Entity Name: Sonoma County Fire Prevention and Hazmat
Entity Title:
Address: 2300 County Center Drive, Suite 220-B
City: Santa Rosa
State: CA
Country:
Zip Code: 95403
Phone: (707) 565-2024

Affil Type Desc: Environmental Contact
Entity Name: Debra Gehm
Entity Title:
Address: 1000 FedEx Drive, Attn: Environmental Affairs Dept.
City: Moon Township
State: PA
Country:
Zip Code: 15108
Phone:

Affil Type Desc: Document Preparer
Entity Name: Hazel Roberts, Blymyer Engineers
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Operator
Entity Name: FedEx Ground - ZSRO
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone: (412) 262-6291

Coordinates

Env Int Type Code:	HWG	**Longitude:**	-122.789440
Program ID:	10455049	**Coord Name:**	
Latitude:	38.517710	**Ref Point Type Desc:**	Center of a facility or station.

11	4 of 5	SSW	0.04 / 227.62	119.01 / -1	500 caletti ave WINDSOR CA	HMIRS

Incident County: SONOMA

HMIR Incident Reports

Report No:	X-2010020073	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2010-01-25	**Report Submit Src:**	XML
Time of Incident:	0700	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	3	**Mode Transport:**	Highway
Commodity Short Nm:	ISOPROPYL ALCOHOL	**Transport Phase:**	Loading
Commodity Long Nm:	ISOPROPYL ALCOHOL	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

ID No:	UN1219	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	Fedex Ground Package System, Inc.
Qty Released:	0.01	**CR Street Name:**	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	**CR City:**	MOON TOWNSHIP
What Failed:	104	**CR State:**	PA
What Failed Desc:	Body	**CR Postal Code:**	15108
How Failed Code:	309	**CR Non US State:**	
How Failed Desc:	Punctured	**CR Fed DOT ID:**	265752
Failure Cause Code:	511	**CR Hazmat Reg ID:**	051909552054R
Failure Cause Desc:	Dropped	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	brainerd chemical
Cont1 Pkging Type:	Drum	**Shipper Street Name:**	1200 north peoria
Cont1 Const Mat:	Steel	**Shipper City:**	TULSA
Cont1 Head Type:		**Shipper State:**	OK
Cont1 Pkg Capacity:	0	**Shipper Postal:**	74106
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	126243310030627
Cont1 Pkg No:	0	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	0	**Origin City:**	
Cont1 Pkg Mnfctr:		**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	
C1 Test Const Mat:	Steel	**Destination City:**	ALAMEDA
C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	94502
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	
C1 Head Thick UOM:		**Cont2 Const Mat:**	
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	0
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	0
C1 Device Model:		**Cont2 Pkg No Failed:**	0
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	TRAVIS MCEWEN
Damage > 500:	No	**Contact Title:**	SAFETY SPECIALIST III - HAZMAT
Material Loss:	0	**Contact Business:**	Fedex Ground Package System, Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive

Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	DRUM METAL
Haz Hosp Old Form:	0	**HMIS Container Code:**	DRUM MTL
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Metal drum
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The pail was dropped during handling causing leakage. The leakage was contained and the package was repacked. Undamaged product was returned to the shipper. The damaged product was properly disposed of in accordance with Federal Regulations.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2010020180	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2010-02-18	**Report Submit Src:**	XML
Time of Incident:	0600	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	5.1	**Mode Transport:**	Highway
Commodity Short Nm:	HYDROGEN PEROXIDE AND PE	**Transport Phase:**	Unloading
Commodity Long Nm:	HYDROGEN PEROXIDE AND PEROXYACETIC ACID MIXTURES, STABILIZED WITH ACIDS, WATER, AND NOT MORE THAN 5 PERCENT PEROXYACETIC ACID	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN3149	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	Yes
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	Fedex Ground Package System, Inc.
Qty Released:	0.01	**CR Street Name:**	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	**CR City:**	MOON TOWNSHIP
What Failed:	109	**CR State:**	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	**CR Postal Code:**	15108
How Failed Code:	308	**CR Non US State:**	
How Failed Desc:	Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	522	**CR Hazmat Reg ID:**	051909552054R
Failure Cause Desc:	Inadequate Procedures	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	veterinary services
Cont1 Pkging Type:	Box	**Shipper Street Name:**	1731 west 16th st
Cont1 Const Mat:	Fiberboard	**Shipper City:**	MERCED
Cont1 Head Type:		**Shipper State:**	CA
Cont1 Pkg Capacity:	0	**Shipper Postal:**	95340
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	571218360401174
Cont1 Pkg No:	0	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	0	**Origin City:**	
Cont1 Pkg Mnfctr:		**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	
C1 Test Const Mat:	Fiberboard	**Destination City:**	PETALUMA

C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	94952
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	Can
C1 Head Thick UOM:		**Cont2 Const Mat:**	Plastic
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	0
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	0
C1 Device Model:		**Cont2 Pkg No Failed:**	0
NRC No:			
RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	TRAVIS MCEWEN
Damage > 500:	No	**Contact Title:**	SAFETY SPECIALIST III - HAZMAT
Material Loss:	0	**Contact Business:**	Fedex Ground Package System, Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	BOX FIBER
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	Yes

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Report No:	X-2009100107	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2009-09-15	**Report Submit Src:**	XML
Time of Incident:	0500	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	2.2	**Mode Transport:**	Highway
Commodity Short Nm:	FIRE EXTINGUISHERS CONTA	**Transport Phase:**	Unloading
Commodity Long Nm:	FIRE EXTINGUISHERS CONTAINING COMPRESSED OR LIQUEFIED GAS	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1044	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	
TIH Hazard Zone:		**Carrier Reporter:**	Fedex Ground Package System, Inc.
Qty Released:	2	**CR Street Name:**	1000 Fedex Drive
Unit of Measure:	Solid - Pound	**CR City:**	MOON TOWNSHIP
What Failed:	128	**CR State:**	PA
What Failed Desc:	Inner Packaging	**CR Postal Code:**	15108
How Failed Code:	303	**CR Non US State:**	
How Failed Desc:	Burst or Ruptured	**CR Fed DOT ID:**	265752
Failure Cause Code:	526	**CR Hazmat Reg ID:**	062904001002M
Failure Cause Desc:	Loose Closure, Component, or Device	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	first alert
Cont1 Pkging Type:	Box	**Shipper Street Name:**	25 spur dr
Cont1 Const Mat:	Fiberboard	**Shipper City:**	EL PASO
Cont1 Head Type:		**Shipper State:**	TX
Cont1 Pkg Capacity:	0	**Shipper Postal:**	79906
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	79909930365503
Cont1 Pkg No:	0	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	0	**Origin City:**	
Cont1 Pkg Mnfctr:		**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	
C1 Test Const Mat:	Fiberboard	**Destination City:**	COTATI
C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	94931
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	Cylinder
C1 Head Thick UOM:		**Cont2 Const Mat:**	Metal (any type)
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	0
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	0
C1 Device Model:		**Cont2 Pkg No Failed:**	0
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No

No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	TRAVIS MCEWEN
Damage > 500:	No	**Contact Title:**	SAFETY SPECIALIST III - HAZMAT
Material Loss:	0	**Contact Business:**	Fedex Ground Package System, Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	BOX FIBER
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the Fire Extinguisher(s) had a loose pin(s) with allowed leakage. The pin(s) were secured. The package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2011090244	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2011-08-16	**Report Submit Src:**	XML
Time of Incident:	0700	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	8	**Mode Transport:**	Highway
Commodity Short Nm:	CORROSIVE LIQUID, ACIDIC	**Transport Phase:**	Unloading
Commodity Long Nm:	CORROSIVE LIQUID, ACIDIC, INORGANIC, N.O.S.	**Incident Occrrnce:**	
Trade Name:	selenious nitric aci	**Mat Ship Approval?:**	No
ID No:	UN3264	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	Fedex Ground Package System, Inc.
Qty Released:	0.1	**CR Street Name:**	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	**CR City:**	Moon Township
What Failed:	104	**CR State:**	PA
What Failed Desc:	Body	**CR Postal Code:**	15108
How Failed Code:	308	**CR Non US State:**	
How Failed Desc:	Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	511	**CR Hazmat Reg ID:**	051910551007S
Failure Cause Desc:	Dropped	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	birchwood labortories
Cont1 Pkging Type:	Drum	**Shipper Street Name:**	7900 fuller rd
Cont1 Const Mat:	Plastic	**Shipper City:**	Eden Prairie
Cont1 Head Type:		**Shipper State:**	MN
Cont1 Pkg Capacity:	0	**Shipper Postal:**	55344
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	55404870010266

Cont1 Pkg No:	0	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	0	**Origin City:**	
Cont1 Pkg Mnfctr:		**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	
C1 Test Const Mat:	Plastic	**Destination City:**	CLOVERDALE
C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95425
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	
C1 Head Thick UOM:		**Cont2 Const Mat:**	
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	0
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	0
C1 Device Model:		**Cont2 Pkg No Failed:**	0
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	GEORGE FETSKO
Damage > 500:	No	**Contact Title:**	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0	**Contact Business:**	Fedex Ground Package System, Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	Moon Township
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	DRUM NON-METAL
Haz Hosp Old Form:	0	**HMIS Container Code:**	DRUM PLS
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Plastic drum
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed

the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2010050131	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	2010-05-07	***Report Submit Src:***	XML
Time of Incident:	2130	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	5.1	***Mode Transport:***	Highway
Commodity Short Nm:	SODIUM CARBONATE PEROXHY	***Transport Phase:***	Unloading
Commodity Long Nm:	SODIUM CARBONATE PEROXHYDRATE	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN3378	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	II
TIH Hazard Zone:		***Carrier Reporter:***	Fedex Ground Package System, Inc.
Qty Released:	1	***CR Street Name:***	1000 Fedex Drive
Unit of Measure:	Solid - Pound	***CR City:***	MOON TOWNSHIP
What Failed:	128	***CR State:***	PA
What Failed Desc:	Inner Packaging	***CR Postal Code:***	15108
How Failed Code:	303	***CR Non US State:***	
How Failed Desc:	Burst or Ruptured	***CR Fed DOT ID:***	265752
Failure Cause Code:	511	***CR Hazmat Reg ID:***	051909552054R
Failure Cause Desc:	Dropped	***CR Country:***	US
Ident. Markings:	5m2/y23/s/08/usa/4ac2609	***Shipper Name:***	barrel builders
Cont1 Pkging Type:		***Shipper Street Name:***	1194 maple ln
Cont1 Const Mat:		***Shipper City:***	CALISTOGA
Cont1 Head Type:		***Shipper State:***	CA
Cont1 Pkg Capacity:	0	***Shipper Postal:***	94515
C1 Capacity UOM:		***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	28882562011702
Cont1 Pkg No:	0	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	0	***Origin City:***	
Cont1 Pkg Mnfctr:		***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	
C1 Test Const Mat:		***Destination City:***	BONNY DOON
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	95060
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0

Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	TRAVIS MCEWEN
Damage > 500:	No	**Contact Title:**	SAFETY SPECIALIST III - HAZMAT
Material Loss:	0	**Contact Business:**	Fedex Ground Package System, Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	BAG PAPER
Haz Hosp Old Form:	0	**HMIS Container Code:**	5M2
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Multi-wall water-resistant paper bag
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2010030052	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2010-02-10	**Report Submit Src:**	XML
Time of Incident:	0700	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	3	**Mode Transport:**	Highway
Commodity Short Nm:	BUTYL ACETATES	**Transport Phase:**	Unloading
Commodity Long Nm:	BUTYL ACETATES	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1123	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	Fedex Ground Package System, Inc.
Qty Released:	0.000264	**CR Street Name:**	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	**CR City:**	MOON TOWNSHIP
What Failed:	128	**CR State:**	PA
What Failed Desc:	Inner Packaging	**CR Postal Code:**	15108
How Failed Code:	308	**CR Non US State:**	
How Failed Desc:	Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	526	**CR Hazmat Reg ID:**	051909552054R
Failure Cause Desc:	Loose Closure, Component, or Device	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	fisher
Cont1 Pkging Type:	Box	**Shipper Street Name:**	4500 turnberry dr
Cont1 Const Mat:	Fiberboard	**Shipper City:**	BARTLETT

Cont1 Head Type:		**Shipper State:**	IL
Cont1 Pkg Capacity:	0	**Shipper Postal:**	60133
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	39064679102146
Cont1 Pkg No:	0	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	0	**Origin City:**	
Cont1 Pkg Mnfctr:		**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	
C1 Test Const Mat:	Fiberboard	**Destination City:**	COTATI
C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	94931
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	Bottle
C1 Head Thick UOM:		**Cont2 Const Mat:**	
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	0
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	0
C1 Device Model:		**Cont2 Pkg No Failed:**	0
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	TRAVIS MCEWEN
Damage > 500:	No	**Contact Title:**	SAFETY SPECIALIST III - HAZMAT
Material Loss:	0	**Contact Business:**	Fedex Ground Package System, Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	BOX FIBER

Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2010010088	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2010-01-11	**Report Submit Src:**	XML
Time of Incident:	0700	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	8	**Mode Transport:**	Highway
Commodity Short Nm:	SODIUM HYDROXIDE, SOLUTI	**Transport Phase:**	Unloading
Commodity Long Nm:	SODIUM HYDROXIDE, SOLUTION	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1824	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	Fedex Ground Package System, Inc.
Qty Released:	0.26418	**CR Street Name:**	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	**CR City:**	MOON TOWNSHIP
What Failed:	117	**CR State:**	PA
What Failed Desc:	Fill Hole	**CR Postal Code:**	15108
How Failed Code:	308	**CR Non US State:**	
How Failed Desc:	Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	526	**CR Hazmat Reg ID:**	051909552054R
Failure Cause Desc:	Loose Closure, Component, or Device	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	ricca chemical company
Cont1 Pkging Type:	Box	**Shipper Street Name:**	448 west fork dr
Cont1 Const Mat:	Fiberboard	**Shipper City:**	ARLINGTON
Cont1 Head Type:		**Shipper State:**	TX
Cont1 Pkg Capacity:	0	**Shipper Postal:**	76012
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	28376135066645
Cont1 Pkg No:	0	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	0	**Origin City:**	
Cont1 Pkg Mnfctr:		**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	
C1 Test Const Mat:	Fiberboard	**Destination City:**	SANTA ROSA
C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95401
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	Bottle
C1 Head Thick UOM:		**Cont2 Const Mat:**	Plastic
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	0
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	0
C1 Device Model:		**Cont2 Pkg No Failed:**	0
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0

RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	TRAVIS MCEWEN
Damage > 500:	No	**Contact Title:**	SAFETY SPECIALIST III - HAZMAT
Material Loss:	0	**Contact Business:**	Fedex Ground Package System, Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	BOX FIBER
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2016010089	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2015-12-11	**Report Submit Src:**	XML
Time of Incident:	0400	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	8	**Mode Transport:**	Highway
Commodity Short Nm:	ACETIC ACID, GLACIAL OR	**Transport Phase:**	Unloading
Commodity Long Nm:	ACETIC ACID, GLACIAL OR ACETIC ACID SOLUTION, WITH MORE THAN 80 PERCENT ACID, BY MASS	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN2789	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	Fedex Ground Package System, Inc.
Qty Released:	0.007812	**CR Street Name:**	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	**CR City:**	Moon Township
What Failed:	109	**CR State:**	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	**CR Postal Code:**	15108

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

How Failed Code:	308	**CR Non US State:**	
How Failed Desc:	Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	526	**CR Hazmat Reg ID:**	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	international supplies
Cont1 Pkging Type:	Box	**Shipper Street Name:**	945 west hyde park blvd
Cont1 Const Mat:	Fiberboard	**Shipper City:**	Inglewood
Cont1 Head Type:		**Shipper State:**	CA
Cont1 Pkg Capacity:	0	**Shipper Postal:**	90302
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	164785621564825494
Cont1 Pkg No:	0	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	0	**Origin City:**	
Cont1 Pkg Mnfctr:		**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	
C1 Test Const Mat:	Fiberboard	**Destination City:**	SANTA ROSA
C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95401
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	Bottle
C1 Head Thick UOM:		**Cont2 Const Mat:**	Plastic
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	0
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	0
C1 Device Model:		**Cont2 Pkg No Failed:**	0
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	GEORGE FETSKO
Damage > 500:	No	**Contact Title:**	HAZMAT - SAFETY ADVISOR
Material Loss:	0	**Contact Business:**	Fedex Ground Package System, Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	CORAOPOLIS
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No

Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	BOX FIBER
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2016080218	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2016-07-13	**Report Submit Src:**	XML
Time of Incident:	0415	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	8	**Mode Transport:**	Highway
Commodity Short Nm:	SULFURIC ACID WITH NOT M	**Transport Phase:**	Unloading
Commodity Long Nm:	SULFURIC ACID WITH NOT MORE THAN 51% ACID	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN2796	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	Fedex Ground Package System, Inc.
Qty Released:	0.03125	**CR Street Name:**	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	**CR City:**	Moon Township
What Failed:	109	**CR State:**	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	**CR Postal Code:**	15108
How Failed Code:	305	**CR Non US State:**	
How Failed Desc:	Crushed	**CR Fed DOT ID:**	265752
Failure Cause Code:	517	**CR Hazmat Reg ID:**	051910551007S
Failure Cause Desc:	Improper Preparation for Transportation	**CR Country:**	US
Ident. Markings:	4G/Y16.7/S/15USA/+CA0562	**Shipper Name:**	Ricca Chemical Co
Cont1 Pkging Type:		**Shipper Street Name:**	448 W Fork Dr
Cont1 Const Mat:		**Shipper City:**	Arlington
Cont1 Head Type:		**Shipper State:**	TX
Cont1 Pkg Capacity:	0	**Shipper Postal:**	76012
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	283761583491765620
Cont1 Pkg No:	0	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	0	**Origin City:**	
Cont1 Pkg Mnfctr:		**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	
C1 Test Const Mat:		**Destination City:**	GEYSERVILLE
C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95441
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	
C1 Head Thick UOM:		**Cont2 Const Mat:**	
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	0
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	0
C1 Device Model:		**Cont2 Pkg No Failed:**	0

NRC No:

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	Yes	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	GEORGE FETSKO
Damage > 500:	No	***Contact Title:***	HAZMAT - SAFETY ADVISOR
Material Loss:	0	***Contact Business:***	Fedex Ground Package System, Inc.
Carrier Damage:	0	***Contact Street:***	1000 Fedex Drive
Property Damage:	0	***Contact City:***	CORAOPOLIS
Response Cost:	0	***Contact State:***	PA
Remediation Cost:	0	***Contact Postal:***	15108
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	0	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	Carrier
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No
Hazmat Injury:	No	***HMIS Bulk Release:***	No
Haz Hospital Empl:	0	***HMIS Marine Pollutnt:***	No
Haz Hospital Resp:	0	***HMIS Radioactive:***	No
Haz Hosp Gen Public:	0	***HMIS Gen Pkg Type:***	BOX FIBER
Haz Hosp Old Form:	0	***HMIS Container Code:***	4G
Total Haz Hosp Inj:	0	***HMIS Container Desc:***	Fiberboard box
Haz Non Hosp Empl:	0	***HMIS Bulk Incident:***	No
Haz Non Hosp Resp:	0	***Undeclared Shipment:***	No

Description of Events: The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2018080369	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	2018-07-12	***Report Submit Src:***	XML
Time of Incident:	2000	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	5.1	***Mode Transport:***	Highway
Commodity Short Nm:	HYDROGEN PEROXIDE AND PE	***Transport Phase:***	Unloading
Commodity Long Nm:	HYDROGEN PEROXIDE AND PEROXYACETIC ACID MIXTURES, STABILIZED WITH ACIDS, WATER, AND NOT MORE THAN 5 PERCENT PEROXYACETIC ACID	***Incident Occrrnce:***	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN3149	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	Fedex Ground Package System, Inc.
Qty Released:	0.001	**CR Street Name:**	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	**CR City:**	CORAOPOLIS
What Failed:	159	**CR State:**	PA
What Failed Desc:	Vent	**CR Postal Code:**	15108
How Failed Code:	308	**CR Non US State:**	
How Failed Desc:	Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	535	**CR Hazmat Reg ID:**	051910551007S
Failure Cause Desc:	Valve Open	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	Forestry Dist
Cont1 Pkging Type:	Box	**Shipper Street Name:**	1025 Delaware Ave
Cont1 Const Mat:	Fiberboard	**Shipper City:**	LONGMONT
Cont1 Head Type:		**Shipper State:**	CO
Cont1 Pkg Capacity:	0	**Shipper Postal:**	80501
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	178940416432337528
Cont1 Pkg No:	0	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	0	**Origin City:**	
Cont1 Pkg Mnfctr:		**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	US
C1 Test Const Mat:	Fiberboard	**Destination City:**	SANTA ROSA
C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95407
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	Bottle
C1 Head Thick UOM:		**Cont2 Const Mat:**	Plastic
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	0
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	0
C1 Device Model:		**Cont2 Pkg No Failed:**	0
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	GEORGE FETSKO
Damage > 500:	No	**Contact Title:**	HAZMAT - SAFETY ADVISOR
Material Loss:	0	**Contact Business:**	Fedex Ground Package System, Inc.

Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	CORAOPOLIS
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	BOX FIBER
Haz Hosp Old Form:	0	**HMIS Container Code:**	4G
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: Original comments: Outbound manager found on shelf on vehicle that the driver had brought back, with orientation arrows not in the upright position. Item was leaking out of the release valve. New Comments:

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2016090017	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2016-08-03	**Report Submit Src:**	XML
Time of Incident:	0700	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	8	**Mode Transport:**	Highway
Commodity Short Nm:	CORROSIVE LIQUID, ACIDIC	**Transport Phase:**	Unloading
Commodity Long Nm:	CORROSIVE LIQUID, ACIDIC, INORGANIC, N.O.S.	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN3264	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	Fedex Ground Package System, Inc.
Qty Released:	0.023438	**CR Street Name:**	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	**CR City:**	Moon Township
What Failed:	109	**CR State:**	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	**CR Postal Code:**	15108
How Failed Code:	308	**CR Non US State:**	
How Failed Desc:	Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	511	**CR Hazmat Reg ID:**	051910551007S
Failure Cause Desc:	Dropped	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	NuGenTec
Cont1 Pkging Type:	Box	**Shipper Street Name:**	1155 Park Ave
Cont1 Const Mat:	Fiberboard	**Shipper City:**	Emeryville
Cont1 Head Type:		**Shipper State:**	CA
Cont1 Pkg Capacity:	0	**Shipper Postal:**	94608
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	76893877429
Cont1 Pkg No:	0	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	0	**Origin City:**	
Cont1 Pkg Mnfctr:		**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	
C1 Test Const Mat:	Fiberboard	**Destination City:**	LARKFIELD
C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95403
C1 Pkg Shell Thick:	0	**Destination Non US:**	

C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	Bottle
C1 Head Thick UOM:		**Cont2 Const Mat:**	Plastic
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	0
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	0
C1 Device Model:		**Cont2 Pkg No Failed:**	0
NRC No:			
RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	GEORGE FETSKO
Damage > 500:	No	**Contact Title:**	HAZMAT - SAFETY ADVISOR
Material Loss:	0	**Contact Business:**	Fedex Ground Package System, Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	CORAOPOLIS
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	BOX FIBER
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2016060118	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2016-05-04	**Report Submit Src:**	XML

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Time of Incident:	0530	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	8	**Mode Transport:**	Highway
Commodity Short Nm:	SODIUM HYDROXIDE, SOLUTI	**Transport Phase:**	Unloading
Commodity Long Nm:	SODIUM HYDROXIDE, SOLUTION	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1824	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	Fedex Ground Package System, Inc.
Qty Released:	0.023438	**CR Street Name:**	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	**CR City:**	Moon Township
What Failed:	109	**CR State:**	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	**CR Postal Code:**	15108
How Failed Code:	308	**CR Non US State:**	
How Failed Desc:	Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	521	**CR Hazmat Reg ID:**	051910551007S
Failure Cause Desc:	Inadequate Preparation for Transportation	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	Aqua Solutions Inc
Cont1 Pkging Type:	Box	**Shipper Street Name:**	6913 hwy 225
Cont1 Const Mat:	Fiberboard	**Shipper City:**	Deer Park
Cont1 Head Type:		**Shipper State:**	TX
Cont1 Pkg Capacity:	0	**Shipper Postal:**	77536
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	60695430
Cont1 Pkg No:	0	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	0	**Origin City:**	
Cont1 Pkg Mnfctr:		**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	
C1 Test Const Mat:	Fiberboard	**Destination City:**	SAINT HELENA
C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	94574
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	Bottle
C1 Head Thick UOM:		**Cont2 Const Mat:**	Plastic
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	0
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	0
C1 Device Model:		**Cont2 Pkg No Failed:**	0
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No

Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	GEORGE FETSKO
Damage > 500:	No	**Contact Title:**	HAZMAT - SAFETY ADVISOR
Material Loss:	0	**Contact Business:**	Fedex Ground Package System, Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	CORAOPOLIS
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	BOX FIBER
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2015070444	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2015-07-08	**Report Submit Src:**	XML
Time of Incident:	0635	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	5.1	**Mode Transport:**	Highway
Commodity Short Nm:	HYDROGEN PEROXIDE AND PE	**Transport Phase:**	Unloading
Commodity Long Nm:	HYDROGEN PEROXIDE AND PEROXYACETIC ACID MIXTURES, STABILIZED WITH ACIDS, WATER, AND NOT MORE THAN 5 PERCENT PEROXYACETIC ACID	**Incident Occrrnce:**	
Trade Name:	stabilized	**Mat Ship Approval?:**	No
ID No:	UN3149	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	Fedex Ground Package System, Inc.
Qty Released:	0.016511	**CR Street Name:**	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	**CR City:**	Moon Township
What Failed:	109	**CR State:**	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	**CR Postal Code:**	15108
How Failed Code:	308	**CR Non US State:**	
How Failed Desc:	Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	526	**CR Hazmat Reg ID:**	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	Medivators
Cont1 Pkging Type:	Box	**Shipper Street Name:**	14605 28th Ave. N
Cont1 Const Mat:	Fiberboard	**Shipper City:**	Minneapolis
Cont1 Head Type:		**Shipper State:**	MN
Cont1 Pkg Capacity:	0	**Shipper Postal:**	55447
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	91101234888487
Cont1 Pkg No:	0	**Ship Hazmat Reg ID:**	

C1 Pkg NO Failed:	0	**Origin City:**	
Cont1 Pkg Mnfctr:		**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	
C1 Test Const Mat:	Fiberboard	**Destination City:**	LARKFIELD
C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95403
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	Bottle
C1 Head Thick UOM:		**Cont2 Const Mat:**	Plastic
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	0
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	0
C1 Device Model:		**Cont2 Pkg No Failed:**	0
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	GEORGE FETSKO
Damage > 500:	No	**Contact Title:**	HAZMAT - SAFETY ADVISOR
Material Loss:	0	**Contact Business:**	Fedex Ground Package System, Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	CORAOPOLIS
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	BOX FIBER
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was

wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2016060138	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	2016-05-05	***Report Submit Src:***	XML
Time of Incident:	0600	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	3	***Mode Transport:***	Highway
Commodity Short Nm:	ETHANOL OR ETHYL ALCOHOL	***Transport Phase:***	Unloading
Commodity Long Nm:	ETHANOL OR ETHYL ALCOHOL OR ETHANOL SOLUTIONS OR ETHYL ALCOHOL SOLUTIONS	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1170	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	II
TIH Hazard Zone:		***Carrier Reporter:***	Fedex Ground Package System, Inc.
Qty Released:	0.070312	***CR Street Name:***	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	***CR City:***	Moon Township
What Failed:	109	***CR State:***	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	***CR Postal Code:***	15108
How Failed Code:	308	***CR Non US State:***	
How Failed Desc:	Leaked	***CR Fed DOT ID:***	265752
Failure Cause Code:	526	***CR Hazmat Reg ID:***	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	Save On Scents
Cont1 Pkging Type:	Jerrican	***Shipper Street Name:***	388 3rd ave
Cont1 Const Mat:	Plastic	***Shipper City:***	Brooklyn
Cont1 Head Type:		***Shipper State:***	NY
Cont1 Pkg Capacity:	0	***Shipper Postal:***	11215
C1 Capacity UOM:		***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	58316111
Cont1 Pkg No:	0	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	0	***Origin City:***	
Cont1 Pkg Mnfctr:		***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	
C1 Test Const Mat:	Plastic	***Destination City:***	SANTA ROSA
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	95407
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No

RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	GEORGE FETSKO
Damage > 500:	No	**Contact Title:**	HAZMAT - SAFETY ADVISOR
Material Loss:	0	**Contact Business:**	Fedex Ground Package System, Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	CORAOPOLIS
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	CONTAINER
Haz Hosp Old Form:	0	**HMIS Container Code:**	CONT
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Container, no description given (do not use if at all possible)
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2016080479	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2016-07-22	**Report Submit Src:**	XML
Time of Incident:	0500	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	8	**Mode Transport:**	Highway
Commodity Short Nm:	CORROSIVE LIQUID, BASIC,	**Transport Phase:**	Unloading
Commodity Long Nm:	CORROSIVE LIQUID, BASIC, INORGANIC, N.O.S.	**Incident Occrrnce:**	
Trade Name:	sodium toltraizole/s	**Mat Ship Approval?:**	No
ID No:	UN3266	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	Fedex Ground Package System, Inc.
Qty Released:	0.007812	**CR Street Name:**	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	**CR City:**	Moon Township
What Failed:	104	**CR State:**	PA
What Failed Desc:	Body	**CR Postal Code:**	15108
How Failed Code:	309	**CR Non US State:**	
How Failed Desc:	Punctured	**CR Fed DOT ID:**	265752
Failure Cause Code:	516	**CR Hazmat Reg ID:**	051910551007S
Failure Cause Desc:	Impact with Sharp or Protruding Object (e.g.,	**CR Country:**	US

nails)

Ident. Markings:		***Shipper Name:***	Mohawk Labs
Cont1 Pkging Type:	Jerrican	***Shipper Street Name:***	932 Kifer Rd
Cont1 Const Mat:	Plastic	***Shipper City:***	Onizuka Afb
Cont1 Head Type:		***Shipper State:***	CA
Cont1 Pkg Capacity:	0	***Shipper Postal:***	94088
C1 Capacity UOM:		***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	95150272305698
Cont1 Pkg No:	0	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	0	***Origin City:***	
Cont1 Pkg Mnfctr:		***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	
C1 Test Const Mat:	Plastic	***Destination City:***	GEYSERVILLE
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	95441
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0
Explosion Result:	No	***Weather Conditions:***	
Water Sewer Result:	No	***Vehicle Overturn:***	No
Gas Dispersion:	No	***Vehicle Left Roadway:***	No
Environment Damage:	No	***Passenger Aircraft:***	No
No Release Result:	No	***Cargo Baggage:***	
Fire EMS Report:	No	***Ship Non Transport:***	No
Fire EMS EMS Report:		***Ship Air First Flight:***	No
Police Report:	No	***Ship Air Subflight:***	No
Police Report No:		***Ship Init Transport:***	No
In House Cleanup:	Yes	***Ship Phase Transfer:***	No
Other Cleanup:	No	***Contact Name:***	GEORGE FETSKO
Damage > 500:	No	***Contact Title:***	HAZMAT - SAFETY ADVISOR
Material Loss:	0	***Contact Business:***	Fedex Ground Package System, Inc.
Carrier Damage:	0	***Contact Street:***	1000 Fedex Drive
Property Damage:	0	***Contact City:***	CORAOPOLIS
Response Cost:	0	***Contact State:***	PA
Remediation Cost:	0	***Contact Postal:***	15108
Damage Old Form:	0	***Contact Non US St:***	
Total Damages Amt:	0	***Contact Country:***	US
Hazmat Fatality:	No	***Inc. Report Prepared:***	Carrier
Haz Fatal Employees:	0	***HMIS Serious Incidnt:***	No
Haz Fatal Respndrs:	0	***HMIS Serious Fatality:***	No
Haz Fatal Gen Public:	0	***HMIS Serious Injury:***	No
Tot Hazmat Fatalities:	0	***HMIS Flight Plan:***	No
Non Hazmat Fatality:	No	***HMIS Serious Evacs:***	No
Non Hazmat Fatals:	0	***HMIS Major Artery:***	No

Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	CONTAINER
Haz Hosp Old Form:	0	**HMIS Container Code:**	CONT
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Container, no description given (do not use if at all possible)
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2016120667	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2016-12-16	**Report Submit Src:**	XML
Time of Incident:	0400	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	8	**Mode Transport:**	Highway
Commodity Short Nm:	HYPOCHLORITE SOLUTIONS	**Transport Phase:**	Unloading
Commodity Long Nm:	HYPOCHLORITE SOLUTIONS	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1791	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	Fedex Ground Package System, Inc.
Qty Released:	0.02	**CR Street Name:**	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	**CR City:**	Moon Township
What Failed:	109	**CR State:**	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	**CR Postal Code:**	15108
How Failed Code:	309	**CR Non US State:**	
How Failed Desc:	Punctured	**CR Fed DOT ID:**	265752
Failure Cause Code:	526	**CR Hazmat Reg ID:**	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	RMR Solutions
Cont1 Pkging Type:	Box	**Shipper Street Name:**	201 Appian Ways # 202
Cont1 Const Mat:	Fiberboard	**Shipper City:**	Brighton
Cont1 Head Type:		**Shipper State:**	MI
Cont1 Pkg Capacity:	0	**Shipper Postal:**	48116
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	7566618706142151320
Cont1 Pkg No:	0	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	0	**Origin City:**	
Cont1 Pkg Mnfctr:		**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	
C1 Test Const Mat:	Fiberboard	**Destination City:**	SANTA ROSA
C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95407
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	Bottle
C1 Head Thick UOM:		**Cont2 Const Mat:**	Plastic
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	0
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	0
C1 Device Model:		**Cont2 Pkg No Failed:**	0
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	GEORGE FETSKO
Damage > 500:	No	**Contact Title:**	HAZMAT - SAFETY ADVISOR
Material Loss:	0	**Contact Business:**	Fedex Ground Package System, Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	CORAOPOLIS
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	BOX FIBER
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2016110571	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2016-10-26	**Report Submit Src:**	XML
Time of Incident:	0530	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	8	**Mode Transport:**	Highway
Commodity Short Nm:	SODIUM HYDROXIDE, SOLUTI	**Transport Phase:**	Unloading
Commodity Long Nm:	SODIUM HYDROXIDE, SOLUTION	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1824	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	Fedex Ground Package System, Inc.
Qty Released:	0.007809	**CR Street Name:**	1000 Fedex Drive

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Unit of Measure:	Liquid - Gallon	**CR City:**	Moon Township
What Failed:	109	**CR State:**	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	**CR Postal Code:**	15108
How Failed Code:	308	**CR Non US State:**	
How Failed Desc:	Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	517	**CR Hazmat Reg ID:**	051910551007S
Failure Cause Desc:	Improper Preparation for Transportation	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	Ecolab
Cont1 Pkging Type:	Drum	**Shipper Street Name:**	13277 San Bernadino Ave
Cont1 Const Mat:	Plastic	**Shipper City:**	Fontana
Cont1 Head Type:		**Shipper State:**	CA
Cont1 Pkg Capacity:	0	**Shipper Postal:**	92335
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	595080273768541
Cont1 Pkg No:	0	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	0	**Origin City:**	
Cont1 Pkg Mnfctr:		**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	US
C1 Test Const Mat:	Plastic	**Destination City:**	SANTA ROSA
C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95401
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	
C1 Head Thick UOM:		**Cont2 Const Mat:**	
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	0
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	0
C1 Device Model:		**Cont2 Pkg No Failed:**	0
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	GEORGE FETSKO
Damage > 500:	No	**Contact Title:**	HAZMAT - SAFETY ADVISOR
Material Loss:	0	**Contact Business:**	Fedex Ground Package System, Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	CORAOPOLIS
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier

Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	DRUM NON-METAL
Haz Hosp Old Form:	0	**HMIS Container Code:**	DRUM PLS
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Plastic drum
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2019070628	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2019-06-26	**Report Submit Src:**	XML
Time of Incident:	0540	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	8	**Mode Transport:**	Highway
Commodity Short Nm:	SODIUM HYDROXIDE, SOLUTI	**Transport Phase:**	Unloading
Commodity Long Nm:	SODIUM HYDROXIDE, SOLUTION	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1824	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	Fedex Ground Package System, Inc.
Qty Released:	0.26418	**CR Street Name:**	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	**CR City:**	CORAOPOLIS
What Failed:	109	**CR State:**	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	**CR Postal Code:**	15108
How Failed Code:	308	**CR Non US State:**	
How Failed Desc:	Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	526	**CR Hazmat Reg ID:**	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	**CR Country:**	US
Ident. Markings:	4g/y24.7/s/19/usa/m4172	**Shipper Name:**	Ecolab
Cont1 Pkging Type:	Box	**Shipper Street Name:**	13277 San Bernardino Ave
Cont1 Const Mat:	Fiberboard	**Shipper City:**	FONTANA
Cont1 Head Type:		**Shipper State:**	CA
Cont1 Pkg Capacity:	0	**Shipper Postal:**	92335
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	5950802494532995638
Cont1 Pkg No:	0	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	0	**Origin City:**	
Cont1 Pkg Mnfctr:		**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	US
C1 Test Const Mat:	Fiberboard	**Destination City:**	SAINT HELENA
C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	94574
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	
C1 Head Thick UOM:		**Cont2 Const Mat:**	
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	0
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	

C1 Device Mnfctr:		**Cont2 Pkg No:**	0
C1 Device Model:		**Cont2 Pkg No Failed:**	0
NRC No:			
RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	GEORGE FETSKO
Damage > 500:	No	**Contact Title:**	HAZMAT - SAFETY ADVISOR
Material Loss:	0	**Contact Business:**	Fedex Ground Package System, Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	CORAOPOLIS
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	BOX FIBER
Haz Hosp Old Form:	0	**HMIS Container Code:**	4G
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2015100341	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2015-09-28	**Report Submit Src:**	XML
Time of Incident:	0700	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	8	**Mode Transport:**	Highway
Commodity Short Nm:	CORROSIVE LIQUID, ACIDIC	**Transport Phase:**	Loading
Commodity Long Nm:	CORROSIVE LIQUID, ACIDIC, ORGANIC, N. O.S.	**Incident Occrrnce:**	
Trade Name:	(urea sulfate)	**Mat Ship Approval?:**	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

ID No:	UN3265	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	Fedex Ground Package System, Inc.
Qty Released:	1	**CR Street Name:**	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	**CR City:**	Moon Township
What Failed:	109	**CR State:**	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	**CR Postal Code:**	15108
How Failed Code:	308	**CR Non US State:**	
How Failed Desc:	Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	517	**CR Hazmat Reg ID:**	051910551007S
Failure Cause Desc:	Improper Preparation for Transportation	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	Ecolab
Cont1 Pkging Type:	Box	**Shipper Street Name:**	13277 San Bernadino Ave.
Cont1 Const Mat:	Fiberboard	**Shipper City:**	Fontana
Cont1 Head Type:		**Shipper State:**	CA
Cont1 Pkg Capacity:	0	**Shipper Postal:**	92335
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	595080272536073
Cont1 Pkg No:	0	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	0	**Origin City:**	
Cont1 Pkg Mnfctr:		**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	
C1 Test Const Mat:	Fiberboard	**Destination City:**	GEYSERVILLE
C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95441
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	Bottle
C1 Head Thick UOM:		**Cont2 Const Mat:**	Plastic
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	0
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	0
C1 Device Model:		**Cont2 Pkg No Failed:**	0
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	GEORGE FETSKO
Damage > 500:	No	**Contact Title:**	HAZMAT - SAFETY ADVISOR
Material Loss:	0	**Contact Business:**	Fedex Ground Package System, Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive

Property Damage:	0	**Contact City:**	CORAOPOLIS
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	BOX FIBER
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2014120370	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2014-12-03	**Report Submit Src:**	XML
Time of Incident:	0700	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	8	**Mode Transport:**	Highway
Commodity Short Nm:	CORROSIVE LIQUID, ACIDIC	**Transport Phase:**	Unloading
Commodity Long Nm:	CORROSIVE LIQUID, ACIDIC, INORGANIC, N.O.S.	**Incident Occrrnce:**	
Trade Name:	Nitric Acid, Phospho	**Mat Ship Approval?:**	No
ID No:	UN3264	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	Fedex Ground Package System, Inc.
Qty Released:	0.2	**CR Street Name:**	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	**CR City:**	Moon Township
What Failed:	109	**CR State:**	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	**CR Postal Code:**	15108
How Failed Code:	308	**CR Non US State:**	
How Failed Desc:	Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	526	**CR Hazmat Reg ID:**	051910551007S
Failure Cause Desc:	Loose Closure, Component, or Device	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	DELAVAL MANUFACTURING
Cont1 Pkging Type:	Box	**Shipper Street Name:**	1855 S MOUNT PROSPECT RD
Cont1 Const Mat:	Fiberboard	**Shipper City:**	DES PLAINES
Cont1 Head Type:		**Shipper State:**	IL
Cont1 Pkg Capacity:	0	**Shipper Postal:**	60018-1805
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	540109502482
Cont1 Pkg No:	0	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	0	**Origin City:**	
Cont1 Pkg Mnfctr:		**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	US
C1 Test Const Mat:	Fiberboard	**Destination City:**	PETALUMA
C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	94952
C1 Pkg Shell Thick:	0	**Destination Non US:**	

C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	Can
C1 Head Thick UOM:		**Cont2 Const Mat:**	Plastic
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	0
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	0
C1 Device Model:		**Cont2 Pkg No Failed:**	0
NRC No:			
RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	GEORGE FETSKO
Damage > 500:	No	**Contact Title:**	HAZMAT - SAFETY ADVISOR
Material Loss:	0	**Contact Business:**	Fedex Ground Package System, Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	CORAOPOLIS
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	BOX FIBER
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2013090103	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2013-08-13	**Report Submit Src:**	XML

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Time of Incident:	0435	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	3	**Mode Transport:**	Highway
Commodity Short Nm:	HEXANES	**Transport Phase:**	Unloading
Commodity Long Nm:	HEXANES	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1208	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	Fedex Ground Package System, Inc.
Qty Released:	1.05672	**CR Street Name:**	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	**CR City:**	Moon Township
What Failed:	104	**CR State:**	PA
What Failed Desc:	Body	**CR Postal Code:**	15108
How Failed Code:	304	**CR Non US State:**	
How Failed Desc:	Cracked	**CR Fed DOT ID:**	265752
Failure Cause Code:	517	**CR Hazmat Reg ID:**	051910551007S
Failure Cause Desc:	Improper Preparation for Transportation	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	Scientific Equipment of Housto
Cont1 Pkging Type:	Box	**Shipper Street Name:**	400 N. LaSalle
Cont1 Const Mat:	Fiberboard	**Shipper City:**	Navasota
Cont1 Head Type:		**Shipper State:**	TX
Cont1 Pkg Capacity:	0	**Shipper Postal:**	77868
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	530781315178245
Cont1 Pkg No:	0	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	0	**Origin City:**	
Cont1 Pkg Mnfctr:		**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	
C1 Test Const Mat:	Fiberboard	**Destination City:**	LARKFIELD
C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95403
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	Bottle
C1 Head Thick UOM:		**Cont2 Const Mat:**	
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	0
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	0
C1 Device Model:		**Cont2 Pkg No Failed:**	0
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No

Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	No	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	GEORGE FETSKO
Damage > 500:	No	**Contact Title:**	SAFETY PROCESS SPECIALIST I - HAZMAT
Material Loss:	0	**Contact Business:**	Fedex Ground Package System, Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	Moon Township
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	BOX FIBER
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2009040180	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2009-03-27	**Report Submit Src:**	XML
Time of Incident:	0700	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	2.2	**Mode Transport:**	Highway
Commodity Short Nm:	FIRE EXTINGUISHERS CONTA	**Transport Phase:**	In Transit
Commodity Long Nm:	FIRE EXTINGUISHERS CONTAINING COMPRESSED OR LIQUEFIED GAS	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1044	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	
TIH Hazard Zone:		**Carrier Reporter:**	Fedex Ground Package System, Inc.
Qty Released:	1	**CR Street Name:**	1000 Fedex Drive
Unit of Measure:	Solid - Pound	**CR City:**	MOON TOWNSHIP
What Failed:	126	**CR State:**	PA
What Failed Desc:	Hose Adaptor or Coupling	**CR Postal Code:**	15108
How Failed Code:	308	**CR Non US State:**	
How Failed Desc:	Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	521	**CR Hazmat Reg ID:**	062904001002M
Failure Cause Desc:	Inadequate Preparation for Transportation	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	hd supply
Cont1 Pkging Type:	Box	**Shipper Street Name:**	3050 ramco
Cont1 Const Mat:	Fiberboard	**Shipper City:**	WEST SACRAMENTO
Cont1 Head Type:		**Shipper State:**	CA
Cont1 Pkg Capacity:	0	**Shipper Postal:**	95691
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	13164997931182
Cont1 Pkg No:	0	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	0	**Origin City:**	
Cont1 Pkg Mnfctr:		**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	US
C1 Test Const Mat:	Fiberboard	**Destination City:**	SAINT HELENA
C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	94574
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	Cylinder
C1 Head Thick UOM:		**Cont2 Const Mat:**	Metal (any type)
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	0
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	0
C1 Device Model:		**Cont2 Pkg No Failed:**	0
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	TRAVIS MCEWEN
Damage > 500:	No	**Contact Title:**	SAFETY SPECIALIST III - HAZMAT
Material Loss:	0	**Contact Business:**	Fedex Ground Package System, Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	BOX FIBER
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the Fire Extinguisher(s) had a loose pin(s) with allowed leakage. The pin(s) were secured. The package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2009040161	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	2009-03-25	***Report Submit Src:***	XML
Time of Incident:	0700	***Inc Multiple Rows:***	No
Haz Class Code:		***Inc Non US State:***	
Hazardous Class:	3	***Mode Transport:***	Highway
Commodity Short Nm:	GASOLINE INCLUDES GASOLI	***Transport Phase:***	Unloading
Commodity Long Nm:	GASOLINE INCLUDES GASOLINE MIXED WITH ETHYL ALCOHOL, WITH NOT MORE THAN 10% ALCOHOL	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1203	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	Yes
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	II
TIH Hazard Zone:		***Carrier Reporter:***	Fedex Ground Package System, Inc.
Qty Released:	1	***CR Street Name:***	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	***CR City:***	MOON TOWNSHIP
What Failed:	128	***CR State:***	PA
What Failed Desc:	Inner Packaging	***CR Postal Code:***	15108
How Failed Code:	304	***CR Non US State:***	
How Failed Desc:	Cracked	***CR Fed DOT ID:***	265752
Failure Cause Code:	534	***CR Hazmat Reg ID:***	062904001002M
Failure Cause Desc:	Too Much Weight on Package	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	miamicycle
Cont1 Pkging Type:	Drum	***Shipper Street Name:***	13416 sw. 68 terrace
Cont1 Const Mat:	Plastic	***Shipper City:***	MIAMI
Cont1 Head Type:		***Shipper State:***	FL
Cont1 Pkg Capacity:	0	***Shipper Postal:***	33183
C1 Capacity UOM:		***Shipper Non US St:***	
Cont1 Pkg Amt:	0	***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	839906310001406
Cont1 Pkg No:	0	***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:	0	***Origin City:***	
Cont1 Pkg Mnfctr:		***Origin State:***	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	***Origin Postal:***	
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	***Origin Country:***	US
C1 Test Const Mat:	Plastic	***Destination City:***	SANTA ROSA
C1 Pkg Dsign Pres.:	0	***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	95407
C1 Pkg Shell Thick:	0	***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:	0	***Cont2 Package Type:***	
C1 Head Thick UOM:		***Cont2 Const Mat:***	
C1 Pkg Srvc Pres.:	0	***Cont2 Pkg Capacity:***	0
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	0
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	0
C1 Device Model:		***Cont2 Pkg No Failed:***	0
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:	0	***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:	0	***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No
Fire Result:	No	***Estimated Speed:***	0

Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	TRAVIS MCEWEN
Damage > 500:	No	**Contact Title:**	SAFETY SPECIALIST III - HAZMAT
Material Loss:	0	**Contact Business:**	Fedex Ground Package System, Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	DRUM NON-METAL
Haz Hosp Old Form:	0	**HMIS Container Code:**	DRUM PLS
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Plastic drum
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	Yes

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2008120315	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2008-12-18	**Report Submit Src:**	XML
Time of Incident:	0714	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	8	**Mode Transport:**	Highway
Commodity Short Nm:	SODIUM HYDROXIDE, SOLUTI	**Transport Phase:**	Unloading
Commodity Long Nm:	SODIUM HYDROXIDE, SOLUTION	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1824	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	Fedex Ground Package System, Inc.
Qty Released:	0.184926	**CR Street Name:**	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	**CR City:**	MOON TOWNSHIP
What Failed:	117	**CR State:**	PA
What Failed Desc:	Fill Hole	**CR Postal Code:**	15108
How Failed Code:	309	**CR Non US State:**	
How Failed Desc:	Punctured	**CR Fed DOT ID:**	265752
Failure Cause Code:	526	**CR Hazmat Reg ID:**	062904001002M
Failure Cause Desc:	Loose Closure, Component, or Device	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	labchem
Cont1 Pkging Type:	Box	**Shipper Street Name:**	200 william pitt way
Cont1 Const Mat:	Fiberboard	**Shipper City:**	PITTSBURGH
Cont1 Head Type:		**Shipper State:**	PA
Cont1 Pkg Capacity:	0	**Shipper Postal:**	15238

C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	15396431110558
Cont1 Pkg No:	0	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	0	**Origin City:**	
Cont1 Pkg Mnfctr:		**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	
C1 Test Const Mat:	Fiberboard	**Destination City:**	WINDSOR
C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95492
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	Bottle
C1 Head Thick UOM:		**Cont2 Const Mat:**	Plastic
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	0
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	0
C1 Device Model:		**Cont2 Pkg No Failed:**	0
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	TRAVIS MCEWEN
Damage > 500:	No	**Contact Title:**	SAFETY SPECIALIST III - HAZMAT
Material Loss:	0	**Contact Business:**	Fedex Ground Package System, Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	BOX FIBER
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Haz Non Hosp Empl: 0
Haz Non Hosp Resp: 0
HMIS Bulk Incident: No
Undeclared Shipment: No
Description of Events: The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.
Recommend Actions Taken:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
11	5 of 5	SSW	0.04 / 227.62	119.01 / -1	FEDEX GROUND PACKAGE SYSTEM INC 500 CALETTI AVE WINDSOR CA 95492	RCRA SQG

EPA Handler ID: CAR000239723
Gen Status Universe: Small Quantity Generator
Contact Name: GAYLYN FROSINI
Contact Address: 1000 FEDEX DRIVE , ENV SVCS , MOON TOWNSHIP , PA, 15108 , US
Contact Phone No and Ext: 412-262-7375
Contact Email: GAYLYN.FROSINI@FEDEX.COM
Contact Country: US
County Name: SONOMA
EPA Region: 09
Land Type: Private
Receive Date: 20130514
Location Latitude: 38.524062
Location Longitude: -122.793063

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20130514
Handler Name: FEDEX GROUND PACKAGE SYSTEM INC
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: 122
Waste Code Description: Alkaline solution without metals (pH > 12.5)

Hazardous Waste Code: 123

Waste Code Description: Unspecified alkaline solution

Hazardous Waste Code: 141
Waste Code Description: Off-specification, aged, or surplus inorganics

Hazardous Waste Code: 214
Waste Code Description: Unspecified solvent mixture

Hazardous Waste Code: 331
Waste Code Description: Off-specification, aged, or surplus organics

Hazardous Waste Code: 791
Waste Code Description: Liquids with pH < 2

Hazardous Waste Code: 792
Waste Code Description: Liquids with pH < 2 with metals

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: D005
Waste Code Description: BARIUM

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D035
Waste Code Description: METHYL ETHYL KETONE

Hazardous Waste Code: D039
Waste Code Description: TETRACHLOROETHYLENE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: U002
Waste Code Description: 2-PROPANONE (I) (OR) ACETONE (I)

Hazardous Waste Code: U117
Waste Code Description: ETHANE, 1,1'-OXYBIS-(I) (OR) ETHYL ETHER (I)

Hazardous Waste Code: U122
Waste Code Description: FORMALDEHYDE

Hazardous Waste Code: U159
Waste Code Description: 2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)

Hazardous Waste Code: U210
Waste Code Description: ETHENE, TETRACHLORO- (OR) TETRACHLOROETHYLENE

Hazardous Waste Code: U220
Waste Code Description: BENZENE, METHYL- (OR) TOLUENE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Hazardous Waste Code: U239
Waste Code Description: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: FEDEX GROUND PACKAGE SYSTEM INC
Date Became Current: 20080916
Date Ended Current:
Phone:
Source Type: Notification
Street No:
Street 1:
Street 2:
City:
State:
Country: US
Zip Code:

Owner/Operator Ind: Current Owner
Type: Private
Name: FEDEX GROUND PACKAGE SYSTEM INC
Date Became Current: 20080916
Date Ended Current:
Phone: 412-262-7375
Source Type: Notification
Street No:
Street 1: 1000 FEDEX DRIVE
Street 2: ENV SVCS
City: MOON TOWNSHIP
State: PA
Country: US
Zip Code: 15108

12	1 of 4	WNW	0.05 / 256.88	113.42 / -7	West Coast Metals 470 Caletti Av Windsor, CA 95492 CA	CUPA SONOMA

Facility ID: 49-000-004854
CERS ID: 10105861

Details

Program Type: Hazardous Waste
Permit Status: Active
Expiration Date: 5/25/2021
Fee Schedule: SQG > 325 gallons/year to <5 tons/year w/source reduction/recycle

Details

Program Type: HMBP
Permit Status: Active
Expiration Date: 5/25/2021
Fee Schedule: Range 5

Details

Program Type: APSA
Permit Status: Active
Expiration Date: 5/25/2021
Fee Schedule: Tier 1 Facility (> 1320 gallons, < 10000 gallons, no single tank > 5000 gals)

12	2 of 4	WNW	0.05 / 256.88	113.42 / -7	West Coast Metals 470 CALETTI AV WINDSOR CA 95492	CERS TANK

Site ID: 407501
Latitude: 38.525765
Longitude: -122.793680

Regulated Programs

EI ID: 10105861
EI Description: Aboveground Petroleum Storage

EI ID: 10105861

EI Description: Chemical Storage Facilities

EI ID: 10105861
EI Description: Hazardous Waste Generator

Violations

Violation Date: 03/20/2018
Violation Source: CERS
Violation Program: HMRRP
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Returned to compliance on 04/18/2018. Include the location of the fire sprinkler water shut off near main gate. Also include location of spill equipment. Update the site map and include the location of storm drains. There are several "blue squares" on the site/map but there is no legend for this symbol.

Violation Description:

Failure to complete and electronically submit a site map with all required content.

Violations

Violation Date: 03/20/2018
Violation Source: CERS
Violation Program: APSA
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: HSC 6.67 25270.4.5 (a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5 (a)
Violation Notes:

Returned to compliance on 05/09/2018. Provide training records for the last 3 years. Facility did not have any training records onsite and the consultant has the APSA/SPCC training records. Provide copies of employee training in the operation and maintenance of equipment i.e. annual spill prevention briefings.

Violation Description:

Failure to include in the SPCC plan an adequate description of employee training. Training shall address, at a minimum: operation and maintenance of equipment to prevent discharges; discharge procedure protocols; applicable pollution control laws, rules, and regulations; general facility operations; content of the facility SPCC plan; and annual discharge prevention briefings for oil-handling personnel to assure adequate understanding of the SPCC plan.

Violations

Violation Date: 03/20/2018
Violation Source: CERS
Violation Program: HW
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: 22 CCR 16 66266.81(a)(4)(B) - California Code of Regulations, Title 22, Chapter 16, Section(s) 66266.81(a)(4)(B)
Violation Notes:

Returned to compliance on 05/09/2018. Provide receipts on manifests for used motor oil disposed 2016 & 2017 and receipts/manifest for used filters for 2015, 2016 & 2017. Waste manifest/receipts for 2015 (*/-, 150 gallons of used motor oils) were on site but no receipts or manifests were on site for 2016 or 2017. Once receipt for use oil 500 gallons was provided. No receipts on manifest were on site for used drained oil filters.

Violation Description:

Failure to retain for at least three years a legible copy of each manifest or bill of lading which identifies spent lead-acid storage batteries shipped to a person who stores the batteries or who uses, reuses, recycles or reclaims the batteries or their components.

Violations

Violation Date: 03/20/2018
Violation Source: CERS
Violation Program: APSA
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Notes:

Returned to compliance on 05/23/2018. If inspection records can be found, provide records for the last 3 years. Records of inspections of the petroleum containers/tanks areas have not been completed. Begin documenting inspections of the petroleum storage areas at least once a month.

Violation Description:

Failure to comply with one or more of the following requirements:
1. Have record of inspections and integrity tests signed by the appropriate supervisor or inspector.
2. Keep written procedures and records of inspections and integrity tests for at least three years.
3. Keep comparison records.

Violations

Violation Date: 03/20/2018
Violation Source: CERS
Violation Program: HMRRP
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)
Violation Notes:

Returned to compliance on 05/09/2018. Provide employee training documentation for the last 3 years. Provide an employee training plan on hazardous materials spills, emergency evacuations, fire extinguishers, etc. Documentation of employee training was not available. According to the owner, the employee training documentation is with his consultant.

Violation Description:

Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.

Violations

Violation Date: 03/20/2018
Violation Source: CERS
Violation Program: HW
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)
Violation Notes:

Returned to compliance on 05/09/2018. Label all chemical containers and/or waste container. There are 2 -55 gallon drums near the 2 diesel tank, neither drum is labeled and both drums have liquid on them.

Violation Description:

Failure to properly label hazardous waste accumulation containers and portable tanks with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.

Violations

Violation Date: 03/20/2018
Violation Source: CERS
Violation Program: HMRRP
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Returned to compliance on 04/18/2018. Updated chemical quantities of propane, motor oil, hydraulic fluid, automatic transmission fluid & oxygen drums. Chemical inventory in CERS is incorrect, several chemicals listed have increased 100 percent or more and have not been updated in CERS.

Violation Description:

Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.

Violations

Violation Date: 03/20/2018
Violation Source: CERS
Violation Program: APSA
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Violation Notes:

Returned to compliance on 04/18/2018. Copy of SPCC require onsite. The location of the SPCC not available on site per Jack G. the consultant has a copy off-site.

Violation Description:

Failure to prepare a Spill Prevention, Control, and Countermeasures (SPCC) Plan.

Violations

Violation Date: 03/20/2018
Violation Source: CERS
Violation Program: APSA
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: HSC 6.67 25270.4.5 (a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5 (a)
Violation Notes:

Returned to compliance on 04/18/2018. Make amendments to the SPCC storage capacities. SPCC has not been amended for the change in motor oil, hydraulic fluid and automatic transmission fluid.

Violation Description:

Failure to amend the SPCC Plan within 6 months:
1. When the facility has had a change in design, construction, operation, or maintenance which affects the facility's discharge potential. AND/OR
2. To include more effective proven technology at the time of the 5-year SPCC Plan review and evaluation.

Evaluations

Eval Date: 01/19/2016
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Compliance OK; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/20/2018
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: APSA
Eval Source: CERS
Eval Notes:

See inspection for additional comments.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 01/19/2016
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

compliant; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/20/2018
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

See inspection for comments.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/20/2018
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

See written inspection for comments.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Affiliations

Affil Type Desc: Document Preparer
Entity Name: Greg Puccioni
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title:
Address: PO Box 791
City: Windsor
State: CA
Country:
Zip Code: 95492
Phone:

Affil Type Desc: Environmental Contact
Entity Name: Jack Gardner
Entity Title:
Address: PO Box 791
City: Windsor
State: CA
Country:
Zip Code: 95492
Phone:

Affil Type Desc: Property Owner
Entity Name: Shiloh Rd. LLC
Entity Title:
Address: PO Box 6132
City: Hicksville
State: NY
Country: United States
Zip Code: 11802
Phone: (925) 357-2011

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Affil Type Desc: Parent Corporation
Entity Name: West Coast Metals
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Identification Signer
Entity Name: Jack Gardner
Entity Title: Owner
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Legal Owner
Entity Name: Jack Gardner
Entity Title:
Address: PO Box 791
City: Windsor
State: CA
Country: United States
Zip Code: 95492
Phone: (707) 838-9731

Affil Type Desc: CUPA District
Entity Name: Sonoma County Fire Prevention and Hazmat
Entity Title:
Address: 2300 County Center Drive, Suite 220-B
City: Santa Rosa
State: CA
Country:
Zip Code: 95403
Phone: (707) 565-2024

Affil Type Desc: Operator
Entity Name: Jack Gardner
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone: (707) 838-9731

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
12	3 of 4	WNW	0.05 / 256.88	113.42 / -7	WEST COAST METALS 470 CALETTI AVE WINDSOR CA 95492-0000	RCRA NON GEN

EPA Handler ID: CAL000272499
Gen Status Universe: No Report
Contact Name: JACK GARDNER
Contact Address: PO BOX 791 , , WINDSOR , CA, 95492 ,
Contact Phone No and Ext: 707-838-9731
Contact Email: BROGARD@COMCAST.NET
Contact Country:
County Name: SONOMA
EPA Region: 09
Land Type:
Receive Date: 20030627
Location Latitude: 38.524325
Location Longitude: -122.793042

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20030627
Handler Name:	WEST COAST METALS
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street 1:***	PO BOX 791
Name:	JACK GARDNER	***Street 2:***	
Date Became Current:		***City:***	WINDSOR
Date Ended Current:		***State:***	CA
Phone:	707-838-9731	***Country:***	
Source Type:	Implementer	***Zip Code:***	95492-0000

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street 1:***	PO BOX 791
Name:	JACK GARDNER	***Street 2:***	
Date Became Current:		***City:***	WINDSOR
Date Ended Current:		***State:***	CA
Phone:	707-838-9731	***Country:***	
Source Type:	Implementer	***Zip Code:***	95492

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
12	4 of 4	WNW	0.05 / 256.88	113.42 / -7	BROGARD INC 470 CALETTI AVE WINDSOR CA 95492	RECYCLING

Cert ID:	RC11448	***Wednesday:***	7:00 am - 3:30 pm
Operation:	3/27/2003	***Thursday H:***	7:00 am - 3:30 pm
Rural:	Y	***Friday Hou:***	7:00 am - 3:30 pm
Organization:	BROGARD INC	***Saturday H:***	8:00 am - 3:30 pm
Aluminium:	Yes	***Sunday Hou:***	CLOSED
Glass:	Yes	***Mailing Ad:***	P O BOX 513
Plastic:	Yes	***Mailing Ci:***	WINDSOR
Bimetal:	Yes	***Mailing St:***	CA
Agency:	N/A	***Mailing Zi:***	95492

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Grand Fath:	N	**Phone No:**	(707) 462-4745
Cert Status:		**Website:**	
Operatione:		**Email:**	brogard@comcast.net
Monday Hou:	7:00 am - 3:30 pm	**Hours of Ope:**	MON - FRI 7:00 AM - 3:30 PM; SAT 8:00 AM - 2:30 PM; SUN CLOSED
Tuesday Ho:	7:00 am - 3:30 pm	**County:**	SONOMA

13	*1 of 4*	*NW*	*0.05 / 272.82*	*113.70 / -6*	***Ahlborn Structural Steel, Inc. - Pruitt*** ***5937 PRUITT AVE*** ***WINDSOR CA 95492***	***CERS HAZ***

Site ID:	431126
Latitude:	38.523557
Longitude:	-122.790564
County:	

Regulated Programs

EI ID:	10752481	**EI Description:**	Chemical Storage Facilities

Violations

Violation Date:	12/19/2017	**Violation Source:**	CERS
Violation Program:	HMRRP	**Violation Division:**	Sonoma County Fire & Emergency Services Department

Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Returned to compliance on 11/07/2018. The business failed to complete and electronically submit the Business Activities Page and/or Business Owner Operator Identification Page. Complete and electronically submit the Business Activities Page and/or Business Owner Operator Identification Page.

Violation Description:

Failure to complete and electronically submit the Business Activities Page and/or Business Owner Operator Identification Page.

Violations

Violation Date:	12/19/2017	**Violation Source:**	CERS
Violation Program:	HMRRP	**Violation Division:**	Sonoma County Fire & Emergency Services Department

Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Returned to compliance on 12/17/2018. The business failed to establish and electronically submit an adequate employee training plan, which is reasonable and appropriate for the size of the business and the nature of the hazardous material handled. Establish and electronically submit an adequate employee training plan, which is reasonable and appropriate for the size of the business and the nature of the hazardous material handled.

Violation Description:

Failure to establish and electronically submit an adequate training program in safety procedures in the event of a release or threatened release of a hazardous material.

Violations

Violation Date:	12/19/2017	**Violation Source:**	CERS
Violation Program:	HMRRP	**Violation Division:**	Sonoma County Fire & Emergency Services Department

Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Returned to compliance on 11/07/2018. The business failed to complete and electronically submit chemical inventory information for all reportable

hazardous materials on site at or above reportable quantities. Complete and electronically submit the chemical inventory information for all reportable hazardous materials on site at or above reportable quantities.

Violation Description:

Failure to complete and electronically submit hazardous material inventory information for all reportable hazardous materials on site at or above reportable quantities.

Violations

Violation Date: 12/19/2017
Violation Source: CERS
Violation Program: HMRRP
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Returned to compliance on 11/07/2018. The business failed to complete and electronically submit a site map with all required content including: north orientation, loading area, internal roads, adjacent streets, storm and sewer drains, access and exit points, emergency shut offs, evacuation staging area, hazardous materials/waste storage areas and emergency response equipment. Complete and electronically submit a site map with all required content.

Violation Description:

Failure to complete and electronically submit a site map with all required content.

Evaluations

Eval Date: 05/18/2021
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

No violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/19/2017
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

New facility as of 11/15/17. Provide a Hazardous Materials Business Plan online at the CERS website.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Affiliations

Affil Type Desc: Document Preparer
Entity Name: jennifer p reed
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Facility Mailing Address
Entity Name: Mailing Address

Entity Title:
Address: 1230 Century Ct
City: Santa Rosa
State: CA
Country:
Zip Code: 95403
Phone:

Affil Type Desc: CUPA District
Entity Name: Sonoma County Fire Prevention and Hazmat
Entity Title:
Address: 2300 County Center Drive, Suite 220-B
City: Santa Rosa
State: CA
Country:
Zip Code: 95403
Phone: (707) 565-2024

Affil Type Desc: Environmental Contact
Entity Name: Jennifer Reed
Entity Title:
Address: 1230 Century Ct
City: Santa Rosa
State: CA
Country:
Zip Code: 95403
Phone:

Affil Type Desc: Legal Owner
Entity Name: Tom Ahlborn
Entity Title:
Address: 1230 Century Ct.
City: Santa Rosa
State: CA
Country: United States
Zip Code: 95403
Phone: (707) 573-0742

Affil Type Desc: Property Owner
Entity Name: Dante Ghilotti
Entity Title:
Address: j.balter@ahlbornco.com
City: windsor
State: CA
Country: United States
Zip Code: 95492
Phone: (707) 837-1970

Affil Type Desc: Identification Signer
Entity Name: Jesse Balter
Entity Title: Safety Manager
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Parent Corporation
Entity Name: Ahlborn Fence & Steel, Inc.
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Operator

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Entity Name: Tom and Cathy Ahlborn
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone: (707) 573-0742

Coordinates

Env Int Type Code: HMBP
Program ID: 10752481
Latitude: 38.523560
Longitude: -122.790560
Coord Name:
Ref Point Type Desc: Center of a facility or station.

---

13 | 2 of 4 | NW | 0.05 / 272.82 | 113.70 / -6 | **Ahlborn Structural Steel, Inc. - Pruitt**
5937 Pruitt Ave Windsor, CA 95492
CA | CUPA SONOMA

Facility ID: 49-000-008550
CERS ID: 10752481

Details

Program Type: Stormwater
Permit Status: Active
Expiration Date: 8/30/2021
Fee Schedule: Storm Water Permit

Details

Program Type: HMBP
Permit Status: Active
Expiration Date: 8/30/2021
Fee Schedule: Range 3

---

13 | 3 of 4 | NW | 0.05 / 272.82 | 113.70 / -6 | **AHLBORN STRUCTURAL STEEL INC**
5937 PRUITT AVE
WINDSOR CA 95492 | RCRA NON GEN

EPA Handler ID: CAL000456688
Gen Status Universe: No Report
Contact Name: JESSE HUSTON
Contact Address: 1230 CENTURY CT , , SANTA ROSA , CA, 95403 ,
Contact Phone No and Ext: 707-495-5456
Contact Email: J.HUSTON@AHLBORNCO.COM
Contact Country:
County Name: SONOMA
EPA Region: 09
Land Type:
Receive Date: 20200909
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20200909
Handler Name:	AHLBORN STRUCTURAL STEEL INC
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street 1:***	1230 CENTURY CT
Name:	JESSE HUSTON	***Street 2:***	
Date Became Current:		***City:***	SANTA ROSA
Date Ended Current:		***State:***	CA
Phone:	707-495-5456	***Country:***	
Source Type:	Implementer	***Zip Code:***	95403
Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street 1:***	1230 CENTURY CT
Name:	AHLBORN STRUCTURAL STEEL INC	***Street 2:***	
Date Became Current:		***City:***	SANTA ROSA
Date Ended Current:		***State:***	CA
Phone:	707-573-0742	***Country:***	
Source Type:	Implementer	***Zip Code:***	95403

13	*4 of 4*	*NW*	*0.05 / 272.82*	*113.70 / -6*	***AHLBORN STEEL 4 FENCE 5937 PRUITT AVENUE WINDSOR CA 95492***	***EMISSIONS***

2019 Criteria Data

CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
Facility ID:	24217	***ROGT:***	1.1462305462869
District:	BA	***COT:***	
Facility SIC Code:	3523	***NOXT:***	
CO ID:	SON	***SOXT:***	
DISN:	BAY AREA AQMD		
PM10T:			
TOGT:	1.160269811		
PMT:			

2019 Toxic Data

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

CO: 49
Air Basin: SF
Faccility ID: 24217
District: BA
Facility SIC Code: 3523
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:
TS:
Health Risk Asmt:
NonCncrChrnicHazInd :
NonCncrActeHazInd:

---

14 | **1 of 5** | **NW** | **0.06 / 330.69** | **113.73 / -6** | **Northgate Ready Mix 5922 Pruitt Ave Windsor, CA 95492 CA** | **CUPA SONOMA**

Facility ID: 49-000-008181
CERS ID: 10472122

Details

Program Type: Stormwater
Permit Status: Active
Expiration Date: 3/8/2021
Fee Schedule: Storm Water Permit

Details

Program Type: Tiered Permits
Permit Status: Inactive
Expiration Date: 3/8/2021
Fee Schedule:

Details

Program Type: APSA
Permit Status: Active
Expiration Date: 3/8/2021
Fee Schedule: Tier 1 Facility (> 1320 gallons, < 10000 gallons, no single tank > 5000 gals)

Details

Program Type: Hazardous Waste
Permit Status: Active
Expiration Date: 3/8/2021
Fee Schedule: SQG > 325 gallons/year to <5 tons/year w/source reduction/recycle

Details

Program Type: HMBP
Permit Status: Active
Expiration Date: 3/8/2021
Fee Schedule: Range 5

---

14 | **2 of 5** | **NW** | **0.06 / 330.69** | **113.73 / -6** | **Northgate Ready Mix 5922 PRUITT AVE WINDSOR CA 95492** | **DELISTED HAZ**

Siteid: 138858
Latitude: 38.523493
Longitude: -122.790809
Original Source: CHAZ
Record Date: 04-JAN-2018

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
14	3 of 5	NW	0.06 / 330.69	113.73 / -6	NORTHGATE READY MIX 5922 PRUITT AVENUE WINDSOR CA 95492	EMISSIONS

2011 Criteria Data

Facility ID:	20297	***CERR Code:***	
Facility SIC Code:	3272	***TOGT:***	
CO:	49	***ROGT:***	
Air Basin:	SF	***COT:***	
District:	BA	***NOXT:***	
COID:	SON	***SOXT:***	
DISN:	BAY AREA AQMD	***PMT:***	0
CHAPIS:		***PM10T:***	0

2011 Toxic Data

Facility ID:	20297	***COID:***	SON
Facility SIC Code:	3272	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2012 Criteria Data

Facility ID:	20297	***CERR Code:***	
Facility SIC Code:	3272	***TOGT:***	
CO:	49	***ROGT:***	
Air Basin:	SF	***COT:***	
District:	BA	***NOXT:***	
COID:	SON	***SOXT:***	
DISN:	BAY AREA AQMD	***PMT:***	. 00108695652173913043478260869565217391 3043
CHAPIS:		***PM10T:***	.001

2012 Toxic Data

Facility ID:	20297	***COID:***	SON
Facility SIC Code:	3272	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2013 Criteria Data

Facility ID:	20297	***CERR Code:***	
Facility SIC Code:	3272	***TOGT:***	
CO:	49	***ROGT:***	
Air Basin:	SF	***COT:***	
District:	BA	***NOXT:***	
COID:	SON	***SOXT:***	

DISN:	BAY AREA AQMD	**PMT:**	.003
CHAPIS:		**PM10T:**	.001

2013 Toxic Data

Facility ID:	20297	**COID:**	SON
Facility SIC Code:	3272	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2014 Criteria Data

Facility ID:	20297	**CERR Code:**	
Facility SIC Code:	3272	**TOGT:**	
CO:	49	**ROGT:**	
Air Basin:	SF	**COT:**	
District:	BA	**NOXT:**	
COID:	SON	**SOXT:**	
DISN:	BAY AREA AQMD	**PMT:**	.000655282
CHAPIS:		**PM10T:**	.00060286

2014 Toxic Data

Facility ID:	20297	**COID:**	SON
Facility SIC Code:	3272	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2015 Criteria Data

Facility ID:	20297	**CERR Code:**	
Facility SIC Code:	3272	**TOGT:**	
CO:	49	**ROGT:**	
Air Basin:	SF	**COT:**	
District:	BA	**NOXT:**	
COID:	SON	**SOXT:**	
DISN:	BAY AREA AQMD	**PMT:**	.002871189
CHAPIS:		**PM10T:**	.002641493

2015 Toxic Data

Facility ID:	20297	**COID:**	SON
Facility SIC Code:	3272	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2016 Criteria Data

Facility ID:	20297	**CERR CODE:**	
Facility SIC Code:	3272	**TOGT:**	
CO:	49	**ROGT:**	
Air Basin:	SF	**COT:**	
District:	BA	**NOXT:**	
COID:	SON	**SOXT:**	
DISN:	BAY AREA AQMD	**PMT:**	.003371241
CHAPIS:		**PM10T:**	.003101541

2016 Toxic Data

Facility ID:	20297	**TS:**	
Facility SIC Code:	3272	**HRA:**	
CERR CODE:		**CH Index:**	
COID:	SON	**AH Index:**	
CO:	49	**Air Basin:**	SF
DISN:	BAY AREA AQMD	**District:**	BA
CHAPIS:			

2017 Criteria Data

Facility ID:	20297	**CERR Code:**	
Facility SIC Code:	3272	**TOGT:**	
CO:	49	**ROGT:**	
Air Basin:	SF	**COT:**	
District:	BA	**NOXT:**	
COID:	SON	**SOXT:**	
DISN:	BAY AREA AQMD	**PMT:**	.003945814
CHAPIS:		**PM10T:**	.003630149

2017 Toxic Data

Facility ID:	20297	**COID:**	SON
Facility SIC Code:	3272	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2018 Criteria Data

Facility ID:	20297	**CERR Code:**	
Facility SIC Code:	3272	**TOGT:**	
CO:	49	**ROGT:**	
Air Basin:	SF	**COT:**	
District:	BA	**NOXT:**	
COID:	SON	**SOXT:**	
DISN:	BAY AREA AQMD	**PMT:**	.006179728
CHAPIS:		**PM10T:**	.00568535

2018 Toxic Data

Facility ID:	20297	**COID:**	SON
Facility SIC Code:	3272	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			

Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

2019 Criteria Data

CO: 49
Air Basin: SF
Facility ID: 20297
District: BA
Facility SIC Code: 3272
CO ID: SON
DISN: BAY AREA AQMD
PM10T: .006937235
TOGT:
PMT: .007540473

CHAPIS:
CERR Code:
ROGT:
COT:
NOXT:
SOXT:

2019 Toxic Data

CO: 49
Air Basin: SF
Faccility ID: 20297
District: BA
Facility SIC Code: 3272
COID: SON
DISN: BAY AREA AQMD

CHAPIS:
CERR Code:
TS:
Health Risk Asmt:
NonCncrChrnicHazInd:
NonCncrActeHazInd:

14	4 of 5	NW	0.06 / 330.69	113.73 / -6	Northgate Ready Mix 5922 PRUITT AVE WINDSOR CA 95492	CERS TANK

Site ID: 138858
Latitude: 38.523547
Longitude: -122.790850

Regulated Programs

EI ID: 10472122
EI Description: Hazardous Waste Generator

EI ID: 10472122
EI Description: Aboveground Petroleum Storage

EI ID: 10472122
EI Description: Chemical Storage Facilities

EI ID: 110057106867
EI Description: US EPA Air Emission Inventory System (EIS)

Violations

Violation Date: 12/03/2013
Violation Program: HMRRP
Violation Source: CERS
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: HSC 6.95 25504(a) - California Health and Safety Code, Chapter 6.95, Section(s) 25504(a)
Violation Notes:

Returned to compliance on 12/31/2013.

Violation Description:

Failure to complete and/or submit hazardous material inventory forms for all reportable hazardous materials on site.

Violations

Violation Date: 12/03/2013 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Sonoma County Fire & Emergency Services Department
Citation: 19 CCR 4 2729.2(a)(1) - California Code of Regulations, Title 19, Chapter 4, Section(s) 2729.2(a)(1)
Violation Notes:

Returned to compliance on 12/31/2013.

Violation Description:

Owner/Operator failed to complete and/or submit the Business Activities Page and/or Business Owner Operator Identification Page.

Violations

Violation Date: 12/03/2013 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Sonoma County Fire & Emergency Services Department
Citation: HSC 6.95 25510 - California Health and Safety Code, Chapter 6.95, Section(s) 25510
Violation Notes:

Returned to compliance on 12/31/2013.

Violation Description:

Failure to update hazardous material inventory within 30 days when one of the following occurs:
A 100 percent or more increase in the quantity of a previously disclosed material.
Any handling of a previously undisclosed hazardous materials A change of business address, business ownership, or business name.

Violations

Violation Date: 08/17/2018 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** Sonoma County Fire & Emergency Services Department
Citation: HSC 6.5 25250.22 - California Health and Safety Code, Chapter 6.5, Section(s) 25250.22
Violation Notes:

Returned to compliance on 08/17/2018. Drum with drained used oil filters not marked with date of initial accumulation. Mark drum with drained used oil filters as "Drained Used Oil Filters" & note initial accumulation date.

Violation Description:

Failure to properly manage used oil and/or fuel filters in accordance with the requirements.

Violations

Violation Date: 12/03/2013 ***Violation Source:*** CERS
Violation Program: HW ***Violation Division:*** Sonoma County Fire & Emergency Services Department
Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)
Violation Notes:

Returned to compliance on 12/31/2013.

Violation Description:

Failure to properly label hazardous waste accumulation containers with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.

Violations

Violation Date: 12/06/2016 **Violation Source:** CERS
Violation Program: HMRRP **Violation Division:** Sonoma County Fire & Emergency Services Department
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Returned to compliance on 12/07/2016. Not all of the concrete chemicals were listed in CERS, i.e. cement, fly ash, additives, colors. Update the site map to include all chemical locations.

Violation Description:

Failure to complete and electronically submit a site map with all required content.

Violations

Violation Date: 08/17/2018 **Violation Source:** CERS
Violation Program: HW **Violation Division:** Sonoma County Fire & Emergency Services Department
Citation: 40 CFR 1 265.33 - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 265.33
Violation Notes:

Returned to compliance on 08/17/2018. Fire extinguisher by diesel tank without inspection tag; tag near haz waste/materials shed last inspected & tagged in May 2017. Have fire extinguishers inspected & tagged annually.

Violation Description:

Failure to test and maintain as necessary all facility communications or alarm systems, fire protection equipment, spill control equipment, and decontamination equipment to assure its proper operation in time of emergency.

Violations

Violation Date: 12/03/2013 **Violation Source:** CERS
Violation Program: HMRRP **Violation Division:** Sonoma County Fire & Emergency Services Department
Citation: 19 CCR 4 2729.2(a)(3) - California Code of Regulations, Title 19, Chapter 4, Section(s) 2729.2(a)(3)
Violation Notes:

Returned to compliance on 12/31/2013.

Violation Description:

Failure to complete and/or submit an annotated site map if required by CUPA.

Violations

Violation Date: 08/17/2018 **Violation Source:** CERS
Violation Program: HW **Violation Division:** Sonoma County Fire & Emergency Services Department
Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)
Violation Notes:

Returned to compliance on 08/17/2018. Drum with oily debris not marked with initial accumulation date. Mark all drums holding hazardous waste as "Hazardous Waste", with company name, address, contents & initial accumulation date clearly marked & visible for inspection.

Violation Description:

Failure to properly label hazardous waste accumulation containers and portable tanks with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.

Violations

Violation Date: 12/03/2013 **Violation Source:** CERS

Violation Program: HW **Violation Division:** Sonoma County Fire & Emergency Services Department
Citation: 22 CCR 16 66266.130 - California Code of Regulations, Title 22, Chapter 16, Section(s) 66266.130
Violation Notes:

Returned to compliance on 12/31/2013.

Violation Description:

Failure to properly handle, manage, label, and recycle used oil and fuel filters.

Violations

Violation Date: 12/03/2013 **Violation Source:** CERS
Violation Program: HW **Violation Division:** Sonoma County Fire & Emergency Services Department
Citation: 22 CCR 12 66262.40(a) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.40(a)
Violation Notes:

Returned to compliance on 12/31/2013.

Violation Description:

Failure to maintain uniform hazardous waste manifest, consolidated manifest, or bills of lading copies for three years.

Violations

Violation Date: 12/03/2013 **Violation Source:** CERS
Violation Program: HMRRP **Violation Division:** Sonoma County Fire & Emergency Services Department
Citation: HSC 6.95 25504(c) - California Health and Safety Code, Chapter 6.95, Section(s) 25504(c)
Violation Notes:

Returned to compliance on 12/31/2013.

Violation Description:

Failure to include provisions in the business plan to ensure that appropriate personnel receive initial and annual training.

Violations

Violation Date: 12/03/2013 **Violation Source:** CERS
Violation Program: HMRRP **Violation Division:** Sonoma County Fire & Emergency Services Department
Citation: HSC 6.95 25504(b) - California Health and Safety Code, Chapter 6.95, Section(s) 25504(b)
Violation Notes:

Returned to compliance on 12/31/2013.

Violation Description:

Failure to include adequate emergency response procedures in the business plan for a release or threatened release.

Violations

Violation Date: 12/03/2013 **Violation Source:** CERS
Violation Program: HMRRP **Violation Division:** Sonoma County Fire & Emergency Services Department
Citation: HSC 6.95 25503.5(a) - California Health and Safety Code, Chapter 6.95, Section(s) 25503.5(a)
Violation Notes:

Returned to compliance on 12/31/2013.

Violation Description:

Owner/Operator failed to establish and implement a Hazardous Materials Business Plan when storing hazardous materials at or above the thresholds quantities of 55 gallons/500 lbs/200 cubic feet.

Evaluations

Eval Date: 12/03/2013
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

Eval Date: 08/17/2018
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Conducted Hazardous Materials Business Plan (HMBP) inspection with Tom Easter. HMBP filed & certified in CERS on 1/28/18. Next CERS certification due by 1/28/19. Be sure to delete old, obsolete federal hazard categories & mark new federal hazard categories. Training conducted & documented (refresher training done 12/17 & initial training also documented). Walked facility & verified inventory.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/03/2013
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Eval Date: 08/17/2018
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: APSA
Eval Source: CERS
Eval Notes:

Reviewed SPCC & walked yard with Tom Easter. 3000-gal diesel tank OK. All water captured & re-used on-site. Daily & weekly inspections are conducted but not documented in writing. I recommend that you maintain written records of these inspections, especially for bulk petroleum storage. Employee training in hazmat procedures conducted & documented.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/06/2016
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

No hazardous waste violations were observed during the inspection.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/06/2016
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Eval Date: 08/17/2018
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

Conducted hazardous waste generator inspection with Tom Easter. Checked hazardous waste storage. Containers closed & labeled, although oily debris & used drained oil filters not marked with initial accumulation dates. Two fire extinguishers without current inspection tags (corrected on site). Checked manifests - OK. CAL000374302. Training conducted & documented. Daily & weekly yard inspections conducted although written records of inspections not maintained.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Affiliations

Affil Type Desc: CUPA District
Entity Name: Sonoma County Fire Prevention and Hazmat
Entity Title:
Address: 2300 County Center Drive, Suite 220-B
City: Santa Rosa
State: CA
Country:
Zip Code: 95403
Phone: (707) 565-2024

Affil Type Desc: Document Preparer
Entity Name: Dawn Soiland
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Identification Signer
Entity Name: Dawn Soiland
Entity Title: CFO
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Operator
Entity Name: Soiland Resources, LLC
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone: (707) 792-2443

Affil Type Desc: Environmental Contact

Entity Name: TROY SOILAND
Entity Title: ENVIRONMENTAL CONTACT
Address: 230 THERESA DRIVE
City: CLOVERDALE
State: CA
Country:
Zip Code:
Phone:

Affil Type Desc: Parent Corporation
Entity Name: Northgate Ready Mix
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Environmental Contact
Entity Name: Troy Soiland
Entity Title:
Address: 5922 Pruitt Avenue
City: Windsor
State: CA
Country:
Zip Code: 95492
Phone:

Affil Type Desc: Operator
Entity Name: SOILAND RESOURCES LLC
Entity Title: OPERATOR
Address: 5922 PRUITT AVENUE
City: WINDSOR
State: CA
Country:
Zip Code:
Phone:

Affil Type Desc: Legal Owner
Entity Name: Soiland Resources, LLC
Entity Title:
Address: 5922 Pruitt Avenue
City: Windsor
State: CA
Country: United States
Zip Code: 95492
Phone: (707) 792-2443

Affil Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title:
Address: 5922 Pruitt Avenue
City: Windsor
State: CA
Country:
Zip Code: 95492
Phone:

Affil Type Desc: Facility Owner
Entity Name: SOILAND RESOURCES LLC
Entity Title: OWNER
Address: 230 THERESA DRIVE
City: CLOVERDALE
State: CA
Country:
Zip Code:
Phone:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Coordinates

Env Int Type Code:	HWG	***Longitude:***	-122.790810
Program ID:	10472122	***Coord Name:***	
Latitude:	38.523490	***Ref Point Type Desc:***	Center of a facility or station.

14	***5 of 5***	***NW***	***0.06 / 330.69***	***113.73 / -6***	***NORTHGATE READY MIX 5922 PRUITT AVE WINDSOR CA 95492***	***RCRA NON GEN***

EPA Handler ID:	CAL000374302
Gen Status Universe:	No Report
Contact Name:	TOM EASTER
Contact Address:	5922 PRUITT AVE , , WINDSOR , CA, 95492 ,
Contact Phone No and Ext:	707-321-8437
Contact Email:	TOM@NORTHGATEREADYMIX.COM
Contact Country:	
County Name:	SONOMA
EPA Region:	09
Land Type:	
Receive Date:	20120507
Location Latitude:	38.523483
Location Longitude:	-122.790885

Violation/Evaluation Summary

Note:	NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20120507
Handler Name:	NORTHGATE READY MIX
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street 1:***	5922 PRUITT AVE
Name:	SOILAND RESOURCES LLC	***Street 2:***	
Date Became Current:		***City:***	WINDSOR

Date Ended Current:			**State:**	CA	
Phone:	707-836-9900		**Country:**		
Source Type:	Implementer		**Zip Code:**	95492-0000	
Owner/Operator Ind:	Current Operator		**Street No:**		
Type:	Other		**Street 1:**	5922 PRUITT AVE	
Name:	TOM EASTER		**Street 2:**		
Date Became Current:			**City:**	WINDSOR	
Date Ended Current:			**State:**	CA	
Phone:	707-321-8437		**Country:**		
Source Type:	Implementer		**Zip Code:**	95492	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
15	1 of 2	NW	0.07 / 357.53	114.06 / -6	SMCI Windsor Fire Remediation Processing 5885 Pruitt Ave. Windsor CA 95492	SWF/LF

SWIS No:	49-AA-0444	**Latitude:**	38.55
EPA Fed Registry ID:		**Longitude:**	-122.81667
Operational Status:	Closed	**County:**	Sonoma
Regulatory Status:	Notification	**Site ZIP:**	95492
Site is Archived:	Yes	**ARB District:**	Bay Area
Absorbed on:		**SWRCB Region:**	North Coast
Absorbed by:		**Site Point of Contact:**	Alyssa Williams

Site Inert Debris Eng Fill:	No
Closed Illegal Aband:	No
Closed Illegal Aband Cat:	
Finance Assuran Responsible:	No
Incorporated City:	Windsor
Local Government:	Windsor
Reporting Agency Legal Name:	County of Sonoma
Reporting Agency Department:	Department of Health Services, Environmental Health & Safety Section
Enforcing Agency Legal Name:	County of Sonoma
Enforcing Agency Department:	Department of Health Services, Environmental Health & Safety Section

Site Owners

Site Type:	Non-Disposal Only	**Contact Name:**	
Owner Name:	Kathleen Kurz	**Contact First Name:**	
Owner Address:	P.O. Box 1878	**Contact Last Name:**	
Owner City:	Windsor	**Contact Title:**	
Owner State:	CA	**Contact Email:**	
Owner ZIP Code:	95492	**Started On:**	
Owner Phone:	(707) 836-4336		

Site Operators

Site Type:	Non-Disposal Only	**Is Archived:**	Yes
Operator Name:	Sierra Mountain Construction, Inc.	**Contact Name:**	Doug Benton
Operator Address:	13919 Mono Way	**Contact First Name:**	Doug
Operator City:	Sonora	**Contact Last Name:**	Benton
Operator State:	CA	**Contact Title:**	
Operator ZIP Code:	95370	**Contact Email:**	
Operator Phone:	(209) 928-1900	**Started on:**	

Site Waste

Site Type:	Non-Disposal Only	**Activity Category:**	Composting
Waste Type:	Green Materials	**Act Classification:**	Solid Waste Facility
Activity Oper Status:	Closed	**Activity Is Archived:**	Yes
Act Regulatory Stat:	Notification		
Activity:	Chipping and Grinding Facility/Operation		

Site Type:	Non-Disposal Only	**Activity Category:**	Composting
Waste Type:	Wood waste	**Act Classification:**	Solid Waste Facility

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Activity Oper Status: Closed
Activity Is Archived: Yes
Act Regulatory Stat: Notification
Activity: Chipping and Grinding Facility/Operation

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
15	2 of 2	NW	0.07 / 357.53	114.06 / -6	SMCI Windsor Receiving Yard 5885 Pruitt Ave. Windsor CA 95492	SWF/LF

SWIS No: 49-AA-0443
EPA Fed Registry ID:
Operational Status: Closed
Regulatory Status: Notification
Site is Archived: Yes
Absorbed on:
Absorbed by:
Site Inert Debris Eng Fill: No
Closed Illegal Abandon: No
Closed Illegal Abandon Cat:
Finance Assuran Responsible: No
Incorporated City: Windsor
Local Government: Windsor
Reporting Agency Legal Name: County of Sonoma
Reporting Agency Department: Department of Health Services, Environmental Health & Safety Section
Enforcing Agency Legal Name: County of Sonoma
Enforcing Agency Department: Department of Health Services, Environmental Health & Safety Section

Latitude: 38.52392
Longitude: -122.79098
County: Sonoma
Site ZIP: 95492
ARB District: Bay Area
SWRCB Region: North Coast
Site Point of Contact: Alyssa Williams

Site Owners

Site Type: Non-Disposal Only
Owner Name: Kathleen Kurz
Owner Address: P.O. Box 1878
Owner City: Windsor
Owner State: CA
Owner ZIP Code: 95492
Owner Phone: (707) 836-4336

Contact Name:
Contact First Name:
Contact Last Name:
Contact Title:
Contact Email:
Started On:

Site Operators

Site Type: Non-Disposal Only
Operator Name: Sierra Mountain Construction, Inc.
Operator Address: 13919 Mono Way
Operator City: Sonora
Operator State: CA
Operator ZIP Code: 95370
Operator Phone: (209) 928-1900

Is Archived: Yes
Contact Name: Doug Benton
Contact First Name: Doug
Contact Last Name: Benton
Contact Title:
Contact Email:
Started on:

Site Waste

Site Type: Non-Disposal Only
Waste Type: Green Materials
Activity Oper Status: Closed
Act Regulatory Stat: Notification
Activity: Emergency Transfer/Processing Operation

Activity Category: Transfer/Processing
Act Classification: Solid Waste Operation
Activity Is Archived: Yes

Site Type: Non-Disposal Only
Waste Type: Wood waste
Activity Oper Status: Closed
Act Regulatory Stat: Notification
Activity: Emergency Transfer/Processing Operation

Activity Category: Transfer/Processing
Act Classification: Solid Waste Operation
Activity Is Archived: Yes

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
16	1 of 3	WNW	0.07 / 378.26	112.85 / -7	Quality Stainless Tanks 510 Caletti Ave, Windsor, CA 95492 CA	CUPA SONOMA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility ID: 49-000-005526 **CERS ID:** 10107019

Details

Program Type: HMBP
Permit Status: Active
Expiration Date: 3/27/2022
Fee Schedule: Range 3

16	2 of 3	WNW	0.07 / 378.26	112.85 / -7	Quality Stainless Tanks 510 Caletti Ave. WINDSOR, CA 95492 CA	DELISTED COUNTY

Original Source Facility ID:
Original Source Name: Sonoma County CUPA Facilities List
Record Date: 11-JAN-2016

16	3 of 3	WNW	0.07 / 378.26	112.85 / -7	Quality Stainless Tanks 510 CALETTI AVE WINDSOR CA 95492	CERS HAZ

Site ID: 145600
Latitude: 38.525765
Longitude: -122.793680
County:

Regulated Programs

EI ID: 10107019 **EI Description:** Chemical Storage Facilities

EI ID: 832743 **EI Description:** Industrial Facility Storm Water

Violations

Violation Date: 05/26/2016 **Violation Source:** CERS
Violation Program: HW **Violation Division:** Sonoma County Fire & Emergency Services Department
Citation: 22 CCR 12 66262.34(b)(1) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(b)(1)
Violation Notes:

Returned to compliance on 08/09/2016. The business had a diesel leak in December of 2015 and has not disposed of the waste. Dispose of the 6-55 gallon drums of Diesel contaminated soil.

Violation Description:

Failure to dispose of hazardous waste after the first 100-kilogram threshold amount was accumulated within a 90 day period.

Violations

Violation Date: 05/26/2016 **Violation Source:** CERS
Violation Program: HMRRP **Violation Division:** Sonoma County Fire & Emergency Services Department
Citation: HSC 6.95 25508.1(a)-(e) - California Health and Safety Code, Chapter 6.95, Section(s) 25508.1(a)-(e)
Violation Notes:

Returned to compliance on 06/11/2016. The business has expanded their operation to a new location at 5900 Pruitt Ave., Suite 108 and has not reported these additional compressed gases. Amend you chemical inventory to include the 32 compressed gas cylinders of welding gases at the new space.

Violation Description:

Failure to electronically update business plan within 30 days of any one of the following events:
A 100 percent or more increase in the quantity of a previously disclosed material.
Any handling of a previously undisclosed hazardous materials at or above reportable quantities.
A change of business address, business ownership, or business name.

Violations

Violation Date: 05/26/2016
Violation Source: CERS
Violation Program: HMRRP
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Returned to compliance on 06/11/2016. The business has leased additional space at an adjacent building but hasn't amended their site map in CERS. Revise the site map for the business to include the new space at 5900 Pruitt Ave., Suite 108.

Violation Description:

Failure to complete and electronically submit a site map with all required content.

Violations

Violation Date: 04/08/2014
Violation Source: CERS
Violation Program: HMRRP
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: HSC 6.95 25505(a) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)
Violation Notes:

Returned to compliance on 04/09/2014. CERS submittal.

Violation Description:

Owner/Operator failed to complete and/or submit a Hazardous Materials Business Plan when storing hazardous materials at or above the thresholds quantities of 55 gallons/500 lbs/200 cubic feet.

Evaluations

Eval Date: 12/14/2015
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Responded to a call about diesel leaking into the storm drain at this address. Quality Stainless had a diesel drum in containment that had sprung a leak, and the valve on the containment was open, allowing 25-45 gallons of diesel to leak out overnight. instructed owner to have cleanup contractor clean diesel-soaked soil and replace with clean fill. All violations are fire code under Rincon Valley Fire - failure to mark drum, Failure to use drum in good condition, failure to use secondary containment.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 05/26/2016
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Eval Date: 12/15/2015

Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

After responding to a release of diesel fuel from a deteriorating drum, found that facility violated fire code requirements for: 1) Failure to label hazardous materials 2) Failure to placard storage area 3) failure to use a good container 4) failure to provide secondary containment (valve on secondary was left open.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/26/2019
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

No HMBP violations; not a fire code inspection but 20 ft separation between acetylene and oxygen in storage was requested. Also, discussed the need for a Confined space program and training. Ben does do some training but they do not appear to have a formal program. To be discussed with management.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/08/2014
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Eval Date: 05/26/2016
Violations Found: Yes
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

Eval Date: 10/25/2016
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Construction Storm Water Compliance Evaluation
Eval Division: Water Boards
Eval Program: INDSTW
Eval Source: SMARTS
Eval Notes:

Site housekeeping excellent, with all manufacturing taking place under roof cover. Inlet protected with weighted gravel bags. Only exterior storage are finished stainless steel wine storage tanks.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/23/2015
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

Follow up visit to inspect cleanup of diesel-contaminated soil. All contaminated soil removed, will inspect later to review documentation.; Note: data in

[EVAL Notes] field for some records is truncated from the source.

Affiliations

Affil Type Desc: Parent Corporation
Entity Name: Quality Stainless Tanks
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: CUPA District
Entity Name: Sonoma County Fire Prevention and Hazmat
Entity Title:
Address: 2300 County Center Drive, Suite 220-B
City: Santa Rosa
State: CA
Country:
Zip Code: 95403
Phone: (707) 565-2024

Affil Type Desc: Owner/Operator
Entity Name: Richard Dapelo
Entity Title: Operator
Address: 510 Caletti Ave
City: Windsor
State: CA
Country:
Zip Code: 95492
Phone:

Affil Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title:
Address: 510 Caletti
City: Windsor
State: CA
Country:
Zip Code: 95492
Phone:

Affil Type Desc: Environmental Contact
Entity Name: Rick Dapelo
Entity Title:
Address: 510 Caletti Ave
City: Windsor
State: CA
Country:
Zip Code: 95492
Phone:

Affil Type Desc: Operator
Entity Name: Rick Dapelo
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone: (707) 837-2721

Affil Type Desc: Legal Owner
Entity Name: Mr. Rick Dapelo
Entity Title:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Address: 510 Caletti Ave
City: Windsor
State: CA
Country: United States
Zip Code: 95492
Phone: (707) 837-2721

Coordinates

Env Int Type Code: SMSWIND
Program ID: 832743
Latitude: 38.525770
Longitude: -122.793690
Coord Name:
Ref Point Type Desc: Unknown

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
17	1 of 1	NW	0.07 / 393.04	113.75 / -6	Standard Structures, Inc. 5910 Pruitt Ave Windsor, CA 95492 CA	DELISTED COUNTY

Original Source Facility ID:
Original Source Name: Sonoma County CUPA Facilities List
Record Date: 11-JAN-2016

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
18	1 of 3	NW	0.07 / 393.77	114.02 / -6	5900 pruiitt WINDSOR CA	HMIRS

Incident County: SONOMA

HMIR Historical Reports

Report No: X-2006060058
Report Type: A hazardous material incident
Date of Incident: 05/15/2006
Time of Incident: 0800
Haz Class Code: 8
Hazardous Class: CORROSIVE MATERIAL
Commodity Short Nm: CORROSIVE LIQUID ACIDIC
Commodity Long Nm: CORROSIVE LIQUID ACIDIC INORGANIC N. O.S.
Trade Name: SODIUM HYDROXIDE
ID No: UN3264
Haz Waste Ind: No
Haz Waste EPA No:
HMIS Tox Inhalation?: No
TIH Hazard Zone:
Qty Released: 0.039062
Unit of Measure: Liquid - Gallon
What Failed: 109
What Failed Desc: Closure (e.g. Cap Top or Plug)
How Failed Code: 308
How Failed Desc: Leaked
Failure Cause Code: 522
Failure Cause Desc: Inadequate Procedures
Ident. Markings:
Cont1 Pkging Type: Box
Cont1 Const Mat: Fiberboard
Cont1 Head Type:
Cont1 Pkg Capacity:
C1 Capacity UOM:
Cont1 Pkg Amt:
C1 Pkg Amt UOM:
Cont1 Pkg No:
C1 Pkg NO Failed:
Cont1 Pkg Mnfctr:
Cont1 Pkg Mnfct Dt:

Fed DOT Agency Nm:
Fed DOT Report No:
Report Submit Src: XML
Inc Multiple Rows: No
Inc Non US State:
Mode Transport: Highway
Transport Phase: LOADING
Incident Occrrnce:
Mat Ship Approval?: No
Mat Ship Approv No:
Undecl Hazmat Ship?: No
Packaging Type: Non-Bulk
Packing Group:
Carrier Reporter: FEDEX GROUND PACKAGE SYSTEM INC.
CR Street Name: 1000 FED EX DR
CR City: CORAOPOLIS
CR State: PA
CR Postal Code: 15108-9373
CR Non US State:
CR Fed DOT ID: 265752
CR Hazmat Reg ID: 062904001002M
CR Country: US
Shipper Name: CHEMPROBE COATING SYSTEMS LP
Shipper Street Name: 2805 INDUSTRIAL LN
Shipper City: GARLAND
Shipper State: TX
Shipper Postal: 75041-2306
Shipper Non US St:
Shipper Country: US
Shipper Waybill: 025130760014562
Ship Hazmat Reg ID:
Origin City: GARLAND
Origin State: TEXAS
Origin Postal: 75041

Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:	Fiberboard	**Destination City:**	ROHNERT PARK
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	94928
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	Bag
C1 Head Thick UOM:		**Cont2 Const Mat:**	Plastic
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	
C1 Device Model:		**Cont2 Pkg No Failed:**	
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:		**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	DENISE HANCHULAK
Damage > 500:	No	**Contact Title:**	TSM MANAGER II - SAFETY
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
18	2 of 3	NW	0.07 / 393.77	114.02 / -6	TDE Equipment INC 5900 PRUITT AVE STE 710 WINDSOR CA 95492	DELISTED HAZ

Siteid: 275750
Latitude: 38.521160
Longitude: -122.789880
Original Source: CHAZ
Record Date: 30-MAY-2017

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
18	3 of 3	NW	0.07 / 393.77	114.02 / -6	5900 pruiitt WINDSOR CA	HMIRS

Incident County: SONOMA

HMIR Incident Reports

Report No:	X-2006060058	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2006-05-15	**Report Submit Src:**	XML
Time of Incident:	0800	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	8	**Mode Transport:**	Highway
Commodity Short Nm:	CORROSIVE LIQUID, ACIDIC	**Transport Phase:**	Loading
Commodity Long Nm:	CORROSIVE LIQUID, ACIDIC, INORGANIC, N.O.S.	**Incident Occrrnce:**	
Trade Name:	SODIUM HYDROXIDE	**Mat Ship Approval?:**	No
ID No:	UN3264	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	
TIH Hazard Zone:		**Carrier Reporter:**	Fedex Ground Package System, Inc.
Qty Released:	0.039062	**CR Street Name:**	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	**CR City:**	MOON TOWNSHIP
What Failed:	109	**CR State:**	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	**CR Postal Code:**	15108
How Failed Code:	308	**CR Non US State:**	
How Failed Desc:	Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	522	**CR Hazmat Reg ID:**	062904001002M
Failure Cause Desc:	Inadequate Procedures	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	chemprobe
Cont1 Pkging Type:	Box	**Shipper Street Name:**	2805 industrial dr
Cont1 Const Mat:	Fiberboard	**Shipper City:**	GARLAND
Cont1 Head Type:		**Shipper State:**	TX
Cont1 Pkg Capacity:	0	**Shipper Postal:**	75041
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	025130760014562
Cont1 Pkg No:	0	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	0	**Origin City:**	
Cont1 Pkg Mnfctr:		**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	US
C1 Test Const Mat:	Fiberboard	**Destination City:**	ROHNERT PARK
C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	94928
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	Bag
C1 Head Thick UOM:		**Cont2 Const Mat:**	Plastic
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	0
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	0
C1 Device Model:		**Cont2 Pkg No Failed:**	0
NRC No:			
RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	DENISE HANCHULAK
Damage > 500:	No	**Contact Title:**	TSM MANAGER II - SAFETY
Material Loss:	0	**Contact Business:**	Fedex Ground Package System, Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	BOX FIBER
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

19	1 of 1	NNW	0.07 / 395.03	118.20 / -2	**QUIZNO'S SUBS** **6580 Hembree LN STE 260** **Windsor, CA 95492** **CA**	CUPA SONOMA

Facility ID: 49-000-007960 ***CERS ID:***

Details

Program Type: HMBP

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Permit Status: Inactive
Expiration Date: 12/31/2015
Fee Schedule: Range 8

20	1 of 2	NW	0.08 / 397.07	114.09 / -6	SHILOH OAKS COMPANY, LLC 5892 PRUITT AVE WINDSOR, CA 95492 CA	CUPA SONOMA

Facility ID: 49-000-008292 **CERS ID:** 10651117

Details

Program Type: APSA
Permit Status: Inactive
Expiration Date: 11/25/2016
Fee Schedule: Tier 1 Facility (> 1320 gallons, < 10000 gallons, no single tank > 5000 gals)

Details

Program Type: HMBP
Permit Status: Inactive
Expiration Date: 10/19/2016
Fee Schedule: Range 2

Details

Program Type: Hazardous Waste
Permit Status: Inactive
Expiration Date: 10/19/2016
Fee Schedule: SQG < 325 gallons/year

20	2 of 2	NW	0.08 / 397.07	114.09 / -6	FRIEDMAN'S D.Y. 5892 PRUITT AVE NO 300 WINDSOR CA 95492	RCRA NON GEN

EPA Handler ID: CAL000463758
Gen Status Universe: No Report
Contact Name: MIKE CURTIN
Contact Address: 3800 LAKEVILLE HWY , , PETALUMA , CA, 94954 ,
Contact Phone No and Ext: 707-769-5388
Contact Email: MCURTIN@FRIEDMANSHOME.COM
Contact Country:
County Name: SONOMA
EPA Region: 09
Land Type:
Receive Date: 20210630
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20210630
Handler Name: FRIEDMAN'S D.Y.
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Other
Name: MIKE CURTIN
Date Became Current:
Date Ended Current:
Phone: 707-769-5388
Source Type: Implementer
Street No:
Street 1: 3800 LAKEVILLE HWY
Street 2:
City: PETALUMA
State: CA
Country:
Zip Code: 94954

Owner/Operator Ind: Current Owner
Type: Other
Name: BARRY FRIEDMAN
Date Became Current:
Date Ended Current:
Phone: 707-328-3645
Source Type: Implementer
Street No:
Street 1: 1385 N MCDOWELL BLVD STE 100
Street 2:
City: PETALUMA
State: CA
Country:
Zip Code: 94954

21	1 of 4	NNW	0.09 / 451.10	120.96 / 1	HIGH TECH BURRITO 6560 HEMBREE LN STE 178 WINDSOR, CA 95492 CA	CUPA SONOMA

Facility ID: 49-000-007968
CERS ID:

Details

Program Type: HMBP
Permit Status: Inactive
Expiration Date: 12/31/2015
Fee Schedule: Range 8

21	2 of 4	NNW	0.09 / 451.10	120.96 / 1	SALLY BEAUTY SUPPLY #3859 6560 HEMBREE LN STE 186 WINDSOR CA 95492	RCRA NON GEN

EPA Handler ID: CAL000411992
Gen Status Universe: No Report
Contact Name: DEBBIE MIDDLETON
Contact Address: 3001 , COLORADO BLVD , , DENTON , TX, 76210 , US
Contact Phone No and Ext: 940-297-4964
Contact Email: DMIDDLETON@SALLYBEAUTY.COM
Contact Country: US

County Name:	SONOMA
EPA Region:	09
Land Type:	
Receive Date:	20210609
Location Latitude:	38.527434
Location Longitude:	-122.78885

Violation/Evaluation Summary

Note:	NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20151104
Handler Name:	SALLY BEAUTY SUPPLIES
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Hazardous Waste Handler Details

Sequence No:	2
Receive Date:	20210609
Handler Name:	SALLY BEAUTY SUPPLY #3859
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street 1:***	3001 COLORADO BLVD
Name:	RANDY GOSS	***Street 2:***	
Date Became Current:		***City:***	DENTON
Date Ended Current:		***State:***	TX
Phone:	940-898-7500	***Country:***	
Source Type:	Implementer	***Zip Code:***	76210

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street 1:***	3001 COLORADO BLVD
Name:	SALLY BEAUTY HOLDING LLC	***Street 2:***	
Date Became Current:		***City:***	DENTON
Date Ended Current:		***State:***	TX

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Phone: 940-898-7500
Source Type: Implementer

Owner/Operator Ind: Current Operator
Type: Other
Name: SALLY HOLDINGS LLC
Date Became Current:
Date Ended Current:
Phone: 940-898-7500
Source Type: Implementer

Country:
Zip Code: 76210

Street No: 3001
Street 1: COLORADO BLVD
Street 2:
City: DENTON
State: TX
Country: US
Zip Code: 76210

Historical Handler Details

Receive Dt: 20151104
Generator Code Description: Not a Generator, Verified
Handler Name: SALLY BEAUTY SUPPLIES

21	3 of 4	NNW	0.09 / 451.10	120.96 / 1	**Sally Beauty Supply #3859** **6560 HEMBREE LN STE 186** **WINDSOR CA 95492**	CERS HAZ

Site ID: 514126
Latitude: 38.527520
Longitude: -122.788860
County:

Regulated Programs

EI ID: 10781782
EI Description: Hazardous Waste Generator

Evaluations

Eval Date: 11/02/2020
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

No violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Affiliations

Affil Type Desc: CUPA District
Entity Name: Sonoma County Fire Prevention and Hazmat
Entity Title:
Address: 2300 County Center Drive, Suite 220-B
City: Santa Rosa
State: CA
Country:
Zip Code: 95403
Phone: (707) 565-2024

Affil Type Desc: Environmental Contact
Entity Name: Debbie Middleton, Environmental and Regulatory Compliance Specialist
Entity Title:
Address: 3001 COLORADO BLVD
City: DENTON
State: TX
Country:
Zip Code: 76210

Phone:

Affil Type Desc: Identification Signer
Entity Name: Erin Baltazar, Agent for Sally Holdings LLC
Entity Title: Regulatory Compliance Specialist, Verisk 3E
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Legal Owner
Entity Name: Sally Holdings LLC
Entity Title:
Address: 3001 Colorado Blvd
City: Denton
State: TX
Country: United States
Zip Code: 76210
Phone: (940) 898-7500

Affil Type Desc: Parent Corporation
Entity Name: Sally Holdings LLC
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Document Preparer
Entity Name: Erin Baltazar, Agent for Sally Holdings LLC
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title:
Address: 3207 Grey Hawk Ct., Suite 200
City: Carlsbad
State: CA
Country:
Zip Code: 92010
Phone:

Affil Type Desc: Property Owner
Entity Name: SHILOH PROPERTIES LLC
Entity Title:
Address: 3240 S WHITE RD, Ste 329
City: SAN JOSE
State: CA
Country: United States
Zip Code: 95148
Phone: (408) 768-0476

Affil Type Desc: Operator
Entity Name: Sally Beauty Supply, LLC
Entity Title:
Address:
City:
State:
Country:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Zip Code:						
Phone:		(940) 898-7500				

21	4 of 4	NNW	0.09 / 451.10	120.96 / 1	Sally Beauty Supply #3859 6560 Hembree Ln Ste 186 Windsor, CA 95492 CA	CUPA SONOMA

Facility ID: 49-000-008632 **CERS ID:** 10781782

Details

Program Type: HMBP
Permit Status: Inactive
Expiration Date:
Fee Schedule: Range 2

Details

Program Type: Stormwater
Permit Status: Active
Expiration Date:
Fee Schedule: Storm Water Permit

Details

Program Type: Hazardous Waste
Permit Status: Active
Expiration Date:
Fee Schedule: SQG < 325 gallons/year

22	1 of 6	NNW	0.09 / 466.27	120.75 / 1	O'Reilly Auto Parts #3553 6500 Hembree Ln 225, Windsor, CA 95492 CA	CUPA SONOMA

Facility ID: 49-000-007357 **CERS ID:** 10111576

Details

Program Type: Stormwater
Permit Status: Active
Expiration Date: 11/16/2023
Fee Schedule: Storm Water Permit

Details

Program Type: HMBP
Permit Status: Active
Expiration Date: 11/16/2023
Fee Schedule: Range 0 - Below Reportable Amounts

Details

Program Type: Hazardous Waste
Permit Status: Active
Expiration Date: 11/16/2023
Fee Schedule: SQG < 325 gallons/year

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
22	2 of 6	NNW	0.09 / 466.27	120.75 / 1	PIZZA GUYS 6500 Hembree LN STE # 202 Windsor, CA 95492 CA	CUPA SONOMA

Facility ID: 49-000-007970 **CERS ID:**

Details

Program Type: HMBP
Permit Status: Inactive
Expiration Date:
Fee Schedule: Range 1

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
22	3 of 6	NNW	0.09 / 466.27	120.75 / 1	WINGSTOP 6500 Hembree Ln Ste 205 Windsor, CA 95492 CA	CUPA SONOMA

Facility ID: 49-000-008480 **CERS ID:** 10733818

Details

Program Type: HMBP
Permit Status: Active
Expiration Date:
Fee Schedule: Range 9 - Restaurants > 1000 SCF CO2

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
22	4 of 6	NNW	0.09 / 466.27	120.75 / 1	O'Reilly Auto Parts #3553 6500 HEMBREE LN 225 WINDSOR CA 95492	CERS HAZ

Site ID: 139350
Latitude: 37.271881
Longitude: -119.270230
County:

Regulated Programs

EI ID: 10111576 **EI Description:** Hazardous Waste Generator

EI ID: 10111576 **EI Description:** Chemical Storage Facilities

Violations

Violation Date: 09/12/2017
Violation Program: HW
Violation Source: CERS
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: HSC 6.5 25250.22 - California Health and Safety Code, Chapter 6.5, Section(s) 25250.22
Violation Notes:

Returned to compliance on 10/03/2017. Oil filters being stored in 5 gallon buckets unlabeled and open. Submit photos to the CUPA demonstrating that the used oil and fuel filters are being properly managed or submit a bill of lading to this department demonstrating proper disposal.

Violation Description:

Failure to properly manage used oil and/or fuel filters in accordance with the requirements.

Evaluations

Eval Date: 11/16/2020

Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

No violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 11/16/2020
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

No violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 09/12/2017
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

Overall, neat and orderly, manager to send photos confirming buckets aren't used for oil filters with out tops and/or labels. cdef; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 09/12/2017
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Affiliations

Affil Type Desc: Environmental Contact
Entity Name: Verisk 3E/Regulatory Department/ O'Reilly Auto Parts
Entity Title:
Address: 3207 Grey Hawk Court, Suite 200
City: Carlsbad
State: CA
Country:
Zip Code: 92010
Phone:

Affil Type Desc: Identification Signer
Entity Name: Erin Baltazar, Agent for O'Reilly Auto Enterprises, L.L.C.
Entity Title: Regulatory Compliance Specialist, Verisk 3E
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Legal Owner

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Entity Name: O'Reilly Auto Enterprises, L.L.C.
Entity Title:
Address: 702 E. Bethany Home Road
City: Phoenix
State: AZ
Country: United States
Zip Code: 85014
Phone: (417) 862-3333

Affil Type Desc: Document Preparer
Entity Name: Erin Baltazar, Agent for O'Reilly Auto Enterprises, L.L.C.
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Operator
Entity Name: O'Reilly Auto Enterprises, L.L.C.
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone: (417) 862-3333

Affil Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title:
Address: Verisk 3E,RegulatoryDept/O'Reilly Auto Parts,3207 Grey Hawk Ct,Ste200
City: Carlsbad
State: CA
Country:
Zip Code: 92010
Phone:

Affil Type Desc: CUPA District
Entity Name: Sonoma County Fire Prevention and Hazmat
Entity Title:
Address: 2300 County Center Drive, Suite 220-B
City: Santa Rosa
State: CA
Country:
Zip Code: 95403
Phone: (707) 565-2024

Affil Type Desc: Parent Corporation
Entity Name: O'Reilly Auto Parts
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

22	5 of 6	NNW	0.09 / 466.27	120.75 / 1	WINGSTOP 6500 HEMBREE LN STE 205 WINDSOR CA 95492	CERS HAZ

Site ID: 422591
Latitude: 38.526900
Longitude: -122.788910
County:

Regulated Programs

EI ID: 10733818 ***EI Description:*** Chemical Storage Facilities

Violations

Violation Date: 05/11/2017 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Sonoma County Fire & Emergency Services Department
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Returned to compliance on 06/02/2017. Provide Employee Training. Provide Employee Training.

Violation Description:

Failure to establish and electronically submit an adequate training program in safety procedures in the event of a release or threatened release of a hazardous material.

Violations

Violation Date: 07/02/2019 ***Violation Source:*** CERS
Violation Program: HMRRP ***Violation Division:*** Sonoma County Fire & Emergency Services Department
Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)
Violation Notes:

Returned to compliance on 07/08/2019. There was no documentation of CO2 training (hazards/evacuation/911 onsite. Provide training in the hazards of C02 and evacuation and signoff sheets showing employees have been trained within 30 days.

Violation Description:

Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.

Evaluations

Eval Date: 07/02/2019
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

CERS is Current; no documentation of CO2 training as noted on inspection.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 05/11/2017
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Affiliations

Affil Type Desc: CUPA District

Entity Name: Sonoma County Fire Prevention and Hazmat
Entity Title:
Address: 2300 County Center Drive, Suite 220-B
City: Santa Rosa
State: CA
Country:
Zip Code: 95403
Phone: (707) 565-2024

Affil Type Desc: Document Preparer
Entity Name: Howard Ko
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Identification Signer
Entity Name: Howard Ko
Entity Title: Owner (President)
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Parent Corporation
Entity Name: Wingstop
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Legal Owner
Entity Name: Howard Ko
Entity Title:
Address: PO Box 5064
City: Novato
State: CA
Country: United States
Zip Code: 94948
Phone: (818) 469-0370

Affil Type Desc: Environmental Contact
Entity Name: Howard Ko
Entity Title:
Address: PO Box 5064
City: Novato
State: CA
Country:
Zip Code: 94948
Phone:

Affil Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title:
Address: 6500 Hembree Lane
City: Windsor
State: CA
Country:
Zip Code: 95492
Phone:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Affil Type Desc: Operator
Entity Name: Howard Ko
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone: (818) 469-0370

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
22	6 of 6	NNW	0.09 / 466.27	120.75 / 1	O'REILLY AUTO PARTS #3553 6500 HEMBREE LN STE 225 WINDSOR CA 95492	C&D DEBRIS RECY

County: SONOMA

Activity Type: USED OIL COLLECTION
Phone No:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
23	1 of 39	NW	0.09 / 467.28	114.06 / -6	5900 PRUITT AVE #164 WINDSOR CA	HMIRS

Incident County: SONOMA

HMIR Historical Reports

Report No: X-2007030411
Report Type: A hazardous material incident
Date of Incident: 03/14/2007
Time of Incident: 0900
Haz Class Code: 3
Hazardous Class: FLAMMABLE - COMBUSTIBLE LIQUID
Commodity Short Nm: COMPOUNDS CLEANING LIQU
Commodity Long Nm: COMPOUNDS CLEANING LIQUID
Trade Name:
ID No: NA1993
Haz Waste Ind: No
Haz Waste EPA No:
HMIS Tox Inhalation?: No
TIH Hazard Zone:
Qty Released: 0.015625
Unit of Measure: Liquid - Gallon
What Failed: 114
What Failed Desc: Cylinder Valve
How Failed Code: 308
How Failed Desc: Leaked
Failure Cause Code: 515
Failure Cause Desc: Human Error
Ident. Markings:
Cont1 Pkging Type: Box
Cont1 Const Mat: Fiberboard
Cont1 Head Type:
Cont1 Pkg Capacity:
C1 Capacity UOM:
Cont1 Pkg Amt:
C1 Pkg Amt UOM:
Cont1 Pkg No:
C1 Pkg NO Failed:
Cont1 Pkg Mnfctr:
Cont1 Pkg Mnfct Dt:
Cont1 Pkg Serial NO:
C1 Pkg Last Test Dt:
C1 Test Const Mat: Fiberboard
C1 Pkg Dsign Pres.:
C1 Dsign Press UOM:

Fed DOT Agency Nm:
Fed DOT Report No:
Report Submit Src: XML
Inc Multiple Rows: No
Inc Non US State:
Mode Transport: Highway
Transport Phase: IN TRANSIT
Incident Occrrnce:
Mat Ship Approval?: No
Mat Ship Approv No:
Undecl Hazmat Ship?: No
Packaging Type: Non-Bulk
Packing Group:
Carrier Reporter: FEDEX GROUND PACKAGE SYSTEM INC.
CR Street Name: 1000 FED EX DR
CR City: CORAOPOLIS
CR State: PA
CR Postal Code: 15108-9373
CR Non US State:
CR Fed DOT ID: 265752
CR Hazmat Reg ID: 062904001002M
CR Country: US
Shipper Name: PRISCO/PACIFIC INC.
Shipper Street Name: 1880 S CARLOS AVE
Shipper City: ONTARIO
Shipper State: CA
Shipper Postal: 91761-8005
Shipper Non US St:
Shipper Country: US
Shipper Waybill: 48678630213932
Ship Hazmat Reg ID:
Origin City: ONTARIO
Origin State: CALIFORNIA
Origin Postal: 91761
Origin Non US St:
Origin Country: US
Destination City: PETALUMA
Destination State: CALIFORNIA
Destination Postal: 94954

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	Cylinder
C1 Head Thick UOM:		**Cont2 Const Mat:**	Metal (any type)
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	
C1 Device Model:		**Cont2 Pkg No Failed:**	
NRC No:			
RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:		**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	MIKE EVERS
Damage > 500:	No	**Contact Title:**	SR MANAGER - HAZARDOUS MATERIALS
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

23	2 of 39	NW	0.09 / 467.28	114.06 / -6	5900 Pruitt Ave. Ste 164 WINDSOR CA	HMIRS

Incident County: SONOMA

HMIR Historical Reports

Report No:	X-2007080165	***Fed DOT Agency Nm:***	
Report Type:	A hazardous material incident	***Fed DOT Report No:***	
Date of Incident:	08/03/2007	***Report Submit Src:***	XML
Time of Incident:	2143	***Inc Multiple Rows:***	No
Haz Class Code:	2.2	***Inc Non US State:***	
Hazardous Class:	NONFLAMMABLE COMPRESSED GAS	***Mode Transport:***	Highway
Commodity Short Nm:	FIRE EXTINGUISHERS CONTA	***Transport Phase:***	UNLOADING
Commodity Long Nm:	FIRE EXTINGUISHERS CONTAINING COMPRESSED OR LIQUEFIED GAS	***Incident Occrrnce:***	
Trade Name:		***Mat Ship Approval?:***	No
ID No:	UN1044	***Mat Ship Approv No:***	
Haz Waste Ind:	No	***Undecl Hazmat Ship?:***	No
Haz Waste EPA No:		***Packaging Type:***	Non-Bulk
HMIS Tox Inhalation?:	No	***Packing Group:***	
TIH Hazard Zone:		***Carrier Reporter:***	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	20	***CR Street Name:***	1000 FED EX DR
Unit of Measure:	Solid - Pound	***CR City:***	CORAOPOLIS
What Failed:	139	***CR State:***	PA
What Failed Desc:	O-Ring or Seals	***CR Postal Code:***	15108-9373
How Failed Code:	303	***CR Non US State:***	
How Failed Desc:	Burst or Ruptured	***CR Fed DOT ID:***	265752
Failure Cause Code:	534	***CR Hazmat Reg ID:***	062904001002M
Failure Cause Desc:	Too Much Weight on Package	***CR Country:***	US
Ident. Markings:		***Shipper Name:***	MCMASTER-CARR SUPPLY COMPANY
Cont1 Pkging Type:	Box	***Shipper Street Name:***	9630 NORWALK BLVD
Cont1 Const Mat:	Fiberboard	***Shipper City:***	SANTA FE SPRINGS
Cont1 Head Type:		***Shipper State:***	CA
Cont1 Pkg Capacity:		***Shipper Postal:***	90670-2954
C1 Capacity UOM:		***Shipper Non US St:***	
Cont1 Pkg Amt:		***Shipper Country:***	US
C1 Pkg Amt UOM:		***Shipper Waybill:***	90131600437965
Cont1 Pkg No:		***Ship Hazmat Reg ID:***	
C1 Pkg NO Failed:		***Origin City:***	SANTA FE SPRINGS
Cont1 Pkg Mnfctr:		***Origin State:***	CALIFORNIA
Cont1 Pkg Mnfct Dt:		***Origin Postal:***	90670
Cont1 Pkg Serial NO:		***Origin Non US St:***	
C1 Pkg Last Test Dt:		***Origin Country:***	US
C1 Test Const Mat:	Fiberboard	***Destination City:***	SONOMA
C1 Pkg Dsign Pres.:		***Destination State:***	CALIFORNIA
C1 Dsign Press UOM:		***Destination Postal:***	95476
C1 Pkg Shell Thick:		***Destination Non US:***	
C1 Shell Thick UOM:		***Destination Country:***	US
C1 Head Thickness:		***Cont2 Package Type:***	Cylinder
C1 Head Thick UOM:		***Cont2 Const Mat:***	Metal (any type)
C1 Pkg Srvc Pres.:		***Cont2 Pkg Capacity:***	
C1 Srvc Press UOM:		***Cont2 Capacity UOM:***	
C1 Valve/Device Fail?:	No	***Cont2 Pkg Amount:***	
C1 Device Type:		***Cont2 Pkg Amt UOM:***	
C1 Device Mnfctr:		***Cont2 Pkg No:***	
C1 Device Model:		***Cont2 Pkg No Failed:***	
NRC No:			

RAM Pkg Category:		***Haz NonHosp Public:***	0
RAM Pkg Cert.:	FALSE	***Haz NonHosp Old:***	0
RAM Pkg Cert. NBR:		***Tot Haz Non Hosp Inj:***	0
RAM Nuclide S:		***Total Hazmat Injuries:***	0
RAM Transport Index:		***Evacuation Indicator:***	No
RAM UOM:		***Public Evacuated:***	0
RAM Activity Rpted:		***Employees Evac:***	0
RAM UOM Rpted:		***Total Evacuated:***	0
RAM Activity:		***Total Evacuation Hrs:***	0
RAM Activity UOM:		***Major Artery Closed:***	No
RAM Mat Safety:		***Mjr Artery Hrs Closed:***	0
Spillage Result:	Yes	***Material Involved:***	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	Yes	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	TRAVIS MCEWEN
Damage > 500:	No	**Contact Title:**	SAFETY SPECIALIST III - HAZMAT
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the Fire Extinguisher(s) had a loose pin(s) with allowed leakage. The pin(s) were secured. The package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2007040029	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	03/19/2007	**Report Submit Src:**	XML
Time of Incident:	1849	**Inc Multiple Rows:**	No
Haz Class Code:	2.0	**Inc Non US State:**	
Hazardous Class:	COMBUSTIBLE LIQUID	**Mode Transport:**	Highway
Commodity Short Nm:	PAINT	**Transport Phase:**	UNLOADING
Commodity Long Nm:	PAINT	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1263	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.75	**CR Street Name:**	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	**CR City:**	CORAOPOLIS
What Failed:	109	**CR State:**	PA
What Failed Desc:	Closure (e.g. Cap Top or Plug)	**CR Postal Code:**	15108-9373
How Failed Code:	302	**CR Non US State:**	
How Failed Desc:	Bent	**CR Fed DOT ID:**	265752
Failure Cause Code:	522	**CR Hazmat Reg ID:**	062904001002M
Failure Cause Desc:	Inadequate Procedures	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	AXALTA COATING SYSTEMS LLC
Cont1 Pkging Type:	Box	**Shipper Street Name:**	11535 PRODUCTION DR
Cont1 Const Mat:	Fiberboard	**Shipper City:**	RENO
Cont1 Head Type:		**Shipper State:**	NV

Cont1 Pkg Capacity:		**Shipper Postal:**	89506-2615
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:		**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	25525930088205
Cont1 Pkg No:		**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:		**Origin City:**	RENO
Cont1 Pkg Mnfctr:		**Origin State:**	NEVADA
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	89506
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:	Fiberboard	**Destination City:**	FORT BRAGG
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95437
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	Can
C1 Head Thick UOM:		**Cont2 Const Mat:**	Metal (any type)
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	
C1 Device Model:		**Cont2 Pkg No Failed:**	
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:		**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	MIKE EVERS
Damage > 500:	No	**Contact Title:**	SR MANAGER - HAZARDOUS MATERIALS
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR

Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The pail was unloaded with leakage noted. Examination of the pail revealed the pail had a loose cap/lid and leaked. The leakage was contained. The cap/lid was secured. Undamaged product was returned to the shipper. The damaged product was properly disposed of in accordance with Federal Regulations.

Recommend Actions Taken:

HMIR Historical Reports

Report No:	X-2007080222	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	08/15/2007	**Report Submit Src:**	XML
Time of Incident:	1853	**Inc Multiple Rows:**	No
Haz Class Code:	3	**Inc Non US State:**	
Hazardous Class:	FLAMMABLE - COMBUSTIBLE LIQUID	**Mode Transport:**	Highway
Commodity Short Nm:	PAINT RELATED MATERIAL I	**Transport Phase:**	UNLOADING
Commodity Long Nm:	PAINT RELATED MATERIAL INCLUDING PAINT THINNING DRYING REMOVING OR REDUCING COMPOUND	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1263	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.80	**CR Street Name:**	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	**CR City:**	CORAOPOLIS
What Failed:	128	**CR State:**	PA
What Failed Desc:	Inner Packaging	**CR Postal Code:**	15108-9373
How Failed Code:	309	**CR Non US State:**	
How Failed Desc:	Punctured	**CR Fed DOT ID:**	265752
Failure Cause Code:	517	**CR Hazmat Reg ID:**	062904001002M
Failure Cause Desc:	Improper Preparation for Transportation	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	PRODUCTS/TECHNIQUES INC.
Cont1 Pkging Type:	Box	**Shipper Street Name:**	3271 S RIVERSIDE AVE
Cont1 Const Mat:	Fiberboard	**Shipper City:**	BLOOMINGTON
Cont1 Head Type:		**Shipper State:**	CA
Cont1 Pkg Capacity:		**Shipper Postal:**	92316-3515
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:		**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	9102160043713
Cont1 Pkg No:		**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:		**Origin City:**	RIALTO
Cont1 Pkg Mnfctr:		**Origin State:**	CALIFORNIA
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	92376
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:	Fiberboard	**Destination City:**	SANTA ROSA
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95407
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	Can
C1 Head Thick UOM:		**Cont2 Const Mat:**	Metal (any type)
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	
C1 Device Model:		**Cont2 Pkg No Failed:**	
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:		**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	Yes	**Ship Non Transport:**	No
Fire EMS EMS Report:	8004249300	**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	TRAVIS MCEWEN
Damage > 500:	No	**Contact Title:**	SAFETY SPECIALIST III - HAZMAT
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The pail was unloaded with leakage noted. Examination of the pail revealed the pail had been punctured and leaked. The leakage was contained and the package was repacked. Undamaged product was returned to the shipper. The damaged product was properly disposed of in accordance with Federal Regulations.

Recommend Actions Taken:

23	*3 of 39*	*NW*	*0.09 / 467.28*	*114.06 / -6*	***5900 pruitt ave # 164 SANTA ROSA CA***	***HMIRS***

Incident County: SONOMA

HMIR Historical Reports

Report No:	X-2008090095	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	08/27/2008	**Report Submit Src:**	XML
Time of Incident:	0545	**Inc Multiple Rows:**	No
Haz Class Code:	8	**Inc Non US State:**	
Hazardous Class:	CORROSIVE MATERIAL	**Mode Transport:**	Highway
Commodity Short Nm:	SODIUM HYDROXIDE SOLUTI	**Transport Phase:**	UNLOADING
Commodity Long Nm:	SODIUM HYDROXIDE SOLUTION	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1824	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk

HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.002642	**CR Street Name:**	1000 FED EX DR
Unit of Measure:	LGA	**CR City:**	CORAOPOLIS
What Failed:	128	**CR State:**	PA
What Failed Desc:	Inner Packaging	**CR Postal Code:**	15108-9373
How Failed Code:	308	**CR Non US State:**	
How Failed Desc:	Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	526	**CR Hazmat Reg ID:**	062904001002M
Failure Cause Desc:	Loose Closure Component or Device	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	AQUA SOLUTIONS INC.
Cont1 Pkging Type:	Box	**Shipper Street Name:**	6913 HIGHWAY 225
Cont1 Const Mat:	Fiberboard	**Shipper City:**	DEER PARK
Cont1 Head Type:		**Shipper State:**	TX
Cont1 Pkg Capacity:		**Shipper Postal:**	77536-2414
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:		**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	35758362532641
Cont1 Pkg No:		**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:		**Origin City:**	DEER PARK
Cont1 Pkg Mnfctr:		**Origin State:**	TEXAS
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	77536
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:		**Destination City:**	HEALDSBURG
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95448
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	Bottle
C1 Head Thick UOM:		**Cont2 Const Mat:**	Plastic
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	
C1 Device Model:		**Cont2 Pkg No Failed:**	
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:		**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	TRAVIS MCEWEN
Damage > 500:	No	**Contact Title:**	SAFETY SPECIALIST III - HAZMAT
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

23	***4 of 39***	***NW***	***0.09 / 467.28***	***114.06 / -6***	***Sonoma Soil Builders 5900 Pruitt Ave Windsor, CA 95492 CA***	***CUPA SONOMA***

Facility ID: 49-000-008028 ***CERS ID:*** 10207087

Details

Program Type:	Hazardous Waste
Permit Status:	Inactive
Expiration Date:	11/8/2019
Fee Schedule:	SQG < 325 gallons/year

Details

Program Type:	HMBP
Permit Status:	Inactive
Expiration Date:	11/8/2019
Fee Schedule:	Range 1

23	***5 of 39***	***NW***	***0.09 / 467.28***	***114.06 / -6***	***KRISTAR 5900 Pruitt AVE STE 230 Windsor, CA 95492 CA***	***CUPA SONOMA***

Facility ID: 49-000-008132 ***CERS ID:*** 10452445

Details

Program Type:	HMBP
Permit Status:	Inactive
Expiration Date:	2/20/2015
Fee Schedule:	

23	***6 of 39***	***NW***	***0.09 / 467.28***	***114.06 / -6***	***New Metal Coachworks, LLC 5900 Pruitt Ave # 104, Windsor, CA 95492 CA***	***CUPA SONOMA***

Facility ID: 49-000-008310 ***CERS ID:*** 10643437

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Details

Program Type: Hazardous Waste
Permit Status: Active
Expiration Date: 1/8/2022
Fee Schedule: SQG < 325 gallons/year

Details

Program Type: Stormwater
Permit Status: Active
Expiration Date: 1/8/2022
Fee Schedule: Storm Water Permit

Details

Program Type: HMBP
Permit Status: Active
Expiration Date: 1/8/2022
Fee Schedule: Range 2

23	*7 of 39*	*NW*	*0.09 / 467.28*	*114.06 / -6*	***Applied Chemical*** ***5900 Pruitt Ave Ste 280 Windsor, CA 95492*** ***CA***	***CUPA SONOMA***

Facility ID: 49-000-008313 ***CERS ID:*** 10649437

Details

Program Type: HMBP
Permit Status: Inactive
Expiration Date: 11/30/2016
Fee Schedule: Range 2

Details

Program Type: Hazardous Waste
Permit Status: Inactive
Expiration Date: 11/30/2016
Fee Schedule: SQG < 325 gallons/year

23	*8 of 39*	*NW*	*0.09 / 467.28*	*114.06 / -6*	***Siddiqui Rums Corporation*** ***5900 Pruitt Ave Ste 404, Windsor, CA 95492*** ***CA***	***CUPA SONOMA***

Facility ID: 49-000-008290 ***CERS ID:*** 10643917

Details

Program Type: HMBP
Permit Status: Inactive
Expiration Date: 6/26/2021
Fee Schedule: Range 3

23	*9 of 39*	*NW*	*0.09 / 467.28*	*114.06 / -6*	***West Coast Auto Craft*** ***5900 PRUITT AVE STE 230 WINDSOR, CA 95492***	***CUPA SONOMA***

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					CA	

Facility ID: 49-000-008434 **CERS ID:** 10711009

Details

Program Type: HMBP
Permit Status: Inactive
Expiration Date:
Fee Schedule: Range 2

Details

Program Type: Hazardous Waste
Permit Status: Inactive
Expiration Date: 1/4/2020
Fee Schedule: SQG < 325 gallons/year

23	10 of 39	NW	0.09 / 467.28	114.06 / -6	West Coast Auto Craft 590 PRUITT AVE STE 230 WINDSOR CA 95492	DELISTED HAZ

Siteid: 412691
Latitude: 38.523830
Longitude: -122.791500
Original Source: CHAZ
Record Date: 22-MAR-2018

23	11 of 39	NW	0.09 / 467.28	114.06 / -6	Applied Chemical 5900 PRUITT AVE STE 280 WINDSOR CA 95492	DELISTED HAZ

Siteid: 360407
Latitude: 38.521160
Longitude: -122.789880
Original Source: CHAZ
Record Date: 22-MAR-2018

23	12 of 39	NW	0.09 / 467.28	114.06 / -6	Shiloh Oaks Co., LLC 5900 PRUITT AVE WINDSOR CA 95492	DELISTED HAZ

Siteid: 361211
Latitude: 38.521160
Longitude: -122.789878
Original Source: CHAZ
Record Date: 22-MAR-2018

23	13 of 39	NW	0.09 / 467.28	114.06 / -6	Sonoma Soil Builders 5900 PRUITT AVE WINDSOR CA 95492	DELISTED HAZ

Siteid: 402479
Latitude: 38.412820
Longitude: -122.721020
Original Source: CHAZ
Record Date: 22-MAR-2018

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
23	14 of 39	NW	0.09 / 467.28	114.06 / -6	New Metal Coachworks, LLC 5900 PRUITT AVE # 104 WINDSOR CA 95492	CERS HAZ

Site ID: 357982
Latitude: 38.521160
Longitude: -122.789880
County:

Regulated Programs

EI ID: 10643437 **EI Description:** Hazardous Waste Generator

EI ID: 10643437 **EI Description:** Chemical Storage Facilities

Violations

Violation Date: 12/14/2015 **Violation Source:** CERS
Violation Program: HMRRP **Violation Division:** Sonoma County Fire & Emergency Services Department
Citation: HSC 6.95 Multiple - California Health and Safety Code, Chapter 6.95, Section(s) Multiple
Violation Notes:

Returned to compliance on 01/06/2016. Secure gas cylinders to wall

Violation Description:

Business Plan Program - Release/Leaks/Spills - General

Violations

Violation Date: 12/14/2015 **Violation Source:** CERS
Violation Program: HMRRP **Violation Division:** Sonoma County Fire & Emergency Services Department
Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)
Violation Notes:

Returned to compliance on 01/08/2016. Received e-mail with training documentation

Violation Description:

Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.

Violations

Violation Date: 12/14/2015 **Violation Source:** CERS
Violation Program: HMRRP **Violation Division:** Sonoma County Fire & Emergency Services Department
Citation: HSC 6.95 25507 - California Health and Safety Code, Chapter 6.95, Section(s) 25507
Violation Notes:

Returned to compliance on 01/07/2016.

Violation Description:

Failure to adequately establish and implement a business plan when storing/handling a hazardous material at or above reportable quantities.

Violations

Violation Date: 12/14/2015 **Violation Source:** CERS

Violation Program: HW ***Violation Division:*** Sonoma County Fire & Emergency Services Department

Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)

Violation Notes:

Returned to compliance on 01/06/2016. Labeling of waste bondo

Violation Description:

Failure to properly label hazardous waste accumulation containers with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.

Evaluations

Eval Date: 12/14/2015
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Eval Date: 12/14/2015
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

Eval Date: 12/04/2018
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

No violations; CERS is current; gas storage areas looked good.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/04/2018
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

Shop very neat and order; welding gasses and shop generates only a small amount of waste paint materials which is brought to HHWF at Meecham under the Business program; disposal paperwork was in order.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Affiliations

Affil Type Desc: Identification Signer
Entity Name: Paul Shaughnessy
Entity Title: Owner
Address:
City:
State:

Country:
Zip Code:
Phone:

Affil Type Desc: Environmental Contact
Entity Name: Paul Shaughnessy
Entity Title:
Address: 5900 Pruitt Ave # 104
City: Windsor
State: CA
Country:
Zip Code: 95492
Phone:

Affil Type Desc: CUPA District
Entity Name: Sonoma County Fire Prevention and Hazmat
Entity Title:
Address: 2300 County Center Drive, Suite 220-B
City: Santa Rosa
State: CA
Country:
Zip Code: 95403
Phone: (707) 565-2024

Affil Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title:
Address: 5900 Pruitt Ave # 104
City: Windsor
State: CA
Country:
Zip Code: 95492
Phone:

Affil Type Desc: Legal Owner
Entity Name: Paul Shaughnessy
Entity Title:
Address: 5900 Pruitt Ave # 104
City: Windsor
State: CA
Country: United States
Zip Code: 95492
Phone: (707) 838-1964

Affil Type Desc: Document Preparer
Entity Name: Paul Shaughnessy
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Operator
Entity Name: Paul Shaughnessy
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone: (707) 328-8636

Affil Type Desc: Parent Corporation
Entity Name: new metal kustomz
Entity Title:
Address:
City:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					State: **Country:** **Zip Code:** **Phone:**	
23	15 of 39	NW	0.09 / 467.28	114.06 / -6	**SHILOH OAKS COMPANY** **5900 PRUITT AVENUE** **WINDSOR CA 95492**	CLEANUP SITES

Global ID: T10000010027
Status: COMPLETED - CASE CLOSED
Status Date: 8/16/2017
Site Facility Type: CLEANUP PROGRAM SITE
Data Source: Cleanup Program Sites from GeoTracker Search; Cleanup Sites from GeoTracker Cleanup Sites Data Download
Latitude: 38.52284
Longitude: -122.79095
County: SONOMA

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail

RB Case No: 1NSO976
Local Case No:
Begin Date: 10/14/2016
File Location:
Lead Agency: NORTH COAST RWQCB (REGION 1)
Local Agency:
Potential COC: Diesel, Waste Oil / Motor / Hydraulic / Lubricating
Potential Media of Concern: Aquifer used for drinking water supply, Other Groundwater (uses other than drinking water), Under Investigation
How Discovered:
How Discovered Description:
Stop Description:
CalWater Watershed Name: Russian River - Middle Russian River - Mark West (114.23)
DWR GW Subbasin Name: Santa Rosa Valley - Santa Rosa Plain (1-055.01)
Disadvantaged Community:
CalEnviroScreen Score: 46-50%
Site History:
Stop Method:
CUF Case: NO
Case Worker: ZZZ

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity

Action Type: ENFORCEMENT
Date: 2017-08-16 00:00:00
Action: Closure/No Further Action Letter

Action Type: ENFORCEMENT
Date: 2017-08-01 00:00:00
Action: Email Correspondence

Action Type: ENFORCEMENT
Date: 2017-07-31 00:00:00
Action: Deed Restriction / Land Use Restriction / Covenant

Action Type: ENFORCEMENT
Date: 2017-07-24 00:00:00
Action: Staff Letter

Action Type: RESPONSE
Date: 2017-07-13 00:00:00
Action: Correspondence - Regulator Responded

Action Type: ENFORCEMENT
Date: 2017-06-13 00:00:00
Action: Notification - Public Notice of Case Closure

Action Type: ENFORCEMENT
Date: 2017-06-09 00:00:00
Action: File Review - Closure

Action Type: RESPONSE

Date: 2017-05-15 00:00:00
Action: Request for Closure

Action Type: ENFORCEMENT
Date: 2017-04-13 00:00:00
Action: Email Correspondence

Action Type: RESPONSE
Date: 2017-04-12 00:00:00
Action: Site Investigation Workplan - Regulator Responded

Action Type: ENFORCEMENT
Date: 2017-04-05 00:00:00
Action: Email Correspondence

Action Type: RESPONSE
Date: 2017-03-13 00:00:00
Action: Request for Closure - Regulator Responded

Action Type: ENFORCEMENT
Date: 2017-02-08 00:00:00
Action: Staff Letter

Action Type: RESPONSE
Date: 2017-02-07 00:00:00
Action: Correspondence

Action Type: RESPONSE
Date: 2017-02-03 00:00:00
Action: Soil and Water Investigation Workplan

Action Type: ENFORCEMENT
Date: 2017-01-20 00:00:00
Action: Cost Recovery Agreement / N. of Reimbursement

Action Type: ENFORCEMENT
Date: 2017-01-20 00:00:00
Action: Staff Letter

Action Type: ENFORCEMENT
Date: 2017-01-10 00:00:00
Action: Technical Correspondence / Assistance / Other

Action Type: RESPONSE
Date: 2016-12-23 00:00:00
Action: Preliminary Site Assessment Report

Action Type: RESPONSE
Date: 2016-10-14 00:00:00
Action: Preliminary Site Assessment Workplan

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History

Status: Completed - Case Closed
Status Date: 2017-08-16 00:00:00

Status: Open - Eligible for Closure
Status Date: 2017-06-13 00:00:00

Status: Open - Active
Status Date: 2017-01-11 00:00:00

Status: Open - Case Begin Date
Status Date: 2016-10-14 00:00:00

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts

Contact Type: Regional Board Caseworker
Contact Name: REGIONAL WATER BOARD SITE CLOSED
Phone No: 7075762220
Organization Name: NORTH COAST RWQCB (REGION 1)
Email:
Address: 5550 SKYLANE BOULEVARD, SUITE A
City: SANTA ROSA

Cleanup Program Sites from GeoTracker Search - Regulatory Profile (as of May 29, 2021)

Project Status:
Cuf Claim No:
CUF Priority Assign:
CUF Amount Paid:
Composting Method:
File Location:
User Defined Beneficial Use:
Designated Beneficial Use: MUN, AGR, IND, PROC, FRSH, CUL, AQUA - Note: R1 BP- all gw same uses.
Designated Beneficl Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply, Freshwater Replenishment, Native American Culture, AQUA - Note: R1 BP- all gw same uses.
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T10000010027
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 8/16/2017
Potential COC: DIESEL, WASTE OIL / MOTOR / HYDRAULIC / LUBRICATING
Potential Media of Concern: AQUIFER USED FOR DRINKING WATER SUPPLY, OTHER GROUNDWATER (USES OTHER THAN DRINKING WATER), UNDER INVESTIGATION
Groundwater Monitoring Frequen:
DWR GW Sub Basin: Santa Rosa Valley - Santa Rosa Plain (1-055.01)
CalWater Watershed Name: Russian River - Middle Russian River - Mark West (114.23)
Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: NORTH COAST RWQCB (REGION 1) (LEAD) - CASE #: 1NSO976
CASEWORKER: REGIONAL WATER BOARD SITE CLOSED
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T10000010027&tabname=regulatoryhistory
Site History:

No site history available

Sites from GeoTracker Search - Regulatory Activities (as of May 29, 2021)

Action Type: Other Regulatory Actions
Action Date: 8/16/2017
Received Issue Date: 8/16/2017
Action: Closure/No Further Action Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000010027&enforcement_id=6335394&temptable=ENFORCEMENT
Title Description Comments:

No Further Action Required

Action Type: Other Regulatory Actions
Action Date: 8/1/2017
Received Issue Date: 8/1/2017
Action: Email Correspondence
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000010027&enforcement_id=6328364&temptable=ENFORCEMENT
Title Description Comments:

8/1/2017 email correspondence with Dustin Abbott

Action Type: Other Regulatory Actions
Action Date: 7/31/2017
Received Issue Date: 7/31/2017
Action: Deed Restriction / Land Use Restriction / Covenant
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?

global_id=T10000010027&enforcement_id=6328365&temptable=ENFORCEMENT

Title Description Comments:

Action Type: Other Regulatory Actions
Action Date: 7/24/2017
Received Issue Date: 7/24/2017
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000010027&enforcement_id=6328363&temptable=ENFORCEMENT
Title Description Comments:

Comments on Notice of Proposed No Further Action

Action Type: Response Requested - Other
Action Date: 7/13/2017
Received Issue Date: 7/7/2017
Action: Correspondence - Regulator Responded
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000010027&doc_id=5930085
Title Description Comments:

Comments on Notice of Proposed No Further Action

Action Type: Notices
Action Date: 6/13/2017
Received Issue Date: 6/13/2017
Action: Notification - Public Notice of Case Closure
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000010027&enforcement_id=6326358&temptable=ENFORCEMENT
Title Description Comments:

Notice of Proposed No Further Action

Action Type: Other Regulatory Actions
Action Date: 6/9/2017
Received Issue Date: 6/9/2017
Action: File Review - Closure
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000010027&enforcement_id=6322544&temptable=ENFORCEMENT
Title Description Comments:

No Further Action Recommendation

Action Type: Response Requested - Other
Action Date: 5/15/2017
Received Issue Date: 5/15/2017
Action: Request for Closure
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000010027&doc_id=5920331
Title Description Comments:

Report: Additional Site Investigation

Action Type: Other Regulatory Actions
Action Date: 4/13/2017
Received Issue Date: 4/13/2017
Action: Email Correspondence
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000010027&enforcement_id=6318437&temptable=ENFORCEMENT
Title Description Comments:

Email Work plan concurrence

Action Type: Response Requested - Workplans
Action Date: 4/12/2017
Received Issue Date: 4/12/2017

Action: Site Investigation Workplan - Regulator Responded
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000010027&doc_id=5918701
Title Description Comments:

Work Plan for Additional Site Investigation

Action Type: Other Regulatory Actions
Action Date: 4/5/2017
Received Issue Date: 4/5/2017
Action: Email Correspondence
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000010027&enforcement_id=6318435&temptable=ENFORCEMENT
Title Description Comments:

email non concurrence with closure

Action Type: Response Requested - Other
Action Date: 3/13/2017
Received Issue Date: 3/13/2017
Action: Request for Closure - Regulator Responded
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000010027&doc_id=5915358
Title Description Comments:

Soil and Groundwater Investigation and Request for Case Closure

Action Type: Other Regulatory Actions
Action Date: 2/8/2017
Received Issue Date: 2/8/2017
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000010027&enforcement_id=6311481&temptable=ENFORCEMENT
Title Description Comments:

Concurrence with Shallow Subsurface Soil and Groundwater Investigation

Action Type: Response Requested - Other
Action Date: 2/7/2017
Received Issue Date: 2/7/2017
Action: Correspondence
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000010027&doc_id=5912186
Title Description Comments:

Signed Cost Recovery Acknowledgement letter

Action Type: Response Requested - Workplans
Action Date: 2/3/2017
Received Issue Date: 2/3/2017
Action: Soil and Water Investigation Workplan
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000010027&doc_id=5912183
Title Description Comments:

Work Plan for Soil and Groundwater Investigation

Action Type: Other Regulatory Actions
Action Date: 1/20/2017
Received Issue Date: 1/20/2017
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000010027&enforcement_id=6311081&temptable=ENFORCEMENT
Title Description Comments:

Request for Additional Investigation

Action Type: Agreements

Action Date: 1/20/2017
Received Issue Date: 1/20/2017
Action: Cost Recovery Agreement / N. of Reimbursement
Doc Link:
Title Description Comments:

Request for Additional Investigation

Action Type: Other Regulatory Actions
Action Date: 1/10/2017
Received Issue Date: 1/10/2017
Action: Technical Correspondence / Assistance / Other
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000010027&enforcement_id=6308357&temptable=ENFORCEMENT
Title Description Comments:

Referral from Sonoma County Department of Health services

Action Type: Response Requested - Reports
Action Date: 12/23/2016
Received Issue Date: 1/11/2017
Action: Preliminary Site Assessment Report
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000010027&doc_id=5909408
Title Description Comments:

PHASE II ENVIRONMENTAL SITE ASSESSMENT REPORT

Action Type: Response Requested - Workplans
Action Date: 10/14/2016
Received Issue Date: 1/11/2017
Action: Preliminary Site Assessment Workplan
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T10000010027&doc_id=5909409
Title Description Comments:

PHASE II ENVIRONMENTAL SITE ASSESSMENT WORK PLAN

Sites from GeoTracker Search - Deed Restrictions (as of May 29, 2021)

Date Recorded: 7/31/2017
Site Management Requirements: SEE LAND USE CONTROL DOCUMENT
Covenant Doc Link: https://geotracker.waterboards.ca.gov/view_documents?cmd=radocuments&global_id=T10000010027&enforcement_id=6328365

Sites from GeoTracker Search - Documents (as of May 29, 2021)

Document Type: Site Documents
Document Date: 8/16/2017
Size :
Submitted:
Submitted By: BETH LAMB (REGULATOR)
Title: NO FURTHER ACTION REQUIRED
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000010027&enforcement_id=6335394
Type: CLOSURE/NO FURTHER ACTION LETTER

Document Type: Site Documents
Document Date: 8/1/2017
Size :
Submitted:
Submitted By: BETH LAMB (REGULATOR)
Title: 8/1/2017 EMAIL CORRESPONDENCE WITH DUSTIN ABBOTT
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000010027&enforcement_id=6328364
Type: EMAIL CORRESPONDENCE

Document Type: Site Documents
Document Date: 7/31/2017
Size :
Submitted:
Submitted By: BETH LAMB (REGULATOR)
Title: UNKNOWN

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000010027&enforcement_id=6328365
Type: DEED RESTRICTION / LAND USE RESTRICTION / COVENANT

Document Type: Site Documents **Submitted:**
Document Date: 7/24/2017 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: COMMENTS ON NOTICE OF PROPOSED NO FURTHER ACTION
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000010027&enforcement_id=6328363
Type: STAFF LETTER

Document Type: Site Documents **Submitted:**
Document Date: 7/7/2017 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: COMMENTS ON NOTICE OF PROPOSED NO FURTHER ACTION
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000010027&document_id=5930085
Type: CORRESPONDENCE

Document Type: Site Documents **Submitted:**
Document Date: 7/7/2017 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: COMMENTS ON NOTICE OF PROPOSED NO FURTHER ACTION - REGULATOR RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000010027&document_id=5930085
Type: CORRESPONDENCE

Document Type: Site Documents **Submitted:**
Document Date: 6/13/2017 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: NOTICE OF PROPOSED NO FURTHER ACTION
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000010027&enforcement_id=6326358
Type: NOTIFICATION - PUBLIC NOTICE OF CASE CLOSURE

Document Type: Site Documents **Submitted:**
Document Date: 6/9/2017 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: NO FURTHER ACTION RECOMMENDATION
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000010027&enforcement_id=6322544
Type: FILE REVIEW - CLOSURE

Document Type: Site Documents **Submitted:**
Document Date: 5/15/2017 **Submitted By:** DAVID L. BUSH, PG (AUTH_RP)
Size : 9,926 KB
Title: REPORT: ADDITIONAL SITE INVESTIGATION
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3796348273/T10000010027.PDF
Type: REQUEST FOR CLOSURE

Document Type: Site Documents **Submitted:**
Document Date: 4/13/2017 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: EMAIL WORK PLAN CONCURRENCE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000010027&enforcement_id=6318437
Type: EMAIL CORRESPONDENCE

Document Type: Site Documents **Submitted:**
Document Date: 4/11/2017 **Submitted By:** DAVID L. BUSH, PG (AUTH_RP)
Size : 18,559 KB
Title: WORK PLAN FOR ADDITIONAL SITE INVESTIGATION
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8139482498/T10000010027.PDF
Type: SITE INVESTIGATION WORKPLAN

Document Type: Site Documents **Submitted:**
Document Date: 4/5/2017 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: EMAIL NON CONCURRENCE WITH CLOSURE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000010027&enforcement_id=6318435
Type: EMAIL CORRESPONDENCE

Document Type: Site Documents **Submitted:**
Document Date: 3/13/2017 **Submitted By:** DAVID L. BUSH, PG (AUTH_RP)
Size : 10,636 KB

Title: SOIL AND GROUNDWATER INVESTIGATION AND REQUEST FOR CASE CLOSURE
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3335676729/T10000010027.PDF
Type: REQUEST FOR CLOSURE

Document Type: Site Documents **Submitted:**
Document Date: 2/8/2017 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: CONCURRENCE WITH SHALLOW SUBSURFACE SOIL AND GROUNDWATER INVESTIGATION
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000010027&enforcement_id=6311481
Type: STAFF LETTER

Document Type: Site Documents **Submitted:**
Document Date: 2/7/2017 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: SIGNED COST RECOVERY ACKNOWLEDGEMENT LETTER
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000010027&document_id=5912186
Type: CORRESPONDENCE

Document Type: Site Documents **Submitted:**
Document Date: 2/3/2017 **Submitted By:** DAVID L. BUSH, PG (AUTH_RP)
Size : 1,150 KB
Title: WORK PLAN FOR SOIL AND GROUNDWATER INVESTIGATION
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5947126924/T10000010027.PDF
Type: SOIL AND WATER INVESTIGATION WORKPLAN

Document Type: Site Documents **Submitted:**
Document Date: 1/20/2017 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: REQUEST FOR ADDITIONAL INVESTIGATION
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000010027&enforcement_id=6311081
Type: STAFF LETTER

Document Type: Site Documents **Submitted:**
Document Date: 1/11/2017 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: PHASE II ENVIRONMENTAL SITE ASSESSMENT WORK PLAN
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000010027&document_id=5909409
Type: PRELIMINARY SITE ASSESSMENT WORKPLAN

Document Type: Site Documents **Submitted:**
Document Date: 1/11/2017 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: PHASE II ENVIRONMENTAL SITE ASSESSMENT REPORT
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000010027&document_id=5909408
Type: PRELIMINARY SITE ASSESSMENT REPORT

Document Type: Site Documents **Submitted:**
Document Date: 1/10/2017 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: REFERRAL FROM SONOMA COUNTY DEPARTMENT OF HEALTH SERVICES
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000010027&enforcement_id=6308357
Type: TECHNICAL CORRESPONDENCE / ASSISTANCE / OTHER

Sites from GeoTracker Search - Cleanup Status History (as of May 29, 2021)

Status: Completed - Case Closed
Date: 8/16/2017

Status: Open - Eligible for Closure
Date: 6/13/2017

Status: Open - Active
Date: 1/11/2017

Status: Open - Case Begin Date
Date: 10/14/2016

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
23	16 of 39	NW	0.09 / 467.28	114.06 / -6	WESTERN TREE REMOVAL SPECIALISTS 5900 PRUITT AVE STE 530 WINDSOR, CA 95492 CA	CUPA SONOMA

Facility ID: 49-000-008477 **CERS ID:** 10733890

Details

Program Type: Hazardous Waste
Permit Status: Inactive
Expiration Date:
Fee Schedule: SQG < 325 gallons/year

Details

Program Type: HMBP
Permit Status: Inactive
Expiration Date:
Fee Schedule: Range 2

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
23	17 of 39	NW	0.09 / 467.28	114.06 / -6	REDBUILT LLC 5900 PRUITT AVENUE WINDSOR CA 95492	EMISSIONS

2011 Criteria Data

Facility ID: 21088
Facility SIC Code: 1531
CO: 49
Air Basin: SF
District: BA
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:
TOGT: .626
ROGT: .5860324
COT:
NOXT:
SOXT:
PMT:
PM10T:

2011 Toxic Data

Facility ID: 21088
Facility SIC Code: 1531
CO: 49
Air Basin: SF
District: BA
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:

2012 Criteria Data

Facility ID: 21088
Facility SIC Code: 1531
CO: 49
Air Basin: SF
District: BA
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:
TOGT: .626
ROGT: .5860324
COT:
NOXT:
SOXT:
PMT:
PM10T:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

2012 Toxic Data

Facility ID:	21088	***COID:***	SON
Facility SIC Code:	1531	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

23	***18 of 39***	***NW***	***0.09 / 467.28***	***114.06 / -6***	***BamCore, LLC*** ***5900 Pruitt Ave Ste 110, Windsor, CA 95492*** ***CA***	***CUPA SONOMA***

Facility ID:	49-000-008512	***CERS ID:***	10736971

Details

Program Type:	Stormwater
Permit Status:	Inactive
Expiration Date:	6/6/2020
Fee Schedule:	Storm Water Permit

Details

Program Type:	Hazardous Waste
Permit Status:	Inactive
Expiration Date:	
Fee Schedule:	SQG < 325 gallons/year

Details

Program Type:	HMBP
Permit Status:	Inactive
Expiration Date:	
Fee Schedule:	Range 2

23	***19 of 39***	***NW***	***0.09 / 467.28***	***114.06 / -6***	***Shiloh Oaks Company*** ***5900 Pruitt Avenue*** ***Windsor CA 95492***	***DEED***

Global ID:	T10000010027
Site Type:	Cleanup Program Site
Status:	Completed - Case Closed
Status Date:	8/16/2017
County:	Sonoma
Latitude:	38.52284
Longitude:	-122.79095
Search URL:	https://geotracker.waterboards.ca.gov/profile_report?global_id=T10000010027

Regulatory Activities GeoTracker Download

Action Type:	ENFORCEMENT
Action:	Deed Restriction / Land Use Restriction / Covenant
Action Date:	7/31/2017

GeoTracker Search - Regulatory Activities (as of May 29, 2021)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Action: Deed Restriction / Land Use Restriction / Covenant
Action Type: Other Regulatory Actions
Action Date: 7/31/2017
Received Issue Date: 7/31/2017
Doclink: https://geotracker.waterboards.ca.gov/view_documents?global_id=T10000010027&enforcement_id=6328365&temptable=ENFORCEMENT
Title Description Comments:

GeoTracker Search - Deed Restrictions (as of May 29, 2021)

Date Recorded: 7/31/2017
Site Management Requirements: SEE LAND USE CONTROL DOCUMENT
Covenant Doc Link: https://geotracker.waterboards.ca.gov/view_documents?cmd=radocuments&global_id=T10000010027&enforcement_id=6328365

23	20 of 39	NW	0.09 / 467.28	114.06 / -6	**Western Tree Removal Specialists** **5900 PRUITT AVE** **WINDSOR CA 95492**	**DELISTED HAZ**

Siteid: 422583
Latitude: 38.521160
Longitude: -122.789878
Original Source: CHAZ
Record Date: 09-JUL-2018

23	21 of 39	NW	0.09 / 467.28	114.06 / -6	**5900 pruitt ave # 164** **SANTA ROSA CA**	**HMIRS**

Incident County: SONOMA

HMIR Historical Reports

Report No:	X-2008090095	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	08/27/2008	**Report Submit Src:**	XML
Time of Incident:	0545	**Inc Multiple Rows:**	No
Haz Class Code:	8	**Inc Non US State:**	
Hazardous Class:	CORROSIVE MATERIAL	**Mode Transport:**	Highway
Commodity Short Nm:	SODIUM HYDROXIDE SOLUTI	**Transport Phase:**	UNLOADING
Commodity Long Nm:	SODIUM HYDROXIDE SOLUTION	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1824	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	FEDEX GROUND PACKAGE SYSTEM INC.
Qty Released:	0.002642	**CR Street Name:**	1000 FED EX DR
Unit of Measure:	Liquid - Gallon	**CR City:**	CORAOPOLIS
What Failed:	128	**CR State:**	PA
What Failed Desc:	Inner Packaging	**CR Postal Code:**	15108-9373
How Failed Code:	308	**CR Non US State:**	
How Failed Desc:	Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	526	**CR Hazmat Reg ID:**	062904001002M
Failure Cause Desc:	Loose Closure Component or Device	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	AQUA SOLUTIONS INC.
Cont1 Pkging Type:	Box	**Shipper Street Name:**	6913 HIGHWAY 225
Cont1 Const Mat:	Fiberboard	**Shipper City:**	DEER PARK
Cont1 Head Type:		**Shipper State:**	TX
Cont1 Pkg Capacity:		**Shipper Postal:**	77536-2414
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:		**Shipper Country:**	US

C1 Pkg Amt UOM:		**Shipper Waybill:**	35758362532641
Cont1 Pkg No:		**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:		**Origin City:**	DEER PARK
Cont1 Pkg Mnfctr:		**Origin State:**	TEXAS
Cont1 Pkg Mnfct Dt:		**Origin Postal:**	77536
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:		**Origin Country:**	US
C1 Test Const Mat:	Fiberboard	**Destination City:**	HEALDSBURG
C1 Pkg Dsign Pres.:		**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95448
C1 Pkg Shell Thick:		**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:		**Cont2 Package Type:**	Bottle
C1 Head Thick UOM:		**Cont2 Const Mat:**	Plastic
C1 Pkg Srvc Pres.:		**Cont2 Pkg Capacity:**	
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	
C1 Device Model:		**Cont2 Pkg No Failed:**	
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	0
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	0
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:		**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:		**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	TRAVIS MCEWEN
Damage > 500:	No	**Contact Title:**	SAFETY SPECIALIST III - HAZMAT
Material Loss:	0	**Contact Business:**	Fedex Ground Package System Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	OHMIR.Ref_Container.descr_txt
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

23	22 of 39	NW	0.09 / 467.28	114.06 / -6	Oakland Packaging 5900 PRUITT AVE STE 100 WINDSOR CA 95492	DELISTED HAZ

Siteid: 431386
Latitude: 38.521160
Longitude: -122.789880
Original Source: CHAZ
Record Date: 04-JAN-2018

23	23 of 39	NW	0.09 / 467.28	114.06 / -6	Oakland Packaging 5900 Pruitt Ave Ste 100, Windsor, CA 95492 CA	CUPA SONOMA

Facility ID: 49-000-008548 **CERS ID:** 10752568

Details

Program Type: HMBP
Permit Status: Inactive
Expiration Date:
Fee Schedule: Range 3

23	24 of 39	NW	0.09 / 467.28	114.06 / -6	ALLIED DIESEL PERFORMANCE 5900 PRUITT AVE STE 512 WINDSOR CA 95992	RCRA NON GEN

EPA Handler ID: CAL000440390
Gen Status Universe: No Report
Contact Name: RYAN GULLY
Contact Address: 5900 PRUITT AVE STE 512 , , WINDSOR , CA, 95992 ,
Contact Phone No and Ext: 707-836-4433
Contact Email: ALLIEDDIESELPERFORMANCE@GMAIL.COM
Contact Country:
County Name: SONOMA
EPA Region: 09
Land Type:
Receive Date: 20181029
Location Latitude: 38.521404
Location Longitude: -122.790713

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No

Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20181029
Handler Name:	ALLIED DIESEL PERFORMANCE
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Other	**Street 1:**	111 WILLIAM CIR
Name:	RYAN GULLY	**Street 2:**	
Date Became Current:		**City:**	CLOVERDALE
Date Ended Current:		**State:**	CA
Phone:	707-217-4370	**Country:**	
Source Type:	Implementer	**Zip Code:**	95425

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Other	**Street 1:**	5900 PRUITT AVE STE 512
Name:	RYAN GULLY	**Street 2:**	
Date Became Current:		**City:**	WINDSOR
Date Ended Current:		**State:**	CA
Phone:	707-836-4433	**Country:**	
Source Type:	Implementer	**Zip Code:**	95992

23	***25 of 39***	***NW***	***0.09 / 467.28***	***114.06 / -6***	***BAMCORE LLC 5900 PRUITT AVE STE 110 WINDSOR CA 95492***	***RCRA NON GEN***

EPA Handler ID:	CAL000404857
Gen Status Universe:	No Report
Contact Name:	KEVAN KURT
Contact Address:	5900 PRUITT AVE STE 110 , , WINDSOR , CA, 95492 ,
Contact Phone No and Ext:	707-328-3797
Contact Email:	KEVAN@BAMCORE.COM
Contact Country:	
County Name:	SONOMA
EPA Region:	09
Land Type:	
Receive Date:	20150305
Location Latitude:	38.521404
Location Longitude:	-122.790713

Violation/Evaluation Summary

Note:	NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No

Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20150305
Handler Name:	BAMCORE LLC
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Other	**Street 1:**	5900 PRUITT AVE STE 110
Name:	KEVAN KURT	**Street 2:**	
Date Became Current:		**City:**	WINDSOR
Date Ended Current:		**State:**	CA
Phone:	707-328-3797	**Country:**	
Source Type:	Implementer	**Zip Code:**	95492

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Other	**Street 1:**	5900 PRUITT AVE STE 110
Name:	BAMCORE LLC	**Street 2:**	
Date Became Current:		**City:**	WINDSOR
Date Ended Current:		**State:**	CA
Phone:	707-328-3797	**Country:**	
Source Type:	Implementer	**Zip Code:**	95492

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
23	26 of 39	NW	0.09 / 467.28	114.06 / -6	TDE EQUIPMENT INC 5900 PRUITT AVE WINDSOR CA 95492	RCRA NON GEN

EPA Handler ID:	CAL000406695
Gen Status Universe:	No Report
Contact Name:	TODD EISENHAUER
Contact Address:	150 DECANTER CIR , , WINDSOR , CA, 95492 ,
Contact Phone No and Ext:	707-484-7140
Contact Email:	TODD@TDEEQUIPMENT.COM
Contact Country:	
County Name:	SONOMA
EPA Region:	09
Land Type:	
Receive Date:	20150508
Location Latitude:	38.521404
Location Longitude:	-122.790713

Violation/Evaluation Summary

Note:	NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20150508
Handler Name:	TDE EQUIPMENT INC
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street 1:***	150 DECANTER CIR
Name:	TODD EISENHAUER	***Street 2:***	
Date Became Current:		***City:***	WINDSOR
Date Ended Current:		***State:***	CA
Phone:	707-484-7140	***Country:***	
Source Type:	Implementer	***Zip Code:***	95492
Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street 1:***	150 DECANTER CIR
Name:	TDE EQUIPMENT INC	***Street 2:***	
Date Became Current:		***City:***	WINDSOR
Date Ended Current:		***State:***	CA
Phone:	707-484-0439	***Country:***	
Source Type:	Implementer	***Zip Code:***	95492

23	***27 of 39***	***NW***	***0.09 / 467.28***	***114.06 / -6***	***NEW METAL COACHWORKS LLC 5900 PRUITT AVE STE 104 WINDSOR CA 94592***	***RCRA NON GEN***

EPA Handler ID:	CAL000423730
Gen Status Universe:	No Report
Contact Name:	PAUL SHAUGHNESSY
Contact Address:	5900 PRUITT AVE #104 , , WINDSOR , CA, 95492-0000 ,
Contact Phone No and Ext:	707-838-1964
Contact Email:	NEWMETALKUSTOMZ@SBCGLOBAL.NET
Contact Country:	
County Name:	SONOMA
EPA Region:	09
Land Type:	
Receive Date:	20161230
Location Latitude:	38.521404
Location Longitude:	-122.790713

Violation/Evaluation Summary

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20161230
Handler Name:	NEW METAL COACHWORKS LLC
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Other	**Street 1:**	5900 PRUITT AVE #104
Name:	PAUL SHAUGHNESSY	**Street 2:**	
Date Became Current:		**City:**	WINDSOR
Date Ended Current:		**State:**	CA
Phone:	707-838-1964	**Country:**	
Source Type:	Implementer	**Zip Code:**	95492-0000

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Other	**Street 1:**	5900 PRUITT AVE #104
Name:	PAUL SHAUGHNESSY	**Street 2:**	
Date Became Current:		**City:**	WINDSOR
Date Ended Current:		**State:**	CA
Phone:	707-838-1964	**Country:**	
Source Type:	Implementer	**Zip Code:**	95492-0000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
23	28 of 39	NW	0.09 / 467.28	114.06 / -6	VINYARD OPS INC 5900 PRUITT AVE 150 WINDSOR CA 95492	RCRA TSD

EPA Handler ID:	CAL000445045
Gen Status Universe:	No Report
Contact Name:	GREG KOVACEVICH
Contact Address:	371 CANDLELIGHT DR , , SANTA ROSA , CA, 95403 ,
Contact Phone No and Ext:	707-338-8482
Contact Email:	GREG@VINYARDOPS.COM
Contact Country:	
Land Type:	
County Name:	SONOMA
EPA Region:	09
Receive Date:	20190409
Location Latitude:	38.521404

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Location Longitude: -122.790713

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Smelting, Melting and Refining: No
Underground Injection Control: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20190409
Handler Name: VINYARD OPS INC
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Other
Name: GREG KOVACEVICH
Date Became Current:
Date Ended Current:
Phone: 707-338-8482
Source Type: Implementer
Street No:
Street 1: 371 CANDLELIGHT DR
Street 2:
City: SANTA ROSA
State: CA
Country:
Zip Code: 95403

Owner/Operator Ind: Current Owner
Type: Other
Name: VINYARD OPS INC
Date Became Current:
Date Ended Current:
Phone: 707-338-8482
Source Type: Implementer
Street No:
Street 1: 371 CANDLELIGHT DR
Street 2:
City: SANTA ROSA
State: CA
Country:
Zip Code: 95403

23	29 of 39	NW	0.09 / 467.28	114.06 / -6	VINYARD OPS INC 5900 PRUITT AVE 150 WINDSOR CA 95492	RCRA NON GEN

EPA Handler ID: CAL000445045
Gen Status Universe: No Report
Contact Name: GREG KOVACEVICH
Contact Address: 371 CANDLELIGHT DR , , SANTA ROSA , CA, 95403 ,
Contact Phone No and Ext: 707-338-8482
Contact Email: GREG@VINYARDOPS.COM
Contact Country:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

County Name: SONOMA
EPA Region: 09
Land Type:
Receive Date: 20190409
Location Latitude: 38.521404
Location Longitude: -122.790713

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20190409
Handler Name: VINYARD OPS INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Other
Name: GREG KOVACEVICH
Date Became Current:
Date Ended Current:
Phone: 707-338-8482
Source Type: Implementer
Street No:
Street 1: 371 CANDLELIGHT DR
Street 2:
City: SANTA ROSA
State: CA
Country:
Zip Code: 95403

Owner/Operator Ind: Current Owner
Type: Other
Name: VINYARD OPS INC
Date Became Current:
Date Ended Current:
Phone: 707-338-8482
Source Type: Implementer
Street No:
Street 1: 371 CANDLELIGHT DR
Street 2:
City: SANTA ROSA
State: CA
Country:
Zip Code: 95403

23	30 of 39	NW	0.09 / 467.28	114.06 / -6	PRAXIS AUTOMOTIVE 5900 PRUITT AVE STE 202 WINDSOR CA 95492	RCRA NON GEN

EPA Handler ID: CAL000448951
Gen Status Universe: No Report

Contact Name:	JUAN GUTIERREZ
Contact Address:	1062 LA CONTENTA CT , , WINDSOR , CA, 95492 ,
Contact Phone No and Ext:	707-490-4840
Contact Email:	JMANUEL7@ME.COM
Contact Country:	
County Name:	SONOMA
EPA Region:	09
Land Type:	
Receive Date:	20190918
Location Latitude:	
Location Longitude:	

Violation/Evaluation Summary

Note:	NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20190918
Handler Name:	PRAXIS AUTOMOTIVE
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Other	**Street 1:**	1062 LA CONTENTA CT
Name:	JUAN GUTIERREZ	**Street 2:**	
Date Became Current:		**City:**	WINDSOR
Date Ended Current:		**State:**	CA
Phone:	707-490-4840	**Country:**	
Source Type:	Implementer	**Zip Code:**	95492

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Other	**Street 1:**	1062 LA CONTENTA CT
Name:	JUAN GUTIERREZ	**Street 2:**	
Date Became Current:		**City:**	WINDSOR
Date Ended Current:		**State:**	CA
Phone:	707-490-4840	**Country:**	
Source Type:	Implementer	**Zip Code:**	95492

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
23	31 of 39	NW	0.09 / 467.28	114.06 / -6	5900 PRUITT AVE #164 WINDSOR CA	HMIRS

Incident County: SONOMA

HMIR Incident Reports

Report No:	X-2007030411	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2007-03-14	**Report Submit Src:**	XML
Time of Incident:	0900	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	3	**Mode Transport:**	Highway
Commodity Short Nm:	COMPOUNDS, CLEANING LIQU	**Transport Phase:**	In Transit
Commodity Long Nm:	COMPOUNDS, CLEANING LIQUID	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	NA1993	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	
TIH Hazard Zone:		**Carrier Reporter:**	Fedex Ground Package System, Inc.
Qty Released:	0.015625	**CR Street Name:**	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	**CR City:**	MOON TOWNSHIP
What Failed:	114	**CR State:**	PA
What Failed Desc:	Cylinder Valve	**CR Postal Code:**	15108
How Failed Code:	308	**CR Non US State:**	
How Failed Desc:	Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	515	**CR Hazmat Reg ID:**	062904001002M
Failure Cause Desc:	Human Error	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	PRINTERS SERVICES
Cont1 Pkging Type:	Box	**Shipper Street Name:**	1880 S CARLOS AVE
Cont1 Const Mat:	Fiberboard	**Shipper City:**	ONTARIO
Cont1 Head Type:		**Shipper State:**	CA
Cont1 Pkg Capacity:	0	**Shipper Postal:**	91761
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	48678630213932
Cont1 Pkg No:	0	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	0	**Origin City:**	
Cont1 Pkg Mnfctr:		**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	US
C1 Test Const Mat:	Fiberboard	**Destination City:**	PETALUMA
C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	94954
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	Cylinder
C1 Head Thick UOM:		**Cont2 Const Mat:**	Metal (any type)
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	0
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	0
C1 Device Model:		**Cont2 Pkg No Failed:**	0
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	MIKE EVERS
Damage > 500:	No	**Contact Title:**	SR MANAGER - HAZARDOUS MATERIALS
Material Loss:	0	**Contact Business:**	Fedex Ground Package System, Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	BOX FIBER
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

23	32 of 39	NW	0.09 / 467.28	114.06 / -6	5900 Pruitt Ave. STE 164 WINDSOR CA	HMIRS

Incident County: SONOMA

HMIR Incident Reports

Report No:	X-2007080165	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2007-08-03	**Report Submit Src:**	XML
Time of Incident:	2143	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	2.2	**Mode Transport:**	Highway
Commodity Short Nm:	FIRE EXTINGUISHERS CONTA	**Transport Phase:**	Unloading
Commodity Long Nm:	FIRE EXTINGUISHERS CONTAINING COMPRESSED OR LIQUEFIED GAS	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1044	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	
TIH Hazard Zone:		**Carrier Reporter:**	Fedex Ground Package System, Inc.
Qty Released:	20	**CR Street Name:**	1000 Fedex Drive

Unit of Measure:	Solid - Pound	**CR City:**	MOON TOWNSHIP
What Failed:	139	**CR State:**	PA
What Failed Desc:	O-Ring or Seals	**CR Postal Code:**	15108
How Failed Code:	303	**CR Non US State:**	
How Failed Desc:	Burst or Ruptured	**CR Fed DOT ID:**	265752
Failure Cause Code:	534	**CR Hazmat Reg ID:**	062904001002M
Failure Cause Desc:	Too Much Weight on Package	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	McMaster-Carr
Cont1 Pkging Type:	Box	**Shipper Street Name:**	9630 Norwalk Blvd
Cont1 Const Mat:	Fiberboard	**Shipper City:**	SANTA FE SPRINGS
Cont1 Head Type:		**Shipper State:**	CA
Cont1 Pkg Capacity:	0	**Shipper Postal:**	90670
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	90131600437965
Cont1 Pkg No:	0	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	0	**Origin City:**	
Cont1 Pkg Mnfctr:		**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	US
C1 Test Const Mat:	Fiberboard	**Destination City:**	SONOMA
C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95476
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	Cylinder
C1 Head Thick UOM:		**Cont2 Const Mat:**	Metal (any type)
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	0
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	0
C1 Device Model:		**Cont2 Pkg No Failed:**	0
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	Yes	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	TRAVIS MCEWEN
Damage > 500:	No	**Contact Title:**	SAFETY SPECIALIST III - HAZMAT
Material Loss:	0	**Contact Business:**	Fedex Ground Package System, Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier

Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	BOX FIBER
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the Fire Extinguisher(s) had a loose pin(s) with allowed leakage. The pin(s) were secured. The package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2007040029	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2007-03-19	**Report Submit Src:**	XML
Time of Incident:	1849	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	2.0	**Mode Transport:**	Highway
Commodity Short Nm:	PAINT	**Transport Phase:**	Unloading
Commodity Long Nm:	PAINT	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1263	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	
TIH Hazard Zone:		**Carrier Reporter:**	Fedex Ground Package System, Inc.
Qty Released:	0.75	**CR Street Name:**	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	**CR City:**	MOON TOWNSHIP
What Failed:	109	**CR State:**	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	**CR Postal Code:**	15108
How Failed Code:	302	**CR Non US State:**	
How Failed Desc:	Bent	**CR Fed DOT ID:**	265752
Failure Cause Code:	522	**CR Hazmat Reg ID:**	062904001002M
Failure Cause Desc:	Inadequate Procedures	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	E. I. Du Pont
Cont1 Pkging Type:	Box	**Shipper Street Name:**	11535 Production Dr.
Cont1 Const Mat:	Fiberboard	**Shipper City:**	RENO
Cont1 Head Type:		**Shipper State:**	NV
Cont1 Pkg Capacity:	0	**Shipper Postal:**	89506
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	25525930088205
Cont1 Pkg No:	0	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	0	**Origin City:**	
Cont1 Pkg Mnfctr:		**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	US
C1 Test Const Mat:	Fiberboard	**Destination City:**	FORT BRAGG
C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95437
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	Can
C1 Head Thick UOM:		**Cont2 Const Mat:**	Metal (any type)
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	0
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	

C1 Device Mnfctr:		**Cont2 Pkg No:**	0
C1 Device Model:		**Cont2 Pkg No Failed:**	0
NRC No:			
RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	MIKE EVERS
Damage > 500:	No	**Contact Title:**	SR MANAGER - HAZARDOUS MATERIALS
Material Loss:	0	**Contact Business:**	Fedex Ground Package System, Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	BOX FIBER
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The pail was unloaded with leakage noted. Examination of the pail revealed the pail had a loose cap/lid and leaked. The leakage was contained. The cap/lid was secured. Undamaged product was returned to the shipper. The damaged product was properly disposed of in accordance with Federal Regulations.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2007080222	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2007-08-15	**Report Submit Src:**	XML
Time of Incident:	1853	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	3	**Mode Transport:**	Highway
Commodity Short Nm:	PAINT RELATED MATERIAL I	**Transport Phase:**	Unloading
Commodity Long Nm:	PAINT RELATED MATERIAL INCLUDING PAINT THINNING, DRYING, REMOVING, OR REDUCING COMPOUND	**Incident Occrrnce:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1263	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	
TIH Hazard Zone:		**Carrier Reporter:**	Fedex Ground Package System, Inc.
Qty Released:	0.8	**CR Street Name:**	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	**CR City:**	MOON TOWNSHIP
What Failed:	128	**CR State:**	PA
What Failed Desc:	Inner Packaging	**CR Postal Code:**	15108
How Failed Code:	309	**CR Non US State:**	
How Failed Desc:	Punctured	**CR Fed DOT ID:**	265752
Failure Cause Code:	517	**CR Hazmat Reg ID:**	062904001002M
Failure Cause Desc:	Improper Preparation for Transportation	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	products/techniques
Cont1 Pkging Type:	Box	**Shipper Street Name:**	3271 s. riverside ave.
Cont1 Const Mat:	Fiberboard	**Shipper City:**	RIALTO
Cont1 Head Type:		**Shipper State:**	CA
Cont1 Pkg Capacity:	0	**Shipper Postal:**	92376
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	9102160043713
Cont1 Pkg No:	0	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	0	**Origin City:**	
Cont1 Pkg Mnfctr:		**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	US
C1 Test Const Mat:	Fiberboard	**Destination City:**	SANTA ROSA
C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95407
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	Can
C1 Head Thick UOM:		**Cont2 Const Mat:**	Metal (any type)
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	0
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	0
C1 Device Model:		**Cont2 Pkg No Failed:**	0
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	Yes	**Ship Non Transport:**	No
Fire EMS EMS Report:	8004249300	**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	TRAVIS MCEWEN
Damage > 500:	No	**Contact Title:**	SAFETY SPECIALIST III - HAZMAT
Material Loss:	0	**Contact Business:**	Fedex Ground Package System, Inc.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	BOX FIBER
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The pail was unloaded with leakage noted. Examination of the pail revealed the pail had been punctured and leaked. The leakage was contained and the package was repacked. Undamaged product was returned to the shipper. The damaged product was properly disposed of in accordance with Federal Regulations.

Recommend Actions Taken:

23	33 of 39	NW	0.09 / 467.28	114.06 / -6	5900 pruitt ave WINDSOR CA	HMIRS

Incident County: SONOMA

HMIR Incident Reports

Report No:	X-2008050309	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2008-05-09	**Report Submit Src:**	XML
Time of Incident:	1155	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	5.1	**Mode Transport:**	Highway
Commodity Short Nm:	HYDROGEN PEROXIDE, AQUEO	**Transport Phase:**	Unloading
Commodity Long Nm:	HYDROGEN PEROXIDE, AQUEOUS SOLUTIONS WITH NOT LESS THAN 20 PERCENT BUT NOT MORE THAN 40 PERCENT HYDROGEN PEROXIDE (STABILIZED AS NECESSARY)	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN2014	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	
TIH Hazard Zone:		**Carrier Reporter:**	Fedex Ground Package System, Inc.
Qty Released:	0.01	**CR Street Name:**	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	**CR City:**	MOON TOWNSHIP
What Failed:	134	**CR State:**	PA
What Failed Desc:	Liquid Valve	**CR Postal Code:**	15108
How Failed Code:	309	**CR Non US State:**	
How Failed Desc:	Punctured	**CR Fed DOT ID:**	265752
Failure Cause Code:	517	**CR Hazmat Reg ID:**	062904001002M
Failure Cause Desc:	Improper Preparation for Transportation	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	national discount pool supply
Cont1 Pkging Type:	Box	**Shipper Street Name:**	8920 58th pl.
Cont1 Const Mat:	Fiberboard	**Shipper City:**	KENOSHA
Cont1 Head Type:		**Shipper State:**	WI
Cont1 Pkg Capacity:	0	**Shipper Postal:**	53144
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US

C1 Pkg Amt UOM:		**Shipper Waybill:**	67871980285122
Cont1 Pkg No:	0	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	0	**Origin City:**	
Cont1 Pkg Mnfctr:		**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	
C1 Test Const Mat:	Fiberboard	**Destination City:**	HIDDEN VALLEY LAKE
C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95467
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	Bottle
C1 Head Thick UOM:		**Cont2 Const Mat:**	Plastic
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	0
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	0
C1 Device Model:		**Cont2 Pkg No Failed:**	0
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	TRAVIS MCEWEN
Damage > 500:	No	**Contact Title:**	SAFETY SPECIALIST III - HAZMAT
Material Loss:	0	**Contact Business:**	Fedex Ground Package System, Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	BOX FIBER
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2006100106	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2006-08-22	**Report Submit Src:**	XML
Time of Incident:	2027	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	8	**Mode Transport:**	Highway
Commodity Short Nm:	CORROSIVE LIQUID, BASIC,	**Transport Phase:**	In Transit Storage
Commodity Long Nm:	CORROSIVE LIQUID, BASIC, ORGANIC, N. O.S.	**Incident Occrrnce:**	
Trade Name:	SODIUM HYDROXIDE	**Mat Ship Approval?:**	No
ID No:	UN3267	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	
TIH Hazard Zone:		**Carrier Reporter:**	Fedex Ground Package System, Inc.
Qty Released:	5	**CR Street Name:**	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	**CR City:**	MOON TOWNSHIP
What Failed:	104	**CR State:**	PA
What Failed Desc:	Body	**CR Postal Code:**	15108
How Failed Code:	305	**CR Non US State:**	
How Failed Desc:	Crushed	**CR Fed DOT ID:**	265752
Failure Cause Code:	511	**CR Hazmat Reg ID:**	062904001002M
Failure Cause Desc:	Dropped	**CR Country:**	US
Ident. Markings:	NO MARKINGS GIVEN	**Shipper Name:**	Light House of Houston
Cont1 Pkging Type:		**Shipper Street Name:**	3530 W. Dallas
Cont1 Const Mat:		**Shipper City:**	HOUSTON
Cont1 Head Type:		**Shipper State:**	TX
Cont1 Pkg Capacity:	0	**Shipper Postal:**	77019
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	032486030090539
Cont1 Pkg No:	0	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	0	**Origin City:**	
Cont1 Pkg Mnfctr:		**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	
C1 Test Const Mat:		**Destination City:**	WINDSOR
C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95492
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	
C1 Head Thick UOM:		**Cont2 Const Mat:**	
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	0
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	0
C1 Device Model:		**Cont2 Pkg No Failed:**	0
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0

RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	SCOTT KERR
Damage > 500:	No	**Contact Title:**	TSM MANAGER II - SAFETY
Material Loss:	0	**Contact Business:**	Fedex Ground Package System, Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	CONTAINER
Haz Hosp Old Form:	0	**HMIS Container Code:**	CONT
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Container, no description given (do not use if at all possible)
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2006100416	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2006-07-05	**Report Submit Src:**	XML
Time of Incident:	0600	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	2.0	**Mode Transport:**	Highway
Commodity Short Nm:	PAINT	**Transport Phase:**	Loading
Commodity Long Nm:	PAINT	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No
ID No:	UN1263	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	
TIH Hazard Zone:		**Carrier Reporter:**	Fedex Ground Package System, Inc.
Qty Released:	0.023438	**CR Street Name:**	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	**CR City:**	MOON TOWNSHIP
What Failed:	109	**CR State:**	PA
What Failed Desc:	Closure (e.g., Cap, Top, or Plug)	**CR Postal Code:**	15108
How Failed Code:	308	**CR Non US State:**	
How Failed Desc:	Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	511	**CR Hazmat Reg ID:**	062904001002M
Failure Cause Desc:	Dropped	**CR Country:**	US

Ident. Markings:	NO MARKINGS GIVEN	**Shipper Name:**	BASF Corporation
Cont1 Pkging Type:		**Shipper Street Name:**	6700 8th st.
Cont1 Const Mat:		**Shipper City:**	BUENA PARK
Cont1 Head Type:		**Shipper State:**	CA
Cont1 Pkg Capacity:	0	**Shipper Postal:**	90620
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	92544160022317
Cont1 Pkg No:	0	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	0	**Origin City:**	
Cont1 Pkg Mnfctr:		**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	US
C1 Test Const Mat:		**Destination City:**	
C1 Pkg Dsign Pres.:	0	**Destination State:**	
C1 Dsign Press UOM:		**Destination Postal:**	
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	
C1 Head Thickness:	0	**Cont2 Package Type:**	
C1 Head Thick UOM:		**Cont2 Const Mat:**	
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	0
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	0
C1 Device Model:		**Cont2 Pkg No Failed:**	0
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	DENISE HANCHULAK
Damage > 500:	No	**Contact Title:**	TSM MANAGER II - SAFETY
Material Loss:	0	**Contact Business:**	Fedex Ground Package System, Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No

Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	PAIL
Haz Hosp Old Form:	0	**HMIS Container Code:**	PAIL
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Pail, open head, capacity 10 gallons or less
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The pail was dropped during handling causing leakage. The leakage was contained and the package was repacked. Undamaged product was returned to the shipper. The damaged product was properly disposed of in accordance with Federal Regulations.

Recommend Actions Taken:

HMIR Incident Reports

Report No:	X-2006030247	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2006-03-10	**Report Submit Src:**	XML
Time of Incident:	0630	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	8	**Mode Transport:**	Highway
Commodity Short Nm:	CORROSIVE LIQUID, ACIDIC	**Transport Phase:**	Loading
Commodity Long Nm:	CORROSIVE LIQUID, ACIDIC, INORGANIC, N.O.S.	**Incident Occrrnce:**	
Trade Name:	SODIUM HYDROXIDE	**Mat Ship Approval?:**	No
ID No:	UN3264	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	
TIH Hazard Zone:		**Carrier Reporter:**	Fedex Ground Package System, Inc.
Qty Released:	1	**CR Street Name:**	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	**CR City:**	MOON TOWNSHIP
What Failed:	135	**CR State:**	PA
What Failed Desc:	Loading or Unloading Lines	**CR Postal Code:**	15108
How Failed Code:	309	**CR Non US State:**	
How Failed Desc:	Punctured	**CR Fed DOT ID:**	265752
Failure Cause Code:	511	**CR Hazmat Reg ID:**	062904001002M
Failure Cause Desc:	Dropped	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	birchwoob lab inc
Cont1 Pkging Type:	Box	**Shipper Street Name:**	7900 fuller rd
Cont1 Const Mat:	Fiberboard	**Shipper City:**	EDEN PRAIRIE
Cont1 Head Type:		**Shipper State:**	MN
Cont1 Pkg Capacity:	0	**Shipper Postal:**	55344
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	055404811430436
Cont1 Pkg No:	0	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	0	**Origin City:**	
Cont1 Pkg Mnfctr:		**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	US
C1 Test Const Mat:	Fiberboard	**Destination City:**	SANTA ROSA
C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95401
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	Bottle
C1 Head Thick UOM:		**Cont2 Const Mat:**	Plastic
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	0
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	0
C1 Device Model:		**Cont2 Pkg No Failed:**	0
NRC No:			
RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	DENISE HANCHULAK
Damage > 500:	No	**Contact Title:**	TSM MANAGER II - SAFETY
Material Loss:	0	**Contact Business:**	Fedex Ground Package System, Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive
Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	BOX FIBER
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was dropped in handling. Examination of the inner container revealed a ruptured seam which allowed the contents to escape. The leakage was contained. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

23	*34 of 39*	*NW*	*0.09 / 467.28*	*114.06 / -6*	***5900 pruitt ave # 164 SANTA ROSA CA***	***HMIRS***

Incident County: SONOMA

HMIR Incident Reports

Report No:	X-2008090095	**Fed DOT Agency Nm:**	
Report Type:	A hazardous material incident	**Fed DOT Report No:**	
Date of Incident:	2008-08-27	**Report Submit Src:**	XML
Time of Incident:	0545	**Inc Multiple Rows:**	No
Haz Class Code:		**Inc Non US State:**	
Hazardous Class:	8	**Mode Transport:**	Highway
Commodity Short Nm:	SODIUM HYDROXIDE, SOLUTI	**Transport Phase:**	Unloading
Commodity Long Nm:	SODIUM HYDROXIDE, SOLUTION	**Incident Occrrnce:**	
Trade Name:		**Mat Ship Approval?:**	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

ID No:	UN1824	**Mat Ship Approv No:**	
Haz Waste Ind:	No	**Undecl Hazmat Ship?:**	No
Haz Waste EPA No:		**Packaging Type:**	Non-Bulk
HMIS Tox Inhalation?:	No	**Packing Group:**	II
TIH Hazard Zone:		**Carrier Reporter:**	Fedex Ground Package System, Inc.
Qty Released:	0.002642	**CR Street Name:**	1000 Fedex Drive
Unit of Measure:	Liquid - Gallon	**CR City:**	MOON TOWNSHIP
What Failed:	128	**CR State:**	PA
What Failed Desc:	Inner Packaging	**CR Postal Code:**	15108
How Failed Code:	308	**CR Non US State:**	
How Failed Desc:	Leaked	**CR Fed DOT ID:**	265752
Failure Cause Code:	526	**CR Hazmat Reg ID:**	062904001002M
Failure Cause Desc:	Loose Closure, Component, or Device	**CR Country:**	US
Ident. Markings:		**Shipper Name:**	auqa solutions
Cont1 Pkging Type:	Box	**Shipper Street Name:**	6913 hwy 225
Cont1 Const Mat:	Fiberboard	**Shipper City:**	DEER PARK
Cont1 Head Type:		**Shipper State:**	TX
Cont1 Pkg Capacity:	0	**Shipper Postal:**	77536
C1 Capacity UOM:		**Shipper Non US St:**	
Cont1 Pkg Amt:	0	**Shipper Country:**	US
C1 Pkg Amt UOM:		**Shipper Waybill:**	35758362532641
Cont1 Pkg No:	0	**Ship Hazmat Reg ID:**	
C1 Pkg NO Failed:	0	**Origin City:**	
Cont1 Pkg Mnfctr:		**Origin State:**	
Cont1 Pkg Mnfct Dt:	0-00-00 00:00:00	**Origin Postal:**	
Cont1 Pkg Serial NO:		**Origin Non US St:**	
C1 Pkg Last Test Dt:	0-00-00 00:00:00	**Origin Country:**	
C1 Test Const Mat:	Fiberboard	**Destination City:**	HEALDSBURG
C1 Pkg Dsign Pres.:	0	**Destination State:**	CALIFORNIA
C1 Dsign Press UOM:		**Destination Postal:**	95448
C1 Pkg Shell Thick:	0	**Destination Non US:**	
C1 Shell Thick UOM:		**Destination Country:**	US
C1 Head Thickness:	0	**Cont2 Package Type:**	Bottle
C1 Head Thick UOM:		**Cont2 Const Mat:**	Plastic
C1 Pkg Srvc Pres.:	0	**Cont2 Pkg Capacity:**	0
C1 Srvc Press UOM:		**Cont2 Capacity UOM:**	
C1 Valve/Device Fail?:	No	**Cont2 Pkg Amount:**	0
C1 Device Type:		**Cont2 Pkg Amt UOM:**	
C1 Device Mnfctr:		**Cont2 Pkg No:**	0
C1 Device Model:		**Cont2 Pkg No Failed:**	0
NRC No:			

RAM Pkg Category:		**Haz NonHosp Public:**	0
RAM Pkg Cert.:	FALSE	**Haz NonHosp Old:**	
RAM Pkg Cert. NBR:		**Tot Haz Non Hosp Inj:**	
RAM Nuclide S:		**Total Hazmat Injuries:**	0
RAM Transport Index:		**Evacuation Indicator:**	No
RAM UOM:		**Public Evacuated:**	0
RAM Activity Rpted:	0	**Employees Evac:**	0
RAM UOM Rpted:		**Total Evacuated:**	0
RAM Activity:	0	**Total Evacuation Hrs:**	0
RAM Activity UOM:		**Major Artery Closed:**	No
RAM Mat Safety:		**Mjr Artery Hrs Closed:**	0
Spillage Result:	Yes	**Material Involved:**	No
Fire Result:	No	**Estimated Speed:**	0
Explosion Result:	No	**Weather Conditions:**	
Water Sewer Result:	No	**Vehicle Overturn:**	No
Gas Dispersion:	No	**Vehicle Left Roadway:**	No
Environment Damage:	No	**Passenger Aircraft:**	No
No Release Result:	No	**Cargo Baggage:**	
Fire EMS Report:	No	**Ship Non Transport:**	No
Fire EMS EMS Report:		**Ship Air First Flight:**	No
Police Report:	No	**Ship Air Subflight:**	No
Police Report No:		**Ship Init Transport:**	No
In House Cleanup:	Yes	**Ship Phase Transfer:**	No
Other Cleanup:	No	**Contact Name:**	TRAVIS MCEWEN
Damage > 500:	No	**Contact Title:**	SAFETY SPECIALIST III - HAZMAT
Material Loss:	0	**Contact Business:**	Fedex Ground Package System, Inc.
Carrier Damage:	0	**Contact Street:**	1000 Fedex Drive

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Property Damage:	0	**Contact City:**	MOON TOWNSHIP
Response Cost:	0	**Contact State:**	PA
Remediation Cost:	0	**Contact Postal:**	15108
Damage Old Form:	0	**Contact Non US St:**	
Total Damages Amt:	0	**Contact Country:**	US
Hazmat Fatality:	No	**Inc. Report Prepared:**	Carrier
Haz Fatal Employees:	0	**HMIS Serious Incidnt:**	No
Haz Fatal Respndrs:	0	**HMIS Serious Fatality:**	No
Haz Fatal Gen Public:	0	**HMIS Serious Injury:**	No
Tot Hazmat Fatalities:	0	**HMIS Flight Plan:**	No
Non Hazmat Fatality:	No	**HMIS Serious Evacs:**	No
Non Hazmat Fatals:	0	**HMIS Major Artery:**	No
Hazmat Injury:	No	**HMIS Bulk Release:**	No
Haz Hospital Empl:	0	**HMIS Marine Pollutnt:**	No
Haz Hospital Resp:	0	**HMIS Radioactive:**	No
Haz Hosp Gen Public:	0	**HMIS Gen Pkg Type:**	BOX FIBER
Haz Hosp Old Form:	0	**HMIS Container Code:**	BOX FBR
Total Haz Hosp Inj:	0	**HMIS Container Desc:**	Fiberboard box or carton
Haz Non Hosp Empl:	0	**HMIS Bulk Incident:**	No
Haz Non Hosp Resp:	0	**Undeclared Shipment:**	No

Description of Events: The package was unloaded with leakage noted on the box. Examination of the inner container revealed that the container(s) had loose cap(s) and leaked. The leakage was contained. The cap(s) were secured. The carton was wet but otherwise undamaged. The undamaged portion of the package was repacked for return to shipper.

Recommend Actions Taken:

23	35 of 39	NW	0.09 / 467.28	114.06 / -6	**Sonoma Brothers Distilling** **5900 PRUITT AVE STE 404** **WINDSOR CA 95492**	CERS HAZ

Site ID: 565956
Latitude: 38.521160
Longitude: -122.789880
County:

Regulated Programs

EI ID: 10841797 **EI Description:** Chemical Storage Facilities

Evaluations

Eval Date: 03/26/2021
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

No violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Affiliations

Affil Type Desc: Parent Corporation
Entity Name: Sonoma Brothers Distilling
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Facility Mailing Address

Entity Name:	Mailing Address
Entity Title:	
Address:	7759 Bell Road
City:	Windsor
State:	CA
Country:	
Zip Code:	95492
Phone:	

Affil Type Desc:	Operator
Entity Name:	Christopher Matthies
Entity Title:	
Address:	
City:	
State:	
Country:	
Zip Code:	
Phone:	(707) 888-2120

Affil Type Desc:	Document Preparer
Entity Name:	Christopher Matthies
Entity Title:	
Address:	
City:	
State:	
Country:	
Zip Code:	
Phone:	

Affil Type Desc:	Property Owner
Entity Name:	SOCO Investments, LLC
Entity Title:	
Address:	5892 Pruitt Avenue
City:	Windsor
State:	CA
Country:	United States
Zip Code:	95492
Phone:	(707) 836-4336

Affil Type Desc:	Environmental Contact
Entity Name:	Christopher Matthies
Entity Title:	
Address:	7759 Bell Road
City:	Windsor
State:	CA
Country:	
Zip Code:	95492
Phone:	

Affil Type Desc:	CUPA District
Entity Name:	Sonoma County Fire Prevention and Hazmat
Entity Title:	
Address:	2300 County Center Drive, Suite 220-B
City:	Santa Rosa
State:	CA
Country:	
Zip Code:	95403
Phone:	(707) 565-2024

Affil Type Desc:	Identification Signer
Entity Name:	Christopher Matthies
Entity Title:	Owner
Address:	
City:	
State:	
Country:	
Zip Code:	
Phone:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Affil Type Desc:	Legal Owner
Entity Name:	Christopher Matthies
Entity Title:	
Address:	7759 Bell Road
City:	Windsor
State:	CA
Country:	United States
Zip Code:	95492
Phone:	(707) 888-2120

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
23	36 of 39	NW	0.09 / 467.28	114.06 / -6	SELENES FRAME AND BODYWORKS 5900 PRUITT AVE STE 104 WINDSOR CA 95492	RCRA NON GEN

EPA Handler ID:	CAL000451464
Gen Status Universe:	No Report
Contact Name:	WILLIAM ALEXANDER
Contact Address:	1055 STONY GLEN LN , , COTATI , CA, 94931 ,
Contact Phone No and Ext:	707-888-5156
Contact Email:	BILL@ALEXANDERCOATINGS.COM
Contact Country:	
County Name:	SONOMA
EPA Region:	09
Land Type:	
Receive Date:	20191219
Location Latitude:	
Location Longitude:	

Violation/Evaluation Summary

Note:	NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20191219
Handler Name:	SELENES FRAME AND BODYWORKS
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Other	**Street 1:**	1055 STONY GLEN LN
Name:	WILLIAM ALEXANDER	**Street 2:**	
Date Became Current:		**City:**	COTATI
Date Ended Current:		**State:**	CA
Phone:	707-888-5156	**Country:**	
Source Type:	Implementer	**Zip Code:**	94931

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Other	**Street 1:**	1055 STONY GLEN LN
Name:	WILLIAM R ALEXANDER	**Street 2:**	
Date Became Current:		**City:**	COTATI
Date Ended Current:		**State:**	CA
Phone:	707-888-5156	**Country:**	
Source Type:	Implementer	**Zip Code:**	94931

23	37 of 39	NW	0.09 / 467.28	114.06 / -6	**USEPA R9 SONOMA FIRE RESPONSE** **5900 PRUITT AVENUE** **WINDSOR CA 95492**	RCRA LQG

EPA Handler ID:	CAP000216017
Gen Status Universe:	Large Quantity Generator
Contact Name:	STEVE CALANOG
Contact Address:	75 HAWTHORNE STREET , , SAN FRANCISCO , CA, 94105 , US
Contact Phone No and Ext:	415-972-3075
Contact Email:	CALANOG.STEVE@EPA.GOV
Contact Country:	US
County Name:	SONOMA
EPA Region:	09
Land Type:	Private
Receive Date:	20171025
Location Latitude:	38.521404
Location Longitude:	-122.790713

Violation/Evaluation Summary

Note:	NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20171025
Handler Name:	USEPA R9 SONOMA FIRE RESPONSE
Federal Waste Generator Code:	1
Generator Code Description:	Large Quantity Generator

Source Type: Notification

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Federal
Name: USEPA REGION 9
Date Became Current: 20171025
Date Ended Current:
Phone: 415-972-3075
Source Type: Notification
Street No:
Street 1: 75 HAWTHORNE STREET
Street 2:
City: SAN FRANCISCO
State: CA
Country: US
Zip Code: 94105

Owner/Operator Ind: Current Operator
Type: Federal
Name: USEPA REGION 9
Date Became Current: 20171025
Date Ended Current:
Phone: 415-972-3075
Source Type: Notification
Street No:
Street 1: 75 HAWTHORNE STREET
Street 2:
City: SAN FRANCISCO
State: CA
Country: US
Zip Code: 94105

---

23 | ***38 of 39*** | ***NW*** | ***0.09 / 467.28*** | ***114.06 / -6*** | ***Sonoma Brothers Distilling 5900 Pruitt Ave Ste 404 Windsor, CA 95492 CA*** | ***CUPA SONOMA***

Facility ID: 49-000-008697
CERS ID: 10841797

Details

Program Type: Stormwater
Permit Status: Active
Expiration Date: 3/26/2024
Fee Schedule: Storm Water Permit

Details

Program Type: HMBP
Permit Status: Active
Expiration Date: 3/26/2024
Fee Schedule: Range 2

---

23 | ***39 of 39*** | ***NW*** | ***0.09 / 467.28*** | ***114.06 / -6*** | ***Atlas Tree Recycling Facility 5900 Pruitt Ave Windsor CA 95492*** | ***SWF/LF***

SWIS No: 49-AA-0447
EPA Fed Registry ID:
Operational Status: Active
Regulatory Status: Permitted
Site is Archived: No
Absorbed on:
Absorbed by:
Site Inert Debris Eng Fill: No
Closed Illegal Aband: No
Closed Illegal Aband Cat:
Finance Assuran Responsible: No
Incorporated City: Windsor
Local Government: Windsor
Latitude: 38.52237
Longitude: -122.7909
County: Sonoma
Site ZIP: 95492
ARB District: Bay Area
SWRCB Region: North Coast
Site Point of Contact: Alyssa Williams

Reporting Agency Legal Name: County of Sonoma
Reporting Agency Department: Department of Health Services, Environmental Health & Safety Section
Enforcing Agency Legal Name: County of Sonoma
Enforcing Agency Department: Department of Health Services, Environmental Health & Safety Section

Site Owners

Site Type: Non-Disposal Only
Owner Name: SOCO Investments, Inc
Owner Address: P.O. Box 1878
Owner City: Windsor
Owner State: CA
Owner ZIP Code: 95492
Owner Phone: (707) 836-4336
Contact Name:
Contact First Name:
Contact Last Name:
Contact Title:
Contact Email:
Started On:

Site Activities (Search Result)

ID: 5448
Act Opl Status: Active
Site Name: Atlas Tree Recycling Facility
Activity: Chipping and Grinding Facility/Operation
Act Regulatory Stat: Permitted
Activity Category: Composting

Site Operators

Site Type: Non-Disposal Only
Operator Name: Atlas Tree Surgery
Operator Address: 1544 Ludwig Avenue
Operator City: Santa Rosa
Operator State: CA
Operator ZIP Code: 95407
Operator Phone: (707) 523-4399
Is Archived: No
Contact Name:
Contact First Name:
Contact Last Name:
Contact Title:
Contact Email:
Started on:

Site Waste

Site Type: Non-Disposal Only
Waste Type: Wood waste
Activity Oper Status: Active
Act Regulatory Stat: Permitted
Activity: Chipping and Grinding Facility/Operation
Activity Category: Composting
Act Classification: Solid Waste Facility
Activity Is Archived: No

Site Type: Non-Disposal Only
Waste Type: Green Materials
Activity Oper Status: Active
Act Regulatory Stat: Permitted
Activity: Chipping and Grinding Facility/Operation
Activity Category: Composting
Act Classification: Solid Waste Facility
Activity Is Archived: No

Extra Details

Enforcement Agency (LEA/EA): Sonoma County

Site Activities (Export)

WDR No:
WDR Landfill Class:
Act is Archived: No
Act Opl Status: Active
Act Regulatory Stat: Permitted
Activity Category: Composting
Act Classification: Solid Waste Facility
Cease Operation:
Cease Operation Tp:
Insp Frequency: Monthly
Remaining Capacity:
Remaining Cap Dt:
Max Permit Cap: 1500
Capacity UOM: Tons per day
Total Acreage: 2.00
Disposal Acreage:
Permitted Elev :
Permitted Elev Tp:
Permitted Depth:
Permitted Depth Tp:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Incorporated City: Windsor
Site Name: Atlas Tree Recycling Facility
Site Point of Contact: Alyssa Williams
Activity: Chipping and Grinding Facility/Operation
Max Permitted Throughput: 500
Throughput UOM: Tons per day

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
24	1 of 2	NNW	0.09 / 500.17	114.89 / -5	KFC/A&W 6610 Hembree Ln Windsor, CA 95492 CA	CUPA SONOMA

Facility ID: 49-000-007905
CERS ID: 10600210

Details

Program Type: HMBP
Permit Status: Active
Expiration Date: 10/3/2020
Fee Schedule: Range 9 - Restaurants > 1000 SCF CO2

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
24	2 of 2	NNW	0.09 / 500.17	114.89 / -5	KFC/A&W 6610 HEMBREE LN WINDSOR CA 95492	CERS HAZ

Site ID: 127814
Latitude: 38.527130
Longitude: -122.790169
County:

Regulated Programs

EI ID: 10600210
EI Description: Chemical Storage Facilities

Violations

Violation Date: 01/03/2014
Violation Source: CERS
Violation Program: HMRRP
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: HSC 6.95 25503.5(a) - California Health and Safety Code, Chapter 6.95, Section(s) 25503.5(a)
Violation Notes:

Returned to compliance on 08/22/2017. Submit HMBP thru CERS within 30 days

Violation Description:

Owner/Operator failed to establish and implement a Hazardous Materials Business Plan when storing hazardous materials at or above the thresholds quantities of 55 gallons/500 lbs/200 cubic feet.

Violations

Violation Date: 11/06/2018
Violation Source: CERS
Violation Program: HMRRP
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)
Violation Notes:

Returned to compliance on 12/03/2018. The business failed to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material including familiarity with the emergency response plan or failure to document and maintain training records for a minimum of three years. Establish and electronically submit an employee training program containing provisions to ensure initial and annual training for all employees in safety procedures in the event of a release or threatened release of a hazardous material and document and maintain training records for a minimum of three years.

Violation Description:

Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.

Violations

Violation Date: 10/13/2015
Violation Source: CERS
Violation Program: HMRRP
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95, Section(s) 25508.2
Violation Notes:

Returned to compliance on 12/23/2015. Owner/Operator failed to submit inventory reports (Activities, Owner/Operator, Hazardous Materials Descriptions and Map pages, if required. Documentation must be resubmitted (for facilities which exceed EPCRA thresholds) or re-certified (for facilities which do not exceed EPCRA thresholds) by March 1. Owner/Operator shall submit inventory reports (Activities, Owner/Operator, Hazardous Materials Descriptions and Map pages, if required. Documentation must be resubmitted (for facilities which exceed EPCRA thresholds) or re-certified (for facilities which do not exceed EPCRA thresholds) by March 1.

Violation Description:

Failure to annually review and electronically certify that the business plan is complete, accurate, and up-to-date.

Evaluations

Eval Date: 10/13/2015
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Must Recertify HMBP on CERS; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 01/03/2014
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Eval Date: 11/06/2018
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

1) There is a haz mat training program but they didn't train this past year; requested signoff sheets. 2) CO2 storage area was blocked by dumpsters; requested minimum 36 inchs; dumpster moved; request also confirm via email. C02 storage area was crammed full of old equipment; request that it be accessible and remove old junk.. 4) Requested NFPA Placard on the CO2 storage door.. Documentation to be provided within 30 days.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Affiliations

Affil Type Desc: Facility Mailing Address

Entity Name:	Mailing Address
Entity Title:	
Address:	2846 Volpey Way
City:	Union City
State:	CA
Country:	
Zip Code:	94587
Phone:	

Affil Type Desc:	Identification Signer
Entity Name:	Travis Gutke
Entity Title:	Director of Real Estate
Address:	
City:	
State:	
Country:	
Zip Code:	
Phone:	

Affil Type Desc:	Property Owner
Entity Name:	HARMAN MANAGEMENT CORP
Entity Title:	
Address:	199 First Street Suite 212
City:	Los Altos
State:	CA
Country:	United States
Zip Code:	94022
Phone:	(650) 941-5681

Affil Type Desc:	Legal Owner
Entity Name:	Harman Managemenmt Corp.
Entity Title:	
Address:	199 First Street Suite 212
City:	Los Altos
State:	CA
Country:	United States
Zip Code:	94022
Phone:	(650) 941-5681

Affil Type Desc:	Parent Corporation
Entity Name:	KFC/A&W
Entity Title:	
Address:	
City:	
State:	
Country:	
Zip Code:	
Phone:	

Affil Type Desc:	Operator
Entity Name:	Kentucky Fried Chicken/A&W
Entity Title:	
Address:	
City:	
State:	
Country:	
Zip Code:	
Phone:	(707) 837-2740

Affil Type Desc:	CUPA District
Entity Name:	Sonoma County Fire Prevention and Hazmat
Entity Title:	
Address:	2300 County Center Drive, Suite 220-B
City:	Santa Rosa
State:	CA
Country:	
Zip Code:	95403
Phone:	(707) 565-2024

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Affil Type Desc: Document Preparer
Entity Name: Travis Gutke
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Environmental Contact
Entity Name: Lourdes Fajardo
Entity Title:
Address: 2846 Volpey Way
City: Union City
State: CA
Country:
Zip Code: 94587
Phone:

Coordinates

Env Int Type Code: HMBP
Program ID: 10600210
Latitude: 38.527160
Longitude: -122.790160
Coord Name:
Ref Point Type Desc: Center of a facility or station.

25	*1 of 1*	*WNW*	*0.12 / 611.61*	*113.05 / -7*	***Best Truck Body & Trailer Repair, Inc.*** ***610 Caletti Rd WINDSOR, CA 95492*** ***CA***	***DELISTED COUNTY***

Original Source Facility ID:
Original Source Name: Sonoma County CUPA Facilities List
Record Date: 11-JAN-2016

26	*1 of 5*	*WNW*	*0.12 / 629.02*	*113.07 / -7*	***IMAGE TREE SERVICE, INC.*** ***564 CALETTI AVENUE*** ***WINDSOR CA 95492***	***RCRA NON GEN***

EPA Handler ID: CAC002983223
Gen Status Universe: No Report
Contact Name: EILEEN DIBARTOLO
Contact Address: 564 CALETTI AVENUE , , WINDSOR , CA, 95492 ,
Contact Phone No and Ext: 707-838-3555
Contact Email: EILEEN@IMAGETREESERVICE.COM
Contact Country:
County Name: SONOMA
EPA Region: 09
Land Type:
Receive Date: 20181003
Location Latitude: 38.523344
Location Longitude: -122.793156

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20181003
Handler Name:	IMAGE TREE SERVICE, INC.
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street 1:***	564 CALETTI AVENUE
Name:	JEFF KOWELL	***Street 2:***	
Date Became Current:		***City:***	WINDSOR
Date Ended Current:		***State:***	CA
Phone:	707-838-3555	***Country:***	
Source Type:	Implementer	***Zip Code:***	95492
Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street 1:***	564 CALETTI AVENUE
Name:	EILEEN DIBARTOLO	***Street 2:***	
Date Became Current:		***City:***	WINDSOR
Date Ended Current:		***State:***	CA
Phone:	707-838-3555	***Country:***	
Source Type:	Implementer	***Zip Code:***	95492

26	*2 of 5*	*WNW*	*0.12 / 629.02*	*113.07 / -7*	***IMAGE TREE SERVICE, INC.*** ***564 CALETTI AVENUE*** ***WINDSOR CA 95492***	***RCRA TSD***

EPA Handler ID:	CAC003009363
Gen Status Universe:	No Report
Contact Name:	EILEEN DIBARTOLO
Contact Address:	564 CALETTI AVENUE , , WINDSOR , CA, 95492 ,
Contact Phone No and Ext:	707-838-3555
Contact Email:	EILEEN@IMAGETREESERVICE.COM
Contact Country:	
Land Type:	
County Name:	SONOMA
EPA Region:	09
Receive Date:	20190409
Location Latitude:	38.523344
Location Longitude:	-122.793156

Violation/Evaluation Summary

Note:	NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Smelting, Melting and Refining:	No
Underground Injection Control:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20190409
Handler Name:	IMAGE TREE SERVICE, INC.
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Implementer

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street 1:***	564 CALETTI AVENUE
Name:	JEFF KOWELL	***Street 2:***	
Date Became Current:		***City:***	WINDSOR
Date Ended Current:		***State:***	CA
Phone:	707-838-3555	***Country:***	
Source Type:	Implementer	***Zip Code:***	95492
Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street 1:***	564 CALETTI AVENUE
Name:	EILEEN DIBARTOLO	***Street 2:***	
Date Became Current:		***City:***	WINDSOR
Date Ended Current:		***State:***	CA
Phone:	707-838-3555	***Country:***	
Source Type:	Implementer	***Zip Code:***	95492

26	***3 of 5***	***WNW***	***0.12 / 629.02***	***113.07 / -7***	***IMAGE TREE SERVICE, INC. 564 CALETTI AVENUE WINDSOR CA 95492***	***RCRA NON GEN***

EPA Handler ID:	CAC003009363
Gen Status Universe:	No Report
Contact Name:	EILEEN DIBARTOLO
Contact Address:	564 CALETTI AVENUE , , WINDSOR , CA, 95492 ,
Contact Phone No and Ext:	707-838-3555
Contact Email:	EILEEN@IMAGETREESERVICE.COM
Contact Country:	
County Name:	SONOMA
EPA Region:	09
Land Type:	
Receive Date:	20190409
Location Latitude:	38.523344
Location Longitude:	-122.793156

Violation/Evaluation Summary

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20190409
Handler Name:	IMAGE TREE SERVICE, INC.
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Other	**Street 1:**	564 CALETTI AVENUE
Name:	JEFF KOWELL	**Street 2:**	
Date Became Current:		**City:**	WINDSOR
Date Ended Current:		**State:**	CA
Phone:	707-838-3555	**Country:**	
Source Type:	Implementer	**Zip Code:**	95492
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Other	**Street 1:**	564 CALETTI AVENUE
Name:	EILEEN DIBARTOLO	**Street 2:**	
Date Became Current:		**City:**	WINDSOR
Date Ended Current:		**State:**	CA
Phone:	707-838-3555	**Country:**	
Source Type:	Implementer	**Zip Code:**	95492

26	***4 of 5***	***WNW***	***0.12 / 629.02***	***113.07 / -7***	***IMAGE TREE SERVICE, INC. 564 CALETTI AVENUE WINDSOR CA 95492***	***RCRA NON GEN***

EPA Handler ID:	CAC003052512
Gen Status Universe:	No Report
Contact Name:	EILEEN DIBARTOLO
Contact Address:	564 CALETTI AVENUE , , WINDSOR , CA, 95492 ,
Contact Phone No and Ext:	707-838-3355
Contact Email:	INFO@IMAGETREESERVICE.COM
Contact Country:	
County Name:	SONOMA
EPA Region:	09
Land Type:	
Receive Date:	20200123
Location Latitude:	

Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20200123
Handler Name:	IMAGE TREE SERVICE, INC.
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street 1:***	564 CALETTI AVENUE
Name:	JEFF KOWELL	***Street 2:***	
Date Became Current:		***City:***	WINDSOR
Date Ended Current:		***State:***	CA
Phone:	707-756-0501	***Country:***	
Source Type:	Implementer	***Zip Code:***	95492

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street 1:***	564 CALETTI AVENUE
Name:	EILEEN DIBARTOLO	***Street 2:***	
Date Became Current:		***City:***	WINDSOR
Date Ended Current:		***State:***	CA
Phone:	707-838-3355	***Country:***	
Source Type:	Implementer	***Zip Code:***	95492

26	***5 of 5***	***WNW***	***0.12 / 629.02***	***113.07 / -7***	***IMAGE TREE SERVICE INC 564 CALETTI AVE WINDSOR CA 95492***	***RCRA NON GEN***

EPA Handler ID:	CAL000461048
Gen Status Universe:	No Report
Contact Name:	EILEEN DIBARTOLO
Contact Address:	564 CALETTI AVE , , WINDSOR , CA, 95492 ,
Contact Phone No and Ext:	707-838-3555
Contact Email:	EILEEN@IMAGETREESERVICE.COM
Contact Country:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

County Name: SONOMA
EPA Region: 09
Land Type:
Receive Date: 20210317
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20210317
Handler Name: IMAGE TREE SERVICE INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Other
Name: EILEEN DIBARTOLO
Date Became Current:
Date Ended Current:
Phone: 707-838-3555
Source Type: Implementer
Street No:
Street 1: 564 CALETTI AVE
Street 2:
City: WINDSOR
State: CA
Country:
Zip Code: 95492

Owner/Operator Ind: Current Owner
Type: Other
Name: IMAGE TREE SERVICE INC
Date Became Current:
Date Ended Current:
Phone: 707-756-0501
Source Type: Implementer
Street No:
Street 1: 10024 LOCH HAVEN DR
Street 2:
City: SANTA ROSA
State: CA
Country:
Zip Code: 95404

27	1 of 1	WNW	0.12 / 631.88	113.09 / -7	Best Truck Body Repair 600 Caletti Windsor, CA 95492 CA	DELISTED COUNTY

Original Source Facility ID:
Original Source Name: Sonoma County CUPA Facilities List

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Record Date:		11-JAN-2016				
28	1 of 1	WNW	0.12 / 645.61	113.07 / -7	WATERWORKS INDUSTRIES INC 930 SHILOH RD BLDG 38 STE D WINDSOR CA 95492	RCRA NON GEN

EPA Handler ID: CAL000431223
Gen Status Universe: No Report
Contact Name: RON DALEY
Contact Address: 930 SHILOH RD BLDG 38 STE D , , WINDSOR , CA, 95492 ,
Contact Phone No and Ext: 707-837-7900
Contact Email: RON@WATERWORKSINDUSTRIES.COM
Contact Country:
County Name: SONOMA
EPA Region: 09
Land Type:
Receive Date: 20171005
Location Latitude: 38.523798
Location Longitude: -122.794745

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20171005
Handler Name: WATERWORKS INDUSTRIES INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Other
Name: WATERWORKS INDUSTRIES INC
Date Became Current:
Date Ended Current:
Phone: 707-837-7900
Source Type: Implementer
Street No:
Street 1: 930 SHILOH RD BLDG 38 STE D
Street 2:
City: WINDSOR
State: CA
Country:
Zip Code: 95492

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner/Operator Ind:	Current Operator	**Street No:**			
Type:	Other	**Street 1:**	930 SHILOH RD BLDG 38 STE D		
Name:	RON DALEY	**Street 2:**			
Date Became Current:		**City:**	WINDSOR		
Date Ended Current:		**State:**	CA		
Phone:	707-837-7900	**Country:**			
Source Type:	Implementer	**Zip Code:**	95492		

29	1 of 1	WNW	0.12 / 652.15	113.09 / -7	ADAMS ENTERPRISES/LOUIE'S IRON WORKS 590 CALETTI WINDSOR, CA 95492 CA	DELISTED COUNTY

Original Source Facility ID:
Original Source Name: Sonoma County CUPA Facilities List
Record Date: 11-JAN-2016

30	1 of 45	WNW	0.12 / 657.88	105.61 / -14	H AND H EXCAVATION 930 SHILOH RD STE 1A WINDSOR CA 95492	RCRA NON GEN

EPA Handler ID: CAR000162255
Gen Status Universe: No Report
Contact Name: LOREN M HUTNICK
Contact Address: 88 WOLFE DR , , SANTA ROSA , CA, 95403 , US
Contact Phone No and Ext: 707-837-0130
Contact Email:
Contact Country: US
County Name: SONOMA
EPA Region: 09
Land Type: Private
Receive Date: 20050504
Location Latitude: 38.523798
Location Longitude: -122.794745

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: Yes
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20050504
Handler Name: H AND H EXCAVATION

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Source Type: Notification
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	
Name:	H AND H EXCAVATION	**Street 2:**	
Date Became Current:	20000229	**City:**	
Date Ended Current:		**State:**	
Phone:		**Country:**	US
Source Type:	Notification	**Zip Code:**	

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	
Name:	H AND H EXCAVATION	**Street 2:**	
Date Became Current:	20000229	**City:**	
Date Ended Current:		**State:**	
Phone:		**Country:**	US
Source Type:	Notification	**Zip Code:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
30	2 of 45	WNW	0.12 / 657.88	105.61 / -14	CLEAR WATER ENVIRON 930 SHILOH RD WINDSOR CA 95492	RCRA NON GEN

EPA Handler ID: CAD982317638
Gen Status Universe: No Report
Contact Name: ENVIRONMENTAL MANAGER
Contact Address: 930 SHILOH RD , , WINDSOR , CA, 95492 , US
Contact Phone No and Ext: 707-579-0981
Contact Email:
Contact Country: US
County Name: SONOMA
EPA Region: 09
Land Type: Other
Receive Date: 19880226
Location Latitude: 38.523798
Location Longitude: -122.794745

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: Yes
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	19880226
Handler Name:	CLEAR WATER ENVIRON
Source Type:	Notification
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	NOT REQUIRED
Name:	NOT REQUIRED	***Street 2:***	
Date Became Current:		***City:***	NOT REQUIRED
Date Ended Current:		***State:***	ME
Phone:	415-555-1212	***Country:***	
Source Type:	Notification	***Zip Code:***	99999
Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	NOT REQUIRED
Name:	DENNIS MAGEE	***Street 2:***	
Date Became Current:		***City:***	NOT REQUIRED
Date Ended Current:		***State:***	ME
Phone:	415-555-1212	***Country:***	
Source Type:	Notification	***Zip Code:***	99999

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
30	3 of 45	WNW	0.12 / 657.88	105.61 / -14	LAKEWOOD ENTERPRISES 930 SHILOH RD WINDSOR CA 95492	RCRA SQG

EPA Handler ID:	CAD981385545
Gen Status Universe:	Small Quantity Generator
Contact Name:	
Contact Address:	US
Contact Phone No and Ext:	
Contact Email:	
Contact Country:	US
County Name:	SONOMA
EPA Region:	09
Land Type:	
Receive Date:	19960901
Location Latitude:	38.523798
Location Longitude:	-122.794745

Violation/Evaluation Summary

Note:	NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19860207
Handler Name: LAKEWOOD ENTERPRISES
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19960901
Handler Name: LAKEWOOD ENTERPRISES
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Implementer

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: SIDDHARTH SHAH
Date Became Current:
Date Ended Current:
Phone: 415-555-1212
Source Type: Notification
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED
State: ME
Country:
Zip Code: 99999

Owner/Operator Ind: Current Operator
Type: Private
Name: NOT REQUIRED
Date Became Current:
Date Ended Current:
Phone: 415-555-1212
Source Type: Implementer
Street No:
Street 1: NOT REQUIRED
Street 2:
City: NOT REQUIRED
State: ME
Country:
Zip Code: 99999

Historical Handler Details

Receive Dt: 19860207
Generator Code Description: Large Quantity Generator
Handler Name: LAKEWOOD ENTERPRISES

30	4 of 45	WNW	0.12 / 657.88	105.61 / -14	KADON TRUCKING INC 930 SHILOH RD NO 15 WINDSOR CA 95492	RCRA SQG

EPA Handler ID: CAR000046862
Gen Status Universe: Small Quantity Generator
Contact Name: DON CARPENTER
Contact Address: P O BOX 1619 , , WINDSOR , CA, 95492-1619 , US
Contact Phone No and Ext: 707-838-8008
Contact Email:
Contact Country: US
County Name: SONOMA
EPA Region: 09
Land Type: Private
Receive Date: 19981204
Location Latitude: 38.523798
Location Longitude: -122.794745

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19981204
Handler Name: KADON TRUCKING INC
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D000
Waste Code Description: DESCRIPTION

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D027
Waste Code Description: 1,4-DICHLOROBENZENE

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: KADON TRUCKING INC
Date Became Current:
Date Ended Current:
Phone: 707-838-8008
Source Type: Notification

Street No:
Street 1: P O BOX 1619
Street 2:
City: WINDSOR
State: CA
Country:
Zip Code: 95492-1619

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
30	5 of 45	WNW	0.12 / 657.88	105.61 / -14	THE FLUOR CORPORATION 930 SHILOH RD WINDSOR CA 95492	RCRA LQG

EPA Handler ID: CAR000035162
Gen Status Universe: Large Quantity Generator
Contact Name: JOE NEELY
Contact Address: 2235 , MERCURY WAY , , SANTA ROSA , CA, 95407 , US
Contact Phone No and Ext: 707-523-1010
Contact Email: JOE.NEELY@GHD.COM
Contact Country: US
County Name: SONOMA
EPA Region: 09
Land Type: Private
Receive Date: 20160104
Location Latitude: 38.525823
Location Longitude: -122.798129

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19980109
Handler Name: FLOUR CORP ECODYNE POND
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: F032
Waste Code Description: WASTEWATERS, PROCESS RESIDUALS, PRESERVATIVE DRIPPAGE, AND SPENT FORMULATIONS FROM WOOD PRESERVING PROCESSES GENERATED AT PLANTS THAT CURRENTLY USE, OR HAVE PREVIOUSLY USED, CHLOROPHENOLIC FORMULATIONS [EXCEPT POTENTIALLY CROSS-CONTAMINATED WASTES THAT HAVE HAD THE F032 WASTE CODE DELETED IN ACCORDANCE WITH SECTION 261.35 (I.E., THE NEWLY PROMULGATED EQUIPMENT CLEANING OR REPLACEMENT STANDARDS), AND WHERE THE GENERATOR DOES NOT RESUME OR INITIATE USE OF CHLOROPHENOLIC FORMULATIONS]. (THIS LISTING DOES NOT INCLUDE K001 BOTTOM SEDIMENT SLUDGE FROM THE TREATMENT OF WASTEWATER FROM WOOD PRESERVING PROCESSES THAT USE CREOSOTE AND/OR PENTACHLOROPHENOL.)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20160104
Handler Name: THE FLUOR CORPORATION
Federal Waste Generator Code: 1
Generator Code Description: Large Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: 611
Waste Code Description: Contaminated soil from site clean-ups

Hazardous Waste Code: D008
Waste Code Description: LEAD

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: STEVE MORRISON
Date Became Current:
Date Ended Current:
Phone: 707-575-9416
Source Type: Notification
Street No:
Street 1: 528 B ST
Street 2:
City: SANTA ROSA
State: CA
Country:
Zip Code: 95401

Owner/Operator Ind: Current Operator
Type: Private
Name: THE FLUOR CORPORATION
Date Became Current: 19520101
Date Ended Current:
Phone:
Source Type: Notification
Street No:
Street 1:
Street 2:
City:
State:
Country: US
Zip Code:

Owner/Operator Ind: Current Owner
Type: Private
Name: THE FLUOR CORPORATION
Date Became Current: 19520101
Date Ended Current:
Phone: 469-398-7660
Source Type: Notification
Street No: 6700
Street 1: LAS COLINAS BLVD
Street 2:
City: IRVING
State: TX
Country: US
Zip Code: 75039

Historical Handler Details

Receive Dt: 19980109
Generator Code Description: Small Quantity Generator
Handler Name: FLOUR CORP ECODYNE POND

30	6 of 45	WNW	0.12 / 657.88	105.61 / -14	MARTINS TRUCK REPAIR L L C 930 SHILOH RD BLDG 1 WINDSOR CA 95492	RCRA SQG

EPA Handler ID: CAR000085415
Gen Status Universe: Small Quantity Generator
Contact Name: GAYE MARTIN
Contact Address: 930 SHILOH RD BLDG 1 , , WINDSOR , CA, 95492 , US
Contact Phone No and Ext: 707-837-0176
Contact Email:
Contact Country: US
County Name: SONOMA
EPA Region: 09
Land Type: Private
Receive Date: 20001025

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Location Latitude: 38.523798
Location Longitude: -122.794745

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20001025
Handler Name: MARTINS TRUCK REPAIR L L C
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D000
Waste Code Description: DESCRIPTION

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D039
Waste Code Description: TETRACHLOROETHYLENE

Hazardous Waste Code: D040
Waste Code Description: TRICHLORETHYLENE

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: THE SHILOH GROUP
Date Became Current:
Date Ended Current:
Phone: 707-836-8203
Source Type: Notification

Street No:
Street 1: P O BOX 2678
Street 2:
City: SANTA ROSA
State: CA
Country:
Zip Code: 95408

30	7 of 45	WNW	0.12 / 657.88	105.61 / -14	LandCare 930 Shiloh Rd Bldg 2, Yard 39 Windsor, CA 95492	CUPA SONOMA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					CA	

Facility ID: 49-000-002774 **CERS ID:** 10501162

Details

Program Type: HMBP
Permit Status: Active
Expiration Date: 11/6/2018
Fee Schedule: Range 2

Details

Program Type: Hazardous Waste
Permit Status: Active
Expiration Date: 11/6/2018
Fee Schedule: SQG > 325 gallons/year to <5 tons/year w/source reduction/recycle

---

30	8 of 45	WNW	0.12 / 657.88	105.61 / -14	Kadon Trucking, Inc. 930 Shiloh Rd Bldg 15 Windsor, CA 95492 CA	CUPA SONOMA

Facility ID: 49-000-000965 **CERS ID:** 10101667

Details

Program Type: HMBP
Permit Status: Active
Expiration Date: 10/9/2018
Fee Schedule: Range 5

Details

Program Type: Hazardous Waste
Permit Status: Active
Expiration Date: 10/9/2018
Fee Schedule: Waste Oil Only > 5 tons/year

30	9 of 45	WNW	0.12 / 657.88	105.61 / -14	All Around Auto Repair 930 Shiloh Rd Windsor, CA 95492 CA	CUPA SONOMA

Facility ID: 49-000-007208 **CERS ID:** 10111180

Details

Program Type: HMBP
Permit Status: Active
Expiration Date: 4/11/2021
Fee Schedule: Range 2

Details

Program Type: Hazardous Waste
Permit Status: Active
Expiration Date: 4/11/2021
Fee Schedule: SQG > 325 gallons/year to <5 tons/year w/source reduction/recycle

---

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
30	10 of 45	WNW	0.12 / 657.88	105.61 / -14	North Bay Concrete, Inc. 930 Shiloh Rd Bldg 46 Windsor, CA 95492 CA	CUPA SONOMA

Facility ID: 49-000-008170 **CERS ID:** 10477591

Details

Program Type: Hazardous Waste
Permit Status: Active
Expiration Date: 4/28/2024
Fee Schedule: SQG < 325 gallons/year

Details

Program Type: HMBP
Permit Status: Active
Expiration Date: 4/28/2024
Fee Schedule: Range 2

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
30	11 of 45	WNW	0.12 / 657.88	105.61 / -14	ECODYNE 930 SHILOH ROAD WINDSOR CA 95492	CLEANUP SITES

Global ID: T0609700026 **Latitude:** 38.5218552747818
Status: OPEN - VERIFICATION MONITORING **Longitude:** -122.794414758682
Status Date: 6/13/2017 **County:** SONOMA
Site Facility Type: CLEANUP PROGRAM SITE
Data Source: Cleanup Program Sites from GeoTracker Search; Cleanup Sites from GeoTracker Cleanup Sites Data Download

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail

RB Case No: 1NSO037 **Stop Method:**
Local Case No: **CUF Case:** NO
Begin Date: 8/1/1987 **Case Worker:** KKH
File Location: Regional Board
Lead Agency: NORTH COAST RWQCB (REGION 1)
Local Agency: SONOMA COUNTY
Potential COC: Chromium
Potential Media of Concern: Aquifer used for drinking water supply
How Discovered: Other Means
How Discovered Description:
Stop Description:
CalWater Watershed Name: Russian River - Middle Russian River - Mark West (114.23)
DWR GW Subbasin Name: Santa Rosa Valley - Santa Rosa Plain (1-055.01)
Disadvantaged Community:
CalEnviroScreen Score: 46-50%
Site History:

Ecodyne operated a wood treatment facility from July 1965 to January 1984, at 930 Shiloh Road property. The discharger utilized chromic acid, sodium dichromate, and occasionally copper sulfate in the wood treatment process. The acid chromated copper was diluted with water and applied to lumber in a pressure vessel. The surplus chemical solution was pumped to an evaporation and settling pond, which was allowed to discharge to a ditch. The drainage ditch discharged to Pruitt Creek and eventually the Russian River. In 1989 the discharger started a groundwater extraction, treatment, and disposal system to remediate groundwater contaminated with hexavalent chromium. The remediation effort was implemented pursuant to Cleanup and Abatement Order No. 89-61 adopted April 14, 1989 and Waste Discharge Requirements Order No 92-39 adopted on May 3, 1993. This system operated from March 1992 to September 1994. In 1997 the discharger started direct injection of calcium polysulfide using a direct-push drilling rig. Injection of calcium polysulfide was conducted during three events from 1997 to 2002. These treatments were successfull in lowering concentrations of chromium in the intermediate and deep groundwater, however elevated concentrations persist in the shallow groundwater near the source area and did not appear to be capable of achieving remedial goals. In September and October 2004 highly impacted soil was treated by mixing calcium polysulfide with the soil using a hydraulic backhoe. In April 2007 additional injection of calcium polysulfide was performed in areas where hexavalent chromium was still persistent. Currently the site is in verification monitoring to assess the impacts of remediation.

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity

Action Type: ENFORCEMENT
Date: 2021-06-08 00:00:00
Action: Annual Estimation Letter

Action Type: ENFORCEMENT
Date: 2020-07-22 00:00:00
Action: Email Correspondence

Action Type: ENFORCEMENT
Date: 2020-07-14 00:00:00
Action: Email Correspondence

Action Type: ENFORCEMENT
Date: 2020-07-03 00:00:00
Action: Annual Estimation Letter

Action Type: ENFORCEMENT
Date: 2019-08-09 00:00:00
Action: Staff Letter

Action Type: RESPONSE
Date: 2019-08-01 00:00:00
Action: CAP/RAP - Final Remediation / Design Plan

Action Type: RESPONSE
Date: 2019-06-12 00:00:00
Action: Correspondence

Action Type: RESPONSE
Date: 2019-06-11 00:00:00
Action: Correspondence

Action Type: ENFORCEMENT
Date: 2019-05-28 00:00:00
Action: Annual Estimation Letter

Action Type: ENFORCEMENT
Date: 2019-05-13 00:00:00
Action: Email Correspondence

Action Type: ENFORCEMENT
Date: 2019-05-06 00:00:00
Action: Staff Letter

Action Type: RESPONSE
Date: 2019-02-28 00:00:00
Action: CAP/RAP - Other Report

Action Type: RESPONSE
Date: 2019-02-01 00:00:00
Action: Correspondence - Regulator Responded

Action Type: ENFORCEMENT
Date: 2019-01-31 00:00:00
Action: Email Correspondence

Action Type: ENFORCEMENT
Date: 2018-12-21 00:00:00
Action: Email Correspondence

Action Type: RESPONSE
Date: 2018-10-30 00:00:00
Action: Correspondence

Action Type: ENFORCEMENT
Date: 2018-10-25 00:00:00
Action: Staff Letter

Action Type: ENFORCEMENT
Date: 2018-10-16 00:00:00
Action: Email Correspondence

Action Type: RESPONSE
Date: 2018-10-09 00:00:00
Action: Email Correspondence - Regulator Responded

Action Type: ENFORCEMENT
Date: 2018-07-20 00:00:00
Action: Staff Letter

Action Type: RESPONSE
Date: 2018-06-28 00:00:00
Action: Correspondence

Action Type: ENFORCEMENT
Date: 2018-05-29 00:00:00
Action: Annual Estimation Letter

Action Type: RESPONSE
Date: 2018-05-17 00:00:00
Action: Correspondence

Action Type: ENFORCEMENT
Date: 2018-05-01 00:00:00
Action: Site Visit / Inspection / Sampling

Action Type: RESPONSE
Date: 2018-03-30 00:00:00
Action: Other Workplan

Action Type: ENFORCEMENT
Date: 2017-12-28 00:00:00
Action: Staff Letter

Action Type: ENFORCEMENT
Date: 2016-11-30 00:00:00
Action: Staff Letter

Action Type: RESPONSE
Date: 2016-11-10 00:00:00
Action: Email Correspondence

Action Type: ENFORCEMENT
Date: 2016-10-10 00:00:00
Action: Waste Discharge Requirements

Action Type: RESPONSE
Date: 2016-06-15 00:00:00
Action: Monitoring Report - Other

Action Type: RESPONSE
Date: 2016-05-02 00:00:00
Action: Correspondence

Action Type: ENFORCEMENT
Date: 2016-05-02 00:00:00
Action: 13267 Monitoring Program

Action Type: RESPONSE
Date: 2016-05-01 00:00:00
Action: Correspondence

Action Type: ENFORCEMENT
Date: 2016-01-15 00:00:00
Action: Staff Letter

Action Type: RESPONSE
Date: 2015-11-13 00:00:00
Action: Monitoring Report - Semi-Annually

Action Type: RESPONSE
Date: 2015-10-15 00:00:00
Action: Email Correspondence - Regulator Responded

Action Type: RESPONSE
Date: 2015-10-14 00:00:00
Action: Correspondence

Action Type: ENFORCEMENT
Date: 2015-09-29 00:00:00
Action: Staff Letter

Action Type: RESPONSE
Date: 2015-09-15 00:00:00
Action: CAP/RAP - Final Remediation / Design Plan - Regulator Responded

Action Type: ENFORCEMENT
Date: 2015-07-10 00:00:00
Action: Staff Letter

Action Type: RESPONSE
Date: 2015-06-19 00:00:00
Action: Correspondence - Regulator Responded

Action Type: ENFORCEMENT
Date: 2015-06-01 00:00:00
Action: Staff Letter

Action Type: RESPONSE
Date: 2015-05-15 00:00:00
Action: Monitoring Report - Semi-Annually - Regulator Responded

Action Type: RESPONSE
Date: 2014-11-14 00:00:00
Action: Monitoring Report - Semi-Annually

Action Type: RESPONSE
Date: 2014-07-31 00:00:00
Action: Correspondence

Action Type: ENFORCEMENT
Date: 2014-07-18 00:00:00
Action: Meeting

Action Type: RESPONSE
Date: 2014-05-05 00:00:00
Action: Monitoring Report - Semi-Annually

Action Type: RESPONSE
Date: 2013-10-16 00:00:00
Action: Correspondence

Action Type: RESPONSE
Date: 2013-10-15 00:00:00
Action: Monitoring Report - Semi-Annually

Action Type: ENFORCEMENT
Date: 2013-05-10 00:00:00
Action: Staff Letter

Action Type: RESPONSE
Date: 2013-04-15 00:00:00
Action: Monitoring Report - Semi-Annually - Regulator Responded

Action Type: RESPONSE

Date: 2012-10-15 00:00:00
Action: Monitoring Report - Semi-Annually

Action Type: ENFORCEMENT
Date: 2012-06-19 00:00:00
Action: Staff Letter

Action Type: RESPONSE
Date: 2012-04-15 00:00:00
Action: Monitoring Report - Semi-Annually

Action Type: ENFORCEMENT
Date: 2012-03-13 00:00:00
Action: Site Visit / Inspection / Sampling

Action Type: ENFORCEMENT
Date: 2012-02-29 00:00:00
Action: Staff Letter

Action Type: RESPONSE
Date: 2012-02-17 00:00:00
Action: Other Workplan - Regulator Responded

Action Type: ENFORCEMENT
Date: 2011-12-05 00:00:00
Action: Staff Letter

Action Type: RESPONSE
Date: 2011-10-15 00:00:00
Action: Monitoring Report - Semi-Annually - Regulator Responded

Action Type: RESPONSE
Date: 2011-04-15 00:00:00
Action: Correspondence - Regulator Responded

Action Type: ENFORCEMENT
Date: 2011-03-09 00:00:00
Action: Staff Letter

Action Type: ENFORCEMENT
Date: 2010-12-09 00:00:00
Action: Meeting

Action Type: ENFORCEMENT
Date: 2010-12-08 00:00:00
Action: Site Visit / Inspection / Sampling

Action Type: ENFORCEMENT
Date: 2010-12-07 00:00:00
Action: Staff Letter

Action Type: RESPONSE
Date: 2010-12-01 00:00:00
Action: Site Investigation Workplan - Regulator Responded

Action Type: RESPONSE
Date: 2010-12-01 00:00:00
Action: Conceptual Site Model - Regulator Responded

Action Type: RESPONSE
Date: 2010-11-24 00:00:00
Action: Correspondence - Regulator Responded

Action Type: RESPONSE
Date: 2010-10-15 00:00:00
Action: Monitoring Report - Semi-Annually

Action Type: ENFORCEMENT
Date: 2010-10-07 00:00:00

Action: Staff Letter

Action Type: ENFORCEMENT
Date: 2010-09-23 00:00:00
Action: Meeting

Action Type: ENFORCEMENT
Date: 2010-09-07 00:00:00
Action: Site Visit / Inspection / Sampling

Action Type: RESPONSE
Date: 2010-04-15 00:00:00
Action: Monitoring Report - Other

Action Type: ENFORCEMENT
Date: 2009-11-03 00:00:00
Action: Staff Letter

Action Type: RESPONSE
Date: 2009-10-30 00:00:00
Action: Soil and Water Investigation Workplan

Action Type: ENFORCEMENT
Date: 2009-06-15 00:00:00
Action: Staff Letter

Action Type: RESPONSE
Date: 2008-04-15 00:00:00
Action: Monitoring Report - Semi-Annually

Action Type: RESPONSE
Date: 2007-11-15 00:00:00
Action: Monitoring Report - Semi-Annually

Action Type: RESPONSE
Date: 2007-09-12 00:00:00
Action: Other Report / Document

Action Type: ENFORCEMENT
Date: 2007-04-19 00:00:00
Action: Site Visit / Inspection / Sampling

Action Type: RESPONSE
Date: 2007-04-15 00:00:00
Action: Monitoring Report - Other

Action Type: ENFORCEMENT
Date: 2007-02-07 00:00:00
Action: Waste Discharge Requirements

Action Type: ENFORCEMENT
Date: 2006-06-29 00:00:00
Action: File review

Action Type: ENFORCEMENT
Date: 2006-06-12 00:00:00
Action: Staff Letter

Action Type: RESPONSE
Date: 2006-04-15 00:00:00
Action: Monitoring Report - Other

Action Type: ENFORCEMENT
Date: 2005-11-30 00:00:00
Action: Staff Letter

Action Type: RESPONSE
Date: 2005-11-01 00:00:00
Action: Monitoring Report - Other

Action Type: RESPONSE
Date: 2005-11-01 00:00:00
Action: Other Report / Document

Action Type: RESPONSE
Date: 2005-11-01 00:00:00
Action: Other Workplan

Action Type: ENFORCEMENT
Date: 2005-08-08 00:00:00
Action: Staff Letter

Action Type: RESPONSE
Date: 2005-05-15 00:00:00
Action: Monitoring Report - Other

Action Type: RESPONSE
Date: 2005-01-20 00:00:00
Action: Other Report / Document

Action Type: ENFORCEMENT
Date: 2004-09-22 00:00:00
Action: * No Action

Action Type: ENFORCEMENT
Date: 2004-01-30 00:00:00
Action: * No Action

Action Type: RESPONSE
Date: 2004-01-30 00:00:00
Action: Other Workplan

Action Type: ENFORCEMENT
Date: 2004-01-29 00:00:00
Action: Staff Letter

Action Type: ENFORCEMENT
Date: 2003-12-31 00:00:00
Action: * No Action

Action Type: RESPONSE
Date: 2003-12-30 00:00:00
Action: Other Report / Document

Action Type: ENFORCEMENT
Date: 2002-07-01 00:00:00
Action: Staff Letter

Action Type: ENFORCEMENT
Date: 1989-04-14 00:00:00
Action: * No Action

Action Type: Other
Date: 1987-08-24 00:00:00
Action: Leak Discovery

Action Type: Other
Date: 1987-08-24 00:00:00
Action: Leak Stopped

Action Type: Other
Date: 1987-08-24 00:00:00
Action: Leak Reported

Action Type: Other
Date: 1987-08-01 00:00:00
Action: Leak Began

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History

Status: Open - Verification Monitoring
Status Date: 2017-06-13 00:00:00

Status: Open - Remediation
Status Date: 2000-05-31 00:00:00

Status: Open - Site Assessment
Status Date: 1992-03-31 00:00:00

Status: Open - Site Assessment
Status Date: 1987-10-04 00:00:00

Status: Open - Case Begin Date
Status Date: 1987-08-01 00:00:00

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts

Contact Type: Regional Board Caseworker
Contact Name: KENT HUTH
Phone No: 7075762669
Organization Name: NORTH COAST RWQCB (REGION 1)
Email: kent.huth@waterboards.ca.gov
Address: 5550 Skylane Blvd. Suite A
City: SANTA ROSA

Contact Type: Local Agency Caseworker
Contact Name: ENVIRON HEALTH STAFF (NON LOP-RB1)
Phone No:
Organization Name: SONOMA COUNTY
Email:
Address: 625 5th Street
City: SANTA ROSA

Cleanup Program Sites from GeoTracker Search - Regulatory Profile (as of May 29, 2021)

Project Status:
Cuf Claim No:
CUF Priority Assign:
CUF Amount Paid:
Composting Method:
File Location: REGIONAL BOARD
User Defined Beneficial Use:
Designated Beneficial Use: MUN, AGR, IND, PROC, FRSH, CUL, AQUA - Note: R1 BP- all gw same uses.
Designated Beneficl Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply, Freshwater Replenishment, Native American Culture, AQUA - Note: R1 BP- all gw same uses.
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T0609700026
Cleanup Status Detail: OPEN - VERIFICATION MONITORING AS OF 6/13/2017
Potential COC: CHROMIUM
Potential Media of Concern: AQUIFER USED FOR DRINKING WATER SUPPLY
Groundwater Monitoring Frequen:
DWR GW Sub Basin: Santa Rosa Valley - Santa Rosa Plain (1-055.01)
CalWater Watershed Name: Russian River - Middle Russian River - Mark West (114.23)
Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: NORTH COAST RWQCB (REGION 1) (LEAD) - CASE #: 1NSO037
CASEWORKER: KENT HUTH
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0609700026&tabname=regulatoryhistory
Site History:

Ecodyne operated a wood treatment facility from July 1965 to January 1984, at 930 Shiloh Road property. The discharger utilized chromic acid, sodium dichromate, and occasionally copper sulfate in the wood treatment process. The acid chromated copper was diluted with water and applied to lumber in a pressure vessel. The surplus chemical solution was pumped to an evaporation and settling pond, which was allowed to discharge to a ditch. The drainage ditch discharged to Pruitt Creek and eventually the Russian River. In 1989 the discharger started a groundwater extraction, treatment, and disposal system to remediate groundwater contaminated with hexavalent chromium. The remediation effort was implemented pursuant to Cleanup and Abatement Order No. 89-61 adopted April 14, 1989 and Waste Discharge Requirements Order No 92-39 adopted on May 3, 1993. This system operated from March 1992 to September 1994. In 1997 the discharger started direct injection of calcium polysulfide using a direct-push drilling rig. Injection of

calcium polysulfide was conducted during three events from 1997 to 2002. These treatments were successfull in lowering concentrations of chromium in the intermediate and deep groundwater, however elevated concentrations persist in the shallow groundwater near the source area and did not appear to be capable of achieving remedial goals. In September and October 2004 highly impacted soil was treated by mixing calcium polysulfide with the soil using a hydraulic backhoe. In April 2007 additional injection of calcium polysulfide was performed in areas where hexavalent chromium was still persistent. Currently the site is in verification monitoring to assess the impacts of remediation.

Sites from GeoTracker Search - Regulatory Activities (as of May 29, 2021)

Action Type: Enforcement - Other
Action Date:
Received Issue Date:
Action: Unknown
Doc Link:
Title Description Comments:

Action Type: Other Regulatory Actions
Action Date: 6/8/2021
Received Issue Date: 6/8/2021
Action: Annual Estimation Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6468496&temptable=ENFORCEMENT
Title Description Comments:

Annual Estimation Letter

Action Type: Other Regulatory Actions
Action Date: 7/22/2020
Received Issue Date: 7/22/2020
Action: Email Correspondence
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6443395&temptable=ENFORCEMENT
Title Description Comments:

Remediation postponed to 2021 due to decommissioning of pipeline.

Action Type: Other Regulatory Actions
Action Date: 7/14/2020
Received Issue Date: 7/14/2020
Action: Email Correspondence
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6443397&temptable=ENFORCEMENT
Title Description Comments:

Marmon contact update.

Action Type: Other Regulatory Actions
Action Date: 7/3/2020
Received Issue Date: 7/3/2020
Action: Annual Estimation Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6440291&temptable=ENFORCEMENT
Title Description Comments:

Annual Estimation Letter

Action Type: Other Regulatory Actions
Action Date: 8/9/2019
Received Issue Date: 8/9/2019
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6411766&temptable=ENFORCEMENT
Title Description Comments:

Final Remedial Action Plan - Concurrence

Action Type: Response Requested - Workplans
Action Date: 8/1/2019
Received Issue Date: 8/1/2019
Action: CAP/RAP - Final Remediation / Design Plan
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700026&doc_id=6001243
Title Description Comments:

2019 ECODYNE FINAL RAP (8/1/2019)

Action Type: Response Requested - Other
Action Date: *6/12/2019
Received Issue Date: 6/12/2019
Action: Correspondence
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700026&doc_id=5996045
Title Description Comments:

The Shiloh Group June 11, 2019 Letter

Action Type: Response Requested - Other
Action Date: 6/11/2019
Received Issue Date: 6/11/2019
Action: Correspondence
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700026&doc_id=5995779
Title Description Comments:

Ecodyne's June 4, 2019 Letter to TSG and Demand for Confirmation of Timely Compliance

Action Type: Other Regulatory Actions
Action Date: 5/28/2019
Received Issue Date: 5/28/2019
Action: Annual Estimation Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6403681&temptable=ENFORCEMENT
Title Description Comments:

ANNUAL ESTIMATION LETTER

Action Type: Other Regulatory Actions
Action Date: 5/13/2019
Received Issue Date: 5/13/2019
Action: Email Correspondence
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6402062&temptable=ENFORCEMENT
Title Description Comments:

Email about meeting

Action Type: Other Regulatory Actions
Action Date: 5/6/2019
Received Issue Date: 5/6/2019
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6402064&temptable=ENFORCEMENT
Title Description Comments:

Final Remedial Action Plan Comments

Action Type: Response Requested - Reports
Action Date: 2/28/2019
Received Issue Date: 2/28/2019
Action: CAP/RAP - Other Report
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700026&doc_id=5991318

Title Description Comments:

2019 ECODYNE FINAL RAP

Action Type: Response Requested - Other
Action Date: 2/1/2019
Received Issue Date: 1/31/2019
Action: Correspondence - Regulator Responded
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700026&doc_id=5983865
Title Description Comments:

Request for Extension

Action Type: Other Regulatory Actions
Action Date: 1/31/2019
Received Issue Date: 1/31/2019
Action: Email Correspondence
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6384243&temptable=ENFORCEMENT
Title Description Comments:

Extension Concurrence

Action Type: Other Regulatory Actions
Action Date: 12/21/2018
Received Issue Date: 12/21/2018
Action: Email Correspondence
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6379723&temptable=ENFORCEMENT
Title Description Comments:

Request for extension

Action Type: Response Requested - Other
Action Date: 10/30/2018
Received Issue Date: 10/30/2018
Action: Correspondence
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700026&doc_id=5978748
Title Description Comments:

Comments on the October 25, 2018 letter

Action Type: Other Regulatory Actions
Action Date: 10/25/2018
Received Issue Date: 10/25/2018
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6375197&temptable=ENFORCEMENT
Title Description Comments:

Work Plan to Prevent Migration of Impacted Site Soils in Storm Water

Action Type: Other Regulatory Actions
Action Date: 10/16/2018
Received Issue Date: 10/16/2018
Action: Email Correspondence
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6372489&temptable=ENFORCEMENT
Title Description Comments:

Extension concurrence for Work Plan to Prevent Migration of Impacted Site Soils in Storm Water

Action Type: Response Requested - Other
Action Date: 10/9/2018

Received Issue Date: 10/9/2018
Action: Email Correspondence - Regulator Responded
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700026&doc_id=5976568
Title Description Comments:

Additional request for extension and meeting by the Shiloh group

Action Type: Other Regulatory Actions
Action Date: 7/20/2018
Received Issue Date: 7/20/2018
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6364477&temptable=ENFORCEMENT
Title Description Comments:

Work Plan to Prevent Migration of Impacted Site Soils in Storm Water

Action Type: Response Requested - Other
Action Date: 6/28/2018
Received Issue Date: 6/28/2018
Action: Correspondence
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700026&doc_id=5968643
Title Description Comments:

California Sportfishing Protection Alliance email/letter

Action Type: Other Regulatory Actions
Action Date: 5/29/2018
Received Issue Date: 5/29/2018
Action: Annual Estimation Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6359464&temptable=ENFORCEMENT
Title Description Comments:

Cost Recovery Estimate

Action Type: Response Requested - Other
Action Date: 5/17/2018
Received Issue Date: 5/17/2018
Action: Correspondence
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700026&doc_id=5966292
Title Description Comments:

Letter from Property owner regarding ditch remediation workplan

Action Type: Other Regulatory Actions
Action Date: 5/1/2018
Received Issue Date: 5/1/2018
Action: Site Visit / Inspection / Sampling
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6364479&temptable=ENFORCEMENT
Title Description Comments:

Site Meeting/ Inspection

Action Type: Response Requested - Workplans
Action Date: 3/30/2018
Received Issue Date: 3/30/2018
Action: Other Workplan
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700026&doc_id=5961777
Title Description Comments:

Work Plan to Prevent Migration of Impacted Site Soils in Storm Water

Action Type: Other Regulatory Actions
Action Date: 12/28/2017
Received Issue Date: 12/28/2017
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6344700&temptable=ENFORCEMENT
Title Description Comments:

Request for a Final Remedial Action Plan Amendment

Action Type: Other Regulatory Actions
Action Date: 11/30/2016
Received Issue Date: 11/30/2016
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6311466&temptable=ENFORCEMENT
Title Description Comments:

Recision of Waste Discharge Requirements R1-2007-0006

Action Type: Response Requested - Other
Action Date: 11/10/2016
Received Issue Date: 11/10/2016
Action: Email Correspondence
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700026&doc_id=5905705
Title Description Comments:

Letter from Brian Carter, Carter Momsen PC, Representing The Shiloh Group, requesting postponement of rescission of Order R1-2007-0006

Action Type: Enforcement/Orders
Action Date: 10/10/2016
Received Issue Date: 10/10/2016
Action: Waste Discharge Requirements
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6304003&temptable=ENFORCEMENT
Title Description Comments:

WDR Order No. R1-2017-0003 Rescinding Waste Discharge Requirements and CeaseRescinding Waste Discharge Requirements

Action Type: Response Requested - Reports
Action Date: 6/15/2016
Received Issue Date: 6/15/2016
Action: Monitoring Report - Other
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700026&doc_id=5905745
Title Description Comments:

Monitoring and Sampling Report October 2015 through March 2016

Action Type: Enforcement/Orders
Action Date: 5/2/2016
Received Issue Date: 5/2/2016
Action: 13267 Monitoring Program
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6284004&temptable=ENFORCEMENT
Title Description Comments:

Monitoring and Reporting Program No. R1-2016-0025

Action Type: Response Requested - Other
Action Date: 5/2/2016
Received Issue Date: 5/3/2016
Action: Correspondence
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700026&doc_id=5888231
Title Description Comments:

Request to reduce monitoring requirements

Action Type: Response Requested - Other
Action Date: 5/1/2016
Received Issue Date: 5/2/2016
Action: Correspondence
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700026&doc_id=5888229
Title Description Comments:

Owners' Comments on Proposed Site Management Plan and Proposed Covenant for Ecodyne Tower Site

Action Type: Other Regulatory Actions
Action Date: 1/15/2016
Received Issue Date: 1/15/2016
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6278053&temptable=ENFORCEMENT
Title Description Comments:

Final Remedial Action Plan

Action Type: Response Requested - Reports
Action Date: 11/13/2015
Received Issue Date: 11/13/2015
Action: Monitoring Report - Semi-Annually
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700026&doc_id=5869651
Title Description Comments:

SEMIANNUAL MONITORING AND SAMPLING REPORT - NOVEMBER 2015

Action Type: Response Requested - Other
Action Date: 10/15/2015
Received Issue Date: 10/8/2018
Action: Email Correspondence - Regulator Responded
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700026&doc_id=5976567
Title Description Comments:

Request for a meeting and extension to November 30, 3018

Action Type: Response Requested - Other
Action Date: 10/14/2015
Received Issue Date: 10/14/2015
Action: Correspondence
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700026&doc_id=5869888
Title Description Comments:

2015101 Ecodyne Final RAP - Public Notice

Action Type: Other Regulatory Actions
Action Date: 9/29/2015
Received Issue Date: 9/29/2015
Action: Staff Letter
Doc Link:
Title Description Comments:

Annual Estimation Letter

Action Type: Response Requested - Workplans
Action Date: 9/15/2015
Received Issue Date: 9/15/2015
Action: CAP/RAP - Final Remediation / Design Plan - Regulator Responded
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700026&doc_id=5858299
Title Description Comments:

Ecodyne Final RAP

Action Type: Other Regulatory Actions
Action Date: 7/10/2015
Received Issue Date: 7/10/2015
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6252201&temptable=ENFORCEMENT
Title Description Comments:

Concurrence with Decommissioning Upgradient Wells

Action Type: Response Requested - Other
Action Date: 6/19/2015
Received Issue Date: 6/19/2015
Action: Correspondence - Regulator Responded
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700026&doc_id=5847728
Title Description Comments:

Request for Concurrence for Removal of Wells LF-01, LF-02, and LF-03 from the Monitoring and Sampling Program

Action Type: Other Regulatory Actions
Action Date: 6/1/2015
Received Issue Date: 6/1/2015
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6252199&temptable=ENFORCEMENT
Title Description Comments:

Comments on Semiannual Monitoring and Sampling Report

Action Type: Response Requested - Reports
Action Date: 5/15/2015
Received Issue Date: 5/15/2015
Action: Monitoring Report - Semi-Annually - Regulator Responded
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700026&doc_id=5841791
Title Description Comments:

Semiannual Monitoring and Sampling Report - May 2015

Action Type: Response Requested - Reports
Action Date: 11/14/2014
Received Issue Date: 11/14/2014
Action: Monitoring Report - Semi-Annually
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700026&doc_id=5822219
Title Description Comments:

Semiannual Monitoring and Sampling Report - November 2014

Action Type: Response Requested - Other
Action Date: 7/31/2014
Received Issue Date: 7/31/2014
Action: Correspondence
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700026&doc_id=5822434
Title Description Comments:

Summary of July 18, 2014 Meeting

Action Type: Other Regulatory Actions
Action Date: 7/18/2014
Received Issue Date: 7/18/2014
Action: Meeting
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6228188&temptable=ENFORCEMENT

Title Description Comments:

Meeting With RP and Consultants

Action Type: Response Requested - Reports
Action Date: 5/5/2014
Received Issue Date: 5/5/2014
Action: Monitoring Report - Semi-Annually
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700026&doc_id=5822223
Title Description Comments:

Semiannual Monitoring and Sampling Report - May 2014

Action Type: Response Requested - Other
Action Date: 10/16/2013
Received Issue Date: 10/16/2013
Action: Correspondence
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700026&doc_id=5785924
Title Description Comments:

Letter to Ray Avendt

Action Type: Response Requested - Reports
Action Date: 10/15/2013
Received Issue Date: 11/15/2013
Action: Monitoring Report - Semi-Annually
Doc Link:
Title Description Comments:

Semiannual Monitoring and Sampling Report

Action Type: Other Regulatory Actions
Action Date: 5/10/2013
Received Issue Date: 5/10/2013
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6160998&temptable=ENFORCEMENT
Title Description Comments:

Comments on Revisions to the Work Plan for In-Situ Treatment to Address Residual Concentrations of Hexavalent Chromium

Action Type: Response Requested - Reports
Action Date: 4/15/2013
Received Issue Date: 4/29/2013
Action: Monitoring Report - Semi-Annually - Regulator Responded
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700026&doc_id=5772092
Title Description Comments:

Semiannual Monitoring and Sampling Report

Action Type: Response Requested - Reports
Action Date: 10/15/2012
Received Issue Date: 11/14/2012
Action: Monitoring Report - Semi-Annually
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700026&doc_id=5772095
Title Description Comments:

Semiannual Monitoring and Sampling Report April through September 2012

Action Type: Other Regulatory Actions
Action Date: 6/19/2012
Received Issue Date: 6/19/2012
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?

global_id=T0609700026&enforcement_id=6129496&temptable=ENFORCEMENT

Title Description Comments:

Annual Cost Estimateion Letter

Action Type: Response Requested - Reports
Action Date: 4/15/2012
Received Issue Date: 5/15/2012
Action: Monitoring Report - Semi-Annually
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700026&doc_id=5741971
Title Description Comments:

Semiannual Monitoring and Sampling Report

Action Type: Other Regulatory Actions
Action Date: 3/13/2012
Received Issue Date: 3/13/2012
Action: Site Visit / Inspection / Sampling
Doc Link:
Title Description Comments:

Site Inspection Injection Project

Action Type: Other Regulatory Actions
Action Date: 2/29/2012
Received Issue Date: 2/29/2012
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?
global_id=T0609700026&enforcement_id=6114661&temptable=ENFORCEMENT
Title Description Comments:

Concurrence with Work Plan for In-Situ Treatment to Address Residual Concentrations of Hexavalent Chromium

Action Type: Response Requested - Workplans
Action Date: 2/17/2012
Received Issue Date: 2/17/2012
Action: Other Workplan - Regulator Responded
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700026&doc_id=5732402
Title Description Comments:

Work Plan for In-Situ Treatment to Address Residual Concentrations of Hexavalent Chromium

Action Type: Other Regulatory Actions
Action Date: 12/5/2011
Received Issue Date: 12/5/2011
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?
global_id=T0609700026&enforcement_id=6106502&temptable=ENFORCEMENT
Title Description Comments:

Comments on Proposed Updates to Site Remedial Action Plan

Action Type: Response Requested - Reports
Action Date: 10/15/2011
Received Issue Date: 11/17/2011
Action: Monitoring Report - Semi-Annually - Regulator Responded
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700026&doc_id=5727305
Title Description Comments:

Semiannual Monitoring and Sampling Report

Action Type: Response Requested - Other
Action Date: 4/15/2011
Received Issue Date: 4/15/2011

Action: Correspondence - Regulator Responded
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700026&doc_id=5713952
Title Description Comments:

Request for Extension: Submittal of May 2011 Semi-Annual Groundwater Montioring Report

Action Type: Other Regulatory Actions
Action Date: 3/9/2011
Received Issue Date: 3/9/2011
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6080846&temptable=ENFORCEMENT
Title Description Comments:

Comments on Updated Conceptual Site Model and Data Gap Evaluation Work Plan

Action Type: Other Regulatory Actions
Action Date: 12/9/2010
Received Issue Date: 12/9/2010
Action: Meeting
Doc Link:
Title Description Comments:

Meeting to Discuss Updated Site Conceptual Model

Action Type: Other Regulatory Actions
Action Date: 12/8/2010
Received Issue Date: 12/8/2010
Action: Site Visit / Inspection / Sampling
Doc Link:
Title Description Comments:

Stormwater Sampling

Action Type: Other Regulatory Actions
Action Date: 12/7/2010
Received Issue Date: 12/7/2010
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6072297&temptable=ENFORCEMENT
Title Description Comments:

Request for Extension

Action Type: Response Requested - Other
Action Date: 12/1/2010
Received Issue Date: 1/21/2011
Action: Conceptual Site Model - Regulator Responded
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700026&doc_id=5713957
Title Description Comments:

Updated Conceptual Site Model and Data Gap Evaluation Work Plan

Action Type: Response Requested - Workplans
Action Date: 12/1/2010
Received Issue Date: 1/21/2011
Action: Site Investigation Workplan - Regulator Responded
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700026&doc_id=5708677
Title Description Comments:

Updated Conceptual Site Model and Datra Gap Evaluation Work Plan

Action Type: Response Requested - Other
Action Date: 11/24/2010

Received Issue Date: 11/24/2010
Action: Correspondence - Regulator Responded
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700026&doc_id=5701295
Title Description Comments:

Request for Extension: Submittal of Updated Conceptual Site Model and Proposed Work Scope

Action Type: Response Requested - Reports
Action Date: 10/15/2010
Received Issue Date: 11/15/2010
Action: Monitoring Report - Semi-Annually
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=T0609700026&doc_id=5701301
Title Description Comments:

Semiannual Monitoring and Sampling Report April through September 2010

Action Type: Other Regulatory Actions
Action Date: 10/7/2010
Received Issue Date: 10/7/2010
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6066408&temptable=ENFORCEMENT
Title Description Comments:

Summary of Meeting and Request for Updated Site Conceptual Model

Action Type: Other Regulatory Actions
Action Date: 9/23/2010
Received Issue Date: 9/23/2010
Action: Meeting
Doc Link:
Title Description Comments:

Meeting with RP and Consultants to discuss final remediation

Action Type: Other Regulatory Actions
Action Date: 9/7/2010
Received Issue Date: 9/7/2010
Action: Site Visit / Inspection / Sampling
Doc Link:
Title Description Comments:

Observe low flow sampling

Action Type: Response Requested - Reports
Action Date: 4/15/2010
Received Issue Date: 5/19/2010
Action: Monitoring Report - Other
Doc Link:
Title Description Comments:

Semiannual Monitoring and Sampling Report

Action Type: Other Regulatory Actions
Action Date: 11/3/2009
Received Issue Date: 11/3/2009
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6035361&temptable=ENFORCEMENT
Title Description Comments:

Work Plan for Groundwater Investigation in the Vicinity of Well MW-12

Action Type: Response Requested - Workplans

Action Date: 10/30/2009
Received Issue Date: 10/30/2009
Action: Soil and Water Investigation Workplan
Doc Link:
Title Description Comments:

Work Plan for Groundwater Investigation in Vicinity of Well MW-12

Action Type: Other Regulatory Actions
Action Date: 6/15/2009
Received Issue Date: 6/15/2009
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6028750&temptable=ENFORCEMENT
Title Description Comments:

ANNUAL ESTIMATION LETTER

Action Type: Response Requested - Reports
Action Date: 4/15/2008
Received Issue Date: 5/19/2008
Action: Monitoring Report - Semi-Annually
Doc Link:
Title Description Comments:

Semiannual Monitoring and Sampling Report - Results from March 2008 sampling event and Storm Water Analyses

Action Type: Response Requested - Reports
Action Date: 11/15/2007
Received Issue Date: 11/15/2007
Action: Monitoring Report - Semi-Annually
Doc Link:
Title Description Comments:

Semi Annual 2007 Monitoring Report - Semi Annual 2007 Monitoring Report

Action Type: Response Requested - Other
Action Date: 9/12/2007
Received Issue Date: 9/12/2007
Action: Other Report / Document
Doc Link:
Title Description Comments:

Technical Report - Revised EPA Method for Hex Cr Analysis to SW7199 from SW7197 to get lower detection limit

Action Type: Other Regulatory Actions
Action Date: 4/19/2007
Received Issue Date: 4/19/2007
Action: Site Visit / Inspection / Sampling
Doc Link:
Title Description Comments:

Observation of In-situ injection of Calcium Polysulfate

Action Type: Response Requested - Reports
Action Date: 4/15/2007
Received Issue Date: 5/16/2007
Action: Monitoring Report - Other
Doc Link:
Title Description Comments:

Self Monitoring Report - Includes in-situ injection report for work conducted 4/07

Action Type: Enforcement/Orders

Action Date: 2/7/2007
Received Issue Date: 2/7/2007
Action: Waste Discharge Requirements
Doc Link:
Title Description Comments:

Waste Discharge Reguirements Order No. R1-2007-0006 for In-situ Treatment of Contaminated Soil

Action Type: Other Regulatory Actions
Action Date: 6/29/2006
Received Issue Date: 6/29/2006
Action: File review
Doc Link:
Title Description Comments:

Data review

Action Type: Other Regulatory Actions
Action Date: 6/12/2006
Received Issue Date: 6/12/2006
Action: Staff Letter
Doc Link:
Title Description Comments:

Concurrance with Additional Source Area Soil Treatment

Action Type: Response Requested - Reports
Action Date: 4/15/2006
Received Issue Date: 5/16/2006
Action: Monitoring Report - Other
Doc Link:
Title Description Comments:

Self Monitoring Report - March 2006 Semi Annual monitoing with request to conduct further soil treatment

Action Type: Other Regulatory Actions
Action Date: 11/30/2005
Received Issue Date: 11/30/2005
Action: Staff Letter
Doc Link:
Title Description Comments:

Action Type: Response Requested - Other
Action Date: 11/1/2005
Received Issue Date: 10/27/2005
Action: Other Report / Document
Doc Link:
Title Description Comments:

OTHER - Response to letter dated 8/8/05 giving time line for submission and storm water control reporting.

Action Type: Response Requested - Reports
Action Date: 11/1/2005
Received Issue Date: 11/9/2005
Action: Monitoring Report - Other
Doc Link:
Title Description Comments:

Self Monitoring Report - Semi Annual monitoring report Sept. 2005

Action Type: Response Requested - Workplans
Action Date: 11/1/2005
Received Issue Date: 11/17/2005

Action: Other Workplan
Doc Link:
Title Description Comments:

- Source Area Confirmation Sampling work plan

Action Type: Other Regulatory Actions
Action Date: 8/8/2005
Received Issue Date: 8/8/2005
Action: Staff Letter
Doc Link:
Title Description Comments:

Action Type: Response Requested - Reports
Action Date: 5/15/2005
Received Issue Date: 5/16/2005
Action: Monitoring Report - Other
Doc Link:
Title Description Comments:

Self Monitoring Report - Semi Annual MOnitioning And Samplin Report

Action Type: Response Requested - Other
Action Date: 1/20/2005
Received Issue Date: 1/20/2005
Action: Other Report / Document
Doc Link:
Title Description Comments:

- source Area Soil Treatment Report

Action Type: Enforcement - Other
Action Date: 9/22/2004
Received Issue Date: 9/22/2004
Action: * No Action
Doc Link:
Title Description Comments:

Action Type: Enforcement - Other
Action Date: 1/30/2004
Received Issue Date: 1/30/2004
Action: * No Action
Doc Link:
Title Description Comments:

Action Type: Response Requested - Workplans
Action Date: 1/30/2004
Received Issue Date: 1/7/2004
Action: Other Workplan
Doc Link:
Title Description Comments:

- Pre-Excavation Source Area Characterization workplan

Action Type: Other Regulatory Actions
Action Date: 1/29/2004
Received Issue Date: 1/29/2004
Action: Staff Letter
Doc Link:
Title Description Comments:

Action Type: Enforcement - Other

Action Date: 12/31/2003
Received Issue Date: 12/31/2003
Action: * No Action
Doc Link:
Title Description Comments:

Action Type: Response Requested - Other
Action Date: 12/30/2003
Received Issue Date: 12/12/2003
Action: Other Report / Document
Doc Link:
Title Description Comments:

OTHER - RP letter stating they will complie with additional data needs

Action Type: Other Regulatory Actions
Action Date: 7/1/2002
Received Issue Date: 7/1/2002
Action: Staff Letter
Doc Link:
Title Description Comments:

ANNUAL ESTIMATION LETTER FOR COST RECOVERY

Action Type: Enforcement - Other
Action Date: 4/14/1989
Received Issue Date: 4/14/1989
Action: * No Action
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action Date: 8/24/1987
Received Issue Date:
Action: Leak Discovery
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action Date: 8/24/1987
Received Issue Date:
Action: Leak Reported
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action Date: 8/24/1987
Received Issue Date:
Action: Leak Stopped
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action Date: 8/1/1987
Received Issue Date:
Action: Leak Began
Doc Link:
Title Description Comments:

Sites from GeoTracker Search - Documents (as of May 29, 2021)

Document Type: Site Documents **Submitted:**
Document Date: 6/8/2021 **Submitted By:** KENT HUTH (REGULATOR)
Size :
Title: ANNUAL ESTIMATION LETTER
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6468496
Type: ANNUAL ESTIMATION LETTER

Document Type: Site Documents **Submitted:**
Document Date: 7/22/2020 **Submitted By:** CODY WALKER (REGULATOR)
Size :
Title: REMEDIATION POSTPONED TO 2021 DUE TO DECOMMISSIONING OF PIPELINE.
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6443395
Type: EMAIL CORRESPONDENCE

Document Type: Site Documents **Submitted:**
Document Date: 7/14/2020 **Submitted By:** CODY WALKER (REGULATOR)
Size :
Title: MARMON CONTACT UPDATE.
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6443397
Type: EMAIL CORRESPONDENCE

Document Type: Site Documents **Submitted:**
Document Date: 7/3/2020 **Submitted By:** CODY WALKER (REGULATOR)
Size :
Title: ANNUAL ESTIMATION LETTER
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6440291
Type: ANNUAL ESTIMATION LETTER

Document Type: Monitoring Reports **Submitted:**
Document Date: 6/2/2020 **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 9,929 KB
Title: MONITORING AND SAMPLING REPORT JUNE 2018 THROUGH MAY 2020
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3143719613/T0609700026.PDF
Type: MONITORING REPORT - OTHER

Document Type: Site Documents **Submitted:**
Document Date: 8/9/2019 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: FINAL REMEDIAL ACTION PLAN - CONCURRENCE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6411766
Type: STAFF LETTER

Document Type: Site Documents **Submitted:**
Document Date: 8/1/2019 **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 14,200 KB
Title: 2019 ECODYNE FINAL RAP (8/1/2019)
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3240374088/T0609700026.PDF
Type: CAP/RAP - FINAL REMEDIATION / DESIGN PLAN

Document Type: Site Documents **Submitted:**
Document Date: 8/1/2019 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: 2019 ECODYNE FINAL RAP (8/1/2019)
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&document_id=6001243
Type: CAP/RAP - FINAL REMEDIATION / DESIGN PLAN

Document Type: Site Documents **Submitted:**
Document Date: 6/12/2019 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: THE SHILOH GROUP JUNE 11, 2019 LETTER
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&document_id=5996045
Type: CORRESPONDENCE

Document Type: Site Documents **Submitted:**
Document Date: 6/11/2019 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: ECODYNE'S JUNE 4, 2019 LETTER TO TSG AND DEMAND FOR CONFIRMATION OF TIMELY COMPLIANCE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&document_id=5995779
Type: CORRESPONDENCE

Document Type: Site Documents
Document Date: 5/28/2019
Size :
Title: ANNUAL ESTIMATION LETTER
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6403681
Type: ANNUAL ESTIMATION LETTER
Submitted:
Submitted By: BETH LAMB (REGULATOR)

Document Type: Site Documents
Document Date: 5/13/2019
Size :
Title: EMAIL ABOUT MEETING
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6402062
Type: EMAIL CORRESPONDENCE
Submitted:
Submitted By: BETH LAMB (REGULATOR)

Document Type: Site Documents
Document Date: 5/6/2019
Size :
Title: FINAL REMEDIAL ACTION PLAN COMMENTS
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6402064
Type: STAFF LETTER
Submitted:
Submitted By: BETH LAMB (REGULATOR)

Document Type: Site Documents
Document Date: 2/28/2019
Size : 4,567 KB
Title: 2019 ECODYNE FINAL RAP
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1720192968/T0609700026.PDF
Type: CAP/RAP - OTHER REPORT
Submitted:
Submitted By: CATHERINE HENDERSON (AUTH_RP)

Document Type: Site Documents
Document Date: 1/31/2019
Size :
Title: EXTENSION CONCURRENCE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6384243
Type: EMAIL CORRESPONDENCE
Submitted:
Submitted By: BETH LAMB (REGULATOR)

Document Type: Site Documents
Document Date: 1/31/2019
Size :
Title: REQUEST FOR EXTENSION
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&document_id=5983865
Type: CORRESPONDENCE
Submitted:
Submitted By: BETH LAMB (REGULATOR)

Document Type: Site Documents
Document Date: 12/21/2018
Size :
Title: REQUEST FOR EXTENSION
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6379723
Type: EMAIL CORRESPONDENCE
Submitted:
Submitted By: BETH LAMB (REGULATOR)

Document Type: Site Documents
Document Date: 10/30/2018
Size :
Title: COMMENTS ON THE OCTOBER 25, 2018 LETTER - REGULATOR RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&document_id=5978748
Type: CORRESPONDENCE
Submitted:
Submitted By: BETH LAMB (REGULATOR)

Document Type: Site Documents
Document Date: 10/25/2018
Size :
Title: WORK PLAN TO PREVENT MIGRATION OF IMPACTED SITE SOILS IN STORM WATER
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6375197
Type: STAFF LETTER
Submitted:
Submitted By: BETH LAMB (REGULATOR)

Document Type: Site Documents
Document Date: 10/16/2018
Size :
Title: EXTENSION CONCURRENCE FOR WORK PLAN TO PREVENT MIGRATION OF IMPACTED SITE SOILS IN STORM WATER
Submitted:
Submitted By: BETH LAMB (REGULATOR)

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6372489
Type: EMAIL CORRESPONDENCE

Document Type: Site Documents **Submitted:**
Document Date: 10/9/2018 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: ADDITIONAL REQUEST FOR EXTENSION AND MEETING BY THE SHILOH GROUP - REGULATOR RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&document_id=5976568
Type: EMAIL CORRESPONDENCE

Document Type: Site Documents **Submitted:**
Document Date: 10/8/2018 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: REQUEST FOR A MEETING AND EXTENSION TO NOVEMBER 30, 3018
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&document_id=5976567
Type: EMAIL CORRESPONDENCE

Document Type: Monitoring Reports **Submitted:**
Document Date: 8/24/2018* **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 9,167 KB
Title: MONITORING AND SAMPLING REPORT APRIL 2016 THROUGH MAY 2018
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8810742318/T0609700026.PDF
Type: MONITORING REPORT - OTHER

Document Type: Site Documents **Submitted:**
Document Date: 7/20/2018 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: WORK PLAN TO PREVENT MIGRATION OF IMPACTED SITE SOILS IN STORM WATER
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6364477
Type: STAFF LETTER

Document Type: Site Documents **Submitted:**
Document Date: 6/28/2018 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: CALIFORNIA SPORTFISHING PROTECTION ALLIANCE EMAIL/LETTER
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&document_id=5968643
Type: CORRESPONDENCE

Document Type: Site Documents **Submitted:**
Document Date: 5/29/2018 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: COST RECOVERY ESTIMATE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6359464
Type: ANNUAL ESTIMATION LETTER

Document Type: Site Documents **Submitted:**
Document Date: 5/17/2018 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: LETTER FROM PROPERTY OWNER REGARDING DITCH REMEDIATION WORKPLAN
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&document_id=5966292
Type: CORRESPONDENCE

Document Type: Site Documents **Submitted:**
Document Date: 5/1/2018 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: SITE MEETING/ INSPECTION
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6364479
Type: SITE VISIT / INSPECTION / SAMPLING

Document Type: Site Documents **Submitted:**
Document Date: 3/30/2018 **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 3,119 KB
Title: WORK PLAN TO PREVENT MIGRATION OF IMPACTED SITE SOILS IN STORM WATER
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1277147293/T0609700026.PDF
Type: OTHER WORKPLAN

Document Type: Site Documents **Submitted:**
Document Date: 12/28/2017 **Submitted By:** BETH LAMB (REGULATOR)

Size :
Title: REQUEST FOR A FINAL REMEDIAL ACTION PLAN AMENDMENT
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6344700
Type: STAFF LETTER

Document Type: Site Documents **Submitted:**
Document Date: 11/30/2016 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: RECISION OF WASTE DISCHARGE REQUIREMENTS R1-2007-0006
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6311466
Type: STAFF LETTER

Document Type: Site Documents **Submitted:**
Document Date: 11/10/2016 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: LETTER FROM BRIAN CARTER, CARTER MOMSEN PC, REPRESENTING THE SHILOH GROUP, REQUESTING POSTPONEMENT OF RESCISSION OF ORDER R1-2007-0006
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&document_id=5905705
Type: EMAIL CORRESPONDENCE

Document Type: Site Documents **Submitted:**
Document Date: 10/10/2016 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: WDR ORDER NO. R1-2017-0003 RESCINDING WASTE DISCHARGE REQUIREMENTS AND CEASERESCINDING WASTE DISCHARGE REQUIREMENTS
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6304003
Type: WASTE DISCHARGE REQUIREMENTS

Document Type: Monitoring Reports **Submitted:**
Document Date: 6/15/2016 **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 5,186 KB
Title: MONITORING AND SAMPLING REPORT OCTOBER 2015 THROUGH MARCH 2016
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5089232027/T0609700026.PDF
Type: MONITORING REPORT - OTHER

Document Type: Site Documents **Submitted:**
Document Date: 5/3/2016 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: REQUEST TO REDUCE MONITORING REQUIREMENTS - REGULATOR RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&document_id=5888231
Type: CORRESPONDENCE

Document Type: Site Documents **Submitted:**
Document Date: 5/2/2016 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: MONITORING AND REPORTING PROGRAM NO. R1-2016-0025
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6284004
Type: 13267 MONITORING PROGRAM

Document Type: Site Documents **Submitted:**
Document Date: 5/2/2016 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: OWNERS' COMMENTS ON PROPOSED SITE MANAGEMENT PLAN AND PROPOSED COVENANT FOR ECODYNE TOWER SITE - REGULATOR RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&document_id=5888229
Type: CORRESPONDENCE

Document Type: Site Documents **Submitted:**
Document Date: 1/15/2016 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: FINAL REMEDIAL ACTION PLAN
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6278053
Type: STAFF LETTER

Document Type: Monitoring Reports **Submitted:**
Document Date: 11/13/2015 **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 4,278 KB
Title: SEMIANNUAL MONITORING AND SAMPLING REPORT - NOVEMBER 2015
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8348075211/T0609700026.PDF

Type: MONITORING REPORT - SEMI-ANNUALLY

Document Type: Site Documents **Submitted:**
Document Date: 10/14/2015 **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 952 KB
Title: 2015101 ECODYNE FINAL RAP - PUBLIC NOTICE
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7863428473/T0609700026.PDF
Type: CORRESPONDENCE

Document Type: Site Documents **Submitted:**
Document Date: 9/15/2015 **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 1,839 KB
Title: 20150515 ECODYNE FINAL RAP
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5734087109/T0609700026.PDF
Type: CAP/RAP - FINAL REMEDIATION / DESIGN PLAN

Document Type: Site Documents **Submitted:**
Document Date: 9/15/2015 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: ECODYNE FINAL RAP - REGULATOR RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&document_id=5858299
Type: CAP/RAP - FINAL REMEDIATION / DESIGN PLAN

Document Type: Site Documents **Submitted:**
Document Date: 7/10/2015 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: CONCURRENCE WITH DECOMMISSIONING UPGRADIENT WELLS
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6252201
Type: STAFF LETTER

Document Type: Site Documents **Submitted:**
Document Date: 6/19/2015 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: REQUEST FOR CONCURRENCE FOR REMOVAL OF WELLS LF-01, LF-02, AND LF-03 FROM THE MONITORING AND SAMPLING PROGRAM - REGULATOR RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&document_id=5847728
Type: CORRESPONDENCE

Document Type: Site Documents **Submitted:**
Document Date: 6/19/2015 **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 403 KB
Title: REQUEST FOR CONCURRENCE FOR REMOVAL OF WELLS LF-01, LF-02, AND LF-03 FROM THE MONITORING AND SAMPLING PROGRAM
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6747581243/T0609700026.PDF
Type: CORRESPONDENCE

Document Type: Site Documents **Submitted:**
Document Date: 6/1/2015 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: COMMENTS ON SEMIANNUAL MONITORING AND SAMPLING REPORT
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6252199
Type: STAFF LETTER

Document Type: Monitoring Reports **Submitted:**
Document Date: 5/15/2015 **Submitted By:** BETH LAMB (REGULATOR)
Size : 241 KB
Title: SEMIANNUAL MONITORING AND SAMPLING REPORT - MAY 2015 - COMMENTS ON SEMIANNUAL MONITORING AND SAMPLING REPORT - REGULATOR RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/1131117105/150601%5FBML%5Fer%5FEcodyne17%2Epdf
Type: MONITORING REPORT - SEMI-ANNUALLY

Document Type: Monitoring Reports **Submitted:**
Document Date: 5/15/2015 **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 6,867 KB
Title: SEMIANNUAL MONITORING AND SAMPLING REPORT - MAY 2015
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7183458447/T0609700026.PDF
Type: MONITORING REPORT - SEMI-ANNUALLY

Document Type: Site Documents **Submitted:**
Document Date: 11/21/2014* **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 138 KB
Title: SUMMARY OF JULY 18, 2014 MEETING
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5994941055/T0609700026.PDF
Type: MEETING NOTES

Document Type: Monitoring Reports **Submitted:**
Document Date: 11/14/2014 **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 5,906 KB
Title: SEMIANNUAL MONITORING AND SAMPLING REPORT - NOVEMBER 2014
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1736854314/T0609700026.PDF
Type: MONITORING REPORT - SEMI-ANNUALLY

Document Type: Site Documents **Submitted:**
Document Date: 7/31/2014 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: SUMMARY OF JULY 18, 2014 MEETING
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&document_id=5822434
Type: CORRESPONDENCE

Document Type: Site Documents **Submitted:**
Document Date: 7/18/2014 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: MEETING WITH RP AND CONSULTANTS
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6228188
Type: MEETING

Document Type: Monitoring Reports **Submitted:**
Document Date: 5/5/2014 **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 6,507 KB
Title: SEMIANNUAL MONITORING AND SAMPLING REPORT - MAY 2014
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9952837109/T0609700026.PDF
Type: MONITORING REPORT - SEMI-ANNUALLY

Document Type: Monitoring Reports **Submitted:**
Document Date: 11/15/2013* **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 6,104 KB
Title: SEMIANNUAL MONITORING AND SAMPLING REPORT - NOVEMBER 2013
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9668260097/T0609700026.PDF
Type: MONITORING REPORT - SEMI-ANNUALLY

Document Type: Site Documents **Submitted:**
Document Date: 10/16/2013 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: LETTER TO RAY AVENDT - REGULATOR RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&document_id=5785924
Type: CORRESPONDENCE

Document Type: Site Documents **Submitted:**
Document Date: 5/10/2013 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: COMMENTS ON REVISIONS TO THE WORK PLAN FOR IN-SITU TREATMENT TO ADDRESS RESIDUAL CONCENTRATIONS OF HEXAVALENT CHROMIUM
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6160998
Type: STAFF LETTER

Document Type: Monitoring Reports **Submitted:**
Document Date: 4/29/2013 **Submitted By:** BETH LAMB (REGULATOR)
Size : 118 KB
Title: SEMIANNUAL MONITORING AND SAMPLING REPORT - COMMENTS ON REVISIONS TO THE WORK PLAN FOR IN-SITU TREATMENT TO ADDRESS RESIDUAL CONCENTRATIONS OF HEXAVALENT CHROMIUM - REGULATOR RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/3463514029/130510%5FBML%5Fdp%5FEcodyne16%2Epdf
Type: MONITORING REPORT - SEMI-ANNUALLY

Document Type: Monitoring Reports **Submitted:**
Document Date: 4/24/2013 **Submitted By:** CATHERINE HENDERSON (AUTH_RP)

Size : 10,676 KB
Title: SEMIANNUAL MONITORING AND SAMPLING REPORT - MAY 2013
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1571801364/T0609700026.PDF
Type: MONITORING REPORT - SEMI-ANNUALLY

Document Type: Monitoring Reports **Submitted:**
Document Date: 11/14/2012 **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 6,997 KB
Title: SEMIANNUAL MONITORING AND SAMPLING REPORT - NOVEMBER 2012
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4325057268/T0609700026.PDF
Type: MONITORING REPORT - SEMI-ANNUALLY

Document Type: Site Documents **Submitted:**
Document Date: 6/19/2012 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: ANNUAL COST ESTIMATEION LETTER
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6129496
Type: STAFF LETTER

Document Type: Monitoring Reports **Submitted:**
Document Date: 5/15/2012 **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 7,793 KB
Title: SEMIANNUAL MONITORING AND SAMPLING REPORT - MAY 2012
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2984649598/T0609700026.PDF
Type: MONITORING REPORT - SEMI-ANNUALLY

Document Type: Site Documents **Submitted:**
Document Date: 2/29/2012 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: CONCURRENCE WITH WORK PLAN FOR IN-SITU TREATMENT TO ADDRESS RESIDUAL CONCENTRATIONS OF HEXAVALENT CHROMIUM
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6114661
Type: STAFF LETTER

Document Type: Site Documents **Submitted:**
Document Date: 2/17/2012 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: WORK PLAN FOR IN-SITU TREATMENT TO ADDRESS RESIDUAL CONCENTRATIONS OF HEXAVALENT CHROMIUM - REGULATOR RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&document_id=5732402
Type: OTHER WORKPLAN

Document Type: Site Documents **Submitted:**
Document Date: 2/14/2012 **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 520 KB
Title: WORK PLAN FOR IN-SITU TREATMENT TO ADDRESS RESIDUAL CONCENTRATIONS OF HEXAVALENT CHROMIUM
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2016584038/T0609700026.PDF
Type: CAP/RAP - FINAL REMEDIATION / DESIGN PLAN

Document Type: Site Documents **Submitted:**
Document Date: 12/5/2011 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: COMMENTS ON PROPOSED UPDATES TO SITE REMEDIAL ACTION PLAN
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6106502
Type: STAFF LETTER

Document Type: Monitoring Reports **Submitted:**
Document Date: 11/17/2011 **Submitted By:** BETH LAMB (REGULATOR)
Size : 262 KB
Title: SEMIANNUAL MONITORING AND SAMPLING REPORT - COMMENTS ON PROPOSED UPDATES TO SITE REMEDIAL ACTION PLAN - REGULATOR RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/9789441764/111205%5FBML%5FEcodyne14%2Epdf
Type: MONITORING REPORT - SEMI-ANNUALLY

Document Type: Monitoring Reports **Submitted:**
Document Date: 11/17/2011 **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 8,662 KB

Title: SEMIANNUAL MONITORING AND SAMPLING REPORT - NOV 2011
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2720092058/T0609700026.PDF
Type: MONITORING REPORT - SEMI-ANNUALLY

Document Type: Monitoring Reports **Submitted:**
Document Date: 5/26/2011* **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 13,738 KB
Title: SEMIANNUAL MONITORING AND SAMPLING REPORT - MAY 2011
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5832905590/T0609700026.PDF
Type: MONITORING REPORT - SEMI-ANNUALLY

Document Type: Site Documents **Submitted:**
Document Date: 4/18/2011* **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 56 KB
Title: REQUEST FOR EXTENSION - SUBMITTAL OF MAY 2011 SEMI-ANNUAL GROUNDWATER MONITORING REPORT
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9922211647/T0609700026.PDF
Type: CORRESPONDENCE

Document Type: Site Documents **Submitted:**
Document Date: 4/15/2011 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: REQUEST FOR EXTENSION: SUBMITTAL OF MAY 2011 SEMI-ANNUAL GROUNDWATER MONTIORING REPORT - REGULATOR RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&document_id=5713952
Type: CORRESPONDENCE

Document Type: Site Documents **Submitted:**
Document Date: 4/4/2011* **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 1,169 KB
Title: ECODYNE - RESPONSE TO RWQCB FIELD OBSERVATIONS FROM DECEMBER 8, 2010
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4011498987/T0609700026.PDF
Type: OTHER REPORT / DOCUMENT

Document Type: Site Documents **Submitted:**
Document Date: 3/9/2011 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: COMMENTS ON UPDATED CONCEPTUAL SITE MODEL AND DATA GAP EVALUATION WORK PLAN
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6080846
Type: STAFF LETTER

Document Type: Site Documents **Submitted:**
Document Date: 1/21/2011 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: UPDATED CONCEPTUAL SITE MODEL AND DATA GAP EVALUATION WORK PLAN - REGULATOR RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&document_id=5713957
Type: CONCEPTUAL SITE MODEL

Document Type: Site Documents **Submitted:**
Document Date: 1/21/2011 **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 1,659 KB
Title: UPDATED CONCEPTUAL SITE MODEL AND DATA GAP EVALUATION WORK PLAN
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4002023279/T0609700026.PDF
Type: SITE CONCEPTUAL MODEL

Document Type: Site Documents **Submitted:**
Document Date: 1/21/2011 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: UPDATED CONCEPTUAL SITE MODEL AND DATRA GAP EVALUATION WORK PLAN - REGULATOR RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&document_id=5708677
Type: SITE INVESTIGATION WORKPLAN

Document Type: Monitoring Reports **Submitted:**
Document Date: 12/16/2010 **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 7,568 KB
Title: SEMIANNUAL MONITORING AND SAMPLING REPORT - NOV 2010
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4280457496/T0609700026.PDF

Type: MONITORING REPORT - SEMI-ANNUALLY

Document Type: Site Documents **Submitted:**
Document Date: 12/7/2010 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: REQUEST FOR EXTENSION
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6072297
Type: STAFF LETTER

Document Type: Site Documents **Submitted:**
Document Date: 11/24/2010 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: REQUEST FOR EXTENSION: SUBMITTAL OF UPDATED CONCEPTUAL SITE MODEL AND PROPOSED WORK SCOPE - REGULATOR RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&document_id=5701295
Type: CORRESPONDENCE

Document Type: Site Documents **Submitted:**
Document Date: 10/7/2010 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: SUMMARY OF MEETING AND REQUEST FOR UPDATED SITE CONCEPTUAL MODEL
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6066408
Type: STAFF LETTER

Document Type: Monitoring Reports **Submitted:**
Document Date: 5/18/2010 **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 11,218 KB
Title: SEMIANNUAL MONITORING AND SAMPLING REPORT - MAY 2010
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5878739714/T0609700026.PDF
Type: MONITORING REPORT - SEMI-ANNUALLY

Document Type: Monitoring Reports **Submitted:**
Document Date: 11/10/2009 **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 6,276 KB
Title: SEMIANNUAL MONITORING AND SAMPLING REPORT - NOVEMBER 2009
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/7649206876/T0609700026.PDF
Type: MONITORING REPORT - SEMI-ANNUALLY

Document Type: Site Documents **Submitted:**
Document Date: 11/3/2009 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: WORK PLAN FOR GROUNDWATER INVESTIGATION IN THE VICINITY OF WELL MW-12
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6035361
Type: STAFF LETTER

Document Type: Site Documents **Submitted:**
Document Date: 8/18/2009 **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 164 KB
Title: WORK PLAN FOR GROUNDWATER INVESTIGATION IN VICINITY OF WELL M-12
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4513460457/T0609700026.PDF
Type: SOIL AND WATER INVESTIGATION WORKPLAN

Document Type: Site Documents **Submitted:**
Document Date: 6/15/2009 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: ANNUAL ESTIMATION LETTER
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=T0609700026&enforcement_id=6028750
Type: STAFF LETTER

Document Type: Monitoring Reports **Submitted:**
Document Date: 5/15/2009 **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 6,645 KB
Title: SEMIANNUAL MONITORING AND SAMPLING REPORT - MAY 2009
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/2656396031/T0609700026.PDF
Type: MONITORING REPORT - SEMI-ANNUALLY

Document Type: Monitoring Reports **Submitted:**
Document Date: 11/15/2008* **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 3,995 KB

Title: SEMIANNUAL MONITORING AND SAMPLING REPORT - NOV 2008
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3847626209/T0609700026.PDF
Type: MONITORING REPORT - SEMI-ANNUALLY

Document Type: Monitoring Reports ***Submitted:***
Document Date: 7/14/2008* ***Submitted By:*** CATHERINE HENDERSON (AUTH_RP)
Size : 3,726 KB
Title: SEMIANNUAL MONITORING AND SAMPLING REPORT - MAY 2007
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9569031238/T0609700026.PDF
Type: MONITORING REPORT - SEMI-ANNUALLY

Document Type: Monitoring Reports ***Submitted:***
Document Date: 7/14/2008* ***Submitted By:*** CATHERINE HENDERSON (AUTH_RP)
Size : 4,027 KB
Title: SEMIANNUAL MONITORING AND SAMPLING REPORT - MAY 2006
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8940184652/T0609700026.PDF
Type: MONITORING REPORT - SEMI-ANNUALLY

Document Type: Monitoring Reports ***Submitted:***
Document Date: 7/14/2008* ***Submitted By:*** CATHERINE HENDERSON (AUTH_RP)
Size : 2,680 KB
Title: SEMIANNUAL MONITORING AND SAMPLING REPORT - MAY 2008
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1258544027/T0609700026.PDF
Type: MONITORING REPORT - SEMI-ANNUALLY

Document Type: Monitoring Reports ***Submitted:***
Document Date: 7/14/2008* ***Submitted By:*** CATHERINE HENDERSON (AUTH_RP)
Size : 2,711 KB
Title: SEMIANNUAL MONITORING AND SAMPLING REPORT - NOV 2007
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8747759759/T0609700026.PDF
Type: MONITORING REPORT - SEMI-ANNUALLY

Document Type: Monitoring Reports ***Submitted:***
Document Date: 7/14/2008* ***Submitted By:*** CATHERINE HENDERSON (AUTH_RP)
Size : 3,096 KB
Title: SEMIANNUAL MONITORING AND SAMPLING REPORT - NOV 2006
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/6634442985/T0609700026.PDF
Type: MONITORING REPORT - SEMI-ANNUALLY

Document Type: Site Documents ***Submitted:***
Document Date: 6/13/2008 ***Submitted By:*** (REGULATOR)
Size : 35 KB
Title: 2008 ANNUAL ESTIMATION LETTER
Title Link: https://geotracker.waterboards.ca.gov/site_documents/5115681290/06042008%5FBML%5FEcodyne%5F2010007%5FARC%2Epdf
Type: LETTER

Document Type: Site Documents ***Submitted:***
Document Date: 12/17/2007 ***Submitted By:*** (REGULATOR)
Size : 23 KB
Title: 2007 ANNUAL ESTIMATION LETTER
Title Link: https://geotracker.waterboards.ca.gov/site_documents/2090458512/061807%202010007%2Epdf
Type: LETTER

Sites from GeoTracker Search - Site Maps (as of May 29, 2021)

Title: GEO_MAP ***Submitted By:*** CATHERINE HENDERSON (AUTH_RP)
Size : 116 KB ***Submitted:*** 5/26/2011*
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/4676319897/T0609700026.PDF

Title: WELL M-22 LOG AND WELL DESIGN (M-22) ***Submitted By:*** CATHERINE HENDERSON (AUTH_RP)
Size : 242 KB ***Submitted:*** 5/26/2011*
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/7855615198/T0609700026.PDF

Title: WELL M-21 LOG AND WELL DESIGN (M-21) ***Submitted By:*** CATHERINE HENDERSON (AUTH_RP)
Size : 239 KB ***Submitted:*** 5/26/2011*
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/3277589201/T0609700026.PDF

Title: LF-02 BORING LOG (LF-02) **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 47 KB **Submitted:** 11/4/2008*
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/8619537830/T0609700026.PDF

Title: M-08 BORING LOG (M-08) **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 36 KB **Submitted:** 11/4/2008*
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/7915572226/T0609700026.PDF

Title: IW-05 BORING LOG (IW-05) **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 117 KB **Submitted:** 11/4/2008*
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/9875275135/T0609700026.PDF

Title: M-05 BORING LOG (M-05) **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 34 KB **Submitted:** 11/4/2008*
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/1853825449/T0609700026.PDF

Title: M-04 BORING LOG (M-04) **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 31 KB **Submitted:** 11/4/2008*
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/1890099644/T0609700026.PDF

Title: DW-01 BORING LOG (DW-01) **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 86 KB **Submitted:** 11/4/2008*
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/9863173544/T0609700026.PDF

Title: IW-08 BORING LOG (IW-08) **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 92 KB **Submitted:** 11/4/2008*
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/6241503655/T0609700026.PDF

Title: IW-02 BORING LOG (IW-02) **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 80 KB **Submitted:** 11/4/2008*
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/7180328845/T0609700026.PDF

Title: LF-03 BORING LOG (LF-03) **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 44 KB **Submitted:** 11/4/2008*
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/5295332968/T0609700026.PDF

Title: M-12 BORING LOG (M-12) **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 42 KB **Submitted:** 11/4/2008*
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/6925034046/T0609700026.PDF

Title: LF-01 BORING LOG (LF-01) **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 45 KB **Submitted:** 11/4/2008*
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/5823088705/T0609700026.PDF

Title: DW-02 BORING LOG (DW-02) **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 79 KB **Submitted:** 11/4/2008*
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/7937286853/T0609700026.PDF

Title: IW-01 BORING LOG (IW-01) **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 83 KB **Submitted:** 11/4/2008*
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_bore/3441681385/T0609700026.PDF

Title: GEO_MAP **Submitted By:** CATHERINE HENDERSON (AUTH_RP)
Size : 73 KB **Submitted:** 9/6/2007
Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_map/1846409678/T0609700026.pdf

Sites from GeoTracker Search - Cleanup Status History (as of May 29, 2021)

Status: Open - Verification Monitoring
Date: 6/13/2017

Status: Open - Remediation
Date: 5/31/2000

Status: Open - Site Assessment
Date: 3/31/1992

Status: Open - Site Assessment

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Date: 10/4/1987

Status: Open - Case Begin Date
Date: 8/1/1987

---

30 | 12 of 45 | WNW | 0.12 / 657.88 | 105.61 / -14 | LAKEWOOD ENTERPRISES
930 SHILOH ROAD
WINSOR CA 94503 | ENVIROSTOR

Estor/EPA ID: 71002776
Site Code:
Nat Priority List: NO
APN: NONE SPECIFIED
Census Tract: 6097152702
Site Type: TIERED PERMIT
Address Description: 930 SHILOH ROAD
Office: CLEANUP BERKELEY
Special Program:
Funding:
Assembly District: 02
Senate District: 02
Permit Renewal Lead:
Public Partici Spclst:
Project Manager:
County: SONOMA
Latitude: 38.5255736
Longitude: -122.7967805
Acres: NONE SPECIFIED
Supervisor:
Cleanup Status: INACTIVE - NEEDS EVALUATION AS OF
Cleanup Oversight Agencies: NONE SPECIFIED
School District:
Past Use that Caused Contam: NONE SPECIFIED
Potential Media Affected: NONE SPECIFIED
Potential Contamin of Concern:

NONE SPECIFIED

Site History:

Status: INACTIVE - NEEDS EVALUATION
Program Type: TIERED PERMIT
CalEnviroScreen Score: 46-50%
Summary Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=71002776

---

30 | 13 of 45 | WNW | 0.12 / 657.88 | 105.61 / -14 | EMPIRE TOWING
930 SHILOH ROAD WINDSOR, CA 95492
CA | DELISTED COUNTY

Original Source Facility ID:
Original Source Name: Sonoma County CUPA Facilities List
Record Date: 11-JAN-2016

---

30 | 14 of 45 | WNW | 0.12 / 657.88 | 105.61 / -14 | BACE ANALYTICAL DIVISION OF BRUNSING & ASSOCIATES
930 SHILOH ROAD WINDSOR, CA 95492
CA | DELISTED COUNTY

Original Source Facility ID:
Original Source Name: Sonoma County CUPA Facilities List
Record Date: 11-JAN-2016

---

30 | 15 of 45 | WNW | 0.12 / 657.88 | 105.61 / -14 | AUTO GRAPHIX
930 SHILOH RD WINDSOR, CA 95492
CA | DELISTED COUNTY

Original Source Facility ID:
Original Source Name: Sonoma County CUPA Facilities List
Record Date: 11-JAN-2016

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
30	16 of 45	WNW	0.12 / 657.88	105.61 / -14	Star Pools 930 Shiloh Road WINDSOR, CA 95492 CA	DELISTED COUNTY

Original Source Facility ID:
Original Source Name: Sonoma County CUPA Facilities List
Record Date: 11-JAN-2016

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
30	17 of 45	WNW	0.12 / 657.88	105.61 / -14	THE SHILOH GROUP PROPERTY 930 SHILOH ROAD WINDSOR CA 95492	VCP

Estor/EPA ID: 60002191
Site Code: 202038, 202132
Nat Priority List: NO
Acres: 30.84 ACRES
Special Program:
Funding: SITE PROPONENT
Assembly District: , 02
Senate District: , 02
School District:
Permit Renewal Lead:
Project Manager: TOM LANPHAR
Supervisor: KIMBERLY WALSH
Public Partici Spclst:
Census Tract: 6097152702
County: SONOMA
Latitude: 38.5250149864007
Longitude: -122.795463203252
APN: NONE SPECIFIED
Cleanup Status: ACTIVE AS OF 5/12/2015
Cleanup Oversight Agencies: DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY
Site Type: VOLUNTARY CLEANUP
Office: CLEANUP BERKELEY
Past Use that Caused Contam: MANUFACTURING - LUMBER/WOOD PRODUCTS
Potential Media Affected: SOIL
Potential Contamin of Concern:

DIOXIN (AS 2,3,7,8-TCDD TEQ)
LEAD
POLYNUCLEAR AROMATIC HYDROCARBONS (PAHS)

Site History:

DTSC entered into a Voluntary Cleanup Agreement (VCA) with Flour Corporation for the completion of a Preliminary Endangerment Assessment for the property owned by The Shiloh Group (TSG) LLC. The site is approximately 31 acres and was once part of the Ecodyne/Flour water tank/cooling tower production facility. The VCA does not include any cleanup actions.

Status: ACTIVE
Program Type: VOLUNTARY CLEANUP
CalEnviroScreen Score: 46-50%
Summary Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=60002191

Future Activities

Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction
Due Date: 2022

Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Removal Action Workplan
Due Date: 2022

Completed Activities

Title: Annual HARP Update
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60488677
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 9/22/2021
Comments: Annual HARP 2021 - 2022

Title: Post PEA Report Correspondence
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&enforcement_id=60420857
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 12/7/2016
Comments: These are letters from Fluor, who entered into a VCA with DTSC to complete PEA and letters from attorney and consultant representing the land owner.

Title: July 2021 Monthly Status Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60489528
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 9/8/2021
Comments: monthly Status Report as required by DTSC Order

Title: March 2021 Monthly Status Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60489524
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 4/15/2021
Comments: monthly status, indoor air sampling discussed with DTSC

Title: Monthly Status Reports - December 2019
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60459572
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 6/1/2020
Comments:

Title: Monthly Status Reports - February 2020
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60459574
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 3/13/2020
Comments: Monthly update as required by DTSC Order

Title: Monthly Status Reports - September 2019
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60459569
Area Name:
Area Link:
Sub Area:
Sub Area Link:

Document Type: Other Report
Date Completed: 10/16/2019
Comments:

Title: June 2021 Monthly Status Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60489527
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 9/8/2021
Comments: June 2021 Monthly Status Report as required by DTSC Order

Title: April 2021 Monthly Status Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60489525
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 5/14/2021
Comments: monthly status report

Title: September 2020 Monthly Status Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60489518
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 11/5/2020
Comments:

Title: 2020-2021 Annual Cost Estimate for DTSC oversight
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&enforcement_id=60488605
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 10/14/2020
Comments: Estimate of DTSC oversight cost for fiscal year 2020-2012

Title: Implementation of Remedial Investigation Work Plan
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60468057
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Fieldwork
Date Completed: 12/1/2019
Comments: completed work plan and now working on phase II sampling plan

Title: Supplemental Site Investigation for OU-A (soil vapor) and OU-B (soil)
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60487214
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Supplemental Site Investigation Workplan
Date Completed: 7/21/2020
Comments: work plan to investigate data gaps in OUs A and B

Title: Monthly Status Reports - August 2019
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60459568
Area Name:
Area Link:
Sub Area:

Sub Area Link:
Document Type: Other Report
Date Completed: 9/13/2019
Comments: monthly status report required by DTSC Order.

Title: Supplemental Investigation Work Plan (follow up to RI Investigation)
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60475241
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Remedial Investigation Workplan
Date Completed: 2/19/2020
Comments: work plan addresses data gaps in soil vapor and PCB in soil

Title: Unilateral Order
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&enforcement_id=60427430
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Unilateral Order (I/SE, RAO, CAO, EPA AO)
Date Completed: 11/6/2018
Comments:

Title: Monthly Status Report - June 2020
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60468076
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 7/10/2020
Comments: regular monthly status report

Title: January 2021 Monthly Status Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60489522
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 2/15/2021
Comments: January 2021 Status Report

Title: Monthly Status Report - April 2020
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60468074
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 5/19/2020
Comments: Monthly Report as required by DTSC order

Title: November 2020 Monthly Status Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60489520
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 12/15/2020
Comments: Monthly report as required by DTSC Order

Title: PEA Workplan Addendum
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60400143
Area Name:
Area Link:

Sub Area:
Sub Area Link:
Document Type: Preliminary Endangerment Assessment Workplan
Date Completed: 10/28/2015
Comments: PEA workplan addresses soil and groundwater.

Title: Monthly Status Report - May 2020
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60468075
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 6/12/2020
Comments: regular monthly status report

Title: August 2020 Monthly Status Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60489517
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 9/15/2020
Comments: monthly status report

Title: Monthly Status Reports - March 2019
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60459563
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 4/2/2019
Comments: regular monthly status report for The Shiloh Group Property

Title: October 2019 Monthly Status Reports
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60459570
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 11/15/2019
Comments: Status report required by DTSC order.

Title: Monthly Status Reports - January 2020
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60459573
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 2/14/2020
Comments: Regular update as required by DTSC Order

Title: REMEDIAL INVESTIGATION WORKPLAN
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60431395
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Remedial Investigation Workplan
Date Completed: 6/12/2019
Comments: Work Plan approved with condition that two additiona groundwater monitoring wells be added. TSG submitted revised Workplan with additional monitoring wells.

Title: Monthly Status Reports - May 2019
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60459565

Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 8/30/2019
Comments:

Title: December 2020 Monthly Status Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60489521
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 1/29/2021
Comments: December 2020 status report as required by Order

Title: Monthly Status Reports - March 2020
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60459575
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 4/13/2020
Comments: Monthly report as required by DTSC Order

Title: Monthly Status Reports - November 2019
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60459571
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 12/16/2019
Comments: Monthly Report for Nov. 2019.

Title: Operable Unit - A Additional Groundwater Investigation Workplan
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60497638
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Remedial Investigation Workplan
Date Completed: 6/10/2021
Comments: work plan includes and additional monitoring well and sampling current well network, added mercury to cocs

Title: Preliminary Endangerment Assessment Report for The Shiloh Group Property
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60397365
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Preliminary Endangerment Assessment Report
Date Completed: 9/27/2016
Comments: PEA Report is approved with conditions and DTSC conclusion for further investigation.

Title: Voluntary Cleanup Agreement
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&enforcement_id=60394022
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Standard Voluntary Agreement
Date Completed: 7/15/2015
Comments: The Voluntary Cleanup Agreement scope includes the completion of a Preliminary Endangerment Assessment for The Shiloh Group Property.

Title: Monthly Status Reports - June 2019
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60459566
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 7/15/2019
Comments: Monthly status report required by DTSC Order.

Title: October 2020 Monthly Status Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60489519
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 11/12/2020
Comments: submittal of Monthly Status Report per IS&E Order

Title: May 2021 Monthly Status Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60489526
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 6/14/2021
Comments: monthly status report as required by DTSC order

Title: Monthly Status Report - July 2020
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60468077
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 8/14/2020
Comments: regular monthly status report

Title: Monthly Status Reports - July 2019
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60459567
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 8/15/2019
Comments: Field preparation activities in anticipation of Remedial Investigation implementation planned for Sept. 2019.

Title: Workplan for Indoor Air Evaluation
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60488114
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Supplemental Site Investigation Workplan
Date Completed: 2/23/2021
Comments: revised Air Monitoring Work plan addressed DTSC comments and is approved.

Title: February 2021 Monthly Status Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60489523
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 3/15/2021
Comments: February 2021 status report required by Order

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Title: Monthly Status Reports - April 2019
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60459564
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 5/17/2019
Comments:

Title: Phase II Site Investigation Work Plan
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60394027
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Preliminary Endangerment Assessment Workplan
Date Completed: 9/10/2015
Comments: The PEA Work Plan proposes an initial phase of shallow soil sampling in order to inform a Preliminary Endangerment Assessment report. DTSC understands than an amendment to the PEA Work Plan will be submitted to DTSC no later than September 25, 2015, to propose additional soil samples, grab groundwater samples, and monitoring well samples.

Title: OUs B, C and D Remedial Investigation Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60488111
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Remedial Investigation Report
Date Completed: 6/25/2021
Comments: NFA for OU-D, polychlorinated biphenyls (PCBs) Aroclor-1254 and Aroclor-1260 in OU-B need remediation and pentachlorophenol (PCP) in OU-C needs remediation. Removal Action Workplan is the next step in cleanup process.

Title: Annual Cost Estimate for DTSC oversight 2021-2022
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&enforcement_id=60507661
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 9/10/2021
Comments: annual estimate of DTSC oversight costs

Title: Cost estimate for work planned during 2019-2020 fiscal year.
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&enforcement_id=60470237
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 10/14/2019
Comments: cost estimate for 19/20

30	18 of 45	WNW	0.12 / 657.88	105.61 / -14	**Marmon Group Ecodyne/Shiloh Industrial Park** **930 Shiloh Road** **Windsor CA 95492**	CDO/CAO

Facility ID: 222151
Facility Type: Industrial
Status: Historical
Status Date: 12/04/15 00:00:00
Place Type: Manufacturing
Place Sub Type: Manufacturing NEC
Agency Type: Privately-Owned Business

Design Flow: 0.0034
Complexity: A
Pretreatment: X - Facility is not a POTW
Fee Code:
SIC Code 1: 2879
SIC Desc 1: Pesticides and Agricultural Chemicals, NEC
SIC Code 2: 4952

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

No of Agencies:	1	**SIC Desc 2:**	Sewerage Systems
Program:	WDRNONMUNIPRCS	**SIC Code 3:**	
No of Programs:	1	**SIC Desc 3:**	
WD ID:	1B82050OSON	**NAICS Code 1:**	
Reg Measure ID:	132707	**NAICS Desc 1:**	
Region 1:	1	**NAICS Code 2:**	
Order No:	R1-2004-0059	**NAICS Desc 2:**	
NPDES No Cano:		**NAICS Code 3:**	
Major Minor:		**NAICS Desc 3:**	
NPDES Type:		**No of Places:**	1
Reclamation:	N - No	**Staff Assigned:**	Beth Lamb
Dredge Fill Fee:		**Place County:**	Sonoma
A301H:		**Place Latitude:**	38.525796
Effective Date:	08/25/04 00:00:00	**Place Longitude:**	-122.797272
Region:	1	**Source of Facility:**	Reg Meas
Agency Name:	Marmon Group		

Status 1:	Active
Facility Waste Type:	Contaminated soil
Facility Waste Type 3:	
Facility Waste Type 4:	
Facility Waste Type 2:	
Title:	Enforcement - 1B82050OSON Marmon Group Ecodyne/Shiloh Industrial Park
Description:	THIRTEEN TASKS ARE TO BE COMPLETED IN THE CLEANUP OF THE SITE.
Threat to Water Quality:	3
Reg Measure Type:	WDR
Program 1:	WDR
No of Programs 1:	1
Enforcement ID EID:	224684
Order Resolution No:	88-114
Enforcement Action Type:	Clean-up and Abatement Order
Effective Date 1:	08/12/88 00:00:00
Year Effective:	08/12/88 00:00:00
Adoption Issuance Date:	
Achieve Date:	
Year Effective2:	
ACL Issuance Date:	
EPL Issuance Date:	
Latest Milestone Completion Da:	
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability Amount:	0
Project Amount:	0
Application Fee Amt Received:	3684.2
Liability Paid:	0
Project Completed:	0
Total Paid Completed Amount:	0
Agency Issuing Enf:	
Date of Oldest Violation Linke:	
Rank 1 Violations:	0
Rank 2 Violations:	0
Rank 3 Violations:	0
Unclassified Violations:	0
Atox Violations No:	0
Expiration Review Date:	08/25/09 00:00:00
Termination Date:	02/07/07 00:00:00
WDR Review Amend:	
WDR Review Revise Renew:	
WDR Review Resc Ind:	
WDR Review No Action Required:	
WDR Review Pending:	
WDR Review Planned:	
Status Enrollee:	No
Individual General:	I
No of Staff Assigned:	1
Supervisor:	
No of Supervisors:	
Direction Voice:	Passive

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Region 2:	1		
Assigned Staff:			
No of Assigned Staff:	1		
Supervisor2:			
No of Supervisors 1:			
Program Category:	WDR	**Tot No of VIO Linked :**	0
Program Category 1:	WDR	**Ctox Violations No:**	0
Late Report VIO No:	0	**Dfcnt Monitor VIO No:**	0
OEV VIO No:	0	**Dfcnt Report VIO No:**	0
Other Codes VIO No:	0	**Enfcmt Act VIO No:**	0
Permit Condit VIO No:	0	**Fees Violations No:**	0
Pretreatment VIO No:	0	**Groundwater VIO No:**	0
SSO Violations No:	0	**Hydro Mod VIO No:**	0
Surface Wtr VIO No:	0	**Effluent MMP Serious:**	0
SWPPP Violations No:	0	**Chronic MMP:**	0
Total MMP VIO No:	0	**Report MMP Serious:**	0
Priority Violations:	0	**Economic Benefit:**	
BMP Violations No:	0	**Staff Cost:**	
Cat1 Violations No:	0	**Max Pot Liability:**	
Cat2 Violations No:	0	**Termination Date 1:**	
Reporting F To Notify VIO No:	0		
Unauthorized Discharge VIO No:	0		
Basin Plan Prohibition VIO:	0		

30	19 of 45	WNW	0.12 / 657.88	105.61 / -14	**Marmon Group Ecodyne/Shiloh Industrial Park** **930 Shiloh Road** **Windsor CA 95492**	CDO/CAO

Facility ID:	222151	**Design Flow:**	0.0034
Facility Type:	Industrial	**Complexity:**	A
Status:	Historical	**Pretreatment:**	X - Facility is not a POTW
Status Date:	12/04/15 00:00:00	**Fee Code:**	
Place Type:	Manufacturing	**SIC Code 1:**	2879
Place Sub Type:	Manufacturing NEC	**SIC Desc 1:**	Pesticides and Agricultural Chemicals, NEC
Agency Type:	Privately-Owned Business	**SIC Code 2:**	4952
No of Agencies:	1	**SIC Desc 2:**	Sewerage Systems
Program:	WDRNONMUNIPRCS	**SIC Code 3:**	
No of Programs:	1	**SIC Desc 3:**	
WD ID:	1B82050OSON	**NAICS Code 1:**	
Reg Measure ID:	132707	**NAICS Desc 1:**	
Region 1:	1	**NAICS Code 2:**	
Order No:	R1-2004-0059	**NAICS Desc 2:**	
NPDES No Cano:		**NAICS Code 3:**	
Major Minor:		**NAICS Desc 3:**	
NPDES Type:		**No of Places:**	1
Reclamation:	N - No	**Staff Assigned:**	Beth Lamb
Dredge Fill Fee:		**Place County:**	Sonoma
A301H:		**Place Latitude:**	38.525796
Effective Date:	08/25/04 00:00:00	**Place Longitude:**	-122.797272
Region:	1	**Source of Facility:**	Reg Meas
Agency Name:	Marmon Group		
Status 1:	Active		
Facility Waste Type:	Contaminated soil		
Facility Waste Type 3:			
Facility Waste Type 4:			
Facility Waste Type 2:			
Title:	Enforcement - 1B82050OSON Marmon Group Ecodyne/Shiloh Industrial Park		
Description:	ESTABLISHES A TIME SCHEDULE FOR COMMENCEMENT OF SHALLOW CLEANUP AND COMPLETION OF INVESTIGATION.		
Threat to Water Quality:	3		
Reg Measure Type:	WDR		
Program 1:	WDR		
No of Programs 1:	1		
Enforcement ID EID:	219083		
Order Resolution No:	88-103		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Enforcement Action Type:	Clean-up and Abatement Order
Effective Date 1:	07/19/88 00:00:00
Year Effective:	
Adoption Issuance Date:	
Achieve Date:	
Year Effective2:	
ACL Issuance Date:	
EPL Issuance Date:	
Latest Milestone Completion Da:	
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability Amount:	0
Project Amount:	0
Application Fee Amt Received:	3684.2
Liability Paid:	0
Project Completed:	0
Total Paid Completed Amount:	0
Agency Issuing Enf:	
Date of Oldest Violation Linke:	
Rank 1 Violations:	0
Rank 2 Violations:	0
Rank 3 Violations:	0
Unclassified Violations:	0
Atox Violations No:	0
Expiration Review Date:	08/25/09 00:00:00
Termination Date:	02/07/07 00:00:00
WDR Review Amend:	
WDR Review Revise Renew:	
WDR Review Resc Ind:	
WDR Review No Action Required:	
WDR Review Pending:	
WDR Review Planned:	
Status Enrollee:	No
Individual General:	I
No of Staff Assigned:	1
Supervisor:	
No of Supervisors:	
Direction Voice:	Passive
Region 2:	1
Assigned Staff:	
No of Assigned Staff:	1
Supervisor2:	
No of Supervisors 1:	

Program Category:	WDR	***Tot No of VIO Linked :***	0
Program Category 1:	WDR	***Ctox Violations No:***	0
Late Report VIO No:	0	***Dfcnt Monitor VIO No:***	0
OEV VIO No:	0	***Dfcnt Report VIO No:***	0
Other Codes VIO No:	0	***Enfcmt Act VIO No:***	0
Permit Condit VIO No:	0	***Fees Violations No:***	0
Pretreatment VIO No:	0	***Groundwater VIO No:***	0
SSO Violations No:	0	***Hydro Mod VIO No:***	0
Surface Wtr VIO No:	0	***Effluent MMP Serious:***	0
SWPPP Violations No:	0	***Chronic MMP:***	0
Total MMP VIO No:	0	***Report MMP Serious:***	0
Priority Violations:	0	***Economic Benefit:***	
BMP Violations No:	0	***Staff Cost:***	
Cat1 Violations No:	0	***Max Pot Liability:***	
Cat2 Violations No:	0	***Termination Date 1:***	
Reporting F To Notify VIO No:	0		
Unauthorized Discharge VIO No:	0		
Basin Plan Prohibition VIO:	0		

30	***20 of 45***	***WNW***	***0.12 / 657.88***	***105.61 / -14***	***Marmon Group Ecodyne/Shiloh Industrial Park***	***CDO/CAO***

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

930 Shiloh Road
Windsor CA 95492

Facility ID:	222151	**Design Flow:**	0.0034
Facility Type:	Industrial	**Complexity:**	A
Status:	Historical	**Pretreatment:**	X - Facility is not a POTW
Status Date:	12/04/15 00:00:00	**Fee Code:**	
Place Type:	Manufacturing	**SIC Code 1:**	2879
Place Sub Type:	Manufacturing NEC	**SIC Desc 1:**	Pesticides and Agricultural Chemicals, NEC
Agency Type:	Privately-Owned Business	**SIC Code 2:**	4952
No of Agencies:	1	**SIC Desc 2:**	Sewerage Systems
Program:	WDRNONMUNIPRCS	**SIC Code 3:**	
No of Programs:	1	**SIC Desc 3:**	
WD ID:	1B82050OSON	**NAICS Code 1:**	
Reg Measure ID:	132707	**NAICS Desc 1:**	
Region 1:	1	**NAICS Code 2:**	
Order No:	R1-2004-0059	**NAICS Desc 2:**	
NPDES No Cano:		**NAICS Code 3:**	
Major Minor:		**NAICS Desc 3:**	
NPDES Type:		**No of Places:**	1
Reclamation:	N - No	**Staff Assigned:**	Beth Lamb
Dredge Fill Fee:		**Place County:**	Sonoma
A301H:		**Place Latitude:**	38.525796
Effective Date:	08/25/04 00:00:00	**Place Longitude:**	-122.797272
Region:	1	**Source of Facility:**	Reg Meas
Agency Name:	Marmon Group		
Status 1:	Active		
Facility Waste Type:	Contaminated soil		
Facility Waste Type 3:			
Facility Waste Type 4:			
Facility Waste Type 2:			
Title:	Enforcement - 1B82050OSON Marmon Group Ecodyne/Shiloh Industrial Park		
Description:	ORDER ACKNOWLEDGES THE NEW LAND OWNERS AS RESPONSIBLE		
Threat to Water Quality:	3		
Reg Measure Type:	WDR		
Program 1:	WDR		
No of Programs 1:	1		
Enforcement ID EID:	224308		
Order Resolution No:	87-137		
Enforcement Action Type:	Clean-up and Abatement Order		
Effective Date 1:	10/19/87 00:00:00		
Year Effective:	10/19/87 00:00:00		
Adoption Issuance Date:			
Achieve Date:			
Year Effective2:			
ACL Issuance Date:			
EPL Issuance Date:			
Latest Milestone Completion Da:	11/16/87 00:00:00		
Total Assessment Amount:	0		
Initial Assessed Amount:	0		
Liability Amount:	0		
Project Amount:	0		
Application Fee Amt Received:	3684.2		
Liability Paid:	0		
Project Completed:	0		
Total Paid Completed Amount:	0		
Agency Issuing Enf:			
Date of Oldest Violation Linke:			
Rank 1 Violations:	0		
Rank 2 Violations:	0		
Rank 3 Violations:	0		
Unclassified Violations:	0		
Atox Violations No:	0		
Expiration Review Date:	08/25/09 00:00:00		
Termination Date:	02/07/07 00:00:00		
WDR Review Amend:			
WDR Review Revise Renew:			
WDR Review Resc Ind:			

WDR Review No Action Required:	
WDR Review Pending:	
WDR Review Planned:	
Status Enrollee:	No
Individual General:	I
No of Staff Assigned:	1
Supervisor:	
No of Supervisors:	
Direction Voice:	Passive
Region 2:	1
Assigned Staff:	
No of Assigned Staff:	1
Supervisor2:	
No of Supervisors 1:	

Program Category:	WDR	***Tot No of VIO Linked :***	0
Program Category 1:	WDR	***Ctox Violations No:***	0
Late Report VIO No:	0	***Dfcnt Monitor VIO No:***	0
OEV VIO No:	0	***Dfcnt Report VIO No:***	0
Other Codes VIO No:	0	***Enfcmt Act VIO No:***	0
Permit Condit VIO No:	0	***Fees Violations No:***	0
Pretreatment VIO No:	0	***Groundwater VIO No:***	0
SSO Violations No:	0	***Hydro Mod VIO No:***	0
Surface Wtr VIO No:	0	***Effluent MMP Serious:***	0
SWPPP Violations No:	0	***Chronic MMP:***	0
Total MMP VIO No:	0	***Report MMP Serious:***	0
Priority Violations:	0	***Economic Benefit:***	
BMP Violations No:	0	***Staff Cost:***	
Cat1 Violations No:	0	***Max Pot Liability:***	
Cat2 Violations No:	0	***Termination Date 1:***	
Reporting F To Notify VIO No:	0		
Unauthorized Discharge VIO No:	0		
Basin Plan Prohibition VIO:	0		

30	***21 of 45***	***WNW***	***0.12 / 657.88***	***105.61 / -14***	***Marmon Group Ecodyne/Shiloh Industrial Park 930 Shiloh Road Windsor CA 95492***	***CDO/CAO***

Facility ID:	222151	***Design Flow:***	0.0034
Facility Type:	Industrial	***Complexity:***	A
Status:	Historical	***Pretreatment:***	X - Facility is not a POTW
Status Date:	12/04/15 00:00:00	***Fee Code:***	
Place Type:	Manufacturing	***SIC Code 1:***	2879
Place Sub Type:	Manufacturing NEC	***SIC Desc 1:***	Pesticides and Agricultural Chemicals, NEC
Agency Type:	Privately-Owned Business	***SIC Code 2:***	4952
No of Agencies:	1	***SIC Desc 2:***	Sewerage Systems
Program:	WDRNONMUNIPRCS	***SIC Code 3:***	
No of Programs:	1	***SIC Desc 3:***	
WD ID:	1B82050OSON	***NAICS Code 1:***	
Reg Measure ID:	132707	***NAICS Desc 1:***	
Region 1:	1	***NAICS Code 2:***	
Order No:	R1-2004-0059	***NAICS Desc 2:***	
NPDES No Cano:		***NAICS Code 3:***	
Major Minor:		***NAICS Desc 3:***	
NPDES Type:		***No of Places:***	1
Reclamation:	N - No	***Staff Assigned:***	Beth Lamb
Dredge Fill Fee:		***Place County:***	Sonoma
A301H:		***Place Latitude:***	38.525796
Effective Date:	08/25/04 00:00:00	***Place Longitude:***	-122.797272
Region:	1	***Source of Facility:***	Reg Meas
Agency Name:	Marmon Group		
Status 1:	Active		
Facility Waste Type:	Contaminated soil		
Facility Waste Type 3:			
Facility Waste Type 4:			

Facility Waste Type 2:	
Title:	Enforcement - 1B82050OSON Marmon Group Ecodyne/Shiloh Industrial Park
Description:	TECHNICAL REPORT EVALUATING THE EFFECTIVENESS OF CLEANUP SHALL BE SUBMITTE4D ANNUALLY.
Threat to Water Quality:	3
Reg Measure Type:	WDR
Program 1:	WDR
No of Programs 1:	1
Enforcement ID EID:	224675
Order Resolution No:	89-061
Enforcement Action Type:	Clean-up and Abatement Order
Effective Date 1:	04/14/89 00:00:00
Year Effective:	
Adoption Issuance Date:	
Achieve Date:	
Year Effective2:	
ACL Issuance Date:	
EPL Issuance Date:	
Latest Milestone Completion Da:	
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability Amount:	0
Project Amount:	0
Application Fee Amt Received:	3684.2
Liability Paid:	0
Project Completed:	0
Total Paid Completed Amount:	0
Agency Issuing Enf:	
Date of Oldest Violation Linke:	
Rank 1 Violations:	0
Rank 2 Violations:	0
Rank 3 Violations:	0
Unclassified Violations:	0
Atox Violations No:	0
Expiration Review Date:	08/25/09 00:00:00
Termination Date:	02/07/07 00:00:00
WDR Review Amend:	
WDR Review Revise Renew:	
WDR Review Resc Ind:	
WDR Review No Action Required:	
WDR Review Pending:	
WDR Review Planned:	
Status Enrollee:	No
Individual General:	I
No of Staff Assigned:	1
Supervisor:	
No of Supervisors:	
Direction Voice:	Passive
Region 2:	1
Assigned Staff:	
No of Assigned Staff:	1
Supervisor2:	
No of Supervisors 1:	

Program Category:	WDR	***Tot No of VIO Linked :***	0
Program Category 1:	WDR	***Ctox Violations No:***	0
Late Report VIO No:	0	***Dfcnt Monitor VIO No:***	0
OEV VIO No:	0	***Dfcnt Report VIO No:***	0
Other Codes VIO No:	0	***Enfcmt Act VIO No:***	0
Permit Condit VIO No:	0	***Fees Violations No:***	0
Pretreatment VIO No:	0	***Groundwater VIO No:***	0
SSO Violations No:	0	***Hydro Mod VIO No:***	0
Surface Wtr VIO No:	0	***Effluent MMP Serious:***	0
SWPPP Violations No:	0	***Chronic MMP:***	0
Total MMP VIO No:	0	***Report MMP Serious:***	0
Priority Violations:	0	***Economic Benefit:***	
BMP Violations No:	0	***Staff Cost:***	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Cat1 Violations No: 0
Cat2 Violations No: 0
Reporting F To Notify VIO No: 0
Unauthorized Discharge VIO No: 0
Basin Plan Prohibition VIO: 0
Max Pot Liability:
Termination Date 1:

---

30 | 22 of 45 | WNW | 0.12 / 657.88 | 105.61 / -14 | The Fluor Corporation, 930 Shiloh Rd Windsor, CA 95492 CA | CUPA SONOMA

Facility ID: 49-000-008444
CERS ID: 10689577

Details

Program Type: HMBP
Permit Status: Inactive
Expiration Date:
Fee Schedule:

Details

Program Type: Hazardous Waste
Permit Status: Inactive
Expiration Date:
Fee Schedule: LQG 25 to <250 tons/year

---

30 | 23 of 45 | WNW | 0.12 / 657.88 | 105.61 / -14 | North Bay Concrete, Inc., 930 SHILOH RD BLDG 46, WINDSOR CA 95492 | CERS HAZ

Site ID: 398319
Latitude: 38.525730
Longitude: -122.796350
County:

Regulated Programs

EI ID: 10477591
EI Description: Chemical Storage Facilities

EI ID: 10477591
EI Description: Hazardous Waste Generator

Violations

Violation Date: 01/06/2021
Violation Program: HMRRP
Violation Source: CERS
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95, Section(s) 25508.2
Violation Notes:

Returned to compliance on 04/28/2021. The business failed to electronically submit and certify that the business plan is complete, accurate, and in compliance with EPCRA on or before the required due date. Electronically submit and certify that the business plan is complete, accurate, and in compliance with EPCRA within 30 days. On an ongoing basis, electronically submit and certify the business plan annually on or before the required due date.

Violation Description:

Failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date.

Violations

Violation Date: 01/06/2021 **Violation Source:** CERS
Violation Program: HW **Violation Division:** Sonoma County Fire & Emergency Services Department
Citation: HSC 6.11 25404(e)(4) - California Health and Safety Code, Chapter 6.11, Section(s) 25404(e)(4)
Violation Notes:

Returned to compliance on 04/28/2021. Owner/Operator failed to report program data electronically into CERS. Complete all required reporting into CERS.

Violation Description:

Failure to report program data electronically.

Violations

Violation Date: 10/25/2013 **Violation Source:** CERS
Violation Program: HMRRP **Violation Division:** Sonoma County Fire & Emergency Services Department
Citation: HSC 6.95 25505(a) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)
Violation Notes:

Returned to compliance on 01/15/2014. Submitted complete HMBP to CERS

Violation Description:

Owner/Operator failed to complete and/or submit a Hazardous Materials Business Plan when storing hazardous materials at or above the thresholds quantities of 55 gallons/500 lbs/200 cubic feet.

Evaluations

Eval Date: 04/28/2021
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

Violation corrected; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 01/06/2021
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

Eval Date: 12/22/2020
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

Attempted to inspect; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 01/06/2021
Violations Found: Yes

Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Update CERS; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/28/2021
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Violation corrected; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/28/2021
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

violation corrected; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 10/25/2013
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Eval Date: 04/09/2018
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

No violations; shop looked good.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/22/2020
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Attempted to inspect; Note: data in [EVAL Notes] field for some records is truncated from the source.

Affiliations

Affil Type Desc: Document Preparer
Entity Name: Lohrie L Pardue
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Operator
Entity Name: North Bay Concrete, Inc.
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone: (707) 836-8500

Affil Type Desc: Legal Owner
Entity Name: North Bay Concrete, Inc.
Entity Title:
Address: 930 Shiloh Rd Bldg 46
City: Windsor
State: CA
Country: United States
Zip Code: 95492
Phone: (707) 836-8500

Affil Type Desc: Property Owner
Entity Name: Shiloh Group, LLC
Entity Title:
Address: lohrie@nobayconc.com
City: WINDSOR
State: CA
Country: United States
Zip Code: 95492-9679
Phone: (707) 217-5339

Affil Type Desc: Parent Corporation
Entity Name: North Bay Concrete, Inc.
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Identification Signer
Entity Name: Lohrie L Pardue
Entity Title: President
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Environmental Contact
Entity Name: Scott Krisl
Entity Title:
Address: 930 Shiloh Rd Bldg 46
City: Windsor
State: CA
Country:
Zip Code: 95492

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Phone:

Affil Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title:
Address: 930 Shiloh Road, Bldg. 46
City: Windsor
State: CA
Country:
Zip Code: 95492
Phone:

Affil Type Desc: CUPA District
Entity Name: Sonoma County Fire Prevention and Hazmat
Entity Title:
Address: 2300 County Center Drive, Suite 220-B
City: Santa Rosa
State: CA
Country:
Zip Code: 95403
Phone: (707) 565-2024

30	24 of 45	WNW	0.12 / 657.88	105.61 / -14	LandCare 930 SHILOH RD BLDG 2, YARD 39 WINDSOR CA 95492	CERS HAZ

Site ID: 163671
Latitude: 38.525730
Longitude: -122.796350
County:

Regulated Programs

EI ID: 10501162 **EI Description:** Chemical Storage Facilities

EI ID: 10501162 **EI Description:** Hazardous Waste Generator

Violations

Violation Date: 05/06/2014 **Violation Source:** CERS
Violation Program: HMRRP **Violation Division:** Sonoma County Fire & Emergency Services Department
Citation: HSC 6.95 25505(a) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)
Violation Notes:

Returned to compliance on 05/06/2014. CERS submittal

Violation Description:

Owner/Operator failed to complete and/or submit a Hazardous Materials Business Plan when storing hazardous materials at or above the thresholds quantities of 55 gallons/500 lbs/200 cubic feet.

Violations

Violation Date: 05/06/2014 **Violation Source:** CERS
Violation Program: HW **Violation Division:** Sonoma County Fire & Emergency Services Department
Citation: 40 CFR 1 265.31 - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 265.31
Violation Notes:

Returned to compliance on 04/21/2020. Remove spilled oil & debris from secondary containment around used oil drums

Violation Description:

Failure to maintain and operate the facility to minimize the possibility of a fire, explosion, or any unplanned sudden or non-sudden release of hazardous waste or hazardous waste constituents to the air, soil, or surface water which could threaten human health or the environment..

Violations

Violation Date: 05/06/2014
Violation Source: CERS
Violation Program: HW
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: 40 CFR 1 265.31 - U.S. Code of Federal Regulations, Title 40, Chapter 1, Section(s) 265.31
Violation Notes:

Returned to compliance on 10/09/2015.

Violation Description:

Failure to maintain and operate the facility to minimize the possibility of a fire, explosion, or any unplanned sudden or non-sudden release of hazardous waste or hazardous waste constituents to the air, soil, or surface water which could threaten human health or the environment..

Violations

Violation Date: 05/06/2014
Violation Source: CERS
Violation Program: HW
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)
Violation Notes:

Returned to compliance on 04/21/2020. Label drums of used oil with dates of initial accumulation

Violation Description:

Failure to properly label hazardous waste accumulation containers with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.

Violations

Violation Date: 05/06/2014
Violation Source: CERS
Violation Program: HW
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)
Violation Notes:

Returned to compliance on 10/09/2015.

Violation Description:

Failure to properly label hazardous waste accumulation containers with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.

Violations

Violation Date: 05/06/2014
Violation Source: CERS
Violation Program: HW
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: HSC 6.95 25505(a) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)
Violation Notes:

Returned to compliance on 08/20/2015. Submit HMBP thru CERS

Violation Description:

Owner/Operator failed to complete and/or submit a Hazardous Materials Business Plan when storing hazardous materials at or above the thresholds quantities of 55 gallons/500 lbs/200 cubic feet.

Enforcements

Enf Action Date: 05/06/2014
Enf Action Program: UNSPEC
Enf Action Type: Notice of Violation (Unified Program)
Enf Action Source: CERS
Enf Action Division: Sonoma County Fire & Emergency Services Department
Enf Action Description: Notice of Violation Issued by the Inspector at the Time of Inspection
Enf Action Notes:

Evaluations

Eval Date: 05/06/2014
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

Eval Date: 05/06/2014
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Eval Date: 05/25/2018
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

Eval Date: 05/08/2018
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Affiliations

Affil Type Desc: CUPA District
Entity Name: Sonoma County Fire Prevention and Hazmat
Entity Title:
Address: 2300 County Center Drive, Suite 220-B
City: Santa Rosa
State: CA
Country:
Zip Code: 95403
Phone: (707) 565-2024

Affil Type Desc: Legal Owner
Entity Name: Duane Faloni

Entity Title:
Address: 930 Shiloh Rd Bldg 44, Ste B
City: Windsor
State: CA
Country: United States
Zip Code: 95492
Phone: (707) 974-8831

Affil Type Desc: Operator
Entity Name: LandCare
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone: (707) 836-1451

Affil Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title:
Address: 930 Shiloh Rd Bldg 44, Ste B
City: Windsor
State: CA
Country:
Zip Code: 95492
Phone:

Affil Type Desc: Document Preparer
Entity Name: Duane Faloni
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Parent Corporation
Entity Name: TruGreen LandCare LLC
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Identification Signer
Entity Name: Duane Faloni
Entity Title: Branch Manager
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Environmental Contact
Entity Name: Duane Faloni
Entity Title:
Address: 930 Shiloh Rd Bldg 44, Ste B
City: Windsor
State: CA
Country:
Zip Code: 95492
Phone:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
30	25 of 45	WNW	0.12 / 657.88	105.61 / -14	Kadon Trucking, Inc. 930 SHILOH RD BLDG 15 WINDSOR CA 95492	CERS HAZ

Site ID: 127098
Latitude: 38.525761
Longitude: -122.793050
County:

Regulated Programs

EI ID: 10101667 **EI Description:** Chemical Storage Facilities

EI ID: 10101667 **EI Description:** Hazardous Waste Generator

Violations

Violation Date: 02/27/2014 **Violation Source:** CERS
Violation Program: HMRRP **Violation Division:** Sonoma County Fire & Emergency Services Department
Citation: HSC 6.95 Multiple - California Health and Safety Code, Chapter 6.95, Section(s) Multiple
Violation Notes:

Returned to compliance on 01/29/2020. No submissions in CERS

Violation Description:

Business Plan Program - Administration/Documentation - General

Violations

Violation Date: 02/27/2014 **Violation Source:** CERS
Violation Program: HW **Violation Division:** Sonoma County Fire & Emergency Services Department
Citation: HSC 6.67 Multiple - California Health and Safety Code, Chapter 6.67, Section(s) Multiple
Violation Notes:

Returned to compliance on 10/08/2015. Label hazardous waste containers with accumulation dates. Provide secondary containment for water treatment chemicals. Provide manifests for waste removal.

Violation Description:

Haz Waste Generator Program - Operations/Maintenance - General

Violations

Violation Date: 02/27/2014 **Violation Source:** CERS
Violation Program: HW **Violation Division:** Sonoma County Fire & Emergency Services Department
Citation: HSC 6.67 Multiple - California Health and Safety Code, Chapter 6.67, Section(s) Multiple
Violation Notes:

Returned to compliance on 01/29/2020. Label hazardous waste containers with accumulation dates. Provide secondary containment for water treatment chemicals. Provide manifests for waste removal.

Violation Description:

Haz Waste Generator Program - Operations/Maintenance - General

Violations

Violation Date: 02/27/2014 **Violation Source:** CERS

Violation Program: HMRRP ***Violation Division:*** Sonoma County Fire & Emergency Services Department

Citation: HSC 6.95 Multiple - California Health and Safety Code, Chapter 6.95, Section(s) Multiple

Violation Notes:

Returned to compliance on 03/20/2014. CERS submittal

Violation Description:

Business Plan Program - Administration/Documentation - General

Evaluations

Eval Date: 02/27/2014
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Eval Date: 04/17/2018
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

No violations; shop looked good. Waste oil is handled by Sacramento Waste Oil; recording keeping and waste records looked good.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 02/27/2014
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

Eval Date: 04/17/2018
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

No violations; CERS was completed during the inspection and is current. Shop storage area looked good.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Affiliations

Affil Type Desc: Identification Signer
Entity Name: Cathi Whitten
Entity Title: Office Manager
Address:
City:
State:

Country:
Zip Code:
Phone:

Affil Type Desc: Parent Corporation
Entity Name: Kadon Trucking, Inc.
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Property Owner
Entity Name: The Shiloh Group
Entity Title:
Address: P.O. Box 2678
City: Santa Rosa
State: CA
Country: United States
Zip Code: 95405
Phone: (707) 836-8203

Affil Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title:
Address: PO Box 1619
City: Windsor
State: CA
Country:
Zip Code: 95492
Phone:

Affil Type Desc: Operator
Entity Name: KADON TRUCKING INC
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone: (707) 838-8008

Affil Type Desc: CUPA District
Entity Name: Sonoma County Fire Prevention and Hazmat
Entity Title:
Address: 2300 County Center Drive, Suite 220-B
City: Santa Rosa
State: CA
Country:
Zip Code: 95403
Phone: (707) 565-2024

Affil Type Desc: Document Preparer
Entity Name: Cathi Whitten
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Environmental Contact
Entity Name: Kimberlina Carpenter
Entity Title:
Address: PO BOX 1619
City: Windsor

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

State: CA
Country:
Zip Code: 95492
Phone:

Affil Type Desc: Legal Owner
Entity Name: Mrs. Karen Carpenter
Entity Title:
Address: PO Box 1619
City: Windsor
State: CA
Country: United States
Zip Code: 95492
Phone: (707) 838-8008

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
30	26 of 45	WNW	0.12 / 657.88	105.61 / -14	The Fluor Corporation 930 SHILOH RD WINDSOR CA 95492	DELISTED HAZ

Siteid: 378130
Latitude: 38.525733
Longitude: -122.796348
Original Source: CHAZ
Record Date: 20-OCT-2017

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
30	27 of 45	WNW	0.12 / 657.88	105.61 / -14	WESTERN FIBERGLASS 930 SHILOH RD, BLDG 2 WINDSOR CA 95492	EMISSIONS

1987 Criteria Data

Facility ID: 3384
Facility SIC Code: 2655
CO: 49
Air Basin: SF
District: BA
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:
TOGT: 3.1
ROGT: 1.9
COT:
NOXT:
SOXT:
PMT:
PM10T:

1987 Toxic Data

Facility ID: 3384
Facility SIC Code: 2655
CO: 49
Air Basin: SF
District: BA
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:

1990 Criteria Data

Facility ID: 3384
Facility SIC Code: 2221
CO: 49
Air Basin: SF
District: BA
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:
TOGT: 10.2
ROGT: 8.7
COT:
NOXT:
SOXT:
PMT:
PM10T:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

1990 Toxic Data

Facility ID:	3384	***COID:***	SON
Facility SIC Code:	2221	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
30	28 of 45	WNW	0.12 / 657.88	105.61 / -14	MARTIN'S TRUCK REPAIR 930 SHILOH RD, BLDG 2, STE B WINDSOR CA 95492	EMISSIONS

1998 Criteria Data

Facility ID:	11834	***CERR Code:***	
Facility SIC Code:	7532	***TOGT:***	.2
CO:	49	***ROGT:***	.1768
Air Basin:	SF	***COT:***	
District:	BA	***NOXT:***	
COID:	SON	***SOXT:***	
DISN:	BAY AREA AQMD	***PMT:***	
CHAPIS:		***PM10T:***	

1998 Toxic Data

Facility ID:	11834	***COID:***	SON
Facility SIC Code:	7532	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

1999 Criteria Data

Facility ID:	11834	***CERR Code:***	
Facility SIC Code:	7532	***TOGT:***	.149
CO:	49	***ROGT:***	.144232
Air Basin:	SF	***COT:***	
District:	BA	***NOXT:***	
COID:	SON	***SOXT:***	
DISN:	BAY AREA AQMD	***PMT:***	
CHAPIS:		***PM10T:***	

1999 Toxic Data

Facility ID:	11834	***COID:***	SON
Facility SIC Code:	7532	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Non-Cancer Acute Haz Ind:

2000 Criteria Data

Facility ID:	11834	**CERR Code:**	
Facility SIC Code:	7532	**TOGT:**	.149
CO:	49	**ROGT:**	.14
Air Basin:	SF	**COT:**	
District:	BA	**NOXT:**	
COID:	SON	**SOXT:**	
DISN:	BAY AREA AQMD	**PMT:**	
CHAPIS:		**PM10T:**	

2000 Toxic Data

Facility ID:	11834	**COID:**	SON
Facility SIC Code:	7532	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2001 Toxic Data

Facility ID:	11834	**COID:**	SON
Facility SIC Code:	7532	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
30	29 of 45	WNW	0.12 / 657.88	105.61 / -14	MARTIN'S TRUCK REPAIR 930 SHILOH RD WINDSOR CA 95492	EMISSIONS

2002 Toxic Data

Facility ID:	11834	**COID:**	SON
Facility SIC Code:	7532	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
30	30 of 45	WNW	0.12 / 657.88	105.61 / -14	RUIZ AUTOBODY 930 SHILOH RD, BLDG 2, STE B WINDSOR CA 95492	EMISSIONS

2003 Criteria Data

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility ID:	13881	**CERR Code:**	
Facility SIC Code:	7532	**TOGT:**	.096
CO:	49	**ROGT:**	.09
Air Basin:	SF	**COT:**	
District:	BA	**NOXT:**	
COID:	SON	**SOXT:**	
DISN:	BAY AREA AQMD	**PMT:**	
CHAPIS:		**PM10T:**	

2003 Toxic Data

Facility ID:	13881	**COID:**	SON
Facility SIC Code:	7532	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

30	*31 of 45*	*WNW*	*0.12 / 657.88*	*105.61 / -14*	***IT CORPORATION 930 SHILOH ROAD WINDSOR CA 95492***	***EMISSIONS***

1999 Toxic Data

Facility ID:	11555	**COID:**	SON
Facility SIC Code:	4953	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2000 Toxic Data

Facility ID:	11555	**COID:**	SON
Facility SIC Code:	4953	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2005 Criteria Data

Facility ID:	11555	**CERR Code:**	
Facility SIC Code:	4953	**TOGT:**	.002
CO:	49	**ROGT:**	.0013972
Air Basin:	SF	**COT:**	
District:	BA	**NOXT:**	
COID:	SON	**SOXT:**	
DISN:	BAY AREA AQMD	**PMT:**	
CHAPIS:		**PM10T:**	

2005 Toxic Data

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility ID: 11555
Facility SIC Code: 4953
CO: 49
Air Basin: SF
District: BA
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:

---

30 | 32 of 45 | WNW | 0.12 / 657.88 | 105.61 / -14 | ECODYNE DRAINAGE DITCH, 930 SHILOH ROAD, WINDSOR CA 95492 | RESPONSE

Estor/EPA ID: 60002525
Site Code: 202143
Nat Priority List: NO
Acres: 1 ACRES
Special Program:
Funding: RESPONSIBLE PARTY
Assembly District: 02
Senate District: 02
School District:
APN: NONE SPECIFIED
Cleanup Status: REFER: RWQCB AS OF 3/12/2018
Cleanup Oversight Agencies: DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY
Site Type: STATE RESPONSE OR NPL
Office: CLEANUP BERKELEY
Past Use that Caused Contam: NONE SPECIFIED
Potential Media Affected: NONE SPECIFIED
Potential Contamin of Concern:

NONE SPECIFIED

Site History:

Permit Renewal Lead:
Project Manager:
Supervisor:
Public Partici Spclst:
Census Tract:
County: SONOMA
Latitude: 0
Longitude: 0

Status: REFER: RWQCB
Program Type: STATE RESPONSE
CalEnviroScreen Score:
Summary Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=60002525

---

30 | 33 of 45 | WNW | 0.12 / 657.88 | 105.61 / -14 | All Around Auto Repair, 930 SHILOH RD, WINDSOR CA 95492 | CERS HAZ

Site ID: 424382
Latitude: 38.525637
Longitude: -122.796270
County:

Regulated Programs

EI ID: 10111180
EI Description: Hazardous Waste Generator

EI ID: 10111180
EI Description: Chemical Storage Facilities

Violations

Violation Date: 08/28/2015
Violation Program: HW
Violation Source: CERS
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: HSC 6.5 Multiple Sections - California Health and Safety Code, Chapter 6.5, Section(s) Multiple Sections
Violation Notes:

Returned to compliance on 11/05/2016. Fire extinguisher low on pressure Have fire extinguisher serviced (low on pressure)

Violation Description:

Haz Waste Generator Program - Operations/Maintenance - General

Violations

Violation Date: 04/03/2018
Violation Source: CERS
Violation Program: HMRRP
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Returned to compliance on 04/10/2018. The business failed to complete and electronically submit a business plan when handling hazardous materials at or above the reportable threshold quantities. Complete and electronically submit a business plan.

Violation Description:

Failure to complete and electronically submit a business plan when storing/handling a hazardous material at or above reportable quantities.

Violations

Violation Date: 04/03/2018
Violation Source: CERS
Violation Program: HMRRP
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Violation Notes:

Returned to compliance on 04/10/2018. The business failed to electronically submit and certify that the business plan is complete, accurate, and in compliance with EPCRA on or before the annual due date. Electronically submit and certify that the business plan is complete, accurate, and in compliance with EPCRA within 30 days. On an ongoing basis, electronically submit and certify the business plan annually on or before the annual due date.

Violation Description:

Failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date.

Violations

Violation Date: 08/28/2015
Violation Source: CERS
Violation Program: HW
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)
Violation Notes:

Returned to compliance on 11/05/2016. Label waste coolant & used oil as Hazardous Waste & note initial accumulation date

Violation Description:

Failure to properly label hazardous waste accumulation containers with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.

Evaluations

Eval Date: 04/03/2018
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW

Eval Source: CERS
Eval Notes:

No violations; manifests were in order; storage area was labled and neat and orderly.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 04/03/2018
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

CERS not submitted; appointment made for 4/10/18 to input Business plan with Dale.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 08/28/2015
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

Affiliations

Affil Type Desc: Operator
Entity Name: Dale johnson
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone: (707) 694-8671

Affil Type Desc: Property Owner
Entity Name: Dale Johnson
Entity Title:
Address: 930 Shiloh Road #53
City: Windsor
State: CA
Country: United States
Zip Code: 95492
Phone: (707) 837-0646

Affil Type Desc: CUPA District
Entity Name: Sonoma County Fire Prevention and Hazmat
Entity Title:
Address: 2300 County Center Drive, Suite 220-B
City: Santa Rosa
State: CA
Country:
Zip Code: 95403
Phone: (707) 565-2024

Affil Type Desc: Environmental Contact
Entity Name: All Around Auto Repair
Entity Title:
Address: 930 Shiloh Road #53
City: Windsor
State: CA

Country:
Zip Code: 95492
Phone:

Affil Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title:
Address: 930 Shiloh Road #53
City: Windsor
State: CA
Country:
Zip Code: 95492
Phone:

Affil Type Desc: Legal Owner
Entity Name: Mr. Dale Johnson
Entity Title:
Address: 930 Shiloh Road #53
City: Windsor
State: CA
Country: United States
Zip Code: 95492
Phone: (707) 837-0646

Affil Type Desc: Parent Corporation
Entity Name: All Around Auto Repair
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Document Preparer
Entity Name: Dale Johnson
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Identification Signer
Entity Name: Dale Johnson
Entity Title: owner
Address:
City:
State:
Country:
Zip Code:
Phone:

Coordinates

Env Int Type Code: HMBP
Program ID: 10111180
Latitude: 38.525733
Longitude: -122.796348
Coord Name:
Ref Point Type Desc: Unknown

30	*34 of 45*	*WNW*	*0.12 / 657.88*	*105.61 / -14*	***THE SHILOH GROUP PROPERTY*** ***930 SHILOH ROAD*** ***WINDSOR CA 95492***	***ENVIROSTOR***

Estor/EPA ID: 60002191
Site Code: 202038, 202132
Nat Priority List: NO
Assembly District: , 02
Senate District: , 02
Permit Renewal Lead:

APN:	NONE SPECIFIED	***Public Partici Spclst:***	
Census Tract:	6097152702	***Project Manager:***	TOM LANPHAR
Site Type:	VOLUNTARY CLEANUP	***County:***	SONOMA
Address Description:	930 SHILOH ROAD	***Latitude:***	38.5250149864007
Office:	CLEANUP BERKELEY	***Longitude:***	-122.795463203252
Special Program:		***Acres:***	30.84 ACRES
Funding:	SITE PROPONENT	***Supervisor:***	KIMBERLY WALSH

Cleanup Status: ACTIVE AS OF 5/12/2015
Cleanup Oversight Agencies: DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY
School District:
Past Use that Caused Contam: MANUFACTURING - LUMBER/WOOD PRODUCTS
Potential Media Affected: SOIL
Potential Contamin of Concern:

DIOXIN (AS 2,3,7,8-TCDD TEQ)
LEAD
POLYNUCLEAR AROMATIC HYDROCARBONS (PAHS)

Site History:

DTSC entered into a Voluntary Cleanup Agreement (VCA) with Flour Corporation for the completion of a Preliminary Endangerment Assessment for the property owned by The Shiloh Group (TSG) LLC. The site is approximately 31 acres and was once part of the Ecodyne/Flour water tank/cooling tower production facility. The VCA does not include any cleanup actions.

Status: ACTIVE
Program Type: VOLUNTARY CLEANUP
CalEnviroScreen Score: 46-50%
Summary Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=60002191

Future Activities

Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Removal Action Workplan
Due Date: 2022

Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Land Use Restriction
Due Date: 2022

Completed Activities

Title: Annual Cost Estimate for DTSC oversight 2021-2022
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&enforcement_id=60507661
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 9/10/2021
Comments: annual estimate of DTSC oversight costs

Title: April 2021 Monthly Status Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60489525
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 5/14/2021
Comments: monthly status report

Title: September 2020 Monthly Status Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60489518
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 11/5/2020
Comments:

Title: Supplemental Site Investigation for OU-A (soil vapor) and OU-B (soil)
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60487214
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Supplemental Site Investigation Workplan
Date Completed: 7/21/2020
Comments: work plan to investigate data gaps in OUs A and B

Title: Monthly Status Report - May 2020
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60468075
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 6/12/2020
Comments: regular monthly status report

Title: Monthly Status Report - April 2020
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60468074
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 5/19/2020
Comments: Monthly Report as required by DTSC order

Title: Monthly Status Reports - March 2020
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60459575
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 4/13/2020
Comments: Monthly report as required by DTSC Order

Title: Cost estimate for work planned during 2019-2020 fiscal year.
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&enforcement_id=60470237
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 10/14/2019
Comments: cost estimate for 19/20

Title: Monthly Status Reports - August 2019
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60459568
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 9/13/2019

Comments: monthly status report required by DTSC Order.

Title: Preliminary Endangerment Assessment Report for The Shiloh Group Property
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60397365
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Preliminary Endangerment Assessment Report
Date Completed: 9/27/2016
Comments: PEA Report is approved with conditions and DTSC conclusion for further investigation.

Title: Monthly Status Reports - December 2019
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60459572
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 6/1/2020
Comments:

Title: Monthly Status Reports - January 2020
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60459573
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 2/14/2020
Comments: Regular update as required by DTSC Order

Title: Annual HARP Update
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60488677
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 9/22/2021
Comments: Annual HARP 2021 - 2022

Title: February 2021 Monthly Status Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60489523
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 3/15/2021
Comments: February 2021 status report required by Order

Title: 2020-2021 Annual Cost Estimate for DTSC oversight
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&enforcement_id=60488605
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 10/14/2020
Comments: Estimate of DTSC oversight cost for fiscal year 2020-2012

Title: Implementation of Remedial Investigation Work Plan
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60468057
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Fieldwork

Date Completed: 12/1/2019
Comments: completed work plan and now working on phase II sampling plan

Title: Monthly Status Reports - July 2019
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60459567
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 8/15/2019
Comments: Field preparation activities in anticipation of Remedial Investigation implementation planned for Sept. 2019.

Title: Monthly Status Reports - April 2019
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60459564
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 5/17/2019
Comments:

Title: Phase II Site Investigation Work Plan
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60394027
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Preliminary Endangerment Assessment Workplan
Date Completed: 9/10/2015
Comments: The PEA Work Plan proposes an initial phase of shallow soil sampling in order to inform a Preliminary Endangerment Assessment report. DTSC understands than an amendment to the PEA Work Plan will be submitted to DTSC no later than September 25, 2015, to propose additional soil samples, grab groundwater samples, and monitoring well samples.

Title: March 2021 Monthly Status Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60489524
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 4/15/2021
Comments: monthly status, indoor air sampling discussed with DTSC

Title: December 2020 Monthly Status Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60489521
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 1/29/2021
Comments: December 2020 status report as required by Order

Title: August 2020 Monthly Status Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60489517
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 9/15/2020
Comments: monthly status report

Title: Supplemental Investigation Work Plan (follow up to RI Investigation)
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60475241
Area Name:

Area Link:
Sub Area:
Sub Area Link:
Document Type: Remedial Investigation Workplan
Date Completed: 2/19/2020
Comments: work plan addresses data gaps in soil vapor and PCB in soil

Title: Monthly Status Reports - May 2019
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60459565
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 8/30/2019
Comments:

Title: Monthly Status Reports - March 2019
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60459563
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 4/2/2019
Comments: regular monthly status report for The Shiloh Group Property

Title: Unilateral Order
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&enforcement_id=60427430
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Unilateral Order (I/SE, RAO, CAO, EPA AO)
Date Completed: 11/6/2018
Comments:

Title: Post PEA Report Correspondence
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&enforcement_id=60420857
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 12/7/2016
Comments: These are letters from Fluor, who entered into a VCA with DTSC to complete PEA and letters from attorney and consultant representing the land owner.

Title: July 2021 Monthly Status Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60489528
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 9/8/2021
Comments: monthly Status Report as required by DTSC Order

Title: Monthly Status Reports - February 2020
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60459574
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 3/13/2020
Comments: Monthly update as required by DTSC Order

Title: Monthly Status Reports - November 2019

Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60459571
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 12/16/2019
Comments: Monthly Report for Nov. 2019.

Title: October 2019 Monthly Status Reports
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60459570
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 11/15/2019
Comments: Status report required by DTSC order.

Title: REMEDIAL INVESTIGATION WORKPLAN
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60431395
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Remedial Investigation Workplan
Date Completed: 6/12/2019
Comments: Work Plan approved with condition that two additiona groundwater monitoring wells be added. TSG submitted revised Workplan with additional monitoring wells.

Title: May 2021 Monthly Status Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60489526
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 6/14/2021
Comments: monthly status report as required by DTSC order

Title: Operable Unit - A Additional Groundwater Investigation Workplan
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60497638
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Remedial Investigation Workplan
Date Completed: 6/10/2021
Comments: work plan includes and additional monitoring well and sampling current well network, added mercury to cocs

Title: Monthly Status Report - June 2020
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60468076
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 7/10/2020
Comments: regular monthly status report

Title: Monthly Status Reports - September 2019
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60459569
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 10/16/2019
Comments:

Title: PEA Workplan Addendum
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60400143
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Preliminary Endangerment Assessment Workplan
Date Completed: 10/28/2015
Comments: PEA workplan addresses soil and groundwater.

Title: Voluntary Cleanup Agreement
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&enforcement_id=60394022
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Standard Voluntary Agreement
Date Completed: 7/15/2015
Comments: The Voluntary Cleanup Agreement scope includes the completion of a Preliminary Endangerment Assessment for The Shiloh Group Property.

Title: November 2020 Monthly Status Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60489520
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 12/15/2020
Comments: Monthly report as required by DTSC Order

Title: Monthly Status Report - July 2020
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60468077
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 8/14/2020
Comments: regular monthly status report

Title: June 2021 Monthly Status Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60489527
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 9/8/2021
Comments: June 2021 Monthly Status Report as required by DTSC Order

Title: OUs B, C and D Remedial Investigation Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60488111
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Remedial Investigation Report
Date Completed: 6/25/2021
Comments: NFA for OU-D, polychlorinated biphenyls (PCBs) Aroclor-1254 and Aroclor-1260 in OU-B need remediation and pentachlorophenol (PCP) in OU-C needs remediation. Removal Action Workplan is the next step in cleanup process.

Title: Workplan for Indoor Air Evaluation
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60488114
Area Name:
Area Link:
Sub Area:

Sub Area Link:
Document Type: Supplemental Site Investigation Workplan
Date Completed: 2/23/2021
Comments: revised Air Monitoring Work plan addressed DTSC comments and is approved.

Title: January 2021 Monthly Status Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60489522
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 2/15/2021
Comments: January 2021 Status Report

Title: October 2020 Monthly Status Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60489519
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 11/12/2020
Comments: submittal of Monthly Status Report per IS&E Order

Title: Monthly Status Reports - June 2019
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60002191&doc_id=60459566
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 7/15/2019
Comments: Monthly status report required by DTSC Order.

---

30 | ***35 of 45*** | ***WNW*** | ***0.12 / 657.88*** | ***105.61 / -14*** | ***ECODYNE DRAINAGE DITCH***
930 SHILOH ROAD
WINDSOR CA 95492 | ***ENVIROSTOR***

Estor/EPA ID: 60002525
Site Code: 202143
Nat Priority List: NO
APN: NONE SPECIFIED
Census Tract:
Site Type: STATE RESPONSE OR NPL
Address Description: 930 SHILOH ROAD
Office: CLEANUP BERKELEY
Special Program:
Funding: RESPONSIBLE PARTY
Assembly District: 02
Senate District: 02
Permit Renewal Lead:
Public Partici Spclst:
Project Manager:
County: SONOMA
Latitude: 0
Longitude: 0
Acres: 1 ACRES
Supervisor:
Cleanup Status: REFER: RWQCB AS OF 3/12/2018
Cleanup Oversight Agencies: DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY
School District:
Past Use that Caused Contam: NONE SPECIFIED
Potential Media Affected: NONE SPECIFIED
Potential Contamin of Concern:

NONE SPECIFIED

Site History:

Status: REFER: RWQCB
Program Type: STATE RESPONSE
CalEnviroScreen Score:
Summary Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=60002525

---

30 | ***36 of 45*** | ***WNW*** | ***0.12 /*** | ***105.61 /*** | ***NORTH BAY CONCRETE INC*** | ***RCRA NON GEN***

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
			657.88	-14	930 SHILOH RD BLDG 46 WINDSOR CA 95492	

EPA Handler ID: CAL000365272
Gen Status Universe: No Report
Contact Name: SHARON TAYLOR
Contact Address: 930 SHILOH RD , BLDG 46 , WINDSOR , CA, 95492 ,
Contact Phone No and Ext: 707-836-8500
Contact Email: SHARON@NOBAYCONC.COM
Contact Country:
County Name: SONOMA
EPA Region: 09
Land Type:
Receive Date: 20110701
Location Latitude: 38.523798
Location Longitude: -122.794745

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20110701
Handler Name: NORTH BAY CONCRETE INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Other
Name: NORTH BAY CONCRETE INC
Date Became Current:
Date Ended Current:
Phone: 707-836-8500
Source Type: Implementer
Street No:
Street 1: 936 CROCKER RD
Street 2:
City: CLOVERDALE
State: CA
Country:
Zip Code: 95425-0000

Owner/Operator Ind: Current Operator
Type: Other
Name: SHARON TAYLOR
Date Became Current:
Date Ended Current:
Street No:
Street 1: 930 SHILOH RD
Street 2: BLDG 46
City: WINDSOR
State: CA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Phone: 707-836-8500 **Country:**
Source Type: Implementer **Zip Code:** 95492

---

30 | **37 of 45** | **WNW** | **0.12 / 657.88** | **105.61 / -14** | **KADON TRUCKING INC**
930 SHILOH BLDG #15
WINDSOR CA 95492-0000

RCRA NON GEN

EPA Handler ID: CAL000084470
Gen Status Universe: No Report
Contact Name: KAREN CARPENTER
Contact Address: 930 SHILOH BLDG #15 , , WINDSOR , CA, 95492 ,
Contact Phone No and Ext: 707-838-8008
Contact Email: CATHI@KADONTRUCKING.COM
Contact Country:
County Name: SONOMA
EPA Region: 09
Land Type:
Receive Date: 19931228
Location Latitude: 38.523798
Location Longitude: -122.794745

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19931228
Handler Name: KADON TRUCKING INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Other
Name: KAREN CARPENTER
Date Became Current:
Date Ended Current:
Phone: 707-838-8008
Source Type: Implementer

Street No:
Street 1: 930 SHILOH BLDG #15
Street 2:
City: WINDSOR
State: CA
Country:
Zip Code: 95492-0000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Other	**Street 1:**	930 SHILOH BLDG #15
Name:	KAREN CARPENTER	**Street 2:**	
Date Became Current:		**City:**	WINDSOR
Date Ended Current:		**State:**	CA
Phone:	707-838-8008	**Country:**	
Source Type:	Implementer	**Zip Code:**	95492

30	38 of 45	WNW	0.12 / 657.88	105.61 / -14	ATLAS VINEYARD MANAGEMENT INC 930 SHILOH RD BLDG 17 WINDSOR CA 95492	RCRA TSD

EPA Handler ID:	CAL000444799
Gen Status Universe:	No Report
Contact Name:	MORGAN MARENGO/ ANABEL BALDERAS
Contact Address:	930 SHILOH RD BLDG 17 , , WINDSOR , CA, 95492 ,
Contact Phone No and Ext:	707-478-7928
Contact Email:	MMARENGO@ATLASVM.COM
Contact Country:	
Land Type:	
County Name:	SONOMA
EPA Region:	09
Receive Date:	20190326
Location Latitude:	38.523798
Location Longitude:	-122.794745

Violation/Evaluation Summary

Note:	NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Smelting, Melting and Refining:	No
Underground Injection Control:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20190326
Handler Name:	ATLAS VINEYARD MANAGEMENT INC
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Implementer

Owner/Operator Details

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Other	**Street 1:**	841 LATOUR CT STE A

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Name:	ATLAS VINEYARD MANAGEMENT INC	**Street 2:**	
Date Became Current:		**City:**	NAPA
Date Ended Current:		**State:**	CA
Phone:	707-402-8858	**Country:**	
Source Type:	Implementer	**Zip Code:**	94558
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Other	**Street 1:**	930 SHILOH RD BLDG 17
Name:	MORGAN MARENGO/ ANABEL BALDERAS	**Street 2:**	
Date Became Current:		**City:**	WINDSOR
Date Ended Current:		**State:**	CA
Phone:	707-478-7928	**Country:**	
Source Type:	Implementer	**Zip Code:**	95492

30	*39 of 45*	*WNW*	*0.12 / 657.88*	*105.61 / -14*	***ATLAS VINEYARD MANAGEMENT INC*** ***930 SHILOH RD BLDG 17*** ***WINDSOR CA 95492***	***RCRA NON GEN***

EPA Handler ID:	CAL000444799
Gen Status Universe:	No Report
Contact Name:	MORGAN MARENGO/ ANABEL BALDERAS
Contact Address:	930 SHILOH RD BLDG 17 , , WINDSOR , CA, 95492 ,
Contact Phone No and Ext:	707-478-7928
Contact Email:	MMARENGO@ATLASVM.COM
Contact Country:	
County Name:	SONOMA
EPA Region:	09
Land Type:	
Receive Date:	20190326
Location Latitude:	38.523798
Location Longitude:	-122.794745

Violation/Evaluation Summary

Note:	NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20190326
Handler Name:	ATLAS VINEYARD MANAGEMENT INC
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street 1:***	841 LATOUR CT STE A
Name:	ATLAS VINEYARD MANAGEMENT INC	***Street 2:***	
Date Became Current:		***City:***	NAPA
Date Ended Current:		***State:***	CA
Phone:	707-402-8858	***Country:***	
Source Type:	Implementer	***Zip Code:***	94558

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street 1:***	930 SHILOH RD BLDG 17
Name:	MORGAN MARENGO/ ANABEL BALDERAS	***Street 2:***	
Date Became Current:		***City:***	WINDSOR
Date Ended Current:		***State:***	CA
Phone:	707-478-7928	***Country:***	
Source Type:	Implementer	***Zip Code:***	95492

30	***40 of 45***	***WNW***	***0.12 / 657.88***	***105.61 / -14***	***VIRAMONTES FAMILY GROUP - SHOP*** ***930 SHILOH ROAD YARD 19*** ***WINDSOR CA 95492***	***RCRA SQG***

EPA Handler ID:	CAR000302257
Gen Status Universe:	Small Quantity Generator
Contact Name:	ALEXANDER VIRAMONTES
Contact Address:	930 SHILOH ROAD , YARD 19 , WINDSOR , CA, 95492 , US
Contact Phone No and Ext:	707-657-9638
Contact Email:	ALEX@VFGRP.NET
Contact Country:	US
County Name:	SONOMA
EPA Region:	09
Land Type:	Other
Receive Date:	20191203
Location Latitude:	38.523798
Location Longitude:	-122.794745

Violation/Evaluation Summary

Note:	NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Receive Date: 20191203
Handler Name: VIRAMONTES FAMILY GROUP - SHOP
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: 181
Waste Code Description: Other inorganic solid waste

Hazardous Waste Code: 213
Waste Code Description: Hydrocarbon solvents (benzene, hexane, Stoddard, etc.)

Hazardous Waste Code: U239
Waste Code Description: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Other
Name: JENNIFER VIRAMONTES
Date Became Current: 20161004
Date Ended Current:
Phone: 707-892-2176
Source Type: Notification
Street No:
Street 1: PO BOX 2018
Street 2:
City: WINDSOR
State: CA
Country: US
Zip Code: 95492

Owner/Operator Ind: Current Operator
Type: Other
Name: ALEXANDER VIRAMONTES
Date Became Current: 20161004
Date Ended Current:
Phone: 707-657-9638
Source Type: Notification
Street No:
Street 1: PO BOX 2018
Street 2:
City: WINDSOR
State: CA
Country: US
Zip Code: 95492

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
30	41 of 45	WNW	0.12 / 657.88	105.61 / -14	SHILOH PARK ADAMS ENTERPRIZES 930 SHILOH RD WINDSOR CA	UST SWEEPS

C C: I49-000-1125
BOE: 44-027750
Comp: 1125
Status: INACTIVE
No of Tanks: 1
Jurisdict: SONOMA COUNTY
Agency: ENVIRONMENTAL HEALTH
Phone: (707) 838-7222
D Filename: NSITE5
Page No: 114
County: SONOMA
State : CA
Zip: 95448
Latitude: 38.525714
Longitude: -122.793913
Georesult: S5HPNTSC-A

Tank Details

Tank ID: 000001
O Tank ID:
SWRCB No: 49-000-001125-000001
Removed: 09-27-91
Installed: 01-01-01
A Date:
Capac: 10000
Tank Use: M.V. FUEL
S Contain: NONE
Stg:
Storage : PRODUCT
Storag Type: PRODUCT
P Contain: UNKNOWN
Content: LEADED
ONA:
D File Name: NTANK5

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
30	42 of 45	WNW	0.12 / 657.88	105.61 / -14	ECODYNE POND 930 SHILOH RD WINDSOR CA 95492	CALSITES

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

ID No:	49240001	**Assembly:**	01
Status Date:	05/01/1986	**Senate:**	02
NPL:	N	**Region:**	2
Tier:		**Region Name:**	BERKELEY
Fund:	C	**County Co:**	49
Access :		**Facility County:**	SONOMA
Access Code:	NOT REPORTED	**Lat Deg:**	0
Cortese:		**Lat Min:**	0
Hrscore:		**Lat Sec:**	0
Hrsdate:		**Lat Dir:**	
Groundwater Contam:	C	**Long Deg:**	0
GW Code:	CONTROLLED	**Long Min:**	0
No Sources:	1	**Long Sec:**	0
RWQCB Name:	NORTH COAST	**Long Dir:**	
Branch Name:	NORTH COAST	**LImethod:**	
Staff:	EGILLERA	**LIdesc:**	
Senior:			

Status Name: ANNUAL WORKPLAN - ACTIVE SITE
Type Name: RESPONSIBLE PARTY
Lead Name: DEPT OF TOXIC SUBSTANCES CONTROL
SIC Name: MANU - LUMBER & WOOD PRODUCTS
Filename: ECODYNE POND SITE
Comments:

Background:

The Ecodyne Pond site was used as a drip treatment facility for wood and metal products until the early 1970's. During site operations pentachlorophenol (PCP), creosote and lead were used to treat wood. Chemicals used in the operations were stored in above-ground and below-grade storage tanks. Surface soil has been contaminated with creosote, PCP, dioxin and furan congeners, and lead. Low levels of PCP have also been detected in the groundwater. Most of the site was covered with asphalt. A pilot was conducted to determine the effectiveness on in-situ ozonation to treat PCP and polynuclear aromatic hydrocarbons (PAHs) was conducted. The process involved the injection of ozone gas to chemically oxidize organic compounds such as PCP and PAHs. Results from the study indicated that a successful reduction in PAH and PCP concentrations in both soil and groundwater.Progressive degradation of the contaminants was also observed over a 6-month period. A report regarding the present contaminant levels is pending.

30	43 of 45	WNW	0.12 / 657.88	105.61 / -14	**Shiloh Shop** **930 Shiloh Rd Bldg 17 Windsor, CA 95492** **CA**	CUPA SONOMA

Facility ID: 49-000-008769 **CERS ID:** 10866346

Details

Program Type: HMBP
Permit Status: Active
Expiration Date:
Fee Schedule: Range 2

Details

Program Type: Hazardous Waste
Permit Status: Active
Expiration Date:
Fee Schedule:

Details

Program Type: Stormwater
Permit Status: Active
Expiration Date:
Fee Schedule: Storm Water Permit

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
30	44 of 45	WNW	0.12 / 657.88	105.61 / -14	Shiloh Shop 930 SHILOH RD BLDG 17 WINDSOR CA 95492	CERS HAZ

Site ID: 572944
Latitude: 38.524490
Longitude: -122.795450
County:

Regulated Programs

EI ID: 10866346 **EI Description:** Hazardous Waste Generator

EI ID: 10866346 **EI Description:** Chemical Storage Facilities

Affiliations

Affil Type Desc: CUPA District
Entity Name: Sonoma County Fire Prevention and Hazmat
Entity Title:
Address: 2300 County Center Drive, Suite 220-B
City: Santa Rosa
State: CA
Country:
Zip Code: 95403
Phone: (707) 565-2024

Affil Type Desc: Operator
Entity Name: Atlas Vineyard Management Inc
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone: (707) 402-8870

Affil Type Desc: Parent Corporation
Entity Name: Atlas Vineyard Management
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title:
Address: 930 Shiloh Rd Bldg 17
City: Windsor
State: CA
Country:
Zip Code: 95492
Phone:

Affil Type Desc: Environmental Contact
Entity Name: Annabel Balderas
Entity Title:
Address: 841 Latour Court Suite.A
City: NAPA
State: CA
Country:
Zip Code: 94558
Phone:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Affil Type Desc: Identification Signer
Entity Name: Annabel Balderas
Entity Title: HR & Safety Manager
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Legal Owner
Entity Name: Glenda Sales
Entity Title:
Address: 930 Shiloh Rd
City: Windsor
State: CA
Country: United States
Zip Code: 95492
Phone: (707) 486-6773

Affil Type Desc: Document Preparer
Entity Name: Annabel Balderas
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

30	45 of 45	WNW	0.12 / 657.88	105.61 / -14	Marmon Group Ecodyne/Shiloh Industrial Park 930 Shiloh Road Windsor CA 95492	CDO/CAO

Facility ID: 222151
Facility Type: Industrial
Status:
Status Date:
Place Type: Manufacturing
Place Sub Type: Manufacturing NEC
Agency Type:
No of Agencies:
Program:
No of Programs:
WD ID:
Reg Measure ID:
Region 1:
Order No:
NPDES No Cano:
Major Minor:
NPDES Type:
Reclamation:
Dredge Fill Fee:
A301H:
Effective Date:
Region: 1
Agency Name:
Status 1: Active
Facility Waste Type:
Facility Waste Type 3:
Facility Waste Type 4:
Facility Waste Type 2:
Title: Enforcement - 1B82050OSON Marmon Group Ecodyne/Shiloh Industrial Park
Description: ECODYNE-GROUND WATER CONTAMINATION. ORIGINAL CAO AMENDED BY 84-001 84-002 86-42 87-25 87-137
Threat to Water Quality:

Design Flow:
Complexity:
Pretreatment:
Fee Code:
SIC Code 1: 2879
SIC Desc 1: Pesticides and Agricultural Chemicals, NEC
SIC Code 2: 4952
SIC Desc 2: Sewerage Systems
SIC Code 3:
SIC Desc 3:
NAICS Code 1:
NAICS Desc 1:
NAICS Code 2:
NAICS Desc 2:
NAICS Code 3:
NAICS Desc 3:
No of Places: 1
Staff Assigned:
Place County: Sonoma
Place Latitude: 38.525796
Place Longitude: -122.797272
Source of Facility: Enf Action

Reg Measure Type:	
Program 1:	WDRINDIVSML
No of Programs 1:	1
Enforcement ID EID:	224351
Order Resolution No:	84-100
Enforcement Action Type:	Clean-up and Abatement Order
Effective Date 1:	08/15/84 00:00:00
Year Effective:	
Adoption Issuance Date:	
Achieve Date:	
Year Effective2:	
ACL Issuance Date:	
EPL Issuance Date:	
Latest Milestone Completion Da:	02/02/87 00:00:00
Total Assessment Amount:	0
Initial Assessed Amount:	0
Liability Amount:	0
Project Amount:	0
Application Fee Amt Received:	
Liability Paid:	0
Project Completed:	0
Total Paid Completed Amount:	0
Agency Issuing Enf:	
Date of Oldest Violation Linke:	
Rank 1 Violations:	0
Rank 2 Violations:	0
Rank 3 Violations:	0
Unclassified Violations:	0
Atox Violations No:	0
Expiration Review Date:	
Termination Date:	
WDR Review Amend:	
WDR Review Revise Renew:	
WDR Review Resc Ind:	
WDR Review No Action Required:	
WDR Review Pending:	
WDR Review Planned:	
Status Enrollee:	
Individual General:	
No of Staff Assigned:	
Supervisor:	
No of Supervisors:	
Direction Voice:	
Region 2:	1
Assigned Staff:	
No of Assigned Staff:	
Supervisor2:	
No of Supervisors 1:	

Program Category:		**Tot No of VIO Linked :**	0
Program Category 1:	WDR	**Ctox Violations No:**	0
Late Report VIO No:	0	**Dfcnt Monitor VIO No:**	0
OEV VIO No:	0	**Dfcnt Report VIO No:**	0
Other Codes VIO No:	0	**Enfcmt Act VIO No:**	0
Permit Condit VIO No:	0	**Fees Violations No:**	0
Pretreatment VIO No:	0	**Groundwater VIO No:**	0
SSO Violations No:	0	**Hydro Mod VIO No:**	0
Surface Wtr VIO No:	0	**Effluent MMP Serious:**	0
SWPPP Violations No:	0	**Chronic MMP:**	0
Total MMP VIO No:	0	**Report MMP Serious:**	0
Priority Violations:	0	**Economic Benefit:**	
BMP Violations No:	0	**Staff Cost:**	
Cat1 Violations No:	0	**Max Pot Liability:**	
Cat2 Violations No:	0	**Termination Date 1:**	
Reporting F To Notify VIO No:	0		
Unauthorized Discharge VIO No:	0		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Basin Plan Prohibition VIO:	0					
31	1 of 1	WNW	0.13 / 664.31	113.09 / -7	Batt's Tip Top Tree Service 584 Caletti Av WINDSOR, CA 95492 CA	DELISTED COUNTY

Original Source Facility ID:
Original Source Name: Sonoma County CUPA Facilities List
Record Date: 11-JAN-2016

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
32	1 of 1	WNW	0.13 / 672.42	113.09 / -7	Alan Precision & Dive Shop 580 Caletti Av WINDSOR, CA 95492 CA	DELISTED COUNTY

Original Source Facility ID:
Original Source Name: Sonoma County CUPA Facilities List
Record Date: 11-JAN-2016

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
33	1 of 1	NNW	0.13 / 702.92	118.63 / -1	O'REILLY AUTO PARTS #3553 6500 HEMBREE LN # 109 WINDSOR CA 95492-6882	RCRA NON GEN

EPA Handler ID: CAL000393254
Gen Status Universe: No Report
Contact Name: JOHN BOUNDS
Contact Address: 233 S. PATTERSON AVE. , , SPRINGFIELD , MO, 65802 ,
Contact Phone No and Ext: 417-520-4589
Contact Email: JBOUNDS2@OREILLYAUTO.COM
Contact Country:
County Name: SONOMA
EPA Region: 09
Land Type:
Receive Date: 20140121
Location Latitude: 38.526364
Location Longitude: -122.789115

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20140121
Handler Name: O'REILLY AUTO PARTS #3553
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Other
Name: O'REILLY AUTO PARTS
Date Became Current:
Date Ended Current:
Phone: 417-862-3333
Source Type: Implementer
Street No:
Street 1: 233 S PATTERSON
Street 2:
City: SPRINGFIELD
State: MO
Country:
Zip Code: 65802-0000

Owner/Operator Ind: Current Operator
Type: Other
Name: JOHN BOUNDS
Date Became Current:
Date Ended Current:
Phone: 417-520-4589
Source Type: Implementer
Street No:
Street 1: 233 S. PATTERSON AVE.
Street 2:
City: SPRINGFIELD
State: MO
Country:
Zip Code: 65802

34	1 of 1	WNW	0.13 / 712.39	113.41 / -7	WMTF 586 Caletti Ave Windsor CA 95492	SWF/LF

SWIS No: 49-AA-0430
EPA Fed Registry ID:
Operational Status: Active
Regulatory Status: Notification
Site is Archived: No
Absorbed on:
Absorbed by:
Site Inert Debris Eng Fill: No
Closed Illegal Aband: No
Closed Illegal Aband Cat:
Finance Assuran Responsible: No
Incorporated City: Windsor
Local Government: Windsor
Reporting Agency Legal Name: County of Sonoma
Reporting Agency Department: Department of Health Services, Environmental Health & Safety Section
Enforcing Agency Legal Name: County of Sonoma
Enforcing Agency Department: Department of Health Services, Environmental Health & Safety Section
Latitude: 38.52122
Longitude: -122.79294
County: Sonoma
Site ZIP: 95492
ARB District: Bay Area
SWRCB Region: North Coast
Site Point of Contact: Alyssa Williams

Site Owners

Site Type: Non-Disposal Only
Owner Name: N. E. W. Shiloh, LLC
Owner Address: 1060 N. Dutton Ave.
Owner City: Santa Rosa
Owner State: CA
Owner ZIP Code: 95407
Owner Phone:
Contact Name:
Contact First Name:
Contact Last Name:
Contact Title:
Contact Email:
Started On:

Site Activities (Search Result)

ID: 5317
Act Opl Status: Active
Site Name: WMTF
Act Regulatory Stat: Notification
Activity Category: Transfer/Processing

Activity: Limited Volume Transfer Operation

Site Operators

Site Type:	Non-Disposal Only	***Is Archived:***	No
Operator Name:	M&M Services	***Contact Name:***	Dustin Abbott
Operator Address:	590 Caletti Ave	***Contact First Name:***	Dustin
Operator City:	Windsor	***Contact Last Name:***	Abbott
Operator State:	CA	***Contact Title:***	
Operator ZIP Code:	95492	***Contact Email:***	
Operator Phone:	(707) 838-2597	***Started on:***	

Site Waste

Site Type:	Non-Disposal Only	***Activity Category:***	Transfer/Processing
Waste Type:	Green Materials	***Act Classification:***	Solid Waste Operation
Activity Oper Status:	Active	***Activity Is Archived:***	No
Act Regulatory Stat:	Notification		
Activity:	Limited Volume Transfer Operation		

Site Type:	Non-Disposal Only	***Activity Category:***	Transfer/Processing
Waste Type:	Other designated	***Act Classification:***	Solid Waste Operation
Activity Oper Status:	Active	***Activity Is Archived:***	No
Act Regulatory Stat:	Notification		
Activity:	Limited Volume Transfer Operation		

Site Type:	Non-Disposal Only	***Activity Category:***	Transfer/Processing
Waste Type:	Mixed municipal	***Act Classification:***	Solid Waste Operation
Activity Oper Status:	Active	***Activity Is Archived:***	No
Act Regulatory Stat:	Notification		
Activity:	Limited Volume Transfer Operation		

Extra Details

Enforcement Agency (LEA/EA): Sonoma County

Site Activities (Export)

WDR No:		***Remaining Capacity:***	
WDR Landfill Class:		***Remaining Cap Dt:***	
Act is Archived:	No	***Max Permit Cap:***	4961
Act Opl Status:	Active	***Capacity UOM:***	Tons per year
Act Regulatory Stat:	Notification	***Total Acreage:***	0.00
Activity Category:	Transfer/Processing	***Disposal Acreage:***	
Act Classification:	Solid Waste Operation	***Permitted Elev :***	
Cease Operation:		***Permitted Elev Tp:***	
Cease Operation Tp:		***Permitted Depth:***	
Insp Frequency:	Quarterly	***Permitted Depth Tp:***	
Incorporated City:	Windsor	***Site Name:***	WMTF
Site Point of Contact:	Alyssa Williams		
Activity:	Limited Volume Transfer Operation		
Max Permitted Throughput:	15		
Throughput UOM:	Tons per day		

35	*1 of 6*	*WNW*	*0.14 / 727.67*	*113.39 / -7*	***M&M Services, Inc 590 Caletti Ave Windsor, CA 95492 CA***	***CUPA SONOMA***

Facility ID: 49-000-006996 ***CERS ID:*** 10129585

Details

Program Type: Stormwater
Permit Status: Active
Expiration Date: 11/12/2023
Fee Schedule: Storm Water Permit

Details

Program Type: Hazardous Waste
Permit Status: Active
Expiration Date: 11/12/2023
Fee Schedule: Waste Oil Only > 5 tons/year

Details

Program Type: HMBP
Permit Status: Active
Expiration Date: 11/12/2023
Fee Schedule: Range 2

---

35 | ***2 of 6*** | ***WNW*** | ***0.14 / 727.67*** | ***113.39 / -7*** | ***Windsor Material Recovery Facility***
590 Caletti Avenue
Windsor CA 95492 | ***SWF/LF***

SWIS No: 49-AA-0398
EPA Fed Registry ID:
Operational Status: Active
Regulatory Status: Permitted
Site is Archived: No
Absorbed on:
Absorbed by:
Site Inert Debris Eng Fill: No
Closed Illegal Aband: No
Closed Illegal Aband Cat:
Finance Assuran Responsible: No
Incorporated City: Windsor
Local Government: Windsor
Reporting Agency Legal Name: County of Sonoma
Reporting Agency Department: Department of Health Services, Environmental Health & Safety Section
Enforcing Agency Legal Name: County of Sonoma
Enforcing Agency Department: Department of Health Services, Environmental Health & Safety Section

Latitude: 38.52138
Longitude: -122.79234
County: Sonoma
Site ZIP: 95492
ARB District: Bay Area
SWRCB Region: North Coast
Site Point of Contact: Alyssa Williams

Site Owners

Site Type: Non-Disposal Only
Owner Name: N. E. W. Shiloh, LLC
Owner Address: 1060 N. Dutton Ave.
Owner City: Santa Rosa
Owner State: CA
Owner ZIP Code: 95407
Owner Phone:

Contact Name:
Contact First Name:
Contact Last Name:
Contact Title:
Contact Email:
Started On:

Site Activities (Search Result)

ID: 5983
Act Opl Status: Active
Site Name: Windsor Material Recovery Facility
Activity: Medium Volume CDI Debris Processing Facility

Act Regulatory Stat: Permitted
Activity Category: Transfer/Processing

Site Operators

Site Type: Non-Disposal Only
Operator Name: M&M Services

Is Archived: No
Contact Name: Dustin Abbott

Operator Address:	590 Caletti Ave	**Contact First Name:**	Dustin
Operator City:	Windsor	**Contact Last Name:**	Abbott
Operator State:	CA	**Contact Title:**	
Operator ZIP Code:	95492	**Contact Email:**	
Operator Phone:	(707) 838-2597	**Started on:**	

Site Waste

Site Type:	Non-Disposal Only	**Activity Category:**	Transfer/Processing
Waste Type:	Inert	**Act Classification:**	Solid Waste Facility
Activity Oper Status:	Active	**Activity Is Archived:**	No
Act Regulatory Stat:	Permitted		
Activity:	Medium Volume CDI Debris Processing Facility		

Site Type:	Non-Disposal Only	**Activity Category:**	Transfer/Processing
Waste Type:	Construction/demolition	**Act Classification:**	Solid Waste Facility
Activity Oper Status:	Active	**Activity Is Archived:**	No
Act Regulatory Stat:	Permitted		
Activity:	Medium Volume CDI Debris Processing Facility		

Extra Details

Enforcement Agency (LEA/EA): Sonoma County

Site Activities (Export)

WDR No:		**Remaining Capacity:**	
WDR Landfill Class:		**Remaining Cap Dt:**	
Act is Archived:	No	**Max Permit Cap:**	54600
Act Opl Status:	Active	**Capacity UOM:**	Tons per year
Act Regulatory Stat:	Permitted	**Total Acreage:**	2.00
Activity Category:	Transfer/Processing	**Disposal Acreage:**	
Act Classification:	Solid Waste Facility	**Permitted Elev :**	
Cease Operation:		**Permitted Elev Tp:**	
Cease Operation Tp:		**Permitted Depth:**	
Insp Frequency:	Monthly	**Permitted Depth Tp:**	
Incorporated City:	Windsor	**Site Name:**	Windsor Material Recovery Facility
Site Point of Contact:	Alyssa Williams		
Activity:	Medium Volume CDI Debris Processing Facility		
Max Permitted Throughput:	175		
Throughput UOM:	Tons per day		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
35	3 of 6	WNW	0.14 / 727.67	113.39 / -7	CALETTI AVE 590 CALETTI AVE WINDSOR CA 95492	VCP

Estor/EPA ID:	60001813	**Permit Renewal Lead:**	
Site Code:	201951, 202212, 202301, 202318	**Project Manager:**	ISABELLA ROMAN
Nat Priority List:	NO	**Supervisor:**	KIMBERLY WALSH
Acres:	13.57 ACRES	**Public Partici Spclst:**	
Special Program:		**Census Tract:**	6097152702
Funding:	NOT APPLICABLE	**County:**	SONOMA
Assembly District:	01, 02	**Latitude:**	38.522108
Senate District:	02	**Longitude:**	-122.792304
School District:			
APN:	059271103		
Cleanup Status:	ACTIVE AS OF 9/25/2018		
Cleanup Oversight Agencies:	DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY		
Site Type:	VOLUNTARY CLEANUP		
Office:	CLEANUP BERKELEY		
Past Use that Caused Contam:	MANUFACTURING - LUMBER/WOOD PRODUCTS		
Potential Media Affected:	SOIL		
Potential Contamin of Concern:			

ARSENIC

LEAD

Site History:

The Caletti Site is located on Caletti Avenue in the Shiloh Business Park in the City of Windsor, Sonoma County. The site (APN 059-271-103) includes the following addresses: 510, 590, 610, 650, and 660 Caletti Avenue (Figure 1). The 13.57 acre property is generally flat and bounded by Caletti Avenue west of the site, Pruitt Avenue to the north and the Standard Structures facility to the east. A trucking company is located south of the site. The site is occupied by several industrial and commercial businesses including: a truck repair shop; stainless steel tank manufacture; a mobile home and earthquake bracing manufacture; a trailer storage facility; a construction material recycler; and a metals recycler.

Prior to 1952, the date of the oldest air photo, the property was open range. The 1957 oblique air photo shows a lumber mill with two teepee burners operating on the property. From the late 1950s through 1980, the site was part of a larger lumber mill operations. The 1980 air photo shows the buildings and teepee burners. The surrounding area appears vacant and remainder of the site is free from lumber. The site is now part of Shiloh Road Industrial Park and includes several industrial and commercial uses.

DTSC, The Shiloh Road LLC and Fluor entered into a Voluntary Cleanup Agreement (VCA) in September 2018 with the intent of completing a Preliminary Endangerment Assessment for the site. A VCA Amendment was signed in 2020 for the current RPs (Bodean Company and Fluor). The PEA Report was finalized with the recommendation to conduct a mercury investigation. The Work Plan for this mercury investigation is currently under review. -Updated 8/2021 IR

Status: ACTIVE
Program Type: VOLUNTARY CLEANUP
CalEnviroScreen Score: 46-50%
Summary Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=60001813

Future Activities

Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Site Characterization Report
Due Date: 2022

Completed Activities

Title: Voluntary Cleanup Agreement
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60001813&enforcement_id=60405707
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Standard Voluntary Agreement
Date Completed: 8/31/2018
Comments:

Title: VCA Invite Letter to Caletti Property Owner
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60001813&enforcement_id=60380978
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 9/10/2014
Comments: Letter inviting The Shiloh Road LLC to enter into a Voluntary Cleanup Agreement letter to investigation whether a release has occurred at the site.

Title: Request for Agency Oversight Application for Prospective Purchaser Agreement
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60001813&doc_id=60476021
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Application
Date Completed: 2/21/2020
Comments: Application for entering into a Prospective Purchaser Agreement between Bodean Company and DTSC.

Title: Annual Oversight Cost Estimate FY 2019-2020
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60001813&enforcement_id=60465140
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 12/16/2019
Comments: Annual cost estimate letter projecting costs for DTSC oversight during fiscal year 2019-2020.

Title: Annual Cost Estimate (Fiscal Year 2020-2021)
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60001813&enforcement_id=60483507
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 9/29/2020
Comments: Annual cost estimate letter projecting costs for DTSC oversight during fiscal year 2020-2021.

Title: letter from Shiloh Road LLC lawyer re: Information Request
Title Link: https://www.envirostor.dtsc.ca.gov/public/
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 1/23/2013
Comments: Letter responded to Shilo Road LLC inquiry regarding complaint recieved by DTSC.

Title: Site Screening Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60001813&doc_id=60311840
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Site Screening
Date Completed: 6/30/2014
Comments: Site assessment recommends additional investigation and completion of Preliminary Endangerment Assessment

Title: Information Request Letter
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60001813&enforcement_id=60313286
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Letter - Notice
Date Completed: 1/3/2013
Comments: letters sent to three addressees

Title: Letter Response: Information Request Property on Caletti Response from Shiloh Road LLC
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60001813&doc_id=60319478
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 4/5/2013
Comments: 10 day letter from Ann Carroll, DTSC attorney to requester

Title: PEA Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60001813&doc_id=60453361
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Preliminary Endangerment Assessment Report
Date Completed: 4/27/2021

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Comments: PEA Report was approved. The PEA Report recommended to conduct a mercury investigation at select locations at the site that exhibited higher concentrations in groundwater samples.

Title: VCA Amendment
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60001813&enforcement_id=60479678
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Amendment - Order/Agreement
Date Completed: 10/7/2020
Comments: VCA Amendment executed to capture the change in ownership from Shiloh Road to N.E.W. Shiloh. N.E.W. Shiloh and Fluor are the current responsible parties.

Title: DTSC Site Visit and Sampling Report at Caletti Property September 26, 2014
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60001813&doc_id=60405022
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 10/11/2014
Comments:

Title: Change of Project Manager Letter
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60001813&enforcement_id=60453436
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 10/18/2018
Comments: Letter for notification of new project manager for DTSC oversight of the site.

Title: Phase 1 Environmental Site Assessment
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60001813&doc_id=60476336
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Phase 1
Date Completed: 1/30/2017
Comments:

Title: PEA Workplan
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60001813&doc_id=60453359
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Preliminary Endangerment Assessment Workplan
Date Completed: 4/29/2019
Comments: Completed Preliminary Endangerment Assessment Workplan to investigate areas where releases of hazardous substances may have occured.

Title: Annual Cost Estimate (Fiscal Year 2021-2022)
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60001813&enforcement_id=60502287
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 8/24/2021
Comments: Letter notifying RP of projected costs for DTSC oversight over fiscal year 2021-2022.

35	4 of 6	WNW	0.14 / 727.67	113.39 / -7	CALETTI AVE 590 CALETTI AVE WINDSOR CA 95492	ENVIROSTOR

Estor/EPA ID:	60001813	***Assembly District:***	01, 02
Site Code:	201951, 202212, 202301, 202318	***Senate District:***	02
Nat Priority List:	NO	***Permit Renewal Lead:***	
APN:	059271103	***Public Partici Spclst:***	
Census Tract:	6097152702	***Project Manager:***	ISABELLA ROMAN
Site Type:	VOLUNTARY CLEANUP	***County:***	SONOMA
Address Description:	590 CALETTI AVE	***Latitude:***	38.522108
Office:	CLEANUP BERKELEY	***Longitude:***	-122.792304
Special Program:		***Acres:***	13.57 ACRES
Funding:	NOT APPLICABLE	***Supervisor:***	KIMBERLY WALSH

Cleanup Status: ACTIVE AS OF 9/25/2018
Cleanup Oversight Agencies: DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY
School District:
Past Use that Caused Contam: MANUFACTURING - LUMBER/WOOD PRODUCTS
Potential Media Affected: SOIL
Potential Contamin of Concern:

ARSENIC
LEAD

Site History:

The Caletti Site is located on Caletti Avenue in the Shiloh Business Park in the City of Windsor, Sonoma County. The site (APN 059-271-103) includes the following addresses: 510, 590, 610, 650, and 660 Caletti Avenue (Figure 1). The 13.57 acre property is generally flat and bounded by Caletti Avenue west of the site, Pruitt Avenue to the north and the Standard Structures facility to the east. A trucking company is located south of the site. The site is occupied by several industrial and commercial businesses including: a truck repair shop; stainless steel tank manufacture; a mobile home and earthquake bracing manufacture; a trailer storage facility; a construction material recycler; and a metals recycler.

Prior to 1952, the date of the oldest air photo, the property was open range. The 1957 oblique air photo shows a lumber mill with two teepee burners operating on the property. From the late 1950s through 1980, the site was part of a larger lumber mill operations. The 1980 air photo shows the buildings and teepee burners. The surrounding area appears vacant and remainder of the site is free from lumber. The site is now part of Shiloh Road Industrial Park and includes several industrial and commercial uses.

DTSC, The Shiloh Road LLC and Fluor entered into a Voluntary Cleanup Agreement (VCA) in September 2018 with the intent of completing a Preliminary Endangerment Assessment for the site. A VCA Amendment was signed in 2020 for the current RPs (Bodean Company and Fluor). The PEA Report was finalized with the recommendation to conduct a mercury investigation. The Work Plan for this mercury investigation is currently under review. -Updated 8/2021 IR

Status: ACTIVE
Program Type: VOLUNTARY CLEANUP
CalEnviroScreen Score: 46-50%
Summary Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=60001813

Future Activities

Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Site Characterization Report
Due Date: 2022

Completed Activities

Title: Voluntary Cleanup Agreement
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60001813&enforcement_id=60405707
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Standard Voluntary Agreement
Date Completed: 8/31/2018
Comments:

Title: Site Screening Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60001813&doc_id=60311840

Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Site Screening
Date Completed: 6/30/2014
Comments: Site assessment recommends additional investigation and completion of Preliminary Endangerment Assessment

Title: Information Request Letter
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60001813&enforcement_id=60313286
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Letter - Notice
Date Completed: 1/3/2013
Comments: letters sent to three addressees

Title: Annual Cost Estimate (Fiscal Year 2020-2021)
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60001813&enforcement_id=60483507
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 9/29/2020
Comments: Annual cost estimate letter projecting costs for DTSC oversight during fiscal year 2020-2021.

Title: Phase 1 Environmental Site Assessment
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60001813&doc_id=60476336
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Phase 1
Date Completed: 1/30/2017
Comments:

Title: Annual Cost Estimate (Fiscal Year 2021-2022)
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60001813&enforcement_id=60502287
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 8/24/2021
Comments: Letter notifying RP of projected costs for DTSC oversight over fiscal year 2021-2022.

Title: PEA Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60001813&doc_id=60453361
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Preliminary Endangerment Assessment Report
Date Completed: 4/27/2021
Comments: PEA Report was approved. The PEA Report recommended to conduct a mercury investigation at select locations at the site that exhibited higher concentrations in groundwater samples.

Title: Request for Agency Oversight Application for Prospective Purchaser Agreement
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60001813&doc_id=60476021
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Application
Date Completed: 2/21/2020
Comments: Application for entering into a Prospective Purchaser Agreement between Bodean Company and DTSC.

Title: PEA Workplan
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60001813&doc_id=60453359
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Preliminary Endangerment Assessment Workplan
Date Completed: 4/29/2019
Comments: Completed Preliminary Endangerment Assessment Workplan to investigate areas where releases of hazardous substances may have occured.

Title: Change of Project Manager Letter
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60001813&enforcement_id=60453436
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 10/18/2018
Comments: Letter for notification of new project manager for DTSC oversight of the site.

Title: VCA Invite Letter to Caletti Property Owner
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60001813&enforcement_id=60380978
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 9/10/2014
Comments: Letter inviting The Shiloh Road LLC to enter into a Voluntary Cleanup Agreement letter to investigation whether a release has occurred at the site.

Title: Letter Response: Information Request Property on Caletti Response from Shiloh Road LLC
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60001813&doc_id=60319478
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 4/5/2013
Comments: 10 day letter from Ann Carroll, DTSC attorney to requester

Title: letter from Shiloh Road LLC lawyer re: Information Request
Title Link: https://www.envirostor.dtsc.ca.gov/public/
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 1/23/2013
Comments: Letter responded to Shilo Road LLC inquiry regarding complaint recieved by DTSC.

Title: VCA Amendment
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60001813&enforcement_id=60479678
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Amendment - Order/Agreement
Date Completed: 10/7/2020
Comments: VCA Amendment executed to capture the change in ownership from Shiloh Road to N.E.W. Shiloh. N.E.W. Shiloh and Fluor are the current responsible parties.

Title: Annual Oversight Cost Estimate FY 2019-2020
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60001813&enforcement_id=60465140
Area Name:
Area Link:
Sub Area:
Sub Area Link:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Document Type: Annual Oversight Cost Estimate
Date Completed: 12/16/2019
Comments: Annual cost estimate letter projecting costs for DTSC oversight during fiscal year 2019-2020.

Title: DTSC Site Visit and Sampling Report at Caletti Property September 26, 2014
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=60001813&doc_id=60405022
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 10/11/2014
Comments:

35	5 of 6	WNW	0.14 / 727.67	113.39 / -7	M & M SERVICES 590 CALETTI AVE WINDSOR CA 95492-8768	RCRA NON GEN

EPA Handler ID: CAL000257159
Gen Status Universe: No Report
Contact Name: DUSTIN ABBOT
Contact Address: 590 CALETTI AVENUE , , WINDSOR , CA, 95492 ,
Contact Phone No and Ext: 707-838-2597
Contact Email: INFO@PACIFICSANITATION.COM
Contact Country:
County Name: SONOMA
EPA Region: 09
Land Type:
Receive Date: 20020806
Location Latitude: 38.523071
Location Longitude: -122.793159

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20020806
Handler Name: M & M SERVICES
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street 1:***	590 CALETTI AVENUE
Name:	M & M SERVICES INC	***Street 2:***	
Date Became Current:		***City:***	WINDSOR
Date Ended Current:		***State:***	CA
Phone:	707-838-2597	***Country:***	
Source Type:	Implementer	***Zip Code:***	95492-0000
Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street 1:***	590 CALETTI AVENUE
Name:	DUSTIN ABBOT	***Street 2:***	
Date Became Current:		***City:***	WINDSOR
Date Ended Current:		***State:***	CA
Phone:	707-838-2597	***Country:***	
Source Type:	Implementer	***Zip Code:***	95492

35	*6 of 6*	*WNW*	*0.14 / 727.67*	*113.39 / -7*	***M AND M SERVICES INC 590 CALETTI AVE WINDSOR CA 95492***	***C&D DEBRIS RECY***

County:	SONOMA
Activity Type:	C&D PROCESSING
Phone No:	(707) 838-2597

36	*1 of 4*	*NNW*	*0.14 / 762.06*	*112.82 / -7*	***WALMART #2553 6650 HEMBREE LN WINDSOR CA 95492***	***RCRA SQG***

EPA Handler ID:	CAR000205708
Gen Status Universe:	Small Quantity Generator
Contact Name:	ROSE ARNOLD
Contact Address:	PO BOX 8041 , , BENTONVILLE , AR, 72712-8041 , US
Contact Phone No and Ext:	479-277-8972
Contact Email:	ROSE.ARNOLD@WALMART.COM
Contact Country:	US
County Name:	SONOMA
EPA Region:	09
Land Type:	Private
Receive Date:	20160620
Location Latitude:	38.540607
Location Longitude:	-122.798021

Violation/Evaluation Summary

Note:	NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No

Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20100308
Handler Name: WALMART NO 2553
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: D004
Waste Code Description: ARSENIC

Hazardous Waste Code: D005
Waste Code Description: BARIUM

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: D016
Waste Code Description: 2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D022
Waste Code Description: CHLOROFORM

Hazardous Waste Code: D026
Waste Code Description: CRESOL

Hazardous Waste Code: D027
Waste Code Description: 1,4-DICHLOROBENZENE

Hazardous Waste Code: D035
Waste Code Description: METHYL ETHYL KETONE

Hazardous Waste Code: D039
Waste Code Description: TETRACHLOROETHYLENE

Hazardous Waste Code: P001
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Hazardous Waste Code: P046
Waste Code Description: ALPHA,ALPHA-DIMETHYLPHENETHYLAMINE (OR) BENZENEETHANAMINE, ALPHA, ALPHA-DIMETHYL-

Hazardous Waste Code: P075
Waste Code Description: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Hazardous Waste Code: U002
Waste Code Description: 2-PROPANONE (I) (OR) ACETONE (I)

Hazardous Waste Code: U034
Waste Code Description: ACETALDEHYDE, TRICHLORO- (OR) CHLORAL

Hazardous Waste Code: U072
Waste Code Description: BENZENE, 1,4-DICHLORO- (OR) P-DICHLOROBENZENE

Hazardous Waste Code: U080
Waste Code Description: METHANE, DICHLORO- (OR) METHYLENE CHLORIDE

Hazardous Waste Code: U154
Waste Code Description: METHANOL (I) (OR) METHYL ALCOHOL (I)

Hazardous Waste Code: U159
Waste Code Description: 2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)

Hazardous Waste Code: U165
Waste Code Description: NAPHTHALENE

Hazardous Waste Code: U182
Waste Code Description: 1,3,5-TRIOXANE, 2,4,6-TRIMETHYL- (OR) PARALDEHYDE

Hazardous Waste Code: U188
Waste Code Description: PHENOL

Hazardous Waste Code: U249
Waste Code Description: ZINC PHOSPHIDE ZN3P2, WHEN PRESENT AT CONCENTRATIONS OF 10% OR LESS

Hazardous Waste Code: U279
Waste Code Description: CARBARYL (OR) 1-NAPHTHALENOL, METHYLCARBAMATE

Hazardous Waste Code: U409
Waste Code Description: CARBAMIC ACID, [1,2-PHENYLENEBIS (IMINOCARBONOTHIOYL)]BIS-, DIMETHYL ESTER (OR) THIOPHANATE-METHYL

Hazardous Waste Code: U411
Waste Code Description: PHENOL, 2-(1-METHYLETHOXY)-, METHYLCARBAMATE (OR) PROPOXUR

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20110627
Handler Name: WALMART NO 2553
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: 122
Waste Code Description: Alkaline solution without metals (pH > 12.5)

Hazardous Waste Code: 135

Waste Code Description: Unspecified aqueous solution

Hazardous Waste Code: 141
Waste Code Description: Off-specification, aged, or surplus inorganics

Hazardous Waste Code: 181
Waste Code Description: Other inorganic solid waste

Hazardous Waste Code: 212
Waste Code Description: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)

Hazardous Waste Code: 213
Waste Code Description: Hydrocarbon solvents (benzene, hexane, Stoddard, etc.)

Hazardous Waste Code: 214
Waste Code Description: Unspecified solvent mixture

Hazardous Waste Code: 221
Waste Code Description: Waste oil and mixed oil

Hazardous Waste Code: 223
Waste Code Description: Unspecified oil-containing waste

Hazardous Waste Code: 232
Waste Code Description: Pesticides and other waste associated with pesticide production

Hazardous Waste Code: 281
Waste Code Description: Adhesives

Hazardous Waste Code: 291
Waste Code Description: Latex waste

Hazardous Waste Code: 311
Waste Code Description: Pharmaceutical waste

Hazardous Waste Code: 331
Waste Code Description: Off-specification, aged, or surplus organics

Hazardous Waste Code: 343
Waste Code Description: Unspecified organic liquid mixture

Hazardous Waste Code: 352
Waste Code Description: Other organic solids

Hazardous Waste Code: 561
Waste Code Description: Detergent and soap

Hazardous Waste Code: 791
Waste Code Description: Liquids with pH < 2

Hazardous Waste Code: 792
Waste Code Description: Liquids with pH < 2 with metals

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: D004
Waste Code Description: ARSENIC

Hazardous Waste Code: D005
Waste Code Description: BARIUM

Hazardous Waste Code: D006

Waste Code Description:	CADMIUM
Hazardous Waste Code:	D007
Waste Code Description:	CHROMIUM
Hazardous Waste Code:	D008
Waste Code Description:	LEAD
Hazardous Waste Code:	D009
Waste Code Description:	MERCURY
Hazardous Waste Code:	D010
Waste Code Description:	SELENIUM
Hazardous Waste Code:	D011
Waste Code Description:	SILVER
Hazardous Waste Code:	D016
Waste Code Description:	2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)
Hazardous Waste Code:	D018
Waste Code Description:	BENZENE
Hazardous Waste Code:	D022
Waste Code Description:	CHLOROFORM
Hazardous Waste Code:	D024
Waste Code Description:	M-CRESOL
Hazardous Waste Code:	D026
Waste Code Description:	CRESOL
Hazardous Waste Code:	D027
Waste Code Description:	1,4-DICHLOROBENZENE
Hazardous Waste Code:	D035
Waste Code Description:	METHYL ETHYL KETONE
Hazardous Waste Code:	D039
Waste Code Description:	TETRACHLOROETHYLENE
Hazardous Waste Code:	P001
Waste Code Description:	2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%
Hazardous Waste Code:	P075
Waste Code Description:	NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS
Hazardous Waste Code:	U002
Waste Code Description:	2-PROPANONE (I) (OR) ACETONE (I)
Hazardous Waste Code:	U034
Waste Code Description:	ACETALDEHYDE, TRICHLORO- (OR) CHLORAL
Hazardous Waste Code:	U035
Waste Code Description:	BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL
Hazardous Waste Code:	U058
Waste Code Description:	2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE
Hazardous Waste Code:	U072
Waste Code Description:	BENZENE, 1,4-DICHLORO- (OR) P-DICHLOROBENZENE
Hazardous Waste Code:	U080
Waste Code Description:	METHANE, DICHLORO- (OR) METHYLENE CHLORIDE
Hazardous Waste Code:	U122

Waste Code Description: FORMALDEHYDE

Hazardous Waste Code: U129
Waste Code Description: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA, 2ALPHA, 3BETA, 4ALPHA, 5ALPHA, 6BETA)- (OR) LINDANE

Hazardous Waste Code: U132
Waste Code Description: HEXACHLOROPHENE (OR) PHENOL, 2,2'-METHYLENEBIS[3,4,6-TRICHLORO-

Hazardous Waste Code: U150
Waste Code Description: L-PHENYLALANINE, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) MELPHALAN

Hazardous Waste Code: U154
Waste Code Description: METHANOL (I) (OR) METHYL ALCOHOL (I)

Hazardous Waste Code: U159
Waste Code Description: 2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)

Hazardous Waste Code: U165
Waste Code Description: NAPHTHALENE

Hazardous Waste Code: U182
Waste Code Description: 1,3,5-TRIOXANE, 2,4,6-TRIMETHYL- (OR) PARALDEHYDE

Hazardous Waste Code: U188
Waste Code Description: PHENOL

Hazardous Waste Code: U200
Waste Code Description: RESERPINE (OR) YOHIMBAN-16-CARBOXYLIC ACID, 11,17-DIMETHOXY-18-[(3,4,5-TRIMETHOXYBENZOYL) OXY]-, METHYL ESTER, (3BETA, 16BETA, 17ALPHA, 18BETA, 20ALPHA)-

Hazardous Waste Code: U205
Waste Code Description: SELENIUM SULFIDE (OR) SELENIUM SULFIDE SES2 (R,T)

Hazardous Waste Code: U248
Waste Code Description: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYL-BUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS OF 0.3% OR LESS (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS OF 0.3% OR LESS

Hazardous Waste Code: U249
Waste Code Description: ZINC PHOSPHIDE ZN3P2, WHEN PRESENT AT CONCENTRATIONS OF 10% OR LESS

Hazardous Waste Code: U279
Waste Code Description: CARBARYL (OR) 1-NAPHTHALENOL, METHYLCARBAMATE

Hazardous Waste Code: U409
Waste Code Description: CARBAMIC ACID, [1,2-PHENYLENEBIS (IMINOCARBONOTHIOYL)]BIS-, DIMETHYL ESTER (OR) THIOPHANATE-METHYL

Hazardous Waste Code: U411
Waste Code Description: PHENOL, 2-(1-METHYLETHOXY)-, METHYLCARBAMATE (OR) PROPOXUR

Hazardous Waste Handler Details

Sequence No: 3
Receive Date: 20141028
Handler Name: WALMART NO 2553
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: 122
Waste Code Description: Alkaline solution without metals (pH > 12.5)

Hazardous Waste Code: 141

Waste Code Description: Off-specification, aged, or surplus inorganics

Hazardous Waste Code: 181
Waste Code Description: Other inorganic solid waste

Hazardous Waste Code: 213
Waste Code Description: Hydrocarbon solvents (benzene, hexane, Stoddard, etc.)

Hazardous Waste Code: 214
Waste Code Description: Unspecified solvent mixture

Hazardous Waste Code: 221
Waste Code Description: Waste oil and mixed oil

Hazardous Waste Code: 232
Waste Code Description: Pesticides and other waste associated with pesticide production

Hazardous Waste Code: 311
Waste Code Description: Pharmaceutical waste

Hazardous Waste Code: 331
Waste Code Description: Off-specification, aged, or surplus organics

Hazardous Waste Code: 352
Waste Code Description: Other organic solids

Hazardous Waste Code: 541
Waste Code Description: Photochemicals / photo processing waste

Hazardous Waste Code: 791
Waste Code Description: Liquids with pH < 2

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: D004
Waste Code Description: ARSENIC

Hazardous Waste Code: D005
Waste Code Description: BARIUM

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: D016
Waste Code Description: 2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)

Hazardous Waste Code: D018

Waste Code Description:	BENZENE
Hazardous Waste Code:	D022
Waste Code Description:	CHLOROFORM
Hazardous Waste Code:	D024
Waste Code Description:	M-CRESOL
Hazardous Waste Code:	D026
Waste Code Description:	CRESOL
Hazardous Waste Code:	D027
Waste Code Description:	1,4-DICHLOROBENZENE
Hazardous Waste Code:	D035
Waste Code Description:	METHYL ETHYL KETONE
Hazardous Waste Code:	D039
Waste Code Description:	TETRACHLOROETHYLENE
Hazardous Waste Code:	D043
Waste Code Description:	VINYL CHLORIDE
Hazardous Waste Code:	P001
Waste Code Description:	2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%
Hazardous Waste Code:	P075
Waste Code Description:	NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS
Hazardous Waste Code:	U002
Waste Code Description:	2-PROPANONE (I) (OR) ACETONE (I)
Hazardous Waste Code:	U034
Waste Code Description:	ACETALDEHYDE, TRICHLORO- (OR) CHLORAL
Hazardous Waste Code:	U035
Waste Code Description:	BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL
Hazardous Waste Code:	U058
Waste Code Description:	2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE
Hazardous Waste Code:	U072
Waste Code Description:	BENZENE, 1,4-DICHLORO- (OR) P-DICHLOROBENZENE
Hazardous Waste Code:	U112
Waste Code Description:	ACETIC ACID, ETHYL ESTER (I) (OR) ETHYL ACETATE (I)
Hazardous Waste Code:	U122
Waste Code Description:	FORMALDEHYDE
Hazardous Waste Code:	U129
Waste Code Description:	CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA, 2ALPHA, 3BETA, 4ALPHA, 5ALPHA, 6BETA)- (OR) LINDANE
Hazardous Waste Code:	U132
Waste Code Description:	HEXACHLOROPHENE (OR) PHENOL, 2,2'-METHYLENEBIS[3,4,6-TRICHLORO-
Hazardous Waste Code:	U134
Waste Code Description:	HYDROFLUORIC ACID (C,T) (OR) HYDROGEN FLUORIDE (C,T)
Hazardous Waste Code:	U150
Waste Code Description:	L-PHENYLALANINE, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) MELPHALAN
Hazardous Waste Code:	U154
Waste Code Description:	METHANOL (I) (OR) METHYL ALCOHOL (I)

Hazardous Waste Code: U159
Waste Code Description: 2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)

Hazardous Waste Code: U165
Waste Code Description: NAPHTHALENE

Hazardous Waste Code: U188
Waste Code Description: PHENOL

Hazardous Waste Code: U200
Waste Code Description: RESERPINE (OR) YOHIMBAN-16-CARBOXYLIC ACID, 11,17-DIMETHOXY-18-[(3,4,5-TRIMETHOXYBENZOYL) OXY]-, METHYL ESTER, (3BETA, 16BETA, 17ALPHA, 18BETA, 20ALPHA)-

Hazardous Waste Code: U205
Waste Code Description: SELENIUM SULFIDE (OR) SELENIUM SULFIDE SES2 (R,T)

Hazardous Waste Code: U210
Waste Code Description: ETHENE, TETRACHLORO- (OR) TETRACHLOROETHYLENE

Hazardous Waste Code: U249
Waste Code Description: ZINC PHOSPHIDE ZN3P2, WHEN PRESENT AT CONCENTRATIONS OF 10% OR LESS

Hazardous Waste Code: U279
Waste Code Description: CARBARYL (OR) 1-NAPHTHALENOL, METHYLCARBAMATE

Hazardous Waste Code: U409
Waste Code Description: CARBAMIC ACID, [1,2-PHENYLENEBIS (IMINOCARBONOTHIOYL)]BIS-, DIMETHYL ESTER (OR) THIOPHANATE-METHYL

Hazardous Waste Handler Details

Sequence No: 4
Receive Date: 20160620
Handler Name: WALMART #2553
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: 122
Waste Code Description: Alkaline solution without metals (pH > 12.5)

Hazardous Waste Code: 141
Waste Code Description: Off-specification, aged, or surplus inorganics

Hazardous Waste Code: 181
Waste Code Description: Other inorganic solid waste

Hazardous Waste Code: 213
Waste Code Description: Hydrocarbon solvents (benzene, hexane, Stoddard, etc.)

Hazardous Waste Code: 214
Waste Code Description: Unspecified solvent mixture

Hazardous Waste Code: 221
Waste Code Description: Waste oil and mixed oil

Hazardous Waste Code: 223
Waste Code Description: Unspecified oil-containing waste

Hazardous Waste Code: 232
Waste Code Description: Pesticides and other waste associated with pesticide production

Hazardous Waste Code: 311
Waste Code Description: Pharmaceutical waste

Hazardous Waste Code:	331
Waste Code Description:	Off-specification, aged, or surplus organics
Hazardous Waste Code:	352
Waste Code Description:	Other organic solids
Hazardous Waste Code:	791
Waste Code Description:	Liquids with pH < 2
Hazardous Waste Code:	D001
Waste Code Description:	IGNITABLE WASTE
Hazardous Waste Code:	D002
Waste Code Description:	CORROSIVE WASTE
Hazardous Waste Code:	D003
Waste Code Description:	REACTIVE WASTE
Hazardous Waste Code:	D004
Waste Code Description:	ARSENIC
Hazardous Waste Code:	D005
Waste Code Description:	BARIUM
Hazardous Waste Code:	D006
Waste Code Description:	CADMIUM
Hazardous Waste Code:	D007
Waste Code Description:	CHROMIUM
Hazardous Waste Code:	D008
Waste Code Description:	LEAD
Hazardous Waste Code:	D009
Waste Code Description:	MERCURY
Hazardous Waste Code:	D010
Waste Code Description:	SELENIUM
Hazardous Waste Code:	D011
Waste Code Description:	SILVER
Hazardous Waste Code:	D016
Waste Code Description:	2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)
Hazardous Waste Code:	D018
Waste Code Description:	BENZENE
Hazardous Waste Code:	D022
Waste Code Description:	CHLOROFORM
Hazardous Waste Code:	D024
Waste Code Description:	M-CRESOL
Hazardous Waste Code:	D026
Waste Code Description:	CRESOL
Hazardous Waste Code:	D027
Waste Code Description:	1,4-DICHLOROBENZENE
Hazardous Waste Code:	D035
Waste Code Description:	METHYL ETHYL KETONE
Hazardous Waste Code:	D039
Waste Code Description:	TETRACHLOROETHYLENE
Hazardous Waste Code:	D043
Waste Code Description:	VINYL CHLORIDE

Hazardous Waste Code:	P001
Waste Code Description:	2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%
Hazardous Waste Code:	P075
Waste Code Description:	NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS
Hazardous Waste Code:	U002
Waste Code Description:	2-PROPANONE (I) (OR) ACETONE (I)
Hazardous Waste Code:	U034
Waste Code Description:	ACETALDEHYDE, TRICHLORO- (OR) CHLORAL
Hazardous Waste Code:	U035
Waste Code Description:	BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL
Hazardous Waste Code:	U058
Waste Code Description:	2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE
Hazardous Waste Code:	U072
Waste Code Description:	BENZENE, 1,4-DICHLORO- (OR) P-DICHLOROBENZENE
Hazardous Waste Code:	U089
Waste Code Description:	DIETHYLSTILBESTEROL (OR) PHENOL, 4,4'-(1,2-DIETHYL-1,2-ETHENEDIYL)BIS, (E)-
Hazardous Waste Code:	U122
Waste Code Description:	FORMALDEHYDE
Hazardous Waste Code:	U129
Waste Code Description:	CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA, 2ALPHA, 3BETA, 4ALPHA, 5ALPHA, 6BETA)- (OR) LINDANE
Hazardous Waste Code:	U132
Waste Code Description:	HEXACHLOROPHENE (OR) PHENOL, 2,2'-METHYLENEBIS[3,4,6-TRICHLORO-
Hazardous Waste Code:	U134
Waste Code Description:	HYDROFLUORIC ACID (C,T) (OR) HYDROGEN FLUORIDE (C,T)
Hazardous Waste Code:	U150
Waste Code Description:	L-PHENYLALANINE, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) MELPHALAN
Hazardous Waste Code:	U154
Waste Code Description:	METHANOL (I) (OR) METHYL ALCOHOL (I)
Hazardous Waste Code:	U159
Waste Code Description:	2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)
Hazardous Waste Code:	U165
Waste Code Description:	NAPHTHALENE
Hazardous Waste Code:	U188
Waste Code Description:	PHENOL
Hazardous Waste Code:	U200
Waste Code Description:	RESERPINE (OR) YOHIMBAN-16-CARBOXYLIC ACID, 11,17-DIMETHOXY-18-[(3,4,5-TRIMETHOXYBENZOYL) OXY]-, METHYL ESTER, (3BETA, 16BETA, 17ALPHA, 18BETA, 20ALPHA)-
Hazardous Waste Code:	U205
Waste Code Description:	SELENIUM SULFIDE (OR) SELENIUM SULFIDE SES2 (R,T)
Hazardous Waste Code:	U210
Waste Code Description:	ETHENE, TETRACHLORO- (OR) TETRACHLOROETHYLENE
Hazardous Waste Code:	U249
Waste Code Description:	ZINC PHOSPHIDE ZN3P2, WHEN PRESENT AT CONCENTRATIONS OF 10% OR LESS
Hazardous Waste Code:	U279

Waste Code Description: CARBARYL (OR) 1-NAPHTHALENOL, METHYLCARBAMATE

Hazardous Waste Code: U409
Waste Code Description: CARBAMIC ACID, [1,2-PHENYLENEBIS (IMINOCARBONOTHIOYL)]BIS-, DIMETHYL ESTER (OR) THIOPHANATE-METHYL

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	
Name:	WAL MART STORES INC	***Street 2:***	
Date Became Current:	19990324	***City:***	
Date Ended Current:		***State:***	
Phone:		***Country:***	
Source Type:	Notification	***Zip Code:***	

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	PO BOX 8041
Name:	WAL-MART STORES INC	***Street 2:***	
Date Became Current:	19990324	***City:***	BENTONVILLE
Date Ended Current:		***State:***	AR
Phone:	479-277-8972	***Country:***	US
Source Type:	Notification	***Zip Code:***	72712-8041

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	
Name:	WAL-MART STORES INC	***Street 2:***	
Date Became Current:	19990324	***City:***	
Date Ended Current:		***State:***	
Phone:		***Country:***	US
Source Type:	Notification	***Zip Code:***	

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	PO BOX 8041
Name:	WAL MART STORES INC	***Street 2:***	
Date Became Current:	19990324	***City:***	BENTONVILLE
Date Ended Current:		***State:***	AR
Phone:		***Country:***	US
Source Type:	Notification	***Zip Code:***	72712-8041

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	PO BOX 8041
Name:	WALMART STORES INC	***Street 2:***	
Date Became Current:	19990324	***City:***	BENTONVILLE
Date Ended Current:		***State:***	AR
Phone:	479-204-3517	***Country:***	US
Source Type:	Notification	***Zip Code:***	72712-8041

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street 1:***	PO BOX 8041
Name:	WAL MART STORES INC	***Street 2:***	
Date Became Current:	19990324	***City:***	BENTONVILLE
Date Ended Current:		***State:***	AR
Phone:	479-204-0402	***Country:***	US
Source Type:	Notification	***Zip Code:***	72712-8041

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street 1:***	
Name:	WALMART STORES INC	***Street 2:***	
Date Became Current:	19990324	***City:***	
Date Ended Current:		***State:***	
Phone:		***Country:***	US
Source Type:	Notification	***Zip Code:***	

Historical Handler Details

Receive Dt: 20141028

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Generator Code Description: Small Quantity Generator
Handler Name: WALMART NO 2553

Receive Dt: 20110627
Generator Code Description: Small Quantity Generator
Handler Name: WALMART NO 2553

Receive Dt: 20100308
Generator Code Description: Small Quantity Generator
Handler Name: WALMART NO 2553

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
36	2 of 4	NNW	0.14 / 762.06	112.82 / -7	Walmart #2553 6650 Hembree Ln Windsor, CA 95492 CA	CUPA SONOMA

Facility ID: 49-000-005742 **CERS ID:** 10107583

Details

Program Type: Hazardous Waste
Permit Status: Active
Expiration Date: 3/16/2024
Fee Schedule: LQG 25 to <250 tons/year

Details

Program Type: Stormwater
Permit Status: Active
Expiration Date: 3/16/2024
Fee Schedule: Storm Water Permit

Details

Program Type: APSA
Permit Status: Active
Expiration Date: 3/16/2024
Fee Schedule: Tier 1 Facility (> 1320 gallons, < 10000 gallons, no single tank > 5000 gals)

Details

Program Type: HMBP
Permit Status: Active
Expiration Date: 3/16/2024
Fee Schedule: Range 3

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
36	3 of 4	NNW	0.14 / 762.06	112.82 / -7	Walmart #2553 6650 HEMBREE LN WINDSOR CA 95492	CERS TANK

Site ID: 407239 **Latitude:** 38.528477
Longitude: -122.790060

Regulated Programs

EI ID: 10107583
EI Description: Chemical Storage Facilities

EI ID: 10107583
EI Description: Aboveground Petroleum Storage

EI ID: 10107583
EI Description: Hazardous Waste Generator

Violations

Violation Date: 02/23/2015
Violation Source: CERS
Violation Program: HMRRP
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95, Section(s) 25508.2
Violation Notes:

Returned to compliance on 02/26/2015.

Violation Description:

Failure to annually review and electronically certify that the business plan is complete, accurate, and up-to-date.

Violations

Violation Date: 03/15/2018
Violation Source: CERS
Violation Program: APSA
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: HSC 6.67 25270.4.5 (a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5 (a)
Violation Notes:

Returned to compliance on 03/15/2018. There was an SPCC from August 17, 2012 onsite but it was never signed and has not been updated since. Complete and document the 5 year review of SPCC Plan and submit verification of proper completion.

Violation Description:

Failure to complete a review and evaluation of the SPCC Plan at least once every five years, document the completion of the review, and sign a statement as to whether the SPCC Plan will be amended.

Evaluations

Eval Date: 03/15/2018
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: APSA
Eval Source: CERS
Eval Notes:

Eval Date: 03/15/2018
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

No violations observed during the inspection.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/16/2021
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

No violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/15/2018
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

No violations observed during the inspection.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 03/16/2021
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: APSA
Eval Source: CERS
Eval Notes:

No violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 02/23/2015
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Eval Date: 02/23/2015
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

Eval Date: 03/16/2021
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

No violations. Facility is well kept. Paperwork is well organized; Note: data in [EVAL Notes] field for some records is truncated from the source.

Affiliations

Affil Type Desc: CUPA District
Entity Name: Sonoma County Fire Prevention and Hazmat
Entity Title:
Address: 2300 County Center Drive, Suite 220-B
City: Santa Rosa
State: CA
Country:

Zip Code: 95403
Phone: (707) 565-2024

Affil Type Desc: Identification Signer
Entity Name: Stacey Miner
Entity Title: Sr Mgr II Environmental Health & Safety Compliance
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Property Owner
Entity Name: WALMART REAL ESTATE BUSINESS TRUST
Entity Title:
Address: PO Box 8050 MS 0555
City: Bentonville
State: AR
Country: United States
Zip Code: 72712
Phone: (479) 204-3911

Affil Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title:
Address: 702 Southwest 8th Street
City: Bentonville
State: AR
Country:
Zip Code: 72716-0500
Phone:

Affil Type Desc: Parent Corporation
Entity Name: Walmart
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Operator
Entity Name: Walmart Inc.
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone: (479) 204-3911

Affil Type Desc: Document Preparer
Entity Name: Aptim Environmental & Infrastructure, Inc.
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Environmental Contact
Entity Name: Stacey Miner, Sr Mgr II Environmental Health & Safety Compliance
Entity Title:
Address: 702 Southwest 8th Street
City: Bentonville
State: AR

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Country:
Zip Code: 72716-0500
Phone:

Affil Type Desc: Legal Owner
Entity Name: Walmart Inc.
Entity Title:
Address: 702 Southwest 8th Street
City: Bentonville
State: AR
Country: United States
Zip Code: 72716-0500
Phone: (479) 204-3911

Coordinates

Env Int Type Code: APSA
Program ID: 10107583
Latitude: 38.528473
Longitude: -122.790047
Coord Name:
Ref Point Type Desc: Unknown

---

36 | 4 of 4 | NNW | 0.14 / 762.06 | 112.82 / -7 | **Walmart**
6650 Hembree Ln
Windsor CA 95492 | **ALT FUELS**

ID: 198738
Federal Agency ID:
Federal Agency:
Fed Agency Name:
Status: Open: The station is open.
Facility Type:
Fuel Type Code: ELEC: Electric
Owner Type Desc:
Expected Date:
Dt Last Confirmed: 2021-10-25
Open Date: 2021-10-25
Updated at: 2021-10-25 01:13:12 UTC
BD Blends:
NG PSI:
NG Fill Type Code:
NG Fill Type Desc:
NG Vehicle Class:
NG Vehicle Class Desc:
E85 Blender Pump:
E85 Blender Pump Desc:
E85 Other Ethanol Blends:
EV Pricing:
EV Pricing French:
EV on Site Renewable Source:
LPG Primary:
LPG Primary Desc:
Restricted Access:
Intersection Directions:
Geocode Status Desc: The location is from a real GPS readout at the station.
Hydrogen Status Link:

CNG Dispenser No:
CNG Fill Type Code:
CNG Site Renew Src:
CNG PSI:
CNG Storage Cap:
CNG Tot Compr Cap:
CNG Vehicle Class:
LPG Nozzle Types:
LNG Site Renew Src:
LNG Vehicle Class:
Hydrogen is Retail:
Hydrogen Pressures:
Hydrogen Standards:
Station Phone: 877-455-3833
Latitude: 38.528056
Longitude: -122.789759

---

37 | 1 of 3 | WNW | 0.15 / 782.55 | 106.01 / -14 | **Redwood Sanitary**
930 Shiloh Rd. WINDSOR, CA 95492
CA | **DELISTED COUNTY**

Original Source Facility ID:
Original Source Name: Sonoma County CUPA Facilities List
Record Date: 11-JAN-2016

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
37	2 of 3	WNW	0.15 / 782.55	106.01 / -14	Battery Systems 930 Shiloh Rd., Bldg 1 Windsor, CA 95492 CA	DELISTED COUNTY

Original Source Facility ID:
Original Source Name: Sonoma County CUPA Facilities List
Record Date: 11-JAN-2016

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
37	3 of 3	WNW	0.15 / 782.55	106.01 / -14	LANDCARE 930 SHILOH RD BLDG 44 STE B WINDSOR CA 95492	RCRA NON GEN

EPA Handler ID: CAL000367315
Gen Status Universe: No Report
Contact Name: DOUG SWISTOCK
Contact Address: 5295 WESTVIEW DR. STE. 100 , , FREDERICK , MD, 21703 ,
Contact Phone No and Ext: 443-463-9208
Contact Email: DOUG.SWISTOCK@LANDCARE.COM
Contact Country:
County Name: SONOMA
EPA Region: 09
Land Type:
Receive Date: 20110909
Location Latitude: 38.523798
Location Longitude: -122.794745

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20110909
Handler Name: LANDCARE
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner **Street No:**

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Type:	Other	**Street 1:**	5295 WESTVIEW DRIVE
Name:	LANDCARE WATER AGENCY	**Street 2:**	
Date Became Current:		**City:**	FREDERICK
Date Ended Current:		**State:**	MD
Phone:	443-463-9208	**Country:**	
Source Type:	Implementer	**Zip Code:**	21730-0000
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Other	**Street 1:**	5295 WESTVIEW DR. STE. 100
Name:	DOUG SWISTOCK	**Street 2:**	
Date Became Current:		**City:**	FREDERICK
Date Ended Current:		**State:**	MD
Phone:	443-463-9208	**Country:**	
Source Type:	Implementer	**Zip Code:**	21703

38	1 of 2	WNW	0.15 / 803.40	113.74 / -6	**Pacific Bracing Company** **610 Caletti Ave Windsor, CA 95492** **CA**	**CUPA SONOMA**

Facility ID:	49-000-005772	**CERS ID:**	10107670

Details

Program Type:	HMBP
Permit Status:	Active
Expiration Date:	4/11/2021
Fee Schedule:	Range 2

38	2 of 2	WNW	0.15 / 803.40	113.74 / -6	**MANIAR CORPORATION DBA** **BEST TRUCK BODY & TRAILER REPAIR** **610 CALETTI AVE** **WINDSOR CA 95492**	**RCRA NON GEN**

EPA Handler ID:	CAL000464661
Gen Status Universe:	No Report
Contact Name:	ABDULGANI MANIAR
Contact Address:	2900 ST PAUL DR APT 111 , , SANTA ROSA , CA, 95405 ,
Contact Phone No and Ext:	669-246-8268
Contact Email:	ABDUL@BESTTRUCKBODY.NET
Contact Country:	
County Name:	SONOMA
EPA Region:	09
Land Type:	
Receive Date:	20210809
Location Latitude:	
Location Longitude:	

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20210809
Handler Name: MANIAR CORPORATION DBA BEST TRUCK BODY & TRAILER REPAIR
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Other
Name: ABDULGANI MANIAR
Date Became Current:
Date Ended Current:
Phone: 669-246-8268
Source Type: Implementer
Street No:
Street 1: 2900 ST PAUL DR APT 111
Street 2:
City: SANTA ROSA
State: CA
Country:
Zip Code: 95405

Owner/Operator Ind: Current Owner
Type: Other
Name: MANIAR CORPORATION
Date Became Current:
Date Ended Current:
Phone: 669-246-8268
Source Type: Implementer
Street No:
Street 1: 2900 ST PAUL DR APT 111
Street 2:
City: SANTA ROSA
State: CA
Country:
Zip Code: 95405

39	1 of 2	W	0.16 / 835.49	115.29 / -5	CARL'S READY MIX 340 STANDARD AVENUE WINDSOR CA 95492	EMISSIONS

1997 Criteria Data

Facility ID: 11018
Facility SIC Code: 5032
CO: 49
Air Basin: SF
District: BA
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:
TOGT:
ROGT:
COT:
NOXT:
SOXT:
PMT: 20.2
PM10T: 18.584

1997 Toxic Data

Facility ID: 11018
Facility SIC Code: 5032
CO: 49
Air Basin: SF
District: BA
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:

1998 Criteria Data

Facility ID:	11018	***CERR Code:***	
Facility SIC Code:	5032	***TOGT:***	
CO:	49	***ROGT:***	
Air Basin:	SF	***COT:***	
District:	BA	***NOXT:***	
COID:	SON	***SOXT:***	
DISN:	BAY AREA AQMD	***PMT:***	14.3
CHAPIS:		***PM10T:***	13.156

1998 Toxic Data

Facility ID:	11018	***COID:***	SON
Facility SIC Code:	5032	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

1999 Criteria Data

Facility ID:	11018	***CERR Code:***	
Facility SIC Code:	5032	***TOGT:***	
CO:	49	***ROGT:***	
Air Basin:	SF	***COT:***	
District:	BA	***NOXT:***	
COID:	SON	***SOXT:***	
DISN:	BAY AREA AQMD	***PMT:***	12
CHAPIS:		***PM10T:***	11.04

1999 Toxic Data

Facility ID:	11018	***COID:***	SON
Facility SIC Code:	5032	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2000 Criteria Data

Facility ID:	11018	***CERR Code:***	
Facility SIC Code:	5032	***TOGT:***	
CO:	49	***ROGT:***	
Air Basin:	SF	***COT:***	
District:	BA	***NOXT:***	
COID:	SON	***SOXT:***	
DISN:	BAY AREA AQMD	***PMT:***	12
CHAPIS:		***PM10T:***	11.05

2000 Toxic Data

Facility ID:	11018	***COID:***	SON
Facility SIC Code:	5032	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	

District: BA
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

2001 Criteria Data

Facility ID:	11018	**CERR Code:**	
Facility SIC Code:	5032	**TOGT:**	
CO:	49	**ROGT:**	
Air Basin:	SF	**COT:**	
District:	BA	**NOXT:**	
COID:	SON	**SOXT:**	
DISN:	BAY AREA AQMD	**PMT:**	4.89
CHAPIS:		**PM10T:**	4.5

2001 Toxic Data

Facility ID:	11018	**COID:**	SON
Facility SIC Code:	5032	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		

TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

2002 Criteria Data

Facility ID:	11018	**CERR Code:**	
Facility SIC Code:	5032	**TOGT:**	
CO:	49	**ROGT:**	
Air Basin:	SF	**COT:**	
District:	BA	**NOXT:**	
COID:	SON	**SOXT:**	
DISN:	BAY AREA AQMD	**PMT:**	4.071
CHAPIS:		**PM10T:**	3.74532

2002 Toxic Data

Facility ID:	11018	**COID:**	SON
Facility SIC Code:	5032	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		

TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

2003 Criteria Data

Facility ID:	11018	**CERR Code:**	
Facility SIC Code:	5032	**TOGT:**	
CO:	49	**ROGT:**	
Air Basin:	SF	**COT:**	
District:	BA	**NOXT:**	
COID:	SON	**SOXT:**	
DISN:	BAY AREA AQMD	**PMT:**	3.737
CHAPIS:		**PM10T:**	3.44

2003 Toxic Data

Facility ID:	11018	***COID:***	SON
Facility SIC Code:	5032	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2004 Criteria Data

Facility ID:	11018	***CERR Code:***	
Facility SIC Code:	5032	***TOGT:***	
CO:	49	***ROGT:***	
Air Basin:	SF	***COT:***	
District:	BA	***NOXT:***	
COID:	SON	***SOXT:***	
DISN:	BAY AREA AQMD	***PMT:***	5.646
CHAPIS:		***PM10T:***	5.19432

2004 Toxic Data

Facility ID:	11018	***COID:***	SON
Facility SIC Code:	5032	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2005 Criteria Data

Facility ID:	11018	***CERR Code:***	
Facility SIC Code:	5032	***TOGT:***	
CO:	49	***ROGT:***	
Air Basin:	SF	***COT:***	
District:	BA	***NOXT:***	
COID:	SON	***SOXT:***	
DISN:	BAY AREA AQMD	***PMT:***	5.481
CHAPIS:		***PM10T:***	5.04252

2005 Toxic Data

Facility ID:	11018	***COID:***	SON
Facility SIC Code:	5032	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2006 Criteria Data

Facility ID:	11018	***CERR Code:***	
Facility SIC Code:	5032	***TOGT:***	

CO:	49	***ROGT:***	
Air Basin:	SF	***COT:***	
District:	BA	***NOXT:***	
COID:	SON	***SOXT:***	
DISN:	BAY AREA AQMD	***PMT:***	7.484
CHAPIS:		***PM10T:***	6.88528

2006 Toxic Data

Facility ID:	11018	***COID:***	SON
Facility SIC Code:	5032	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2007 Criteria Data

Facility ID:	11018	***CERR Code:***	
Facility SIC Code:	5032	***TOGT:***	
CO:	49	***ROGT:***	
Air Basin:	SF	***COT:***	
District:	BA	***NOXT:***	
COID:	SON	***SOXT:***	
DISN:	BAY AREA AQMD	***PMT:***	7.484
CHAPIS:		***PM10T:***	6.88528

2007 Toxic Data

Facility ID:	11018	***COID:***	SON
Facility SIC Code:	5032	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2008 Criteria Data

Facility ID:	11018	***CERR Code:***	
Facility SIC Code:	5032	***TOGT:***	
CO:	49	***ROGT:***	
Air Basin:	SF	***COT:***	
District:	BA	***NOXT:***	
COID:	SON	***SOXT:***	
DISN:	BAY AREA AQMD	***PMT:***	7.484
CHAPIS:		***PM10T:***	6.88528

2008 Toxic Data

Facility ID:	11018	***COID:***	SON
Facility SIC Code:	5032	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Non-Cancer Acute Haz Ind:						
39	2 of 2	W	0.16 / 835.49	115.29 / -5	STANDARD STRUCTURES 340 STANDARD AVE WINDSOR CA 95492	RCRA SQG

EPA Handler ID: CAP000141747
Gen Status Universe: Small Quantity Generator
Contact Name: ED TAYLOR
Contact Address: PO BOX K , , SANTA ROSA , CA, 95402 , US
Contact Phone No and Ext: 707-544-2982
Contact Email:
Contact Country: US
County Name: SONOMA
EPA Region: 09
Land Type: Private
Receive Date: 20030319
Location Latitude: 38.523196
Location Longitude: -122.791387

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20030319
Handler Name: STANDARD STRUCTURES
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Temporary

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D039
Waste Code Description: TETRACHLOROETHYLENE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Hazardous Waste Code: D040
Waste Code Description: TRICHLORETHYLENE

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: VIC COLLETTI
Date Became Current: 19960601
Date Ended Current:
Phone:
Source Type: Temporary
Street No:
Street 1:
Street 2:
City:
State:
Country: US
Zip Code:

Owner/Operator Ind: Current Owner
Type: Private
Name: VIC COLLETTI
Date Became Current: 19960601
Date Ended Current:
Phone:
Source Type: Temporary
Street No:
Street 1:
Street 2:
City:
State:
Country: US
Zip Code:

40	1 of 1	NNW	0.16 / 843.20	118.67 / -1	Panda Express #1598 6560 Hembree Lane, Pad 6 Building Windsor, CA 95492 CA	CUPA SONOMA

Facility ID: 49-000-007965
CERS ID: 10480576

Details

Program Type: HMBP
Permit Status: Active
Expiration Date: 11/18/2019
Fee Schedule: Range 9 - Restaurants > 1000 SCF CO2

Details

Program Type: Stormwater
Permit Status: Active
Expiration Date: 11/18/2019
Fee Schedule: Storm Water Permit

41	1 of 5	N	0.16 / 853.03	121.96 / 2	SUBWAY 6400 Hembree LN STE 120 Windsor, CA 95492 CA	CUPA SONOMA

Facility ID: 49-000-007969
CERS ID:

Details

Program Type: HMBP
Permit Status: Inactive
Expiration Date:
Fee Schedule: Range 1

41	2 of 5	N	0.16 / 853.03	121.96 / 2	Former Office Depot #2208 (CLOSED) 6400 Hembree Ln Ste 100 Windsor, CA 95492 CA	CUPA SONOMA

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility ID: 49-000-008426 **CERS ID:** 10707247

Details

Program Type: Hazardous Waste
Permit Status: Inactive
Expiration Date: 7/6/2020
Fee Schedule: SQG < 325 gallons/year

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
41	3 of 5	N	0.16 / 853.03	121.96 / 2	OFFICE DEPOT 2208 6400 HEMBREE LANE SUITE 100 WINDSOR CA 95492	RCRA NON GEN

EPA Handler ID: CAL000420831
Gen Status Universe: No Report
Contact Name: ANA FERNANDEZ
Contact Address: 6600 N MILITARY TRAIL C456 , , BOCA RATON , FL, 33496 ,
Contact Phone No and Ext: 561-438-7903
Contact Email: ANA.FERNANDEZ@OFFICEDEPOT.COM
Contact Country:
County Name: SONOMA
EPA Region: 09
Land Type:
Receive Date: 20161010
Location Latitude: 38.526804
Location Longitude: -122.78804

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20161010
Handler Name: OFFICE DEPOT 2208
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator **Street No:**

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Type:	Other	**Street 1:**	6600 N MILITARY TRAIL C456
Name:	ANA FERNANDEZ	**Street 2:**	
Date Became Current:		**City:**	BOCA RATON
Date Ended Current:		**State:**	FL
Phone:	561-438-7903	**Country:**	
Source Type:	Implementer	**Zip Code:**	33496
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Other	**Street 1:**	6600 N MILITARY TRAIL
Name:	OFFICE DEPOT INC	**Street 2:**	
Date Became Current:		**City:**	BOCA RATON
Date Ended Current:		**State:**	FL
Phone:	561-438-4800	**Country:**	
Source Type:	Implementer	**Zip Code:**	33496

41	4 of 5	N	0.16 / 853.03	121.96 / 2	**SAVNNICKSS INCORPORATED (GROCERY OUTLET OF WINDSOR)** **6400 HEMBREE LN STE 100** **WINDSOR CA 95492**	**RCRA NON GEN**

EPA Handler ID:	CAL000459613
Gen Status Universe:	No Report
Contact Name:	NICHOLAS DIGIROLAMO
Contact Address:	6400 HEMBREE LN STE 100 , , WINDSOR , CA, 95492 ,
Contact Phone No and Ext:	707-416-9133
Contact Email:	WINDSOR@GROCERYOUTLET.COM
Contact Country:	
County Name:	SONOMA
EPA Region:	09
Land Type:	
Receive Date:	20210126
Location Latitude:	
Location Longitude:	

Violation/Evaluation Summary

Note:	NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20210126
Handler Name:	SAVNNICKSS INCORPORATED (GROCERY OUTLET OF WINDSOR)
Source Type:	Implementer
Federal Waste Generator Code:	N

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Other	**Street 1:**	6400 HEMBREE LN STE 100
Name:	NICHOLAS DIGIROLAMO	**Street 2:**	
Date Became Current:		**City:**	WINDSOR
Date Ended Current:		**State:**	CA
Phone:	707-416-9133	**Country:**	
Source Type:	Implementer	**Zip Code:**	95492

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Other	**Street 1:**	501 MATHEWS DR
Name:	SAVNNICKSJ INCORPORATED	**Street 2:**	
Date Became Current:		**City:**	VACAVILLE
Date Ended Current:		**State:**	CA
Phone:	707-416-9133	**Country:**	
Source Type:	Implementer	**Zip Code:**	95687

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
41	5 of 5	N	0.16 / 853.03	121.96 / 2	Grocery Outlet 6400 HEMBREE LN WINDSOR, CA 95492 CA	CUPA SONOMA

Facility ID: 49-000-008774 **CERS ID:** 0

Details

Program Type: HMBP
Permit Status: Active
Expiration Date:
Fee Schedule: Range 2

Details

Program Type: Hazardous Waste
Permit Status: Active
Expiration Date:
Fee Schedule: SQG < 325 gallons/year

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
42	1 of 1	NNW	0.17 / 879.21	114.36 / -6	HOME DEPOT #6667 6280 HEMBREE LANE WINDSOR CA 95492	EMISSIONS

2003 Criteria Data

Facility ID:	13223	**CERR Code:**	
Facility SIC Code:	5211	**TOGT:**	.001
CO:	49	**ROGT:**	0
Air Basin:	SF	**COT:**	.002
District:	BA	**NOXT:**	.011
COID:	SON	**SOXT:**	0
DISN:	BAY AREA AQMD	**PMT:**	.001
CHAPIS:		**PM10T:**	0

2003 Toxic Data

Facility ID:	13223	**COID:**	SON
Facility SIC Code:	5211	**DISN:**	BAY AREA AQMD

CO: 49
Air Basin: SF
District: BA
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
CHAPIS:
CERR Code:

2004 Criteria Data

Facility ID: 13223
Facility SIC Code: 5211
CO: 49
Air Basin: SF
District: BA
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:
TOGT: .001
ROGT: .0008367
COT: .002
NOXT: .011
SOXT: 0
PMT: .001
PM10T: .000976

2004 Toxic Data

Facility ID: 13223
Facility SIC Code: 5211
CO: 49
Air Basin: SF
District: BA
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:

2005 Criteria Data

Facility ID: 13223
Facility SIC Code: 5211
CO: 49
Air Basin: SF
District: BA
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:
TOGT: .001
ROGT: .0008367
COT: .002
NOXT: .011
SOXT: 0
PMT: .001
PM10T: .000976

2005 Toxic Data

Facility ID: 13223
Facility SIC Code: 5211
CO: 49
Air Basin: SF
District: BA
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:

2006 Criteria Data

Facility ID: 13223
Facility SIC Code: 5211
CO: 49
Air Basin: SF
District: BA
COID: SON
DISN: BAY AREA AQMD
CERR Code:
TOGT: .001
ROGT: .0008367
COT: .003
NOXT: .012
SOXT: 0
PMT: .001

CHAPIS: **PM10T:** .000976

2006 Toxic Data

Facility ID: 13223
Facility SIC Code: 5211
CO: 49
Air Basin: SF
District: BA
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:

2007 Criteria Data

Facility ID: 13223
Facility SIC Code: 5211
CO: 49
Air Basin: SF
District: BA
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:
TOGT: .001
ROGT: .0008367
COT: .003
NOXT: .012
SOXT: 0
PMT: .001
PM10T: .000976

2007 Toxic Data

Facility ID: 13223
Facility SIC Code: 5211
CO: 49
Air Basin: SF
District: BA
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:

2008 Criteria Data

Facility ID: 13223
Facility SIC Code: 5211
CO: 49
Air Basin: SF
District: BA
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:
TOGT: .001
ROGT: .0008367
COT: .003
NOXT: .012
SOXT: 0
PMT: .001
PM10T: .000976

2008 Toxic Data

Facility ID: 13223
Facility SIC Code: 5211
CO: 49
Air Basin: SF
District: BA
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:

2009 Criteria Data

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility ID:	13223	**CERR Code:**	
Facility SIC Code:	5211	**TOGT:**	.002
CO:	49	**ROGT:**	.0016734
Air Basin:	SF	**COT:**	.007
District:	BA	**NOXT:**	.03
COID:	SON	**SOXT:**	0
DISN:	BAY AREA AQMD	**PMT:**	.002
CHAPIS:		**PM10T:**	.001952

2009 Toxic Data

Facility ID:	13223	**COID:**	SON
Facility SIC Code:	5211	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2010 Toxic Data

Facility ID:	13223	**COID:**	SON
Facility SIC Code:	5211	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2011 Criteria Data

Facility ID:	13223	**CERR Code:**	
Facility SIC Code:	5211	**TOGT:**	.002
CO:	49	**ROGT:**	.0016734
Air Basin:	SF	**COT:**	.007
District:	BA	**NOXT:**	.034
COID:	SON	**SOXT:**	0
DISN:	BAY AREA AQMD	**PMT:**	.00204918032786885245901639344262295081967 2
CHAPIS:		**PM10T:**	.002

2011 Toxic Data

Facility ID:	13223	**COID:**	SON
Facility SIC Code:	5211	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

43	*1 of 2*	*N*	*0.17 / 919.49*	*122.57 / 3*	***Burger King*** ***6351 Hembree Ln, Windsor, CA 95492*** ***CA***	***CUPA SONOMA***

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility ID: 49-000-007904 **CERS ID:** 10638154

Details

Program Type: HMBP
Permit Status: Active
Expiration Date:
Fee Schedule: Range 9 - Restaurants > 1000 SCF CO2

43	2 of 2	N	0.17 / 919.49	122.57 / 3	McDonalds- Walmart 6351 Hembree Lane Windsor, CA 95492 CA	DELISTED COUNTY

Original Source Facility ID:
Original Source Name: Sonoma County CUPA Facilities List
Record Date: 11-JAN-2016

44	1 of 3	WSW	0.18 / 933.25	116.35 / -4	Windsor Yard 550 Caletti Ave # 5, Windsor, CA 95492 CA	CUPA SONOMA

Facility ID: 49-000-008562 **CERS ID:** 10759141

Details

Program Type: HMBP
Permit Status: Inactive
Expiration Date:
Fee Schedule: Range 2

Details

Program Type: Hazardous Waste
Permit Status: Inactive
Expiration Date:
Fee Schedule:

44	2 of 3	WSW	0.18 / 933.25	116.35 / -4	WILDEASE LLC 550 CALETTI AVE WINDSOR CA 95492	RCRA NON GEN

EPA Handler ID: CAC002964519
Gen Status Universe: No Report
Contact Name: WILDEASE LLC
Contact Address: 5922 PRUITT AVE , , WINDSOR , CA, 95492 ,
Contact Phone No and Ext: 707-836-9900
Contact Email: WHOGGATT@CAL-INC.COM
Contact Country:
County Name: SONOMA
EPA Region: 09
Land Type:
Receive Date: 20180601
Location Latitude: 38.523492
Location Longitude: -122.793155

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20180601
Handler Name:	WILDEASE LLC
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street 1:***	5922 PRUITT AVE
Name:	WILDEASE LLC	***Street 2:***	
Date Became Current:		***City:***	WINDSOR
Date Ended Current:		***State:***	CA
Phone:	707-836-9900	***Country:***	
Source Type:	Implementer	***Zip Code:***	95492

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street 1:***	5922 PRUITT AVE
Name:	WILDEASE LLC	***Street 2:***	
Date Became Current:		***City:***	WINDSOR
Date Ended Current:		***State:***	CA
Phone:	707-836-9900	***Country:***	
Source Type:	Implementer	***Zip Code:***	95492

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
44	3 of 3	WSW	0.18 / 933.25	116.35 / -4	ELITE CONCRETE CONSTRUCTION INC 550 CALETTI AVE WINDSOR CA 95492	RCRA NON GEN

EPA Handler ID:	CAL000451229
Gen Status Universe:	No Report
Contact Name:	MICHELLE DUNLOP
Contact Address:	5885 PRUITT AVE , , WINDSOR , CA, 95492 ,
Contact Phone No and Ext:	707-836-4350
Contact Email:	MICHELLE@E-LITECONCRETE.COM
Contact Country:	
County Name:	SONOMA
EPA Region:	09
Land Type:	
Receive Date:	20191211
Location Latitude:	
Location Longitude:	

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20191211
Handler Name:	ELITE CONCRETE CONSTRUCTION INC
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street 1:***	5885 PRUITT AVE
Name:	ELITE CONCRETE CONSTUCTION	***Street 2:***	
Date Became Current:		***City:***	WINDSOR
Date Ended Current:		***State:***	CA
Phone:	707-836-4350	***Country:***	
Source Type:	Implementer	***Zip Code:***	95492
Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street 1:***	5885 PRUITT AVE
Name:	MICHELLE DUNLOP	***Street 2:***	
Date Became Current:		***City:***	WINDSOR
Date Ended Current:		***State:***	CA
Phone:	707-836-4350	***Country:***	
Source Type:	Implementer	***Zip Code:***	95492

45	*1 of 5*	***SSW***	***0.18 / 956.85***	***118.60 / -1***	***Silara Medtech Inc.*** ***451 Aviation Blvd., Suite 107A*** ***Santa Rosa, CA 95403*** ***CA***	***CUPA SONOMA***

Facility ID:	49-000-008130	***CERS ID:***	10129897

Details

Program Type:	HMBP
Permit Status:	Active
Expiration Date:	5/14/2022

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Fee Schedule: Range 3

Details

Program Type: Stormwater
Permit Status: Active
Expiration Date: 5/14/2022
Fee Schedule: Storm Water Permit

Details

Program Type: Hazardous Waste
Permit Status: Active
Expiration Date: 5/14/2022
Fee Schedule: SQG < 325 gallons/year

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
45	2 of 5	SSW	0.18 / 956.85	118.60 / -1	MITRALIFE 451 AVIATION BLVD SANTA ROSA, CA 95403 CA	DELISTED COUNTY

Original Source Facility ID:
Original Source Name: Sonoma County CUPA Facilities List
Record Date: 11-JAN-2016

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
45	3 of 5	SSW	0.18 / 956.85	118.60 / -1	HAISCO US MED TECH INC 451 AVIATION BLVD STE 107A SANTA ROSA CA 95404	RCRA TSD

EPA Handler ID: CAL000426304
Gen Status Universe: No Report
Contact Name: JOSEPH TAMAYO
Contact Address: 451 AVIATION BLVD STE 107A , 451 AVIATION BLVD STE 107A , SANTA ROSA , CA, 95403 ,
Contact Phone No and Ext: 707-757-5725
Contact Email: JTAMAYO@HAISCOMEDTECH.COM
Contact Country:
Land Type:
County Name: SONOMA
EPA Region: 09
Receive Date: 20170329
Location Latitude: 38.514837
Location Longitude: -122.790572

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Smelting, Melting and Refining: No
Underground Injection Control: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20170329
Handler Name: HAISCO US MED TECH INC
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Other
Name: HAISCO US MED TECH INC
Date Became Current:
Date Ended Current:
Phone: 707-757-5725
Source Type: Implementer
Street No:
Street 1: 451 AVIATION BLVD STE 107A
Street 2: 451 AVIATION BLVD STE 107A
City: SANTA ROSA
State: CA
Country:
Zip Code: 95403

Owner/Operator Ind: Current Operator
Type: Other
Name: JOSEPH TAMAYO
Date Became Current:
Date Ended Current:
Phone: 707-757-5725
Source Type: Implementer
Street No:
Street 1: 451 AVIATION BLVD STE 107A
Street 2: 451 AVIATION BLVD STE 107A
City: SANTA ROSA
State: CA
Country:
Zip Code: 95403

45	4 of 5	SSW	0.18 / 956.85	118.60 / -1	HAISCO US MED TECH INC 451 AVIATION BLVD STE 107A SANTA ROSA CA 95404	RCRA NON GEN

EPA Handler ID: CAL000426304
Gen Status Universe: No Report
Contact Name: JOSEPH TAMAYO
Contact Address: 451 AVIATION BLVD STE 107A , 451 AVIATION BLVD STE 107A , SANTA ROSA , CA, 95403 ,
Contact Phone No and Ext: 707-757-5725
Contact Email: JTAMAYO@HAISCOMEDTECH.COM
Contact Country:
County Name: SONOMA
EPA Region: 09
Land Type:
Receive Date: 20170329
Location Latitude: 38.514837
Location Longitude: -122.790572

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No

Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20170329
Handler Name:	HAISCO US MED TECH INC
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street 1:***	451 AVIATION BLVD STE 107A
Name:	JOSEPH TAMAYO	***Street 2:***	451 AVIATION BLVD STE 107A
Date Became Current:		***City:***	SANTA ROSA
Date Ended Current:		***State:***	CA
Phone:	707-757-5725	***Country:***	
Source Type:	Implementer	***Zip Code:***	95403

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street 1:***	451 AVIATION BLVD STE 107A
Name:	HAISCO US MED TECH INC	***Street 2:***	451 AVIATION BLVD STE 107A
Date Became Current:		***City:***	SANTA ROSA
Date Ended Current:		***State:***	CA
Phone:	707-757-5725	***Country:***	
Source Type:	Implementer	***Zip Code:***	95403

45	***5 of 5***	***SSW***	***0.18 / 956.85***	***118.60 / -1***	***SUTTER PACIFIC MEDICAL FOUNDATION 451 AVIATION BLVD SUITE 101 SANTA ROSA CA 95403***	***RCRA NON GEN***

EPA Handler ID:	CAC003129754
Gen Status Universe:	No Report
Contact Name:	TIMOTHY HUNT
Contact Address:	451 AVIATION BLVD , SUITE 101 , SANTA ROSA , CA, 95403 ,
Contact Phone No and Ext:	415-902-6181
Contact Email:	HUNTTW@SUTTERHEALTH.ORG
Contact Country:	
County Name:	SONOMA
EPA Region:	09
Land Type:	
Receive Date:	20210716
Location Latitude:	
Location Longitude:	

Violation/Evaluation Summary

Note:	NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No

Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20210716
Handler Name:	SUTTER PACIFIC MEDICAL FOUNDATION
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street 1:***	451 AVIATION BLVD
Name:	TIMOTHY HUNT	***Street 2:***	SUITE 101
Date Became Current:		***City:***	SANTA ROSA
Date Ended Current:		***State:***	CA
Phone:	415-902-6181	***Country:***	
Source Type:	Implementer	***Zip Code:***	95403

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street 1:***	451 AVIATION BLVD
Name:	ERIN NEAL	***Street 2:***	SUITE 101
Date Became Current:		***City:***	SANTA ROSA
Date Ended Current:		***State:***	CA
Phone:	707-521-8871	***Country:***	
Source Type:	Implementer	***Zip Code:***	95403

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
46	*1 of 1*	*S*	*0.18 / 957.80*	*121.64 / 2*	***Sonoma EO*** ***428 Aviation Blvd Santa Rosa, CA 95403*** ***CA***	***CUPA SONOMA***

Facility ID:	49-000-007150	***CERS ID:***	10111021

Details

Program Type:	HMBP
Permit Status:	Active
Expiration Date:	5/31/2020
Fee Schedule:	Range 5

Details

Program Type:	Stormwater
Permit Status:	Active
Expiration Date:	5/31/2020
Fee Schedule:	Storm Water Permit

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Details

Program Type: Hazardous Waste
Permit Status: Active
Expiration Date: 5/31/2020
Fee Schedule: SQG > 325 gallons/year to <5 tons/year w/source reduction/recycle

---

47 *1 of 2* *WNW* *0.19 / 993.02* *106.40 / -14* ***ECODYNE COOLING SHILOH ROAD WINDSOR CA 95442*** ***RESPONSE***

Estor/EPA ID: 49420002
Site Code:
Nat Priority List: NO
Acres: NONE SPECIFIED
Special Program:
Funding: RESPONSIBLE PARTY
Assembly District: 02
Senate District: 02
School District:
Permit Renewal Lead:
Project Manager:
Supervisor:
Public Partici Spclst:
Census Tract: 6097152702
County: SONOMA
Latitude: 38.5257972222222
Longitude: -122.797291666667
APN: NONE SPECIFIED
Cleanup Status: REFER: RWQCB AS OF 4/3/1992
Cleanup Oversight Agencies: RWQCB 1 - NORTH COAST - LEAD AGENCY
Site Type: STATE RESPONSE OR NPL
Office: CLEANUP BERKELEY
Past Use that Caused Contam: NONE SPECIFIED
Potential Media Affected: NONE SPECIFIED
Potential Contamin of Concern:

NONE SPECIFIED

Site History:

Status: REFER: RWQCB
Program Type: STATE RESPONSE
CalEnviroScreen Score: 46-50%
Summary Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=49420002

Completed Activities

Title: Semiannual Monitoring and Sampling Report (Oct 2008 to Mar 2009)
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49420002&doc_id=6023800
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Monitoring Report
Date Completed: 5/15/2009
Comments: Regular activity report. No review necessary.

Title: Semi-Annual Monitoring and Sampling Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49420002&doc_id=6021447
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 11/18/2008
Comments: Received Report on Nov. 17, 2008; Uploaded for record.

---

47 *2 of 2* *WNW* *0.19 / 993.02* *106.40 / -14* ***ECODYNE COOLING SHILOH ROAD WINDSOR CA 95442*** ***ENVIROSTOR***

Estor/EPA ID: 49420002
Assembly District: 02

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Site Code:
Nat Priority List: NO
APN: NONE SPECIFIED
Census Tract: 6097152702
Site Type: STATE RESPONSE OR NPL
Address Description: SHILOH ROAD
Office: CLEANUP BERKELEY
Special Program:
Funding: RESPONSIBLE PARTY
Cleanup Status: REFER: RWQCB AS OF 4/3/1992
Cleanup Oversight Agencies: RWQCB 1 - NORTH COAST - LEAD AGENCY
School District:
Past Use that Caused Contam: NONE SPECIFIED
Potential Media Affected: NONE SPECIFIED
Site History:

Senate District: 02
Permit Renewal Lead:
Public Partici Spclst:
Project Manager:
County: SONOMA
Latitude: 38.5257972222222
Longitude: -122.797291666667
Acres: NONE SPECIFIED
Supervisor:

Potential Contamin of Concern:

NONE SPECIFIED

Status: REFER: RWQCB
Program Type: STATE RESPONSE
CalEnviroScreen Score: 46-50%
Summary Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=49420002

Completed Activities

Title: Semi-Annual Monitoring and Sampling Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49420002&doc_id=6021447
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 11/18/2008
Comments: Received Report on Nov. 17, 2008; Uploaded for record.

Title: Semiannual Monitoring and Sampling Report (Oct 2008 to Mar 2009)
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49420002&doc_id=6023800
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Monitoring Report
Date Completed: 5/15/2009
Comments: Regular activity report. No review necessary.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
48	1 of 2	S	0.20 / 1,033.88	120.96 / 1	Airport Health Club 432 Aviation Blvd Santa Rosa, CA 95403 CA	CUPA SONOMA

Facility ID: 49-000-005781
CERS ID: 10107694

Details

Program Type: Stormwater
Permit Status: Active
Expiration Date: 3/8/2021
Fee Schedule: Storm Water Permit

Details

Program Type: HMBP

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Permit Status:		Active				
Expiration Date:		3/8/2021				
Fee Schedule:		Range 2				
48	2 of 2	S	0.20 / 1,033.88	120.96 / 1	AIRPORT HEALTH CLUB 432 AVIATION BOULEVARD SANTA ROSA CA 95403	EMISSIONS

2012 Criteria Data

Facility ID:	20694	**CERR Code:**	
Facility SIC Code:	5091	**TOGT:**	.589
CO:	49	**ROGT:**	.0538346
Air Basin:	SF	**COT:**	.08
District:	BA	**NOXT:**	.032
COID:	SON	**SOXT:**	.001
DISN:	BAY AREA AQMD	**PMT:**	.00905432595573440643863179074446680080 4829
CHAPIS:		**PM10T:**	.009

2012 Toxic Data

Facility ID:	20694	**COID:**	SON
Facility SIC Code:	5091	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2013 Criteria Data

Facility ID:	20694	**CERR Code:**	
Facility SIC Code:	5091	**TOGT:**	2.031
CO:	49	**ROGT:**	.1856334
Air Basin:	SF	**COT:**	.277
District:	BA	**NOXT:**	.109
COID:	SON	**SOXT:**	.002
DISN:	BAY AREA AQMD	**PMT:**	.032
CHAPIS:		**PM10T:**	.032

2013 Toxic Data

Facility ID:	20694	**COID:**	SON
Facility SIC Code:	5091	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2014 Criteria Data

Facility ID:	20694	**CERR Code:**	
Facility SIC Code:	5091	**TOGT:**	1.886787219
CO:	49	**ROGT:**	

Air Basin:	SF	**COT:**	.256857442
District:	BA	**NOXT:**	.101555173
COID:	SON	**SOXT:**	.001697193
DISN:	BAY AREA AQMD	**PMT:**	.030047421
CHAPIS:		**PM10T:**	.029867137

2014 Toxic Data

Facility ID:	20694	**COID:**	SON
Facility SIC Code:	5091	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2015 Criteria Data

Facility ID:	20694	**CERR Code:**	
Facility SIC Code:	5091	**TOGT:**	1.951974
CO:	49	**ROGT:**	.02696375
Air Basin:	SF	**COT:**	.2657319
District:	BA	**NOXT:**	.1050639
COID:	SON	**SOXT:**	.001755831
DISN:	BAY AREA AQMD	**PMT:**	.03108557
CHAPIS:		**PM10T:**	.03089906

2015 Toxic Data

Facility ID:	20694	**COID:**	SON
Facility SIC Code:	5091	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2016 Criteria Data

Facility ID:	20694	**CERR CODE:**	
Facility SIC Code:	5091	**TOGT:**	1.838413692
CO:	49	**ROGT:**	.1711563147252
Air Basin:	SF	**COT:**	.250272298
District:	BA	**NOXT:**	.098951571
COID:	SON	**SOXT:**	.001653682
DISN:	BAY AREA AQMD	**PMT:**	.029277087
CHAPIS:		**PM10T:**	.029101425

2016 Toxic Data

Facility ID:	20694	**TS:**	
Facility SIC Code:	5091	**HRA:**	
CERR CODE:		**CH Index:**	
COID:	SON	**AH Index:**	
CO:	49	**Air Basin:**	SF
DISN:	BAY AREA AQMD	**District:**	BA
CHAPIS:			

2017 Criteria Data

Facility ID:	20694	***CERR Code:***	
Facility SIC Code:	5091	***TOGT:***	2.00404711
CO:	49	***ROGT:***	.186576785941
Air Basin:	SF	***COT:***	.272820705
District:	BA	***NOXT:***	.107866685
COID:	SON	***SOXT:***	.001802671
DISN:	BAY AREA AQMD	***PMT:***	.031914851
CHAPIS:		***PM10T:***	.031723362

2017 Toxic Data

Facility ID:	20694	***COID:***	SON
Facility SIC Code:	5091	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2018 Criteria Data

Facility ID:	20694	***CERR Code:***	
Facility SIC Code:	5091	***TOGT:***	2.005376912
CO:	49	***ROGT:***	.1867005905072
Air Basin:	SF	***COT:***	.273001738
District:	BA	***NOXT:***	.10793826
COID:	SON	***SOXT:***	.001803867
DISN:	BAY AREA AQMD	***PMT:***	.031936028
CHAPIS:		***PM10T:***	.031744412

2018 Toxic Data

Facility ID:	20694	***COID:***	SON
Facility SIC Code:	5091	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2019 Criteria Data

CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
Facility ID:	20694	***ROGT:***	.167508958183
District:	BA	***COT:***	.244938906
Facility SIC Code:	5091	***NOXT:***	.096842895
CO ID:	SON	***SOXT:***	.001618441
DISN:	BAY AREA AQMD		
PM10T:	.028481293		
TOGT:	1.79923693		
PMT:	.028653212		

2019 Toxic Data

CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Faccility ID: 20694
District: BA
Facility SIC Code: 5091
COID: SON
DISN: BAY AREA AQMD
TS:
Health Risk Asmt:
NonCncrChrnicHazInd :
NonCncrActeHazInd:

---

49 | **1 of 3** | **N** | **0.20 / 1,046.83** | **123.44 / 3** | **The Home Depot Store #6667**
6280 Hembree Lane Windsor, CA 95492
CA | **CUPA SONOMA**

Facility ID: 49-000-006198
CERS ID: 10108861

Details

Program Type: HMBP
Permit Status: Active
Expiration Date: 3/7/2022
Fee Schedule: Range 3

Details

Program Type: Hazardous Waste
Permit Status: Active
Expiration Date: 3/7/2022
Fee Schedule: LQG 5 to < 25 tons/year

---

49 | **2 of 3** | **N** | **0.20 / 1,046.83** | **123.44 / 3** | **THE HOME DEPOT #6667**
6280 HEMBREE LANE
WINDSOR CA 95492 | **EMISSIONS**

2012 Criteria Data

Facility ID: 13223
Facility SIC Code: 5211
CO: 49
Air Basin: SF
District: BA
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:
TOGT: .002
ROGT: .0016734
COT: .007
NOXT: .034
SOXT: 0
PMT: .00204918032786885245901639344262295081 9672
PM10T: .002

2012 Toxic Data

Facility ID: 13223
Facility SIC Code: 5211
CO: 49
Air Basin: SF
District: BA
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:

2013 Criteria Data

Facility ID: 13223
CERR Code:

Facility SIC Code:	5211	**TOGT:**	.004
CO:	49	**ROGT:**	.0033468
Air Basin:	SF	**COT:**	.011
District:	BA	**NOXT:**	.049
COID:	SON	**SOXT:**	0
DISN:	BAY AREA AQMD	**PMT:**	.004
CHAPIS:		**PM10T:**	.003

2013 Toxic Data

Facility ID:	13223	**COID:**	SON
Facility SIC Code:	5211	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2014 Criteria Data

Facility ID:	13223	**CERR Code:**	
Facility SIC Code:	5211	**TOGT:**	.003512826
CO:	49	**ROGT:**	
Air Basin:	SF	**COT:**	.010607999
District:	BA	**NOXT:**	.048794549
COID:	SON	**SOXT:**	.00002262
DISN:	BAY AREA AQMD	**PMT:**	.00363235
CHAPIS:		**PM10T:**	.003487056

2014 Toxic Data

Facility ID:	13223	**COID:**	SON
Facility SIC Code:	5211	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2015 Criteria Data

Facility ID:	13223	**CERR Code:**	
Facility SIC Code:	5211	**TOGT:**	.00190841
CO:	49	**ROGT:**	.001858008
Air Basin:	SF	**COT:**	.005762999
District:	BA	**NOXT:**	.02650858
COID:	SON	**SOXT:**	.000012289
DISN:	BAY AREA AQMD	**PMT:**	.000378579
CHAPIS:		**PM10T:**	.000363436

2015 Toxic Data

Facility ID:	13223	**COID:**	SON
Facility SIC Code:	5211	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			

Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

2016 Criteria Data

Facility ID:	13223	***CERR CODE:***	
Facility SIC Code:	5211	***TOGT:***	.00190841
CO:	49	***ROGT:***	.001676538185
Air Basin:	SF	***COT:***	.005762999
District:	BA	***NOXT:***	.026508581
COID:	SON	***SOXT:***	.000012289
DISN:	BAY AREA AQMD	***PMT:***	.000378579
CHAPIS:		***PM10T:***	.000363436

2016 Toxic Data

Facility ID:	13223	***TS:***	
Facility SIC Code:	5211	***HRA:***	
CERR CODE:		***CH Index:***	
COID:	SON	***AH Index:***	
CO:	49	***Air Basin:***	SF
DISN:	BAY AREA AQMD	***District:***	BA
CHAPIS:			

2018 Criteria Data

Facility ID:	13223	***CERR Code:***	
Facility SIC Code:	5211	***TOGT:***	.002776497
CO:	49	***ROGT:***	.0024391526145
Air Basin:	SF	***COT:***	.007370791
District:	BA	***NOXT:***	.034205765
COID:	SON	***SOXT:***	.000013351
DISN:	BAY AREA AQMD	***PMT:***	.00028184808853118712273641851106639839 0342
CHAPIS:		***PM10T:***	.000280157

2018 Toxic Data

Facility ID:	13223	***COID:***	SON
Facility SIC Code:	5211	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2019 Criteria Data

CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
Facility ID:	13223	***ROGT:***	.002485397733
District:	BA	***COT:***	.007651272
Facility SIC Code:	5211	***NOXT:***	.035507401
CO ID:	SON	***SOXT:***	.000013852
DISN:	BAY AREA AQMD		
PM10T:	.000290818		
TOGT:	.002829138		
PMT:	.000302935		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

2019 Toxic Data

CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
Faccility ID:	13223	***TS:***	
District:	BA	***Health Risk Asmt:***	
Facility SIC Code:	5211	***NonCncrChrnicHazInd :***	
COID:	SON	***NonCncrActeHazInd:***	
DISN:	BAY AREA AQMD		

49	*3 of 3*	*N*	*0.20 / 1,046.83*	*123.44 / 3*	***HOME DEPOT 6667*** ***6280 HEMBREE LN*** ***WINDSOR CA 95492***	***RCRA SQG***

EPA Handler ID:	CAR000168070
Gen Status Universe:	Small Quantity Generator
Contact Name:	ASHLEY CAMPBELL
Contact Address:	9950 , CHEMICAL RD , , PASADENA , TX, 77507 , US
Contact Phone No and Ext:	281-842-0809
Contact Email:	ACAMPBELL@HARSCO.COM
Contact Country:	US
County Name:	SONOMA
EPA Region:	09
Land Type:	Private
Receive Date:	20210812
Location Latitude:	38.527785
Location Longitude:	-122.786195

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Aug, 2021.

Evaluation Details

Evaluation Start Date:	20160113
Evaluation Type Description:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Violation Short Description:	
Return to Compliance Date:	
Evaluation Agency:	State

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No: 1

Receive Date: 20050622
Handler Name: HOME DEPOT USA INC HD 6667
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D016
Waste Code Description: 2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D035
Waste Code Description: METHYL ETHYL KETONE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Sequence No: 2
Receive Date: 20210812
Handler Name: HOME DEPOT 6667
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification

Waste Code Details

Hazardous Waste Code: 122
Waste Code Description: Alkaline solution without metals (pH > 12.5)

Hazardous Waste Code: 141
Waste Code Description: Off-specification, aged, or surplus inorganics

Hazardous Waste Code: 181
Waste Code Description: Other inorganic solid waste

Hazardous Waste Code: 213
Waste Code Description: Hydrocarbon solvents (benzene, hexane, Stoddard, etc.)

Hazardous Waste Code: 214
Waste Code Description: Unspecified solvent mixture

Hazardous Waste Code: 331
Waste Code Description: Off-specification, aged, or surplus organics

Hazardous Waste Code: 352
Waste Code Description: Other organic solids

Hazardous Waste Code: 791
Waste Code Description: Liquids with pH < 2

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D002
Waste Code Description: CORROSIVE WASTE

Hazardous Waste Code: D003
Waste Code Description: REACTIVE WASTE

Hazardous Waste Code: D005
Waste Code Description: BARIUM

Hazardous Waste Code: D006
Waste Code Description: CADMIUM

Hazardous Waste Code: D007
Waste Code Description: CHROMIUM

Hazardous Waste Code: D008
Waste Code Description: LEAD

Hazardous Waste Code: D009
Waste Code Description: MERCURY

Hazardous Waste Code: D010
Waste Code Description: SELENIUM

Hazardous Waste Code: D011
Waste Code Description: SILVER

Hazardous Waste Code: D016
Waste Code Description: 2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Code: D035
Waste Code Description: METHYL ETHYL KETONE

Hazardous Waste Code: F003
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: F005
Waste Code Description: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Code: U002
Waste Code Description: 2-PROPANONE (I) (OR) ACETONE (I)

Hazardous Waste Code: U240
Waste Code Description: 2,4-D, SALTS & ESTERS (OR) ACETIC ACID, (2,4-DICHLOROPHENOXY)-, SALTS & ESTERS (OR) DICHLOROPHENOXYACETIC ACID 2,4-D

Hazardous Waste Code: U279
Waste Code Description: CARBARYL (OR) 1-NAPHTHALENOL, METHYLCARBAMATE

Owner/Operator Details

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street 1:**	2455 PACES FERRY RD
Name:	HOME DEPOT USA	**Street 2:**	
Date Became Current:	20010628	**City:**	ATLANTA
Date Ended Current:		**State:**	GA
Phone:		**Country:**	US
Source Type:	Notification	**Zip Code:**	30339

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	
Name:	HOME DEPOT USA	**Street 2:**	
Date Became Current:	20010628	**City:**	
Date Ended Current:		**State:**	
Phone:		**Country:**	
Source Type:	Notification	**Zip Code:**	

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street 1:**	
Name:	HOME DEPOT USA	**Street 2:**	
Date Became Current:	20010628	**City:**	
Date Ended Current:		**State:**	
Phone:		**Country:**	US
Source Type:	Notification	**Zip Code:**	

Historical Handler Details

Receive Dt: 20050622
Generator Code Description: Small Quantity Generator
Handler Name: HOME DEPOT USA INC HD 6667

---

50 *1 of 2* *WNW* *0.21 / 1,093.88* *114.37 / -6* ***Best Truck Body***
600 Caletti Ave Windsor, CA 95492
CA ***CUPA SONOMA***

Facility ID: 49-000-008547 **CERS ID:** 10752562

Details

Program Type: Stormwater
Permit Status: Active
Expiration Date: 3/8/2021
Fee Schedule: Storm Water Permit

Details

Program Type: HMBP
Permit Status: Active
Expiration Date: 3/8/2021
Fee Schedule: Range 2

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
50	2 of 2	WNW	0.21 / 1,093.88	114.37 / -6	BEST TRUCK BODY INC. 600 CALETTI AVE WINDSOR CA 95492	RCRA NON GEN

EPA Handler ID: CAC003054328
Gen Status Universe: No Report
Contact Name: DOMINICK TARANTINO
Contact Address: 600 CALETTI AVE. , , WINDSOR , CA, 95492 ,
Contact Phone No and Ext: 707-536-5298
Contact Email: BESTTRUCKBODY@GMAIL.COM
Contact Country:
County Name: SONOMA
EPA Region: 09
Land Type:
Receive Date: 20200205
Location Latitude:
Location Longitude:

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20200205
Handler Name: BEST TRUCK BODY INC.
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Other
Name: DOMINICK TARANTINO
Date Became Current:
Date Ended Current:
Phone: 707-536-5298
Source Type: Implementer
Street No:
Street 1: 600 CALETTI AVE.
Street 2:
City: WINDSOR
State: CA
Country:
Zip Code: 95492

Owner/Operator Ind: Current Owner
Type: Other
Name: RUSSELL MORECI
Street No:
Street 1: P.O. BOX 2283
Street 2:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Date Became Current:
Date Ended Current:
Phone: 707-953-9742
Source Type: Implementer
City: WINDSOR
State: CA
Country:
Zip Code: 95492

---

51 **1 of 2** **NNW** **0.21 / 1,093.99** **114.39 / -6**

Les Schwab Tire Center #635
6700 Hembree Ln Windsor, CA 95492
CA

CUPA SONOMA

Facility ID: 49-000-008054
CERS ID: 10401802

Details

Program Type: HMBP
Permit Status: Inactive
Expiration Date:
Fee Schedule:

Details

Program Type: Hazardous Waste
Permit Status: Active
Expiration Date: 5/31/2020
Fee Schedule: SQG < 325 gallons/year

---

51 **2 of 2** **NNW** **0.21 / 1,093.99** **114.39 / -6**

LES SCHWAB TIRES CENTERS OF CA, INC.
6700 HEMBREE LN
WINDSOR CA 95492

RCRA NON GEN

EPA Handler ID: CAL000255334
Gen Status Universe: No Report
Contact Name: SCOTT KNUTZ
Contact Address: PO BOX 5350 , , BEND , OR, 97708 ,
Contact Phone No and Ext: 541-416-5514
Contact Email: SCOTT.W.KNUTZ@LESSCHWAB.COM
Contact Country:
County Name: SONOMA
EPA Region: 09
Land Type:
Receive Date: 20020709
Location Latitude: 38.529144
Location Longitude: -122.792009

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No

Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20020709
Handler Name: LES SCHWAB TIRES CENTERS OF CA, INC.
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Other
Name: SCOTT KNUTZ
Date Became Current:
Date Ended Current:
Phone: 541-416-5514
Source Type: Implementer
Street No:
Street 1: PO BOX 5350
Street 2:
City: BEND
State: OR
Country:
Zip Code: 97708

Owner/Operator Ind: Current Owner
Type: Other
Name: LES SCHWAB INC
Date Became Current:
Date Ended Current:
Phone: 541-447-4136
Source Type: Implementer
Street No:
Street 1: 20900 COOLEY RD
Street 2: PO BOX 5350
City: BEND
State: OR
Country:
Zip Code: 97701

52	1 of 6	SSE	0.22 / 1,146.01	122.62 / 3	LITHOCRAFT INC 424 AVIATION BLVD SANTA ROSA CA 95403	RCRA SQG

EPA Handler ID: CAD983635954
Gen Status Universe: Small Quantity Generator
Contact Name: HAROLD LANGFORD
Contact Address: 424 AVIATION BLVD , , SANTA ROSA , CA, 95403 , US
Contact Phone No and Ext: 707-544-8681
Contact Email:
Contact Country: US
County Name: SONOMA
EPA Region: 09
Land Type: Private
Receive Date: 19920511
Location Latitude: 38.514756
Location Longitude: -122.785713

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 19920511
Handler Name: LITHOCRAFT INC
Federal Waste Generator Code: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: JACK FAIRCLOUGH AND TONY LANDEN
Date Became Current:
Date Ended Current:
Phone: 707-544-8681
Source Type: Notification
Street No:
Street 1: 424 AVIATION BLVD
Street 2:
City: SANTA ROSA
State: CA
Country:
Zip Code: 95403

52	*2 of 6*	*SSE*	*0.22 / 1,146.01*	*122.62 / 3*	***Lithocraft, Inc.*** ***424 Aviation Blvd. SANTA ROSA, CA 95403*** ***CA***	***DELISTED COUNTY***

Original Source Facility ID:
Original Source Name: Sonoma County CUPA Facilities List
Record Date: 11-JAN-2016

52	*3 of 6*	*SSE*	*0.22 / 1,146.01*	*122.62 / 3*	***L-3 SONOMA EO*** ***424 AVIATION BLVD SANTA ROSA, CA 95403*** ***CA***	***DELISTED COUNTY***

Original Source Facility ID:
Original Source Name: Sonoma County CUPA Facilities List
Record Date: 11-JAN-2016

52	*4 of 6*	*SSE*	*0.22 / 1,146.01*	*122.62 / 3*	***L-3 SONOMA EO*** ***424 AVIATION BLVD SANTA ROSA, CA 95403*** ***CA***	***CUPA SONOMA***

Facility ID: 49-000-008293
CERS ID:

Details

Program Type: Hazardous Waste
Permit Status: Inactive
Expiration Date: 11/19/2016
Fee Schedule: SQG < 325 gallons/year

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Details

Program Type:	HMBP
Permit Status:	Inactive
Expiration Date:	11/19/2015
Fee Schedule:	Range 2

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
52	5 of 6	SSE	0.22 / 1,146.01	122.62 / 3	LITHOCRAFT, INC 424 AVIATION BOULEVARD SANTA ROSA CA 95403	EMISSIONS

1993 Criteria Data

Facility ID:	6944	***CERR Code:***	
Facility SIC Code:	2752	***TOGT:***	6.1
CO:	49	***ROGT:***	5.12734
Air Basin:	SF	***COT:***	
District:	BA	***NOXT:***	
COID:	SON	***SOXT:***	
DISN:	BAY AREA AQMD	***PMT:***	
CHAPIS:		***PM10T:***	

1993 Toxic Data

Facility ID:	6944	***COID:***	SON
Facility SIC Code:	2752	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

1995 Criteria Data

Facility ID:	6944	***CERR Code:***	
Facility SIC Code:	2752	***TOGT:***	8.7
CO:	49	***ROGT:***	7.48706
Air Basin:	SF	***COT:***	
District:	BA	***NOXT:***	
COID:	SON	***SOXT:***	
DISN:	BAY AREA AQMD	***PMT:***	
CHAPIS:		***PM10T:***	

1995 Toxic Data

Facility ID:	6944	***COID:***	SON
Facility SIC Code:	2752	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

1996 Criteria Data

Facility ID:	6944	***CERR Code:***	

Facility SIC Code:	2752	**TOGT:**	8.7
CO:	49	**ROGT:**	7.48706
Air Basin:	SF	**COT:**	
District:	BA	**NOXT:**	
COID:	SON	**SOXT:**	
DISN:	BAY AREA AQMD	**PMT:**	
CHAPIS:		**PM10T:**	

1996 Toxic Data

Facility ID:	6944	**COID:**	SON
Facility SIC Code:	2752	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

1997 Criteria Data

Facility ID:	6944	**CERR Code:**	
Facility SIC Code:	2752	**TOGT:**	12.8
CO:	49	**ROGT:**	10.89748
Air Basin:	SF	**COT:**	
District:	BA	**NOXT:**	
COID:	SON	**SOXT:**	
DISN:	BAY AREA AQMD	**PMT:**	
CHAPIS:		**PM10T:**	

1997 Toxic Data

Facility ID:	6944	**COID:**	SON
Facility SIC Code:	2752	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

1998 Criteria Data

Facility ID:	6944	**CERR Code:**	
Facility SIC Code:	2752	**TOGT:**	19.2
CO:	49	**ROGT:**	16.39664
Air Basin:	SF	**COT:**	
District:	BA	**NOXT:**	
COID:	SON	**SOXT:**	
DISN:	BAY AREA AQMD	**PMT:**	
CHAPIS:		**PM10T:**	

1998 Toxic Data

Facility ID:	6944	**COID:**	SON
Facility SIC Code:	2752	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			

Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

1999 Criteria Data

Facility ID:	6944	***CERR Code:***	
Facility SIC Code:	2752	***TOGT:***	15.219
CO:	49	***ROGT:***	12.1872174
Air Basin:	SF	***COT:***	
District:	BA	***NOXT:***	
COID:	SON	***SOXT:***	
DISN:	BAY AREA AQMD	***PMT:***	
CHAPIS:		***PM10T:***	

1999 Toxic Data

Facility ID:	6944	***COID:***	SON
Facility SIC Code:	2752	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
District:	BA		

TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

2000 Criteria Data

Facility ID:	6944	***CERR Code:***	
Facility SIC Code:	2752	***TOGT:***	15.219
CO:	49	***ROGT:***	12.2
Air Basin:	SF	***COT:***	
District:	BA	***NOXT:***	
COID:	SON	***SOXT:***	
DISN:	BAY AREA AQMD	***PMT:***	
CHAPIS:		***PM10T:***	

2000 Toxic Data

Facility ID:	6944	***COID:***	SON
Facility SIC Code:	2752	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
District:	BA		

TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

2001 Criteria Data

Facility ID:	6944	***CERR Code:***	
Facility SIC Code:	2752	***TOGT:***	13.5
CO:	49	***ROGT:***	11.45
Air Basin:	SF	***COT:***	
District:	BA	***NOXT:***	
COID:	SON	***SOXT:***	
DISN:	BAY AREA AQMD	***PMT:***	
CHAPIS:	Y	***PM10T:***	

2001 Toxic Data

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility ID:	6944	**COID:**	SON
Facility SIC Code:	2752	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	Y
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2002 Criteria Data

Facility ID:	6944	**CERR Code:**	
Facility SIC Code:	2752	**TOGT:**	13.635
CO:	49	**ROGT:**	11.5586734
Air Basin:	SF	**COT:**	
District:	BA	**NOXT:**	
COID:	SON	**SOXT:**	
DISN:	BAY AREA AQMD	**PMT:**	
CHAPIS:	Y	**PM10T:**	

2002 Toxic Data

Facility ID:	6944	**COID:**	SON
Facility SIC Code:	2752	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	Y
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2003 Criteria Data

Facility ID:	6944	**CERR Code:**	
Facility SIC Code:	2752	**TOGT:**	13.635
CO:	49	**ROGT:**	11.55
Air Basin:	SF	**COT:**	
District:	BA	**NOXT:**	
COID:	SON	**SOXT:**	
DISN:	BAY AREA AQMD	**PMT:**	
CHAPIS:	Y	**PM10T:**	

2003 Toxic Data

Facility ID:	6944	**COID:**	SON
Facility SIC Code:	2752	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	Y
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

52	***6 of 6***	***SSE***	***0.22 / 1,146.01***	***122.62 / 3***	***SONOMA EO 424 AVIATION BLVD SANTA ROSA CA 95403-1069***	***RCRA NON GEN***

EPA Handler ID:	CAL000298612
Gen Status Universe:	No Report
Contact Name:	THOMAS LAWSON

Contact Address:	424 AVIATION BLVD , , SANTA ROSA , CA, 95403 ,
Contact Phone No and Ext:	707-568-3000
Contact Email:	TOMLAWSON@L3T.COM
Contact Country:	
County Name:	SONOMA
EPA Region:	09
Land Type:	
Receive Date:	20050920
Location Latitude:	38.514756
Location Longitude:	-122.785713

Violation/Evaluation Summary

Note:	NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20050920
Handler Name:	SONOMA EO
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Other	**Street 1:**	600 THIRD AVE
Name:	L3 COMMUNICATIONS	**Street 2:**	
Date Became Current:		**City:**	NEW YORK
Date Ended Current:		**State:**	NY
Phone:	212-697-1111	**Country:**	
Source Type:	Implementer	**Zip Code:**	10016-0000
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Other	**Street 1:**	424 AVIATION BLVD
Name:	THOMAS LAWSON	**Street 2:**	
Date Became Current:		**City:**	SANTA ROSA
Date Ended Current:		**State:**	CA
Phone:	707-568-3000	**Country:**	
Source Type:	Implementer	**Zip Code:**	95403

53	*1 of 9*	*NNE*	*0.22 / 1,147.56*	*124.46 / 4*	***Shiloh Center Shell 6301 Hembree Ln***	***DELISTED TNK***

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					Windsor CA 95492	

Delisted Storage Tanks

Facility ID: 49-000-005989
Permitting Agency: SONOMA COUNTY
County: Sonoma
Latitude: 38.52645
Longitude: -122.78714
Original Source: UST
Record Date: 30-JAN-2017

53	2 of 9	NNE	0.22 / 1,147.56	124.46 / 4	Hembree Shell #130 6301 Hembree Ln Windsor, CA 95492 CA	CUPA SONOMA

Facility ID: 49-000-005989 ***CERS ID:*** 10108264

Details

Program Type: UST
Permit Status: Active
Expiration Date: 7/23/2022
Fee Schedule: Permit to Operate - 3 tanks

Details

Program Type: Hazardous Waste
Permit Status: Active
Expiration Date: 7/23/2022
Fee Schedule: SQG > 325 gallons/year to <5 tons/year w/source reduction/recycle

Details

Program Type: HMBP
Permit Status: Active
Expiration Date: 7/23/2022
Fee Schedule: Range 2

53	3 of 9	NNE	0.22 / 1,147.56	124.46 / 4	SHELL SERVICE STATION 6301 HEMBREE LANE WINDSOR CA 95492	CLEANUP SITES

Global ID: SL0609779948 ***Latitude:*** 38.526115
Status: COMPLETED - CASE CLOSED ***Longitude:*** -122.786332
Status Date: 1/19/2005 ***County:*** SONOMA
Site Facility Type: CLEANUP PROGRAM SITE
Data Source: Cleanup Program Sites from GeoTracker Search; Cleanup Sites from GeoTracker Cleanup Sites Data Download

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail

RB Case No: 1NSO853 ***Stop Method:***
Local Case No: ***CUF Case:*** NO
Begin Date: 5/13/2002 ***Case Worker:*** ZZZ
File Location: Regional Board
Lead Agency: NORTH COAST RWQCB (REGION 1)
Local Agency:
Potential COC: * Petroleum - Diesel fuels
Potential Media of Concern: Aquifer used for drinking water supply

How Discovered: * Other Means
How Discovered Description: SUBSURFACE MONITORING
Stop Description:
CalWater Watershed Name: Russian River - Middle Russian River - Mark West (114.23)
DWR GW Subbasin Name: Santa Rosa Valley - Santa Rosa Plain (1-055.01)
Disadvantaged Community:
CalEnviroScreen Score: 26-30%
Site History:

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity

Action Type: ENFORCEMENT
Date: 2005-01-19 00:00:00
Action: Closure/No Further Action Letter

Action Type: RESPONSE
Date: 2004-12-17 00:00:00
Action: Unknown

Action Type: ENFORCEMENT
Date: 2004-11-16 00:00:00
Action: Notification - Preclosure

Action Type: RESPONSE
Date: 2004-10-15 00:00:00
Action: Monitoring Report - Quarterly

Action Type: RESPONSE
Date: 2004-07-15 00:00:00
Action: Monitoring Report - Quarterly

Action Type: RESPONSE
Date: 2004-04-15 00:00:00
Action: Monitoring Report - Quarterly

Action Type: RESPONSE
Date: 2004-01-15 00:00:00
Action: Monitoring Report - Quarterly

Action Type: RESPONSE
Date: 2003-12-01 00:00:00
Action: Sensitive Receptor Survey Report

Action Type: RESPONSE
Date: 2003-12-01 00:00:00
Action: Monitoring Report - Quarterly

Action Type: ENFORCEMENT
Date: 2003-09-18 00:00:00
Action: Staff Letter

Action Type: ENFORCEMENT
Date: 2003-07-14 00:00:00
Action: * No Action

Action Type: ENFORCEMENT
Date: 2003-05-13 00:00:00
Action: * No Action

Action Type: RESPONSE
Date: 2003-03-28 00:00:00
Action: Preliminary Site Assessment Report

Action Type: RESPONSE
Date: 2003-03-10 00:00:00
Action: Unauthorized Release Form

Action Type: Other
Date: 2003-02-12 00:00:00
Action: Leak Reported

Action Type: Other
Date: 2003-02-06 00:00:00
Action: Leak Discovery

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History

Status: Completed - Case Closed
Status Date: 2005-01-19 00:00:00

Status: Open - Verification Monitoring
Status Date: 2003-09-13 00:00:00

Status: Open - Case Begin Date
Status Date: 2002-05-13 00:00:00

Status: Open - Site Assessment
Status Date: 2002-05-13 00:00:00

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts

Contact Type: Regional Board Caseworker
Contact Name: REGIONAL WATER BOARD SITE CLOSED
Phone No: 7075762220
Organization Name: NORTH COAST RWQCB (REGION 1)
Email:
Address: 5550 SKYLANE BOULEVARD, SUITE A
City: SANTA ROSA

Cleanup Program Sites from GeoTracker Search - Regulatory Profile (as of May 29, 2021)

Project Status:
Cuf Claim No:
CUF Priority Assign:
CUF Amount Paid:
Composting Method:
File Location: REGIONAL BOARD
User Defined Beneficial Use:
Designated Beneficial Use: MUN, AGR, IND, PROC, FRSH, CUL, AQUA - Note: R1 BP- all gw same uses.
Designated Beneficl Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply, Freshwater Replenishment, Native American Culture, AQUA - Note: R1 BP- all gw same uses.
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=SL0609779948
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 1/19/2005
Potential COC: PETROLEUM - DIESEL FUELS
Potential Media of Concern: AQUIFER USED FOR DRINKING WATER SUPPLY
Groundwater Monitoring Frequen:
DWR GW Sub Basin: Santa Rosa Valley - Santa Rosa Plain (1-055.01)
CalWater Watershed Name: Russian River - Middle Russian River - Mark West (114.23)
Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: NORTH COAST RWQCB (REGION 1) (LEAD) - CASE #: 1NSO853
CASEWORKER: REGIONAL WATER BOARD SITE CLOSED
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=SL0609779948&tabname=regulatoryhistory
Site History:

No site history available

Facility Type:
WDR Place Type:
Wdr File No:
Wdr Order No:

Sites from GeoTracker Search - Regulatory Activities (as of May 29, 2021)

Action Type: Other Regulatory Actions

Action Date: 1/19/2005
Received Issue Date: 1/19/2005
Action: Closure/No Further Action Letter
Doc Link:
Title Description Comments:

Action Type: Response Requested - Other
Action Date: 12/17/2004
Received Issue Date: 12/17/2004
Action: Unknown
Doc Link:
Title Description Comments:

- Well destruction report

Action Type: Notices
Action Date: 11/16/2004
Received Issue Date: 11/16/2004
Action: Notification - Preclosure
Doc Link:
Title Description Comments:

Action Type: Response Requested - Reports
Action Date: 10/15/2004
Received Issue Date: 10/1/2004
Action: Monitoring Report - Quarterly
Doc Link:
Title Description Comments:

Monitoring Report - Quarterly - 3rd Qrt 2004 QMR

Action Type: Response Requested - Reports
Action Date: 7/15/2004
Received Issue Date: 8/24/2004
Action: Monitoring Report - Quarterly
Doc Link:
Title Description Comments:

Monitoring Report - Quarterly - 2nd Qrt 2004 QMR

Action Type: Response Requested - Reports
Action Date: 4/15/2004
Received Issue Date: 4/23/2004
Action: Monitoring Report - Quarterly
Doc Link:
Title Description Comments:

Monitoring Report - Quarterly - 1st Qrt 2004 QMR

Action Type: Response Requested - Reports
Action Date: 1/15/2004
Received Issue Date: 2/25/2004
Action: Monitoring Report - Quarterly
Doc Link:
Title Description Comments:

Monitoring Report - Quarterly - 4th Qrt 2003 QMR

Action Type: Response Requested - Reports
Action Date: 12/1/2003
Received Issue Date: 12/4/2003
Action: Sensitive Receptor Survey Report
Doc Link:

Title Description Comments:

Sensitive Receptor Survey Report - Sensitive Receptor Survey

Action Type: Response Requested - Reports
Action Date: 12/1/2003
Received Issue Date: 11/24/2003
Action: Monitoring Report - Quarterly
Doc Link:
Title Description Comments:

Monitoring Report - Quarterly

Action Type: Other Regulatory Actions
Action Date: 9/18/2003
Received Issue Date: 9/18/2003
Action: Staff Letter
Doc Link:
Title Description Comments:

Action Type: Enforcement - Other
Action Date: 7/14/2003
Received Issue Date: 7/14/2003
Action: * No Action
Doc Link:
Title Description Comments:

Action Type: Enforcement - Other
Action Date: 5/13/2003
Received Issue Date: 5/13/2003
Action: * No Action
Doc Link:
Title Description Comments:

Action Type: Response Requested - Reports
Action Date: 3/28/2003
Received Issue Date: 3/28/2003
Action: Preliminary Site Assessment Report
Doc Link:
Title Description Comments:

Preliminary Site Assessment Report

Action Type: Response Requested - Other
Action Date: 3/10/2003
Received Issue Date: 3/10/2003
Action: Unauthorized Release Form
Doc Link:
Title Description Comments:

Unauthorized Release Form - UNSURE IF TANK RELEASE OR OTHER.

Action Type: Leak Action
Action Date: 2/12/2003
Received Issue Date:
Action: Leak Reported
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action Date: 2/6/2003
Received Issue Date:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Action: Leak Discovery
Doc Link:
Title Description Comments:

Sites from GeoTracker Search - Cleanup Status History (as of May 29, 2021)

Status: Completed - Case Closed
Date: 1/19/2005

Status: Open - Verification Monitoring
Date: 9/13/2003

Status: Open - Site Assessment
Date: 5/13/2002

Status: Open - Case Begin Date
Date: 5/13/2002

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
53	4 of 9	NNE	0.22 / 1,147.56	124.46 / 4	Hembree Shell #130 6301 HEMBREE LN WINDSOR CA 95492	CERS TANK

Site ID: 122176
Latitude: 38.526116
Longitude: -122.786340

Regulated Programs

EI ID: 10108264
EI Description: Underground Storage Tank

EI ID: 10108264
EI Description: Chemical Storage Facilities

EI ID: 10108264
EI Description: Hazardous Waste Generator

Violations

Violation Date: 07/11/2013
Violation Source: CERS
Violation Program: UST
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: 23 CCR 16 2637(e) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2637(e)
Violation Notes:

Returned to compliance on 08/05/2013.

Violation Description:

Failure to submit a copy of the secondary containment test results to the CUPA within 30 days after the test.

Violations

Violation Date: 09/01/2016
Violation Source: CERS
Violation Program: UST
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: 23 CCR 16 2632, 2634, 2712(b) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2632, 2634, 2712(b)
Violation Notes:

Returned to compliance on 10/10/2016. The "Flammable Vapors - No Smoking" sign on the vapor recovery tank is faded. Provide a new "Flammable Vapors - No Smoking" sign on the UST vapor recovery tank near the vent stacks.

Violation Description:

Failure to maintain monitoring and maintenance records (e.g., alarm logs) and/or maintain records of appropriate follow-up actions.

Violations

Violation Date: 07/03/2019
Violation Source: CERS
Violation Program: HW
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: HSC 6.5 25123.3(h)(1) - California Health and Safety Code, Chapter 6.5, Section(s) 25123.3(h)(1)
Violation Notes:

Returned to compliance on 07/07/2020. Owner/Operator is a small quantity generator and failed to send hazardous waste offsite for treatment, storage, or disposal within 180 days (or 270 days if waste is transported over 200 miles), or has failed to comply with the conditions of CCR 66262.34(d) and has stored hazardous waste over 90 days. Dispose of hazardous waste that has been stored over the applicable time limit and provide documentation that the violation has been corrected.

Violation Description:

Failure to send hazardous waste offsite for treatment, storage, or disposal within 180 days (or 270 days if waste is transported over 200 miles) for a generator who generates less than 1000 kilogram per month if all of the following conditions are met:
(1) The quantity of hazardous waste accumulated onsite never exceeds 6,000 kilograms.

(2) The generator complies with the requirements of 40 Code of Federal Regulations section 262.34(d), (e) and (f).

(3) The generator does not hold acutely hazardous waste or extremely hazardous waste in an amount greater than one kilogram for more than 90 days.

Violations

Violation Date: 07/03/2019
Violation Source: CERS
Violation Program: HW
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: 22 CCR 12 66262.34(f) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(f)
Violation Notes:

Returned to compliance on 07/03/2019. [55 gallon Drum] of [HAZARDOUS WASTE] located in the [carwash area] was observed without a hazardous waste label. Submit a photo to the CUPA demonstrating that the container listed above has been properly labeled. (Corrected on site)

Violation Description:

Failure to properly label hazardous waste accumulation containers and portable tanks with the following requirements: "Hazardous Waste", name and address of the generator, physical and chemical characteristics of the Hazardous Waste, and starting accumulation date.

Violations

Violation Date: 07/10/2014
Violation Source: CERS
Violation Program: UST
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: 23 CCR 16 2715(f) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2715(f)
Violation Notes:

CORRECTIVE ACTION: Ensure all employees have received annual hazmat refresher training and all employees hired receive training within 30 days of employment.

Violation Description:

Failure to comply with one or more of the following: provide training to facility employee(s) responsible for proper operation and maintenance every 12 months

and/or

train new employee(s) who are responsible for proper operation and maintenance within 30-days of hire

and/or

to have at least one employee present during operating hours that has been trained in the proper operation and maintenance of the UST system.

Violations

Violation Date: 07/07/2020
Violation Source: CERS
Violation Program: UST
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: 23 CCR 16 2636(f)(2) - California Code of Regulations, Title 23, Chapter 16, Section(s) 2636(f)(2)
Violation Notes:

Returned to compliance on 07/10/2020. Diesel Line Leak Detector Siphon valve broken in Turbine Head. Replace necessary components and retest within seven days or diesel dispensers will be red tagged

Violation Description:

Failure of the functional line leak detector (LLD) monitoring pressurized piping to meet one or more of the following requirements: Monitored at least hourly with the capability of detecting a release of 3.0 gallons per hour leak at 10 pounds per square inch and restrict or shut off the flow of product through the piping when a leak is detected.

Violations

Violation Date: 07/11/2013
Violation Source: CERS
Violation Program: HW
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: 22 CCR 12 66262.34(d) - California Code of Regulations, Title 22, Chapter 12, Section(s) 66262.34(d)
Violation Notes:

Returned to compliance on 08/10/2013.

Violation Description:

Failure to dispose of hazardous waste within 180 days (or 270 if waste is transported over 200 miles) for the generator who generates less than 1000 kilogram per month, but more than 100 kilograms per month.

Violations

Violation Date: 09/01/2016
Violation Source: CERS
Violation Program: UST
Violation Division: Sonoma County Fire & Emergency Services Department
Citation: 23 CCR 16 2665 - California Code of Regulations, Title 23, Chapter 16, Section(s) 2665
Violation Notes:

Returned to compliance on 10/12/2016.

Violation Description:

Failure to comply with one or more of the following:

Failure to install or maintain a liquid-tight spill bucket.

Have a minimum capacity of five gallons.

Have a functional drain valve or other method for the removal of liquid from the spill bucket/spill container.

Be resistant to galvanic corrosion.

Evaluations

Eval Date: 07/09/2015
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency

Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

No violations noted - all systems passed with PSD and/or A/V alarms. LLDs passed. Spill buckets passed. D/O log book reviewed - complete monthly reports, D/O form and employee training.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 09/01/2016
Violations Found: Yes
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: UST
Eval Source: CERS
Eval Notes:

Eval Date: 07/03/2019
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

Eval Date: 07/07/2020
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: UST
Eval Source: CERS
Eval Notes:

Remove liquid from Hazardous materials drums near car wash; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 07/06/2017
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: UST
Eval Source: CERS
Eval Notes:

All systems passed as designed or programmed. D/O log book and employee training complete and current. No violations noted.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 12/26/2019
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: UST
Eval Source: CERS
Eval Notes:

Drop tube replacement; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 07/11/2013
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency

Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: UST
Eval Source: CERS
Eval Notes:

Eval Date: 07/21/2016
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: UST
Eval Source: CERS
Eval Notes:

Cold start conducted on 3 USTs with brine annulars. All STP sump, fill sump, annular high/low, and UDC sensors were tested and passed with positive shutdown and/or audible visual alarms. Also tested sensor out, failsafe and emergency shut off - passed. Electronic line leak detectors passed at 3 GPH leak rate @ 10 PSI pressure. No violations noted.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 07/07/2016
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

Eval Date: 05/23/2016
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: UST
Eval Source: CERS
Eval Notes:

Reviewed SB989 testing performed by James Moore of Able Maintenance.; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 07/11/2013
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HW
Eval Source: CERS
Eval Notes:

Eval Date: 07/03/2019
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Eval Date: 07/03/2018
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: UST
Eval Source: CERS

Eval Notes:

Witnessed UST monitoring cert conducted by Sammy with Able Maintenance. Tested power down - PSD activated. Tested sensor out - PSD activated. Tested 3 X turbine sump sensors in water - PSD activated. Tested 5 X dispenser sensors - PSD activated. Tested 3 X fill sump sensors & 3 X annular sensors - audible & visual alarms activatted. Tested 87, 91 & diesel PLLDs - OK - flow limited. Tested 3 X spill buckets - OK - passed 1-hour tests. Tested ESO - OK - PSD activated. Checked DO training records - OK - employee training conducted & documented. Checked DO inspection records - OK. Monthly DO inspections conducted & documented. CERS submitted OK - next certification due by 2/2/19. Certificate of Financial Responsibility expires on 3/1/19. No violations; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 07/03/2019
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: UST
Eval Source: CERS
Eval Notes:

Notice water in the sumps (Reg, Prem, DSL); Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 07/10/2020
Violations Found: No
Eval General Type: Other/Unknown
Eval Type: Other, not routine, done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: UST
Eval Source: CERS
Eval Notes:

Turbine head and motor replaced. Detector working as designed; Note: data in [EVAL Notes] field for some records is truncated from the source.

Eval Date: 07/10/2014
Violations Found: Yes
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: UST
Eval Source: CERS
Eval Notes:

Eval Date: 07/07/2016
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: UST
Eval Source: CERS
Eval Notes:

Eval Date: 07/07/2016
Violations Found: No
Eval General Type: Compliance Evaluation Inspection
Eval Type: Routine done by local agency
Eval Division: Sonoma County Fire & Emergency Services Department
Eval Program: HMRRP
Eval Source: CERS
Eval Notes:

Affiliations

Affil Type Desc: Parent Corporation
Entity Name: AU Energy LLC
Entity Title:

Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Property Owner
Entity Name: AU Energy, LLC
Entity Title:
Address: 41805 Albrae Street
City: Fremont
State: CA
Country: United States
Zip Code: 94538
Phone: (510) 657-9150

Affil Type Desc: Identification Signer
Entity Name: Sunny Goyal
Entity Title: Project Manager
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: Environmental Contact
Entity Name: Sunny Goyal
Entity Title:
Address: 41805 Albrae Street
City: Fremont
State: CA
Country:
Zip Code: 94538
Phone:

Affil Type Desc: UST Tank Owner
Entity Name: AU Energy, LLC
Entity Title:
Address: 41805 Albrae St
City: Fremont
State: CA
Country: United States
Zip Code: 94538
Phone: (510) 657-9150

Affil Type Desc: Legal Owner
Entity Name: AU Energy, LLC
Entity Title:
Address: 41805 Albrae Street
City: Fremont
State: CA
Country: United States
Zip Code: 94538
Phone: (510) 657-9150

Affil Type Desc: Document Preparer
Entity Name: Stantec Consulting Services Inc.
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone:

Affil Type Desc: UST Permit Applicant
Entity Name: Sunny Goyal

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Entity Title: Project Manager
Address:
City:
State:
Country:
Zip Code:
Phone: (510) 657-9150

Affil Type Desc: UST Property Owner Name
Entity Name: AU Energy, LLC
Entity Title:
Address: 41805 Albrae Street
City: Fremont
State: CA
Country: United States
Zip Code: 94538
Phone: (510) 657-9150

Affil Type Desc: Facility Mailing Address
Entity Name: Mailing Address
Entity Title:
Address: 41805 Albrae Street
City: Fremont
State: CA
Country:
Zip Code: 94538
Phone:

Affil Type Desc: Operator
Entity Name: AU Energy, LLC
Entity Title:
Address:
City:
State:
Country:
Zip Code:
Phone: (510) 657-9150

Affil Type Desc: UST Tank Operator
Entity Name: AU Energy, LLC
Entity Title:
Address: 41805 Albrae St
City: Fremont
State: CA
Country: United States
Zip Code: 94538
Phone: (510) 657-9150

Affil Type Desc: CUPA District
Entity Name: Sonoma County Fire Prevention and Hazmat
Entity Title:
Address: 2300 County Center Drive, Suite 220-B
City: Santa Rosa
State: CA
Country:
Zip Code: 95403
Phone: (707) 565-2024

Coordinates

Env Int Type Code: HWG
Program ID: 10108264
Latitude: 38.526115
Longitude: -122.786339
Coord Name:
Ref Point Type Desc: Unknown

53	5 of 9	NNE	0.22 / 1,147.56	124.46 / 4	Hembree Shell #130 6301 Hembree Ln Windsor CA 95492	UST

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility ID: 49-000-005989
CERS ID: 10108264
County: Sonoma
Latitude: 38.526116
Longitude: -122.78634
Permitting Agency: Sonoma County Fire & Emergency Services Department
Note: Information related to facilities can be searched on Geo Tracker Website: https://geotracker.waterboards.ca.gov/search
Site Facility Type: PERMITTED UNDERGROUND STORAGE TANK (UST)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
53	6 of 9	NNE	0.22 / 1,147.56	124.46 / 4	AU ENERGY-HEMBREE SHELL 6301 HEMBREE LN WINDSOR CA 95492-6856	RCRA NON GEN

EPA Handler ID: CAL000350865
Gen Status Universe: No Report
Contact Name: JORGE IZEPPI
Contact Address: 41805 ALBRAE ST , , FREMONT , CA, 94538 ,
Contact Phone No and Ext: 510-270-3457
Contact Email: JORGE@VINTNERSDIST.COM
Contact Country:
County Name: SONOMA
EPA Region: 09
Land Type:
Receive Date: 20100315
Location Latitude: 38.52612
Location Longitude: -122.786555

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20100315
Handler Name: AU ENERGY-HEMBREE SHELL
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Other
Street No:
Street 1: 41805 ALBRAE ST

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Name:	AU ENERGY LLC	**Street 2:**	
Date Became Current:		**City:**	FREMONT
Date Ended Current:		**State:**	CA
Phone:	510-270-3457	**Country:**	
Source Type:	Implementer	**Zip Code:**	94538-3120
Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Other	**Street 1:**	41805 ALBRAE ST
Name:	JORGE IZEPPI	**Street 2:**	
Date Became Current:		**City:**	FREMONT
Date Ended Current:		**State:**	CA
Phone:	510-270-3457	**Country:**	
Source Type:	Implementer	**Zip Code:**	94538

53	7 of 9	NNE	0.22 / 1,147.56	124.46 / 4	**SHELL OIL PRODUCTS SAP 166257** **6301 HEMBREE LN** **WINDSOR CA 95492**	**RCRA NON GEN**

EPA Handler ID:	CAR000189530
Gen Status Universe:	No Report
Contact Name:	TESSA BEMIS
Contact Address:	12700 NORTHBOROUGH , RM 300 F07 , HOUSTON , TX, 77067 , US
Contact Phone No and Ext:	214-483-5460
Contact Email:	TESSA.BEMIS@GHD.COM
Contact Country:	US
County Name:	SONOMA
EPA Region:	09
Land Type:	Private
Receive Date:	20181217
Location Latitude:	
Location Longitude:	

Violation/Evaluation Summary

Note:	NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20080111
Handler Name:	SHELL OIL PRODUCTS SAP 166257
Source Type:	Notification
Federal Waste Generator Code:	2
Generator Code Description:	Small Quantity Generator

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Waste Code Details

Hazardous Waste Code: D001
Waste Code Description: IGNITABLE WASTE

Hazardous Waste Code: D018
Waste Code Description: BENZENE

Hazardous Waste Handler Details

Sequence No: 1
Receive Date: 20181217
Handler Name: SHELL OIL PRODUCTS SAP 166257
Source Type: Deactivation
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: SHELL OIL PRODUCTS US
Date Became Current: 19980801
Date Ended Current:
Phone:
Source Type: Deactivation
Street No:
Street 1:
Street 2:
City:
State:
Country:
Zip Code:

Owner/Operator Ind: Current Owner
Type: Private
Name: SHELL OIL PRODUCTS US
Date Became Current: 19980801
Date Ended Current:
Phone:
Source Type: Deactivation
Street No:
Street 1: PO BOX 2099
Street 2:
City: HOUSTON
State: TX
Country: US
Zip Code: 77252

Owner/Operator Ind: Current Owner
Type: Private
Name: SHELL OIL PRODUCTS US
Date Became Current: 19980801
Date Ended Current:
Phone:
Source Type: Notification
Street No:
Street 1: PO BOX 2099
Street 2:
City: HOUSTON
State: TX
Country: US
Zip Code: 77252

Owner/Operator Ind: Current Operator
Type: Private
Name: SHELL OIL PRODUCTS US
Date Became Current: 19980801
Date Ended Current:
Phone:
Source Type: Notification
Street No:
Street 1:
Street 2:
City:
State:
Country:
Zip Code:

Historical Handler Details

Receive Dt: 20080111
Generator Code Description: Small Quantity Generator
Handler Name: SHELL OIL PRODUCTS SAP 166257

53	8 of 9	NNE	0.22 / 1,147.56	124.46 / 4	HEMBREE SHELL 6301 HEMBREE LN WINDSOR CA 95492	EMISSIONS

2017 Criteria Data

Facility ID:	112297	***CERR Code:***	
Facility SIC Code:	5411	***TOGT:***	.546472861
CO:	49	***ROGT:***	.546472861
Air Basin:	SF	***COT:***	
District:	BA	***NOXT:***	
COID:	SON	***SOXT:***	
DISN:	BAY AREA AQMD	***PMT:***	
CHAPIS:		***PM10T:***	

2017 Toxic Data

Facility ID:	112297	***COID:***	SON
Facility SIC Code:	5411	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2018 Criteria Data

Facility ID:	112297	***CERR Code:***	
Facility SIC Code:	5541	***TOGT:***	.546472861
CO:	49	***ROGT:***	.546472861
Air Basin:	SF	***COT:***	
District:	BA	***NOXT:***	
COID:	SON	***SOXT:***	
DISN:	BAY AREA AQMD	***PMT:***	
CHAPIS:		***PM10T:***	

2018 Toxic Data

Facility ID:	112297	***COID:***	SON
Facility SIC Code:	5541	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2019 Criteria Data

CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
Facility ID:	112297	***ROGT:***	.546472861
District:	BA	***COT:***	
Facility SIC Code:	5541	***NOXT:***	
CO ID:	SON	***SOXT:***	
DISN:	BAY AREA AQMD		
PM10T:			
TOGT:	.546472861		
PMT:			

2019 Toxic Data

CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Faccility ID:	112297	**TS:**	
District:	BA	**Health Risk Asmt:**	
Facility SIC Code:	5541	**NonCncrChrnicHazInd :**	
COID:	SON	**NonCncrActeHazInd:**	
DISN:	BAY AREA AQMD		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
53	9 of 9	NNE	0.22 / 1,147.56	124.46 / 4	AU ENERGY HEMBREE SHELL #130 6301 HEMBREE LANE WINDSOR CA 95492	RCRA NON GEN

EPA Handler ID:	CAC003076609
Gen Status Universe:	No Report
Contact Name:	JORGE IZEPPI
Contact Address:	6301 HEMBREE LANE , , WINDSOR , CA, 95492 ,
Contact Phone No and Ext:	310-918-2166
Contact Email:	LAKEIA.YANCY@KVACENV.COM
Contact Country:	
County Name:	SONOMA
EPA Region:	09
Land Type:	
Receive Date:	20200728
Location Latitude:	
Location Longitude:	

Violation/Evaluation Summary

Note:	NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20200728
Handler Name:	AU ENERGY HEMBREE SHELL #130
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Other	**Street 1:**	6301 HEMBREE LANE
Name:	JORGE IZEPPI	**Street 2:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Date Became Current:		**City:**	WINDSOR
Date Ended Current:		**State:**	CA
Phone:	310-918-2166	**Country:**	
Source Type:	Implementer	**Zip Code:**	95492
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Other	**Street 1:**	6301 HEMBREE LANE
Name:	JORGE IZEPPI	**Street 2:**	
Date Became Current:		**City:**	WINDSOR
Date Ended Current:		**State:**	CA
Phone:	310-918-2166	**Country:**	
Source Type:	Implementer	**Zip Code:**	95492

54	1 of 1	SSW	0.23 / 1,198.71	117.68 / -2	ICON GENERAL CONTRACTORS, INC. 451 AVIATION BLVD. SUITE 101 & 103 SANTA ROSA CA 95403	RCRA NON GEN

EPA Handler ID:	CAC003076496
Gen Status Universe:	No Report
Contact Name:	BRYCE JACQUET
Contact Address:	5725 REDWOOD DRIVE , SUITE C , ROHNERT PARK , CA, 94928 ,
Contact Phone No and Ext:	916-224-3213
Contact Email:	ALISON@ICONGC.COM
Contact Country:	
County Name:	SONOMA
EPA Region:	09
Land Type:	
Receive Date:	20200727
Location Latitude:	
Location Longitude:	

Violation/Evaluation Summary

Note:	NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity:	No
Mixed Waste Generator:	No
Transporter Activity:	No
Transfer Facility:	No
Onsite Burner Exemption:	No
Furnace Exemption:	No
Underground Injection Activity:	No
Commercial TSD:	No
Used Oil Transporter:	No
Used Oil Transfer Facility:	No
Used Oil Processor:	No
Used Oil Refiner:	No
Used Oil Burner:	No
Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Hazardous Waste Handler Details

Sequence No:	1
Receive Date:	20200727
Handler Name:	ICON GENERAL CONTRACTORS, INC.
Source Type:	Implementer
Federal Waste Generator Code:	N
Generator Code Description:	Not a Generator, Verified

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Other	***Street 1:***	5725 REDWOOD DRIVE
Name:	ICON GENERAL CONTRACTORS, INC.	***Street 2:***	SUITE C
Date Became Current:		***City:***	ROHNERT PARK
Date Ended Current:		***State:***	CA
Phone:	707-536-9859	***Country:***	
Source Type:	Implementer	***Zip Code:***	94928

Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Other	***Street 1:***	5725 REDWOOD DRIVE
Name:	BRYCE JACQUET	***Street 2:***	SUITE C
Date Became Current:		***City:***	ROHNERT PARK
Date Ended Current:		***State:***	CA
Phone:	916-224-3213	***Country:***	
Source Type:	Implementer	***Zip Code:***	94928

55	*1 of 1*	*SW*	*0.23 / 1,237.11*	*116.51 / -3*	***Filtration Group 498 Aviation Blvd Santa Rosa, CA 95403 CA***	***CUPA SONOMA***

Facility ID:	49-000-006203	***CERS ID:***	10108876

Details

Program Type:	Stormwater
Permit Status:	Active
Expiration Date:	3/1/2024
Fee Schedule:	Storm Water Permit

Details

Program Type:	HMBP
Permit Status:	Active
Expiration Date:	3/1/2024
Fee Schedule:	Range 4

Details

Program Type:	Hazardous Waste
Permit Status:	Active
Expiration Date:	3/1/2024
Fee Schedule:	SQG < 325 gallons/year

56	*1 of 1*	*SW*	*0.23 / 1,238.02*	*116.30 / -4*	***Sonoma County IDS (2136) 475 Aviation Blvd Santa Rosa CA 95403***	***SWF/LF***

SWIS No:	49-CR-0039	***Latitude:***	38.51664
EPA Fed Registry ID:		***Longitude:***	-122.7907
Operational Status:	Clean Closed	***County:***	Sonoma
Regulatory Status:	Unpermitted	***Site ZIP:***	95403
Site is Archived:	Yes	***ARB District:***	Bay Area
Absorbed on:		***SWRCB Region:***	North Coast
Absorbed by:		***Site Point of Contact:***	Dawn Liang
Site Inert Debris Eng Fill:	No		
Closed Illegal Aband:	No		
Closed Illegal Aband Cat:			
Finance Assuran Responsible:	No		
Incorporated City:	Santa Rosa		
Local Government:	Santa Rosa		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Reporting Agency Legal Name: County of Sonoma
Reporting Agency Department: Department of Health Services, Environmental Health & Safety Section
Enforcing Agency Legal Name: County of Sonoma
Enforcing Agency Department: Department of Health Services, Environmental Health & Safety Section

Site Owners

Site Type: Disposal Only
Owner Name: Sonoma County Dept. of Health Services
Owner Address: Christine Sosko 475 Aviation Blvd. Suite 220
Owner City: Santa Rosa
Owner State: CA
Owner ZIP Code: 95403
Owner Phone: (707) 565-6521
Contact Name:
Contact First Name:
Contact Last Name:
Contact Title:
Contact Email: csosko@sonoma-county.org
Started On:

Site Operators

Site Type: Disposal Only
Operator Name: Sonoma County Dept. of Health Services
Operator Address: Christine Sosko 475 Aviation Blvd. Suite 220
Operator City: Santa Rosa
Operator State: CA
Operator ZIP Code: 95403
Operator Phone: (707) 565-6521
Is Archived: Yes
Contact Name:
Contact First Name:
Contact Last Name:
Contact Title:
Contact Email: csosko@sonoma-county.org
Started on:

---

57 | ***1 of 1*** | ***SSW*** | ***0.24 / 1,255.85*** | ***118.43 / -2*** | ***Tonnellerie Radoux USA, Inc 480 Aviation Boulevard, Santa Rosa, CA 95403 CA*** | ***CUPA SONOMA***

Facility ID: 49-000-006202
CERS ID: 10129267

Details

Program Type: Stormwater
Permit Status: Active
Expiration Date: 7/31/2021
Fee Schedule: Storm Water Permit

Details

Program Type: HMBP
Permit Status: Active
Expiration Date: 7/31/2021
Fee Schedule: Range 2

---

58 | ***1 of 2*** | ***SSW*** | ***0.24 / 1,260.00*** | ***119.12 / -1*** | ***Exchange Bank 440 Aviation Blvd, Santa Rosa, CA 95403 CA*** | ***CUPA SONOMA***

Facility ID: 49-000-005775
CERS ID: 10107679

Details

Program Type: Stormwater
Permit Status: Active
Expiration Date: 10/27/2020
Fee Schedule: Storm Water Permit

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Details

Program Type: HMBP
Permit Status: Active
Expiration Date: 10/27/2020
Fee Schedule: Range 3

58	2 of 2	SSW	0.24 / 1,260.00	119.12 / -1	EXCHANGE BANK 440 AVIATION BOULEVARD SANTA ROSA CA 95403	EMISSIONS

2008 Criteria Data

Facility ID: 15868
Facility SIC Code: 4931
CO: 49
Air Basin: SF
District: BA
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:
TOGT: .005
ROGT: .0041835
COT: .014
NOXT: .081
SOXT: 0
PMT: .004
PM10T: .003904

2008 Toxic Data

Facility ID: 15868
Facility SIC Code: 4931
CO: 49
Air Basin: SF
District: BA
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:

2009 Criteria Data

Facility ID: 15868
Facility SIC Code: 4931
CO: 49
Air Basin: SF
District: BA
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:
TOGT: .005
ROGT: .0041835
COT: .014
NOXT: .081
SOXT: 0
PMT: .00409836065573770491803278688524590163 9344
PM10T: .004

2009 Toxic Data

Facility ID: 15868
Facility SIC Code: 4931
CO: 49
Air Basin: SF
District: BA
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:

2010 Toxic Data

Facility ID: 15868
Facility SIC Code: 4931
CO: 49
Air Basin: SF
District: BA
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:

2011 Criteria Data

Facility ID: 15868
Facility SIC Code: 4931
CO: 49
Air Basin: SF
District: BA
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:
TOGT: .01
ROGT: .008367
COT: .031
NOXT: .167
SOXT: 0
PMT: .0102459016393442622950819672131147540984
PM10T: .01

2011 Toxic Data

Facility ID: 15868
Facility SIC Code: 4931
CO: 49
Air Basin: SF
District: BA
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:

2012 Criteria Data

Facility ID: 15868
Facility SIC Code: 4931
CO: 49
Air Basin: SF
District: BA
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:
TOGT: .007
ROGT: .0058569
COT: .022
NOXT: .117
SOXT: 0
PMT: .0071721311475409836065573770491803278688852
PM10T: .007

2012 Toxic Data

Facility ID: 15868
Facility SIC Code: 4931
CO: 49
Air Basin: SF
District: BA
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:

2013 Criteria Data

Facility ID: 15868
CERR Code:

Facility SIC Code:	4931	**TOGT:**	.007
CO:	49	**ROGT:**	.0058569
Air Basin:	SF	**COT:**	.022
District:	BA	**NOXT:**	.117
COID:	SON	**SOXT:**	0
DISN:	BAY AREA AQMD	**PMT:**	.007
CHAPIS:		**PM10T:**	.007

2013 Toxic Data

Facility ID:	15868	**COID:**	SON
Facility SIC Code:	4931	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2014 Criteria Data

Facility ID:	15868	**CERR Code:**	
Facility SIC Code:	4931	**TOGT:**	.000625237
CO:	49	**ROGT:**	
Air Basin:	SF	**COT:**	.002273017
District:	BA	**NOXT:**	.025638458
COID:	SON	**SOXT:**	.000026382
DISN:	BAY AREA AQMD	**PMT:**	.000404734
CHAPIS:		**PM10T:**	.000388544

2014 Toxic Data

Facility ID:	15868	**COID:**	SON
Facility SIC Code:	4931	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2015 Criteria Data

Facility ID:	15868	**CERR Code:**	
Facility SIC Code:	4931	**TOGT:**	.000625237
CO:	49	**ROGT:**	.000517029
Air Basin:	SF	**COT:**	.002273017
District:	BA	**NOXT:**	.025638461
COID:	SON	**SOXT:**	.000026382
DISN:	BAY AREA AQMD	**PMT:**	.000404734
CHAPIS:		**PM10T:**	.000388544

2015 Toxic Data

Facility ID:	15868	**COID:**	SON
Facility SIC Code:	4931	**DISN:**	BAY AREA AQMD
CO:	49	**CHAPIS:**	
Air Basin:	SF	**CERR Code:**	
District:	BA		
TS:			
Health Risk Asmt:			

Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:

2016 Criteria Data

Facility ID:	15868	***CERR CODE:***	
Facility SIC Code:	4931	***TOGT:***	.001541663
CO:	49	***ROGT:***	.0013543509455
Air Basin:	SF	***COT:***	.004930214
District:	BA	***NOXT:***	.033513664
COID:	SON	***SOXT:***	.000025882
DISN:	BAY AREA AQMD	***PMT:***	.000506155
CHAPIS:		***PM10T:***	.00048591

2016 Toxic Data

Facility ID:	15868	***TS:***	
Facility SIC Code:	4931	***HRA:***	
CERR CODE:		***CH Index:***	
COID:	SON	***AH Index:***	
CO:	49	***Air Basin:***	SF
DISN:	BAY AREA AQMD	***District:***	BA
CHAPIS:			

2017 Criteria Data

Facility ID:	15868	***CERR Code:***	
Facility SIC Code:	4931	***TOGT:***	.001541663
CO:	49	***ROGT:***	.0013543509455
Air Basin:	SF	***COT:***	.004930214
District:	BA	***NOXT:***	.033513664
COID:	SON	***SOXT:***	.000025882
DISN:	BAY AREA AQMD	***PMT:***	.000506155
CHAPIS:		***PM10T:***	.00048591

2017 Toxic Data

Facility ID:	15868	***COID:***	SON
Facility SIC Code:	4931	***DISN:***	BAY AREA AQMD
CO:	49	***CHAPIS:***	
Air Basin:	SF	***CERR Code:***	
District:	BA		
TS:			
Health Risk Asmt:			
Non-Cancer Chronic Haz Ind:			
Non-Cancer Acute Haz Ind:			

2018 Criteria Data

Facility ID:	15868	***CERR Code:***	
Facility SIC Code:	4931	***TOGT:***	.003356588
CO:	49	***ROGT:***	.002948762558
Air Basin:	SF	***COT:***	.010301792
District:	BA	***NOXT:***	.053917938
COID:	SON	***SOXT:***	.000031232
DISN:	BAY AREA AQMD	***PMT:***	.00078662
CHAPIS:		***PM10T:***	.000755155

2018 Toxic Data

Facility ID:	15868	***COID:***	SON
Facility SIC Code:	4931	***DISN:***	BAY AREA AQMD

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

CO: 49
Air Basin: SF
District: BA
TS:
Health Risk Asmt:
Non-Cancer Chronic Haz Ind:
Non-Cancer Acute Haz Ind:
CHAPIS:
CERR Code:

2019 Criteria Data

CO: 49
Air Basin: SF
Facility ID: 15868
District: BA
Facility SIC Code: 4931
CO ID: SON
DISN: BAY AREA AQMD
PM10T: .000755155
TOGT: .003356588
PMT: .00078662
CHAPIS:
CERR Code:
ROGT: .002948762558
COT: .010301792
NOXT: .053917938
SOXT: .000031232

2019 Toxic Data

CO: 49
Air Basin: SF
Faccility ID: 15868
District: BA
Facility SIC Code: 4931
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:
TS:
Health Risk Asmt:
NonCncrChrnicHazInd :
NonCncrActeHazInd:

---

59 | ***1 of 5*** | ***SW*** | ***0.24 / 1,287.84*** | ***116.06 / -4*** | ***Bio-Rad Laboratories, Inc. 487 Aviation Blvd # 100 Santa Rosa, CA 95403 CA*** | ***CUPA SONOMA***

Facility ID: 49-000-006924
CERS ID: 10110415

Details

Program Type: Hazardous Waste
Permit Status: Active
Expiration Date: 6/30/2020
Fee Schedule: SQG < 325 gallons/year

Details

Program Type: HMBP
Permit Status: Active
Expiration Date: 6/30/2020
Fee Schedule: Range 3

Details

Program Type: Stormwater
Permit Status: Active
Expiration Date: 6/30/2020
Fee Schedule: Storm Water Permit

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
59	2 of 5	SW	0.24 / 1,287.84	116.06 / -4	FMC Santa Rosa North 487 Aviation Blvd. SANTA ROSA, CA 95403 CA	DELISTED COUNTY

Original Source Facility ID:
Original Source Name: Sonoma County CUPA Facilities List
Record Date: 11-JAN-2016

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
59	3 of 5	SW	0.24 / 1,287.84	116.06 / -4	FMC Dialysis 487 AVIATION BLVD, STE 110 SANTA ROSA CA 95403	DELISTED HAZ

Siteid: 380797
Latitude: 38.517668
Longitude: -122.791630
Original Source: CHAZ
Record Date: 30-MAY-2017

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
59	4 of 5	SW	0.24 / 1,287.84	116.06 / -4	BIO RAD LABORATORIES INC 487 AVIATION BLVD STE 100 SANTA ROSA CA 95403-1069	RCRA NON GEN

EPA Handler ID: CAL000389056
Gen Status Universe: No Report
Contact Name: MARK KESSLER
Contact Address: 9500 JERONIMO ROAD , , IRVINE , CA, 92618-2017 ,
Contact Phone No and Ext: 949-598-1233
Contact Email: MARK_KESSLER@BIO-RAD.COM
Contact Country:
County Name: SONOMA
EPA Region: 09
Land Type:
Receive Date: 20130829
Location Latitude: 38.517516
Location Longitude: -122.791491

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Furnace Exemption: No
Underground Injection Activity: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Sequence No: 1
Receive Date: 20130829
Handler Name: BIO RAD LABORATORIES INC
Source Type: Implementer
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Other
Name: BIO-RAD LABORATORIES
Date Became Current:
Date Ended Current:
Phone: 510-741-1000
Source Type: Implementer
Street No:
Street 1: 1000 ALFRED NOBEL DR
Street 2:
City: HERCULES
State: CA
Country:
Zip Code: 94547-1801

Owner/Operator Ind: Current Operator
Type: Other
Name: MARK KESSLER
Date Became Current:
Date Ended Current:
Phone: 949-598-1233
Source Type: Implementer
Street No:
Street 1: 9500 JERONIMO ROAD
Street 2:
City: IRVINE
State: CA
Country:
Zip Code: 92618-2017

59	5 of 5	SW	0.24 / 1,287.84	116.06 / -4	**BIO-RAD LABORATORIES** **487 AVIATION BLVD, STE 100** **SANTA ROSA CA 95403**	**EMISSIONS**

2019 Criteria Data

CO: 49
Air Basin: SF
Facility ID: 24142
District: BA
Facility SIC Code: 8732
CO ID: SON
DISN: BAY AREA AQMD
PM10T:
TOGT: .324993057
PMT:
CHAPIS:
CERR Code:
ROGT: .1299972228
COT:
NOXT:
SOXT:

2019 Toxic Data

CO: 49
Air Basin: SF
Facility ID: 24142
District: BA
Facility SIC Code: 8732
COID: SON
DISN: BAY AREA AQMD
CHAPIS:
CERR Code:
TS:
Health Risk Asmt:
NonCncrChrnicHazInd:
NonCncrActeHazInd:

60	1 of 1	W	0.24 / 1,287.87	115.27 / -5	**Four Corners (under construction)** **792 Caletti Santa Rosa, CA** **CA**	**DELISTED COUNTY**

Original Source Facility ID:
Original Source Name: Sonoma County CUPA Facilities List
Record Date: 11-JAN-2016

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
61	1 of 1	SSE	0.25 / 1,316.75	123.85 / 4	HILTON GARDEN INN 417 Aviation SANTA ROSA, CA 95403 CA	CUPA SONOMA

Facility ID: 49-000-007993 **CERS ID:**

Details

Program Type: HMBP
Permit Status: Inactive
Expiration Date: 12/31/2015
Fee Schedule: Range 8

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
62	1 of 3	W	0.26 / 1,355.29	114.45 / -6	ECODYNE POND 930 SHILOH RD WINDSOR CA 95492	RESPONSE

Estor/EPA ID: 49240001
Site Code: 200028
Nat Priority List: NO
Acres: 1.6 ACRES
Special Program:
Funding: RESPONSIBLE PARTY
Assembly District: 02
Senate District: 02
School District:
Permit Renewal Lead:
Project Manager: TOM LANPHAR
Supervisor: KIMBERLY WALSH
Public Partici Spclst:
Census Tract: 6097152702
County: SONOMA
Latitude: 38.5213488483674
Longitude: -122.793704398678
APN: 05-9271-014
Cleanup Status: ACTIVE AS OF 5/1/1986
Cleanup Oversight Agencies: DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY;RWQCB 1 - NORTH COAST
Site Type: STATE RESPONSE OR NPL
Office: CLEANUP BERKELEY
Past Use that Caused Contam: MANUFACTURING - LUMBER/WOOD PRODUCTS
Potential Media Affected: OTHER GROUNDWATER AFFECTED (USES OTHER THAN DRINKING WATER), SOIL
Potential Contamin of Concern:

DIOXIN (AS 2,3,7,8-TCDD TEQ)
LEAD
PENTACHLOROPHENOL
POLYNUCLEAR AROMATIC HYDROCARBONS (PAHS)

Site History:

The Site consists of approximately 30,000 square feet located within the 28-acre Shiloh Road Industrial Park. From 1952 to 1961 the Site was used for wood treatment operations in support of storage tank and cooling tower manufacturing. In addition to wood treatment at the Site, lead coatings were applied to hardware for tanks and piping. Fluor sold the property and business in 1969 to Ecodyne Corporation and Fluor Products Company became a wholly owned subsidiary of Ecodyne Corporation. Ecodyne. Ecodyne Corporation continued operations at the site until 1984 when they sold the property to Mr. Shah. The Shiloh Group purchased the property from Mr. Shah in 1999.

Site assessment, characterization and remedial investigation undertaken between 1985 and 1998 identified PAHs, lead and dioxin in soils at the Site. On May 4, 2011 DTSC approved a Remedial Action Plan (RAP). The remedy approved in the included in-situ ozonation, for the treatment of PAHs in soil, and excavation with off-site disposal for soil containing lead and dioxin above levels appropriate for industrial use.

On August 26, 2014 DTSC informed Fluor Corporation that new information on the Site had caused DTSC to reevaluate the selected remedial action. DTSC determined that the selected remedy in the 2011 RAP was not protective of human health and the environment because of the following:

1) the selected remedy was based on the existence of an asphalt and concrete cover over the Site;
2) the asphalt and concrete cover currently contains cracks and areas of exposed soil;
3) operations and maintenance of the cover was not included in the 2011 RAP; and
4) the selected remedy does not address the possible transport of potentially contaminated soil, which may be exposed at the surface, to offsite locations.

In response to DTSC's determination, Fluor Corporation submitted a Revised RAP that includes the following changes:
• Elimination of ozonation as on-site soil treatment;
• Changes in the cleanup goals to meet unrestrictive standards;
• An increase in the amount of soil being excavated from 500 cubic yards to 819 cubic yard;
• Elimination of the need for a Land Use Covenant, which would prohibit the use of the property for residential or other sensitive uses;

• Elimination Operations and Maintenance requirements.
DTSC approved the Revised RAP on September 8, 2015. Fluor Corporation began implementation of the Revised RAP in October 2015. Identification of additional areas of contamination and the need to suspend excavation activities during the winter months has delayed the completion of the Revised RAP implementation. The completion of the excavation, backfill and site restoration is schedule for completion in October 2018.

Directly adjacent to the Ecodyne Pond Site to the northwest is another hazardous waste site currently undergoing remediation. The adjacent site is known as the Ecodyne (Cooling) Towers Site. The Ecodyne Towers Site is being cleaned up with the oversight of the Regional Water Quality Control Board (RWQCB).
(Updated 9/12/2018; TPL)

Status: ACTIVE
Program Type: STATE RESPONSE
CalEnviroScreen Score: 46-50%
Summary Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=49240001

Currently Scheduled Activities

Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Certification
Due Date: 4/9/2022
Revised Date:

Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Remedial Action Completion Report
Due Date: 4/24/2022
Revised Date:

Completed Activities

Title: Well Destruction Work Plan
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60398902
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Well Decommissioning Workplan
Date Completed: 9/2/2015
Comments: The Well Destruction Work Plan describes the destruction of onsite wells.

Title: DTSC Letter to Fluor requesting addendum to Remedial Design Workplan
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60405871
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 2/17/2016
Comments: Letter to Fluor requesting Addendum to RDIP was a result of in field adjustment to implementation work due to increase in size of excavations.

Title: Remedial Investigation / Feasibility Study
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=5002103
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Remedial Investigation / Feasibility Study
Date Completed: 2/14/1994
Comments: RI/FS with capping of the site with land use restrictions as the recommended alternative approved. This alternative was subsequently rejected after public comment.

Title: Cost Estimates 2009-2010
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=6017387
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 9/15/2009
Comments: Received cost estimate acknowledgment from Fluor.

Title: Annual Cost Estimate
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60433566
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 9/28/2017
Comments: Cost estimate for DTSC oversight for FY 2017-2018.

Title: Post Excavation Sampling Report(prior to partial backfill)
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60426601
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 5/10/2017
Comments: Letter was requires for approval to backfill Excavation 7 and a Portion of Excavation 8. Letter provided data and 95 UCL calculation. One sample location must be excavated prior backfill of that location. Other areas are okay for backfill.

Title: Site Screening
Title Link: https://www.envirostor.dtsc.ca.gov/public/
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Site Screening
Date Completed: 3/24/1987
Comments:

Title: Letter from DTSC to Fluor Corporation requesting a Amended RAP for Site
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60388789
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 1/15/2015
Comments: Letter requests the submittal of a revised RAP for Ecodyne Pond site to address COCs in soil.

Title: Environmental Document Analysis
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60393479
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: CEQA - Initial Study/ Neg. Declaration
Date Completed: 9/8/2015
Comments: An addendum to the previously adopted negative declaration was prepared by DTSC because of significant changes in the remedial action for the site.

Title: Order to Post and Fence Docket #PF 88/89-003 for Ecodyne Pond
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60426627
Area Name:
Area Link:
Sub Area:

Sub Area Link:
Document Type: Fence & Post Order
Date Completed: 3/10/1989
Comments: Order to Post and Fence for Ecodyne Pond Site

Title: Correspondence regarding delay in remaining excavation field work due to PGE gas line delays
Title Link: https://www.envirostor.dtsc.ca.gov/public/
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 4/13/2021
Comments: Excavation of drainage ditch in Ecodyne Corp/Tower Site is delayed because of PGE work to decommission gas line delayed again by PGE. PGE work scheduled now for 6/2021.

Title: Work Notice Soil Excavation
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60273750
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Work Notice
Date Completed: 11/13/2015
Comments: Work notice was sent to site mailing list.

Title: Supplemental Sampling Plan for Limited Off-Site Sampling Within the Drainage Ditch
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60417729
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Site Characterization Workplan
Date Completed: 6/1/1992
Comments: The purpose of the workplan was to provide additional soil data in drainage ditch after the completion of the RI Report.

Title: Summary of Analytical Air Sampling Results Collected on November 13, 2016
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60422852
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Monitoring Report
Date Completed: 3/9/2017
Comments: DTSC Industrial Hygienist and Toxicologist review concurred on the conclusions of the air monitoring report; there is no significant risk to workers or public if vapor control measures are followed.

Title: Fact Sheet
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=6009089
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Fact Sheets
Date Completed: 2/16/2011
Comments: Fact sheet mailed out to to announce 30-day public comment period for Draft Remedial Action Plan and CEQA Negative Declaration/Initial Study.

Title: Backfill Request for Excavation 7 and portion of 8: Post Excavation Soil Sampling
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60427449
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Monitoring Report
Date Completed: 5/24/2017
Comments:

Title: Evaluation of Potential change in CEQA Determination
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60313282
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Technical Report
Date Completed: 2/4/2013
Comments: This report evaluates the former CEQA decision as it relates to a proposed change in remedy.

Title: Notice of New Project Manger Ltr
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=6013901
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 5/21/2009
Comments: Letter Send.

Title: Annual Cost Estimate
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60417102
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 9/27/2016
Comments: Annual cost estimate for DTSC oversight costs.

Title: Letter from The Shiloh Group regarding backfill of Excavation
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60427455
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 5/24/2017
Comments: sent letter to The Shiloh Group explaining the evaluation of data and that data showed confirmation samples meet remedial goals.

Title: Memo to File: DTSC investigation in to issues raised by Trans Tech Consultant for The Shiloh Group LLC regarding RDIP
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60328774
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 6/30/2014
Comments:

Title: Order
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=5002106
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Consent Order
Date Completed: 12/31/1989
Comments: Consent Agreement with the Fluor Corporation to conduct remediation activities at the former Ecodyne Pond site.

Title: letter on shallow groundwater
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60386964
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence

Date Completed: 1/15/2015
Comments:

Title: Soil & Groundwater Sampling Summary Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=6012828
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Remedial Investigation Report
Date Completed: 6/1/2007
Comments: Report approved with modifications.

Title: Removal Action Completion Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Removal Action Completion Report
Date Completed: 2/28/1986
Comments: A berm was constructed on the southwestern edge of the site to prevent potential transport of chemicals in site runoff.

Title: Remedial Action Plan
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=6016031
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Remedial Action Plan
Date Completed: 5/5/2011
Comments:

Title: 2018 - 2019 Annual Oversight Cost Estimate
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60451486
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 10/1/2018
Comments: Annual cost estimate for DTSC oversight.

Title: Public Participation Plan / Community Relations Plan
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=5002105
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Public Participation Plan / Community Relations Plan
Date Completed: 1/31/1991
Comments: Public Participation Plan prepared for the site.

Title: Air Monitoring for Ecodyne Pond Site
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60418670
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Monitoring Plan
Date Completed: 11/10/2016
Comments: air monitoring plan approved and implemented on November 13, 2016. Tom Lanphar, Project Manager for DTSC, was present during the monitoring.

Title: Response to June 12, 2012 letter from Shilo Group Representative
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60302949
Area Name:
Area Link:

Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 8/15/2012
Comments: letter completed

Title: Feasibility Study
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=6016030
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Feasibility Study Report
Date Completed: 11/20/2008
Comments:

Title: Public Notice
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=6009091
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Public Notice
Date Completed: 2/16/2011
Comments: Public notice published in Press Democrat to announce 30-day public comment period for Draft Remedial Action Plan and CEQA Negative Declaration/Initial Study.

Title: Site Certification
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=6012819
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Certification
Date Completed: 6/27/2019
Comments: Soil has been excavated and disposed of off-site. Remediation met unrestricted cleanup goals and no further action is required for the Ecodyne Pond Site. More work is needed at the adjacent Ecodyne Tower Site to address contaminants that have migrated off of the Pond Site and onto the Tower Site.

Title: Letter to Mr. Jared Carter from Thomas Lanphar 2-17-2016
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60420289
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 2/17/2016
Comments: letter to Mr. Carter on the subject of the Remedial Action Plan and Land Use Covenant

Title: 2013 Annual Oversight Cost Estimate
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60277348
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 10/30/2014
Comments:

Title: Letter on proposal to revise RAP for Ecodyne Pond Site
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60385866
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 11/6/2014
Comments: Letter from Verrill Dana, representing Fluor Corporation, stating intent to revise the remedy for Ecodyne Pond Site.

Title: Human Health Risk Assessment
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=6016029
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Risk Assessment Report
Date Completed: 12/15/2003
Comments: Risk Assessment approved.

Title: Remedial Design and Implementation Plan - Addendum
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60428379
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Remedial Action Implementation Workplan
Date Completed: 6/20/2017
Comments: Addendum adds additional excavation in the trench area south of Ecodyne Pond site boundary. It also adds a disposal facility for non-hazardous waste soil.

Title: Remedial Design Implementation Plan Addendum
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60409406
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Design/Implementation Workplan
Date Completed: 4/16/2016
Comments: The addendum addresses changes in plan caused by increases in amount of excavated soil.

Title: Interim Soil Removal Completion Report and Winterization Workplan
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60434891
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Remedial Action Completion Report
Date Completed: 10/17/2017
Comments: Work plan is for placing a temporary asphalt cover to eliminate rain water in excavation. Excavation will continue in Spring or Summer 208.

Title: Remedial Investigation / Feasibility Study
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=5002097
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Treatability Study Report
Date Completed: 12/15/2003
Comments: Pilot study utilizing in-situ ozonation to reduce source contaminants implemented at the Site between November 1997 and July 1998. Ozone was injected to the subsurface to reduce contaminant concentrations. Results indicated that the technology reduced contaminant concentrations of PCP and PAHs in soil by 87%.

Title: Native American Heritage Commission
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60188256
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 2/2/2010
Comments: Letter faxed and reply received. No cultural resources found on Site.

Title: Order
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=5002104
Area Name:
Area Link:
Sub Area:

Sub Area Link:
Document Type: Amendment - Order/Agreement
Date Completed: 6/13/1991
Comments: Order Amendment Signed

Title: Cost Recovery Demand Letter
Title Link: https://www.envirostor.dtsc.ca.gov/public/
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 7/28/2005
Comments:

Title: Revised Remediation Work Plan
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60298031
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 5/16/2012
Comments: DTSC agrees to consider a change to the Ecodyne remedial action plan.

Title: 2015 Annual Oversight Cost Estimate
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60277349
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 9/28/2015
Comments:

Title: Letter from TransTech Consultants on groundwater in shallow zone wells
Title Link: https://www.envirostor.dtsc.ca.gov/public/
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 10/7/2014
Comments: Letter from Trans Tech Consultants, representing Shiloh Group LLC, on the issue of shallow groundwater wells.

Title: Soil Investigation for better delineation of planned excavated soil
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60305046
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Fieldwork
Date Completed: 10/30/2012
Comments:

Title: 2012 Annual Oversight Cost Estimate
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60277347
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 8/17/2012
Comments:

Title: 2011 Annual Oversight Cost Estimate
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60275716
Area Name:
Area Link:

Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 10/6/2011
Comments: cost estimate sent to Ecodyne Pond

Title: Initial Study & Negative Declaration
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=6011123
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: CEQA - Initial Study/ Neg. Declaration
Date Completed: 5/3/2011
Comments: NOD and Negative Declaration signed 5.3.11.

Title: Soil and Groundwater Sampling
Title Link: https://www.envirostor.dtsc.ca.gov/public/
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Fieldwork
Date Completed: 11/13/2006
Comments: All groundwater and soil sampling activities have been completed as of 11/13/2006.

Title: Remedial Design Workplan
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=6021992
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Design/Implementation Workplan
Date Completed: 3/14/2012
Comments: RDIP approved with conditions.

Title: Letter to Verrill Dana LLP, representing Fluor Corp. regarding deficiencies in remedy at Ecodyne Pond
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60379666
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 8/26/2014
Comments: Letter addresses DTSC evaluation of information on Ecodyne Pond Site and reevaluation of selected remedy.

Title: Public Participation Plan - New
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=6020626
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Public Participation Plan / Community Relations Plan
Date Completed: 5/29/2009
Comments: PPP final and signed.

Title: Remedial or Removal Design
Title Link: https://www.envirostor.dtsc.ca.gov/public/
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Design/Implementation Workplan
Date Completed: 6/4/1997
Comments: An alternate treatment utilizing in-situ treatment of soils containing organic contaminants with ozonation presented.

Title: Implementation of Remedial Action: Excavation
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60305050
Area Name:

Area Link:
Sub Area:
Sub Area Link:
Document Type: Fieldwork
Date Completed: 2/1/2019
Comments: RAP Implementation complete, soil excavation met unrestricted cleanup goals.

Title: Site Investigation Report: defining extent of excavation
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60305048
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Technical Report
Date Completed: 3/25/2013
Comments: This Report documents the recent site investigation conducted at the Ecodyne Pond Site. The purpose of the investigation is to update information on the extent of the contaminants of concern at the site and to prepare a preliminary map showing the predicted extent of future excavations.

Title: Site Investigtion Work Plan in support of Remedial Design
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60304826
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Site Characterization Workplan
Date Completed: 8/3/2012
Comments: approved work plan

Title: In-Situ Ozonation Technology Demonstrations Project Report for Remediation of PCP and PAHs in Soil and Groundwater
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60188622
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Remedial Investigation Report
Date Completed: 12/15/2003
Comments:

Title: Soil Removal Completion Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=6020627
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Remedial Action Completion Report
Date Completed: 6/26/2019
Comments: Soil has been excavated and sent off-site for disposal. Unrestricted cleanup goals met and No Further Action is needed for Ecodyne Pond Site. Additional work needed at the Ecodyne Tower Site to address contamination that migrated off-site.

Title: Workplan for Additional Soil and Groundwater Sampling - Post Ozonation Pilot Study
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=6012386
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Treatability Study Workplan
Date Completed: 8/18/2006
Comments: Workplan approved.

Title: Public Notice Remedial Action Plan Explanation of Significant Differences
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60381534
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Public Notice

Date Completed: 9/10/2015
Comments:

Title: Revised Remedial Design and Implementation Plan
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60298314
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Remedial Action Implementation Workplan
Date Completed: 9/23/2015
Comments:

Title: Remedial Action Plan Revision
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60379706
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Remedial Action Plan w/ESD
Date Completed: 9/10/2015
Comments: DTSC has determined that the RAP Revision satisfactorily addresses all applicable state and federal statutes and regulations and therefore approves the document.

Title: 2021 - 2022 Annual DTSC Oversight Cost Estimate
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60506774
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 9/10/2021
Comments: annual oversight estimate 2021 -2022

Title: Letters from Brian Carter to Tom Lanphar
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60310641
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 11/19/2012
Comments: letter in reponse to Mr. Carters letter

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
62	2 of 3	W	0.26 / 1,355.29	114.45 / -6	ECODYNE POND 930 SHILOH RD WINDSOR CA 95492	HWSS CLEANUP

Estor/EPA ID: 49240001
Site Code: 200028
Status Date: 5/1/1986
Nat Priority List: NO
Program Type: STATE RESPONSE
Cal Enviro Score: 46-50%
Acres: 1.6 ACRES
Assembly District: 02
Senate District: 02
School District:
APN: 05-9271-014
Status: ACTIVE
Cleanup Status: ACTIVE AS OF 5/1/1986
Cleanup Oversight Agencies: DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY;RWQCB 1 - NORTH COAST
Site Type: STATE RESPONSE OR NPL
Special Program:
Cause of Contamination: MANUFACTURING - LUMBER/WOOD PRODUCTS
Potential Media Affected: OTHER GROUNDWATER AFFECTED (USES OTHER THAN DRINKING WATER), SOIL
Summary URL: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=49240001
Press Contact:

Census Tract: 6097152702
Funding: RESPONSIBLE PARTY
Office: CLEANUP BERKELEY
Permit Renew Lead:
Public Particip Spec:
Project Manager: TOM LANPHAR
Supervisor: KIMBERLY WALSH
County: SONOMA
Latitude: 38.5213488483674
Longitude: -122.793704398678

Potential Contaminants:

DIOXIN (AS 2,3,7,8-TCDD TEQ)
LEAD
PENTACHLOROPHENOL
POLYNUCLEAR AROMATIC HYDROCARBONS (PAHS)

Site History:

The Site consists of approximately 30,000 square feet located within the 28-acre Shiloh Road Industrial Park. From 1952 to 1961 the Site was used for wood treatment operations in support of storage tank and cooling tower manufacturing. In addition to wood treatment at the Site, lead coatings were applied to hardware for tanks and piping. Fluor sold the property and business in 1969 to Ecodyne Corporation and Fluor Products Company became a wholly owned subsidiary of Ecodyne Corporation. Ecodyne. Ecodyne Corporation continued operations at the site until 1984 when they sold the property to Mr. Shah. The Shiloh Group purchased the property from Mr. Shah in 1999.

Site assessment, characterization and remedial investigation undertaken between 1985 and 1998 identified PAHs, lead and dioxin in soils at the Site. On May 4, 2011 DTSC approved a Remedial Action Plan (RAP). The remedy approved in the included in-situ ozonation, for the treatment of PAHs in soil, and excavation with off-site disposal for soil containing lead and dioxin above levels appropriate for industrial use.

On August 26, 2014 DTSC informed Fluor Corporation that new information on the Site had caused DTSC to reevaluate the selected remedial action. DTSC determined that the selected remedy in the 2011 RAP was not protective of human health and the environment because of the following:

1) the selected remedy was based on the existence of an asphalt and concrete cover over the Site;
2) the asphalt and concrete cover currently contains cracks and areas of exposed soil;
3) operations and maintenance of the cover was not included in the 2011 RAP; and
4) the selected remedy does not address the possible transport of potentially contaminated soil, which may be exposed at the surface, to offsite locations.

In response to DTSC's determination, Fluor Corporation submitted a Revised RAP that includes the following changes:
• Elimination of ozonation as on-site soil treatment;
• Changes in the cleanup goals to meet unrestrictive standards;
• An increase in the amount of soil being excavated from 500 cubic yards to 819 cubic yard;
• Elimination of the need for a Land Use Covenant, which would prohibit the use of the property for residential or other sensitive uses;
• Elimination Operations and Maintenance requirements.
DTSC approved the Revised RAP on September 8, 2015. Fluor Corporation began implementation of the Revised RAP in October 2015. Identification of additional areas of contamination and the need to suspend excavation activities during the winter months has delayed the completion of the Revised RAP implementation. The completion of the excavation, backfill and site restoration is schedule for completion in October 2018.

Directly adjacent to the Ecodyne Pond Site to the northwest is another hazardous waste site currently undergoing remediation. The adjacent site is known as the Ecodyne (Cooling) Towers Site. The Ecodyne Towers Site is being cleaned up with the oversight of the Regional Water Quality Control Board (RWQCB).
(Updated 9/12/2018; TPL)

Future Activities

Area Name:
Area Name URL:
Sub Area:
Sub Area URL:
Document Type: Certification
Activity Type: Future Activities
Due Date: 2022

Area Name:
Area Name URL:
Sub Area:
Sub Area URL:
Document Type: Remedial Action Completion Report
Activity Type: Future Activities
Due Date: 2021

Completed Activities

Area Name:
Area URL:
Sub Area:

Sub Area URL:
Title: Revised Remediation Work Plan
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60298031
Document Type: Correspondence
Activity Type: Completed Activities
Date Completed: 5/16/2012
Comments: DTSC agrees to consider a change to the Ecodyne remedial action plan.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Initial Study & Negative Declaration
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=6011123
Document Type: CEQA - Initial Study/ Neg. Declaration
Activity Type: Completed Activities
Date Completed: 5/3/2011
Comments: NOD and Negative Declaration signed 5.3.11.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Public Notice
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=6009091
Document Type: Public Notice
Activity Type: Completed Activities
Date Completed: 2/16/2011
Comments: Public notice published in Press Democrat to announce 30-day public comment period for Draft Remedial Action Plan and CEQA Negative Declaration/Initial Study.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Cost Estimates 2009-2010
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=6017387
Document Type: Annual Oversight Cost Estimate
Activity Type: Completed Activities
Date Completed: 9/15/2009
Comments: Received cost estimate acknowledgment from Fluor.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Public Participation Plan - New
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=6020626
Document Type: Public Participation Plan / Community Relations Plan
Activity Type: Completed Activities
Date Completed: 5/29/2009
Comments: PPP final and signed.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Air Monitoring for Ecodyne Pond Site
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60418670
Document Type: Monitoring Plan
Activity Type: Completed Activities
Date Completed: 11/10/2016
Comments: air monitoring plan approved and implemented on November 13, 2016. Tom Lanphar, Project Manager for DTSC, was present during the monitoring.

Area Name:
Area URL:
Sub Area:
Sub Area URL:

Title: Annual Cost Estimate
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60417102
Document Type: Annual Oversight Cost Estimate
Activity Type: Completed Activities
Date Completed: 9/27/2016
Comments: Annual cost estimate for DTSC oversight costs.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Remedial Design Implementation Plan Addendum
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60409406
Document Type: Design/Implementation Workplan
Activity Type: Completed Activities
Date Completed: 4/16/2016
Comments: The addendum addresses changes in plan caused by increases in amount of excavated soil.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Revised Remedial Design and Implementation Plan
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60298314
Document Type: Remedial Action Implementation Workplan
Activity Type: Completed Activities
Date Completed: 9/23/2015
Comments:

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Native American Heritage Commission
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60188256
Document Type: Correspondence
Activity Type: Completed Activities
Date Completed: 2/2/2010
Comments: Letter faxed and reply received. No cultural resources found on Site.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Notice of New Project Manger Ltr
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=6013901
Document Type: Correspondence
Activity Type: Completed Activities
Date Completed: 5/21/2009
Comments: Letter Send.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Remedial Investigation / Feasibility Study
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=5002103
Document Type: Remedial Investigation / Feasibility Study
Activity Type: Completed Activities
Date Completed: 2/14/1994
Comments: RI/FS with capping of the site with land use restrictions as the recommended alternative approved. This alternative was subsequently rejected after public comment.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Environmental Document Analysis
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60393479

Document Type: CEQA - Initial Study/ Neg. Declaration
Activity Type: Completed Activities
Date Completed: 9/8/2015
Comments: An addendum to the previously adopted negative declaration was prepared by DTSC because of significant changes in the remedial action for the site.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: 2013 Annual Oversight Cost Estimate
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60277348
Document Type: Annual Oversight Cost Estimate
Activity Type: Completed Activities
Date Completed: 10/30/2014
Comments:

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Letter to Verrill Dana LLP, representing Fluor Corp. regarding deficiencies in remedy at Ecodyne Pond
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60379666
Document Type: Correspondence
Activity Type: Completed Activities
Date Completed: 8/26/2014
Comments: Letter addresses DTSC evaluation of information on Ecodyne Pond Site and reevaluation of selected remedy.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Memo to File: DTSC investigation in to issues raised by Trans Tech Consultant for The Shiloh Group LLC regarding RDIP
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60328774
Document Type: Correspondence
Activity Type: Completed Activities
Date Completed: 6/30/2014
Comments:

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Response to June 12, 2012 letter from Shilo Group Representative
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60302949
Document Type: Correspondence
Activity Type: Completed Activities
Date Completed: 8/15/2012
Comments: letter completed

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Remedial Action Plan
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=6016031
Document Type: Remedial Action Plan
Activity Type: Completed Activities
Date Completed: 5/5/2011
Comments:

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Feasibility Study
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=6016030
Document Type: Feasibility Study Report

Activity Type: Completed Activities
Date Completed: 11/20/2008
Comments:

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Remedial Investigation / Feasibility Study
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=5002097
Document Type: Treatability Study Report
Activity Type: Completed Activities
Date Completed: 12/15/2003
Comments: Pilot study utilizing in-situ ozonation to reduce source contaminants implemented at the Site between November 1997 and July 1998. Ozone was injected to the subsurface to reduce contaminant concentrations. Results indicated that the technology reduced contaminant concentrations of PCP and PAHs in soil by 87%.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Remedial or Removal Design
Title URL:
Document Type: Design/Implementation Workplan
Activity Type: Completed Activities
Date Completed: 6/4/1997
Comments: An alternate treatment utilizing in-situ treatment of soils containing organic contaminants with ozonation presented.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Order
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=5002104
Document Type: Amendment - Order/Agreement
Activity Type: Completed Activities
Date Completed: 6/13/1991
Comments: Order Amendment Signed

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Site Screening
Title URL:
Document Type: Site Screening
Activity Type: Completed Activities
Date Completed: 3/24/1987
Comments:

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: 2018 - 2019 Annual Oversight Cost Estimate
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60451486
Document Type: Annual Oversight Cost Estimate
Activity Type: Completed Activities
Date Completed: 10/1/2018
Comments: Annual cost estimate for DTSC oversight.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Interim Soil Removal Completion Report and Winterization Workplan
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60434891
Document Type: Remedial Action Completion Report
Activity Type: Completed Activities

Date Completed: 10/17/2017
Comments: Work plan is for placing a temporary asphalt cover to eliminate rain water in excavation. Excavation will continue in Spring or Summer 208.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Remedial Design and Implementation Plan - Addendum
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60428379
Document Type: Remedial Action Implementation Workplan
Activity Type: Completed Activities
Date Completed: 6/20/2017
Comments: Addendum adds additional excavation in the trench area south of Ecodyne Pond site boundary. It also adds a disposal facility for non-hazardous waste soil.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Site Certification
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=6012819
Document Type: Certification
Activity Type: Completed Activities
Date Completed: 6/27/2019
Comments: Soil has been excavated and disposed of off-site. Remediation met unrestricted cleanup goals and no further action is required for the Ecodyne Pond Site. More work is needed at the adjacent Ecodyne Tower Site to address contaminants that have migrated off of the Pond Site and onto the Tower Site.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Soil Removal Completion Report
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=6020627
Document Type: Remedial Action Completion Report
Activity Type: Completed Activities
Date Completed: 6/26/2019
Comments: Soil has been excavated and sent off-site for disposal. Unrestricted cleanup goals met and No Further Action is needed for Ecodyne Pond Site. Additional work needed at the Ecodyne Tower Site to address contamination that migrated off-site.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: letter on shallow groundwater
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60386964
Document Type: Correspondence
Activity Type: Completed Activities
Date Completed: 1/15/2015
Comments:

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Letter from DTSC to Fluor Corporation requesting a Amended RAP for Site
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60388789
Document Type: Correspondence
Activity Type: Completed Activities
Date Completed: 1/15/2015
Comments: Letter requests the submittal of a revised RAP for Ecodyne Pond site to address COCs in soil.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Letter from TransTech Consultants on groundwater in shallow zone wells

Title URL:
Document Type: Correspondence
Activity Type: Completed Activities
Date Completed: 10/7/2014
Comments: Letter from Trans Tech Consultants, representing Shiloh Group LLC, on the issue of shallow groundwater wells.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Letters from Brian Carter to Tom Lanphar
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60310641
Document Type: Correspondence
Activity Type: Completed Activities
Date Completed: 11/19/2012
Comments: letter in reponse to Mr. Carters letter

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Site Investigtion Work Plan in support of Remedial Design
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60304826
Document Type: Site Characterization Workplan
Activity Type: Completed Activities
Date Completed: 8/3/2012
Comments: approved work plan

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Soil & Groundwater Sampling Summary Report
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=6012828
Document Type: Remedial Investigation Report
Activity Type: Completed Activities
Date Completed: 6/1/2007
Comments: Report approved with modifications.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Human Health Risk Assessment
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=6016029
Document Type: Risk Assessment Report
Activity Type: Completed Activities
Date Completed: 12/15/2003
Comments: Risk Assessment approved.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Order
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=5002106
Document Type: Consent Order
Activity Type: Completed Activities
Date Completed: 12/31/1989
Comments: Consent Agreement with the Fluor Corporation to conduct remediation activities at the former Ecodyne Pond site.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Order to Post and Fence Docket #PF 88/89-003 for Ecodyne Pond
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60426627
Document Type: Fence & Post Order
Activity Type: Completed Activities

Date Completed: 3/10/1989
Comments: Order to Post and Fence for Ecodyne Pond Site

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Soil Investigation for better delineation of planned excavated soil
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60305046
Document Type: Fieldwork
Activity Type: Completed Activities
Date Completed: 10/30/2012
Comments:

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: 2012 Annual Oversight Cost Estimate
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60277347
Document Type: Annual Oversight Cost Estimate
Activity Type: Completed Activities
Date Completed: 8/17/2012
Comments:

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Fact Sheet
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=6009089
Document Type: Fact Sheets
Activity Type: Completed Activities
Date Completed: 2/16/2011
Comments: Fact sheet mailed out to to announce 30-day public comment period for Draft Remedial Action Plan and CEQA Negative Declaration/Initial Study.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: In-Situ Ozonation Technology Demonstrations Project Report for Remediation of PCP and PAHs in Soil and Groundwater
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60188622
Document Type: Remedial Investigation Report
Activity Type: Completed Activities
Date Completed: 12/15/2003
Comments:

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Work Notice Soil Excavation
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60273750
Document Type: Work Notice
Activity Type: Completed Activities
Date Completed: 11/13/2015
Comments: Work notice was sent to site mailing list.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Remedial Action Plan Revision
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60379706
Document Type: Remedial Action Plan w/ESD
Activity Type: Completed Activities
Date Completed: 9/10/2015

Comments: DTSC has determined that the RAP Revision satisfactorily addresses all applicable state and federal statutes and regulations and therefore approves the document.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Well Destruction Work Plan
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60398902
Document Type: Well Decommissioning Workplan
Activity Type: Completed Activities
Date Completed: 9/2/2015
Comments: The Well Destruction Work Plan describes the destruction of onsite wells.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Letter on proposal to revise RAP for Ecodyne Pond Site
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60385866
Document Type: Correspondence
Activity Type: Completed Activities
Date Completed: 11/6/2014
Comments: Letter from Verrill Dana, representing Fluor Corporation, stating intent to revise the remedy for Ecodyne Pond Site.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Soil and Groundwater Sampling
Title URL:
Document Type: Fieldwork
Activity Type: Completed Activities
Date Completed: 11/13/2006
Comments: All groundwater and soil sampling activities have been completed as of 11/13/2006.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Cost Recovery Demand Letter
Title URL:
Document Type: Other Report
Activity Type: Completed Activities
Date Completed: 7/28/2005
Comments:

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Annual Cost Estimate
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60433566
Document Type: Annual Oversight Cost Estimate
Activity Type: Completed Activities
Date Completed: 9/28/2017
Comments: Cost estimate for DTSC oversight for FY 2017-2018.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Backfill Request for Excavation 7 and portion of 8: Post Excavation Soil Sampling
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60427449
Document Type: Monitoring Report
Activity Type: Completed Activities
Date Completed: 5/24/2017
Comments:

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Site Investigation Report: defining extent of excavation
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60305048
Document Type: Technical Report
Activity Type: Completed Activities
Date Completed: 3/25/2013
Comments: This Report documents the recent site investigation conducted at the Ecodyne Pond Site. The purpose of the investigation is to update information on the extent of the contaminants of concern at the site and to prepare a preliminary map showing the predicted extent of future excavations.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Remedial Design Workplan
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=6021992
Document Type: Design/Implementation Workplan
Activity Type: Completed Activities
Date Completed: 3/14/2012
Comments: RDIP approved with conditions.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: 2011 Annual Oversight Cost Estimate
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60275716
Document Type: Annual Oversight Cost Estimate
Activity Type: Completed Activities
Date Completed: 10/6/2011
Comments: cost estimate sent to Ecodyne Pond

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Removal Action Completion Report
Title URL:
Document Type: Removal Action Completion Report
Activity Type: Completed Activities
Date Completed: 2/28/1986
Comments: A berm was constructed on the southwestern edge of the site to prevent potential transport of chemicals in site runoff.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Correspondence regarding delay in remaining excavation field work due to PGE gas line delays
Title URL:
Document Type: Correspondence
Activity Type: Completed Activities
Date Completed: 4/13/2021
Comments: Excavation of drainage ditch in Ecodyne Corp/Tower Site is delayed because of PGE work to decommission gas line delayed again by PGE. PGE work scheduled now for 6/2021.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Implementation of Remedial Action: Excavation
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60305050
Document Type: Fieldwork
Activity Type: Completed Activities
Date Completed: 2/1/2019
Comments: RAP Implementation complete, soil excavation met unrestricted cleanup goals.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Post Excavation Sampling Report(prior to partial backfill)
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60426601
Document Type: Other Report
Activity Type: Completed Activities
Date Completed: 5/10/2017
Comments: Letter was requires for approval to backfill Excavation 7 and a Portion of Excavation 8. Letter provided data and 95 UCL calculation. One sample location must be excavated prior backfill of that location. Other areas are okay for backfill.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Summary of Analytical Air Sampling Results Collected on November 13, 2016
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60422852
Document Type: Monitoring Report
Activity Type: Completed Activities
Date Completed: 3/9/2017
Comments: DTSC Industrial Hygienist and Toxicologist review concurred on the conclusions of the air monitoring report; there is no significant risk to workers or public if vapor control measures are followed.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Letter to Mr. Jared Carter from Thomas Lanphar 2-17-2016
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60420289
Document Type: Correspondence
Activity Type: Completed Activities
Date Completed: 2/17/2016
Comments: letter to Mr. Carter on the subject of the Remedial Action Plan and Land Use Covenant

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: DTSC Letter to Fluor requesting addendum to Remedial Design Workplan
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60405871
Document Type: Correspondence
Activity Type: Completed Activities
Date Completed: 2/17/2016
Comments: Letter to Fluor requesting Addendum to RDIP was a result of in field adjustment to implementation work due to increase in size of excavations.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: 2015 Annual Oversight Cost Estimate
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60277349
Document Type: Annual Oversight Cost Estimate
Activity Type: Completed Activities
Date Completed: 9/28/2015
Comments:

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Public Notice Remedial Action Plan Explanation of Significant Differences
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60381534
Document Type: Public Notice
Activity Type: Completed Activities
Date Completed: 9/10/2015

Comments:

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Evaluation of Potential change in CEQA Determination
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60313282
Document Type: Technical Report
Activity Type: Completed Activities
Date Completed: 2/4/2013
Comments: This report evaluates the former CEQA decision as it relates to a proposed change in remedy.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Workplan for Additional Soil and Groundwater Sampling - Post Ozonation Pilot Study
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=6012386
Document Type: Treatability Study Workplan
Activity Type: Completed Activities
Date Completed: 8/18/2006
Comments: Workplan approved.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Supplemental Sampling Plan for Limited Off-Site Sampling Within the Drainage Ditch
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60417729
Document Type: Site Characterization Workplan
Activity Type: Completed Activities
Date Completed: 6/1/1992
Comments: The purpose of the workplan was to provide additional soil data in drainage ditch after the completion of the RI Report.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Public Participation Plan / Community Relations Plan
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=5002105
Document Type: Public Participation Plan / Community Relations Plan
Activity Type: Completed Activities
Date Completed: 1/31/1991
Comments: Public Participation Plan prepared for the site.

Area Name:
Area URL:
Sub Area:
Sub Area URL:
Title: Letter from The Shiloh Group regarding backfill of Excavation
Title URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60427455
Document Type: Correspondence
Activity Type: Completed Activities
Date Completed: 5/24/2017
Comments: sent letter to The Shiloh Group explaining the evaluation of data and that data showed confirmation samples meet remedial goals.

Community Involvement Documents

OU Name:
Area:
Title/Description: Draft RAP Public Notice
Title/Description URL: https://www.envirostor.dtsc.ca.gov/public/community_involvement_documents?global_id=49240001&document_folder=+2438077628
Document Type: Public Meeting Notice
Document Date: 2/16/2011

Document Group: UPDATES AND INFORMATION

OU Name:
Area:
Title/Description: Public Notice Remedial Action Plan Explanation of Significant Differences
Title/Description URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60381534
Document Type: Public Notice
Document Date: 9/10/2015
Document Group: UPDATES AND INFORMATION

OU Name:
Area:
Title/Description: Draft CEQA Negative Declaration
Title/Description URL: https://www.envirostor.dtsc.ca.gov/public/community_involvement_documents?global_id=49240001&document_folder=+7412275016
Document Type: CEQA
Document Date: 2/16/2011
Document Group: DRAFT DOCUMENTS FOR REVIEW

OU Name:
Area:
Title/Description: Public Notice
Title/Description URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=6009091
Document Type: Public Notice
Document Date: 2/16/2011
Document Group: UPDATES AND INFORMATION

OU Name:
Area:
Title/Description: Public Participation Plan - New
Title/Description URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=6020626
Document Type: Public Participation Plan
Document Date: 5/29/2009
Document Group: PROJECT RELATED DOCUMENTS

OU Name:
Area:
Title/Description: California Environmental Quality Act (CEQA) Initial Study
Title/Description URL: https://www.envirostor.dtsc.ca.gov/public/community_involvement_documents?global_id=49240001&document_folder=+2923673331
Document Type: CEQA
Document Date: 2/16/2011
Document Group: DRAFT DOCUMENTS FOR REVIEW

OU Name:
Area:
Title/Description: Public Participation Plan / Community Relations Plan
Title/Description URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=5002105
Document Type: Public Participation Plan
Document Date: 1/31/1991
Document Group: PROJECT RELATED DOCUMENTS

OU Name:
Area:
Title/Description: Draft Preliminary Non-Binding Allocation of Responsibility
Title/Description URL: https://www.envirostor.dtsc.ca.gov/public/community_involvement_documents?global_id=49240001&document_folder=+4360685050
Document Type: Remedial Action Plan
Document Date: 2/16/2011
Document Group: DRAFT DOCUMENTS FOR REVIEW

OU Name:
Area:
Title/Description: Draft RAP Fact Sheet
Title/Description URL: https://www.envirostor.dtsc.ca.gov/public/community_involvement_documents?global_id=49240001&document_folder=+2125928580
Document Type: Public Meeting Notice
Document Date: 2/16/2011
Document Group: UPDATES AND INFORMATION

OU Name:
Area:
Title/Description: Remedial Action Plan for Ecodyne Pond Site Soil Remediation, Final Draft
Title/Description URL: https://www.envirostor.dtsc.ca.gov/public/community_involvement_documents?global_id=49240001&document_folder=+1313214957
Document Type: Remedial Action Plan
Document Date: 2/16/2011
Document Group: DRAFT DOCUMENTS FOR REVIEW

OU Name:
Area:
Title/Description: Fact Sheet
Title/Description URL: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=6009089
Document Type: Fact Sheet
Document Date: 2/16/2011
Document Group: FACT SHEETS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
62	3 of 3	W	0.26 / 1,355.29	114.45 / -6	ECODYNE POND 930 SHILOH RD WINDSOR CA 95492	ENVIROSTOR

Estor/EPA ID: 49240001
Site Code: 200028
Nat Priority List: NO
APN: 05-9271-014
Census Tract: 6097152702
Site Type: STATE RESPONSE OR NPL
Address Description: 930 SHILOH RD
Office: CLEANUP BERKELEY
Special Program:
Funding: RESPONSIBLE PARTY
Assembly District: 02
Senate District: 02
Permit Renewal Lead:
Public Partici Spclst:
Project Manager: TOM LANPHAR
County: SONOMA
Latitude: 38.5213488483674
Longitude: -122.793704398678
Acres: 1.6 ACRES
Supervisor: KIMBERLY WALSH
Cleanup Status: ACTIVE AS OF 5/1/1986
Cleanup Oversight Agencies: DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY;RWQCB 1 - NORTH COAST
School District:
Past Use that Caused Contam: MANUFACTURING - LUMBER/WOOD PRODUCTS
Potential Media Affected: OTHER GROUNDWATER AFFECTED (USES OTHER THAN DRINKING WATER), SOIL
Potential Contamin of Concern:

DIOXIN (AS 2,3,7,8-TCDD TEQ)
LEAD
PENTACHLOROPHENOL
POLYNUCLEAR AROMATIC HYDROCARBONS (PAHS)

Site History:

The Site consists of approximately 30,000 square feet located within the 28-acre Shiloh Road Industrial Park. From 1952 to 1961 the Site was used for wood treatment operations in support of storage tank and cooling tower manufacturing. In addition to wood treatment at the Site, lead coatings were applied to hardware for tanks and piping. Fluor sold the property and business in 1969 to Ecodyne Corporation and Fluor Products Company became a wholly owned subsidiary of Ecodyne Corporation. Ecodyne. Ecodyne Corporation continued operations at the site until 1984 when they sold the property to Mr. Shah. The Shiloh Group purchased the property from Mr. Shah in 1999.

Site assessment, characterization and remedial investigation undertaken between 1985 and 1998 identified PAHs, lead and dioxin in soils at the Site. On May 4, 2011 DTSC approved a Remedial Action Plan (RAP). The remedy approved in the included in-situ ozonation, for the treatment of PAHs in soil, and excavation with off-site disposal for soil containing lead and dioxin above levels appropriate for industrial use.

On August 26, 2014 DTSC informed Fluor Corporation that new information on the Site had caused DTSC to reevaluate the selected remedial action. DTSC determined that the selected remedy in the 2011 RAP was not protective of human health and the environment because of the following:

1) the selected remedy was based on the existence of an asphalt and concrete cover over the Site;
2) the asphalt and concrete cover currently contains cracks and areas of exposed soil;
3) operations and maintenance of the cover was not included in the 2011 RAP; and
4) the selected remedy does not address the possible transport of potentially contaminated soil, which may be exposed at the surface, to offsite locations.

In response to DTSC's determination, Fluor Corporation submitted a Revised RAP that includes the following changes:
• Elimination of ozonation as on-site soil treatment;
• Changes in the cleanup goals to meet unrestrictive standards;
• An increase in the amount of soil being excavated from 500 cubic yards to 819 cubic yard;

• Elimination of the need for a Land Use Covenant, which would prohibit the use of the property for residential or other sensitive uses;
• Elimination Operations and Maintenance requirements.
DTSC approved the Revised RAP on September 8, 2015. Fluor Corporation began implementation of the Revised RAP in October 2015. Identification of additional areas of contamination and the need to suspend excavation activities during the winter months has delayed the completion of the Revised RAP implementation. The completion of the excavation, backfill and site restoration is schedule for completion in October 2018.

Directly adjacent to the Ecodyne Pond Site to the northwest is another hazardous waste site currently undergoing remediation. The adjacent site is known as the Ecodyne (Cooling) Towers Site. The Ecodyne Towers Site is being cleaned up with the oversight of the Regional Water Quality Control Board (RWQCB).
(Updated 9/12/2018; TPL)

Status: ACTIVE
Program Type: STATE RESPONSE
CalEnviroScreen Score: 46-50%
Summary Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=49240001

Currently Scheduled Activities

Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Certification
Due Date: 4/9/2022
Revised Date:

Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Remedial Action Completion Report
Due Date: 4/24/2022
Revised Date:

Completed Activities

Title: Correspondence regarding delay in remaining excavation field work due to PGE gas line delays
Title Link: https://www.envirostor.dtsc.ca.gov/public/
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 4/13/2021
Comments: Excavation of drainage ditch in Ecodyne Corp/Tower Site is delayed because of PGE work to decommission gas line delayed again by PGE. PGE work scheduled now for 6/2021.

Title: Interim Soil Removal Completion Report and Winterization Workplan
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60434891
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Remedial Action Completion Report
Date Completed: 10/17/2017
Comments: Work plan is for placing a temporary asphalt cover to eliminate rain water in excavation. Excavation will continue in Spring or Summer 208.

Title: Work Notice Soil Excavation
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60273750
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Work Notice
Date Completed: 11/13/2015

Comments: Work notice was sent to site mailing list.

Title: 2015 Annual Oversight Cost Estimate
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60277349
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 9/28/2015
Comments:

Title: Well Destruction Work Plan
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60398902
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Well Decommissioning Workplan
Date Completed: 9/2/2015
Comments: The Well Destruction Work Plan describes the destruction of onsite wells.

Title: Letter from TransTech Consultants on groundwater in shallow zone wells
Title Link: https://www.envirostor.dtsc.ca.gov/public/
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 10/7/2014
Comments: Letter from Trans Tech Consultants, representing Shiloh Group LLC, on the issue of shallow groundwater wells.

Title: Feasibility Study
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=6016030
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Feasibility Study Report
Date Completed: 11/20/2008
Comments:

Title: Workplan for Additional Soil and Groundwater Sampling - Post Ozonation Pilot Study
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=6012386
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Treatability Study Workplan
Date Completed: 8/18/2006
Comments: Workplan approved.

Title: Remedial Investigation / Feasibility Study
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=5002097
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Treatability Study Report
Date Completed: 12/15/2003
Comments: Pilot study utilizing in-situ ozonation to reduce source contaminants implemented at the Site between November 1997 and July 1998. Ozone was injected to the subsurface to reduce contaminant concentrations. Results indicated that the technology reduced contaminant concentrations of PCP and PAHs in soil by 87%.

Title: Supplemental Sampling Plan for Limited Off-Site Sampling Within the Drainage Ditch
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60417729
Area Name:
Area Link:
Sub Area:

Sub Area Link:
Document Type: Site Characterization Workplan
Date Completed: 6/1/1992
Comments: The purpose of the workplan was to provide additional soil data in drainage ditch after the completion of the RI Report.

Title: Annual Cost Estimate
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60417102
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 9/27/2016
Comments: Annual cost estimate for DTSC oversight costs.

Title: DTSC Letter to Fluor requesting addendum to Remedial Design Workplan
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60405871
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 2/17/2016
Comments: Letter to Fluor requesting Addendum to RDIP was a result of in field adjustment to implementation work due to increase in size of excavations.

Title: Public Notice Remedial Action Plan Explanation of Significant Differences
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60381534
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Public Notice
Date Completed: 9/10/2015
Comments:

Title: Soil Investigation for better delineation of planned excavated soil
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60305046
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Fieldwork
Date Completed: 10/30/2012
Comments:

Title: Site Investigtion Work Plan in support of Remedial Design
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60304826
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Site Characterization Workplan
Date Completed: 8/3/2012
Comments: approved work plan

Title: Public Notice
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=6009091
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Public Notice
Date Completed: 2/16/2011
Comments: Public notice published in Press Democrat to announce 30-day public comment period for Draft Remedial Action Plan and CEQA Negative Declaration/Initial Study.

Title: Native American Heritage Commission

Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60188256
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 2/2/2010
Comments: Letter faxed and reply received. No cultural resources found on Site.

Title: In-Situ Ozonation Technology Demonstrations Project Report for Remediation of PCP and PAHs in Soil and Groundwater
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60188622
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Remedial Investigation Report
Date Completed: 12/15/2003
Comments:

Title: Remedial Investigation / Feasibility Study
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=5002103
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Remedial Investigation / Feasibility Study
Date Completed: 2/14/1994
Comments: RI/FS with capping of the site with land use restrictions as the recommended alternative approved. This alternative was subsequently rejected after public comment.

Title: Soil Removal Completion Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=6020627
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Remedial Action Completion Report
Date Completed: 6/26/2019
Comments: Soil has been excavated and sent off-site for disposal. Unrestricted cleanup goals met and No Further Action is needed for Ecodyne Pond Site. Additional work needed at the Ecodyne Tower Site to address contamination that migrated off-site.

Title: Summary of Analytical Air Sampling Results Collected on November 13, 2016
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60422852
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Monitoring Report
Date Completed: 3/9/2017
Comments: DTSC Industrial Hygienist and Toxicologist review concurred on the conclusions of the air monitoring report; there is no significant risk to workers or public if vapor control measures are followed.

Title: Letter to Verrill Dana LLP, representing Fluor Corp. regarding deficiencies in remedy at Ecodyne Pond
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60379666
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 8/26/2014
Comments: Letter addresses DTSC evaluation of information on Ecodyne Pond Site and reevaluation of selected remedy.

Title: 2012 Annual Oversight Cost Estimate
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60277347
Area Name:
Area Link:
Sub Area:

Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 8/17/2012
Comments:

Title: Fact Sheet
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=6009089
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Fact Sheets
Date Completed: 2/16/2011
Comments: Fact sheet mailed out to to announce 30-day public comment period for Draft Remedial Action Plan and CEQA Negative Declaration/Initial Study.

Title: Cost Estimates 2009-2010
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=6017387
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 9/15/2009
Comments: Received cost estimate acknowledgment from Fluor.

Title: Public Participation Plan - New
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=6020626
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Public Participation Plan / Community Relations Plan
Date Completed: 5/29/2009
Comments: PPP final and signed.

Title: Site Certification
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=6012819
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Certification
Date Completed: 6/27/2019
Comments: Soil has been excavated and disposed of off-site. Remediation met unrestricted cleanup goals and no further action is required for the Ecodyne Pond Site. More work is needed at the adjacent Ecodyne Tower Site to address contaminants that have migrated off of the Pond Site and onto the Tower Site.

Title: Annual Cost Estimate
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60433566
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 9/28/2017
Comments: Cost estimate for DTSC oversight for FY 2017-2018.

Title: Letter from The Shiloh Group regarding backfill of Excavation
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60427455
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 5/24/2017
Comments: sent letter to The Shiloh Group explaining the evaluation of data and that data showed confirmation samples meet remedial goals.

Title: Backfill Request for Excavation 7 and portion of 8: Post Excavation Soil Sampling
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60427449
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Monitoring Report
Date Completed: 5/24/2017
Comments:

Title: Post Excavation Sampling Report(prior to partial backfill)
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60426601
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 5/10/2017
Comments: Letter was requires for approval to backfill Excavation 7 and a Portion of Excavation 8. Letter provided data and 95 UCL calculation. One sample location must be excavated prior backfill of that location. Other areas are okay for backfill.

Title: Letter to Mr. Jared Carter from Thomas Lanphar 2-17-2016
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60420289
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 2/17/2016
Comments: letter to Mr. Carter on the subject of the Remedial Action Plan and Land Use Covenant

Title: 2013 Annual Oversight Cost Estimate
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60277348
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 10/30/2014
Comments:

Title: Memo to File: DTSC investigation in to issues raised by Trans Tech Consultant for The Shiloh Group LLC regarding RDIP
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60328774
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 6/30/2014
Comments:

Title: 2011 Annual Oversight Cost Estimate
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60275716
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 10/6/2011
Comments: cost estimate sent to Ecodyne Pond

Title: Initial Study & Negative Declaration
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=6011123
Area Name:
Area Link:
Sub Area:
Sub Area Link:

Document Type: CEQA - Initial Study/ Neg. Declaration
Date Completed: 5/3/2011
Comments: NOD and Negative Declaration signed 5.3.11.

Title: Remedial or Removal Design
Title Link: https://www.envirostor.dtsc.ca.gov/public/
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Design/Implementation Workplan
Date Completed: 6/4/1997
Comments: An alternate treatment utilizing in-situ treatment of soils containing organic contaminants with ozonation presented.

Title: Order
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=5002104
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Amendment - Order/Agreement
Date Completed: 6/13/1991
Comments: Order Amendment Signed

Title: Order
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=5002106
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Consent Order
Date Completed: 12/31/1989
Comments: Consent Agreement with the Fluor Corporation to conduct remediation activities at the former Ecodyne Pond site.

Title: Site Screening
Title Link: https://www.envirostor.dtsc.ca.gov/public/
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Site Screening
Date Completed: 3/24/1987
Comments:

Title: Implementation of Remedial Action: Excavation
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60305050
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Fieldwork
Date Completed: 2/1/2019
Comments: RAP Implementation complete, soil excavation met unrestricted cleanup goals.

Title: Revised Remedial Design and Implementation Plan
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60298314
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Remedial Action Implementation Workplan
Date Completed: 9/23/2015
Comments:

Title: Letter from DTSC to Fluor Corporation requesting a Amended RAP for Site
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60388789
Area Name:
Area Link:
Sub Area:

Sub Area Link:
Document Type: Correspondence
Date Completed: 1/15/2015
Comments: Letter requests the submittal of a revised RAP for Ecodyne Pond site to address COCs in soil.

Title: Letter on proposal to revise RAP for Ecodyne Pond Site
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60385866
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 11/6/2014
Comments: Letter from Verrill Dana, representing Fluor Corporation, stating intent to revise the remedy for Ecodyne Pond Site.

Title: Site Investigation Report: defining extent of excavation
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60305048
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Technical Report
Date Completed: 3/25/2013
Comments: This Report documents the recent site investigation conducted at the Ecodyne Pond Site. The purpose of the investigation is to update information on the extent of the contaminants of concern at the site and to prepare a preliminary map showing the predicted extent of future excavations.

Title: Human Health Risk Assessment
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=6016029
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Risk Assessment Report
Date Completed: 12/15/2003
Comments: Risk Assessment approved.

Title: Remedial Design and Implementation Plan - Addendum
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60428379
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Remedial Action Implementation Workplan
Date Completed: 6/20/2017
Comments: Addendum adds additional excavation in the trench area south of Ecodyne Pond site boundary. It also adds a disposal facility for non-hazardous waste soil.

Title: Remedial Design Implementation Plan Addendum
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60409406
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Design/Implementation Workplan
Date Completed: 4/16/2016
Comments: The addendum addresses changes in plan caused by increases in amount of excavated soil.

Title: Remedial Action Plan Revision
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60379706
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Remedial Action Plan w/ESD
Date Completed: 9/10/2015
Comments: DTSC has determined that the RAP Revision satisfactorily addresses all applicable state and federal statutes and regulations and therefore approves the document.

Title: letter on shallow groundwater
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60386964
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 1/15/2015
Comments:

Title: Evaluation of Potential change in CEQA Determination
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60313282
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Technical Report
Date Completed: 2/4/2013
Comments: This report evaluates the former CEQA decision as it relates to a proposed change in remedy.

Title: Notice of New Project Manger Ltr
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=6013901
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 5/21/2009
Comments: Letter Send.

Title: Soil and Groundwater Sampling
Title Link: https://www.envirostor.dtsc.ca.gov/public/
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Fieldwork
Date Completed: 11/13/2006
Comments: All groundwater and soil sampling activities have been completed as of 11/13/2006.

Title: Cost Recovery Demand Letter
Title Link: https://www.envirostor.dtsc.ca.gov/public/
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Other Report
Date Completed: 7/28/2005
Comments:

Title: 2021 - 2022 Annual DTSC Oversight Cost Estimate
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60506774
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 9/10/2021
Comments: annual oversight estimate 2021 -2022

Title: 2018 - 2019 Annual Oversight Cost Estimate
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60451486
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Annual Oversight Cost Estimate
Date Completed: 10/1/2018
Comments: Annual cost estimate for DTSC oversight.

Title: Environmental Document Analysis
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60393479
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: CEQA - Initial Study/ Neg. Declaration
Date Completed: 9/8/2015
Comments: An addendum to the previously adopted negative declaration was prepared by DTSC because of significant changes in the remedial action for the site.

Title: Revised Remediation Work Plan
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60298031
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 5/16/2012
Comments: DTSC agrees to consider a change to the Ecodyne remedial action plan.

Title: Remedial Design Workplan
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=6021992
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Design/Implementation Workplan
Date Completed: 3/14/2012
Comments: RDIP approved with conditions.

Title: Soil & Groundwater Sampling Summary Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=6012828
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Remedial Investigation Report
Date Completed: 6/1/2007
Comments: Report approved with modifications.

Title: Public Participation Plan / Community Relations Plan
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=5002105
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Public Participation Plan / Community Relations Plan
Date Completed: 1/31/1991
Comments: Public Participation Plan prepared for the site.

Title: Removal Action Completion Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Removal Action Completion Report
Date Completed: 2/28/1986
Comments: A berm was constructed on the southwestern edge of the site to prevent potential transport of chemicals in site runoff.

Title: Air Monitoring for Ecodyne Pond Site
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=60418670
Area Name:
Area Link:
Sub Area:
Sub Area Link:

Document Type: Monitoring Plan
Date Completed: 11/10/2016
Comments: air monitoring plan approved and implemented on November 13, 2016. Tom Lanphar, Project Manager for DTSC, was present during the monitoring.

Title: Letters from Brian Carter to Tom Lanphar
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60310641
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 11/19/2012
Comments: letter in reponse to Mr. Carters letter

Title: Response to June 12, 2012 letter from Shilo Group Representative
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60302949
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 8/15/2012
Comments: letter completed

Title: Remedial Action Plan
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&doc_id=6016031
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Remedial Action Plan
Date Completed: 5/5/2011
Comments:

Title: Order to Post and Fence Docket #PF 88/89-003 for Ecodyne Pond
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49240001&enforcement_id=60426627
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Fence & Post Order
Date Completed: 3/10/1989
Comments: Order to Post and Fence for Ecodyne Pond Site

63	1 of 2	WNW	0.26 / 1,355.77	109.45 / -11	AIRPORT BUSINESS CENTER (LOTS 15 & 16) 1010 SHILOH ROAD WINDSOR CA 95492	CLEANUP SITES

Global ID: T0609793410
Status: COMPLETED - CASE CLOSED
Status Date: 12/20/2004
Site Facility Type: CLEANUP PROGRAM SITE
Data Source: Cleanup Program Sites from GeoTracker Search; Cleanup Sites from GeoTracker Cleanup Sites Data Download
Latitude: 38.524468
Longitude: -122.798524
County: SONOMA

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail

RB Case No: 1NSO648
Local Case No:
Begin Date: 6/2/1997
File Location: Regional Board
Lead Agency: NORTH COAST RWQCB (REGION 1)
Local Agency: SONOMA COUNTY
Potential COC: Diesel
Potential Media of Concern: Aquifer used for drinking water supply
How Discovered: Other Means
Stop Method:
CUF Case: NO
Case Worker: ZZZ

How Discovered Description:
Stop Description:
CalWater Watershed Name: Russian River - Middle Russian River - Mark West (114.23)
DWR GW Subbasin Name: Santa Rosa Valley - Santa Rosa Plain (1-055.01)
Disadvantaged Community:
CalEnviroScreen Score: 66-70%
Site History:

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity

Action Type: ENFORCEMENT
Date: 2006-10-26 00:00:00
Action: * No Action

Action Type: RESPONSE
Date: 2004-12-31 00:00:00
Action: Other Workplan

Action Type: ENFORCEMENT
Date: 2004-12-22 00:00:00
Action: * No Action

Action Type: ENFORCEMENT
Date: 2004-10-26 00:00:00
Action: Staff Letter

Action Type: RESPONSE
Date: 2004-09-01 00:00:00
Action: Monitoring Report - Quarterly

Action Type: ENFORCEMENT
Date: 2004-07-30 00:00:00
Action: Staff Letter

Action Type: RESPONSE
Date: 2004-07-16 00:00:00
Action: Other Report / Document

Action Type: ENFORCEMENT
Date: 2004-07-13 00:00:00
Action: Staff Letter

Action Type: ENFORCEMENT
Date: 2004-06-18 00:00:00
Action: Staff Letter

Action Type: RESPONSE
Date: 2004-05-31 00:00:00
Action: Monitoring Report - Quarterly

Action Type: ENFORCEMENT
Date: 2004-05-14 00:00:00
Action: Staff Letter

Action Type: RESPONSE
Date: 2004-02-28 00:00:00
Action: Monitoring Report - Quarterly

Action Type: ENFORCEMENT
Date: 2004-01-12 00:00:00
Action: Staff Letter

Action Type: RESPONSE
Date: 2004-01-01 00:00:00
Action: Other Report / Document

Action Type: ENFORCEMENT

Date: 2003-12-12 00:00:00
Action: Staff Letter

Action Type: RESPONSE
Date: 2003-12-01 00:00:00
Action: Monitoring Report - Quarterly

Action Type: RESPONSE
Date: 2003-10-31 00:00:00
Action: Other Report / Document

Action Type: ENFORCEMENT
Date: 2003-10-16 00:00:00
Action: Staff Letter

Action Type: ENFORCEMENT
Date: 2003-09-30 00:00:00
Action: Staff Letter

Action Type: ENFORCEMENT
Date: 2003-09-29 00:00:00
Action: Staff Letter

Action Type: ENFORCEMENT
Date: 2003-09-22 00:00:00
Action: Staff Letter

Action Type: ENFORCEMENT
Date: 2003-09-17 00:00:00
Action: Staff Letter

Action Type: RESPONSE
Date: 2003-07-01 00:00:00
Action: Preliminary Site Assessment Report

Action Type: ENFORCEMENT
Date: 2003-05-28 00:00:00
Action: * No Action

Action Type: ENFORCEMENT
Date: 2003-05-08 00:00:00
Action: * No Action

Action Type: RESPONSE
Date: 2003-04-14 00:00:00
Action: Unknown

Action Type: ENFORCEMENT
Date: 2003-03-27 00:00:00
Action: Staff Letter

Action Type: ENFORCEMENT
Date: 2003-03-14 00:00:00
Action: Staff Letter

Action Type: ENFORCEMENT
Date: 2002-04-10 00:00:00
Action: Staff Letter

Action Type: ENFORCEMENT
Date: 2002-01-15 00:00:00
Action: Staff Letter

Action Type: Other
Date: 1997-06-02 00:00:00
Action: Leak Reported

Action Type: Other
Date: 1997-06-02 00:00:00

Action: Leak Discovery

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History

Status: Completed - Case Closed
Status Date: 2004-12-20 00:00:00

Status: Open - Verification Monitoring
Status Date: 2003-11-02 00:00:00

Status: Open - Verification Monitoring
Status Date: 2003-11-01 00:00:00

Status: Open - Site Assessment
Status Date: 2003-09-10 00:00:00

Status: Open - Site Assessment
Status Date: 2001-12-04 00:00:00

Status: Open - Site Assessment
Status Date: 2001-03-26 00:00:00

Status: Open - Site Assessment
Status Date: 2000-07-06 00:00:00

Status: Open - Case Begin Date
Status Date: 1997-06-02 00:00:00

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts

Contact Type: Local Agency Caseworker
Contact Name: ENVIRON HEALTH STAFF (NON LOP-RB1)
Phone No:
Organization Name: SONOMA COUNTY
Email:
Address: 625 5th Street
City: SANTA ROSA

Contact Type: Regional Board Caseworker
Contact Name: REGIONAL WATER BOARD SITE CLOSED
Phone No: 7075762220
Organization Name: NORTH COAST RWQCB (REGION 1)
Email:
Address: 5550 SKYLANE BOULEVARD, SUITE A
City: SANTA ROSA

Cleanup Program Sites from GeoTracker Search - Regulatory Profile (as of May 29, 2021)

Project Status:
Cuf Claim No:
CUF Priority Assign:
CUF Amount Paid:
Composting Method:
File Location: REGIONAL BOARD
User Defined Beneficial Use:
Designated Beneficial Use: MUN, AGR, IND, PROC, FRSH, CUL, AQUA - Note: R1 BP- all gw same uses.
Designated Beneficl Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply, Freshwater Replenishment, Native American Culture, AQUA - Note: R1 BP- all gw same uses.
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T0609793410
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 12/20/2004
Potential COC: DIESEL
Potential Media of Concern: AQUIFER USED FOR DRINKING WATER SUPPLY
Groundwater Monitoring Frequen:
DWR GW Sub Basin: Santa Rosa Valley - Santa Rosa Plain (1-055.01)
CalWater Watershed Name: Russian River - Middle Russian River - Mark West (114.23)
Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: NORTH COAST RWQCB (REGION 1) (LEAD) - CASE #: 1NSO648
Facility Type:
WDR Place Type:
Wdr File No:
Wdr Order No:

CASEWORKER: REGIONAL WATER BOARD SITE CLOSED
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0609793410&tabname=regulatoryhistory
Site History:

No site history available

Sites from GeoTracker Search - Regulatory Activities (as of May 29, 2021)

Action Type: Enforcement - Other
Action Date: 10/26/2006
Received Issue Date: 10/26/2006
Action: * No Action
Doc Link:
Title Description Comments:

Action Type: Response Requested - Workplans
Action Date: 12/31/2004
Received Issue Date: 11/2/2004
Action: Other Workplan
Doc Link:
Title Description Comments:

- Monitoring Well destruction application from Sonoma County

Action Type: Enforcement - Other
Action Date: 12/22/2004
Received Issue Date: 12/22/2004
Action: * No Action
Doc Link:
Title Description Comments:

Action Type: Other Regulatory Actions
Action Date: 10/26/2004
Received Issue Date: 10/26/2004
Action: Staff Letter
Doc Link:
Title Description Comments:

Action Type: Response Requested - Reports
Action Date: 9/1/2004
Received Issue Date: 9/16/2004
Action: Monitoring Report - Quarterly
Doc Link:
Title Description Comments:

Monitoring Report - Quarterly

Action Type: Other Regulatory Actions
Action Date: 7/30/2004
Received Issue Date: 7/30/2004
Action: Staff Letter
Doc Link:
Title Description Comments:

Action Type: Response Requested - Other
Action Date: 7/16/2004
Received Issue Date: 7/6/2004
Action: Other Report / Document
Doc Link:
Title Description Comments:

Action Type: Other Regulatory Actions
Action Date: 7/13/2004
Received Issue Date: 7/13/2004
Action: Staff Letter
Doc Link:
Title Description Comments:

Action Type: Other Regulatory Actions
Action Date: 6/18/2004
Received Issue Date: 6/18/2004
Action: Staff Letter
Doc Link:
Title Description Comments:

Action Type: Response Requested - Reports
Action Date: 5/31/2004
Received Issue Date: 5/7/2004
Action: Monitoring Report - Quarterly
Doc Link:
Title Description Comments:

Monitoring Report - Quarterly - 2nd QRPT

Action Type: Other Regulatory Actions
Action Date: 5/14/2004
Received Issue Date: 5/14/2004
Action: Staff Letter
Doc Link:
Title Description Comments:

Action Type: Response Requested - Reports
Action Date: 2/28/2004
Received Issue Date: 4/21/2004
Action: Monitoring Report - Quarterly
Doc Link:
Title Description Comments:

Monitoring Report - Quarterly - Quarterly monitoring report

Action Type: Other Regulatory Actions
Action Date: 1/12/2004
Received Issue Date: 1/12/2004
Action: Staff Letter
Doc Link:
Title Description Comments:

Action Type: Response Requested - Other
Action Date: 1/1/2004
Received Issue Date: 11/25/2003
Action: Other Report / Document
Doc Link:
Title Description Comments:

- Native Material Reuse letter

Action Type: Other Regulatory Actions
Action Date: 12/12/2003
Received Issue Date: 12/12/2003
Action: Staff Letter
Doc Link:
Title Description Comments:

Action Type: Response Requested - Reports
Action Date: 12/1/2003
Received Issue Date: 12/11/2003
Action: Monitoring Report - Quarterly
Doc Link:
Title Description Comments:

Monitoring Report - Quarterly

Action Type: Response Requested - Other
Action Date: 10/31/2003
Received Issue Date: 11/25/2005
Action: Other Report / Document
Doc Link:
Title Description Comments:

- Comments on Stockpile use for Excavation Backfill

Action Type: Other Regulatory Actions
Action Date: 10/16/2003
Received Issue Date: 10/16/2003
Action: Staff Letter
Doc Link:
Title Description Comments:

Action Type: Other Regulatory Actions
Action Date: 9/30/2003
Received Issue Date: 9/30/2003
Action: Staff Letter
Doc Link:
Title Description Comments:

Action Type: Other Regulatory Actions
Action Date: 9/29/2003
Received Issue Date: 9/29/2003
Action: Staff Letter
Doc Link:
Title Description Comments:

Action Type: Other Regulatory Actions
Action Date: 9/22/2003
Received Issue Date: 9/22/2003
Action: Staff Letter
Doc Link:
Title Description Comments:

Action Type: Other Regulatory Actions
Action Date: 9/17/2003
Received Issue Date: 9/17/2003
Action: Staff Letter
Doc Link:
Title Description Comments:

Action Type: Response Requested - Reports
Action Date: 7/1/2003
Received Issue Date: 9/10/2003
Action: Preliminary Site Assessment Report
Doc Link:
Title Description Comments:

Preliminary Site Assessment Report

Action Type: Enforcement - Other
Action Date: 5/28/2003
Received Issue Date: 5/28/2003
Action: * No Action
Doc Link:
Title Description Comments:

Action Type: Enforcement - Other
Action Date: 5/8/2003
Received Issue Date: 5/8/2003
Action: * No Action
Doc Link:
Title Description Comments:

Action Type: Response Requested - Other
Action Date: 4/14/2003
Received Issue Date: 4/14/2003
Action: Unknown
Doc Link:
Title Description Comments:

Describes the current status of the source water - Pit water analytical data

Action Type: Other Regulatory Actions
Action Date: 3/27/2003
Received Issue Date: 3/27/2003
Action: Staff Letter
Doc Link:
Title Description Comments:

Concur with workplan / Requerst for report of field findings

Action Type: Other Regulatory Actions
Action Date: 3/14/2003
Received Issue Date: 3/14/2003
Action: Staff Letter
Doc Link:
Title Description Comments:

Review Workplan - Proposed Groundwater Investigation

Action Type: Other Regulatory Actions
Action Date: 4/10/2002
Received Issue Date: 4/10/2002
Action: Staff Letter
Doc Link:
Title Description Comments:

Action Type: Other Regulatory Actions
Action Date: 1/15/2002
Received Issue Date: 1/15/2002
Action: Staff Letter
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action Date: 6/2/1997
Received Issue Date:
Action: Leak Discovery
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action Date: 6/2/1997
Received Issue Date:
Action: Leak Reported
Doc Link:
Title Description Comments:

Sites from GeoTracker Search - Cleanup Status History (as of May 29, 2021)

Status: Completed - Case Closed
Date: 12/20/2004

Status: Open - Verification Monitoring
Date: 11/2/2003

Status: Open - Verification Monitoring
Date: 11/1/2003

Status: Open - Site Assessment
Date: 9/10/2003

Status: Open - Site Assessment
Date: 12/4/2001

Status: Open - Site Assessment
Date: 3/26/2001

Status: Open - Site Assessment
Date: 7/6/2000

Status: Open - Case Begin Date
Date: 6/2/1997

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
63	2 of 2	WNW	0.26 / 1,355.77	109.45 / -11	AIRPORT BUSINESS CENTER, PHASE 5, LOT 9 1010 SHILOH ROAD WINDSOR CA 95492	CLEANUP SITES

Global ID: SL0609725291
Status: COMPLETED - CASE CLOSED
Status Date: 11/13/1997
Site Facility Type: CLEANUP PROGRAM SITE
Data Source: Cleanup Program Sites from GeoTracker Search; Cleanup Sites from GeoTracker Cleanup Sites Data Download
Latitude: 38.524468
Longitude: -122.798524
County: SONOMA

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail

RB Case No: 1NSO869
Local Case No:
Begin Date: 1/9/1995
File Location: Regional Board
Lead Agency: NORTH COAST RWQCB (REGION 1)
Local Agency:
Potential COC: Diesel
Potential Media of Concern: Aquifer used for drinking water supply
How Discovered:
How Discovered Description:
Stop Description:
CalWater Watershed Name: Russian River - Middle Russian River - Mark West (114.23)
DWR GW Subbasin Name: Santa Rosa Valley - Santa Rosa Plain (1-055.01)
Disadvantaged Community:
CalEnviroScreen Score: 66-70%
Site History:
Stop Method:
CUF Case: NO
Case Worker: ZZZ

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity

Action Type: ENFORCEMENT
Date: 1997-11-12 00:00:00
Action: Staff Letter

Action Type: RESPONSE
Date: 1997-11-12 00:00:00
Action: Other Report / Document

Action Type: ENFORCEMENT
Date: 1997-10-22 00:00:00
Action: Waste Discharge Requirements

Action Type: RESPONSE
Date: 1997-09-01 00:00:00
Action: NPDES / WDR Reports

Action Type: ENFORCEMENT
Date: 1997-08-14 00:00:00
Action: * Public Notification for Remediation

Action Type: RESPONSE
Date: 1997-07-23 00:00:00
Action: Other Report / Document

Action Type: ENFORCEMENT
Date: 1997-07-17 00:00:00
Action: Staff Letter

Action Type: RESPONSE
Date: 1997-06-20 00:00:00
Action: Other Report / Document

Action Type: ENFORCEMENT
Date: 1997-05-07 00:00:00
Action: Notice of Responsibility

Action Type: Other
Date: 1997-02-17 00:00:00
Action: Leak Reported

Action Type: Other
Date: 1995-01-09 00:00:00
Action: Leak Discovery

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History

Status: Completed - Case Closed
Status Date: 1997-11-13 00:00:00

Status: Open - Site Assessment
Status Date: 1997-06-03 00:00:00

Status: Open - Site Assessment
Status Date: 1997-02-23 00:00:00

Status: Open - Site Assessment
Status Date: 1997-02-18 00:00:00

Status: Open - Case Begin Date
Status Date: 1995-01-09 00:00:00

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts

Contact Type: Regional Board Caseworker ***Address:*** 5550 SKYLANE BOULEVARD, SUITE A

Contact Name: REGIONAL WATER BOARD SITE CLOSED **City:** SANTA ROSA
Phone No: 7075762220
Organization Name: NORTH COAST RWQCB (REGION 1)
Email:

Cleanup Program Sites from GeoTracker Search - Regulatory Profile (as of May 29, 2021)

Project Status:
Cuf Claim No:
CUF Priority Assign:
CUF Amount Paid:
Composting Method:
Facility Type:
WDR Place Type:
Wdr File No:
Wdr Order No:
File Location: REGIONAL BOARD
User Defined Beneficial Use:
Designated Beneficial Use: MUN, AGR, IND, PROC, FRSH, CUL, AQUA - Note: R1 BP- all gw same uses.
Designated Beneficl Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply, Freshwater Replenishment, Native American Culture, AQUA - Note: R1 BP- all gw same uses.
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=SL0609725291
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 11/13/1997
Potential COC: DIESEL
Potential Media of Concern: AQUIFER USED FOR DRINKING WATER SUPPLY
Groundwater Monitoring Frequen:
DWR GW Sub Basin: Santa Rosa Valley - Santa Rosa Plain (1-055.01)
CalWater Watershed Name: Russian River - Middle Russian River - Mark West (114.23)
Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: NORTH COAST RWQCB (REGION 1) (LEAD) - CASE #: 1NSO869
CASEWORKER: REGIONAL WATER BOARD SITE CLOSED
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=SL0609725291&tabname=regulatoryhistory
Site History:

No site history available

Sites from GeoTracker Search - Regulatory Activities (as of May 29, 2021)

Action Type: Response Requested - Other
Action Date: 11/12/1997
Received Issue Date: 11/12/1997
Action: Other Report / Document
Doc Link:
Title Description Comments:

OTHER - Waiver Transmitted to RP.

Action Type: Other Regulatory Actions
Action Date: 11/12/1997
Received Issue Date: 11/12/1997
Action: Staff Letter
Doc Link:
Title Description Comments:

Action Type: Enforcement/Orders
Action Date: 10/22/1997
Received Issue Date: 10/22/1997
Action: Waste Discharge Requirements
Doc Link:
Title Description Comments:

Action Type: Response Requested - Reports
Action Date: 9/1/1997
Received Issue Date: 9/1/1997

Action: NPDES / WDR Reports
Doc Link:
Title Description Comments:

Waste Discharge Report - Waiver of WDRs

Action Type: Notices
Action Date: 8/14/1997
Received Issue Date: 8/14/1997
Action: * Public Notification for Remediation
Doc Link:
Title Description Comments:

Action Type: Response Requested - Other
Action Date: 7/23/1997
Received Issue Date: 7/23/1997
Action: Other Report / Document
Doc Link:
Title Description Comments:

Soil Disposal Report - Negative Declaration from Windsor.

Action Type: Other Regulatory Actions
Action Date: 7/17/1997
Received Issue Date: 7/17/1997
Action: Staff Letter
Doc Link:
Title Description Comments:

Action Type: Response Requested - Other
Action Date: 6/20/1997
Received Issue Date: 6/20/1997
Action: Other Report / Document
Doc Link:
Title Description Comments:

OTHER - ROWD

Action Type: Notices
Action Date: 5/7/1997
Received Issue Date: 5/7/1997
Action: Notice of Responsibility
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action Date: 2/17/1997
Received Issue Date:
Action: Leak Reported
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action Date: 1/9/1995
Received Issue Date:
Action: Leak Discovery
Doc Link:
Title Description Comments:

Sites from GeoTracker Search - Cleanup Status History (as of May 29, 2021)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Status: Completed - Case Closed
Date: 11/13/1997

Status: Open - Site Assessment
Date: 6/3/1997

Status: Open - Site Assessment
Date: 2/23/1997

Status: Open - Site Assessment
Date: 2/18/1997

Status: Open - Case Begin Date
Date: 1/9/1995

---

64 | **1 of 2** | **WNW** | **0.26 / 1,390.94** | **109.38 / -11** | **Rasmussen, C.A., Inc.**
1012 Shiloh Rd
Windsor CA | **LOP SONOMA**

LOP No: 00001389
RB No: 1TSO643
Status: Y
Status Desc: Closed Site
Date: 10/7/1999

Global ID: T0609700459
APN: 164-240-010
Staff:
Staff Name:

---

64 | **2 of 2** | **WNW** | **0.26 / 1,390.94** | **109.38 / -11** | **RASMUSSEN, C.A., INC.**
1012 SHILOH RD
WINDSOR CA 95492 | **LUST**

Global ID: T0609700459
Status: COMPLETED - CASE CLOSED
Status Date: 10/7/1999
Case Type: LUST CLEANUP SITE
Date Source: LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download

County: SONOMA
Latitude: 38.523703
Longitude: -122.797016

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail

RB Case No: 1TSO643
Local Case No: 00001389
Begin Date: 11/7/1996
Lead Agency: SONOMA COUNTY LOP
Local Agency: SONOMA COUNTY LOP
CUF Case: YES

Potential COC: Diesel, Gasoline
How Discovered:
Stop Method:
Stop Description:
Case Worker: LCW
File Location: All Files are on GeoTracker or in the Local Agency Database

Potential Media of Concern: Aquifer used for drinking water supply
How Discovered Description:
Calwater Watershed Name: Russian River - Middle Russian River - Mark West (114.23)
DWR GW Subbasin Name: Santa Rosa Valley - Santa Rosa Plain (1-055.01)
Disadvantaged Community:
Calenviroscreen Score: 66-70%
Site History:

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity

Action Type: REMEDIATION
Date : 7/28/1999
Action: Excavation

Action Type: Other
Date : 11/7/1996
Action: Leak Discovery

Action Type: Other
Date : 1/2/1965
Action: Leak Reported

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts

Contact Type: Regional Board Caseworker
Contact Name: SONOMA COUNTY LOP CLOSED SITE
City: SANTA ROSA
Organization Name: NORTH COAST RWQCB (REGION 1)
Address: 5550 SKYLANE BOULEVARD, SUITE A
Email:
Phone No: 7075656565

Contact Type: Local Agency Caseworker
Contact Name: LOP CLOSED IN RB01
City: SANTA ROSA
Organization Name: SONOMA COUNTY LOP
Address: 625 FIFTH STREET
Email:
Phone No:

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History

Status: Completed - Case Closed
Status Date: 10/7/1999

Status: Open - Site Assessment
Status Date: 5/7/1997

Status: Open - Case Begin Date
Status Date: 11/7/1996

LUST Sites from GeoTracker Search - Regulatory Profile

Site Facility Name: RASMUSSEN, C.A., INC.
Site Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Project Status:
WDR Place Type:
WDR File:
WDR Order:
CUF Priority Assig: C
CUF Amount Paid: $28,551
Potential COC: DIESEL, GASOLINE
Facility Type:
Composting Method:
Address: 1012 SHILOH RD
City: WINDSOR
Zip: 95492
County: SONOMA
CUF Claim: 12287, 12287
File Location: ALL FILES ARE ON GEOTRACKER OR IN THE LOCAL AGENCY DATABASE
Designated Beneficial Use: MUN, AGR, IND, PROC, FRSH, CUL, AQUA - Note: R1 BP- all gw same uses.
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T0609700459
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 10/7/1999
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0609700459&tabname=regulatoryhistory
Potential Media of Concern: AQUIFER USED FOR DRINKING WATER SUPPLY
User Defined Beneficial Use:
DWR GW Sub Basin: Santa Rosa Valley - Santa Rosa Plain (1-055.01)
Calwater Watershed Name: Russian River - Middle Russian River - Mark West (114.23)
Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: SONOMA COUNTY LOP (LEAD) - CASE #: 00001389
CASEWORKER: LOP CLOSED IN RB01
NORTH COAST RWQCB (REGION 1) - CASE #: 1TSO643
CASEWORKER: SONOMA COUNTY LOP CLOSED SITE
Gndwater Monitoring Freque:
Designated Beneficial Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply, Freshwater Replenishment, Native American Culture, AQUA - Note: R1 BP- all gw same uses.
Site History:

No site history available

LUST Sites from GeoTracker Search - Cleanup Status History

Status: Completed - Case Closed

Date : 10/7/1999

Status: Open - Site Assessment
Date : 5/7/1997

Status: Open - Case Begin Date
Date : 11/7/1996

LUST Sites from GeoTracker Search - Cleanup Action Report (as of May 29, 2021)

Action Type: EXCAVATION
Phase: Soil
Contaminant Mass Removed:
Description:
Begin Date: 7/28/1999
End Date:

LUST Sites from GeoTracker Search - Regulatory Activities (as of May 29, 2021)

Action Type: Cleanup Action
Action Date: 7/28/1999
Received Issue Date:
Action: Excavation
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action Date: 11/7/1996
Received Issue Date:
Action: Leak Discovery
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action Date: 1/2/1965
Received Issue Date:
Action: Leak Reported
Doc Link:
Title Description Comments:

65	1 of 1	SW	0.27 / 1,414.28	115.04 / -5	Kenwood Distribution Center 501 AVIATION BLVD SANTA ROSA CA 95403	DELISTED HAZ

Siteid: 395822
Latitude: 38.517220
Longitude: -122.792660
Original Source: CHAZ
Record Date: 14-MAR-2017

66	1 of 1	SSE	0.30 / 1,583.95	122.93 / 3	SONOMA COUNTY WATER AGENCY 404 AVIATION BLVD SANTA ROSA CA 95403	C&D DEBRIS RECY

County: SONOMA

Activity Type: MEDICATION COLLECTION
Phone No: (707) 547-1900

67	1 of 1	NW	0.34 / 1,787.42	108.08 / -12	American Tank Company, Inc. 501 AMERICAN WAY	DELISTED HAZ

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					WINDSOR CA 95492	

Siteid: 418492
Latitude: 38.529743
Longitude: -122.795090
Original Source: CHAZ
Record Date: 30-MAY-2017

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
68	1 of 1	NNE	0.37 / 1,968.36	130.84 / 11	Wine Country Autoworks 399 BUSINESS PARK CT STE 102 WINDSOR CA 95492	DELISTED HAZ

Siteid: 416422
Latitude: 38.528225
Longitude: -122.784330
Original Source: CHAZ
Record Date: 30-MAY-2017

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
69	1 of 1	NW	0.40 / 2,095.94	105.88 / -14	ENCORE EVENTS RENTALS INC 1101 AMERICAN WAY WINDSOR CA 95492	RCRA TSD

EPA Handler ID: CAL000446240
Gen Status Universe: No Report
Contact Name: JOHN BUHAGIAR
Contact Address: 20 MILL ST , , HEALDSBURG , CA, 95448 ,
Contact Phone No and Ext: 707-364-9703
Contact Email: JOHN@ENCOREEVENTSRENTALS.COM
Contact Country:
Land Type:
County Name: SONOMA
EPA Region: 09
Receive Date: 20190523
Location Latitude: 38.530123
Location Longitude: -122.798726

Violation/Evaluation Summary

Note: NO RECORDS: As of Aug 2021, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility: No
Onsite Burner Exemption: No
Smelting, Melting and Refining: No
Underground Injection Control: No
Commercial TSD: No
Used Oil Transporter: No
Used Oil Transfer Facility: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No

Hazardous Waste Handler Details

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Sequence No: 1
Receive Date: 20190523
Handler Name: ENCORE EVENTS RENTALS INC
Federal Waste Generator Code: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Other
Name: ENCORE EVENTS RENTALS INC
Date Became Current:
Date Ended Current:
Phone: 707-763-5665
Source Type: Implementer

Street No:
Street 1: 1300 PETALUMA BLVD N
Street 2:
City: PETALUMA
State: CA
Country:
Zip Code: 94592

Owner/Operator Ind: Current Operator
Type: Other
Name: JOHN BUHAGIAR
Date Became Current:
Date Ended Current:
Phone: 707-364-9703
Source Type: Implementer

Street No:
Street 1: 20 MILL ST
Street 2:
City: HEALDSBURG
State: CA
Country:
Zip Code: 95448

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
70	1 of 1	SE	0.41 / 2,144.19	129.28 / 9	Mi Burrito Mexican Restaurant & Bar 385 AVIATION BLVD STE D SANTA ROSA CA 95403	DELISTED HAZ

Siteid: 356017
Latitude: 38.512160
Longitude: -122.779880
Original Source: CHAZ
Record Date: 22-MAR-2018

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
71	1 of 1	S	0.45 / 2,364.30	120.97 / 1	Santa Rosa Army Airfield WINDSOR CA	FUDS

FUDS Property No: J09CA0026
EMS Map Link: https://fudsportal.usace.army.mil/ems/ems/inventory/map/map?id=57051
FUDS INST ID: CA99799F524400
Status:
SDS ID:
NPL Status Code: Not on the NPL
Eligibility: Eligible
Site Eligib:
Current Owner:
Has Project: Yes
DOD FUDS Pro:
Project Required: Yes
No Further Action:
Congressional District: 05
EPA Region: 09
County: SONOMA
Latitude: 38.51
Longitude: -122.81194444
Fiscal year: 2019
USACE Division: SPD
USACE District: Sacramento District (SPK)
Shape Area: .00048705
Shape Len: .1152361
Centroid Latitude:
Centroid Longitude:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Media ID:
Metadata ID:
Feature Desc:
Property History: Between 1942 and 1946, the U.S. acquired the land for the Santa Rosa Army Airfield. The Air Force used the site as a pre-combat training facility. On 15 December 1943, 1.38 acres leased from the Northwestern Pacific Railroad Company were terminated. By d

---

72 | **1 of 2** | **SSE** | **0.46 / 2,410.35** | **123.89 / 4** | **Soiland Co., Inc.**
1210 Airport Blvd
Santa Rosa CA | **LOP SONOMA**

LOP No: 00001821
RB No: 1TSO305
Status: Y
Status Desc: Closed Site
Date: 3/6/1998
Global ID: T0609700225
APN: 059-240-054
Staff:
Staff Name:

---

72 | **2 of 2** | **SSE** | **0.46 / 2,410.35** | **123.89 / 4** | **SOILAND CO., INC.**
1210 AIRPORT BLVD
SANTA ROSA CA 95401 | **LUST**

Global ID: T0609700225
Status: COMPLETED - CASE CLOSED
Status Date: 3/6/1998
Case Type: LUST CLEANUP SITE
Date Source: LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download
County: SONOMA
Latitude: 38.510168
Longitude: -122.785239

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail

RB Case No: 1TSO305
Local Case No: 00001821
Begin Date: 8/25/1989
Lead Agency: SONOMA COUNTY LOP
Local Agency: SONOMA COUNTY LOP
CUF Case: NO
Potential COC: Gasoline
How Discovered:
Stop Method:
Stop Description:
Case Worker: LCW
File Location: All Files are on GeoTracker or in the Local Agency Database

Potential Media of Concern: Soil
How Discovered Description:
Calwater Watershed Name: Russian River - Middle Russian River - Mark West (114.23)
DWR GW Subbasin Name: Santa Rosa Valley - Santa Rosa Plain (1-055.01)
Disadvantaged Community:
Calenviroscreen Score: 66-70%
Site History:

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity

Action Type: REMEDIATION
Date : 8/9/1993
Action: Excavation

Action Type: Other
Date : 8/25/1989
Action: Leak Discovery

Action Type: Other
Date : 1/2/1965
Action: Leak Reported

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts

Contact Type:	Local Agency Caseworker	**Address:**	625 FIFTH STREET
Contact Name:	LOP CLOSED IN RB01	**Email:**	
City:	SANTA ROSA	**Phone No:**	
Organization Name:	SONOMA COUNTY LOP		

Contact Type:	Regional Board Caseworker	**Address:**	5550 SKYLANE BOULEVARD, SUITE A
Contact Name:	SONOMA COUNTY LOP CLOSED SITE	**Email:**	
City:	SANTA ROSA	**Phone No:**	7075656565
Organization Name:	NORTH COAST RWQCB (REGION 1)		

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History

Status:	Completed - Case Closed
Status Date:	3/6/1998
Status:	Open - Site Assessment
Status Date:	12/4/1989
Status:	Open - Case Begin Date
Status Date:	8/25/1989

LUST Sites from GeoTracker Search - Regulatory Profile

Site Facility Name:	SOILAND CO., INC.	**Potential COC:**	GASOLINE
Site Facility Type:	LUST CLEANUP SITE	**Facility Type:**	
Cleanup Status:	COMPLETED - CASE CLOSED	**Composting Method:**	
Project Status:		**Address:**	1210 AIRPORT BLVD
WDR Place Type:		**City:**	SANTA ROSA
WDR File:		**Zip:**	95401
WDR Order:		**County:**	SONOMA
CUF Priority Assig:		**CUF Claim:**	
CUF Amount Paid:			

File Location:	ALL FILES ARE ON GEOTRACKER OR IN THE LOCAL AGENCY DATABASE
Designated Beneficial Use:	MUN, AGR, IND, PROC, FRSH, CUL, AQUA - Note: R1 BP- all gw same uses.
Project Oversight Agencies:	
Report Link:	https://geotracker.waterboards.ca.gov/profile_report?global_id=T0609700225
Cleanup Status Detail:	COMPLETED - CASE CLOSED AS OF 3/6/1998
Cleanup History Link:	https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0609700225&tabname=regulatoryhistory
Potential Media of Concern:	SOIL
User Defined Beneficial Use:	
DWR GW Sub Basin:	Santa Rosa Valley - Santa Rosa Plain (1-055.01)
Calwater Watershed Name:	Russian River - Middle Russian River - Mark West (114.23)
Post Closure Site Management:	
Future Land Use:	
Cleanup Oversight Agencies:	SONOMA COUNTY LOP (LEAD) - CASE #: 00001821 CASEWORKER: LOP CLOSED IN RB01 NORTH COAST RWQCB (REGION 1) - CASE #: 1TSO305 CASEWORKER: SONOMA COUNTY LOP CLOSED SITE
Gndwater Monitoring Freque:	
Designated Beneficial Use Desc:	Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply, Freshwater Replenishment, Native American Culture, AQUA - Note: R1 BP- all gw same uses.
Site History:	

No site history available

LUST Sites from GeoTracker Search - Cleanup Status History

Status:	Completed - Case Closed
Date :	3/6/1998
Status:	Open - Site Assessment
Date :	12/4/1989
Status:	Open - Case Begin Date
Date :	8/25/1989

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

LUST Sites from GeoTracker Search - Cleanup Action Report (as of May 29, 2021)

Action Type: EXCAVATION
Begin Date: 8/9/1993
Phase: Soil
End Date:
Contaminant Mass Removed:
Description:

LUST Sites from GeoTracker Search - Regulatory Activities (as of May 29, 2021)

Action Type: Cleanup Action
Action Date: 8/9/1993
Received Issue Date:
Action: Excavation
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action Date: 8/25/1989
Received Issue Date:
Action: Leak Discovery
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action Date: 1/2/1965
Received Issue Date:
Action: Leak Reported
Doc Link:
Title Description Comments:

73	1 of 1	SSE	0.46 / 2,415.71	127.44 / 7	ROUND-TO-IT TIRE RECYCLERS 1070 AIRPORT BOULEVARD SANTA ROSA CA 95403	CLEANUP SITES

Global ID: T0609793283
Latitude: 38.50943
Status: COMPLETED - CASE CLOSED
Longitude: -122.782355
Status Date: 2/10/1998
County: SONOMA
Site Facility Type: CLEANUP PROGRAM SITE
Data Source: Cleanup Program Sites from GeoTracker Search; Cleanup Sites from GeoTracker Cleanup Sites Data Download

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail

RB Case No: 1NSO533
Stop Method:
Local Case No:
CUF Case: NO
Begin Date: 9/27/1992
Case Worker: ZZZ
File Location: Regional Board
Lead Agency: NORTH COAST RWQCB (REGION 1)
Local Agency: SONOMA COUNTY
Potential COC: Diesel
Potential Media of Concern: Soil
How Discovered: Other Means
How Discovered Description:
Stop Description:
CalWater Watershed Name: Russian River - Middle Russian River - Mark West (114.23)
DWR GW Subbasin Name: Santa Rosa Valley - Santa Rosa Plain (1-055.01)
Disadvantaged Community:
CalEnviroScreen Score: 66-70%
Site History:

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity

Action Type: ENFORCEMENT
Date: 1992-11-03 00:00:00
Action: * Historical Enforcement

Action Type: Other
Date: 1992-09-27 00:00:00
Action: Leak Discovery

Action Type: Other
Date: 1992-09-27 00:00:00
Action: Leak Reported

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History

Status: Open - Remediation
Status Date: 1998-02-10 00:00:00

Status: Completed - Case Closed
Status Date: 1998-02-10 00:00:00

Status: Open - Verification Monitoring
Status Date: 1998-02-10 00:00:00

Status: Open - Site Assessment
Status Date: 1998-02-10 00:00:00

Status: Open - Site Assessment
Status Date: 1992-11-02 00:00:00

Status: Open - Case Begin Date
Status Date: 1992-09-27 00:00:00

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts

Contact Type: Local Agency Caseworker
Contact Name: ENVIRON HEALTH STAFF (NON LOP-RB1)
Phone No:
Organization Name: SONOMA COUNTY
Email:
Address: 625 5th Street
City: SANTA ROSA

Contact Type: Regional Board Caseworker
Contact Name: REGIONAL WATER BOARD SITE CLOSED
Phone No: 7075762220
Organization Name: NORTH COAST RWQCB (REGION 1)
Email:
Address: 5550 SKYLANE BOULEVARD, SUITE A
City: SANTA ROSA

Cleanup Program Sites from GeoTracker Search - Regulatory Profile (as of May 29, 2021)

Project Status:
Cuf Claim No:
CUF Priority Assign:
CUF Amount Paid:
Composting Method:
File Location: REGIONAL BOARD
User Defined Beneficial Use:
Designated Beneficial Use: MUN, AGR, IND, PROC, FRSH, CUL, AQUA - Note: R1 BP- all gw same uses.
Designated Beneficl Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply, Freshwater Replenishment, Native American Culture, AQUA - Note: R1 BP- all gw same uses.
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T0609793283
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 2/10/1998
Potential COC: DIESEL
Potential Media of Concern: SOIL
Facility Type:
WDR Place Type:
Wdr File No:
Wdr Order No:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Groundwater Monitoring Frequen:
DWR GW Sub Basin: Santa Rosa Valley - Santa Rosa Plain (1-055.01)
CalWater Watershed Name: Russian River - Middle Russian River - Mark West (114.23)
Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: NORTH COAST RWQCB (REGION 1) (LEAD) - CASE #: 1NSO533
CASEWORKER: REGIONAL WATER BOARD SITE CLOSED
SONOMA COUNTY LOP
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0609793283&tabname=regulatoryhistory
Site History:

No site history available

Sites from GeoTracker Search - Regulatory Activities (as of May 29, 2021)

Action Type: Enforcement/Orders
Action Date: 11/3/1992
Received Issue Date: 11/3/1992
Action: * Historical Enforcement
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action Date: 9/27/1992
Received Issue Date:
Action: Leak Reported
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action Date: 9/27/1992
Received Issue Date:
Action: Leak Discovery
Doc Link:
Title Description Comments:

Sites from GeoTracker Search - Cleanup Status History (as of May 29, 2021)

Status: Completed - Case Closed
Date: 2/10/1998

Status: Open - Verification Monitoring
Date: 2/10/1998

Status: Open - Site Assessment
Date: 2/10/1998

Status: Open - Remediation
Date: 2/10/1998

Status: Open - Site Assessment
Date: 11/2/1992

Status: Open - Case Begin Date
Date: 9/27/1992

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
74	1 of 1	SSE	0.46 / 2,419.05	127.69 / 8	slaight heavy haul yard 1060 AIRPORT BLVD SANTA ROSA CA 95403	DELISTED HAZ

Siteid: 357065
Latitude: 38.511093

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Longitude: -122.782199
Original Source: CHAZ
Record Date: 22-MAR-2018

---

75 | **1 of 1** | **SSE** | **0.46 / 2,427.01** | **128.49 / 8** | **Round-TO-It Illegal Waste Tire TS**
1050 Airport Blvd
Santa Rosa CA 99999
SWF/LF

SWIS No: 49-CR-0004
EPA Fed Registry ID:
Operational Status: To be Determined
Regulatory Status: Unpermitted
Site is Archived: Yes
Absorbed on:
Absorbed by:
Site Inert Debris Eng Fill: No
Closed Illegal Aband: No
Closed Illegal Aband Cat:
Finance Assuran Responsible: No
Incorporated City: Santa Rosa
Local Government: Santa Rosa
Reporting Agency Legal Name: County of Sonoma
Reporting Agency Department: Department of Health Services, Environmental Health & Safety Section
Enforcing Agency Legal Name: County of Sonoma
Enforcing Agency Department: Department of Health Services, Environmental Health & Safety Section

Latitude: 38.43333
Longitude: -122.71667
County: Sonoma
Site ZIP: 99999
ARB District: Bay Area
SWRCB Region: North Coast
Site Point of Contact: Dawn Liang

Site Owners

Site Type: Disposal Only
Owner Name: Laier K
Owner Address: 175 Airport Blvd
Owner City: Santa Rosa
Owner State: CA
Owner ZIP Code: 95403
Owner Phone:

Contact Name: Kantock Laier
Contact First Name: Kantock
Contact Last Name: Laier
Contact Title:
Contact Email:
Started On:

---

76 | **1 of 1** | **SSW** | **0.47 / 2,483.16** | **119.15 / -1** | **SANTA ROSA STAINLESS STEEL**
1400 AIRPORT BOULEVARD
SANTA ROSA CA 95403
CLEANUP SITES

Global ID: SL0609759886
Status: COMPLETED - CASE CLOSED
Status Date: 6/7/2013
Site Facility Type: CLEANUP PROGRAM SITE
Data Source: Cleanup Program Sites from GeoTracker Search; Cleanup Sites from GeoTracker Cleanup Sites Data Download

Latitude: 38.51083320565
Longitude: -122.790112495422
County: SONOMA

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail

RB Case No: 1NSO868
Local Case No:
Begin Date: 11/10/2003
File Location: Regional Board
Lead Agency: NORTH COAST RWQCB (REGION 1)
Local Agency: SONOMA COUNTY
Potential COC: * Acids/Corrosives, * Chlorinated Solvents - TCE
Potential Media of Concern: Well used for drinking water supply
How Discovered:
How Discovered Description:
Stop Description:
CalWater Watershed Name: Russian River - Middle Russian River - Mark West (114.23)
DWR GW Subbasin Name: Santa Rosa Valley - Santa Rosa Plain (1-055.01)
Disadvantaged Community:
CalEnviroScreen Score: 66-70%
Site History:

Stop Method:
CUF Case: NO
Case Worker: ZZZ

In response to an anonymous complaint groundwater from the on-site domestic well was sampled. Trichloroethene (TCE) as well as several breakdown products of TCE were detected in the water sample. Specifically 1,1-Dichloroethane, 1,1-Dichloroethene and Vinyl Chloride all were detected at concentrations above the California Department of Health Services Maximum Contaminant Level (MCL). These chemicals have also been detected in the domestic well to the south of your property at 3660 Copperhill Lane (formerly 1514 Airport Blvd) and in monitoring wells located adjacent to your property at 3650 Brickway Blvd (formerly 1588 Airport Blvd). Numerous soil and groundwater samples were collected at various depths from the property. Results showed that site activities were not the source of the VOCs in the groundwater and that the extent of VOCs detected in the groundwater from the domestic well is limited. Concentrations of VOCs in the groundwater collected from the domestic well have declined over time due to natural attenuation and will not pose a threat to human health or the environment over the projected time frame required to meet water quality objectives. Groundwater is no longer used as a source of water supply at this property. The case was closed with no further remediation required after the domestic well was destroyed.

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity

Action Type: ENFORCEMENT
Date: 2013-06-07 00:00:00
Action: Closure/No Further Action Letter

Action Type: RESPONSE
Date: 2013-05-30 00:00:00
Action: Well Destruction Report - Regulator Responded

Action Type: ENFORCEMENT
Date: 2013-04-17 00:00:00
Action: Staff Letter

Action Type: RESPONSE
Date: 2013-04-13 00:00:00
Action: Well Destruction Workplan - Regulator Responded

Action Type: RESPONSE
Date: 2013-03-26 00:00:00
Action: Fact Sheets - Public Participation

Action Type: ENFORCEMENT
Date: 2013-03-13 00:00:00
Action: Notification - Public Notice of Case Closure

Action Type: ENFORCEMENT
Date: 2013-03-13 00:00:00
Action: Staff Letter

Action Type: ENFORCEMENT
Date: 2013-03-12 00:00:00
Action: File Review - Closure

Action Type: RESPONSE
Date: 2013-01-15 00:00:00
Action: Monitoring Report - Annually - Regulator Responded

Action Type: ENFORCEMENT
Date: 2012-11-05 00:00:00
Action: Staff Letter

Action Type: RESPONSE
Date: 2012-10-22 00:00:00
Action: Other Workplan - Regulator Responded

Action Type: ENFORCEMENT
Date: 2012-08-21 00:00:00
Action: Staff Letter

Action Type: ENFORCEMENT
Date: 2012-08-15 00:00:00
Action: Staff Letter

Action Type: ENFORCEMENT

Date: 2012-06-19 00:00:00
Action: Staff Letter

Action Type: ENFORCEMENT
Date: 2012-06-09 00:00:00
Action: Staff Letter

Action Type: RESPONSE
Date: 2012-02-15 00:00:00
Action: Miscellaneous Decision Documents

Action Type: RESPONSE
Date: 2012-01-15 00:00:00
Action: Monitoring Report - Annually

Action Type: ENFORCEMENT
Date: 2011-04-18 00:00:00
Action: Staff Letter

Action Type: ENFORCEMENT
Date: 2011-03-11 00:00:00
Action: Meeting

Action Type: RESPONSE
Date: 2010-08-17 00:00:00
Action: Site Investigation

Action Type: ENFORCEMENT
Date: 2010-07-06 00:00:00
Action: Site Visit / Inspection / Sampling

Action Type: ENFORCEMENT
Date: 2009-09-10 00:00:00
Action: Staff Letter

Action Type: RESPONSE
Date: 2009-08-28 00:00:00
Action: Soil and Water Investigation Workplan

Action Type: ENFORCEMENT
Date: 2009-06-15 00:00:00
Action: Staff Letter

Action Type: ENFORCEMENT
Date: 2009-06-09 00:00:00
Action: Warning Letter

Action Type: ENFORCEMENT
Date: 2005-07-11 00:00:00
Action: Notice of Reimbursement

Action Type: ENFORCEMENT
Date: 2005-07-11 00:00:00
Action: Staff Letter

Action Type: RESPONSE
Date: 2005-03-01 00:00:00
Action: Other Report / Document

Action Type: ENFORCEMENT
Date: 2004-11-09 00:00:00
Action: * No Action

Action Type: RESPONSE
Date: 2004-10-20 00:00:00
Action: Preliminary Site Assessment Workplan

Action Type: ENFORCEMENT
Date: 2004-07-20 00:00:00

Action: Notice of Responsibility

Action Type: ENFORCEMENT
Date: 2003-12-12 00:00:00
Action: Staff Letter

Action Type: Other
Date: 2003-11-10 00:00:00
Action: Leak Reported

Action Type: Other
Date: 2003-11-10 00:00:00
Action: Leak Discovery

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History

Status: Completed - Case Closed
Status Date: 2013-06-07 00:00:00

Status: Open - Site Assessment
Status Date: 2004-11-09 00:00:00

Status: Open - Site Assessment
Status Date: 2004-10-21 00:00:00

Status: Open - Site Assessment
Status Date: 2004-07-15 00:00:00

Status: Open - Case Begin Date
Status Date: 2003-11-10 00:00:00

Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts

Contact Type: Regional Board Caseworker
Contact Name: REGIONAL WATER BOARD SITE CLOSED
Phone No: 7075762220
Organization Name: NORTH COAST RWQCB (REGION 1)
Email:
Address: 5550 SKYLANE BOULEVARD, SUITE A
City: SANTA ROSA

Contact Type: Local Agency Caseworker
Contact Name: ENVIRON HEALTH STAFF (NON LOP-RB1)
Phone No:
Organization Name: SONOMA COUNTY
Email:
Address: 625 5th Street
City: SANTA ROSA

Cleanup Program Sites from GeoTracker Search - Regulatory Profile (as of May 29, 2021)

Project Status:
Cuf Claim No:
CUF Priority Assign:
CUF Amount Paid:
Composting Method:
File Location: REGIONAL BOARD
User Defined Beneficial Use:
Designated Beneficial Use: MUN, AGR, IND, PROC, FRSH, CUL, AQUA - Note: R1 BP- all gw same uses.
Designated Beneficl Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply, Freshwater Replenishment, Native American Culture, AQUA - Note: R1 BP- all gw same uses.
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=SL0609759886
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 6/7/2013
Potential COC: ACIDS/CORROSIVES, CHLORINATED SOLVENTS - TCE
Potential Media of Concern: WELL USED FOR DRINKING WATER SUPPLY
Groundwater Monitoring Frequen:
DWR GW Sub Basin: Santa Rosa Valley - Santa Rosa Plain (1-055.01)
CalWater Watershed Name: Russian River - Middle Russian River - Mark West (114.23)
Facility Type:
WDR Place Type:
Wdr File No:
Wdr Order No:

Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: NORTH COAST RWQCB (REGION 1) (LEAD) - CASE #: 1NSO868
CASEWORKER: REGIONAL WATER BOARD SITE CLOSED
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=SL0609759886&tabname=regulatoryhistory
Site History:

In response to an anonymous complaint groundwater from the on-site domestic well was sampled. Trichloroethene (TCE) as well as several breakdown products of TCE were detected in the water sample. Specifically 1,1-Dichloroethane, 1,1-Dichloroethene and Vinyl Chloride all were detected at concentrations above the California Department of Health Services Maximum Contaminant Level (MCL). These chemicals have also been detected in the domestic well to the south of your property at 3660 Copperhill Lane (formerly 1514 Airport Blvd) and in monitoring wells located adjacent to your property at 3650 Brickway Blvd (formerly 1588 Airport Blvd).
Numerous soil and groundwater samples were collected at various depths from the property. Results showed that site activities were not the source of the VOCs in the groundwater and that the extent of VOCs detected in the groundwater from the domestic well is limited. Concentrations of VOCs in the groundwater collected from the domestic well have declined over time due to natural attenuation and will not pose a threat to human health or the environment over the projected time frame required to meet water quality objectives. Groundwater is no longer used as a source of water supply at this property. The case was closed with no further remediation required after the domestic well was destroyed.

Sites from GeoTracker Search - Regulatory Activities (as of May 29, 2021)

Action Type: Other Regulatory Actions
Action Date: 6/7/2013
Received Issue Date: 6/7/2013
Action: Closure/No Further Action Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0609759886&enforcement_id=6161865&temptable=ENFORCEMENT
Title Description Comments:

Santa Rosa Stainless Steel NFA

Action Type: Response Requested - Reports
Action Date: 5/30/2013
Received Issue Date: 5/30/2013
Action: Well Destruction Report - Regulator Responded
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0609759886&doc_id=5772682
Title Description Comments:

Domestic Well Decommissioning Notification

Action Type: Other Regulatory Actions
Action Date: 4/17/2013
Received Issue Date: 4/17/2013
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0609759886&enforcement_id=6157890&temptable=ENFORCEMENT
Title Description Comments:

Domestic Well Decommissioning

Action Type: Response Requested - Workplans
Action Date: 4/13/2013
Received Issue Date: 3/25/2013
Action: Well Destruction Workplan - Regulator Responded
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0609759886&doc_id=5766503
Title Description Comments:

Domestic Well Decommissioning

Action Type: Response Requested - Other
Action Date: 3/26/2013
Received Issue Date: 3/26/2013
Action: Fact Sheets - Public Participation
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0609759886&doc_id=5766420

Title Description Comments:

Documentation of Public Noticing

Action Type: Notices
Action Date: 3/13/2013
Received Issue Date: 3/13/2013
Action: Notification - Public Notice of Case Closure
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0609759886&enforcement_id=6154391&temptable=ENFORCEMENT
Title Description Comments:

Public Notice for No Further Action Required

Action Type: Other Regulatory Actions
Action Date: 3/13/2013
Received Issue Date: 3/13/2013
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0609759886&enforcement_id=6154435&temptable=ENFORCEMENT
Title Description Comments:

Public Notice for No Further Action Required

Action Type: Other Regulatory Actions
Action Date: 3/12/2013
Received Issue Date: 3/12/2013
Action: File Review - Closure
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0609759886&enforcement_id=6154389&temptable=ENFORCEMENT
Title Description Comments:

Site Conceptual Model and No Further Action Recommendation

Action Type: Response Requested - Reports
Action Date: 1/15/2013
Received Issue Date: 1/30/2013
Action: Monitoring Report - Annually - Regulator Responded
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0609759886&doc_id=5766415
Title Description Comments:

Results of December 2012 Groundwater Sampling and Request for Case Closure

Action Type: Other Regulatory Actions
Action Date: 11/5/2012
Received Issue Date: 11/5/2012
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0609759886&enforcement_id=6154387&temptable=ENFORCEMENT
Title Description Comments:

Concurrence with Workplan for Additional Groundwater Sampling

Action Type: Response Requested - Workplans
Action Date: 10/22/2012
Received Issue Date: 10/22/2012
Action: Other Workplan - Regulator Responded
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0609759886&doc_id=5757879
Title Description Comments:

Workplan for Additional Groundwater Sampling

Action Type: Other Regulatory Actions
Action Date: 8/21/2012

Received Issue Date: 8/21/2012
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0609759886&enforcement_id=6136054&temptable=ENFORCEMENT
Title Description Comments:

Request for Groundwater Analysis for 1,4-Dioxane

Action Type: Other Regulatory Actions
Action Date: 8/15/2012
Received Issue Date: 8/15/2012
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0609759886&enforcement_id=6136053&temptable=ENFORCEMENT
Title Description Comments:

Non Concurrence with No Further Action

Action Type: Other Regulatory Actions
Action Date: 6/19/2012
Received Issue Date: 6/19/2012
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0609759886&enforcement_id=6129509&temptable=ENFORCEMENT
Title Description Comments:

Annual Cost Recovery Estimation Letter

Action Type: Other Regulatory Actions
Action Date: 6/9/2012
Received Issue Date: 6/9/2012
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0609759886&enforcement_id=6129506&temptable=ENFORCEMENT
Title Description Comments:

Annual Cost Recovery Estimation Letter

Action Type: Response Requested - Reports
Action Date: 2/15/2012
Received Issue Date: 2/15/2012
Action: Miscellaneous Decision Documents
Doc Link:
Title Description Comments:

Evaluation of Degradation Trends and Request for Case Closure

Action Type: Response Requested - Reports
Action Date: 1/15/2012
Received Issue Date: 1/31/2012
Action: Monitoring Report - Annually
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0609759886&doc_id=5741976
Title Description Comments:

Supplemental Monitoring Results and Request for Case Closure

Action Type: Other Regulatory Actions
Action Date: 4/18/2011
Received Issue Date: 4/18/2011
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0609759886&enforcement_id=6129505&temptable=ENFORCEMENT
Title Description Comments:

Supplemental Monitoring

Action Type: Other Regulatory Actions
Action Date: 3/11/2011
Received Issue Date: 3/11/2011
Action: Meeting
Doc Link:
Title Description Comments:

Meeting to Discuss No Further Action Recomendation

Action Type: Response Requested - Reports
Action Date: 8/17/2010
Received Issue Date: 8/17/2010
Action: Site Investigation
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0609759886&doc_id=5696425
Title Description Comments:

Additional Investigation Results

Action Type: Other Regulatory Actions
Action Date: 7/6/2010
Received Issue Date: 7/6/2010
Action: Site Visit / Inspection / Sampling
Doc Link:
Title Description Comments:

Observed drilling of GW-5

Action Type: Other Regulatory Actions
Action Date: 9/10/2009
Received Issue Date: 9/10/2009
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0609759886&enforcement_id=6029820&temptable=ENFORCEMENT
Title Description Comments:

Additional Investigation Workplan

Action Type: Response Requested - Workplans
Action Date: *8/28/2009
Received Issue Date: 9/2/2009
Action: Soil and Water Investigation Workplan
Doc Link: https://geotracker.waterboards.ca.gov/view_documents_all?global_id=SL0609759886&doc_id=5650536
Title Description Comments:

Additional Investigation Workplan

Action Type: Other Regulatory Actions
Action Date: 6/15/2009
Received Issue Date: 6/15/2009
Action: Staff Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0609759886&enforcement_id=6028756&temptable=ENFORCEMENT
Title Description Comments:

ANNUAL ESTIMATION LETTER

Action Type: Enforcement/Orders
Action Date: 6/9/2009
Received Issue Date: 6/9/2009
Action: Warning Letter
Doc Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0609759886&enforcement_id=6028747&temptable=ENFORCEMENT
Title Description Comments:

Second Request for Workplan

Action Type: Notices
Action Date: 7/11/2005
Received Issue Date: 7/11/2005
Action: Notice of Reimbursement
Doc Link:
Title Description Comments:

Action Type: Other Regulatory Actions
Action Date: 7/11/2005
Received Issue Date: 7/11/2005
Action: Staff Letter
Doc Link:
Title Description Comments:

Action Type: Response Requested - Other
Action Date: 3/1/2005
Received Issue Date: 3/26/2005
Action: Other Report / Document
Doc Link:
Title Description Comments:

Action Type: Enforcement - Other
Action Date: 11/9/2004
Received Issue Date: 11/9/2004
Action: * No Action
Doc Link:
Title Description Comments:

Action Type: Response Requested - Workplans
Action Date: 10/20/2004
Received Issue Date: 10/21/2004
Action: Preliminary Site Assessment Workplan
Doc Link:
Title Description Comments:

Preliminary Site Assessment Workplan - Workplan Site Investigation

Action Type: Notices
Action Date: 7/20/2004
Received Issue Date: 7/20/2004
Action: Notice of Responsibility
Doc Link:
Title Description Comments:

Action Type: Other Regulatory Actions
Action Date: 12/12/2003
Received Issue Date: 12/12/2003
Action: Staff Letter
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action Date: 11/10/2003
Received Issue Date:
Action: Leak Reported
Doc Link:
Title Description Comments:

Action Type: Leak Action

Action Date: 11/10/2003
Received Issue Date:
Action: Leak Discovery
Doc Link:
Title Description Comments:

Sites from GeoTracker Search - Documents (as of May 29, 2021)

Document Type: Site Documents ***Submitted:***
Document Date: 6/7/2013 ***Submitted By:*** BETH LAMB (REGULATOR)
Size :
Title: SANTA ROSA STAINLESS STEEL NFA
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0609759886&enforcement_id=6161865
Type: CLOSURE/NO FURTHER ACTION LETTER

Document Type: Site Documents ***Submitted:***
Document Date: 5/30/2013 ***Submitted By:*** BETH LAMB (REGULATOR)
Size :
Title: DOMESTIC WELL DECOMMISSIONING NOTIFICATION - REGULATOR RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0609759886&document_id=5772682
Type: WELL DESTRUCTION REPORT

Document Type: Site Documents ***Submitted:***
Document Date: 5/29/2013 ***Submitted By:*** PES ENVIRONMENTAL (AUTH_RP)
Size : 885 KB
Title: DOMESTIC WELL DECOMISSIONING NOTIFICATION
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/9644829928/SL0609759886.PDF
Type: WELL DESTRUCTION REPORT

Document Type: Site Documents ***Submitted:***
Document Date: 4/17/2013 ***Submitted By:*** BETH LAMB (REGULATOR)
Size :
Title: DOMESTIC WELL DECOMMISSIONING
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0609759886&enforcement_id=6157890
Type: STAFF LETTER

Document Type: Site Documents ***Submitted:***
Document Date: 3/26/2013 ***Submitted By:*** BETH LAMB (REGULATOR)
Size :
Title: DOCUMENTATION OF PUBLIC NOTICING
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0609759886&document_id=5766420
Type: FACT SHEETS - PUBLIC PARTICIPATION

Document Type: Site Documents ***Submitted:***
Document Date: 3/25/2013 ***Submitted By:*** BETH LAMB (REGULATOR)
Size :
Title: DOMESTIC WELL DECOMMISSIONING - REGULATOR RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0609759886&document_id=5766503
Type: WELL DESTRUCTION WORKPLAN

Document Type: Site Documents ***Submitted:***
Document Date: 3/22/2013 ***Submitted By:*** PES ENVIRONMENTAL (AUTH_RP)
Size : 428 KB
Title: DOMESTIC WELL DECOMMISSIONING
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8482560634/SL0609759886.PDF
Type: WELL DESTRUCTION WORKPLAN

Document Type: Site Documents ***Submitted:***
Document Date: 3/13/2013 ***Submitted By:*** BETH LAMB (REGULATOR)
Size :
Title: PUBLIC NOTICE FOR NO FURTHER ACTION REQUIRED
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0609759886&enforcement_id=6154391
Type: NOTIFICATION - PUBLIC NOTICE OF CASE CLOSURE

Document Type: Site Documents ***Submitted:***
Document Date: 3/13/2013 ***Submitted By:*** BETH LAMB (REGULATOR)
Size :

Title: PUBLIC NOTICE FOR NO FURTHER ACTION REQUIRED
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0609759886&enforcement_id=6154435
Type: STAFF LETTER

Document Type: Site Documents **Submitted:**
Document Date: 3/12/2013 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: SITE CONCEPTUAL MODEL AND NO FURTHER ACTION RECOMMENDATION
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0609759886&enforcement_id=6154389
Type: FILE REVIEW - CLOSURE

Document Type: Monitoring Reports **Submitted:**
Document Date: 1/30/2013 **Submitted By:** BETH LAMB (REGULATOR)
Size : 117 KB
Title: RESULTS OF DECEMBER 2012 GROUNDWATER SAMPLING AND REQUEST FOR CASE CLOSURE - PUBLIC NOTICE FOR NO FURTHER ACTION REQUIRED - REGULATOR RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/8068237125/130313%5FBML%5Fdp%5FSRSS%5FNFA%5FPN%5FcovLTR%2Epdf
Type: MONITORING REPORT - ANNUALLY

Document Type: Monitoring Reports **Submitted:**
Document Date: 1/30/2013 **Submitted By:** BETH LAMB (REGULATOR)
Size : 70 KB
Title: RESULTS OF DECEMBER 2012 GROUNDWATER SAMPLING AND REQUEST FOR CASE CLOSURE - PUBLIC NOTICE FOR NO FURTHER ACTION REQUIRED - REGULATOR RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/regulators/deliverable_documents/8068237125/130313%5FBML%5Fdp%5FSRSS%5FPN%2Epdf
Type: MONITORING REPORT - ANNUALLY

Document Type: Site Documents **Submitted:**
Document Date: 1/28/2013 **Submitted By:** PES ENVIRONMENTAL (AUTH_RP)
Size : 1,646 KB
Title: RESULTS OF DECEMBER 2012 GROUNDWATER SAMPLING AND REQUEST FOR CASE CLOSURE
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1567626237/SL0609759886.PDF
Type: REQUEST FOR CLOSURE

Document Type: Site Documents **Submitted:**
Document Date: 11/5/2012 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: CONCURRENCE WITH WORKPLAN FOR ADDITIONAL GROUNDWATER SAMPLING
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0609759886&enforcement_id=6154387
Type: STAFF LETTER

Document Type: Site Documents **Submitted:**
Document Date: 10/22/2012 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: WORKPLAN FOR ADDITIONAL GROUNDWATER SAMPLING - REGULATOR RESPONSE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0609759886&document_id=5757879
Type: OTHER WORKPLAN

Document Type: Site Documents **Submitted:**
Document Date: 10/17/2012 **Submitted By:** PES ENVIRONMENTAL (AUTH_RP)
Size : 88 KB
Title: WORKPLAN FOR ADDITIONAL GROUNDWATER SAMPLING
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/5282515764/SL0609759886.PDF
Type: SOIL AND WATER INVESTIGATION WORKPLAN

Document Type: Site Documents **Submitted:**
Document Date: 8/21/2012 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: REQUEST FOR GROUNDWATER ANALYSIS FOR 1,4-DIOXANE
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0609759886&enforcement_id=6136054
Type: STAFF LETTER

Document Type: Site Documents **Submitted:**
Document Date: 8/15/2012 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: NON CONCURRENCE WITH NO FURTHER ACTION
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0609759886&enforcement_id=6136053

Type: STAFF LETTER

Document Type: Site Documents **Submitted:**
Document Date: 6/19/2012 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: ANNUAL COST RECOVERY ESTIMATION LETTER
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0609759886&enforcement_id=6129509
Type: STAFF LETTER

Document Type: Site Documents **Submitted:**
Document Date: 6/9/2012 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: ANNUAL COST RECOVERY ESTIMATION LETTER
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0609759886&enforcement_id=6129506
Type: STAFF LETTER

Document Type: Monitoring Reports **Submitted:**
Document Date: 12/22/2011 **Submitted By:** PES ENVIRONMENTAL (AUTH_RP)
Size : 210 KB
Title: EVALUATION OF DEGREDATION TRENDS AND REQUEST FOR CASE CLOSUE
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3473786354/SL0609759886.PDF
Type: MONITORING REPORT - OTHER

Document Type: Monitoring Reports **Submitted:**
Document Date: 11/15/2011 **Submitted By:** PES ENVIRONMENTAL (AUTH_RP)
Size : 618 KB
Title: SUPPLEMENTAL MONITORING RESULTS AND REQUEST FOR CASE CLOSURE
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/8888257622/SL0609759886.PDF
Type: MONITORING REPORT - OTHER

Document Type: Site Documents **Submitted:**
Document Date: 4/18/2011 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: SUPPLEMENTAL MONITORING
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0609759886&enforcement_id=6129505
Type: STAFF LETTER

Document Type: Site Documents **Submitted:**
Document Date: 4/4/2011* **Submitted By:** PES ENVIRONMENTAL (AUTH_RP)
Size : 55 KB
Title: WORKPLAN SUPPLEMENTAL MONITORING
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/4754862487/SL0609759886.PDF
Type: SITE INVESTIGATION WORKPLAN

Document Type: Site Documents **Submitted:**
Document Date: 8/17/2010 **Submitted By:** PES ENVIRONMENTAL (AUTH_RP)
Size : 1,791 KB
Title: MEMO - ADDITIONAL INVESTIGATION RESULTS
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/3840729713/SL0609759886.PDF
Type: SITE INVESTIGATION

Document Type: Site Documents **Submitted:**
Document Date: 9/10/2009 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: ADDITIONAL INVESTIGATION WORKPLAN
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0609759886&enforcement_id=6029820
Type: STAFF LETTER

Document Type: Site Documents **Submitted:**
Document Date: 8/28/2009* **Submitted By:** PES ENVIRONMENTAL (AUTH_RP)
Size : 962 KB
Title: ADDITIONAL INVESTIGATION WORKPLAN
Title Link: https://geotracker.waterboards.ca.gov/esi/uploads/geo_report/1811123073/SL0609759886.PDF
Type: OTHER WORKPLAN

Document Type: Site Documents **Submitted:**
Document Date: 6/15/2009 **Submitted By:** BETH LAMB (REGULATOR)
Size :
Title: ANNUAL ESTIMATION LETTER

Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0609759886&enforcement_id=6028756
Type: STAFF LETTER

Document Type: Site Documents
Document Date: 6/9/2009
Size :
Submitted:
Submitted By: BETH LAMB (REGULATOR)
Title: SECOND REQUEST FOR WORKPLAN
Title Link: https://geotracker.waterboards.ca.gov/view_documents?global_id=SL0609759886&enforcement_id=6028747
Type: WARNING LETTER

Document Type: Site Documents
Document Date: 6/13/2008
Size : 24 KB
Submitted:
Submitted By: (REGULATOR)
Title: 2008 ANNUAL ESTIMATION LETTER
Title Link: https://geotracker.waterboards.ca.gov/site_documents/4154102921/060408%5FBML%5FSRSS%5F2010046%5FACR%2Epdf
Type: LETTER

Document Type: Site Documents
Document Date: 12/17/2007
Size : 23 KB
Submitted:
Submitted By: (REGULATOR)
Title: 2007 ANNUAL ESTIMATION LETTER
Title Link: https://geotracker.waterboards.ca.gov/site_documents/5230488419/061807%202010046%2Epdf
Type: LETTER

Sites from GeoTracker Search - Cleanup Status History (as of May 29, 2021)

Status: Completed - Case Closed
Date: 6/7/2013

Status: Open - Site Assessment
Date: 11/9/2004

Status: Open - Site Assessment
Date: 10/21/2004

Status: Open - Site Assessment
Date: 7/15/2004

Status: Open - Case Begin Date
Date: 11/10/2003

77	1 of 2	ENE	0.47 / 2,507.72	134.49 / 14	Yolo Trucking 5807 Old Redwood Hwy Santa Rosa CA	LOP SONOMA

LOP No: 00002231
RB No: 1TSO394
Status: Y
Status Desc: Closed Site
Date: 9/24/1997
Global ID: T0609700284
APN: 059-310-046
Staff:
Staff Name:

77	2 of 2	ENE	0.47 / 2,507.72	134.49 / 14	YOLO TRUCKING 5807 OLD REDWOOD HWY SANTA ROSA CA 95403	LUST

Global ID: T0609700284
Status: COMPLETED - CASE CLOSED
Status Date: 9/24/1997
Case Type: LUST CLEANUP SITE
Date Source: LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download
County: SONOMA
Latitude: 38.522661
Longitude: -122.777415

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail

RB Case No: 1TSO394
Local Case No: 00002231
Begin Date: 5/4/1990
Lead Agency: SONOMA COUNTY LOP
Local Agency: SONOMA COUNTY LOP
CUF Case: YES

Potential COC: Gasoline, Diesel
How Discovered:
Stop Method:
Stop Description:
Case Worker: LCW
File Location: All Files are on GeoTracker or in the Local Agency Database

Potential Media of Concern: Aquifer used for drinking water supply
How Discovered Description:
Calwater Watershed Name: Russian River - Middle Russian River - Mark West (114.23)
DWR GW Subbasin Name: Santa Rosa Valley - Santa Rosa Plain (1-055.01)
Disadvantaged Community:
Calenviroscreen Score: 36-40%
Site History:

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity

Action Type: REMEDIATION
Date : 10/14/1991
Action: Excavation

Action Type: Other
Date : 5/4/1990
Action: Leak Discovery

Action Type: Other
Date : 1/2/1965
Action: Leak Reported

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts

Contact Type: Regional Board Caseworker
Contact Name: SONOMA COUNTY LOP CLOSED SITE
City: SANTA ROSA
Organization Name: NORTH COAST RWQCB (REGION 1)
Address: 5550 SKYLANE BOULEVARD, SUITE A
Email:
Phone No: 7075656565

Contact Type: Local Agency Caseworker
Contact Name: LOP CLOSED IN RB01
City: SANTA ROSA
Organization Name: SONOMA COUNTY LOP
Address: 625 FIFTH STREET
Email:
Phone No:

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History

Status: Completed - Case Closed
Status Date: 9/24/1997

Status: Open - Site Assessment
Status Date: 6/20/1991

Status: Open - Remediation
Status Date: 4/25/1991

Status: Open - Case Begin Date
Status Date: 5/4/1990

LUST Sites from GeoTracker Search - Regulatory Profile

Site Facility Name: YOLO TRUCKING
Site Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Project Status:
WDR Place Type:

Potential COC: DIESEL, GASOLINE
Facility Type:
Composting Method:
Address: 5807 OLD REDWOOD HWY
City: SANTA ROSA

WDR File:
WDR Order:
CUF Priority Assig: B
CUF Amount Paid: $50,796
Zip: 95403
County: SONOMA
CUF Claim: 6564
File Location: ALL FILES ARE ON GEOTRACKER OR IN THE LOCAL AGENCY DATABASE
Designated Beneficial Use: MUN, AGR, IND, PROC, FRSH, CUL, AQUA - Note: R1 BP- all gw same uses.
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T0609700284
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 9/24/1997
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0609700284&tabname=regulatoryhistory
Potential Media of Concern: AQUIFER USED FOR DRINKING WATER SUPPLY
User Defined Beneficial Use:
DWR GW Sub Basin: Santa Rosa Valley - Santa Rosa Plain (1-055.01)
Calwater Watershed Name: Russian River - Middle Russian River - Mark West (114.23)
Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: SONOMA COUNTY LOP (LEAD) - CASE #: 00002231
CASEWORKER: LOP CLOSED IN RB01
NORTH COAST RWQCB (REGION 1) - CASE #: 1TSO394
CASEWORKER: SONOMA COUNTY LOP CLOSED SITE
Gndwater Monitoring Freque:
Designated Beneficial Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply, Freshwater Replenishment, Native American Culture, AQUA - Note: R1 BP- all gw same uses.
Site History:

No site history available

LUST Sites from GeoTracker Search - Cleanup Status History

Status: Completed - Case Closed
Date : 9/24/1997

Status: Open - Site Assessment
Date : 6/20/1991

Status: Open - Remediation
Date : 4/25/1991

Status: Open - Case Begin Date
Date : 5/4/1990

LUST Sites from GeoTracker Search - Cleanup Action Report (as of May 29, 2021)

Action Type: EXCAVATION
Phase: Soil
Begin Date: 10/14/1991
End Date:
Contaminant Mass Removed:
Description:

LUST Sites from GeoTracker Search - Regulatory Activities (as of May 29, 2021)

Action Type: Cleanup Action
Action Date: 10/14/1991
Received Issue Date:
Action: Excavation
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action Date: 5/4/1990
Received Issue Date:
Action: Leak Discovery
Doc Link:
Title Description Comments:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Action Type: Leak Action
Action Date: 1/2/1965
Received Issue Date:
Action: Leak Reported
Doc Link:
Title Description Comments:

---

78 | **1 of 2** | **SSW** | **0.49 / 2,565.09** | **118.67 / -1** | **K & C Trucking**
1514 Airport Blvd
Santa Rosa CA | **LOP SONOMA**

LOP No: 00001239
RB No: 1TSO679
Status: Y
Status Desc: Closed Site
Date: 6/25/2003
Global ID: T0609700486
APN: 059-250-004
Staff:
Staff Name:

---

78 | **2 of 2** | **SSW** | **0.49 / 2,565.09** | **118.67 / -1** | **K & C TRUCKING**
1514 AIRPORT BLVD
SANTA ROSA CA 95401-1010 | **LUST**

Global ID: T0609700486
Status: COMPLETED - CASE CLOSED
Status Date: 6/25/2003
Case Type: LUST CLEANUP SITE
Date Source: LUST Cleanup Sites & Military UST Site from GeoTracker Project Search Results Export; LUST Cleanup Sites & Military UST Site from GeoTracker Cleanup Sites Data Download
County: SONOMA
Latitude: 38.509232868
Longitude: -122.791480297

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Facilities Detail

RB Case No: 1TSO679
Local Case No: 00001239
Begin Date: 9/10/1998
Lead Agency: SONOMA COUNTY LOP
Local Agency: SONOMA COUNTY LOP
CUF Case: NO
Potential Media of Concern: Aquifer used for drinking water supply
How Discovered Description:
Calwater Watershed Name: Russian River - Middle Russian River - Mark West (114.23)
DWR GW Subbasin Name: Santa Rosa Valley - Santa Rosa Plain (1-055.01)
Disadvantaged Community:
Calenviroscreen Score: 66-70%
Site History:
Potential COC: Diesel
How Discovered: Tank Closure
Stop Method: Close and Remove Tank
Stop Description:
Case Worker: LCW
File Location: Local Agency

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Activity

Action Type: ENFORCEMENT
Date : 6/25/2003
Action: Closure/No Further Action Letter

Action Type: ENFORCEMENT
Date : 3/21/2003
Action: * Historical Enforcement

Action Type: ENFORCEMENT
Date : 3/20/2003
Action: Notification - Public Notice of Case Closure

Action Type: ENFORCEMENT
Date : 9/15/1998
Action: Notification - Proposition 65

Action Type: Other
Date : 9/10/1998
Action: Leak Reported

Action Type: Other
Date : 9/10/1998
Action: Leak Discovery

Action Type: REMEDIATION
Date : 8/31/1998
Action: Excavation

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Regulatory Contacts

Contact Type: Regional Board Caseworker
Contact Name: SONOMA COUNTY LOP CLOSED SITE
City: SANTA ROSA
Organization Name: NORTH COAST RWQCB (REGION 1)
Address: 5550 SKYLANE BOULEVARD, SUITE A
Email:
Phone No: 7075656565

Contact Type: Local Agency Caseworker
Contact Name: LOP CLOSED IN RB01
City: SANTA ROSA
Organization Name: SONOMA COUNTY LOP
Address: 625 FIFTH STREET
Email:
Phone No:

LUST Cleanup Sites from GeoTracker Cleanup Sites Data Download - Status History

Status: Completed - Case Closed
Status Date: 6/25/2003

Status: Open - Site Assessment
Status Date: 12/18/1999

Status: Open - Site Assessment
Status Date: 1/7/1999

Status: Open - Case Begin Date
Status Date: 9/10/1998

LUST Sites from GeoTracker Search - Regulatory Profile

Site Facility Name: K & C TRUCKING
Site Facility Type: LUST CLEANUP SITE
Cleanup Status: COMPLETED - CASE CLOSED
Project Status:
WDR Place Type:
WDR File:
WDR Order:
CUF Priority Assig:
CUF Amount Paid:
Potential COC: DIESEL
Facility Type:
Composting Method:
Address: 1514 AIRPORT BLVD
City: SANTA ROSA
Zip: 95401-1010
County: SONOMA
CUF Claim:
File Location: LOCAL AGENCY
Designated Beneficial Use: MUN, AGR, IND, PROC, FRSH, CUL, AQUA - Note: R1 BP- all gw same uses.
Project Oversight Agencies:
Report Link: https://geotracker.waterboards.ca.gov/profile_report?global_id=T0609700486
Cleanup Status Detail: COMPLETED - CASE CLOSED AS OF 6/25/2003
Cleanup History Link: https://geotracker.waterboards.ca.gov/profile_report_include?global_id=T0609700486&tabname=regulatoryhistory
Potential Media of Concern: AQUIFER USED FOR DRINKING WATER SUPPLY
User Defined Beneficial Use:
DWR GW Sub Basin: Santa Rosa Valley - Santa Rosa Plain (1-055.01)
Calwater Watershed Name: Russian River - Middle Russian River - Mark West (114.23)
Post Closure Site Management:
Future Land Use:
Cleanup Oversight Agencies: SONOMA COUNTY LOP (LEAD) - CASE #: 00001239
CASEWORKER: LOP CLOSED IN RB01
NORTH COAST RWQCB (REGION 1) - CASE #: 1TSO679
CASEWORKER: SONOMA COUNTY LOP CLOSED SITE

Gndwater Monitoring Freque:
Designated Beneficial Use Desc: Municipal and Domestic Supply, Agricultural Supply, Industrial Service Supply, Industrial Process Supply, Freshwater Replenishment, Native American Culture, AQUA - Note: R1 BP- all gw same uses.
Site History:

No site history available

LUST Sites from GeoTracker Search - Cleanup Status History

Status: Completed - Case Closed
Date : 6/25/2003

Status: Open - Site Assessment
Date : 12/18/1999

Status: Open - Site Assessment
Date : 1/7/1999

Status: Open - Case Begin Date
Date : 9/10/1998

LUST Sites from GeoTracker Search - Cleanup Action Report (as of May 29, 2021)

Action Type: EXCAVATION
Phase: Soil
Contaminant Mass Removed:
Description: Removed at time of tank removal.
Begin Date: 8/31/1998
End Date: 11/12/1998

LUST Sites from GeoTracker Search - Regulatory Activities (as of May 29, 2021)

Action Type: Other Regulatory Actions
Action Date: 6/25/2003
Received Issue Date: 6/25/2003
Action: Closure/No Further Action Letter
Doc Link:
Title Description Comments:

Site Closure 6/25/03

Action Type: Enforcement/Orders
Action Date: 3/21/2003
Received Issue Date: 3/21/2003
Action: * Historical Enforcement
Doc Link:
Title Description Comments:

Recommendation for case closure sent to the NCRWQCB

Action Type: Notices
Action Date: 3/20/2003
Received Issue Date: 3/20/2003
Action: Notification - Public Notice of Case Closure
Doc Link:
Title Description Comments:

Action Type: Notices
Action Date: 9/15/1998
Received Issue Date: 9/15/1998
Action: Notification - Proposition 65
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action Date: 9/10/1998
Received Issue Date:
Action: Leak Discovery
Doc Link:
Title Description Comments:

Action Type: Leak Action
Action Date: 9/10/1998
Received Issue Date:
Action: Leak Reported
Doc Link:
Title Description Comments:

Action Type: Cleanup Action
Action Date: 8/31/1998
Received Issue Date:
Action: Excavation
Doc Link:
Title Description Comments:

Removed at time of tank removal.

LUST Sites from GeoTracker Search - Documents (as of May 29, 2021)

Document Type: Site Documents
Document Date: 6/25/2003
Type:
Title: SITE CLOSURE DOCUMENT
Title Link: https://geotracker.waterboards.ca.gov/site_documents/2031995475/1514Airport%2Epdf
Size : 1,843 KB
Submitted By: DARCY BERING (REGULATOR)
Submitted:

---

79 | ***1 of 1*** | ***SSW*** | ***0.51 / 2,713.31*** | ***117.71 / -2*** | ***CREAMS DISMANTLING INC.***
1588 AIRPORT BLVD
WINDSOR CA 95492 | ***ENVIROSTOR***

Estor/EPA ID: 49500017
Site Code:
Nat Priority List: NO
APN: NONE SPECIFIED
Census Tract: 6097152702
Site Type: * HISTORICAL
Address Description: 1588 AIRPORT BLVD
Office: CLEANUP BERKELEY
Special Program: * RURAL COUNTY SURVEY PROGRAM
Funding:
Cleanup Status: REFER: RWQCB AS OF 9/27/1993
Cleanup Oversight Agencies: NONE SPECIFIED
School District:
Past Use that Caused Contam: NONE SPECIFIED
Potential Media Affected: NONE SPECIFIED
Potential Contamin of Concern:
Assembly District: 02
Senate District: 02
Permit Renewal Lead:
Public Partici Spclst:
Project Manager:
County: SONOMA
Latitude: 38.5110909
Longitude: -122.7924272
Acres: NONE SPECIFIED
Supervisor:

NONE SPECIFIED

Site History:

Status: REFER: RWQCB
Program Type: HISTORICAL
CalEnviroScreen Score: 46-50%
Summary Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=49500017

Completed Activities

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Title: Site Screening
Title Link: https://www.envirostor.dtsc.ca.gov/public/
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Site Screening
Date Completed: 4/22/1988
Comments: SITE SCREENING DONE AUTO DISMANTLER

Title: Discovery
Title Link: https://www.envirostor.dtsc.ca.gov/public/
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: * Discovery
Date Completed: 4/18/1988
Comments: FACILITY IDENTIFIED PHONE DIR 1987

---

80 | ***1 of 1*** | ***WSW*** | ***0.62 / 3,260.24*** | ***104.86 / -15*** | ***DYNATEX INTERNATIONAL 5577 SKYLANE BOULEVARD SANTA ROSA CA 95403*** | ***ENVIROSTOR***

Estor/EPA ID: 71003406
Site Code:
Nat Priority List: NO
APN: NONE SPECIFIED
Census Tract: 6097152702
Site Type: TIERED PERMIT
Address Description: 5577 SKYLANE BOULEVARD
Office: CLEANUP BERKELEY
Special Program:
Funding:
Assembly District: 02
Senate District: 02
Permit Renewal Lead:
Public Partici Spclst:
Project Manager:
County: SONOMA
Latitude: 38.51717
Longitude: -122.799832
Acres: NONE SPECIFIED
Supervisor:
Cleanup Status: INACTIVE - NEEDS EVALUATION AS OF
Cleanup Oversight Agencies: NONE SPECIFIED
School District:
Past Use that Caused Contam: NONE SPECIFIED
Potential Media Affected: NONE SPECIFIED
Potential Contamin of Concern:

NONE SPECIFIED

Site History:

Status: INACTIVE - NEEDS EVALUATION
Program Type: TIERED PERMIT
CalEnviroScreen Score: 46-50%
Summary Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=71003406

---

81 | ***1 of 1*** | ***SW*** | ***0.67 / 3,533.17*** | ***113.86 / -6*** | ***SANTA ROSA ARMY AIRFIELD 2232 AIRPORT BLVD SANTA ROSA CA 95403*** | ***ENVIROSTOR***

Estor/EPA ID: 49450004
Site Code: 200586
Nat Priority List: NO
APN: NONE SPECIFIED
Census Tract: 6097152702
Site Type: FUDS
Address Description: 2232 AIRPORT BLVD
Office: CLEANUP SACRAMENTO
Special Program:
Funding: DERA
Assembly District: 02
Senate District: 02
Permit Renewal Lead:
Public Partici Spclst:
Project Manager: CARRIE TATOIAN-CAIN
County: SONOMA
Latitude: 38.5110638888889
Longitude: -122.797438888889
Acres: 1589.13 ACRES
Supervisor: AJIT VAIDYA
Cleanup Status: NO FURTHER ACTION AS OF 9/18/2014
Cleanup Oversight Agencies: DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY;RWQCB 1 - NORTH COAST

School District:
Past Use that Caused Contam: NONE SPECIFIED
Potential Media Affected: NONE SPECIFIED
Potential Contamin of Concern:

NONE SPECIFIED

Site History:

Santa Rosa Army Airfield (SRAAF) is a Formerly Used Defense Site (FUDS). The site is located in Sonoma County, California, approximately 5 miles northwest of the city of Santa Rosa. The Santa Rosa Army Air Field comprised 1,589.13 acres. Today the site is used as the Sonoma County Airport. The former SRAAF was used to train fighter groups and squadrons from 1942 to 1946. To support the training activities, aircraft and vehicle maintenance operations, a photographic laboratory, personnel barracks, medical facilities, and other support and maintenance facilities including a sewage treatment plant were constructed. The support operations took place immediately to the east of the runways in an area formally referred to as the cantonment area.

Facilities that could have resulted in potential environmental contamination include: 36 hard stands, three (3) former underground storage tank (UST) refueling groups, a former machine gun range, an aircraft hanger and adjacent washrack, the former photographic laboratory building, two (2) skeet shooting ranges, and a sewage treatment plant. All that remains of the sewage treatment plant is the circular concrete foundation of the trickling filter. The hard stands, USTs, aircraft hanger and its adjacent washrack, and the skeet shooting ranges are inside the boundaries of the current Sonoma County Airport.

Current development at the former SRAAF includes the municipal airport, the Sonoma County North County Detention Facility (a medium security prison), business parks, commercial and light industrial businesses, and some private residences. All cleanup action, with the exception of Military Munitions Program chemical warfare sites, is complete. The North Skeet Range has been used by the Santa Rosa Rod and Gun Club after transfer from the military.

Known and potential contamination associated with historic military ranges and chemical warfare agent kits have not been addressed.

Status: NO FURTHER ACTION
Program Type: MILITARY EVALUATION
CalEnviroScreen Score: 46-50%
Summary Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=49450004

Completed Activities

Title: RWQCB letter to Army re: reopen site closure
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49450004&enforcement_id=60342181
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Correspondence
Date Completed: 11/7/2013
Comments: RWQCB letter to Army

Title: No Department Defense Action Indicated - J09CA0026
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=49450004&doc_id=60381711
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: No Department of Defense Action Indicated (NDAI)
Date Completed: 9/18/2014
Comments: This determination is based on information in DTSC's and the Water Boards' possession at this time concerning Department of Defense (DoD) activities on the sites listed above. DTSC and the Water Boards reserve the right to address any appropriate environmental or human health related issue, should additional information concerning the environmental condition of this site become available in the future.

Title: Preliminary Endangerment Assessment Report
Title Link: https://www.envirostor.dtsc.ca.gov/public/
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Preliminary Endangerment Assessment Report
Date Completed: 6/23/1998
Comments: PEA - BASWD -- Preliminary Investigation of 11 sites at Formerly Used Defense Site (FUDS).

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
82	1 of 2	WSW	0.94 / 4,987.30	114.74 / -5	APEX AVIATION CORP. 2240 AIRPORT BLVD SANTA ROSA CA 94503	RESPONSE

Estor/EPA ID: 80001206
Site Code: 201770
Nat Priority List: NO
Acres: 2 ACRES
Special Program: VOLUNTARY CLEANUP PROGRAM
Funding: OTHER NON-MILITARY FUNDS
Assembly District: 02
Senate District: 02
School District:
Permit Renewal Lead:
Project Manager:
Supervisor: CHARLES RIDENOUR
Public Partici Spclst:
Census Tract: 6097152702
County: SONOMA
Latitude: 38.5123245728531
Longitude: -122.804479764557
APN: NONE SPECIFIED
Cleanup Status: NO FURTHER ACTION AS OF 8/18/2010
Cleanup Oversight Agencies: DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY
Site Type: CLOSED BASE
Office: CLEANUP SACRAMENTO
Past Use that Caused Contam: UNKNOWN
Potential Media Affected: SOIL
Potential Contamin of Concern:

UNDER INVESTIGATION

Site History:

The two acre parcel is located in Sonoma County and is situated within the boundaries of the formerly used defense site (FUDS) known as the Santa Rosa Army Air Field. In a July 2005 Negative Mitigated Declaration, Sonoma County required the property owner and project proponent to investigate the 2 acre parcel for evidence of chemical agent. The investigation was initiated in response to a 1982 discovery of a chemical agent identification set (CAIS) made during installation of a nearby sewer line. Northgate Environmental was contracted to develop the work plan and perform the site investigation. DTSC reviewed the work plan and issued a letter of concurrence dated December 13, 2007. Work was completed and no finds or evidence of CAIS was detected..

Status: NO FURTHER ACTION
Program Type: STATE RESPONSE
CalEnviroScreen Score: 46-50%
Summary Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001206

Completed Activities

Title: Voluntary Cooperative Agreement
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001206&enforcement_id=5009503
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: *Voluntary Cleanup Agreement Completion
Date Completed: 3/13/2008
Comments: Voluntary Cooperative Agreement for review of Geophysical and soil sampling work plan that addresses the investigation of a 2 acre parcel on the former Santa Rosa Army Airfield Formerly Used Defense Site.

Title: Work Plan for Munitions and Explosives of Concern (MEC)/Chemical Site Investigation at the Sonoma County Airport Apex Aviation Site
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001206&doc_id=5011852
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Preliminary Assessment Work Plan
Date Completed: 3/13/2008
Comments: Work plan for geophysical and chemistry of soils on a 2 acre portion of the Santa Rosa Army Airfield Formerly Used Defense Site.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
82	2 of 2	WSW	0.94 / 4,987.30	114.74 / -5	APEX AVIATION CORP. 2240 AIRPORT BLVD	ENVIROSTOR

SANTA ROSA CA 94503

Estor/EPA ID:	80001206	***Assembly District:***	02
Site Code:	201770	***Senate District:***	02
Nat Priority List:	NO	***Permit Renewal Lead:***	
APN:	NONE SPECIFIED	***Public Partici Spclst:***	
Census Tract:	6097152702	***Project Manager:***	
Site Type:	CLOSED BASE	***County:***	SONOMA
Address Description:	2240 AIRPORT BLVD	***Latitude:***	38.5123245728531
Office:	CLEANUP SACRAMENTO	***Longitude:***	-122.804479764557
Special Program:	VOLUNTARY CLEANUP PROGRAM	***Acres:***	2 ACRES
Funding:	OTHER NON-MILITARY FUNDS	***Supervisor:***	CHARLES RIDENOUR

Cleanup Status: NO FURTHER ACTION AS OF 8/18/2010
Cleanup Oversight Agencies: DTSC - SITE CLEANUP PROGRAM - LEAD AGENCY
School District:
Past Use that Caused Contam: UNKNOWN
Potential Media Affected: SOIL
Site History:

The two acre parcel is located in Sonoma County and is situated within the boundaries of the formerly used defense site (FUDS) known as the Santa Rosa Army Air Field. In a July 2005 Negative Mitigated Declaration, Sonoma County required the property owner and project proponent to investigate the 2 acre parcel for evidence of chemical agent. The investigation was initiated in response to a 1982 discovery of a chemical agent identification set (CAIS) made during installation of a nearby sewer line. Northgate Environmental was contracted to develop the work plan and perform the site investigation. DTSC reviewed the work plan and issued a letter of concurrence dated December 13, 2007. Work was completed and no finds or evidence of CAIS was detected..

Potential Contamin of Concern:

UNDER INVESTIGATION

Status: NO FURTHER ACTION
Program Type: STATE RESPONSE
CalEnviroScreen Score: 46-50%
Summary Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=80001206

Completed Activities

Title: Voluntary Cooperative Agreement
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001206&enforcement_id=5009503
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: *Voluntary Cleanup Agreement Completion
Date Completed: 3/13/2008
Comments: Voluntary Cooperative Agreement for review of Geophysical and soil sampling work plan that addresses the investigation of a 2 acre parcel on the former Santa Rosa Army Airfield Formerly Used Defense Site.

Title: Work Plan for Munitions and Explosives of Concern (MEC)/Chemical Site Investigation at the Sonoma County Airport Apex Aviation Site
Title Link: https://www.envirostor.dtsc.ca.gov/public/final_documents2?global_id=80001206&doc_id=5011852
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: Preliminary Assessment Work Plan
Date Completed: 3/13/2008
Comments: Work plan for geophysical and chemistry of soils on a 2 acre portion of the Santa Rosa Army Airfield Formerly Used Defense Site.

Unplottable Summary

Total: 8 Unplottable sites

DB	Company Name/Site Name	Address	City	Zip	ERIS ID
CALSITES	ECODYNE COOLING	SHILOH ROAD	WINDSOR CA	95442	891193776
CALSITES	STANDARD STRUCTURES	HWY 101 BETWEEN SHILOH & AIRPORT	WINDSOR CA	95492	891193936
CERCLIS	STANDARD STRUCTURES INC	HWY 101 BETW SHILOH & AIRPORT ***Site EPA ID:*** CAD053247425	WINDSOR CA	95492	805429230
CERCLIS NFRAP	STANDARD STRUCTURES INC	HWY 101 BETW SHILOH & AIRPORT ***Site EPA ID:*** CAD053247425	WINDSOR CA	95492	805463428
CHMIRS	Town of Windsor	Intersection of Sky Line and Shiloh Road	Windsor CA	95492	867284087
ENVIROSTOR	STANDARD STRUCTURES	HWY 101 BETWEEN SHILOH & AIRPORT ***Estor/EPA ID	Cleanup Status:*** 49320002 | REFER: RWQCB AS OF 9/27/1993	WINDSOR CA	95492	820360883
FINDS/FRS	SHAH & ECODYNE CORP	SHILOH BUSINESS PARK ***Registry ID:*** 110010061592	WINDSOR CA	95492	816571545
SEMS ARCHIVE	STANDARD STRUCTURES INC	HWY 101 BETW SHILOH & AIRPORT ***EPA ID:*** CAD053247425	WINDSOR CA	95492	828875130

Unplottable Report

Site: ***ECODYNE COOLING***
SHILOH ROAD WINDSOR CA 95442

CALSITES

ID No:	49420002	***Assembly:***	
Status Date:	04/03/1992	***Senate:***	
NPL:	N	***Region:***	2
Tier:		***Region Name:***	BERKELEY
Fund:		***County Co:***	49
Access :		***Facility County:***	SONOMA
Access Code:	NOT REPORTED	***Lat Deg:***	0
Cortese:		***Lat Min:***	0
Hrscore:		***Lat Sec:***	0
Hrsdate:		***Lat Dir:***	
Groundwater Contam:		***Long Deg:***	0
GW Code:	NOT REPORTED	***Long Min:***	0
No Sources:	0	***Long Sec:***	0
RWQCB Name:		***Long Dir:***	
Branch Name:	NORTH COAST	***Llmethod:***	
Staff:		***Lldesc:***	
Senior:			
Status Name:	PROPERTY/SITE REFERRED TO RWQCB		
Type Name:	RESPONSIBLE PARTY		
Lead Name:	REGIONAL WATER QUALITY CONTROL BOARD		
SIC Name:	TRUCKING & WAREHOUSING		
Filename:			
Comments:			

This is the date the site was first listed AWP pursuant to Section 25356.

Background:

Site: ***STANDARD STRUCTURES***
HWY 101 BETWEEN SHILOH & AIRPORT WINDSOR CA 95492

CALSITES

ID No:	49320002	***Assembly:***	
Status Date:	09/27/1993	***Senate:***	
NPL:		***Region:***	2
Tier:		***Region Name:***	BERKELEY
Fund:		***County Co:***	49
Access :		***Facility County:***	SONOMA
Access Code:	NOT REPORTED	***Lat Deg:***	0
Cortese:		***Lat Min:***	0
Hrscore:		***Lat Sec:***	0
Hrsdate:		***Lat Dir:***	
Groundwater Contam:		***Long Deg:***	0
GW Code:	NOT REPORTED	***Long Min:***	0
No Sources:	0	***Long Sec:***	0
RWQCB Name:	NORTH COAST	***Long Dir:***	
Branch Name:	NORTH COAST	***Llmethod:***	
Staff:		***Lldesc:***	
Senior:			
Status Name:	PROPERTY/SITE REFERRED TO RWQCB		
Type Name:	N/A		
Lead Name:	N/A		
SIC Name:	MANU - STONE, CLAY & GLASS PRODUCTS		
Filename:			
Comments:			

FACILITY IDENTIFIED EPA-CERCLIS INSPECTION(FED) PA1 SITE SCREENING DONE PA DONE BY EPA, NEED TO REVIEW DHS RCVD FIT

SSI- EPA RECOMMENDS LSI 9-12-90.

Background:

Site: ***STANDARD STRUCTURES INC***
HWY 101 BETW SHILOH & AIRPORT WINDSOR CA 95492

CERCLIS

Site ID:	0901430	***RNPL Status Code:***	N
Site EPA ID:	CAD053247425	***NPL Status:***	Not on the NPL
Site Street Address 2:		***RFED Facility Code:***	N
Site County Name:	SONOMA	***RFED Facility Desc:***	Not a Federal Facility
Site FIPS Code:	06097	***USGS Hydro Unit No.:***	18010110
Region Code:	09	***Site Cong. Dist. Code:***	02
Site SMSA No.:	7500	***ROT Desc:***	Unknown
Site Prim. Latitude:	38D31M35S	***FR NPL Update No.:***	
Site Prim. Longitude:	122D46M52S	***RFRA Code:***	
Lat Long Source:			

RNON NPL Status Desc: NFRAP-Site does not qualify for the NPL based on existing information

CERCLIS Assess History

OU ID:	00	***RALT Short Name:***	EPA Fund
Act Code ID:	001	***Act Start Date:***	
RAT Code:	PA	***Act Complete Date:***	7/1/1980 00:00:00
RAT Short Name:	PA	***AGT Order No.:***	130
RAT Name:	PRELIMINARY ASSESSMENT	***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:	B	***SH Seq:***	
RAT Level:	1	***SH Start Date:***	
RAT DEF OU:	00	***SH Complete Date:***	
RFBS Code:	P	***SH Lead:***	
SPA Code:	13		

RAT Def: Collection of diverse existing information about the source and nature of the site hazard. It is EPA policy to complete the preliminary assessment within one year of site discovery.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	00	***RALT Short Name:***	EPA Fund
Act Code ID:	002	***Act Start Date:***	
RAT Code:	PA	***Act Complete Date:***	2/28/1989 00:00:00
RAT Short Name:	PA	***AGT Order No.:***	130
RAT Name:	PRELIMINARY ASSESSMENT	***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:	B	***SH Seq:***	
RAT Level:	1	***SH Start Date:***	
RAT DEF OU:	00	***SH Complete Date:***	
RFBS Code:	P	***SH Lead:***	
SPA Code:	13		

RAT Def: Collection of diverse existing information about the source and nature of the site hazard. It is EPA policy to complete the preliminary assessment within one year of site discovery.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	00	***RALT Short Name:***	EPA Fund
Act Code ID:	002	***Act Start Date:***	
RAT Code:	SI	***Act Complete Date:***	3/27/1991 00:00:00
RAT Short Name:	SI	***AGT Order No.:***	160
RAT Name:	SITE INSPECTION	***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:	B	***SH Seq:***	
RAT Level:	1	***SH Start Date:***	
RAT DEF OU:	00	***SH Complete Date:***	

RFBS Code: P
SPA Code: 13
RAT Def: The process of collecting site data and samples to characterize the severity of the hazard for the hazard ranking score and/or enforcement support.
Site Desc:
Site Alias:

SH Lead:

CERCLIS Assess History

OU ID: 00
Act Code ID: 001
RAT Code: VS
RAT Short Name: ARCH SITE
RAT Name: ARCHIVE SITE
RAT Hist. Only Flag:
RAT NSI Indicator: B
RAT Level: 1
RAT DEF OU: 00
RFBS Code:
SPA Code: 13
RAT Def: The decision is made that no further activity is planned at the site.
Site Desc:
Site Alias:

RALT Short Name: EPA In-House
Act Start Date:
Act Complete Date: 3/27/1991 00:00:00
AGT Order No.: 1500
SH OU:
SH Code:
SH Seq:
SH Start Date:
SH Complete Date:
SH Lead:

CERCLIS Assess History

OU ID: 00
Act Code ID:
RAT Code:
RAT Short Name:
RAT Name:
RAT Hist. Only Flag:
RAT NSI Indicator:
RAT Level:
RAT DEF OU:
RFBS Code:
SPA Code:
RAT Def:
Site Desc: No description available
.
Site Alias: STANDARD STRUCTURES INC,920 SHILOH RD,SANTA ROSA,CA,95401;

RALT Short Name:
Act Start Date:
Act Complete Date:
AGT Order No.: 0
SH OU:
SH Code:
SH Seq:
SH Start Date:
SH Complete Date:
SH Lead:

CERCLIS Assess History

OU ID: 00
Act Code ID: 001
RAT Code: SI
RAT Short Name: SI
RAT Name: SITE INSPECTION
RAT Hist. Only Flag:
RAT NSI Indicator: B
RAT Level: 1
RAT DEF OU: 00
RFBS Code: P
SPA Code: 13
RAT Def: The process of collecting site data and samples to characterize the severity of the hazard for the hazard ranking score and/or enforcement support.
Site Desc:
Site Alias:

RALT Short Name: EPA Fund
Act Start Date:
Act Complete Date: 8/30/1990 00:00:00
AGT Order No.: 160
SH OU:
SH Code:
SH Seq:
SH Start Date:
SH Complete Date:
SH Lead:

CERCLIS Assess History

OU ID: 00
Act Code ID: 001
RAT Code: DS
RAT Short Name: DISCVRY
RAT Name: DISCOVERY
RAT Hist. Only Flag:

RALT Short Name: EPA Fund
Act Start Date:
Act Complete Date: 11/1/1979 00:00:00
AGT Order No.: 10
SH OU:
SH Code:

RAT NSI Indicator:	B	***SH Seq:***	
RAT Level:	1	***SH Start Date:***	
RAT DEF OU:	00	***SH Complete Date:***	
RFBS Code:		***SH Lead:***	
SPA Code:	13		

RAT Def: The process by which a potential hazardous waste site is brought to the attention of the EPA. The process can occur through the use of several mechanisms such as a phone call or referral by another government agency.

Site Desc:
Site Alias:

Site: ***STANDARD STRUCTURES INC***
HWY 101 BETW SHILOH & AIRPORT WINDSOR CA 95492

CERCLIS NFRAP

Site ID:	901430	***Site FIPS Code:***	6097
Site EPA ID:	CAD053247425	***Region Code:***	9
Site Parent ID:		***Site Cong. Dist. Code:***	2
Site County Name:	SONOMA	***Federal Facility:***	
Parent Site Name:			

CERCLIS-NFRAP Assess History

OU ID:	0	***Act Start Date:***	
Act Code ID:	1	***Act Complete Date:***	8/30/1990
RAT Code:	SI	***AGT Order No.:***	160
RAT Short Name:	SI	***SH OU:***	
RAT Name:	SITE INSPECTION	***SH Code:***	
RAT Hist. Only Flag:		***SH Seq:***	
RAT NSI Indicator:	B	***SH Start Date:***	
RAT Level:	1	***SH Complete Date:***	
RAT DEF OU:	00	***SH Lead:***	
RFBS Code:	P	***SH Qual:***	
SPA Code:	13	***RAQ Act. Qual Short:***	Low priority
RALT Short Name:	EPA Fund	***RNPL Status Code:***	N

RAT Def: The process of collecting site data and samples to characterize the severity of the hazard for the hazard ranking score and/or enforcement support.

RNON NPL Status Desc: NFRAP-Site does not qualify for the NPL based on existing information

CERCLIS-NFRAP Assess History

OU ID:	0	***Act Start Date:***	
Act Code ID:	1	***Act Complete Date:***	11/1/1979
RAT Code:	DS	***AGT Order No.:***	10
RAT Short Name:	DISCVRY	***SH OU:***	
RAT Name:	DISCOVERY	***SH Code:***	
RAT Hist. Only Flag:		***SH Seq:***	
RAT NSI Indicator:	B	***SH Start Date:***	
RAT Level:	1	***SH Complete Date:***	
RAT DEF OU:	00	***SH Lead:***	
RFBS Code:		***SH Qual:***	
SPA Code:	13	***RAQ Act. Qual Short:***	
RALT Short Name:	EPA Fund	***RNPL Status Code:***	N

RAT Def: The process by which a potential hazardous waste site is brought to the attention of the EPA. The process can occur through the use of several mechanisms such as a phone call or referral by another government agency.

RNON NPL Status Desc: NFRAP-Site does not qualify for the NPL based on existing information

CERCLIS-NFRAP Assess History

OU ID:	0	***Act Start Date:***	
Act Code ID:	2	***Act Complete Date:***	3/27/1991
RAT Code:	SI	***AGT Order No.:***	160
RAT Short Name:	SI	***SH OU:***	
RAT Name:	SITE INSPECTION	***SH Code:***	
RAT Hist. Only Flag:		***SH Seq:***	
RAT NSI Indicator:	B	***SH Start Date:***	
RAT Level:	1	***SH Complete Date:***	
RAT DEF OU:	00	***SH Lead:***	
RFBS Code:	P	***SH Qual:***	
SPA Code:	13	***RAQ Act. Qual Short:***	NFRAP

RALT Short Name:	EPA Fund	***RNPL Status Code:***	N
RAT Def:	The process of collecting site data and samples to characterize the severity of the hazard for the hazard ranking score and/or enforcement support.		
RNON NPL Status Desc:	NFRAP-Site does not qualify for the NPL based on existing information		

CERCLIS-NFRAP Assess History

OU ID:	0	***Act Start Date:***	
Act Code ID:	1	***Act Complete Date:***	3/27/1991
RAT Code:	VS	***AGT Order No.:***	1500
RAT Short Name:	ARCH SITE	***SH OU:***	
RAT Name:	ARCHIVE SITE	***SH Code:***	
RAT Hist. Only Flag:		***SH Seq:***	
RAT NSI Indicator:	B	***SH Start Date:***	
RAT Level:	1	***SH Complete Date:***	
RAT DEF OU:	00	***SH Lead:***	
RFBS Code:		***SH Qual:***	
SPA Code:	13	***RAQ Act. Qual Short:***	
RALT Short Name:	EPA In-House	***RNPL Status Code:***	N
RAT Def:	The decision is made that no further activity is planned at the site.		
RNON NPL Status Desc:	NFRAP-Site does not qualify for the NPL based on existing information		

CERCLIS-NFRAP Assess History

OU ID:	0	***Act Start Date:***	
Act Code ID:	1	***Act Complete Date:***	7/1/1980
RAT Code:	PA	***AGT Order No.:***	130
RAT Short Name:	PA	***SH OU:***	
RAT Name:	PRELIMINARY ASSESSMENT	***SH Code:***	
RAT Hist. Only Flag:		***SH Seq:***	
RAT NSI Indicator:	B	***SH Start Date:***	
RAT Level:	1	***SH Complete Date:***	
RAT DEF OU:	00	***SH Lead:***	
RFBS Code:	P	***SH Qual:***	
SPA Code:	13	***RAQ Act. Qual Short:***	Low priority
RALT Short Name:	EPA Fund	***RNPL Status Code:***	N
RAT Def:	Collection of diverse existing information about the source and nature of the site hazard. It is EPA policy to complete the preliminary assessment within one year of site discovery.		
RNON NPL Status Desc:	NFRAP-Site does not qualify for the NPL based on existing information		

CERCLIS-NFRAP Assess History

OU ID:	0	***Act Start Date:***	
Act Code ID:	2	***Act Complete Date:***	2/28/1989
RAT Code:	PA	***AGT Order No.:***	130
RAT Short Name:	PA	***SH OU:***	
RAT Name:	PRELIMINARY ASSESSMENT	***SH Code:***	
RAT Hist. Only Flag:		***SH Seq:***	
RAT NSI Indicator:	B	***SH Start Date:***	
RAT Level:	1	***SH Complete Date:***	
RAT DEF OU:	00	***SH Lead:***	
RFBS Code:	P	***SH Qual:***	
SPA Code:	13	***RAQ Act. Qual Short:***	Low priority
RALT Short Name:	EPA Fund	***RNPL Status Code:***	N
RAT Def:	Collection of diverse existing information about the source and nature of the site hazard. It is EPA policy to complete the preliminary assessment within one year of site discovery.		
RNON NPL Status Desc:	NFRAP-Site does not qualify for the NPL based on existing information		

Site: ***Town of Windsor***
Intersection of Sky Line and Shiloh Road Windsor CA 95492

CHMIRS

Control No:	17-5413	***Notified Date:***	
County:	Sonoma County	***Notified Date Time:***	
Year:	2017		
URL:	https://w3.calema.ca.gov/operational/malhaz.nsf/f1841a103c102734882563e200760c4a/3bd079d94bab37318825816e006c80c4?OpenDocument		

California Hazardous Material Incident Report System (2017)

Contained:	Yes	***Incident Date:***	7/31/2017
1 Substance:	Reclaimed/Tertiary Water (Highly Treated Recycled Water)	***Incident Time:***	1017
1 Quantity:	420	***Spill Site:***	Road
1 Measure:	Gal(s)	***Injuries?:***	No
1 Type:	CHEMICAL	***No of Injuries:***	
1 Pipeline:	No	***Fatals?:***	No
1 Vessel >= 300 Tons:	No	***No of Fatals:***	
1 Other:		***Evacs?:***	No
2 Substance:		***No of Evacs:***	
2 Quantity:		***Cleanup:***	Reporting Party
2 Measure:		***Site:***	Strom Drain
2 Type:		***Cause:***	Mechanical
2 Other:		***Cause Other:***	
2 Pipeline:	No	***Drinking Wtr Imp:***	No
2 Vessel >= 300 Tons:	No	***Known Impact:***	None
3 Substance:		***Water:***	No
3 Quantity:		***Water Way:***	Strom Drain
3 Measure:		***City:***	Windsor
3 Type:		***County:***	Sonoma County
3 Other:		***Zip:***	95492
3 Pipeline:	No	***DOG No:***	
3 Vessel >= 300 Tons:	No		

Admin Agency: Sonoma County Fire Services Department

Notification Area: AA/CUPA,DTSC,RWQCB,US EPA,USFWS,DFG-OSPR,CDPH-D.O.,LANDS,PARKS & REC,USCG,Co/Hlth,Co/E-Hlth

Location: Intersection of Sky Line and Shiloh Road

Description: RP states that 420 gallons of reclaimed/tertiary water released, due to a broken main-line valve, impacting a storm drain. The release is contained within the storm drain, and the Town of Windsor is performing the clean-up at the time of this report. Half of the release has been vacuumed, and the other half will be pumped to dry land.

Spill Report View

Amount 1:		***Creation Date:***	07/31/2017 12:45 PM
Amount 2:		***Received By:***	
Amount 3:		***Admin Agency:***	
Type:	CHEMICAL	***Admin Agency 2:***	
Water:		***Additional County:***	
On Scene:		***Phone No:***	
Other on Scene:		***Ext:***	
Other Notified:		***Pag Cell:***	
Document Title:	SPILL Report		
Spill Site:	Road		
Cause Desc for Other:			
Person Notifying Cal OES:			

Hazardous Materials Spill Report

Contained:	Yes	***Control Cal OES:***	17-5413
Date :	07/31/2017	***Control NRC:***	
Time:	1245	***Received By:***	
Incident Date:	07/31/2017	***Cleanup By:***	Reporting Party
Incident Time:	1017	***2 Substance:***	
Water Involved:	No	***2 Qty:***	=
Waterway:	Strom Drain	***2 Amount:***	
Drink Wtr Impact:	No	***2 Measure:***	
Detail for Other:		***2 Type:***	
UPRR Rim No:		***2 Other:***	
DOG Unit:		***2 Pipeline:***	No
RWQCB Unit:	1	***2 Ves >= 300 Tns:***	No
1 Substance:	Reclaimed/Tertiary Water (Highly Treated Recycled Water)	***3 Substance:***	
1 Qty:	=	***3 Qty:***	=
1 Amount :	420	***3 Amount:***	
1 Measure:	Gal(s)	***3 Measure:***	
1 Type:	CHEMICAL	***3 Type:***	
1 Other:		***3 Other:***	
1 Pipeline:	No	***3 Pipeline:***	No

1 Yes >= 300 Tons:	No	***3 Yes >= 300 Tons:***	No

Incident Location: Intersection of Sky Line and Shiloh Road
Additional County:
Injuries: No
Fatality: No
Evacuation: No
Known Impact: None
Name:
Agency: Town of Windsor
Phone:
Ext:
Pag Cell:
PRS Name:
PRS Agency:
PRS Phone:
PRS Ext:
PRS Pag Cell:
Sec Agency:
Admin Agency: Sonoma County Fire Services Department
Admin Agency 2:
Notification Info:
Notification List:
On Scene:
Other on Scene:
Other Notified:
Header Unknown: BAY AREA AQMD
Incident Desc:
Site: Road
Reported Cause: Mechanical
R R Crssing < 50 Ft:
Description: RP states that 420 gallons of reclaimed/tertiary water released, due to a broken main-line valve, impacting a storm drain. The release is contained within the storm drain, and the Town of Windsor is performing the clean-up at the time of this report. Half of the release has been vacuumed, and the other half will be pumped to dry land.

Site: ***STANDARD STRUCTURES***
HWY 101 BETWEEN SHILOH & AIRPORT WINDSOR CA 95492

ENVIROSTOR

Estor/EPA ID:	49320002	***Assembly District:***	
Site Code:		***Senate District:***	
Nat Priority List:	NO	***Permit Renewal Lead:***	
APN:	NONE SPECIFIED	***Public Partici Spclst:***	
Census Tract:		***Project Manager:***	
Site Type:	* HISTORICAL	***County:***	SONOMA
Address Description:	HWY 101 BETWEEN SHILOH & AIRPORT	***Latitude:***	0
Office:	CLEANUP BERKELEY	***Longitude:***	0
Special Program:	* RURAL COUNTY SURVEY PROGRAM	***Acres:***	NONE SPECIFIED
Funding:		***Supervisor:***	

Cleanup Status: REFER: RWQCB AS OF 9/27/1993
Cleanup Oversight Agencies: NONE SPECIFIED
School District:
Past Use that Caused Contam: NONE SPECIFIED
Potential Media Affected: NONE SPECIFIED
Potential Contamin of Concern:

NONE SPECIFIED

Site History:

Status: REFER: RWQCB
Program Type: HISTORICAL
CalEnviroScreen Score:
Summary Link: https://www.envirostor.dtsc.ca.gov/public/profile_report?global_id=49320002

Completed Activities

Title: Site Screening
Title Link: https://www.envirostor.dtsc.ca.gov/public/
Area Name:
Area Link:

Sub Area:
Sub Area Link:
Document Type: Site Screening
Date Completed: 4/21/1988
Comments: SITE SCREENING DONE PA DONE BY EPA, NEED TO REVIEW

Title: Discovery
Title Link: https://www.envirostor.dtsc.ca.gov/public/
Area Name:
Area Link:
Sub Area:
Sub Area Link:
Document Type: * Discovery
Date Completed: 11/1/1979
Comments: FACILITY IDENTIFIED EPA-CERCLIS

Site: ***SHAH & ECODYNE CORP***
SHILOH BUSINESS PARK WINDSOR CA 95492

FINDS/FRS

Registry ID: 110010061592
FIPS Code: CA097
HUC Code:
Site Type Name: STATIONARY
Location Description: SHAH & ECODYNE CORP
Supplemental Location:
Create Date: 01-MAR-00
Update Date: 03-MAY-15
Interest Types: ICIS-NPDES UNPERMITTED
SIC Codes:
SIC Code Descriptions:
NAICS Codes:
NAICS Code Descriptions:
Conveyor:
Federal Facility Code:
Federal Agency Name:
Tribal Land Code:
Tribal Land Name:
Congressional Dist No:
Census Block Code:
EPA Region Code: 09
County Name: SONOMA
US/Mexico Border Ind:
Latitude:
Longitude:
Reference Point:
Coord Collection Method:
Accuracy Value:
Datum: NAD83
Source:
Facility Detail Rprt URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110010061592
Program Acronyms:

NPDES:CAU000003

Site: ***STANDARD STRUCTURES INC***
HWY 101 BETW SHILOH & AIRPORT WINDSOR CA 95492

SEMS ARCHIVE

Site ID: 0901430
EPA ID: CAD053247425
Superfund Alt Agmt: No
Federal Facility: No
FF Docket: No
FIPS Code: 06097
Cong District: 02
Region: 09
County: SONOMA
NPL: Not on the NPL
Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

Action Information

Operable Units:	00	***Start Actual:***	
Action Code:	PA	***Finish Actual:***	07/01/1980
Action Name:	PA	***Qual:***	L
SEQ:	1	***Curr Action Lead:***	EPA Perf
Operable Units:	00	***Start Actual:***	
Action Code:	VS	***Finish Actual:***	03/27/1991
Action Name:	ARCH SITE	***Qual:***	
SEQ:	1	***Curr Action Lead:***	EPA Perf In-Hse
Operable Units:	00	***Start Actual:***	
Action Code:	PA	***Finish Actual:***	02/28/1989
Action Name:	PA	***Qual:***	L
SEQ:	2	***Curr Action Lead:***	EPA Perf
Operable Units:	00	***Start Actual:***	
Action Code:	SI	***Finish Actual:***	08/30/1990
Action Name:	SI	***Qual:***	L
SEQ:	1	***Curr Action Lead:***	EPA Perf
Operable Units:	00	***Start Actual:***	11/01/1979
Action Code:	DS	***Finish Actual:***	11/01/1979
Action Name:	DISCVRY	***Qual:***	
SEQ:	1	***Curr Action Lead:***	EPA Perf
Operable Units:	00	***Start Actual:***	
Action Code:	SI	***Finish Actual:***	03/27/1991
Action Name:	SI	***Qual:***	N
SEQ:	2	***Curr Action Lead:***	EPA Perf

Appendix: Database Descriptions

Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. ERIS updates databases as set out in ASTM Standard E1527-13, Section 8.1.8 Sources of Standard Source Information:

"Government information from nongovernmental sources may be considered current if the source updates the information at least every 90 days, or, for information that is updated less frequently than quarterly by the government agency, within 90 days of the date the government agency makes the information available to the public."

Standard Environmental Record Sources

Federal

Formerly Utilized Sites Remedial Action Program: DOE FUSRAP

The U.S. Department of Energy (DOE) established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from the Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations. The DOE Office of Legacy Management (LM) established long-term surveillance and maintenance (LTS&M) requirements for remediated FUSRAP sites. DOE evaluates the final site conditions of a remediated site on the basis of risk for different future uses. DOE then confirms that LTS&M requirements will maintain protectiveness.

Government Publication Date: Mar 4, 2017

National Priority List: NPL

National Priorities List (Superfund)-NPL: EPA's (United States Environmental Protection Agency) list of the most serious uncontrolled or abandoned hazardous waste sites identified for possible long-term remedial action under the Superfund program. The NPL, which EPA is required to update at least once a year, is based primarily on the score a site receives from EPA's Hazard Ranking System. A site must be on the NPL to receive money from the Superfund Trust Fund for remedial action.

Government Publication Date: Aug 25, 2021

National Priority List - Proposed: PROPOSED NPL

Includes sites proposed (by the EPA, the state, or concerned citizens) for addition to the NPL due to contamination by hazardous waste and identified by the Environmental Protection Agency (EPA) as a candidate for cleanup because it poses a risk to human health and/or the environment.

Government Publication Date: Aug 25, 2021

Deleted NPL: DELETED NPL

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Government Publication Date: Aug 25, 2021

SEMS List 8R Active Site Inventory: SEMS

The Superfund Program has deployed the Superfund Enterprise Management System (SEMS), which integrates multiple legacy systems into a comprehensive tracking and reporting tool. This inventory contains active sites evaluated by the Superfund program that are either proposed to be or are on the National Priorities List (NPL) as well as sites that are in the screening and assessment phase for possible inclusion on the NPL. The Active Site Inventory Report displays site and location information at active SEMS sites. An active site is one at which site assessment, removal, remedial, enforcement, cost recovery, or oversight activities are being planned or conducted.

Government Publication Date: Oct 20, 2021

Inventory of Open Dumps, June 1985: ODI

The Resource Conservation and Recovery Act (RCRA) provides for publication of an inventory of open dumps. The Act defines "open dumps" as facilities which do not comply with EPA's "Criteria for Classification of Solid Waste Disposal Facilities and Practices" (40 CFR 257).

Government Publication Date: Jun 1985

SEMS List 8R Archive Sites: SEMS ARCHIVE

The Superfund Enterprise Management System (SEMS) Archived Site Inventory displays site and location information at sites archived from SEMS. An archived site is one at which EPA has determined that assessment has been completed and no further remedial action is planned under the Superfund program at this time.

Government Publication Date: Oct 20, 2021

Comprehensive Environmental Response, Compensation and Liability Information System - CERCLIS: CERCLIS

Superfund is a program administered by the United States Environmental Protection Agency (EPA) to locate, investigate, and clean up the worst hazardous waste sites throughout the United States. CERCLIS is a database of potential and confirmed hazardous waste sites at which the EPA Superfund program has some involvement. It contains sites that are either proposed to be or are on the National Priorities List (NPL) as well as sites that are in the screening and assessment phase for possible inclusion on the NPL. The EPA administers the Superfund program in cooperation with individual states and tribal governments; this database is made available by the EPA.

Government Publication Date: Oct 25, 2013

EPA Report on the Status of Open Dumps on Indian Lands: IODI

Public Law 103-399, The Indian Lands Open Dump Cleanup Act of 1994, enacted October 22, 1994, identified congressional concerns that solid waste open dump sites located on American Indian or Alaska Native (AI/AN) lands threaten the health and safety of residents of those lands and contiguous areas. The purpose of the Act is to identify the location of open dumps on Indian lands, assess the relative health and environment hazards posed by those sites, and provide financial and technical assistance to Indian tribal governments to close such dumps in compliance with Federal standards and regulations or standards promulgated by Indian Tribal governments or Alaska Native entities.

Government Publication Date: Dec 31, 1998

CERCLIS - No Further Remedial Action Planned: CERCLIS NFRAP

An archived site is one at which EPA has determined that assessment has been completed and no further remedial action is planned under the Superfund program at this time. The Archive designation means that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL). This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Government Publication Date: Oct 25, 2013

CERCLIS Liens: CERCLIS LIENS

A Federal Superfund lien exists at any property where EPA has incurred Superfund costs to address contamination ("Superfund site") and has provided notice of liability to the property owner. A Federal CERCLA ("Superfund") lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. This database is made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: Jan 30, 2014

RCRA CORRACTS-Corrective Action: RCRA CORRACTS

RCRA Info is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. At these sites, the Corrective Action Program ensures that cleanups occur. EPA and state regulators work with facilities and communities to design remedies based on the contamination, geology, and anticipated use unique to each site.

Government Publication Date: Aug 30, 2021

RCRA non-CORRACTS TSD Facilities: RCRA TSD

RCRA Info is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. This database includes Non-Corrective Action sites listed as treatment, storage and/or disposal facilities of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA).

Government Publication Date: Aug 30, 2021

RCRA Generator List: RCRA LQG

RCRA Info is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Large Quantity Generators (LQGs) generate 1,000 kilograms per month or more of hazardous waste or more than one kilogram per month of acutely hazardous waste.

Government Publication Date: Aug 30, 2021

RCRA Small Quantity Generators List: RCRA SQG

RCRA Info is the EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Small Quantity Generators (SQGs) generate more than 100 kilograms, but less than 1,000 kilograms, of hazardous waste per month.

Government Publication Date: Aug 30, 2021

RCRA Very Small Quantity Generators List: RCRA VSQG

RCRA Info is the EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Very Small Quantity Generators (VSQG) generate 100 kilograms or less per month of hazardous waste, or one kilogram or less per month of acutely hazardous waste. Additionally, VSQG may not accumulate more than 1,000 kilograms of hazardous waste at any time.

Government Publication Date: Aug 30, 2021

RCRA Non-Generators: RCRA NON GEN

RCRA Info is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Non-Generators do not presently generate hazardous waste.

Government Publication Date: Aug 30, 2021

Federal Engineering Controls-ECs: FED ENG

Engineering controls (ECs) encompass a variety of engineered and constructed physical barriers (e.g., soil capping, sub-surface venting systems, mitigation barriers, fences) to contain and/or prevent exposure to contamination on a property. This database is made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: Feb 23, 2021

Federal Institutional Controls- ICs: FED INST

Institutional controls are non-engineered instruments, such as administrative and legal controls, that help minimize the potential for human exposure to contamination and/or protect the integrity of the remedy. Although it is EPA's (United States Environmental Protection Agency) expectation that treatment or engineering controls will be used to address principal threat wastes and that groundwater will be returned to its beneficial use whenever practicable, ICs play an important role in site remedies because they reduce exposure to contamination by limiting land or resource use and guide human behavior at a site.

Government Publication Date: Feb 23, 2021

Land Use Control Information System: LUCIS

The LUCIS database is maintained by the U.S. Department of the Navy and contains information for former Base Realignment and Closure (BRAC) properties across the United States.

Government Publication Date: Sep 1, 2006

Emergency Response Notification System: ERNS 1982 TO 1986

Database of oil and hazardous substances spill reports controlled by the National Response Center. The primary function of the National Response Center is to serve as the sole national point of contact for reporting oil, chemical, radiological, biological, and etiological discharges into the environment anywhere in the United States and its territories.

Government Publication Date: 1982-1986

Emergency Response Notification System: ERNS 1987 TO 1989

Database of oil and hazardous substances spill reports controlled by the National Response Center. The primary function of the National Response Center is to serve as the sole national point of contact for reporting oil, chemical, radiological, biological, and etiological discharges into the environment anywhere in the United States and its territories.

Government Publication Date: 1987-1989

Emergency Response Notification System: ERNS

Database of oil and hazardous substances spill reports made available by the United States Coast Guard National Response Center (NRC). The NRC fields initial reports for pollution and railroad incidents and forwards that information to appropriate federal/state agencies for response. These data contain initial incident data that has not been validated or investigated by a federal/state response agency.

Government Publication Date: Jul 26, 2021

The Assessment, Cleanup and Redevelopment Exchange System (ACRES) Brownfield Database: FED BROWNFIELDS

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties protects the environment, reduces blight, and takes development pressures off greenspaces and working lands. This database is made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: Aug 20, 2021

FEMA Underground Storage Tank Listing: FEMA UST

The Federal Emergency Management Agency (FEMA) of the Department of Homeland Security maintains a list of FEMA owned underground storage tanks.

Government Publication Date: Dec 31, 2017

Facility Response Plan: FRP

List of facilities that have submitted Facility Response Plans (FRP) to EPA. Facilities that could reasonably be expected to cause "substantial harm" to the environment by discharging oil into or on navigable waters are required to prepare and submit Facility Response Plans (FRPs). Harm is determined based on total oil storage capacity, secondary containment and age of tanks, oil transfer activities, history of discharges, proximity to a public drinking water intake or sensitive environments.

Government Publication Date: Dec 2, 2020

Historical Gas Stations: HIST GAS STATIONS

This historic directory of service stations is provided by the Cities Service Company. The directory includes Cities Service filling stations that were located throughout the United States in 1930.

Government Publication Date: Jul 1, 1930

Petroleum Refineries: REFN

List of petroleum refineries from the U.S. Energy Information Administration (EIA) Refinery Capacity Report. Includes operating and idle petroleum refineries (including new refineries under construction) and refineries shut down during the previous year located in the 50 States, the District of Columbia, Puerto Rico, the Virgin Islands, Guam, and other U.S. possessions. Survey locations adjusted using public data.

Government Publication Date: Jul 10, 2020

Petroleum Product and Crude Oil Rail Terminals: BULK TERMINAL

List of petroleum product and crude oil rail terminals made available by the U.S. Energy Information Administration (EIA). Includes operable bulk petroleum product terminals located in the 50 States and the District of Columbia with a total bulk shell storage capacity of 50,000 barrels or more, and/or the ability to receive volumes from tanker, barge, or pipeline; also rail terminals handling the loading and unloading of crude oil that were active between 2017 and 2018. Petroleum product terminals comes from the EIA-815 Bulk Terminal and Blender Report, which includes working, shell in operation, and shell idle for several major product groupings. Survey locations adjusted using public data.

Government Publication Date: Apr 28, 2020

LIEN on Property: SEMS LIEN

The EPA Superfund Enterprise Management System (SEMS) provides LIEN information on properties under the EPA Superfund Program.

Government Publication Date: Oct 20, 2021

Superfund Decision Documents: SUPERFUND ROD

This database contains a listing of decision documents for Superfund sites. Decision documents serve to provide the reasoning for the choice of (or) changes to a Superfund Site cleanup plan. The decision documents include Records of Decision (ROD), ROD Amendments, Explanations of Significant Differences (ESD), along with other associated memos and files. This information is maintained and made available by the US EPA (Environmental Protection Agency).

Government Publication Date: Jun 28, 2021

State

State Response Sites: RESPONSE

A list of identified confirmed release sites where the Department of Toxic Substances Control (DTSC) is involved in remediation, either in a lead or oversight capacity. These confirmed release sites are generally high-priority and high potential risk. This database is state equivalent NPL.

Government Publication Date: Sep 15, 2021

EnviroStor Database: ENVIROSTOR

The EnviroStor Data Management System is made available by the Department of Toxic Substances Control (DTSC). Includes Corrective Action sites, Tiered Permit sites, Historical Sites and Evaluation/Investigation sites. This database is state equivalent CERCLIS.

Government Publication Date: Sep 15, 2021

Delisted State Response Sites: DELISTED ENVS

Sites removed from the list of State Response Sites made available by the EnviroStor Data Management System, Department of Toxic Substances Control (DTSC).

Government Publication Date: Sep 15, 2021

Solid Waste Information System (SWIS): SWF/LF

The Solid Waste Information System (SWIS) database made available by the Department of Resources Recycling and Recovery (CalRecycle) contains information on solid waste facilities, operations, and disposal sites throughout the State of California. The types of facilities found in this database include landfills, transfer stations, material recovery facilities, composting sites, transformation facilities, waste tire sites, and closed disposal sites.

Government Publication Date: Nov 2, 2021

Solid Waste Disposal Sites with Waste Constituents Above Hazardous Waste Levels: SWRCB SWF

This is a list of solid waste disposal sites identified by California State Water Resources Control Board with waste constituents above hazardous waste levels outside the waste management unit.

Government Publication Date: Sep 20, 2006

EnviroStor Hazardous Waste Facilities: HWP

A list of hazardous waste facilities including permitted, post-closure and historical facilities found in the Department of Toxic Substances Control (DTSC) EnviroStor database.

Government Publication Date: Sep 15, 2021

Sites Listed in the Solid Waste Assessment Test (SWAT) Program Report: SWAT

In a 1993 Memorandum of Understanding, the State Water Resources Control Board (SWRCB) agreed to submit a comprehensive report on the Solid Waste Assessment Test (SWAT) Program to the California Integrated Waste Management Board (CIWMB). This report summarizes the work completed to date on the SWAT Program, and addresses both the impacts that leakage from solid waste disposal sites (SWDS) may have upon waters of the State and the actions taken to address such leakage.

Government Publication Date: Dec 31, 1995

Construction and Demolition Debris Recyclers: C&D DEBRIS RECY

This listing of Construction and Demolition Debris Recyclers is maintained by the California Intergrated Waste Management Board-common C&D materials include lumber, drywall, metals, masonry (brick, concrete, etc.), carpet, plastic, pipe, rocks, dirt, paper, cardboard, or green waste related to land development.

Government Publication Date: Jun 20, 2018

Recycling Centers: RECYCLING

This list of Certified Recycling Centers that are operating under the state of California's Beverage Container Recycling Program is maintained by the California Department of Resources Recycling and Recovery.

Government Publication Date: Nov 2, 2020

Listing of Certified Processors: PROCESSORS

This list of Certified Processors that are operating under the state of California's Beverage Container Recycling Program is maintained by the California Department of Resources Recycling and Recovery.

Government Publication Date: Oct 27, 2020

Listing of Certified Dropoff, Collection, and Community Service Programs: CONTAINER RECY

This list of Certified Dropoff, Collection, and Community Service Programs (non-buyback) operating under the state of California's Beverage Container Recycling Program is maintained by the California Department of Resources Recycling and Recovery.

Government Publication Date: Dec 16, 2020

Land Disposal Sites: LDS

Land Disposal Sites in GeoTracker, the State Water Resources Control Board (SWRCB)'s data management system. The Land Disposal program regulates of waste discharge to land for treatment, storage and disposal in waste management units. Waste management units include waste piles, surface impoundments, and landfills.

Government Publication Date: Jun 22, 2021

Leaking Underground Fuel Tank Reports: LUST

List of Leaking Underground Storage Tanks within the Cleanup Sites data in GeoTracker database. GeoTracker is the State Water Resources Control Board's (SWRCB) data management system for managing sites that impact groundwater, especially those that require groundwater cleanup (Underground Storage Tanks, Department of Defense and Site Cleanup Program) as well as permitted facilities such as operating Underground Storage Tanks. The Leak Prevention Program that overlooks LUST sites is the SWRCB in California's Environmental Protection Agency.

Government Publication Date: Jun 22, 2021

Delisted Leaking Storage Tanks: DELISTED LST

List of Leaking Underground Storage Tanks (LUST) cleanup sites removed from GeoTracker, the State Water Resources Control Board (SWRCB)'s database system, as well as sites removed from the SWRCB's list of UST Case closures.

Government Publication Date: Jun 22, 2021

Permitted Underground Storage Tank (UST) in GeoTracker: UST

List of Permitted Underground Storage Tank (UST) sites made available by the State Water Resources Control Board (SWRCB) in California's Environmental Protection Agency (EPA).

Government Publication Date: Oct 17, 2021

Proposed Closure of Underground Storage Tank Cases: UST CLOSURE

List of UST cases that are being considered for closure by either the California Environmental Protection Agency, State Water Resources Control Board or the Executive Director that have been posted for a 60-day public comment period.

Government Publication Date: May 5, 2021

Historical Hazardous Substance Storage Information Database: HHSS

The Historical Hazardous Substance Storage database contains information collected in the 1980s from facilities that stored hazardous substances. The information was originally collected on paper forms, was later transferred to microfiche, and recently indexed as a searchable database. When using this database, please be aware that it is based upon self-reported information submitted by facilities which has not been independently verified. It is unlikely that every facility responded to the survey and the database should not be expected to be a complete inventory of all facilities that were operating at that time. This database is maintained by the California State Water Resources Control Board's (SWRCB) Geotracker.

Government Publication Date: Aug 27, 2015

Statewide Environmental Evaluation and Planning System: UST SWEEPS

The Statewide Environmental Evaluation and Planning System (SWEEPS) is a historical listing of active and inactive underground storage tanks made available by the California State Water Resources Control Board (SWRCB).

Government Publication Date: Oct 1, 1994

Aboveground Storage Tanks: AST

A statewide list from 2009 of aboveground storage tanks (ASTs) made available by the Cal FIRE Office of the State Fire Marshal (OSFM). This list is no longer maintained or updated by the Cal FIRE OSFM.

Government Publication Date: Aug 31, 2009

SWRCB Historical Aboveground Storage Tanks: AST SWRCB

A list of aboveground storage tanks made available by the California State Water Resources Control Board (SWRCB). Effective January 1, 2008, the Certified Unified Program Agencies (CUPAs) are vested with the responsibility and authority to implement the Aboveground Petroleum Storage Act (APSA).

Government Publication Date: Dec 1, 2007

Oil and Gas Facility Tanks: TANK OIL GAS

Locations of oil and gas tanks that fall under the jurisdiction of the Geologic Energy Management Division of the California Department of Conservation (CalGEM) (CCR 1760). CalGEM was formerly the Division of Oil, Gas, and Geothermal Resources (DOGGR).

Government Publication Date: Sep 13, 2021

Delisted Storage Tanks: DELISTED TNK

This database contains a list of storage tank sites that were removed by the State Water Resources Control Board (SWRCB) in California's Environmental Protection Agency (EPA) and the Cal FIRE Office of State Fire Marshal (OSFM).

Government Publication Date: Oct 26, 2021

California Environmental Reporting System (CERS) Tanks: CERS TANK

List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the Aboveground Petroleum Storage and Underground Storage Tank regulatory programs. The CalEPA oversees the statewide implementation of the Unified Program which applies regulatory standards to protect Californians from hazardous waste and materials.

Government Publication Date: Sep 24, 2021

Delisted California Environmental Reporting System (CERS) Tanks: DELISTED CTNK

This database contains a list of Aboveground Petroleum Storage and Underground Storage Tank sites that were removed from in the California Environmental Protection Agency (CalEPA) Regulated Site Portal.

Government Publication Date: Sep 24, 2021

Historical Hazardous Substance Storage Container Information - Facility Summary: HIST TANK

The State Water Resources Control Board maintained the Hazardous Substance Storage Containers listing and inventory in th 1980s. This facility summary lists historic tank sites where the following container types were present: farm motor vehicle fuel tanks; waste tanks; sumps; pits, ponds, lagoons, and others; and all other product tanks. This set, published in May 1988, lists facility and owner information, as well as the number of containers. This data is historic and will not be updated.

Government Publication Date: May 27, 1988

Site Mitigation and Brownfields Reuse Program Facility Sites with Land Use Restrictions: LUR

The Department of Toxic Substances Control (DTSC) Site Mitigation and Brownfields Reuse Program (SMBRP) list includes sites cleaned up under the program's oversight and generally does not include current or former hazardous waste facilities that required a hazardous waste facility permit. The list represents land use restrictions that are active. Some sites have multiple land use restrictions.

Government Publication Date: Sep 15, 2021

CALSITES Database: CALSITES

This historical database was maintained by the Department of Toxic Substance Control (DTSC) for more than a decade. CALSITES contains information on Brownfield properties with confirmed or potential hazardous contamination. In 2006, DTSC introduced EnviroStor as the latest Brownfields site database.

Government Publication Date: May 1, 2004

Hazardous Waste Management Program Facility Sites with Deed / Land Use Restrictions: HLUR

The Department of Toxic Substances Control (DTSC) Hazardous Waste Management Program (HWMP) has developed a list of current or former hazardous waste facilities that have a recorded land use restriction at the local county recorder's office. The land use restrictions on this list were required by the DTSC HWMP as a result of the presence of hazardous substances that remain on site after the facility (or part of the facility) has been closed or cleaned up. The types of land use restriction include deed notice, deed restriction, or a land use restriction that binds current and future owners.

Government Publication Date: Feb 18, 2021

Deed Restrictions and Land Use Restrictions: DEED

List of Deed Restrictions, Land Use Restrictions and Covenants in GeoTracker made available by the State Water Resources Control Board (SWRCB) in California's Environmental Protection Agency. A deed restriction (land use covenant) may be required to facilitate the remediation of past environmental contamination and to protect human health and the environment by reducing the risk of exposure to residual hazardous materials.

Government Publication Date: Jun 22, 2021

Voluntary Cleanup Program: VCP

List of sites in the Voluntary Cleanup Program made available by the Department of Toxic Substances and Control (DTSC). The Voluntary Cleanup Program was designed to respond to lower priority sites. Under the Voluntary Cleanup Program, DTSC enters site-specific agreements with project proponents for DTSC oversight of site assessment, investigation, and/or removal or remediation activities, and the project proponents agree to pay DTSC's reasonable costs for those services.

Government Publication Date: Sep 15, 2021

GeoTracker Cleanup Program Sites: CLEANUP SITES

A list of Cleanup Program sites in the state of California made available by The State Water Resources Control Board (SWRCB) of the California Environmental Protection Agency (EPA). SWRCB tracks leaking underground storage tank cleanups as well as other water board cleanups.

Government Publication Date: Jun 22, 2021

Delisted County Records: DELISTED COUNTY

Records removed from county or CUPA databases. Records may be removed from the county lists made available by the respective county departments because they are inactive, or because they have been deemed to be below reportable thresholds.

Government Publication Date: Oct 8, 2021

Tribal

Leaking Underground Storage Tanks (LUSTs) on Indian Lands: INDIAN LUST
LUSTs on Tribal/Indian Lands in Region 9, which includes California.
Government Publication Date: Apr 8, 2020

Underground Storage Tanks (USTs) on Indian Lands: INDIAN UST
USTs on Tribal/Indian Lands in Region 9, which includes California.
Government Publication Date: Apr 8, 2020

Delisted Tribal Leaking Storage Tanks: DELISTED ILST
Leaking Underground Storage Tank facilities which have been removed from the Regional Tribal LUST lists made available by the EPA.
Government Publication Date: Apr 14, 2020

Delisted Tribal Underground Storage Tanks: DELISTED IUST
Underground Storage Tank facilities which have been removed from the Regional Tribal UST lists made available by the EPA.
Government Publication Date: Apr 14, 2020

County

Sonoma County - LOP Site List: LOP SONOMA
A list of Leaking Underground Storage Tank (LUST) facilities in Sonoma County. This list is made available by Sonoma County Department of Health Services. Sonoma County Local Oversight Program (LOP) oversees the investigation and cleanup of fuel releases from underground storage tanks in all areas of the County with the exception of the Cities of Santa Rosa and Healdsburg.
Government Publication Date: Jun 30, 2021

Sonoma County - CUPA Facilities List: CUPA SONOMA
A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in Sonoma County. This list is made available by Sonoma County Hazardous Materials (HazMat) Division which has been designated as the CUPA for the County.
Government Publication Date: Jul 2, 2021

Sonoma County - Petaluma City CUPA Facilities: CUPA PETALUMA
A list of facilities associated with various Certified Unified Program Agency (CUPA) programs in Petaluma City, as well as Closed files including pre-CUPA sites. This list is made available by Petaluma Fire Prevention Bureau which is the CUPA for Petaluma City in Sonoma County.
Government Publication Date: Oct 26, 2021

Additional Environmental Record Sources

Federal

PFOA/PFOS Contaminated Sites: PFAS NPL
List of sites where PFOA or PFOS contaminants have been found in drinking water or soil. Made available by the Federal Environmental Protection Agency (EPA).
Government Publication Date: Sep 17, 2021

Facility Registry Service/Facility Index: FINDS/FRS
The Facility Registry Service (FRS) is a centrally managed database that identifies facilities, sites, or places subject to environmental regulations or of environmental interest. FRS creates high-quality, accurate, and authoritative facility identification records through rigorous verification and management procedures that incorporate information from program national systems, state master facility records, and data collected from EPA's Central Data Exchange registrations and data management personnel. This list is made available by the Environmental Protection Agency (US EPA).

Government Publication Date: Nov 2, 2020

Toxics Release Inventory (TRI) Program: TRIS

The EPA's Toxics Release Inventory (TRI) is a database containing data on disposal or other releases of over 650 toxic chemicals from thousands of U. S. facilities and information about how facilities manage those chemicals through recycling, energy recovery, and treatment. One of TRI's primary purposes is to inform communities about toxic chemical releases to the environment.

Government Publication Date: Aug 24, 2021

Perfluorinated Alkyl Substances (PFAS) Releases: PFAS TRI

List of Toxics Release Inventory (TRI) facilities at which the reported chemical is a Per- or polyfluorinated alkyl substance (PFAS) included in the Environmental Protection Agency (EPA)'s consolidated PFAS Master List of PFAS Substances. The EPA's Toxics Release Inventory (TRI) is a database containing data on disposal or other releases of over 650 toxic chemicals from thousands of U.S. facilities and information about how facilities manage those chemicals through recycling, energy recovery, and treatment.

Government Publication Date: Aug 24, 2021

Perfluorinated Alkyl Substances (PFAS) Water Quality: PFAS WATER

The Water Quality Portal (WQP) is a cooperative service sponsored by the United States Geological Survey (USGS), the Environmental Protection Agency (EPA), and the National Water Quality Monitoring Council (NWQMC). This listing includes records from the Water Quality Portal where the characteristic (environmental measurement) is in the Environmental Protection Agency (EPA)'s consolidated PFAS Master List of PFAS Substances.

Government Publication Date: Jul 20, 2020

Hazardous Materials Information Reporting System: HMIRS

US DOT - Department of Transportation Pipeline and Hazardous Materials Safety Administration (PHMSA) Incidents Reports Database taken from Hazmat Intelligence Portal, U.S. Department of Transportation.

Government Publication Date: Sep 1, 2020

National Clandestine Drug Labs: NCDL

The U.S. Department of Justice ("the Department") provides this data as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy.

Government Publication Date: Oct 5, 2020

Toxic Substances Control Act: TSCA

The Environmental Protection Agency (EPA) is amending the Toxic Substances Control Act (TSCA) section 8(a) Inventory Update Reporting (IUR) rule and changing its name to the Chemical Data Reporting (CDR) rule.

The CDR enables EPA to collect and publish information on the manufacturing, processing, and use of commercial chemical substances and mixtures (referred to hereafter as chemical substances) on the TSCA Chemical Substance Inventory (TSCA Inventory). This includes current information on chemical substance production volumes, manufacturing sites, and how the chemical substances are used. This information helps the Agency determine whether people or the environment are potentially exposed to reported chemical substances. EPA publishes submitted CDR data that is not Confidential Business Information (CBI).

Government Publication Date: Apr 11, 2019

Hist TSCA: HIST TSCA

The Environmental Protection Agency (EPA) is amending the Toxic Substances Control Act (TSCA) section 8(a) Inventory Update Reporting (IUR) rule and changing its name to the Chemical Data Reporting (CDR) rule.

The 2006 IUR data summary report includes information about chemicals manufactured or imported in quantities of 25,000 pounds or more at a single site during calendar year 2005. In addition to the basic manufacturing information collected in previous reporting cycles, the 2006 cycle is the first time EPA collected information to characterize exposure during manufacturing, processing and use of organic chemicals. The 2006 cycle also is the first time manufacturers of inorganic chemicals were required to report basic manufacturing information.

Government Publication Date: Dec 31, 2006

FTTS Administrative Case Listing: FTTS ADMIN

An administrative case listing from the Federal Insecticide, Fungicide, & Rodenticide Act (FIFRA) and Toxic Substances Control Act (TSCA), together known as FTTS. This database was obtained from the Environmental Protection Agency's (EPA) National Compliance Database (NCDB). The FTTS and NCDB was shut down in 2006.

Government Publication Date: Jan 19, 2007

FTTS Inspection Case Listing: FTTS INSP

An inspection case listing from the Federal Insecticide, Fungicide, & Rodenticide Act (FIFRA) and Toxic Substances Control Act (TSCA), together known as FTTS. This database was obtained from the Environmental Protection Agency's (EPA) National Compliance Database (NCDB). The FTTS and NCDB was shut down in 2006.

Government Publication Date: Jan 19, 2007

Potentially Responsible Parties List: PRP

Early in the cleanup process, the Environmental Protection Agency (EPA) conducts a search to find the potentially responsible parties (PRPs). EPA looks for evidence to determine liability by matching wastes found at the site with parties that may have contributed wastes to the site.

Government Publication Date: Oct 20, 2021

State Coalition for Remediation of Drycleaners Listing: SCRD DRYCLEANER

The State Coalition for Remediation of Drycleaners (SCRD) was established in 1998, with support from the U.S. Environmental Protection Agency (EPA) Office of Superfund Remediation and Technology Innovation. Coalition members are states with mandated programs and funding for drycleaner site remediation. Current members are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Government Publication Date: Nov 08, 2017

Integrated Compliance Information System (ICIS): ICIS

The Integrated Compliance Information System (ICIS) is a system that provides information for the Federal Enforcement and Compliance (FE&C) and the National Pollutant Discharge Elimination System (NPDES) programs. The FE&C component supports the Environmental Protection Agency's (EPA) Civil Enforcement and Compliance program activities. These activities include Compliance Assistance, Compliance Monitoring and Enforcement. The NPDES program supports tracking of NPDES permits, limits, discharge monitoring data and other program reports.

Government Publication Date: Jun 14, 2021

Drycleaner Facilities: FED DRYCLEANERS

A list of drycleaner facilities from Enforcement and Compliance History Online (ECHO) online search. The Environmental Protection Agency (EPA) tracks facilities that possess NAIC and SIC codes that classify businesses as drycleaner establishments.

Government Publication Date: May 5, 2021

Delisted Drycleaner Facilities: DELISTED FED DRY

List of sites removed from the list of Drycleaner Facilities (sites in the EPA's Integrated Compliance Information System (ICIS) with NAIC or SIC codes identifying the business as a drycleaner establishment).

Government Publication Date: May 5, 2021

Formerly Used Defense Sites: FUDS

Formerly Used Defense Sites (FUDS) are properties that were formerly owned by, leased to, or otherwise possessed by and under the jurisdiction of the Secretary of Defense prior to October 1986, where the Department of Defense (DoD) is responsible for an environmental restoration. This list is published by the U.S. Army Corps of Engineers.

Government Publication Date: May 26, 2021

Former Military Nike Missile Sites: FORMER NIKE

This information was taken from report DRXTH-AS-IA-83A016 (Historical Overview of the Nike Missile System, 12/1984) which was performed by Environmental Science and Engineering, Inc. for the U.S. Army Toxic and Hazardous Materials Agency Assessment Division. The Nike system was deployed between 1954 and the mid-1970's. Among the substances used or stored on Nike sites were liquid missile fuel (JP-4); starter fluids (UDKH, aniline, and furfuryl alcohol); oxidizer (IRFNA); hydrocarbons (motor oil, hydraulic fluid, diesel fuel, gasoline, heating oil); solvents (carbon tetrachloride, trichloroethylene, trichloroethane, stoddard solvent); and battery electrolyte. The quantities of material a disposed of and procedures for disposal are not documented in published reports. Virtually all information concerning the potential for contamination at Nike sites is confined to personnel who were assigned to Nike sites. During deactivation most hardware was shipped to depot-level supply points. There were reportedly instances where excess materials were disposed of on or near the site itself at closure. There was reportedly no routine site decontamination.

Government Publication Date: Dec 2, 1984

PHMSA Pipeline Safety Flagged Incidents: PIPELINE INCIDENT

A list of flagged pipeline incidents made available by the U.S. Department of Transportation (US DOT) Pipeline and Hazardous Materials Safety Administration (PHMSA). PHMSA regulations require incident and accident reports for five different pipeline system types.

Government Publication Date: Jul 7, 2020

Material Licensing Tracking System (MLTS): MLTS

A list of sites that store radioactive material subject to the Nuclear Regulatory Commission (NRC) licensing requirements. This list is maintained by the NRC. As of September 2016, the NRC no longer releases location information for sites. Site locations were last received in July 2016.

Government Publication Date: May 11, 2021

Historic Material Licensing Tracking System (MLTS) sites: HIST MLTS

A historic list of sites that have inactive licenses and/or removed from the Material Licensing Tracking System (MLTS). In some cases, a site is removed from the MLTS when the state becomes an "Agreement State". An Agreement State is a State that has signed an agreement with the Nuclear Regulatory Commission (NRC) authorizing the State to regulate certain uses of radioactive materials within the State.

Government Publication Date: Jan 31, 2010

Mines Master Index File: MINES

The Master Index File (MIF) contains mine identification numbers issued by the Department of Labor Mine Safety and Health Administration (MSHA) for mines active or opened since 1971. Note that addresses may or may not correspond with the physical location of the mine itself.

Government Publication Date: Nov 3, 2020

Surface Mining Control and Reclamation Act Sites: SMCRA

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by the Office of Surface Mining Reclamation and Enforcement (OSMRE) to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of Abandoned Mine Land (AML) impacts, as well as information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Government Publication Date: Dec 18, 2020

Mineral Resource Data System: MRDS

The Mineral Resource Data System (MRDS) is a collection of reports describing metallic and nonmetallic mineral resources throughout the world. Included are deposit name, location, commodity, deposit description, geologic characteristics, production, reserves, resources, and references. This database contains the records previously provided in the Mineral Resource Data System (MRDS) of USGS and the Mineral Availability System/Mineral Industry Locator System (MAS/MILS) originated in the U.S. Bureau of Mines, which is now part of USGS. The USGS has ceased systematic updates of the MRDS database with their focus more recently on deposits of critical minerals while providing a well-documented baseline of historical mine locations from USGS topographic maps.

Government Publication Date: Mar 15, 2006

Uranium Mill Tailings Radiation Control Act Sites: URANIUM

The Legacy Management Office of the Department of Energy (DOE) manages radioactive and chemical waste, environmental contamination, and hazardous material at over 100 sites across the U.S. The L.M. Office manages this database of sites registered under the Uranium Mill Tailings Control Act (UMTRCA).

Government Publication Date: Mar 4, 2017

Alternative Fueling Stations: ALT FUELS

List of alternative fueling stations made available by the US Department of Energy's Office of Energy Efficiency & Renewable Energy. Includes Biodiesel stations, Ethanol (E85) stations, Liquefied Petroleum Gas (Propane) stations, Ethanol (E85) stations, Natural Gas stations, Hydrogen stations, and Electric Vehicle Supply Equipment (EVSE). The National Renewable Energy Laboratory (NREL) obtains information about new stations from trade media, Clean Cities coordinators, a Submit New Station form on the Station Locator website, and through collaborating with infrastructure equipment and fuel providers, original equipment manufacturers (OEMs), and industry groups.

Government Publication Date: Oct 25, 2021

Registered Pesticide Establishments: SSTS

List of active EPA-registered foreign and domestic pesticide-producing and device-producing establishments based on data from the Section Seven Tracking System (SSTS). The Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) Section 7 requires that facilities producing pesticides, active ingredients, or devices be registered. The list of establishments is made available by the EPA.

Government Publication Date: Apr 13, 2021

Polychlorinated Biphenyl (PCB) Notifiers: PCB

Facilities included in the national list of facilities that have notified the United States Environmental Protection Agency (EPA) of Polychlorinated Biphenyl (PCB) activities. Any company or person storing, transporting or disposing of PCBs or conducting PCB research and development must notify the EPA and receive an identification number.

Government Publication Date: Nov 19, 2020

State

Dry Cleaning Facilities: DRYCLEANERS

A list of drycleaner related facilities that have EPA ID numbers. These are facilities with certain SIC codes: power laundries, family and commercial, linen supply, commercial laundry, dry cleaning and pressing machines - Coin Operated Laundry and Dry Cleaning. This is provided by the Department of Toxic Substance Control.

Government Publication Date: Aug 27, 2021

Delisted Drycleaners: DELISTED DRYCLEANERS

Sites removed from the list of drycleaner related facilities that have EPA ID numbers, made available by the California Department of Toxic Substance Control.

Government Publication Date: Aug 27, 2021

Non-Toxic Dry Cleaning Incentive Program: DRYC GRANT

A list of grant recipients of the Non-Toxic Dry Cleaning Incentive Program made available by the California Air Resources Board (CARB). The program provides grants to eligible dry cleaning businesses to assist them in transitioning away from PERC machines to alternative non-toxic and non-smog forming technologies.

Government Publication Date: Feb 28, 2018

Per- and Polyfluoroalkyl Substances (PFAS): PFAS

List of sites from the State Water Resources Control Board (SWRCB)'s GeoTracker at which one or more of the potential contaminants of concern are in the PFAS Master List of PFAS Substances made available by the Environmental Protection Agency (US EPA).

Government Publication Date: Jun 22, 2021

PFOA/PFOS Groundwater: PFAS GW

A list of water wells from the Groundwater Ambient Monitoring and Assessment Program (GAMA) Groundwater Information System with the groundwater chemical perfluorooctanoic acid (PFOA) (NL = 0.014 UG/L) or perfluorooctanoic sulfonate (PFOS) (NL = 0.013 UG/L). The GAMA Groundwater Information System search is made available by California Water Boards.

Government Publication Date: Oct 22, 2020

Hazardous Waste and Substances Site List - Site Cleanup: HWSS CLEANUP

The Hazardous Waste and Substances Sites (Cortese) List is a planning document used by the State, local agencies and developers to comply with the California Environmental Quality Act requirements in providing information about the location of hazardous materials release sites. This list is published by California Department of Toxic Substance Control.

Government Publication Date: May 20, 2021

List of Hazardous Waste Facilities Subject to Corrective Action: DTSC HWF

This is a list of hazardous waste facilities identified in Health and Safety Code (HSC) § 25187.5. These facilities are those where Department of Toxic Substances Control (DTSC) has taken or contracted for corrective action because a facility owner/operator has failed to comply with a date for taking corrective action in an order issued under HSC § 25187, or because DTSC determined that immediate corrective action was necessary to abate an imminent or substantial endangerment.

Government Publication Date: Jul 18, 2016

EnviroStor Inspection, Compliance, and Enforcement: INSP COMP ENF

A list of permitted facilities with inspections and enforcements tracked in the Department of Toxic Substance Control (DTSC) EnviroStor.

Government Publication Date: Apr 29, 2021

School Property Evaluation Program Sites: SCH

A list of sites registered with The Department of Toxic Substances Control (DTSC) School Property Evaluation and Cleanup (SPEC) Division. SPEC is responsible for assessing, investigating and cleaning up proposed school sites. The Division ensures that selected properties are free of contamination or, if the properties were previously contaminated, that they have been cleaned up to a level that protects the students and staff who will occupy the new school.

Government Publication Date: Sep 15, 2021

California Hazardous Material Incident Report System (CHMIRS): CHMIRS

A list of reported hazardous material incidents, spills, and releases from the California Hazardous Material Incident Report System (CHMIRS). This list has been made available by the California Office of Emergency Services (OES).

Government Publication Date: Aug 1, 2021

Historical California Hazardous Material Incident Report System (CHMIRS): HIST CHMIRS

A list of reported hazardous material incidents, spills, and releases from the California Hazardous Material Incident Report System (CHMIRS) prior to 1993. This list has been made available by the California Office of Emergency Services (OES).

Government Publication Date: Jan 1, 1993

Hazardous Waste Manifest Data: HAZNET

A list of hazardous waste manifests received each year by Department of Toxic Substances Control (DTSC). The volume of manifests is typically 900,000 - 1,000,000 annually, representing approximately 450,000 - 500,000 shipments.

Government Publication Date: Oct 24, 2016

Historical Hazardous Waste Manifest Data: HIST MANIFEST

A list of historic hazardous waste manifests received by the Department of Toxic Substances Control (DTSC) from year the 1980 to 1992. The volume of manifests is typically 900,000 - 1,000,000 annually, representing approximately 450,000 - 500,000 shipments.

Government Publication Date: Dec 31, 1992

DTSC Registered Hazardous Waste Transporters: HW TRANSPORT

The California Department of Toxic Substances Control (DTSC) maintains this list of Registered Hazardous Waste Transporters.

Government Publication Date: Oct 19, 2020

Registered Waste Tire Haulers: WASTE TIRE

This list of registered waste tire haulers is maintained by the California Department of Resources Recycling and Recovery.

Government Publication Date: Dec 16, 2020

California Medical Waste Management Program Facility List: MEDICAL WASTE

This list of Medical Waste Management Program Facilities is maintained by the California Department of Public Health. The Medical Waste Management Program (MWMP) regulates the generation, handling, storage, treatment, and disposal of medical waste by providing oversight for the implementation of the Medical Waste Management Act (MWMA). The MWMP permits and inspects all medical waste off-site treatment facilities, medical waste transporters, and medical waste transfer stations. This list contains transporters, treatment, and transfer facilities.

Government Publication Date: Dec 31, 2020

Historical Cortese List: HIST CORTESE

List of sites which were once included on the Cortese list. The Hazardous Waste and Substances Sites (Cortese) List is a planning document used by the State, local agencies and developers to comply with the California Environmental Quality Act requirements for providing information about the location of hazardous sites.

Government Publication Date: Nov 13, 2008

Cease and Desist Orders and Cleanup and Abatement Orders: CDO/CAO

The California Environment Protection Agency "Cortese List" of active Cease and Desist Orders (CDO) and Cleanup and Abatement Orders (CAO). This list contains many CDOs and CAOs that do NOT concern the discharge of wastes that are hazardous materials. Many of the listed orders concern, as examples, discharges of domestic sewage, food processing wastes, or sediment that do not contain hazardous materials, but the Water Boards' database does not distinguish between these types of orders.

Government Publication Date: Jul 19, 2020

California Environmental Reporting System (CERS) Hazardous Waste Sites: CERS HAZ

List of sites in the California Environmental Protection Agency (CalEPA) Regulated Site Portal which fall under the following regulatory programs: Hazardous Chemical Management, Hazardous Waste Onsite Treatment, Household Hazardous Waste Collection, Hazardous Waste Generator, RCRA LQ HW Generator. The CalEPA oversees the statewide implementation of the Unified Program which applies regulatory standards to protect Californians from hazardous waste and materials.

Government Publication Date: Sep 24, 2021

Delisted Environmental Reporting System (CERS) Hazardous Waste Sites: DELISTED HAZ

This database contains a list of sites that were removed from the California Environmental Protection Agency (CalEPA) in the following regulatory programs: Hazardous Chemical Management, Hazardous Waste Onsite Treatment, Household Hazardous Waste Collection, Hazardous Waste Generator, RCRA LQ HW Generator.

Government Publication Date: Nov 29, 2018

Sites in GeoTracker: GEOTRACKER

GeoTracker is the State Water Resource Control Boards' data management system for sites that impact, or have the potential to impact, water quality in California, with emphasis on groundwater. This is a list of sites in GeoTracker that aren't otherwise categorized as LUST, Land Disposal Sites (LDS), Cleanup Sites, or sites having Waste Discharge Requirements (WDR). This listing includes program types such as Underground Injection Control (UIC), Confined Animal Facilities (CAF), Irrigated Lands Regulatory Program, plans, and non-case information.

Government Publication Date: Jun 22, 2021

Mines Listing: MINE

This list includes mine site locations extracted from the Mines Online database, maintained by the California Department of Conservation. Mines Online (MOL) is an interactive web map designed with GIS features that provide information such as the mine name, mine status, commodity sold, location, and other mine specific data. Please note: Mine location information is provided to assist experts in determining the location of mine operators in accordance with California Civil Code section 1103.4 and reflects information reported by mine operators in annual reports provided under Public Resources Code section 2207. While the Division of Mine Reclamation (DMR) attempts to populate MOL with accurate location information, the DMR cannot guarantee the accuracy of operator reported location information.

Government Publication Date: Jan 12, 2021

Recorded Environmental Cleanup Liens: LIEN

The California Department of Toxic Substance Control (DTSC) maintains this list of liens placed upon real properties. A lien is utilized by the DTSC to obtain reimbursement from responsible parties for costs associated with the remediation of contaminated properties.

Government Publication Date: Nov 16, 2020

Waste Discharge Requirements: WASTE DISCHG

List of sites in California State Water Resources Control Board (SWRCB) Waste Discharge Requirements (WDRs) Program in California, made available by the SWRCB via GeoTracker. The WDR program regulates point discharges that are exempt pursuant to Subsection 20090 of Title 27 and not subject to the Federal Water Pollution Control Act. The scope of the WDRs Program also includes the discharge of wastes classified as inert, pursuant to section 20230 of Title 27.

Government Publication Date: Jun 22, 2021

Toxic Pollutant Emissions Facilities: EMISSIONS

A list of criteria and toxic pollutant emissions data for facilities in California made available by the California Environmental Protection Agency - Air Resources Board (ARB). Risk data may be based on previous inventory submittals. The toxics data are submitted to the ARB by the local air districts as requirement of the Air Toxics "Hot Spots" Program. This program requires emission inventory updates every four years.

Government Publication Date: Dec 31, 2019

Clandestine Drug Lab Sites: CDL

The Department of Toxic Substances Control (DTSC) maintains a listing of drug lab sites. DTSC is responsible for removal and disposal of hazardous substances discovered by law enforcement officials while investigating illegal/clandestine drug laboratories.

Government Publication Date: Jan 19, 2021

Tribal

No Tribal additional environmental record sources available for this State.

County

No County additional environmental databases were selected to be included in the search.

Definitions

Database Descriptions: This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

Detail Report: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

Distance: The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

Direction: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

Elevation: The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.

Map Key: The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

Unplottables: These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.

APPENDIX D: QUALIFICATIONS

PARTNER

PARTNER

Zachary Oretsky, M.S.
Staff Scientist

Education

M.S. Geology, University of California, Davis
B.S. Geoscience, Trinity University (TX)

Highlights

Phase I Environmental Site Assessments
Transaction Screen Assessments
Environmental Desktop Reports

Experience Summary

Mr. Oretsky currently serves as a Staff Scientist in the Environmental Due Diligence Division at Partner Engineering and Science, Inc. (Partner). Based out of the Roseville, California office, his responsibilities include performing Phase I Environmental Site Assessments (ESAs), Transaction Screen Assessments (TSAs), and Environmental Desktop Reports in compliance with the American Society of Testing and Materials (ASTM) and US Environmental Protection Agency's All Appropriate Inquiry (AAI) standards for residential, agricultural, industrial, and commercial properties.

Through coursework, scientific research, and industry experience, Mr. Oretsky has demonstrated his ability to successfully perform the practices of environmental due diligence at a high level. Mr. Oretsky is skilled in spatial data analysis, field data collection, extensive historical research, technical report writing, and interpersonal communication. Mr. Oretsky has performed environmental assessments for sites including, but not limited to, manufacturing, industrial/warehouse facilities, dry-cleaning facilities, agricultural facilities, gas service stations, multi-family residential, and commercial office buildings. He has worked with a variety of financial institutions including US Bank, Umpqua Bank, and Mechanic's Bank.

Project Experience

Commercial Warehouse, Union City, California. Mr. Oretsky performed a Phase 1 ESA for a 22,374 square-foot multi-tenant commercial warehouse.

Commercial Printing, Sacramento, California. Mr. Oretsky performed a Phase 1 ESA for a 10,000 square-foot industrial building used for commercial printing operations. An underground storage tank was discovered after Mr. Oretsky recommended a Phase II investigation.

Industrial and Agricultural, Cutler, California. Mr. Oretsky performed a Phase 1 ESA for a property consisting of a 78,217 square-foot box manufacturing facility and citrus orchard on 36 acres of farmland.

Gas Station and Car Wash, Chico, California. Mr. Oretsky performed a Phase 1 ESA for a gas station and car wash facility that has been equipped with four underground storage tanks since 1986. A Phase

Commercial Office and Dry-Cleaning, Walnut Creek, California. Mr. Oretsky performed a Phase 1 ESA for a property consisting of a medical office and detached dry-cleaning facility in the heart of Walnut Creek city center.

Multi-Family Apartment Complex, Orland, California. Mr. Oretsky performed a Phase 1 ESA for a property consisting of 15 buildings and 49 residential units totaling 36,000 square-feet.

Auto Repair and Gas Station, Trumbull, Connecticut. Mr. Oretsky assisted in an Enhanced TSA for a 50+ year-old gas station and auto repair facility as part of a large multi-project portfolio spanning the states of Connecticut, Massachusetts, and Rhode Island.

Affiliations

Association of Environmental and Engineering Geologist (AEG)
Geological Society of America (GSA)

Contact

zoretsky@partneresi.com
(209) 843-3567

Education

B.S., Civil Engineering, Environmental Specialty. Texas A&M University

Registrations

Registered Environmental Manager (REM) No. 11732
Certified Florida Environmental Assessor (CFEA) No. 308
Engineer in Training (EIT): Texas No. ET-26189
Registered Environmental Property Assessor (REPA) No. 5995

Training

40-Hour OSHA-approved Health & Safety Training
8-hour OSHA HAZWOPER Annual Refresher
AHERA Asbestos Building Inspector
FEAA Phase I & II ESA Training Course
Trained in EPA CLP Data Validation

Highlights

15 years of experience in the environmental service industry
Phase I Environmental Site Assessments
Phase II and III Subsurface Investigations

Experience Summary

As Senior Project Manager for due diligence services as part of the Investment Advisory Group, Ms. Howard focuses on managing staff, report quality, client service, and sharing years of expertise with staff and clients.

Ms. Howard has performed hundreds of Phase I Environmental Site Assessments, Third Party Reviews, Due Diligence Audits, Record Search and Risk Assessments, Phase II and III Subsurface Investigations, Underground storage tank investigations, Remedial Investigations, Radon Studies, Mold Assessments, Methane Surveys, Indoor Air Quality Assessments, and Lead-in-water sampling and analysis.

Clients have varied and have included: individual investors, institutional investors, private and institutional equity companies, insurance companies, attorneys, brokers, developers, and multiple lenders.

Project Experience

Ms. Howard currently serves as a Senior Project Manager for Partner providing solutions to clients' due diligence and engineering needs. She is responsible for ensuring consistency, quality, and on-time delivery of due diligence and engineering services provided by Partner. Current day-to-day responsibilities include project oversight, staff supervision, report review, and client management. The following select projects summarize her experience and due diligence background:

Senior Project Manager, United States, Canada, United Kingdom, Cornerstone Real Estate Advisers
Responsible for the environmental asset management and environmental consulting services for nationwide equity and mortgage portfolio as consultant for Cornerstone Real Estate Advisers LLC (CREA)/

Massachusetts Mutual Life Insurance Company for residential/mixed use, commercial, joint venture developments and industrial properties and assets.

Manage and coordinate all of CREA's environmental due diligence and environmental actions associated with acquisitions, property development, joint venture developments, property divestments and finance group loan transactions. Environmental due diligence includes Phase I ESAs, Phase II ESAs, indoor air quality assessments, mold assessment and mitigation planning, asbestos investigations, asbestos abatement, operation and maintenance plan development, remedial action development and implementation, regulatory correspondence and permitting.

Environmental Regulatory Compliance, United States
Developed and updated regulatory compliance documentation for a major medical supply corporation. Documentation included a hazardous waste management manual, a hazardous materials management manual and training program, and material safety data sheets (2005). Developed an Environmental Compliance Manual for a large car rental corporation to be used as a regulatory framework for environmental compliance for water, air, soil, hazardous waste management, and occupational health and safety (2004-2012).

Homeland Security, Northeast Florida
Participated in and planned project Planned Freedom II and III for the Regional Domestic Security Task Force and the Northeast Florida Regional Planning Council. The purpose of the project is to provide the public, local, regional, state and federal agencies with information and guidance necessary to plan, design, and conduct a weapons of mass destruction terrorism exercise program (2005 and 2008). Ms. Howard acted as primary point of contact for Northeast Florida and supported the implementation of full-scale exercises including a conventional blast with mass casualties, a chemical blast with mass casualties, a SWAT event, and an agricultural infection component (2005). Ms. Howard acted as primary point of contact for the Jacksonville office and Senior Controller for the City of Jacksonville/Duval County Logistics Staging Area/Mutual Aid Reception Point/Volunteer Reception Center Full Scale Exercise. The exercise was based on a Category 3 hurricane in the City of Jacksonville (July 2008).

Storage Tank Programs
Completed UST Closure Reports, Limited Site Assessments, Soil Assessment Reports, Soil Closure Reports, and Corrective Action Plans for submittal to regulatory agencies for UST sites owned by various industrial and government entities (2000).

Subsurface Investigations
Conducted soil and groundwater assessments at multiple petroleum retail sites located throughout Texas. Activities included field oversight of groundwater monitoring well installation using mud-rotary, air-rotary, and hollow-stem augers; soil and groundwater sampling; receptor surveys; and elevation surveys of installed monitoring wells and soil borings (1998-2000).

Contact

RHoward@partneresi.com

Education

B.A., Geology, College of Wooster, Wooster, OH

Affiliations

Member, National Association of Environmental Professionals (NAEP) Member, Florida Association of Environmental Professionals (FAEP)
Member, International Council of Shopping Centers (ICSC)

Training

OSHA, Hazardous Waste Operator (HAZWOPER) 40-hour Certification - Certified Project Manager
USEPA Incident Mitigation and Treatment Methods
USEPA Hazardous Materials Emergency Response

Experience Summary

Mr. Marcus has over 29 years of experience in consulting services industry with a focus on environmental assessment and engineering due diligence assessments for a variety of property types meeting the needs and requirements of a varied number of reporting standards including: ASTM 1527-13, EPA's All Appropriate Inquiry (AAI), ASTM Standard E2018-08 for Property Conditions Assessments and customized client formats. Mr. Marcus has performed and managed Phase I Environmental Site Assessments, Third Party Reviews, Due Diligence Audits, Record Search and Risk Assessments, Phase II and III Subsurface Investigations, Remedial Investigations and Corrective Actions. His background also includes management of all phases of Industrial Hygiene Services, including; Asbestos and Lead Based Paint surveys and abatement, Radon Studies and Mitigation, Moisture and Microbial Assessments, Methane Surveys, Indoor Air Quality Assessments, and Lead-in-water sampling and analysis.

As Principal National Client Service Manager for due diligence services as part of the Investment Advisory Group, Mr. Marcus focuses on high level of client service for the management and direction of multi-disciplined due diligence projects. Mr. Marcus understanding the client needs and objectives of real estate transactions and offers years of experience and practical solutions to all phases of due diligence and corrective actions.

Over his professional consulting career, Mr. Marcus has performed and managed environmental and contamination site assessments, remedial actions and cost analysis, industrial hygiene projects and property conditions assessments for a wide range of client bases. Other equity and finance level services managed and directed by Mr. Marcus include management of ALTA Land Surveys, zoning reports, Seismic Risk Assessments (PML), Construction Risk Management, construction monitoring services and construction document cost review analysis.

Clients managed under Mr. Marcus' direction are varied and include:

- Equity Investors
- Real Estate Finance Institutions
- REITs
- Commercial and Residential Developers
- Retail Companies

- Real Estate Brokers
- Property Management Companies
- Private Property Owners
- Local and State Government

Project Experience

Mr. Marcus has conducted, managed and directed thousands of ESAs, industrial hygiene and engineering assessment throughout his career and has been Senior Project Manager for hundreds of property condition assessments, environmental risk assessments site investigations, characterization studies and remediation projects throughout the Southeast Region and the US. The following select projects and client base summarize his consulting experience and due diligence background:

Portfolio Management/Transaction Due Diligence

National Program Manager, MassMutal/Cornerstone Real Estate Advisers (MMLIC/CREA). For over 16 years Mr. Marcus served as Principal environmental programs client manager to MassMutual Life Insurance Company/Cornerstone Real Estate Advisers Equity and Finance Group Portfolio. In this managing role, Mr. Marcus performed overall portfolio management of due diligence services related to real estate acquisitions, finance deals, transfers, dispositions, as well as asset refinances for MMLIC/CREA. Closely coordinate with client Managing Directors, asset management, property managers, risk management team and counsel to provide risk evaluation, ASTM reporting and project oversight in meeting client/lender objectives. Services performed and managed include review of third-party reports, industrial hygiene services, asbestos surveys, subsurface investigations, remediation and development of soil and groundwater management plans. Manage all environmental matters involving client joint venture/at risk developments related to environmental risk management, development oversight and regulatory reporting.

Portfolio Program Manager, Hospitality Client. Manage and direct all acquisition level due diligence and disposition assessments for nationally based hospitality firm. Portfolio management services provided for full-service consulting include environmental assessments, risk assessments, industrial hygiene services, engineering evaluations, ADA surveys and property conditions assessments. As part of our acquisition level assessments, coordinate with lending institutions for permanent financing in providing reports and reliance to selected client lender.

Subsurface Investigations/Remedial Actions

Senior Project Manager, Wesley Chapel, FL, Confidential Client. Managed and directed technical and project management services for an 8-year long project associated with a chlorinated solvent impacted site involving assessment and in-situ remediation and long term-monitoring. Site impacts include impacts to a multiple aquifers with tetrachloroethylene (PCE), trichloroethylene (TCE) and breakdown products cis 1,2-dichloroethene (cis 1,2-DCE) and vinyl chloride (VC). The impacted zones also include an off-site solvent plume which was co-mingled with on-site source of contaminates. The assessment phase included a 2-year comprehensive Site Assessment delineation and subsequent approvals by FDEP for remedial action plan for site-wide groundwater treatment using in-situ bioremediation methods. Reductive dechlorinization of

groundwater impacts has resulted in approvals of long-term natural attenuation monitoring program with FDEP.

Senior Project Manager, Commercial Property Development, Charlotte, NC. Managed and directed environmental assessment, risk evaluation and regulatory program management for development of a commercial office complex in Uptown Charlotte. The 300 South Tryon development is a 25-story, Class A commercial office building under construction as of 2015 and included an extensive environmental history and program management since land was acquired by client in 2008. Multiple subsurface assessments were conducted to evaluate extent of soil and groundwater impacts for development of soil and groundwater management plans implemented during development. Remedial efforts, including soil excavation, disposal and groundwater effluent treatment and discharge monitoring, resulted in effective source removal. All environmental phases and remedial actions summarized and reported to the lead regulatory agency, NCDENR, with formal request for No Further Actions upon foundation completion. Coordination of this entire project with equity investor, development team, regulatory agencies and financial institutions to provide adequate risk evaluation and mitigation plans during the due diligence, subsurface investigation and development phases.

Municipal/State Contracts

Senior Project Manager, Broward County Aviation Department. Environmental program manager for consulting services at Ft. Lauderdale/ Hollywood International Airport. Provided and managed environmental assessments and corrective action planning associated with historical areas of impacts to soils and groundwater. Multiple project sites included, remedial actions at car rental facilities, vinyl chloride plume assessments, former Navy dump sites and areas subject to airport expansion. Environmental permitting support and groundwater modeling/assessments/remedial actions conducted for development of parking garages, consolidated fuel distribution center and runway expansion program.

Senior Program Manager, South Florida Water Management District. Environmental program manager for SFWMD conducting pre-acquisition level Phase I and Phase II Environmental Site Assessments on over 500,000-acres of agricultural land in Dade, Broward, Palm Beach, Collier and Hendry Counties. Work associated with Comprehensive Everglades Restoration Plan (CERP) involved development or remedial actions and risk assessments including multi-media sampling of soil, groundwater, sediment and surface waters which required development of Site-Specific Ecological Risk Assessments for SFWMD and US Fish and Wildlife Department.

Contact

wmarcus@partneresi.com

April 20, 2023

Larry DiVito
ldivito@brennanllc.com>

Site: 790 Shiloh Road, Windsor (APN 059-271-095)
Subject: Proposed bioretention features

Dear Mr. DeVito,

I reviewed the documents you provided to determine if the proposed bioretention/ recharge (LID) features on your development would impact the neighboring North Coast Regional Water Quality Control Board Cleanups closed case called the “Shiloh Oaks Company” located at 5900 Pruitt Avenue in Windsor. Based on the information you provided to me and documents available in the Cleanups case file it does not appear that your proposed development or any LID features would impact any remaining contaminants on the Cleanups case site as long as no groundwater supply wells are installed and operated at your project site. Please let me know if you have any more questions. Thank you.

Sincerely,

Heidi Bauer
Senior Engineering Geologist